

FRIMS Assam



Flood Reporting And Information Management System

	Assam Daily Flood Report as on 14-10-2022 at 4:00 PM										
Particulars	Situation as o										
Rivers	Rivers flowin	g above dan	ger level	•							
flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowin level			Nil							
	No. of										
District	Districts Affected	Name of l	Flood Affec	ted Districts							
Affected	11	Golaghat,		ubri, Dibrugarh, rajhar, Lakhimpur, ıkia							
No. Of Revenue Circles Affected	24										
	District	Total	Revenue	Circle							
	Darrang	1	Sipajhar Committee Committ								
	Dhemaji	4	Dhemaji, Sissiborgaon, Gogamukh, Jonai								
	Dhubri	1		Chapar Chabua, Dibrugarh West							
Name Of	Dibrugarh Golaghat	3		Khumtai, Bo							
Revenue	Jorhat	1	Jorhat W		Kakiiai						
Circles	Kokrajhar	1	Bagribari								
Affected	Lakhimpur	6			impur. Nowboi	cha, Naravanpur, Dhakuak	hana, Bihpu	ıria			
	Majuli	2	Subansiri, North Lakhimpur, Nowboicha, Narayanpur, Dhakuakhana, Bihpuria Ujani Majuli, Majuli								
	Nagaon	2	Nagaon, Kampur								
	Tinsukia	1	Tinsukia								
	Total	24									
	District	Total	Revenue Circle								
	Darrang	3	(Sipajhai								
	Dhemaji	52		(Dhemaji 2), (Sissiborgaon 1), (Gogamukh 15), (Jonai 34)							
	Dhubri	18	(Chabua 2) (Dibrugarh West 1)								
	Dibrugarh	3	(Chabua 2), (Dibrugarh West 1) (Dergaon 6), (Khumtai 3), (Bokakhat 19)								
Villages	Golaghat Jorhat	28 12	(Dergaon 6), (Khumtai 3), (Bokakhat 19) (Jorhat West 12)								
Affected	Kokrajhar	22	(Jorhat West 12) (Bagribari 22)								
Affected	Lakhimpur	99	(Subansiri 2) (Subansiri 1), (North Lakhimpur 4), (Nowboicha 12), (Narayanpur 17), (Dhakuakhana 28), (Bihpuria 37)								
	Majuli	32	28), (Binpuria 37) (Ujani Majuli 9), (Majuli 23)								
	Nagaon	11	(Nagaon 8), (Kampur 3)								
	Tinsukia	3	(Tinsukia 3)								
	Total	283									
	District	Male	Female	Children	Total Population	Population Details	Crop Area (in Hect.)	Crop Area Details			
	Darrang	0	0	0	0	(Sipajhar 0)	110.00	(Sipajhar 110.00)			
Population And Crop Area Affected	Dhemaji	3730	3630	1348	8708	(Dhemaji 507), (Sissiborgaon 370), (Gogamukh 7015), (Jonai 816)	2250.40	(Dhemaji 16.00), (Sissiborgaon 15.00), (Gogamukh 100.00), (Jonai 2119.40)			
	Dhubri	0	0	0	0	(Chapar 0), (Bilasipara 0)	283.50	(Chapar 283.50), (Bilasipara 0.00)			
	Dibrugarh	1567	1240	1050	3857	(Chabua 3857), (Dibrugarh West 0)	65.00	(Chabua 25.00), (Dibrugarh West 40.00)			

	Golaghat	0	0	0	0	(Dergaon Bokakhat (Khumtai 0	0),(753.09	(Bokakh	a 69.00), at 663.50 tai 20.59
	Jorhat	0	0	0	0	(Jorhat West 0)		103.00	0 (Jorhat West 103.00)	
	Kokrajhar	0	0	0	0	(Bagribari	0)	259.63 (Bagribari 259.63		
	Lakhimpur	10848	8967	6241	26056	(Subansiri North Lakh 7439), (No 18580), (N 0), (Dhaku), (Bihpuria	impur owboicha Jarayanpur aakhana 0	2094.50	(North L 0.00), (N 0.00), (Narayanp), (Dhaki	(Bihpuria
	Majuli	0	0	0	0	(Ujani Majuli 0), (Majuli 0)		581.19	(Ujani Majuli 272.69), (Majuli 308.50)	
	Nagaon	0	0	0	0	(Nagaon 0 Kampur 0		279.00		174.00), 105.00)
	Tinsukia	985	848	833	2666	(Tinsukia		238.00		1 238.00)
	Total	17130	14685	9472	41287	,	/	7017.31	,	, /
	District	Total	Relief Ca		.1207		Relief Dist		entres	
Relief Camps / Centres	Lakhimpur	13), Nowboicha	0, Bihpuria		akhimpur		ha 6,
Opened	Tinsukia	1	0(Tinsuki	ia 0)			1(Tinsukia			
	Total	14	0	(0)			14	1 - /		
Inmates In Relief Camps	Nil	1 2 1								
Human Lives										
Lost - Confirmed	Nil									
Human Lives Lost Confirmed - Death Type	Nil									
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
Турс	District	Total	Big	Small	Poultry					
	Darrang	474	474	0	0					
Animals	Dhemaji	13946	6755	3775	3416					
Affected	Lakhimpur	6966	5000	1966	0					
	Total	21386	12229	5741	3416					
Animals Washed Away	Nil				V 124					
Houses Damaged	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
Damagou	Dhemaji	1	0	1	23	0	23	0	0	0
	Total	1	0	1	23	0	23	0	0	0
Rescue Operation	Nil									
Relief Distributed	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)		
	Lakhimpur	191.00	35.22	10.57	1057.00	0.00	0.00	0.00		
	Tinsukia	42.99	7.99	2.39	239.00	0.00	0.00	0.00		
	Total	233.99	43.21	12.96	1296.00	0.00	0.00	0.00		
Relief	District	Baby Food	d Liquid	Baby Food	Solid	Others				
Distributed	1	100				HTW-22.00				

	Tinsukia	0.00-Q	0.00-Q 0-0.00-Q				
Infrastructure Damaged - Embankment Breached	Nil						
Infrastructure	District	Number	Details				
Damaged - Embankment Affected	Biswanath	1	Halem - Mild Erosion occured in Paken Area on 14.10.2022 R/Bank of River Brahmaputra (Long - 93.373098, Lat - 26.480320)				
Affected	Total District	1 Number	Details				
	District	Number	Halem - Road from Dathkala to Louguti From Ch. 5.90 KM to 7.40 KM Overtopped by flash				
Infrastructure Damaged - Road	Biswanath	2	flood water on 14.10.2022 (Long - 0.000000, Lat - 0.000000), Phuleswari aai than approach road Ch 0.00 KM to 0.750 KM Overtopped by flash flood water on 14.10.2022 (Long - 0.000000, Lat - 0.000000)				
	Bongaigaon Dhemaji	5	Boitamari - Jogighopa Salbari Road Salbari Massive errosion occurred by the river Champa along Jogighopa Salbariat 16 th km. as per report received from PWRD, Bongaigaon dated-14.10.2022. (Long - 90.484613, Lat - 26.288374), Jogighopa Salbari Road Salbari One HP Culvert partially damaged by the errosion of river Champa at 16th km.as per report received from PWRD, Bongaigaon dated-14.10.2022 (Long - 90.484952, Lat - 26.289116), Srijangram - Haripur to Malegarh apahar via Amguri PtI road Amguri Errosion occurred by river Mora Manas at 5th km. as per report received from PWRD, Bongaigaon dated- 14.10.2022 (Long - 90.664496, Lat - 26.281566), Extension of Bhadaipara Road Bhadaipara Road surface get damaged due to prolong rainy days at 1st km. as per report received from PWRD, Bongaigaon dated- 14.10.2022 (Long - 90.708403, Lat - 26.312975), Tilapara to Ambari Kacharipety road Tilapara Side slope erroded at ch 200.00m & Ch. 700.00m. as per report received from PWRD, Bongaigaon dated- 14.10.2022 (Long - 90.704907, Lat - 26.343889) Dhemaji - Batamari to Machkhowa PWD road Machkhowa Yesterday on 13/10/2022, Bridge approach(Br.No.4/1) damaged occurred at Batamari to Machkhowa PWD road (Length-5 m.) (Long - 94.481637, Lat - 27.320369)				
	Total	8	(Long - 94.481037, Lat - 27.520309)				
Infrastructure Damaged - Bridge Infrastructure	Nil						
Damaged - Wildlife	Nil						
	District	Other Det					
Infrastructure Damaged - Others	Baksa	Jalah - Anganwadi Centres Affected 1. 41 No Betbari AWC 2. 46 No dubagoan AWC 3. dolajani-1 AWC 4. Dolajani-2 AWC 5. No-2 Jalah AWC 6. No-1 Pub Khagrabari AWC 7. No-4 Charna AWC 5. No-1 Pachim Rehabari AWC has damaged due to heavy raining on 13 10-2022 as per report received from CDPO Jalah on 14-10-2022, Irrigation Canal/Scheme Damaged 1. Damage of Earthen Canal from ch. 2000.00m to 7230.00m of Branch Canal-1 of Bhumki F.I.S due to heavy rain water as per report received from EE,Irrigartion Dept,Tihu Division on 13-10-2022, Irrigation Canal/Scheme Damaged Damage of Earthen Canal from ch. 1600.00m to 2350.00m of Branch Canal-2 of Bhumki F.I.S due to heavy rain water as per report received from EE,Irrigartion Dept,Tihu Division on 13-10-2022, Irrigation Canal/Scheme Damaged Damage of Earthen Canal from ch. 4400.00m to 5580.00m of Branch Canal-3 of Bhumki F.I.S Damage of Earthen Canal from ch. 4400.00m to 5580.00m of Branch Canal-3 of Bhumki F.I.S Damage of Earthen Canal from ch. 4400.00m to 5580.00m of Branch Canal-3 of Bhumki F.I.S Damage of Earthen Canal from EE,Irrigartion Dept,Tihu Division on 13-10-2022, Irrigation Canal/Scheme Damaged Damage of Earthen Canal from ch. 1200.00m to 3250.00m of Branch Canal-5 of Bhumki F.I.S Damage of Earthen Canal from ch. 1200.00m to 3250.00m of Branch Canal-5 of Bhumki F.I.S due to heavy rain water as per report received from EE,Irrigartion Dept,Tihu Division on 13-10-2022, Irrigation Canal/Scheme Damaged Damage of Earthen Canal from ch. 10800.00m to 12190.00m of Main Canal-1 of Bhumki F.I.S due to heavy rain water as per report received from EE,Irrigartion Dept,Tihu Division on 13-10-2022					
	Bongaigaon	Srijangram - Bridge Approach Road Damaged Approach and SPT Bridge partially damaged due to prolong rainy days at 1st km. as per report received from PWRD, Bongaigaon dated - 14.10.2022. Long - 90.666070 Lati - 26.335395 Chabua - Anganwadi Centres Affected DODHIA AWC AFFECTED AS PER INFORMATION					
	Dibrugarh	RECEIVED FROM SOCIAL WELFARE DEPT ON 14/10/2022, N27 36.390 " E9513.651, Anganwadi Centres Affected DODHIA KULIGAON AWC AFFECTED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 14/10/2022, N2735.845 E9513.227,					

	Anganwadi Centres Affected DODHIA TENGABARI AWC AFFECTED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 14/10/2022, N2736.652 E9514.237, Anganwadi Centres Affected DODHIA CHALBIL AISUNG AWC AFFECTED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 14/10/2022, N27 34.890 E95 13.563,, Anganwadi Centres Affected DODHIA ROMAI AWC AFFECTED AS PER INFORMATION RECEIVED
	FROM SOCIAL WELFARE DEPT ON 14/10/2022,N27 36.450 E95 13.782, Anganwadi Centres Affected DODHIA CHALBIL AWC AFFECTED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 14/10/2022,N27. 5714 E95. 2346,
	Anganwadi Centres Affected KULIGAON AWC AFFECTED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 14/10/2022,N27 35.860 E95 13.460
	North Lakhimpur - Power Dept. Poles PSC POLE 8.5 MTR 20 NOS as reported by APDCL, NLP on 14/10/2022.,
Lakhimpur	Power Dept. Poles PSC POLE 7.5 MTR 46 NOS as reported by APDCL, NLP on 14/10/2022., Power Dept. Conductors 27.8 KM APPROX as reported by APDCL, NLP on 14/10/2022., Dhakuakhana - Sericulture Deptt. Damaged About 27,400 numbers of Muga Silk Worm damaged at Maj
	Jalbhari on 14/10/2022 as reported by Sericulture Department., Dhakuakhana. Bhuragaon - Elementary Schools Damaged Seojia Pather LP School eroded by Brahmaputra river on 13-
Morigaon	10-2022, Health Sub-Centre 2 NO Barkur Sub center eroded by Brahmaputra river on 13-10-2022
	Udalguri - Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at the left bank of Jakaibhangi F.I.S around 1200m at Sonari Basti on 24.09.2022 GPS – Lat-26.675788 Long-92.025329, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch. 13960.00m of B3M canal around 10m at Baligaon on 24.09.2022 GPS – Lat- 26.686493 Long-92.044493,
	Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch. 13980.00m of B3M canal around 10m at Baligaon on 24.09.2022 GPS – Lat-26.86813 Long-92.044353, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch. 13990.00m of B3M canal around 10m at Baligaon on 24.09.2022 GPS – Lat- 26.68607 Long-92.044352,
	Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch. 13950.00m of B3M canal around 10m at Baligaon on 24.09.2022 GPS – Lat- 26.68607 Long-92.044352, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Breach occurred at Ch. 7500.00m to 7550.00m of B5M canal around 50m at Honglabasti on 24.09.2022 GPS – Lat- 26.701007
	Long- 92.012781, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Breach occurred at Ch. 270.00m to 280.00m of D2B2M canal around 10m at Golandihabi on 24.09.2022 GPS – Lat- 26.772724 Long- 92.086823, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion & Damage
Udalguri	occurred at Dhalkata FIS around 15m at Dhalkata on 24.09.2022 GPS – Lat- 26.68111111 Long- 92.07861111, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Breach occurred at Ch. 5640.00m to 5650.00m of B2M canal around 7m at Monpur on 25.09.2022 GPS – Lat- 26.772724 Long-
	92.086823, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch. 1780.00 m to 1790m of D1B3M canal around 10m at Borigaon no. 1 on 24.09.2022 GPS – Lat-
	26.780893 Long- 92.070957, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch. 1790.00 m to 1800m of D1B3M canal around 10m at Borigaon no. 1 on 24.09.2022 GPS – Lat-26.780893 Long- 92.070957,
	Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Breach occurred at Ch. 2650.00m to 2670.00m of K2M canal around 20m at Odola Kahibari on 20.09.2022 GPS – Lat-26.7891403 Long- 92.011623,
	Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Damage of CC fall at Ch. 2600.00m of K2M around 10m at Odola Kahibari on 20.09.2022 GPS – Lat- 26.781733 Long-92.011525,
	Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch. 9000.00 m of B1M canal around 40m at Mashkhuti on 21.09.2022 GPS – Lat- 26.775429 Long- 92.17741,
	Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch. 9560.00 m of B1M canal around 10m at Jogigaon on 21.09.2022 GPS – Lat- 26.755501 Long- 92.78416,
	Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch 9515.00 m of B1M canal around around 15m at Dahalapara on 21.09.2022 GPS – Lat- 26.75701 Long-92.177191,
	Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch 9580.00 m of B1M canal around 12m at Dahalapara on 21.09.2022 GPS – Lat- 26.750596 Long-

		03.171275
		92.171275, Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch 9660.00 m of B1M canal around 14m at Dahalapara on 21.09.2022 GPS – Lat- 26.754636 Long- 92.17931,
		Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch 9640.00 m of B1M canal around 15m at Dahalapara on 21.09.2022 GPS – Lat- 26.754636 Long- 92.179155,
		Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch 9770.00 m of B1M canal around 10m at Ranabasti on 21.09.2022 GPS – Lat- 26.753023 Long- 92.180532,
		Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion & Siltation occurred at Ch 9900.00 m of B1M canal around 40m at Ranabasti on 21.09.2022 GPS – Lat-26.753023 Long- 92.180532,
		Irrigation Canal/Scheme Damaged As per report of Irrigation Department on 14.10.2022, Erosion occurred at Ch 450.00 m Moradhansiri canal of Dhansiri Irrigation Project around 15m at Rowta on 02.09.2022 GPS – Lat- 26.723021 Long- 92.192831
	District	Details
	Biswanath	Gohpur - R/Bank of River Solengi at Nalbari Area Erosion has been observed in the R/Bank of River Solengi at Nalbari Area on 14.10.2022 0, Halem - Upsteam of Kalyani Than (Dipara Dani Village) Erosion observed at upstream of Kalyani Than on R/Bank of River Brahmaputra on 14.10.2022 0
Erosion	Bongaigaon	Srijangram - Tinkonia part II(90.646717 26.23971) & Chillyapara Part II (90.734774 26.381555) Erosion has been going on today on 14.10.2022 at Tinkonia part II on river bank of Manas -Brahmaputra in a length of 200-250 m and at Chillyapara Part II on river bank of Aie in a length of 100-150 m approximately. 0
	Dhemaji	Jonai - At Badalpur, Pakuriguri and Jamuguri on 13/10/2022, 1 hectare of land got eroded by Dikhari and Lali River affecting Ten nos. families. As per report received from Lot Mandal at Badalpur, Pakuriguri and Jamuguri on 13/10/2022, 1 hectare of land got eroded by Dikhari and Lali River affecting Ten nos. families. 51
	Dhubri	South Salmara Part - Sundarpara pt-iii As per information received from concerned GP Secretary 60 nos family has been eroded due to erosion by river Brahmaputra at village Sundarpara pt-iii under south salmara rev Circle on 11/10/22 to 13/10/22 area Aprox lenth 1.5 km and breath 0.5 km. Eroded families has been shifted to the safe place. 237
	Dibrugarh	Dibrugarh East - 16/177 ORR Grant (Nagaghoolie Kachari Line) - Philonuguri Grant 8/152 No ORR Grant As per report received from Water resource Deptt continuous erosion is taking place since 08-10-2022 at 16/177 ORR Grant (Nagaghoolie Kachari Line) - Philonuguri Grant 8/152 No ORR Grant. 48 families affected who are provided GR again for 5 days., Rice - 6.2 Qntls, Dal - 1.145 Qntls, Salt - 0.343 Qntls, M.Oil - 48 (200ml) Pkt, Cerelac - 46 Pkt, Reached length - 5 Km, Relief Distribution Centre Name:- Okland Dyke (27.31'32.84"N/95.0'42.55"E) GPS Co-Ordinates are - (27.31'32.84"N/95.0'42.55"E) to (27.30'47.01" N/94.57'52.29" E) 223
	Morigaon	Bhuragaon - Balidunga Pam Brahmaputra river eroded 1 meter from 13-10-2022 to 15-10-2022 0, Laharighat - Leruamukh As per report of the Water Resources Dept on 14-10-22, erosion is observed in Leruamukh with max erosion of 2m. 0
	Tinsukia	Tinsukia - 1. KHAMTIGUWALI KOILA PATHER Active river bank erosion is going on at Dibru River since 11/10/2022 till 14/10/2022. As per report by the Gaonpradhan, the stretch area is 30 m. 0, Doomdooma - 1. Village: Phelai NC (Nawkata NC) River Bank erosion is being observed at Phelai area on the left Bank of River Brahmaputra since 10/10/2022 till 14/10/2022. The embankment is under risk of erosion in the downstream. As per information received from WR department officials the affected stretch is about 300 m in length. 0
	District	Details
Landslide	Karimganj	(Karimganj) At District - NH-8 road from near Shankar Lohar's House to Giriojamati's house. Reported on 08/08/2022 by the Executive Engineer, PWRD, Patharkandi & Ratabari T. R. Divn., Ramkrishnanagar, that road from NH-8 near Shankar Lohar's House to Giriojamati's house was badly damaged by landslide due to rain water & flood water from 17-06-2022 to 24-06-2022. Approx. length = 400m (from 0.00m to 1000m) of road was washed out by devastating current of torrential rain and also in some areas side berms, hard crust etc was badly damaged. 0
Urban Flood	Nil	, and cade, cannaged to