

FRIMS Assam



Flood Reporting And Information Management System

			Assam	Daily Flood Report as on	23-05-2022 at 4:00 PM					
Particulars	Situation as	Situation as on 23-05-2022 (in last 24 hours)								
Rivers flowing	Rivers flow level	ing above o	danger	Kopili (Dharamtul/Kampur)						
above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flow flood level	ing above l	highest	Nil						
	No. of Districts Affected	Name of	Flood Affe	ected Districts	Name of Urban Flood Districts					
District Affected	22	Dibrugar Golaghat Kamrup, Karimgar	h, Dima-Ha , Hailakano Kamrup (M nj, Lakhim	urang, Dhubri, asao, Goalpara, di, Hojai, Jorhat, M), Karbi Anglong West, pur, Majuli, Morigaon, onitpur, Udalguri						
No. Of Revenue Circles Affected	56									
	District	Total	Revenue	Circle						
	Barpeta	5	Barpeta,	Baghbar, Sarthebari, Kalga	achia, Chenga					
	Cachar	5	Katigora	h, Udharbond, Sonai, Lakh	ipur, Silchar					
	Darrang	3	Patharigl	Patharighat, Mangaldoi, Dalgaon						
	Dhubri	1	Athani							
	Dibrugarh	1	Chabua							
	Dima- Hasao	1	Haflong							
	Goalpara	4	Matia, Balijana, Rongjuli, Lakhipur							
	Golaghat	2		Bokakhat, Khumtai						
	Hailakand	1	Algapur	· · · · · · · · · · · · · · · · · · ·						
	Hojai	3	Lanka, D	Lanka, Doboka, Hojai						
	Jorhat	2	Jorhat West, Jorhat East							
Name Of	Kamrup	10	Kayan, Palashbari, Rangia, Boko, Hajo, Kamalpur, Nagarbera, Chaygaon, North Ghy, Chamaria							
Revenue		10	кауап, ғалаsпраті, каngıa, воко, најо, Kamalpur, Nagarbera, Chaygaon, North Ghy, Chamaria							
Circles Affected	Kamrup (M)	2	Chandrapur, Sonapur							
	Karbi Anglong West	1	Donkam	Donkamokam						
	Karimgan j	2	Karimga	Karimganj, Badarpur						
	Lakhimpu r	1	Bihpuria							
	Majuli	2		Jjani Majuli						
	Morigaon	2	Morigao	n, Mayong						
	Nagaon	3		Nagaon, Raha						
	Nalbari	2	_	Nalbari, Barkhetri						
	Sonitpur	1	Dhekiaju							
	Udalguri	2		, Mazbat						
	Total	56		,						
	District	Total	Revenue	Circle						
	Barpeta	255), (Chenga 39), (Barpeta 50), (Baghbar 64)					
Villages	Cachar	368			(Katigorah 149), (Sonai 40), (Lakhipur 60)					
Affected	Darrang	17		Idoi 8), (Patharighat 6)						
	Darrang	100	(Athani		, (Daigaon 3)					
	Diluon	100	(Auiaili	1100)						

-											
	Dibrugarh	1	(Chabu	a 1)							
	Dima- Hasao	7	(Haflon	g 7)							
	Goalpara	263	(Matia	43), (Balija	na 75), (Ro	ngjuli 22), (Lakhipur 12	23)				
	Golaghat	4	(Bokak	hat 1), (Kh	umtai 3)						
	Hailakand i	4	(Algapı	ır 4)							
	Hojai	31		(Lanka 2), (Doboka 24), (Hojai 5)							
	Jorhat	12			orhat East 7) ingia 2), (Boko 2), (Ha	io 24) (Va	molnur 22) (Nagarbara			
	Kamrup	104				1 1 1 Chamaria 22 1 22 1 22 2 2 2 2	190 24), (K ai	naipui 22), (ivagaibeia			
	Kamrup (M)	21	(Chanda	rapur 10), (Sonapur 11)					
	Karbi Anglong West	2	(Donka	mokam 2)							
	Karimgan j	11	(Karim	ganj 5), (Ba	adarpur 6)						
	Lakhimpu r	23	(Bihpur	ria 23)							
	Majuli	6		2), (Ujani							
	Morigaon	213			lorigaon 89)	1.40					
	Nagaon Nalbari	250 6			na 84), (Nag), (Barkhetri						
	Sonitpur	8	(Dhekia), (Barknetn	[3]					
	Udalguri	3		ıri 2), (Maz	zbat 1)						
	Total	1709		. ,, ,	<u> </u>						
	District	Male	Femal e	Children	Total Populatio	Population Details	Crop Area (in	Crop Area Details			
					n	(Barpeta 0), (Hect.)	(Barpeta 4620.00), (
						Sarthebari 0), (Sarthebari 4449.00), (
	Barpeta	0	0	0	0	Kalgachia 0), (11389.96	Kalgachia 814.00), (
						Chenga 0), (Baghbar 0)		Chenga 772.00), (Baghbar 734.96)			
						(Katigorah 91228), ((Katigorah 3125.00),			
						Udharbond 7503), ((Udharbond 0.00), (
	Cachar	80801	71066	46261	198128	Sonai 33963), (4616.00	Sonai 0.00), (
						Lakhipur 33526), (Silchar 31908)		Lakhipur 223.00), (Silchar 1268.00)			
						(Patharighat 787), ((Patharighat 285.50),			
	Darrang	3083	2531	2149	7763	Mangaldoi 6976), (10223.00	(Mangaldoi 2496.00			
						Dalgaon 0)), (Dalgaon 7441.50)			
	Dhubri	0	0	0	0	(Bilasipara 0), (Athani 0)	2167.69	(Bilasipara 0.00), (Athani 2167.69)			
Population And Crop	Dima- Hasao	424	267	188	879	(Haflong 879)	99.00	(Haflong 99.00)			
And Crop Area	паѕао							(Balijana 2570.00), (
Affected	C1			0		(Balijana 0), (Matia	16012.00	Lakhipur 10060.00), (
	Goalpara	0	0	0	0	Lakhipur 0), (Matia 0), (Rongjuli 0)	16012.00	Matia 2522.00), (
								Rongjuli 860.00)			
	Golaghat	0	0	0	0	(Bokakhat 0), (Khumtai 0)	32.00	(Bokakhat 15.00), (Khumtai 17.00)			
	Uoisi	24021	17099	3394	11511	(Lanka 621), (1595.00	(Lanka 221.00), (
	Hojai	24021	17099	3394	44514	Doboka 42909), (Hojai 984)	1393.00	Doboka 1238.00), (Hojai 136.00)			
	T 1 .	0	0	0	0	(Jorhat West 0), (164.50	(Jorhat West 136.00			
	Jorhat	0	0	0	0	Jorhat East 0)	164.50), (Jorhat East 28.50)			
						(Nagarbera 0), ((Nagarbera 1583.00),			
						Chaygaon 0), ((Chaygaon 52.00), (Chamaria 1829.50), (
						Chamaria 0), (Kayan		Kayan 60.10), (
	Kamrup	180	46	40	266	0), (Palashbari 0), (Rangia 0), (Boko 0	4994.02	Palashbari 10.00), (
), (Hajo 50), (Rangia 10.00), (
1	1	1	1	ĺ	ĺ		1	Boko 69.00), (Hajo			
						Kamalpur 216), (1334 29) (Kamalaur			
						Kamalpur 216), (North Ghy 0)		1334.29), (Kamalpur 44.00), (North Ghy			

	1		1		1			1			
	Kamrup (M)	301	226	0	527	(Chandrapi Sonapur 5		1170.50	(Chandrapu (Sonapur 2		
	Karbi Anglong West	180	193	166	539		(Donkamokam 539)		(Donkamokam 0.00)		
	Karimgan	2429	1986	1267	5682	(Karimgan Badarpur		0.00	(Karimganj Badarpur 0		
	Lakhimpu r	0	0	0	0	(Narayanpı Bihpuria 0	ur 0), (448.00	(Narayanpu Bihpuria 44	r 0.00), (
	Majuli	0	0	0	0	(Majuli 0 Majuli 0)		53.76	(Majuli 20 Ujani Majuli	i 33.45)	
	Morigaon	15807	15366	9172	40345	(Morigaon Mayong 0)	13901.33	(Morigaon (Mayong 9	965.50)	
	Nagaon	151428	13694 5	62697	351070	(Kampur 1 Nagaon 29 Raha 8471	9202), (15324.24	(Kampur 5 Nagaon 362 Raha 6101.	23.00), (24)	
	Nalbari	0	0	0	0	(Paschim N (Barkhetri	Nalbari 0), 0)	108.00	(Paschim Na 42.00), (Ba 66.00)		
	Sonitpur	0	0	0	0	(Dhekiajuli	i 0)	204.00	(Dhekiajuli	204.00)	
	Udalguri	343	209	137	689	(Kalaigaon Harisinga Udalguri 4 Mazbat 27	0),(413),(0.00	(Kalaigaon Harisinga 0 Udalguri 0. Mazbat 0.0	0.00), (00), (
	Total	278997	24593 4	125471	650402	Widzodt 27	0)	82503.00	Wazbat 0.0	<u> </u>	
	District	Total	Relief C	amp			Relief Dist	ribution Cent	res		
	Barpeta	3	0(Sarthe				3(Sarthebar				
	Cachar	419	288(Udl		Katigorah 102 ipur 0)	2, Silchar	131(Udharbond 6, Katigorah 92, Silchar 9, Sonai 1, Lakhipur 23)				
	Dibrugarh	1	0(Chabu	ıa 0)	-		1(Chabua	1)			
	Dima- Hasao	10	4(Haflor	ng 4)			6(Haflong 6)				
Relief	Hailakand i	4	3(Algap				1(Algapur				
Camps /	Hojai	14		oka 11, Hoja		1.0)		0, Hojai 0)	. 1 145		
Centres Opened	Kamrup Karbi Anglong West	2		a 0, Kayan amokam 0)	0, Kamalpur	(0)	3(Rangia 1, Kayan 1, Kamalpur 1) 2(Donkamokam 2)				
	Karimgan	15	6(Badar	pur 6, Karin	nganj 0)		9(Badarpur 0, Karimganj 9)				
	Morigaon	21	3(Morig	aon 3)			18(Morigae				
	Nagaon	162	48(Kam	pur 15, Rah	a 7, Nagaon	26)	114(Kampur 0, Raha 80, Nagaon 34)				
	Udalguri	2	0(Udalg	uri 0)			2(Udalguri 2)				
	Total	656	366				290			•	
	District	Total	Revenue	e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y	
	Cachar	62508	43), (Se	rah 33462), onai 10309) har 18694)		26394	21181	14878	38	17	
Inmates In Relief	Dima- Hasao	268	(Haflong			90	110	66	1	1	
Camps	Hojai	6716	(Lanka (Hojai	0), (Doboka 430)	6286),	3131	2267	1317	1	0	
	Karimgan j	308		anj 0), (Bad		161	94	39	14	0	
	Morigaon	105		on 105), (M	• • •	47	38	20	0	0	
	Nagaon	20692		r 7102), (Ra ı 12063)	ına 1527),	9838	7471	3235	146	2	
Uп	Total District	90597	Male	Female	Children	39661 Revenue C	31161	19555	200	20	
Human Lives Lost -		Total		remate				r () (Silcher	1), (Sonai 0))	
Confirmed	Cachar	1	0	1	0	(Udharbono		. 1 0), (Blichal	1 1), (Bollai U	,,	

	Total	1	0	1	0					
Human Lives Lost	District	Total	Flood Death	General Drownin g (Non	Landslide					
Confirmed -			Death	Flood)						
Death Type	Cachar	1	1	0	0					
	Total	1	1	0	0					
Human Lives Lost - Missing	Nil	Nil								
Human Lives Lost Missing - Type	Nil									
	District	Total	Big	Small	Poultry					
	Barpeta	29710	13781	8429	7500					
	Darrang	13629	5252	4077	4300					
	Dibrugarh	214	189	25	0					
Animals	Goalpara	1250	720	530	0					
Affected	Hojai	270	160	110	0					
	Kamrup	4885	2109	1196	1580					
	Morigaon	75910	28043	17116	30751					
	Nagaon Total	101661 227529	56346 10660	28105 59588	17210 61341					
	District	Total	0 Big	Small	Doultmy					
Animals	Hojai	2	2	0	Poultry 0					
Washed	Nagaon	200	0	0	200					
Away	Total	202	2	0	200					
Houses	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
Damaged	Hojai	4	0	4	0	0	0	0	0	0
	Total	4	0	4	0	0	0	0	0	0
	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d
	Cachar				0	0	0	0	0	19
Rescue	Darrang				0	0	0	0	0	2
Operation	Karimgan j	Civil Defe Volunteer	ence/Train s, SDRF	ed	1	25	0	0	0	0
	Lakhimpu r				0	0	0	0	0	1
	Nagaon	SDRF			7	0	0	0	0	18
	Nalbari	Circle Off Administr			12	85	48	0	0	0
	Total				20	110	48	0	0	40
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed	- Rice Bran (i	in Q)
	Barpeta	0.00	0.00	0.00	0.00	0.00	270.81	0.00		
	Cachar	571.89	146.47	52.09	2234.00	0.00	0.00	0.00		
Relief	Darrang	0.00	0.00	0.00	0.00	0.00	0.00	308.28		
Distributed	Dibrugarh	0.00	0.00	0.00	0.00	0.00	17.50	0.00		
Distributed	Dima- Hasao	37.17	3.54	1.77	177.00	0.00	0.00	0.00		
	Hailakand i	4.86	0.85	0.26	25.50	0.00	0.00	0.00		
	Hojai	44.00	2.55	1.30	69.00	0.00	0.00	0.00		
	Kamrup	3.65	0.65	0.20	0.20	0.00	234.82	0.00		
	Karbi Anglong	11.40	1.61	0.49	0.49	0.00	0.00	0.00		

	West										
	Karimgan	11.81	2.26	0.68	0.00	0.00	0.00	0.00			
	Morigaon	600.10	106.95	32.09	0.00	0.00	256.00	0.00			
	Nagaon	2121.64	390.37	117.11	0.00	0.00	145.00	0.00			
	Udalguri	8.53	1.66	0.50	49.78	0.00	0.00	0.00			
	Total	3415.05	656.91	206.49	2555.97	0.00	924.13	308.28			
	District	Baby Foo Liquid	od	Baby Food	d Solid	Others					
	Barpeta	0.00-Q		0.00-Q							
	Cachar	0.00-Q		0.00-Q				Candle-1202.00-Pkt; Match Box - -408.55-Kg; Potato-7118.00-Pkt			
	Darrang	0.00-Q		0.00-Q			-100.00-Pieces				
	Dibrugarh	0.00-Q		0.00-Q							
	Dima- Hasao	0.00-Q		0.00-Q							
Relief	Hailakand i	0.00-Q		0.00-Q							
Distributed Others	Hojai	0.00-Q		0.00-Q		Biscuit-14	140.00-Pkt; Ph	paulin-160.00-Pieces; Water-1200.00-L; enyl-20.00-Pieces; Bleaching powder- 98.00-L; Chira-11.25-Q; Gur-1.50-Q			
	Kamrup	0.00-Q		0.00-Q		0-0.00-Q					
	Karbi Anglong West	0.00-Q		0.00-Q							
	Karimgan j	0.00-Q		0.00-Q		0-1.00-Q	0-1.00-Q				
	Morigaon	1800.00-I		2000.00-P		TARPAULIN-1000.00-Pieces					
	Nagaon	0.00-ml, 6			3300.00-Pkt	Tarpaulin-338.00-Pieces Sanitary Pad-63.00-Pkt					
	Udalguri	0.00-Q, 0 Numbe		0.00-Q, 25	0.00-PKt	Sanitary F	² ad-65.00-PKt				
Infrastructur e Damaged -	District	r	Details Raha - I	Raha Chaki I	Hariamukh Me	eteka Emban	kment cum ro	ad Durgajan Date of occurence-			
Embankment	Nagaon	1						territorial Sub -Division			
Breached	Total	1									
Infrastructur e Damaged - Embankment s Affected	Nil										
	District	Numbe r	Details								
Infrastructur e Damaged - Road	Barpeta	17	Barnagar - As per report received from Rupshi Dev Block Office dtd. 22/05/2022, Const. of road start from PMGSY road to Abed ali house damaged due to heavy rain fall Vill- Dharmapur , As per Wt message received from EE, PWD Sorbhog & Damage amp; Jania Territorial Road Divn, dtd. 23/05/2022 Surface damages on Sorbhog Kalgachia Road from Chainage 0.00 M to 500.00M Length= 500.00 M, Breadth= 5.5M damaged due to heavy rainfall. Village- Niz Chakabaushi , Baghbar - Gajia Kadong road at chainage 3rd, 5th, & 6th km. Medhirtary Date of Damage - 16.5.2022 Type of Damage - Both side Shoulder damaged Damage Length - 180 miter. Reported by PWD Department. , Manas Bridge approach to barpeta FAA Medical college(SH2) at chainage 51th, 52th, 54th, 56th & 58th km. Jania, chanpura, chapra Date of Damage - 16.5.2022 Type of Damage - Both side Shoulder & Hard crust damaged Damage Length - 570 m Reported by PWD Department. , Culvert approach & Road Shoulder of Jania to Howly Road at chainage 1st & 2nd km. Jania Date of Damage - 16.5.2022 Type of Damage - Culvert approach & Both side Shoulder damaged Damage Length - 160 m Reported by PWD Department. , Milijuli Bazar to Satrakanara 9 no seat Road Pkg no As-01-344 Satra kanara 9 no. seat Date of Damage - 17.5.2022 Type of Damage - Shouldre & H/C damaged Damage Length - 1150 m Reported by PWD Department. , Mondia Dighirpam road to Mourigaon Road Pkg no As-01-223 Mourigaon Date of Damage - 17.5.2022 Type of Damage - Shouldre & H/C damaged Damage Length - 950 m Reported by PWD Department. , 1254 no Paharpur LPS to Salimpur MPNA Road. Pkg no As-01-239 salimpur Date of Damage - 17.5.2022 Type of Damage - Shouldre & H/C damaged Damage Length - 700 m Reported by PWD Department. , Satrakanara 5 no seat Kabarsthan to Satrakanar 9 no seat Pkg no As-01-214 Dighirpam Date of Damage - 17.5.2022 Type of Damage - Shouldre & H/C damaged Damage Length - 500 m Reported by PWD Department. ,								

		Agarjan to Agmondia Madhyapara road Pkg no As-01-242 Ag mandia Date of Damage - 17.5.2022 Type of Damage - Shouldre & H/C damaged Damage Length - 850 m Reported by PWD Department.
		Sarthebari - Gumir Pathar Village road Gumir Pathar Gumir Pathar Village road damaged at two points near Abdul Latif house to Shahjamal house approx. 20 ft & near Jahida Khatun house approx. 40 ft (reported by LM, 23.05.2022),
		Teleria Gaon Village Road Teleria Damaged approx. 300 Ft. at near Akbar Ali house (reported by LM, 23.05.2022),
		Village road of Thekar Pathar gaon Thekar Pathar Damaged approx. 40 ft at near LPS , Thekar Pathar (reported by LM, 23.05.2022),
		Kalatali Village road Kalatali Damaged approx. 200 m. (reported by JE, PWD Road, 23.05.2022), Kalgachia - Vill road st from Rampur Bazar to Musaraf Ali House. Rampur Vill As per report received from BDO, Rupshi on 22/05/2022 (evening), due to heavy rainfall repairing of sandgravel road st from Rampur Bazar to Musaraf Ali house damaged(L=30m, B= 3.00m, H=0.60m)., Khatartary vill road Khatartary vill As per report received from BDO, Rupshi on 22/05/2022 (evening), due to heavy rainfall repairing of sand gravel road st from Ismail Hussain house to SaharAli house damaged(L=30m, B= 2.00m, H=0.60m)
		Sonai - Baroail to Lamargram Road Baroail Baroail to Lamargram Road (At CH. 850.00M) was damaged, as per the report received from PWD Sonai (T) Division, as on 23.05.2022,
		Satkarakandi Bagpur Ferry Road Satkarakandi Satkarakandi Bagpur Ferry Road (PMGSY AS 03 103) was damaged, as per the report received from PWD Sonai (T) Division, as on 23.05.2022, Neirgram to Ganganagar Road Neirgram Neirgram to Ganganagar Road ch.100m to 3100m submerged as per the report received from PWD Sonai (T) Division, as on 23.05.2022, Sonai Sonabarighat Road Sonabarighat Sonai Sonabarighat Road ch.4700m to 6000m submerged as
		per the report received from PWD Sonai (T) Division, as on 23.05.2022, Silchar - Silchar Hailakandi Road Boalmara Boalmara Silchar Hailakandi Road Boalmara covering a length of 1.00 km is completely submerged, as per the report received from PWD Roads (T) Division. as on 23.05.22, Palei Derbi Rogislange Road Rogislange Bolei Derbi Rogislange Road (RDR) at 8th Km. ab. 2070.
Cachar	10	Paloi Derbi Borjelenga Road Borjelenga Paloi Derbi Borjelenga Road (PDB) at 8th Km, ch, 8070 m to 8100 m submerged, as per the report received from PWD Roads (T) Division. as on 20.05.22, PDB Road to Sarbantilla Road Sarbantilla PMGSY PKG No. AS-03-260, Road from 18t Km of PDB Road to Sarbantilla, ch 1100m to 1300m submerged, as per the report received from PWD Roads (T) Division. as on 20.05.22,
		Silchar Hailkandi road to Tarutajbari, Tarutajbari PMGSY PKG NO. AS-03-181 Silchar Hailkandi road to Tarutajbari, ch. 0m to 200m & 200m to 900m submerged, as per the report received from PWD Roads (T) Division. as on 20.05.22, Dwarbond Pratappur Road Dwarbond PMGSY PKG No AS-03-228, Dwarbond Pratappur Road
		Ch. 16050m to 16150m submerged, as per the report received from PWD Roads (T) Division. as on 20.05.22,
		Silcoorie PMGSY Road Silcoorie Silcoorie PMGSY Road to Irongmara Bapuji LP School of Irongmara Grant Village under APART (Pkg No. APART/NOCP/ROADS/C-06) submerged, as per the report received from PWD Roads (T) Division. as on 20.05.22
		Dalgaon - Kawadanga Rajapukhuri road Kawadanga Rajapukhuri road at CH-1st KM as per report
Darrang	1	received from SDO, PWRD, Kalaigaon Territorial road sub division Kawadanga Rajapukhuri road at CH-1st KM damaged. length - 100m, date of occurrence - 17/05/2022
		Golakganj - SIDE BERM, SIDE SLOPES & Samp; CULVERT APPROACH DAMAGED ON PTATAPGANJ PESTIRGHAT ROAD TO NH-31 NEAR SANI MANDIR AT CHARAIKHOLA
		VILLAGE AT 1ST. DATE OF OCCURANCE-21-05-22 PTATAPGANJ PESTIRGHAT ROAD TO NH-31 NEAR SANI MANDIR AT CHARAIKHOLA VILLAGE AT 1ST. , SIDE BERM, SIDE SLOPES & Samp; CULVERT APPROACH DAMAGED ON NH-31 TO
		B&D BUND NEAR DURGA MANDIR 1ST KM. DATE OF OCCURANCE-21-05-22 NH-31 TO B&D BUND NEAR DURGA MANDIR 1ST KM. ,
		SIDE BERM, SIDE SLOPES & Samp; CULVERT APPROACH DAMAGED ON NH-31 TO GOLAKGANJ ROAD VIA DOULATRAM BETA AT 1ST KM. DATE OF OCCURANCE-21-05-22 NH-31 TO GOLAKGANJ ROAD VIA DOULATRAM BETA AT 1ST KM. ,
Dhubri	10	SIDE BERM, SIDE SLOPES & Samp; BOX CULVERT APPROACH DAMAGED ON 718 NO NORTH TOKRERCHARA TO GOLAKGANJ KUMARGANJ ROAD AT 1ST & Samp; 2ND KM.
Diluoii	10	DATE OF OCCURANCE-21-05-22 718 NO NORTH TOKRERCHARA TO GOLAKGANJ KUMARGANJ ROAD AT 1ST & 2ND KM. , BRIDGE APPROACH DAMAGED OF RCC BR. NO 1/1 BARUNDANGA MORE TO HARIRHAT
		BAZAR ROAD. DATE OF OCCURANCE-21-05-22 RCC BR. NO 1/1 BARUNDANGA MORE TO HARIRHAT BAZAR ROAD. ,
		SIDE BERM & SIDE SLOPES DAMAGED ON UTTAR TOKRERCHARA PWD ROAD TO NH-31 NEAR TOLL GATE AT 1ST & DATE OF OCCURANCE-21-05-22 UTTAR
		TOKRERCHARA PWD ROAD TO NH-31 NEAR TOLL GATE AT 1ST & D. , SIDE BERM, SIDE SLOPES & DX CULVERT APPROACH DAMAGED ON G.K ROAD
		TO HAZIPARA VIA PUBERGAON AT 1ST KM. DATE OF OCCURANCE-21-05-22 G.K ROAD TO HAZIPARA VIA PUBERGAON AT 1ST KM. ,
		SIDE BERM & SIDE SLOPES DAMAGED ON KANURI DIMAKURI ROAD AT 2ND KM.

DATE OF OCCURANCE-1-05-22 I. KANNOR IDMANCH ROAD AT 2ND MY. I. ROAD FORMATON HAID TO AMAGED AN GOAR GROND PINCES READ NEAR RAFMATON HAID SCHOOL Aming, ME SCHOOL AT 1ST KM. DATE OF OCCURANCE-21-05-20 I. CONTROL AND AMAGED AMAGED AND AMAGED AND AMAGED AND AMAGED AND AMAGED AND AMAGED AND AMAGED AMAGED AND AMAGED AND AMAGED AND AMAGED AND AMAGED AMAGED AND AMAGED AMAGED AND AMAGED AMAGE			DATE OF OCCUPANCE 21 OF 22 VANUED DIMARUDI DO AD ATTOMO VAL
RAHMATGANI HIGH SCHOOL samps ME SCHOOL AT 1ST KM, DATE OF OCCURANCE-21-05-22 (IGOLAGAN) PROSEY ROAD NEAR RAHMATGAN) HIGH SCHOOL ∓ ME SCHOOL AT 1ST KM, 1. SIDE REPEM &man SIDE SI OPES DAMAGED ON KANURI BINNACHARA ROAD AT 1 ARHTMARI VILLAGE AT 1ST KM, DATE OF OCCURANCE-21-05-22 [KANURI BINNACHARA ROAD AT 1 ARHTMARI VILLAGE AT 1ST KM, DATE OF OCCURANCE-21-05-22 [KANURI BINNACHARA ROAD AT 1 ARHTMARI VILLAGE AT 1ST KM, 1. Balljana - Dowafa Pathimari Road Dowafa Pathimari Date of occurrence-22-05-2022 Lenghidimension Lengh afficacel 100 ml of uch of usual vertical resolution of information received-2-30-52 22 in 00.07 pm. Kumi Buan to Darkfort Lenguar Road Kamir Buare to Darkfort Lenguar Date of occurrence-2-20-5-2022 upon pm. Kumi Buan to Darkfort Lenguar Road Kamir Buare to Darkfort Lenguar Road Kamir Buare to Darkfort Lenguar Road Kamir Buare to Darkfort Lenguar Road Road 20-05-2022 upon pm. Kumir Buan to Darkfort Lenguar Road Kamir Buare to Darkfort Lenguar Road Road 20-05-2022 upon pm. Kumir Buan to Darkfort Lenguar Road Road upon to 10-05-2022 upon pm. Kumir Buan to Darkfort Lenguar Road Road upon to 10-05-2022 upon pm. Aga to Sampuar Road Alacewar Territorial Road Div. Date and time of information received-2-30-50-22 upon pm. Aga to Sampuar Road Road upon pm. Aga to Sampuar Road Bankar Buan upon pm. Aga to Sampuar Road u			DATE OF OCCURANCE-21-05-22 KANURI DIMAKURI ROAD AT 2ND KM. , ROAD FORMATION BADLY DAMAGED ON GOLAKGANI PMGSY ROAD NEAR
0.5-22 (GOLAKGAN JPMGSY ROAD NLAR RAHMATGAN) HIGH SCHOOL Kampp. ML SCHOOL AT 15T KM.]. SIDE BERM & Samp; SIDE SLOPES DAMAGED ON KANURI BINNACHARA ROAD AT LAKHMARA VILLAGE AT 15T KM. DATE OF OCCURANCE-21-65-22 [KANURI BINNACHARA ROAD AT LAKHMARA VILLAGE AT 15T KM.] Buljuma-1-Dwarda rehatumin Road Dwarda Puthama Tio and Loward Time Tio and Ch. 1900.0004 An			
SCHOOL AT IST KM.]. SIDE BERM Amps. SIDE SI OPES DAMAGED ON KANURI BINNACHARA ROAD AT LAKHMARI VILLAGE AT 1ST KM.]. BINSACHARA ROAD AT LAKHMARI VILLAGE AT 1ST KM.] BINSACHARA ROAD AT LAKHMARI VILLAGE AND LAKHMARI PART OF DAVID AND DAVID LONG DAVID LONG OF CULTURE AND LAKHMARI PART OF DAVID LAKHMARI LAMPARI LAMPARI DAVID LAKHMARI LAMPARI DAVID LAKHMARI LAMPARI LAMPARI DAVID LAMPARI LAMPARI DAVID LAMPARI			* '
LAKHIMARI VILLAGE AT IST KM. DATE OF OCCUEANICE 2-10-5-22 [KANURI BINNACHARA NOAD AT I-ARKHIMARI VILLAGE AT IST KM.] Balijana - Dwarks Puthimari Road [Dwarks Puthimari [Date of occurrence-22-05-2022 Length-dimension-Length affected 10.00 m. (ac. 16.190.0084) Average depth of suthmergence-45-00 cm Report received from Department—Godpara West and Jaleswar Territorial Road Div. Date and time of infirmation received-25-35-2022 a (10.070 m) or (ac. 16.201.0004, Ch. 1000.0004) and Ch. 1900.0004 and Ch. 1900.0004 haverage depth of submergence-30.00 cm Culturer damaged Report received from Department—Godpara West and Jaleswar Territorial Road Div. Date and time of information received-23-05.022 a (19.07) pm. Agia to Sanapara Road [Agia to Sarapara] Date of occurrence-22-05.2022 tength-dimension-Length affected 3000 m (ac th. 63.000 at 0.000 m). Agia to Sanapara Road [Agia to Sarapara] Date of occurrence-22-05.2022 tength-dimension-Length affected 3000 m (ac th. 63.000 M). Department—Godpara West and Jaleswar Territorial Road Div. Date and time of information received-2-20.50.2022 a longth-dimension-Louer damaged and foresched about 20 M. Department—Godpara West and Jaleswar Territorial Road Div. Date and time of information received-2-20.50.2022 a longth-dimension-Culturer damaged and information received-2-20.50.2022 a 100-100 pm. HCC Culvert on Baramatolinga Lenguar Road Banamatinga Lenguar Date of occurrence-2-20.50.2022 in phylidrimension-Culvert damaged at Ch. 30.000 DM Average depth of submergence-25.00 cm Department—Godpara West and Jaleswar House of the Charles of the Charle			
BINNACHARIA ROJAD AT LAKHIMARI VILLAGIE AT IST KM. Balijam - Dwark Puthimari Roud Downka Puthimari Date of occurrence -2.05.2022 Lenghédimension- Lengh affected 10.00 m (at Ch. 150.000M) Average depth of submergence -4.50 on Report received from Department—Goalpara West and Jaleswar Territorial Road Div. Date and time of information received -2.05.05.2022 (at 90.07 pm.) Kumin Bazar to Dardon't Lenghar Road [Kumin Bazar to Dardon't Lenpara] Date of occurrence-22.05.2022 Length/dimension- Length affected 50.00 m (at Ch. 200.0004, Ch. 1000.0004 and Ch. 1900.0004) Average depth of submergence -3.000 m (at Unit Lenghar) Date of occurrence -22.05.2022 Length/dimension- Length affected 20.00 m (at 50.0004) Revision and Jase of occurrence -22.05.2022 Length/dimension- Length affected 20.00 m (at 50.0004) Revision and Jase of occurrence -22.05.2022 Length/dimension- Length affected 20.00 m (at 50.0004) Revision and Jase of occurrence -22.05.2022 Length/dimension- Length affected 20.00 m (at 50.0004) Revision and Jase of occurrence -22.05.2022 Length/dimension- Culvert damaged at Ch. 3410.000 M Average depth of submergence-25.00 cm Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received- 23.05.2022 at 199.07 pm. Lakhipur - Kessapara Charidia to Kolabari rad Ilvent Peritorial Road Div. Date and time of information received- 23.05.2022 at 199.07 pm. Lakhipur - Kessapara Charidia to Kolabari rad Ilvent Peritorial Road Div. Date and time of information received- 23.05.2022 at 199.07 pm. Lakhipur - Kessapara Charidia to Kolabari rad Ilvent Festapara The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.25 KM by overflowing water of rain water from 2205/2022 to 101 data 2305/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.25 KM by overflowing water of rain water from 2205/2022 to 101 data 2305/2022. Karimgani - FN ROAD TO BHEDRANG PT II, PMGSY Y PKG NO-AS 13.20			SIDE BERM & SIDE SLOPES DAMAGED ON KANURI BINNACHARA ROAD AT
Bulliama - Dourska Puthimari Road Dourska Puthimari Date of occurrence-2 205 2022 Lenghth/dimension-Lenght affected 10,00 m (ac No. 150,000M) Average depth of submergence-4 5.00 cm Report received from Department - Godpara West and Jaleswar Territorial Road Div. Date and time of information received-2 35,0222 at 00170 m (ac ft. 62,000 MC, 10,000 000 and Ch. 1900,000 M). Average depth of submergence-30,00 cm Cutvert damaged Report received from Department-Golapar West and Jaleswar Territorial Road Div. Date and time of information received-21,05,2022 at 09,07 pm. Agia to Sanpapar Road Agia to Sarapara Date of occurrence-22,05 2022 Lenght/dimension-Length affected 10,000 m (ac ft. 62,000 M). Department-Golapara West and Jaleswar Territorial Road Div. Date and time of information received-23,05,2022 at 09,07 pm. Agia to Sanpapar Road Agia to Sarapara Date of occurrence-22,05 2022 Lenght/dimension-Length affected 20,000 m (ac ft. 8 MN) HPC damaged and breached about 20 M. Department-Golapara West and Jaleswar Territorial Road Div. Date and time of information received-23,05,2022 at 09,07 pm. HPC Culvert on Barmundanga Lempara Road Barmundanga Lempara Date of occurrence-22,05,2022 Lenght/dimension-Culvert damaged at Ch. 34,000 oM Average depth of submergence-25,00 cm Department-Golapara West and Jaleswar Territorial Road Div. Date and time of information received-23,05,2022 at 0,000 pm. Lakhtpur - Kesrapaac Chariali to Kolabari affected length & KM by overflowing water of rain water from 2205/2022 to ill date 23,05/2022. Lakhipur to Jaleswar Road Ala Rajmair The approach road of PWD department Lakhipur to Jaleswar Road AR Agiamia The approach road of PWD department Lakhipur to Jaleswar Road AR Agiamia The approach road of PWD department Lakhipur to Jaleswar Road AR Agiamia The approach road of PWD department Lakhipur to Jaleswar Road AR Agiamia The approach road of PWD department Lakhipur to Jaleswar Road Agiamia The approach road of PWD department Akhipur to Khal			·
Length/dimension. Length affected 10.00 m (at Ch. 1500.00M) Average depth of submergence-20.50 m Report neceived from Department. Gnalparus West and Jaleswar Territorial Road Div. Date and time of information received—23.05.2022 at 90.07 pm. Kumin Bazar to Dardivial Lengther Road Kumin Bazar to Dardivial Lemparu Date of occurrence-22.05.2022 Length/dimension. Length affected 50.00 m (at Ch. 620.00M, Ch. 1000.00M and Ch. 1900.00M) Average depth of submergence. 20.00.00 cm (Liver Amaged Report received from Department Goalpara West and Jaleswar Territorial Road Div. Date and time of information received—518.50.2022 at 1973 pm. Again to Suraparu Road Again to Suraparu Date of occurrence-22.05.2022 Length/dimension- Length affected 20.00 m (at 5th RA) IPIDE Changed and breached about 20 M. Department—Goalpara West and Jaleswar Territorial Road Div. Date and time of information received—23.05.2022 at 19.07 pm. HPC Clubret to Bammudanga Lempara Road Bammudanga Lempara Date of occurrence-22.05.00.2022 Length/dimension. Culvert damaged at Ch. 3400.00 M Average depth of submergence-22.05 occurrence-23.05.2022 Length/dimension. Culvert damaged at Ch. 3400.00 M Average depth of submergence-22.05 occurrence-23.05.2022 Length/dimension. Culvert damaged at Ch. 3400.00 M Average depth of submergence-22.05 occurrence-23.05.2022 at 19.07 pm. Labibjur - Kestapara Chanila to Kolabari affected length 2 K M by overflowing water of rain water from 22.05.2022 to ill date 23.05.2022. Lakibjur to Jaleswar Road Na Rajuntia The approach road of PWD department Lakibjur to Jaleswar Road Nater Khalisavita The approach road of PWD department Lakibjur to Khalisavita road affected length 0.20 KM by overflowing water of rain water from 2205.2022 to ill date 23.05.2022. Lakibjur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakibjur to Khalisavita road affected length 0.20 KM by overflowing water of rain water from 2205.2022 to ill date 23.05.2022. Karingaan Fin Road To Berbara Near			·
em Report received from Department - Goalpara West and Jaleswar Territorial Road Div. Date and time of information received-23.05.2022 at 09.00 m. (at Ch. 62.000M, Ch. 1000.00M and Ch. 1900.00M Average depth of submergence-30.00 cm Culvert damaged Report received from Department- Goalpara West and Jaleswar Territorial Road Div. Journal and time of information received-23.05.2022 at 09.07 pm . Again to Sarapara Road Again to Sarapara Date of occurrence-22.05.2022 Length/dimension-Length affected 20.00 m (at 5th KM) HTC damaged and breached about 20 M. Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received-23.05.2022 at 09.07 pm , HPC Culvert on Barmundanga Lempara Road Barmundanga Lempara Date of occurrence-22.05.2022 at 09.07 pm , HPC Culvert on Barmundanga Lempara Road Barmundanga Lempara Date of occurrence-22.05.00 cm Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received-23.05.2022 at 09.07 pm , Lakhipur - Kesrapara Chariali to Kolabari affected length 2 KM by overflowing water of rain water from 22.055.2022 to dil date 23.055.2022. Lakhipur to Jaleswar Road Afa Rajintial The approach road of PWD department Eakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 22.055.2022 to till date 23.055.2022. Lakhipur to Kladisavita Road Near Kladisavita The approach road of PWD department Lakhipur to Kladisavita Road Near Kladisavita The Agoint Road Near Road Ne			· · · · · · · · · · · · · · · · · · ·
time of information received- 23 05.2022 at 09.07 pm. Kumin Bazar to Dardou's Length affected 50.00 in GCh. 62.00.00 ft., 1000.00M and Ch. 1900.000 M Average depth of submergence 5.00 cm Gulvert damaged Report received from Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received- 23 05.2022 at 09.07 pm. Again to Surapara Road I Again to Surapara I Date of occurrence- 22.05.2022 at 109.07 pm. Again to Surapara Road I Again to Surapara I Date of occurrence- 22.05.2022 at 09.07 pm. Again to Surapara Road I Again to Surapara I Date of occurrence- 22.05.2022 at 09.07 pm. Again to Surapara Road I Piv. Date and time of information received- 23.05.2022 at 09.07 pm. HPC Cultwert on Bamundraga Lempara Road I Bamundraga Lempara I Date of occurrence- 22.05.2022 Length/dimension. Cultvert damaged at Ch. 3400.00 M Average depth of submergence- 25.05 cm. 20 peraturent- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received- 23.05.2022 at 09.07 pm. Labhipur - Kesrapara Charidi to Kolabari affected length 2 KM by overflowing water of rain water from 22.05.2022 to ill date 23.05.2022. Lakhipur to Jaleswar Road J Again in Road Again affected length 2 KM by overflowing water of rain water from 22.05.2022 to ill date 23.05.2022. Lakhipur to Khalisswita Road J Near Khalisswita [The approach road of PWD department Lakhipur to Jaleswar Road J Again			
Kumit Bazar to Dariduri Lempara Road Kumri Bazar to Dariduri Lempara Dacid of occurrence- 22.05.2021 anghddimension-Length affected 50.00 m (ar. Ch. 50.000M), A. Di80.00M and Ch. 1900.00M) Average depth of submergence- 30.00 cm Culvert damaged Report received from Department- Coalpara West and Ialeswar Territorial Road Div. Date and time of information received- 23.05.2022 at 09.07 pm , Agin to Sarapara Road Agin to Sarapara Date of occurrence- 22.05.2022 lengthdimension-Length affected 20.00 m (ar 5th KM) HPC damaged and breached about 20 M. Department-Goalpara West and Jaleswar Territorial Road Div. Date and time of information received- 23.05.2022 at 09.07 pm , HPC Culvert on Baranachanga Lempara Road Baranachanga Lempara Date of occurrence- 22.05.00 cm Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received- 23.05.2022 at 19.07 pm , Lakhipur to Jaleswar Road Alexandria The approach road of PWD department Kesrapara Charalit in Kolabari affected length 2 KM by overflowing water of rain water from 22.05.2022 to till date 23.05.2022. Lakhipur to Jaleswar Road Alexandria The approach road of PWD department Lakhipur to Jaleswar Road Afected length 0.05 KM by overflowing water of rain water from 22.05.2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.05 KM by overflowing water of rain water from 22.05.2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.05 KM by overflowing water of rain water from 22.05.2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.25 KM by overflowing water of rain water from 22.05.2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.25 KM by overflowing water of rain water from			
22.05.2022 Length/dimension- Length affected 50.00 m (Cluve Gamaged Report received from Ch. 1900.00M) Average depth of submergence 50.00 cm Culver damaged Report received from Department- Gealpara West and Jaleswar Territorial Road Div. Date and time of information received. 250.5.2022 at opp 40 pm. Again to Sarapara Road J Again to Sarapara Date of occurrence- 22.05.2022 Length/dimension- Length affected 20.00 m (at 5th Kth) HPC Clamaged and breuched about 20.00 h. Department- Gealpara West and Jaleswar Territorial Road Div. Date and time of information received- 23.05.2022 at 09.07 pm. HPC Clabvert on Barumdanga Lempara Road Barumdanga Lempara Date of occurrence- 22.05.2022 at 09.07 pm. HPC Clabvert on Barumdanga Lempara Road Barumdanga Lempara Date of occurrence- 22.05.2022 Length/dimension- Culvert damaged at Ch. 3400.00 M Average depth of submergence- 25.00 cm Department- Geological west Territorial Road Div. Date and time of information received- 23.05.2022 at 09.07 pm. Lakhipur - Kesrapara Charidi to Kolabari affected length 2 KM by overflowing water of rain water from 22.05.2022 to ill date 23.05.2022. Lakhipur to Jaleswar Road Al Rajimita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 22.05.2022 to ill date 23.05.2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22.05.2022 to ill date 23.05.2022. Karimganj - FN ROAD TO BHEDRANO PT IL PAGES V PKG NO.28 13.207 BARTHEDRANO DUE TO INCESSANT RAIN PKG REFLEATER DUE TO INCESSANT RAIN PKG RASTT PAKCHITUP AFFECT PAKCHIT			
Ch. 1900.00M) Average depth of submergences—30.00 cm Culvert damaged Report received from Department—Goalpara West and Jaleswar Territorial Road Div. Date and time of information received—23.05.2022 at 09.07 pm. Agia to Sampuran Road Agia to Sampura Date of occurrences—22.05.2022 Length/dimension—Length affected 20.00 m (as 5th KM) HPC damaged and breached about 20 M. Department—Goalpara West and Jaleswar Territorial Road Div. Date and time of information received—32.02 at 09.07 pm. 14 PPC Culvert on Bamundanea Lempora Road Bamundanega Lempora Date of occurrences—22.05 cond to Department—Goalpara West and Jaleswar Territorial Road Div. Date and time of information received—23.05 2022 at 09.07 pm. 15 Lakipur - Kesnapiara Chariali to Kolabari affected length 2 KM by overflowing water of rain water from 22045/2022 to ill date 23005/2022. 16 Lakipur - Kesnapiara Chariali to Kolabari road Near Kesnapiar The approach road of PWD department Lakipur to Jaleswar Road Al Rajimital The approach road of PWD department Lakipur to Jaleswar Road Al Rajimital The approach road of PWD department Lakipur to Road Road Al Rajimital The approach road of PWD department Lakipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22052/2022 to ill date 2305/2022. 15 Lakipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 2205/2022 to ill date 2305/2022. 16 Karimganj - FN ROAD TO BHEDRANG PT ILPMGSY PKG NO-AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 2005/2022. 20 DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 1805/2022. 21 DE ROAD TO RAJIGHAR PT HI RANIGRAM PT II DUE			
Department-Gualpara West and Jaleswar Territorial Road Div. Date and time of information received. 23.05.2022 at 09.07 pm. Agia to Sarapara Road Agia to Sarapara Date of occurrence-22.05.2022 Length/dimension-Length affected 20.00 m (or 5 fts. Mb) HPC damaged and breached about 20 M. Department. Goalpara West and Jaleswar Territorial Road Div. Date and time of information received-23.05.2022 at 09.07 pm. HPC Cubert on Bammadanya Lempara Road Hamundrang Lempara Road Div. Date and time of information received-23.05.2022 at 09.07 pm. HPC Cubert on Bammadanya Lempara Road Hamundrang Lempara The approach road of PWD department Kostapara infected length 25.05.2022 at 09.07 pm. Lakhipur 1 Kesnapara Charial to Kolabari road Near Kesnapara The approach road of PWD department Kesnapara Charial to Kolabari road Near Kesnapara The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 22.05.2022 to till date 23.05.2022. Lakhipur to khalisaviria Road Near Khalisaviria The approach road of PWD department Lakhipur to Kalisavira and Near Khalisavira The approach road of PWD department Lakhipur to Kalisavira and Near Khalisavira The approach road of PWD department Lakhipur to Kalisavira and Near Khalisavira The approach road of PWD department Lakhipur to Kalisavira and Near Khalisavira The approach road of PWD department Lakhipur to Kalisavira Road Near Khalisavira The approach road of PWD department Lakhipur to Kalisavira Road Near Khalisavira The approach road of PWD department Lakhipur to Kalisavira Road Near Khalisavira The approach road of PWD department Lakhipur to Kalisavira Road Near Khalisavira The Approach road of PWD department Lakhipur to Kalisavira Near Road Near Khalisavira The Approach road PWD department Lakhipur to Kalisavira Near Road Near Road			
Agia to Sarapara Road Agia to Sarapara Date of occurrence- 22.05.2022 Length/dimension- Length affected 20.00 (n) (af 15 ft.8b/ HPC damaged and breached about 20 M. Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received- 23.05.2022 at 09.07 pm. HPC Culter on Bamundanga Lempara Road Bamundanga Lempara Date of colorerace- 22.05.3022 Length/dimension- Culvert damaged at Ch. 3400.00 M Average depth of submergence- 25.00 cm Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received- 23.05.2022 at 09.07 pm., Lakhipur - Resrapara Charial to Kolobari affected length 2 KM by overflowing water of rain water from 2205/2022 to ill date 23.05/2022. Lakhipur to Jaleswar Road Af Rajinita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 kM by overflowing water of rain water from 2205/2022 to ill date 23.05/2022. Lakhipur to Shahisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.59 kM by overflowing water of rain water from 2205/2022 to ill date 23.05/2022. Lakhipur to Shahisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita and affected length 0.29 kM by overflowing water of rain water from 2205/2022 to ill date 23.05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita Road Near Khalisavita The Approach road of PWD department Lakhipur to Khalisavita Road Near Khalisavita The Approach road of PWD department Lakhipur to Khalisavita Road Near Khalisavita The Approach road of PWD department Lakhipur to Khalisavita Road Near Khalisavita The Approach road of PWD department Lakhipur to Khalisavita Road Near Khalisavita The Approach road road road road road road road road			
and Jaleswar Territorial Road Div. Date and utime of information received; 2,305,2022 at 09.07 pm, HPC Culvert on Barnundanga Lempara Road Barnundanga Lempara Date of occurrence: 22.05,2022 Lengthdimension- Culvert damaged at Ch. 3400.00 M Average depth of submergence: 25.09 cm Department- Goulparo West and Jaleswar Territorial Road Div. Date and time of information received: 23.05.2022 at 09.07 pm, Lakhipur. Kestapara Charilat io Kolabari road Near Kestapara The approach road of PWD department Kestapara Charilat io Kolabari affected length 2 kM by overflowing water of rain water from 22.05/2022 to ill date 23.05/2022. Lakhipur to Jaleswar Road At Rajmita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 6.96 kM by overflowing water of rain water from 22.05/2022. Lakhipur to Kalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 6.29 kM by overflowing water of rain water from 22.05/2022 to iill date 23.05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 6.29 kM by overflowing water of rain water from 22.05/2022 to iill date 23.05/2022. Karimgani - FN ROAD TO BHEDRANG PTILPRIGSY PKG NOAS 13.207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DANS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21.05/2022. KULCHERRI PWD ROAD TO SEKHILLDHI, AND H.P.CULVERT NO 1/2 SEKHILLDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DANS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18.05/2022. LC ROAD TO KULCHERRI PTI KULCHERRI PTI DUE TO INCESSANT RAIN FOR THE LAST FEW DAN'S THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18.05/2022. LC ROAD TO RANIGERA PTI HI EAAST FEW DAN'S THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS			
and Jaleswar Territorial Road Div. Date and time of information received: 23.05.2022 at 20.5 2022 Length/dimension- Culvert damaged at Ch. 340,000 M Average depth of submergence-25.00 cm Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received: 23.05.2022 at 19.07 pm. Lakhipur - Resrapara Charial to Kolabari road Near Kesrapara The approach road of PWD department Kesrapara Charial to Kolabari road Near Kesrapara The approach road of PWD department Kesrapara Charial to Kolabari rafected length 2 kM by overflowing water of rain water from 2205/2022 to till date 23.05/2022. Lakhipur to Jaleswar Road Ar Rajmita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 kM by overflowing water of rain water from 2205/2022 to till date 23.05/2022. Lakhipur to Shalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 kM by overflowing water of rain water from 2205/2022 to till date 23.05/2022. Karingan - Fr ROAD TO BHEDRANG PT II,PMGSY PKG NO-AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 2005/2022. DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21.05/2022. KULCHERRI PWR DAO AD TO SEKHILUDH, AND HE PCULVERT NO 12 SEKHILUDH1 DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 1805/2022. LC ROAD TO KULCHERNI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 1805/2022. ENGINEER WAS STILLE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE W			
HPC Culvert on Bamundanga Lempara (Date of occurrence-20.5 (2022 Length/dimension - Culvert admaged at Ch. 34/00.00 M Average depth of submergence-25.00 cm Department-Goalpara West and Jaleswar Territorial Road Div. Date and time of information received-23.05.2022 at 69.07 pm, Lakhipur-Kesrapara Charilat lo Kolabari affected length 2 KM by overflowing water of rain water from 22.05.2022 to ill date 23.05.2022. Lakhipur to Jaleswar Road At Rajimita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 22.05.2022. Lakhipur to Jaleswar Road Near Khalisavita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.29 KM by overflowing water of rain water from 22.05.2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22.05.2022 to till date 23.05.2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita The Approach road of PWD department Lakhipur to Khalisavita The Approach road of PWD department Lakhipur to Khalisavita The Approach road of PWD department Lakhipur to Khalisavita The Approach road of PWD department Lakhipur to Khalisavita The Approach road of PWD department Lakhipur to Khalisavita The Approach road of PWD department Lakhipur to Khalisavita The Approach road of PWD department Lakhipur to Khalisavita The Approach road of PWD department Lakhipur to Jaleswar The Approach road of PWD department Lakhipur to Jaleswar The Approach road of PWD department Lakhipur to Jaleswar The Approach road of PWD department Lakhipur to Jaleswar The Approach road of PWD department Lakhipur to Jaleswar The Approach road of PWD department Lakhipur to Jaleswar The Approach road road pwd road Nakhipur to Jaleswar The Approach road road Nakhipur Day Nakhipur The Approach road road road Nakhipur			
22.05.2022 Lengthdimension- Culvert damaged at Ch. 3400.00 M Average depth of submeregence-25.00 on Department. Goodpara West and Jaleswar Ferritorial Road Div. Date and time of information received: 23.05.2022 at 09.07 pm. Lakhipur - Kesrapara Chariali to Kolabari road Near Kesrapara The approach road of PWD department Kesrapara Chariali to Kolabari road Near Kesrapara The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.90 KM by overflowing water of rain water from 2205/2022 to till date 23.05/2022. Lakhipur to Isleswar Road Near Khalisavita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.90 KM by overflowing water of rain water from 2205/2022 to till date 23:05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22:05/2022 to till date 23:05/2022. Karimgan FNR ROAD TO BHEDRANG PT ILPMGSY PKG NO:AS 13:207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWBO ON 2005/2022, DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWBO ON 2005/2022, UKUCHERRI PWB ROAD TO SEKHILLUDHI, AND BH PCULVERT NO 12 SEKHILLUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWBD ON 18:05:2022, LC ROAD TO KULCHERRI PTI IKULCHERRI PTI IDUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWBD ON 18:05:2022, BAGABARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur reported damage to the said road where earthen shoulder, emb	Coolmono	7	*
25.00 cm Department-Goalpara West and Jaleswar Territorial Road Div. Date and time of information received-2 305.2022 at 09.07 pm. Lakhipur - Kesrapara Chariali to Kolabari aracted length 2 KM by overflowing water of rain water from 2205/2022 to tild date 2305/2022. Lakhipur to Jaleswar Road Ar Rajmini The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 2205/2022 to tild date 2305/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to tild date 23/05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to tild date 23/05/2022. Karingan - FN ROAD TO BHEDRANG PT II, PMGSY PKG NO:AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD OO 21/05/2022. DIGALBAGHROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD OO 31/05/2022. KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD OO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROAD TO KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROAD S WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022. LC ROAD TO KULCHERRI PT II KILCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT	Goaipara	'	
information received- 23 05 2022 at 09.07 pm. Lakhipur - Kesrapara Chariali to Kolabari road I Near Kesrapara The approach road of PWD department Kesrapara Chariali to Kolabari affected length 2 KM by overflowing water of rain water from 22/05/2022 to ill date 23/05/2022. Lakhipur to Jaleswar Road At Rajmita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 22/05/2022 to ill date 23/05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to ill date 23/05/2022. Karimganj - FN ROAD TO BHEDRANG PT II,PMGSY PKG NO:AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWBD ON 20/05/2022. DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWBD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 [SEKHILUDHI] DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWBD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III [RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III [RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT X,			
Lakhipur - Kesrapara Chariali to Kolabari froed Near Kesrapara The approach road of PWD department Kesrapara Chariali to Kolabari affected length 2 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022., Lakhipur to Jaleswar Road Ar Rajinita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Karimganj = FN ROAD TO BHEDRANG PT IL PMGSY PKG NO.AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 2.005/2022. DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 2.105/2022. KULCHERRI PWD ROAD TO SEKHIL UDHI, AND H.P.CULVERT NO 1/2 SEKHILLIDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022. LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022. LC ROAD TO KUNCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022. LC ROAD TO KUNCHERRI PT III KUNCHERRI PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022. LC ROAD TO KUNCHERRI PT III ROAD BAR			
department Kesrapara Chariali to Kolabari affected length 2 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Lakhipur to Jaleswar Road At Rajmita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Karimganj - FN ROAD TO BHEDRANG PT II,PMGSY PKG NO:AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 20/05/2022. DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022. KULCHERRI PWD ROAD TO SEKHLUDHI, AND H.P.CULVERT NO 1/2 SEKHLUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 1/2 SEKHLUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur -BADABRUR AND RAIN PROTECTION OF THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur -BADABRUR ADARKUNA ROAD TO BARTHAL PT XII VANAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII ON 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported			
Lakhipur to Jaleswar Road Al Rajmita The approach road of PWD department Lakhipur to Jaleswar Road Affected length 0.50 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Karimganj - FN ROAD TO BHEDRANG PT II,PMGSY PKG NO-AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWBO DO NO.05/2022. DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD DO 12/05/2022, KULCHERRI PWID ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ENDOYER OADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022. LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022. LC ROAD TO RAIGRAM PT III RULCHERRI PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022. Karimgan j 10 10 EXAMINE AND ASSTER EXECUTIVE ENGINEER, PWRD ON 18/05/2022. Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII OA NGARSIGOOL, PKG AS-13-197 BARTHAL PT XII OA 19-05-2022, ASSIL EXECUTIVE ENGINEER, PWRD ON 18/05/2022. BADARPUR ADARRUNA ROAD TO BARTHAL PT XI, PT X, PT AS-124 Barthal PT X I OA 19-05-2022, ASSIL EXECUTIVE ENGINEER, PWRD ON 18/05/2022. BADARPUR ADARRUNA ROAD TO BARTHAL PT X, PK GA S-13-201 BARTHAL PT X I OA 19-05-2022, ASSIL EXECUTIVE E			
Road Affected length 0.50 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Karimganj - FN ROAD TO BHEDRANG PT IL.PMGSY PKG NO-AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 20/05/2022, DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROAD WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, EVER DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, DRAINGAM PT III DRAINGAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, ASST. EXECUTIVE ENGINEER, PWRD ON			
23:05:2022. Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22:05:2022 to till date 23:05:2022. Karimganj - FN ROAD TO BHEDRANG PT IL-PMGSY PKG NO-AS 13:207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 20:05:2022. DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21:05:2022, KULCHERR PWD ROAD TO SEKHHLUDHI, AND H.P.CULVERT NO 12 SEKHHLUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE BEDOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18:05:2022. LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18:05:2022. LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18:05:2022. LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18:05:2022. ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18:05:2022. ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE RANIGRAM PT III DUE TO INC			
Lakhipur to Khalisavita Road Near Khalisavita The approach road of PWD department Lakhipur to Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Karimgan FN ROAD TO BHEDRANG PT II.PMGSY PKG NO-AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 20/05/2022, DIGALBAGH ROAD DIGALBAGH FOOD TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-19 JBARTHAL PT XII ON 19-05-2022, ASSTT. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 375 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, ASSTT. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-201 BARTHA			
Khalisavita road affected length 0.29 KM by overflowing water of rain water from 22/05/2022 to till date 23/05/2022. Karimganj - FN ROAD TO BHEDRANG PT II.PMGSY PKG NO:AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 20/05/2022, DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XI IVIA NAGARSIGOOL, WE ASSERT A STREAM OF THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur BADARPUR ADARKUNA ROAD TO BARTHAL PT XI IVIA NAGARSIGOOL (POS) BADARPUR ADARKUNA ROAD TO BARTHAL PT XI IVIA NAGARSIGOOL, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On			
date 23/05/2022. Karinganj - FN ROAD TO BHEDRANG PT II,PMGSY PKG NO:AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 20/05/2022, DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, ASSTT. EXECUTIVE ENGINEER, PWRD, Badarpur Territorial Road Sub-Division, Badarpur			
Karimganj - FN ROAD TO BHEDRANG PT II,PMGSY PKG NO:AS 13 207 BHEDRANG DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 20/05/2022, DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, BAGARDY AND SAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, BAGARDY AND SAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, BAGARDY AND SAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, BAGARDY AND SAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, ASSTT. EXECUTIVE ENGINEER, PWRD DARBYD AND ARBYD ARBY			
TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED PARTIALLY AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 20.05/2022, DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21.05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18.05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18.05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18.05/2022, Badarpur -BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PRG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 375 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Exec			
EXECUTIVE ENGINEER, PWRD ON 20/05/2022, DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHLUDHI, AND H.P.CULPERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1875 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen s			TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED
DIGALBAGH ROAD DIGALBAGH DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADAVENDA BOAD TO BARTHAL PT XII NA NAGARSIGOOL, PKG AS:13-197 BARTHAL PT XII TO 119-05-2022, ASST. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, BADARPUR ADARKUNA ROAD TO BARTHAL PT XII NA NAGARSIGOOL, PKG AS:13-197 BARTHAL PT XII TO 19-05-2022, ASST. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, ASST. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, ASST. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, ASST. Executive Engineer, PWRD, Ba			
THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, BADAPRUP ADARRUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported dama			
SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 21/05/2022, KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PW			
KULCHERRI PWD ROAD TO SEKHILUDHI, AND H.P.CULVERT NO 1/2 SEKHILUDHI DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PRG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M , BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19- 05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Camp; amp; Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur report			
DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged. TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, LC ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19- 05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
LC ROAD TO KULCHERRI PT II KULCHERRI PT II DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Surpart Proported damage to the said road where earthen shoulder, embankment, Surface & Surpart Proported damage to the said road where earthen shoulder, embankment, Surface & Surpart Proported damage to the said road where earthen shoulder, embankment, Surface & Surpart Proported damage to the said road where earthen shoulder, embankment, Surface & Surpart Proported damage to the said road where earthen shoulder, embankment, Surface & Surpart Pro			DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT.
LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M , BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Devision, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Devision, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Devision, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Devision, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Devision, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Devision, Badarpur reported damage to			EXECUTIVE ENGINEER, PWRD ON 18/05/2022,
MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, L.C ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & amp; amp; Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
Karimgan j 10 L.C ROAD TO RANIGRAM PT III RANIGRAM PT III DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19- 05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & mp; amp; Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
Karimgan j LAST FEW DAYS THE ABOVE ROADS WAS DAMAGED AT VARIOUS STRETCHES AS WT MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19- 05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Empiremy; Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
Karimgan j MESSAGE WAS SUBMITTED BY ASSTT. EXECUTIVE ENGINEER, PWRD ON 18/05/2022, Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19- 05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
Rarimgan j Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT XII VIA NAGARSIGOOL, PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Emp; amp; Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
PKG AS-13-197 BARTHAL PT XII On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to	Karimgan	10	
embankment and edge resistances etc. were damaged from Ch 2350 to 2625 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19- 05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Emp; Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to		10	
BADARPUR ADARKUNA ROAD TO BARTHAL PT X, PKG AS-13-245 Barthal Pt X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Division, Badarpur Tomaged, TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Emp; amp; Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Delvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
damaged from Ch 575 M to 950 M, BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Delvet No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
BADARPUR ADARKUNA ROAD TO BARTHAL PT XI, PKG AS-13-201 BARTHAL PT XI On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Delvision, Badarpur Road Sub-Division, were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Devertor No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
Badarpur reported damage to the said road where earthen shoulder, embankment and edge resistances etc. were damaged from Ch 1800 M to 1950 M, BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Delvision, Colvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
BADARPUR ADARKUNA ROAD TO TAJURTHAL TAJURTHAL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Division, Badarpur No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to the said road where earthen shoulder, embankment, Surface & Division, Badarpur Ro. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
the said road where earthen shoulder, embankment, Surface & Damp; Culvert No. 2/3 at 2 K.M were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
were damaged., TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
TAJURTHAL ROAD TO NAGARSIGOOL ROAD NAGARSIGOOL On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			
Executive Engineer, PWRD, Badarpur Territorial Road Sub-Division, Badarpur reported damage to			

			Mayong - Karatipam Bazar to Chotogarjan Road Submerged at 2nd kms As reported by PWD
	Morigaon	1	District Territorial Road Division on 23/05/22
			Kampur - Garubandha to Dabblong Kampur Garubandha to Dabblong, PMGSY, Package No. AS-19-421 Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022,
			L088-KSB Road to Pachim Birinati Kampur L088-KSB Road to Pachim Birinati, PMGSY, Package No. AS-19-425, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022,
			Maikolong to Gauranga ati Road Kampur Maikolong to Gauranga ati, PMGSY, Package No. AS-19-429, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022,
			Simaluguri to Marisuti Kampur Simaluguri to Marisuti, PMGSY, Package No. AS-19-435, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022, Missamari to Gaurangapar Kampur Missamari to Gaurangapar, PMGSY, Package No. AS-19-436, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022, Simaluguri to Pramila Basti, PMGSY, Package No. AS-19-461 Kampur Simaluguri to Pramila Basti, PMGSY, Package No. AS-19-461, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022, Puthimari to Puthimari I Kampur Puthimari to Puthimari I, PMGSY, Package No. AS-19-634, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022, L068-Kumbhi dubi to Chirapathar Kampur L068-Kumbhi dubi to Chirapathar, PMGSY, Package
	Nagaon	17	No. AS-19-462, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022, Nagaon-Dakhinpat-Kampur Road to Kolaikhuwa Kampur Nagaon-Dakhinpat-Kampur Road to
			Kolaikhuwa, PMGSY, Package No. AS-19-305, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022, Bamunigosain Than To Noipam Via Bengena Ati Kampur Bamunigosain Than To Noipam Via
			Bengena Ati, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022,
			Sengmora Road to Kachupit Kampur Sengmora Road to Kachupit, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022,
			Borhula to Telia ati Road Kampur Borhula to Telia ati Road, Submerged/Damaged reported by PWD Barhampur Territorial Road Sub-Division, Dtd-22.05.2022, Solmari to kamalchuk kampur Solmari to kamalchuk, Submerged/Damaged reported by PWD
			Barhampur Territorial Road Sub-Division, Dtd-22.05.2022, Nagaon - Nonoi Dakhinpat Road to Burhaguhainthan, Burhaguhainthan, Nagaon Nonoi Dakhinpat
			Road to Burhaguhainthan , Length -5M, Date-22/5/2022, PWRd Nagao Territorial Road Sub- Duvision,
			Raha - Phulaguri to Haibar Gaon dyke Phulaguri Garmari village Date of Occurence-22/05/2022 Leakage, Seepage and boiling-15 m Department- Raha Water Resources Sub -Division, Raha, Phulaguri to Mulankatra R/B dyke Durgajan Date of Occurence-22/05/2022 Breach like damage-25 m Department- Raha Water Resources Sub -Division, Raha,
			Raha to Chaparmukh dyke Titaimari Channel Date of Occurence-22/05/2022 Crest depression-10 m Department- Raha Water Resources Sub -Division, Raha
			Paschim Nalbari - Gadira SC Supa link road Village Gadira Length 1750.00 m. Side beam eroded, edge restrains with BP damaged due to heavy rain fall. Information received from PWRD dwpartment on 22/05/2022 via WhatsApp.,
	Nalbari	lbari 2	Bangaon Bagurihati Chupa to Simaliya road, Bagurihati village Side beam eroded and restrains in damage due to heavy rain fall in many stretches. Information received from EE, PWRD, Nalbari
			District Territorial Road Division, Nalbari on 21/05/2022 via WT message on today i.e 23/05/2022 Naduar - As per report submitted by Asst. Executive Engineer, PWD Sootea Territorial Road Sub-Division on 22/05/2022, Total no. of road affected-5 nos. Name of the road affected-1. Dhalaibil
	Sonitpur	6	Jamuguri road (Length affected- CH. 4300.00m to CH.6300.00m=2.00 k.m.) 2. Jamuguri Higher Secondary to Nandikeswar approach road (Length affected-Ch.0.00 m to CH.1500.00m=1.50k.m.) 3. Madhab Nandikeswar road(Length affected-CH.0.00m to CH.200.00m=0.20km)4. Borigaon to Uperkuri road(Length affected-CH.1100.00m to CH.2100.00m=1.00 k.m), Length of damaged road=4.70 k.m. Naduar ,
			Chariduar - ROAD SIDE EMBANKMENT AT 3RD KM OF RANGAPARA HARCHURA TO BALIPARA KHELMATI ROAD ERODED BADLY AND CLVERT NO 3/1 ALSO DAMAGED BADLY DUE TO HEAVY INCESSANT RAIN LENGTH OF ERODED PORTION 15.00 m REPORTED BY PWD RANGAPARA TERROTORIAL ROAD DIVISION BALIPARA dtd 23/05/2022 CHARIDUAR
	Total	81 Numbe	
I C	District	Numbe r	Details
Infrastructur e Damaged - Bridge	Barpeta	1	Sarthebari - SPT Bridge of Kaljahi Village Kaljahi Burikhamar Bajar to Kaljahi Bridge SPT bridge damaged road side approx. 300m & approach side damaged approx. 60 m. (reported by JE, PWD Road, 23.05.2022)
	Darrang	1	Dalgaon - SPT BR NO.1/1 SPT BR NO.1/1 on jogipara to fakirpara road has been damaged due to

	V	flood. as per report received from Executive Engineer, PWRD, Mangaldai & Dalgaon Territorial road division, Mangaldai, SPT BR NO.1/1 on jogipara to fakirpara road has been damaged due to flood at CH-40M, L-27M(Approx), Date of occurrence -16/05/2022 Badarpur - BADARPUR ADARKUNA ROAD TO BARTHAL PT X, BRIDGE NO. 1/3					
	Karimgan j	BARTHAL PT X On 19-05-2022, Asstt. Executive Engineer, PWRD, Badarpur TR Sub-Division,					
	Nalbari	Badarpur reported damaged to the said bridge No. 1/3 at Ch. 990 M. Paschim Nalbari - SPT BR. No. 1/1 on Balizar Mahzid Chowk to Shaniroad via Phulguri over Phulguri Jan Phulguri village Damaged length 30.00 m. Information received from EE, PWRD, Nalbari District Territorial Road Division, Nalbari on 21/05/2022 via WT message on today i.e 23/05/2022, Bamboo foot bridge at phulguri Village Phulguri. Damaged on Phulguri LP School to Baragopal Than L-35 M. Information received from EE, PWRD, Nalbari District Territorial Road Division, Nalbari on 21/05/2022 via WT message on today i.e 23/05/2022, RCC Bridge No. 1/1 at Baralia Lokhopur road via Sasabori Lokhopur Approaches damaged. Information received from EE, PWRD, Nalbari District Territorial Road Division, Nalbari on 21/05/2022 via WT message on today i.e 23/05/2022					
- 4	Total	6					
Infrastructur e Damaged - Wildlife	Nil						
	District	Other Details					
	Barpeta	Barnagar - Bridge Approach Road Damaged As per Wt message received from EE, PWD Sorbhog & Samp; Jania Territorial Road Divn, dtd. 23/05/2022 Surface damages on Sorbhog Kalgachia Bridge approach of Bridge No. 3/1 on Roha Bagulamari Road side berm eroded on both side due to heavy rain fall. Approach ength= 200.00M Breadth= 1.5M. Long= 90.830154, Lat= 26.440337., Agri Bundh Damaged As per report received from Kalgachia Dev block Office, dtd. 22/05/2022 Const. of Earthen field bundh start from PMGSY road to Mazibur Rahmanhouse at vill- Dharmapur damaged due to heavy rainfall. Length=200M, Breadth= 1.00M. Height= 0.6M Long= 90.863857, Lat= 26.417019					
	Cachar	Lakhipur - Power Dept. Poles 3 nos of HT PSC pole 9.75m & 4 nos of LT PSC poles 7.5m, Damage due to Flood at Digli Bahadurpur, Omednagar, Binnakandi, Hatirhar and adjoining areas. as per report received from APDCL Department on 20.05.2022, Power Dept. Transformers 1 no of 25KVA transformer & 1 no of 16KVA transformer Damage due to Flood at Digli Bahadurpur, Omednagar, Binnakandi, Hatirhar and adjoining areas. as per report received from APDCL Department on 20.05.2022, Silchar - Power Dept. Transformers 63KVA transformer 1 no. (due to inundation by flood) Vill Krishnanagar on 20.05.222					
	Darrang	Mangaldoi - Handloom & Textile Deptt As reported by Handloom & Department a total of 295 Nos. of weavers were affected due to flood as on 19/05/2022. The report is received on 23/05/2022., Dalgaon - Washed away Culverts As per report received from SDO, PWRD, Dalgaon Territorial Road sub division, NH-15 to borghuli road single HPC wash away. L-15m date of occurrence - 16/05/2022					
Infrastructur e Damaged - Others	Hojai	Hojai - PWSS Damaged Vill- Alinagar , Distribution pipe line,FHTC,UGR ,TP,filter media & pump sets are damaged on dated 22/05/2022 with GPS coordinates 26.0342 N And 92.67543 E , PWSS Damaged Vill- Fatehpur, Distribution pipe line , FHTC, UGR,TP,filter media & pump sets are damag on dated 22/05/2022 with GPS coordinates 26.0562 N and 92.69721 E, PWSS Damaged vill- Taradubi, Distribution pipe line , FHTC,UGR, TP,filter media & pump sets are damage on dated 22/05/2022 with GPS coordinates 26.09171 N and 92.8239 E, PWSS Damaged vill- Kacharibasti, Distribution pipe line,FHTC,UGR,TP.filter media & pump sets are damage on dated 22/05/2022 with GPS coordinates 25.9932 N and 92.81232 E					
	Karimgan j	Karimganj - Elementary Schools Damaged 654 NO. VIVEKANANDA VIDYANIKETAN,E & Emp; D COLONY, KARIMGANJ WAS AFFECTED DUE TO INCESSANT RAIN AND ARTIFICIAL FLOOD HAVE BEEN CREATED AT SCHOOL, AS A RESULT FLOOR OF THE CLASS ROOM, FURNITURE AND UTENSILS OF MDM HAVE BEEN DAMAGED WHICH WAS SUBMITTED BY HEAD TEACHER OF SAID SCHOOL ON 21/05/2022					
	Morigaon	Morigaon - Elementary Schools Damaged (22-05-2022) RUPAIBORI ANCHALIK RN DAS ME (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) BHUGDUBA BEEL LP (E) (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) MANTABORI LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) SILBHETA LP (E) (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) SILBHETA LP (V) (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) NO 1 MATIPARBAT LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) NO 2 MATIPARBAT LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) MATIPARBAT LP (E) (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) BORAMARI KOLBARI LP (V) (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) DAMAL TELAHI ME (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) DAMAL LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) DAMAL LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) DAMAL LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) BAKARI CHAPARI LP (E) (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) BAKARI CHAPARI LP (E) (PARTIALLY SUBMERGED),					

		Elementary Schools Damaged (22-05-2022) MULADHARI LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) NO 2 PALAHGURI LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) 1 NO GUNAMARA LP (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) 2 NO GUNAMARA LP (PARTIALLY SUBMERGED),
		Elementary Schools Damaged (22-05-2022) THEKERAGURI JANAJATI LP (E) (PARTIALLY SUBMERGED), Elementary Schools Damaged (22-05-2022) BASUNDHARI PANJEGANA LP (E) (PARTIALLY GURDAGED)
		SUBMERGED), Mayong - Elementary Schools Damaged lecharipar pam lp (E) partially submerged as reported by concerned LM on 23/05/22
	Nalbari	Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Deptt Nalbari via whatsapp group on 23.05.2022, Slab culvert damaged at kajipara tum Suburi. Approximate length 21.9 M
	Udalguri	Harisinga - Power Dept. Poles LT and HT poles at village No.4 Rajagarh damaged on 13/05/2022. under Tangla electrical sub-division, Power Dept. Conductors Conductors were snapped at various places like Villages No.4 Rajagarh, No.2
	District	Rajagarh, Badlapara, Uttar Garuajhar, Purani Tangla on 13/05/2022 under Tangla electrical sub-division Details
	District	Kalgachia - 1. Shawrachara Gaon, 2. Kharballi vill, 3. Isabpur vill, 4. Chatala NC vill, 5. Patharchali vill, 6.Kharballi vill 1. As per report received from BDO, Rupshi on 22/05/2022(evening), ShantiBazar to Shawrachara vill road eroded by river Beki(L=200m, B=4m, H=1.50m), location coordinates - 26.2644500,
	Barpeta	90.829638. 2. As per report received from BDO, Rupshi on 22/05/2022(evening)Flood protection bundh st. from Sanowar Hussain house to Rahij Uddin house eroded by river Beki in Kharballi vill (L=70m, B=3.75m, H=1.50m), location coordinates- 26.357375, 90.891429. 3. As per report received from BDO, Rupshi on 22/05/2022(evening), Boundary wall of Isabpur LPS, Isabpur partially eroded by river Manas (L=20m), location coordinates- 26.279483, 90.734919. 4. As per report of concerned LM on 23/05/2022, 12 nos of KUTCHA houses are eroded in Chatala NC vill, Family affected-12 nos, Basti land eroded- 6B-2K-0L, Agril land eroded- 9B-1K-10L, location coordinates- 26.24693, 90.64455. 5. As per report of concerned LM on 23/05/2022, 8 nos of KUTCHA houses are eroded in Patharchali vill, Family affected-8nos, Basti land eroded- 4B-2K-10L, Agril land eroded- 3B-3K-10L, location coordinates- 26.179907, 90.606059. 6. As per report of concerned LM on 23/05/2022, 1 no of PUCCA house (PMGAY house) is eroded in Kharballi vill, Family affected-1 no, Basti land eroded- 0B-1K-05L, location coordinates- 26.354496, 90.889913. 95, Chenga - Roumari Pathar, Roumari Gaon, Kachumara 11 nos. houses eroded by the river Brahmaputra at
	Biswanat	Roumari Gaon, Kachumara village on 22.5.22 reported by Gaon Pradhan. Total 3300 nos. water pouch were distributed among erosion affected families by PHE deptt. on 22/5/22 54 Naduar RC part - No-2 Bhojmari Active bank erosion at No-2 Bhojmari area on right bank of river
Erosion	h Dhubri	Brahmaputra, Length=400m, on 23.05.2022. Reported by water resource dept. 0 Bilasipara - at village Chinamari gaon Erosion occurred due to rising of water level of river Gaurang at village:- Chinamari gaon.Date of incident:- 20-05-2022 and 21-05-2022 Land eroded:- Land measuring around 0 Bigha 02 Katha 05 Lessa 9, Athani - Katlamari Pt-IV Erosion is going on at village Katlamari Pt-IV by River Brahmaputra from 13.5.2022 to 23.05.2022 under Podmer Alga GP. As per field verification it is seen that patta land measuring 6B-0K-10L of 6 Nos. of families have been eroded. All the families have been shifted to their another lands. It is also to be mentioned that land measuring 20B-2K-9L of Govt. Khas land has also been eroded. No families have become landless due to the erosion and situation for opening relief camp has not arises yet. 30
	Dibrugarh	Moran - Borbeel Khalihamari area As per WRD report Flood damages is Occurring at Borbeel Khalihamari area, length affected - 500 m, Lat N27. 2739 Long E94. 8269 as on 23/05/2022 which may affect DRDA ring bund and PWD road at an offset of 40m. 0
	Goalpara	Matia - Baladmari Char Pt-IV Left Bank erosion of river Jaljali at Baladmari Char Pt-IV. Total reach length = 150 m (approx.) and Average width = 1.5 m as on 23/05/2022 as received from Water Resources Department, Goalpara. 0
	Golaghat	Morongi - L/bank of river Dhansiri at Mithaam Chapori and Moinapara A)U/S of protection work Longitude: a) 90.505927E Latitude: a) 26.342950N Remarks: Bank erosion on the left bank of river Dhansiri at U/S of geo bag protection work for length of 50m on 23.05.2022 B) D/S of protection work Longitude: a) 90.505152E Latitude: a) 26.344223N Remarks: Bank erosion on the left bank of river Dhansiri at D/S of geo bag protection work for length of 500m on 23.05.2022 C) U/S of RCC bridge at Moinapara Longitude: 93.95179 Latitude: 26.504077 Remarks: Bank erosion on the left bank of river Dhansiri at U/S of RCC bridge at Moinapara area for length of 700m on 23.05.2022 0
	Nalbari	Nalbari - Village Moiradanag As per the report received from W.R Deptt, Nalbari via whatsapp group on 21.05.2022, in Right Bank of River Pagaldia at Village Moiradanga erosion takes place. But by mistakenly concern deptt had mention the name of village Goiroimara instead of Moiradanga. And report was already given in FRIMS on 22.05.2022. Approximate length of erosion 600M 0, Barkhetri - Bhangnamari River bank erosion of river Brahmaputra at Bhangnamari. Length 500m approx. Date 23/05/2022. Shifting Bhangnamri Ps, PWD(B) IB AND COMMUNITY HALL, Laupara Bhangnamri LPS, Madhyakamrup milan HS, 16 houses shifting, 30 shops shifting due to erosion. 130
	Sivasagar	Demow - Makhowabari Erosion at Desang bund right bank for a length 150 metre due to rise of water level from 22/5/2022 to 23/5/2022. The report has been received from WR Divison, Demow under Demow RC 0, Sivsagar - Barichuk Sloughing and river bank erosion has been observed on 20-05-2022 at Ch 11600 M to Ch 11620 of LB of Dikhow bund from AT Road to Namdungoutfall (At Barichuk) under Sivasagar Revenue Circle.

		As per report received from WR department, Sivasagar. 0
	a	Thelamara - Village- Bhara Singri Severe bank erosion occured at L/Bank embankment of river Belsiri at
	Sonitpur	Bhara Singri at Ch 3700 m to 3800m as reported by Water Resource deptt. on 23/05/2022. 0
	Tinsukia	Sadiya - 1. Koilabasti, 2. Gurungbasti, 3. Sunpura purona bazar, 4 sunpura nadikinar, 5. 8th mile. 1. Active erosion is reported from Koilabasti area by Kundil river since 12/05/2022 till 23/05/2022. As per report received from the WR department and concerned Gaon Pradhan, the stretch area is 50m. (Lati 27.84688889, Long 95.71255556) 2. River bank erosion at Gurung Basti area since 15/05/2022 till 23/05/2022. As per report by WR department, the stretch area is 50m. (Lati 27.89750000, Long 95.77833333) 3. Active erosion at Sunpura Purana Bazar by Balijan river since 20/05/2022 till 23/05/2022. As per report by WR department, the stretch area is 70m. Location(Lati 27.84849444 N, Long 95.89472222 E). 4. Active erosion at Sunpura Nadikinar by Balijan river since 19/05/2022 till 23/05/2022 As per report by WR Dept, the stretch area is 100m. Location (Lati 27.84161944 N, Long 95.88021389 E). 5. Active erosion at 8th Mile by Kundil river under the bridge since 18/05/2022 till 23/05/2022. As per report by Gaon Pradhan the stretch area is 30m. Location (Lati 27.86722222 N, Long 95.76000000 E). 0, Domdooma - 1. Village: No. 3 Kordoiguri (Goriyating), 2. Village: No. 1 Kordoiguri(Darjijan), 3. Village: No. 2 Kordoiguri (Simoluguri Satra). 1. River Bank erosion is being observed at No. 3 Kordoiguri on the left Bank of River Brahmaputra (Ananta Nallah) since 2/04/2022 till 23/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 200 m in length. (Long: 95.468184, Lati: 27.650410), population affected 122. 2. River Bank erosion is being observed at No. 1 Kordoiguri (Dorzijan)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 23/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 300 m in length. (Long: 95.450531, Lati: 27.651217), population affected 37. 3. River Bank erosion is being observed at No. 2 Kordoiguri (Simoluguri Satra)on the left Bank of River Bra
	Udalguri	Udalguri - 1. No. 02 Sonaripara 2. Bhairaguri 3. Baligaon 4. Jharabari 5. Simaluguri 1. Erosion Ocured on the left bank of Kawadanga river at No2 Sonaripara village around 140m on 22.05.2022. GPS - Lat -26.673569 Long - 92.046683. 2. Erosion Ocured on Left Bank of Kawadanga River at Bhairaguri village around 200m on 22.05.2022. GPS - Lat -26.653731 Long - 92.048293 3. Erosion Ocured on Right Bank from River Chandana at Baligaon around 185m on 22.5.2022. GPS - Lat -26.683282 Long - 92.042168 4. Severe Bank from river Kawadanga and Gully Erosion at several points at Jharabari village around 100m altogether on 22.05.2022. GPS - Lat -26.740956 Long - 92.051662 5. Severe Gully Erosion at simaluguri village around 30m on 22.05.2022. GPS - Lat -26.667925 Long - 92.243706 0
Landslide	Nil	
Urban Flood	Nil	