

FRIMS Assam



Flood Reporting And Information Management System

			Agger Dolly El- 1 Day	on 19.05.2022 at 4:00 PM				
Particulars	Situation as o	n 18-05-20	Assam Daily Flood Report as of 22 (in last 24 hours)	DH 10-03-2022 at 4:00 PW				
Rivers	Rivers flowing			(Nanglamuraghat)				
flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing flood level			, vengama og net				
,	No. of Districts	Name of	Flood Affected Districts	Name of Urban Flood Districts				
District Affected	Affected 27	Cachar, C Dibrugarh Hojai, Kar West, Kar	ksa, Barpeta, Biswanath, Bongaigaon, haraideo, Darrang, Dhemaji, n, Dima-Hasao, Goalpara, Hailakandi, nrup, Kamrup (M), Karbi Anglong imganj, Kokrajhar, Lakhimpur, Majuli, , Nagaon, Nalbari, Sonitpur, , Udalguri	Darrang, Nalbari				
No. Of Revenue Circles Affected	70							
	District	Total	Revenue Circle					
	Bajali	1	Bajali					
	Baksa	1	Barama					
	Barpeta	4	Baghbar, Chenga, Sarthebari, Kalgachia					
	Biswanath	4	Halem, Naduar RC part, Gohpur, Biswa					
	Bongaigaon	4	Manikpur, Bongaigaon, Boitamari, Srijangram					
	Cachar	5	Sonai, Lakhipur, Udharbond, Silchar, Katigorah					
	Charaideo	1	Sapekhati					
	Darrang	4	Patharighat, Mangaldoi, Dalgaon, Sipajhar					
	Dhemaji	4	Gogamukh, Dhemaji, Sissiborgaon, Jonai					
	Dibrugarh	1	Chabua					
	Dima- Hasao	1	Haflong					
	Goalpara	1	Rongjuli					
Name Of	Hailakandi	1	Algapur					
Revenue	Hojai	3	Lanka, Hojai, Doboka					
Circles	Kamrup	2	Kayan, Rangia					
Affected	Kamrup (M)	1	Chandrapur					
	Karbi Anglong West	1	Donkamokam					
	Karimganj	2	Badarpur, Karimganj					
	Kokrajhar	2	Kokrajhar, Bagribari					
	Lakhimpur	4	Bihpuria, Nowboicha, North Lakhimpu	ır, Narayanpur				
	Majuli	2	Majuli, Ujani Majuli					
	Morigaon	2	Mayong, Morigaon					
	Nagaon	3	Raha, Kampur, Nagaon					
	Nalbari	7	Banekuchi, Nalbari, Barkhetri, Paschim	n Nalbari, Barbhag, Tihu, Ghograpar				
	Sonitpur	4	Naduar, Dhekiajuli, Chariduar, Tezpur					
	Tamulpur	1	Tamulpur					
	Udalguri	4	Udalguri, Khairabari, Kalaigaon, Harisi	nga				
	Total	70						
	District	Total	Revenue Circle					
	Bajali	12	(Bajali 12)					
	Baksa	1	(Barama 1)	1.1.1144) (%). 1.106)				
Villages	Barpeta	81	(Baghbar 21), (Chenga 13), (Sart					
Affected	Biswanath	66	(Naduar RC part 4), (Gohpur 16),					
	Bongaigaon	76	(Bongaigaon 11), (Manikpur 47),					
	Cachar	288		Lakhipur 16), (Sonai 43), (Katigorah 79)				
	Charaideo	2	(Sapekhati 2)					

	Darrang	142	(Dalgaor	n 45), (Patha	arighat 40), (Sipajhar 16), (Mangaldoi 41)	1				
	Dhemaji	26	(Gogam	ukh 1), (Dhe	maji 1), (Sis	siborgaon 12), (Jonai 12)					
	Dibrugarh	2	(Chabua								
	Dima-	12	(Haflong	. ,							
	Hasao Goalpara	15	(Rongjul	,							
	Hailakandi	1	(Algapur	<u> </u>							
	Hojai	83		(Doboka 23), (Hojai 49), (Lanka 11)							
		35				11 /					
	Kamrup	33	(Kayan	13), (Rangia	22)						
	Kamrup (M)	7	(Chandr	(Chandrapur 7)							
	Karbi Anglong West	5	(Donkan	nokam 5)							
	Karimganj	5	(Badarp	ur 1), (Karim	ngani I 4)						
	Kokrajhar	96	1	ar 18), (Bag							
	Lakhimpur	65				r 1), (Narayanpur 24), (Bihpu	ria I 26 \				
	Majuli	22		18), (Ujani M		11), (Narayanpar 21), (Empa	114 20 /				
	Morigaon	66		g 36), (Mori							
						1.02.)					
	Nagaon	147	1		46), (Kampur		-) / D -	47) (The LC) (Characa			
	Nalbari	72	(Baneku	cni 2), (Bark	netri 20), (N	Nalbari 3), (Paschim Nalbari 1	o), (Barbhag	17), (Tinu 6), (Gnograpar			
	Sonitpur Tamulpur	38 9	(Dhekiaj (Tamulp		luar 2), (Cha	ariduar 9), (Tezpur 15)					
	Udalguri	39	<u> </u>	· ·	gaon I 10 \ / V	hairabari 7), (Harisinga 1)					
	Total	1413	(Oddigui	11 12), (Kalai	gaon 13), (k	inanaban [7), (nansinga [1)					
	District	Male	Female	Children	Total	Population Details	Crop Area (Crop Area Details			
				-	Population		in Hect.)	·			
	Bajali	31	27	4	62	(Bajali 62)	0.00	(Bajali 0.00)			
	Baksa	2	1	0	3	(Barama 3)	0.00	(Barama 0.00)			
	Barpeta	0	0	0	0	(Chenga 0), (Sarthebari 0), (Baghbar 0), (Kalgachia 0)	2599.30	(Chenga 1446.80), (Sarthebari 153.00), (Baghbar 222.00), (
	Biswanath	12828	10580	3874	27282	(Halem 19012), (Naduar RC part 1450), (Gohpur 4036), (Biswanath 2784)	2566.50	Kalgachia 777.50) (Halem 593.00), (Naduar RC part 191.50), (Gohpur 532.00), (Biswanath 1250.00)			
	Bongaigaon	0	0	0	0	(Manikpur 0), (Bongaigaon 0), (Boitamari 0), (Srijangram 0)	951.00	(Manikpur 544.00), (Bongaigaon 197.00), (Boitamari 44.00), (Srijangram 166.00)			
Paralletian	Cachar	47372	39483	32815	119670	(Sonai 10105), (Lakhipur 6740), (Udharbond 1830), (Silchar 30000), (Katigorah 70995)	7424.90	(Sonai 1449.80), (Lakhipur 106.00), (Udharbond 507.50), (Silchar 1137.50), (Katigorah 4224.10)			
Population And Crop	Charaideo	82	57	51	190	(Sapekhati 190)	0.00	(Sapekhati 0.00)			
Area Affected	Darrang	24975	21902	13685	60562	(Patharighat 24395), (Mangaldoi 30390), (Dalgaon 4977), (Sipajhar 800)	7582.60	(Patharighat 366.90), (Mangaldoi 1559.00), (Dalgaon 5388.70), (Sipajhar 268.00)			
	Dhemaji	153	123	53	329	(Gogamukh 71), (Jonai 0), (Dhemaji 258), (Sissiborgaon 0)	387.20	(Gogamukh 0.00), (Jonai 303.60), (Dhemaji 5.00), (Sissiborgaon 78.60)			
	Dibrugarh	1949	1490	1148	4587	(Chabua 4587)	3.50	(Chabua 3.50)			
	Dima- Hasao	770	990	440	2200	(Haflong 2200)	0.00	(Haflong 0.00)			
	Goalpara	0	0	0	0	(Rongjuli 0)	276.20	(Rongjuli 276.20)			
	Hailakandi	290	280	190	760	(Algapur 760)	154.00	(Algapur 154.00)			
	Hojai	56592	36899	13708	107199	(Doboka 53795), (Hojai 46569), (Lanka 6835)	5802.00	(Doboka 874.00), (Hojai 4278.00), (Lanka 650.00)			
	Kamrup	396	299	140	835	(Kayan 416), (Rangia 419)	504.70	(Kayan 242.70), (Rangia 262.00)			
	Kamrup (M)	0	0	0	0	(Chandrapur 0)	778.00	(Chandrapur 778.00)			
	Karbi Anglong	1334	1335	1297	3966	(Donkamokam 3966)	290.00	(Donkamokam 290.00)			

Karimganj 1490 1211 865 3566 Karimganj 3356) Company Compa											
Lakhimpur		Karimganj	1490	1211	865	3566	1		0.00	(Badarpur 0.0 Karimganj 0.0	
Lakhimpur 1594 1433 3290 6317 Lakhimpur 600), (Narayanpur 110), (Bihpuria 4692) 883.20 North Lakhim Narayanpur Bihpuria 25 Majuli 0 0 0 0 (Majuli 0), (Ujani Majuli 193.47 (Majuli 167 Majuli 26.09 Morigaon 0 0 0 (Mayong 0), (Morigaon 0) 2070.69 (Mayong 1) Nagaon 126253 114454 47605 288312 (Raha 56125), (Kampur 9742 57 Kampur 560 170		Kokrajhar	0	0	0	0		, (Bagribari	2060.00	(Kokrajhar 26 Bagribari 179	
Majuli 0		Lakhimpur	1594	1433	3290	6317	Lakhimpur 60 Narayanpur 1	0), (883.20	(Nowboicha North Lakhimpo Narayanpur 4 Bihpuria 258.	ur 4.00), (76.70), (
Morigaon 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Majuli	0	0	0	0		Jjani Majuli	193.47	(Majuli 167.3 Majuli 26.09)	
Nagaon 126253 114454 47605 288312 (Raha 56125), (Kampur 9742 57 Kampur 560		Morigaon	0	0	0	0	(Mayong 0),)	(Morigaon 0	2070.69	(Mayong 127 Morigaon 795	,. ,
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Nagaon	126253	114454	47605	288312	_ ·		9742.57	(Raha 3974.5 Kampur 5600 Nagaon 168.0	57), (.00), (
Nalbari 4492 3558 1275 9325 Sarkhetri 0), (Barbhag 0), (Banekuchi 120), (Banekuchi 120), (Banekuchi 3 Barkhetri 5 Sarkhetri 1241), (Tihu 7964), (Ghograpar 0) O, (Tihu 292)		Nalbari	4492	3558	1275	9325	(Banekuchi 1 Barkhetri 0), Nalbari 1241	20), ((Paschim), (Tihu 7964	1251.00	(Nalbari 15.0 Barbhag 128. Banekuchi 38 Barkhetri 594 Paschim Nalbar), (Tihu 292.0 Ghograpar 31	50), (.50), (.00), (ri 152.00
Sonitpur 2750 2625 2090 7465 894), (Chariduar 4632), (435.60 Chariduar 0		Sonitpur	2750	2625	2090	7465	894), (Charidu	ar 4632), (435.60	(Naduar 151. Dhekiajuli 62. Chariduar 0.0 Tezpur 222.00	60), (0), (
		Tamulpur	0	0	0	0	(Tamulpur 0)	60.00	(Tamulpur 60	
Udalguri 9325 7469 2961 19755 Kalaigaon 11355), (Khairabari 629), (Harisinga 144.00 Kalaigaon 2 Khairabari 0		Udalguri	9325	7469	2961	19755	Kalaigaon 113	355), (144.00	(Udalguri 122 Kalaigaon 22. Khairabari 0.0 Harisinga 0.00	00), (00), (
		Total	292678	244216	125491	662385			46160.43		
		District	Total	Relief Ca	mp			Relief Distribu	tion Centres	<u>'</u>	
Total 292678 244216 125491 662385 46160.43		Bajali	4	0(Bajali	0)			4(Bajali 4)			
Total 292678 244216 125491 662385 46160.43 District Total Relief Camp Relief Distribution Centres		Biswanath	18	2(Halem	2, Naduar RC	part 0, Bisw	anath 0)	16(Halem 9,	Naduar RC part	t 2, Biswanath	5)
Total 292678 244216 125491 662385 46160.43		Cachar	64	•		nar 27, Lakhip	our 5, Sonai	O(Udharbond 0, Silchar 0, Lakhipur 0, Sonai 0, Katigorah 0)			
Total 292678 244216 125491 662385 46160.43		Charaideo	1	0(Sapekh	ati 0)			1(Sapekhati 1)			
Total 292678 244216 125491 662385 46160.43		Darrang	13	0(Manga	ldoi 0, Pathai	righat 0)		13(Mangaldoi 4, Patharighat 9)			
Total 292678 244216 125491 662385 46160.43		Dima- Hasao	4	4(Haflon	g 4)			O(Haflong O)			
Total 292678 244216 125491 662385 46160.43	Relief Camps	Hailakandi	6	2(Algapu	r 2)			4(Algapur 4)			
Total 292678 244216 125491 662385 46160.43	/ Centres		74			1. Lanka 0)		27(Hojai 5, Doboka 17, Lanka 5)			
Total 292678 244216 125491 662385	Opened					_,		0(Rangia 0)			
Total 292678 244216 125491 662385 46160.43		Karbi	-	1(Rangia 1)			O(Rangia I O)				
Total 292678 244216 125491 662385 46160.43			3	0(Donkar					m 3)		
Total 292678 244216 125491 662385 Relief Distribution Centres		West		,	mokam 0)			3(Donkamoka			
Total 292678 244216 125491 662385 46160.43		West Karimganj	9	2(Badarp	mokam 0) our 2, Karimga			3(Donkamokai 7(Badarpur C), Karimganj 7		
Total 292678 244216 125491 662385		West Karimganj Nagaon	9 31	2(Badarp	mokam 0) our 2, Karimga on 5, Raha 2			3(Donkamokai 7(Badarpur 0 20(Nagaon 0), Karimganj 7		
Total 292678 244216 125491 662385 Relief Distribution Centres		West Karimganj Nagaon	9 31	2(Badarp 11(Nagac 0(Naduar	mokam 0) our 2, Karimgs on 5, Raha 2	2, Kampur 4)		3(Donkamokai 7(Badarpur C 20(Nagaon O 2(Naduar 2)), Karimganj 7 , Raha 1, Kam	npur 19)	
Total 292678 244216 125491 662385		West Karimganj Nagaon Sonitpur	9 31 2	2(Badarp 11(Nagad 0(Naduar 2(Khairak	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu	2, Kampur 4)		3(Donkamokal 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari), Karimganj 7 , Raha 1, Kam	npur 19)	Harisinga
Total 292678 244216 125491 662385 46160.43		West Karimganj Nagaon Sonitpur Udalguri	9 31 2 18	2(Badarp 11(Nagad 0(Naduar 2(Khairak Harisinga	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu	2, Kampur 4)		3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1)), Karimganj 7 , Raha 1, Kam	npur 19)	Harisinga
Total 292678 244216 125491 662385 Relief Distribution Centres		West Karimganj Nagaon Sonitpur Udalguri Total	9 31 2 18 248	2(Badarp 11(Nagac 0(Naduar 2(Khairak Harisinga 135	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu	2, Kampur 4)	on 0,	3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1) 113), Karimganj 7 , Raha 1, Kam 2, Udalguri !	pur 19) 5, Kalaigaon 8, I Pregnant / Lactating	Harisinga Person with Disability
Total 292678 244216 125491 662385 46160.43		West Karimganj Nagaon Sonitpur Udalguri Total District	9 31 2 18 248 Total	2(Badarp 11(Nagac 0(Naduar 2(Khairat Harisinga 135 Revenue	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu a 0) Circlewise 52), (Naduar R	2, Kampur 4) uri 0, Kalaigad	on 0,	3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1) 113 Female	D, Karimganj 7 , Raha 1, Kam 2, Udalguri 9 Children	pur 19) 5, Kalaigaon 8, B Pregnant / Lactating Mother	Person with
Total 292678 244216 125491 662385	Inmates In	West Karimganj Nagaon Sonitpur Udalguri Total District Biswanath Cachar	9 31 2 18 248 Total 52	2(Badarp 11(Nagac 0(Naduar 2(Khairat Harisinga 135 Revenue (Halem (Gohpur (Sonai 1) (Udharbo	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu a 0) Circlewise 52), (Naduar R 0), (Biswanat 1013), (Lakhipu ond 27), (Silch	2, Kampur 4) uri 0, Kalaigad RC part 0), th 0) ur 1575),	Male 17	3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1) 113 Female	Children	pur 19) 5, Kalaigaon 8, F Pregnant / Lactating Mother 1	Person with Disability
Total 292678 244216 125491 662385 46160.43		West Karimganj Nagaon Sonitpur Udalguri Total District Biswanath Cachar	9 31 2 18 248 Total 52 11693	2(Badarp 11(Nagac 0(Naduar 2(Khairat Harisinga 135 Revenue (Halem (Gohpur (Sonai 1) (Udharbot (Katigora	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu a 0) Circlewise 52), (Naduar R 0), (Biswanat 1013), (Lakhipu ond 27), (Silch h 3143)	2, Kampur 4) uri 0, Kalaigad RC part 0), th 0) ur 1575),	Male 17 4388	3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1) 113 Female 27	Children 7	Pregnant / Lactating Mother	Person with Disability
Total 292678 244216 125491 662385 46160.43		West Karimganj Nagaon Sonitpur Udalguri Total District Biswanath Cachar Dima- Hasao	9 31 2 18 248 Total 52 11693	2(Badarp 11(Nagac 0(Naduar 2(Khairak Harisinga 135 Revenue (Halem (Gohpur (Sonai 1 (Udharbo (Katigora (Haflong	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu a 0) Circlewise 52), (Naduar R 0), (Biswanat 1013), (Lakhipu ond 27), (Silch h 3143)	2, Kampur 4) uri 0, Kalaigad RC part 0), th 0) ur 1575),	Male 17 4388 205	3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1) 113 Female 27 3928	Children 7 3374	Pregnant / Lactating Mother 1 3	Person with Disability 0
Total 292678 244216 125491 662385		West Karimganj Nagaon Sonitpur Udalguri Total District Biswanath Cachar Dima- Hasao Hailakandi	9 31 2 18 248 Total 52 11693 906 464	2(Badarp 11(Nagac 0(Naduar 2(Khairat Harisinga 135 Revenue (Halem (Gohpur (Sonai 1 (Udharbo (Katigora (Haflong (Algapur (Lanka 1	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu a 0) Circlewise 52), (Naduar R 0), (Biswanat 1013), (Lakhipu ond 27), (Silch h 3143) 906) 464)	2, Kampur 4) uri 0, Kalaigad RC part 0), th 0) ur 1575), nar 5935),	Male 17 4388 205 117	3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1) 113 Female 27 3928 381 117	Children 7 3374 320 230	Pregnant / Lactating Mother 1 3	Person with Disability 0 0
Total 292678 244216 125491 662385 46160.43		West Karimganj Nagaon Sonitpur Udalguri Total District Biswanath Cachar Dima- Hasao Hailakandi Hojai	9 31 2 18 248 Total 52 11693 906 464 31981	2(Badarp 11(Nagac 0(Naduar 2(Khairat Harisinga 135 Revenue (Halem (Gohpur (Sonai 1 (Udharbo (Katigora (Haflong (Algapur (Lanka 1 31981)	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu a 0) Circlewise 52), (Naduar R 0), (Biswanat 1013), (Lakhipu ond 27), (Silch h 3143) 906) 464) 0), (Doboka 0	2, Kampur 4) uri 0, Kalaigad RC part 0), th 0) ur 1575), nar 5935),	Male 17 4388 205 117 20046	3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1) 113 Female 27 3928 381 117 9623	Children 7 3374 320 2295	Pregnant / Lactating Mother 1 3 0 0 15	Person with Disability 0 0 0
Total 292678 244216 125491 662385		West Karimganj Nagaon Sonitpur Udalguri Total District Biswanath Cachar Dima- Hasao Hailakandi Hojai Kamrup	9 31 2 18 248 Total 52 11693 906 464 31981 40	2(Badarp 11(Nagac 0(Naduar 2(Khairat Harisinga 135 Revenue (Halem (Gohpur (Sonai 1 (Udharbo (Katigora (Haflong (Algapur (Lanka 1 31981) (Kayan	mokam 0) our 2, Karimga on 5, Raha 2 r 0) oari 2, Udalgu a 0) Circlewise 52), (Naduar R 0), (Biswanat 1013), (Lakhipu ond 27), (Silch h 3143) 906) 464) 0), (Doboka 0 0), (Rangia 44	2, Kampur 4) uri 0, Kalaigad RC part 0), th 0) ur 1575), nar 5935),	Male 17 4388 205 117 20046	3(Donkamokai 7(Badarpur 0 20(Nagaon 0 2(Naduar 2) 16(Khairabari 1) 113 Female 27 3928 381 117 9623 12	Children 7 3374 320 2295	Pregnant / Lactating Mother 1 3 0 0 15	Person with Disability 0 0 0 2

	Udalguri	163		i 0), (Kalaigad		55	63	45	0	0
			(Harising	a 0), (Khairal	oari 163)				50	4
Home and the second	Total District	48304 Total	Male	Female	Children	26095 Revenue Circle	15244	6911	50	4
Human Lives Lost -	Darrang	1	1	0	0		Mangaldoi 0),	(Patharighat I 1	(Sinaihar I 0)	
Confirmed	Total	1	1	0	0	(Daiguoti O), (ividingulatin 0),	(Tatrianghat 2	i, (Sipajilai O)	
Human Lives Lost Confirmed -	District	Total	Flood Death	General Drowning (Non Flood)	Landslide					
Death Type	Darrang	1	1	0	0					
	Total	1	1	0	0					
Human Lives Lost - Missing Human Lives Lost Missing -	Nil Nil									
Туре			•	1	1					
	District	Total	Big	Small	Poultry					
	Bajali	80	30	50	0					
	Biswanath	5166	3972	1194	0					
	Cachar	31851	20637	11214	0					
	Darrang	143146	64302	37744	41100					
	Dibrugarh	1599	1412	187 30	0					
Animals	Hailakandi Hojai	553 19224	305 7354	3232	218 8638					
Affected		12897	5504	3232	4165					
	Kamrup Lakhimpur	6957	4183	2774	0					
	Nagaon	38523	23774	7484	7265					
	Nalbari	41777	15863	13214	12700					
	Sonitpur	2321	1669	652	0					
	Udalguri	3755	2381	1174	200					
	Total	307849	151386	82177	74286					
Animals	District	Total	Big	Small	Poultry					
Washed	Biswanath	2	2	0	0					
Away	Total	2	2	0	0					
		Fully	Fully		Partially	Partially	Partially	Others	Others Cattle	Others
	District	Kuccha	Pukka	Fully Total	Kuccha	Pukka	Total	Huts	Shed	Total
Houses	Biswanath	12	0	12	1	0	1	0	0	0
Damaged	Cachar	802	0	802	5089	1055	6144	1000	300	1300
	Udalguri	0	0	0	0	0	0	0	1	1
	Total	814	0	814	5090	1055	6145	1000	301	1301
	District	Agency			Boats Deployed	Person Evacuated By Boats	Animal Evacuated By Boats	Helicopters Deployed	Person Evacuated By Helicopters	Medical Team Deployed
	Cachar	Defence/1 Local Peop Resources Emergenc Army/Part SDRF	ation, Civil Frained Vol ple, Police, S Departme cy Services	unteers, Water ent, Fire &	14	1252	0	0	0	26
	Darrang	SDRF			2	42	0	0	0	3
Rescue	Dima- Hasao	Army/Par	amilitary fo	orce	0	0	0	2	12	0
		Army/Paramilitary force			1	5	0	0	0	2
Operation	Hailakandi	SDRF SDRF, Local Country Boat 1 no, Circle Office/Local Administration, Local People, NDRF, Army boat, Army/Paramilitary force, Country			1	5	U	U	U	
Operation	Hallakandi	SDRF, Loc Circle Offi Administr NDRF, Arr	ce/Local ation, Loca ny boat,	l People,	95	5539	120	0	0	5
Operation		SDRF, Loc Circle Offi Administr NDRF, Arr Army/Par	ce/Local ation, Loca ny boat,	l People,						5
Operation	Hojai	SDRF, Loc Circle Offi Administr NDRF, Arr Army/Par. Boats Civil Defer SDRF	ce/Local ation, Loca ny boat, amilitary fo	l People, orce, Country d Volunteers,	95	5539	120	0	0	
Operation	Hojai Kamrup	SDRF, Loc Circle Offi Administr NDRF, Arr Army/Par. Boats Civil Defer SDRF	ce/Local ation, Loca my boat, amilitary fo	l People, orce, Country d Volunteers,	95	5539	120	0	0	1
Operation	Hojai Kamrup Karimganj	SDRF, Loc Circle Offi Administr NDRF, Arr Army/Par. Boats Civil Defer SDRF Fire & Em	ce/Local ation, Loca my boat, amilitary fo	l People, orce, Country d Volunteers,	95 0 1	5539 0 16	120 0 0	0 0 0	0 0	1 0

						Fooder (in Q)	(in Q)		
	D-i-li	0.00	0.00	0.00	0.00			0.00	
	Bajali	0.00	0.00	0.00	0.00	0.00	82.68	0.00	
	Biswanath	244.34	43.48	2.67	132.39	0.00	79.38	0.00	
	Cachar	239.00	98.12	23.34	2360.70	0.00	80.00	0.00	
	Charaideo	2.63	0.47	0.17	0.17	0.00	0.00	0.00	
	Darrang	270.61	50.00	14.99	263.49	0.00	0.00	54.00	
	Dima-								
	Hasao	9.43	1.82	0.78	44.74	0.00	0.00	0.00	
	Hailakandi	46.00	8.40	2.52	252.00	0.00	0.00	0.00	
	Hojai	344.05	63.88	19.17	1916.34	0.00	0.00	532.50	
	Kamrup	0.00	0.00	0.00	0.00	0.00	356.28	0.00	
	Karbi								
	Anglong West	100.56	18.92	5.67	500.67	9.00	0.00	0.00	
	Karimganj	37.17	6.76	2.03	0.00	0.00	0.00	0.00	
	Nagaon	367.24	69.70	20.91	0.00	0.00	1200.00	0.00	
	Sonitpur	29.34	5.21	1.56	0.00	0.00	0.00	0.00	
	Udalguri	91.43	16.78	5.07	506.98	0.00	0.00	0.00	
	Total	1781.80	383.54	98.88	5977.48	9.00	1798.34	586.50	
	District	Baby Food	d Liquid	Baby Food S	olid	Others			
	Bajali	0.00-Q		0.00-Q					
	Biswanath	0.00-Q		0.00-Q, 1.00	-Dk+	Wheat Bran-16	0.64-Q; Corn Fla	kes-5.00-Pkt; Mosquito Coil-3.00-Pkt; Milk	
	Diswariatri	0.00-Q		0.00-0, 1.00	-1 KC	(Amul Taza)-5.00-L Cook Food-6.00-Pkt; Palm Sugar-508.00-Pkt; Sagu-277.00-Pkt; Mortein-			
	Cachar	0.00-Q, 50)8.00-Pkt	0.00-Q, 224.	00-Pkt	1017.00-Pkt; Sc	r-508.00-Pkt; Sagu-2/7.00-Pkt; Mortein- g; Potato-2196.00-Kg; Candle-1727.00-Pkt; n-750.00-Pkt; Tarpulin-700.00-Pieces		
	Charaideo	0.00-Q		0.00-Q					
	Darrang	0.00-Q		0.00-Q, 44.0	0-Pkt	0-0.00-Q; Tarpa	ulin-500.00-Pied	ces	
	Dhemaji	0.00-Q		0.00-Q		Tarpulin-15.00-	Pieces		
Relief	Dima-							t; candle-33.00-Pkt; Match-30.00-Pieces;	
Distributed	Hasao	0.00-Q	0.00-Q			Mortin-3.00-Pkt; Tarpoulin-25.00-Pieces			
		050 00 PI	+ 00 00 Pl+			Wiortin-3:00-Pkt; Tarpoulin-25:00-Pieces			
Others	Hailakandi	850.00-Pkt		80.00-Pkt		Chira -20.40-Q; Gur-3.84-Q; Water bottle-330.00-L; Amul Taza-311.00-L			
	Hojai	1272.00-L, 0.00-Q		0.00-Pkt, 0.0	00-Q	Chira -20.40-Q;	Gur-3.84-Q; Wa	ter bottle-330.00-L; Amul Taza-311.00-L	
	Kamrup	0.00-Q	0.00-Q						
	Karbi								
	Anglong	0.00-Q		0.00-Q					
	West								
	Karimganj	10.00-Pkt		82.00-Pkt, 0.	.00-Q	chira-11.85-Q;	Gur-2.15-Q		
	Nagaon	0.00-Q, 10	0.00-Pkt	250.00-ml, 1	.00.00-Pkt	CANDLE-61.00-	Pkt; MAXO COIL-	-61.00-Pkt; 0-0.00-Pieces	
	Sonitpur	0.00-Q		0.00-Q			,	,	
				217.00-Pkt, (∩ ∩∩-Kσ	Sanitary Pad-13	39 NN-Pk+· N-N N	0-Pkt; CANDLE-25.00-Pkt; MATCHES-49.00-	
	Udalguri	0.00-Q, 34	1.00-Pkt	0.00-Q	0.00 Kg,	,	3.00-Pkt; Matche	,	
	District	Number	Details	0.00-Q		Tieces, caridies	J.00-1 Kt, Wateri	E3 DOX-1.00-1 Kt	
	DISTRICT	Number		The Decel	- 1 le C D	and and another a least	ala a sana a San I	Kalatali Dathar Laran ahad ba 184	
	Barpeta	1		•	yat bundn of B	urnadia river brea	icn approx. 5m	Kalatali Pathar reported by LM ,	
			18.05.20						
Infrastructure Damaged - Embankment Breached	Biswanath	4	almost 4 Brahmaja m on 17/ Brahmaja almost 3 Brahmaja	Halem - Brahmajan Embankment Nirmala TE Left embankment of Brahmajan breached at Nirmala TE an almost 40 m on 17/05/2022, Brahmajan Embankment Goroimari Left embankment of Brahmajan breached at Goroimari area by almom on 17/05/2022, Brahmajan Embankment Garudhuwadubi Left embankment of Brahmajan breached at Garudhuwadubi almost 35 m on 17/05/2022, Brahmajan Embankment Boranipathar Right embankment of Brahmajan breached at Boranipathar area almost 8 m on 17/05/2022					
	Goalpara	1	Dudhnoi	- Marginal Bur	nd from Habri		ver to NH 17 Amjonga Marginal bund from Habri River to NH 17 Raod apprx. 6 Metre on dated : 17-05-2022		
	Nagaon	1	Kampur	- Embankment	on River Haria	Tetelisara Gran	it Embankmen	t on River Haria breached at Tetelisara	
	_					M. The embankm i, Bhathuwakhan		RDA. Tihu Nadi, Date of Occurance:18/05/2022,	
	Nalbari	1	_		-	eived from GB, Sk	-		
	Total	8							
	District	Number	Details						
Infrastructure Damaged - Embankment Affected	Tamulpur	3	stretch,A Puthimai embankr Goreswa	ffected area-1 i RB Embankm nent in a reach r - DRDA emba	800 sqm Date- nent Village-J n length-600 m ankment at Vill	15/5/22, ukmari Bank erc trs,Damaged area age Tengajhar V	oision on RB of ri 1-1200sqm,Date- Village Tengajhar	ver Puthimari near 3rd km of puthimari RB -15/5/22, 17/05/2022. Active Bank erosion on east o active erosion reported on 18/05/2022.	
	Total	3							
Infrastructure	District	Number	Details						
Damaged -	Bajali	4	Bajali - G	aremari Bagar	ara Road Niz	Sathisamukha I I	Damage occured	on 16/05/2022 and this report is received	
		1	, ,	0~			J	, ,	

Road			from department of PWD Roads. The length of breach is 4.50m and breath is 8.20m., Badankuchi to pub kolorguri road bhotanta mohitara village Damage occured on 17/05/2022 and This report is received from Block Developement Officer, Bajali Dev. Block. The length of the breach is 15m and breadth 4m, Kochdiga Village road kochdiga Damage occured on 17/05/2022 and This report is received from Block Developement Officer, Bajali Dev. Block. The length of the damage is apprx 250m and breadth is 4m.,
			Patacharkuchi Anchali Road Golaghat Damage occured on 17/05/2022 and this report is received from
			department of PWD Roads.The length of damage is 1m and breath is 2m.
	Barpeta	2	Sarthebari - kalatali to batia connectivity PWD road Kalatali Pathar reported by Gaon Pradhan (18/05/2022), Kalgachia - State Highway 2 Various point from Manas Bridge to Barpeta Medical College. Due to heavy rainfall both side of road shoulder damaged with hard crust of SH2 from Manas Bridge approach to Barpeta Medical College at chainage 48th Km(Length= 120 m, average Breadth=2.5m, depth=3.00m, Location- 26.330593, 90.862387) and at 49th Km(Length= 120 m, average Breadth=3.00m, depth=3.50m, Location- 26.33381, 90.869323)Date-18-05-2022
			Halem - Jalukbari to Itapara road Jalukbari Jalukbari to Itapara road damaged by almost 700m on 17/05/2022,
			Collegeguri to Milan Nagar Road Collegeguri Collegeguri to Milan Nagar Road overtopped by 300m on 17/05/2022,
			Sonapukhuri Sewa Ahsram Road Amjaroni Sonapukhuri Sewa Ahsram Road at Amjaroni overtopped by 150m on 17/05/2022,
	Biswanath	6	Jotte Balijan Road Amjaroni Jotte Balijan road at Amjaroni damaged by 300m on 17/05/2022, Gohpur - Mornoiguri PWD to Singarajan Road Singarajan A total of 1200 mtrs of Road is affected from flood water from mornoi river. 18/05/2022 (Report from PWD).,
			Biswanath - Geruabari kharasimalu mijika road Geruabari Kharasimalu Submergence Occurred At Geruabari
			Kharasimalu to Mijika Road (pmgsy pkg no AS-22-672) From Ch. 750.00M to 810.00M for an average depth of 30
			Cm and from ch. 840.00M to 9000.00M for an average depth of 20 Cm on 17-05-2022 (Report from PWD) Boitamari - Village Road Balapara Severe erosion approx. 500m on 17/05/2022,
	Bongaigaon	2	Village Road Chatpara to koreya pt-1 Eosion at several bank site of the road (approx 2 km) on 18/05/2022
			Sonai - Neirgram to Gangapur Road Bagpur Neirgram Neirgram to Gangapur covering a length of 3.00 km is
			completely submerged due to heavy rainfall and communication disrupted to Bagpur Neirgram villages under
			Sonai RC, above report recevied from PWD Sonai (T) Road division as on 18.05.2022, Lakhipur - NH 53 Jirighat T.E. to Lalpani via. Bhagkhal, Kapakhal and Mirpur Jirighat T.E. to Lalpani via. Bhagkhal,
			Kapakhal and Mirpur NH-53 Jirighat T.E. to Lalpani via. Bhagkhal, Kapakhal and Mirpur. Length of submerged Ch-
			200.00 m Ch-500.00 m and Ch-750.00 m to Ch- 1400.00 m. As per the report received from PWD Lakhipur(T)
			Division, As on 18.05.2022,
			NH-53 to Alney T.E. via Choubari Alney T.E. via Choubari NH-53 to Alney T.E. via Choubari Length of lands slide Ch-1420.00 m to Ch-1450.00 m. As per the report received from PWD Lakhipur(T) Division, As on 18.05.2022,
			Jirighat Bahadurpur road Jirighat Bahadurpur Jirighat Bahadurpur road submerged at Ch-3100.00 m to Ch-
			3160.00 m.As per the report received from PWD Lakhipur(T) Division, As on 18.05.2022,
			Dighli to Makhan Nagar via Karjanbasti road Dighli to Makhan Nagar via Karjanbasti Dighli to Makhan Nagar via Karjanbasti road submerged at Ch-1800.00 m to Ch-2400.00.As per the report received from PWD Lakhipur(T)
			Division, As on 18.05.2022,
			Poilapool to Kumbhirgram Road Poilapool to Kumbhirgram Poilapool to Kumbhirgram Road erosion from ch
			2350.00 to 2415.00M. As per the report received from PWD Lakhipur(T) Division, As on 18.05.2022,
			Shibpur Lakhipur road (Crematorium road). Shibpur Lakhipur road (Crematorium road). Shibpur Lakhipur road (Crematorium road). As per the report received from PWD Lakhipur(T) Division, As on 18.05.2022,
			Poilapool to Kumbhirgram Road erosion Poilapool to Kumbhirgram Poilapool to Kumbhirgram Road erosion
			from ch 2350.00 to 2415.00M. As per the report received from PWD Lakhipur(T) Division, As on 18.05.2022,
			Pallorbond bridge approach Pallorbond Pallorbond bridge approach erosion at ch 177.00M. As per the report
			received from PWD Lakhipur(T) Division, As on 18.05.2022, Udharbond - Laisong Rajabazar Road AT CH. 21400.00 M to CH. 21475.00M AND CH. 22600.00 M to CH.
	Cachar	36	22650.00M Side Berm Damage on 18.05.2022 Rajabazar ,
			Silchar - Arkatipur to Badripar via Maidanbeel and Digor Kashipur, Arkatipur to Badripar via Maidanbeel and
			Digor Kashipur, APPROACH OF BRIDGE NO.3/3 AT BADRIPAR SIDE AT CH.2.600 KM of Road from MRL-02 Arkatipur to Badripar via Maidanbeel and Digor Kashipur, Package No. AS-03-262, damaged, Report received from
			PWD Silchar & Digor Nami PwD Silchar & Sampi Control of the Contro
			Silchar - Hailakandi Road Silchar - Hailakandi Silchar - Hailakandi Road side eroded at KM 16th and 17th in
			stretches.Report received from PWD Silchar & Delicarities and Division. As on 18.05.2022.,
			Silchar Hailakandi Road Silcoorie to Bairagitilla Hailakandi Road at Silcoorie to Bairagitilla covering a length of 300.00m is completely submerged due to heavy rainfall and communication disrupted to Bairagitilla. Report
			received from PWD Silchar & Division. As on 18.05.2022.,
			Katigorah - 1.G.N Road to Telkargrant via Saraspur, PMGSY Package No.: AS-03-91(1" Km to 5 Km) 2.
			Mahadevpur Bus Stand at Mahadevpur Part-I to Part-II, PMGSY Package No.: AS-03-9101" Km to 3 Km) 3.
			Telkar grant to Natanpur, PMGSY Package No.: AS-03-69 (1, 2 & Dr. 9th Km) 4. NH-44 at Lakhipur-1 to Boraitali PMGSY Package No.: AS-03-68 (1" ,3 & Dr. 9th Mey Package No.: AS-03-68 (1" ,3 & Dr. 9th Mey Package No.: AS-03-68 (1" ,3 & Dr. 9th Mey Package No.: AS-03-68 (1" ,3 & Dr. 9th Mey Package No.: AS-03-68 (1" ,3 & Dr. 9th Mey Package No.: AS-03-69 (1, 2 & Dr. 9th Mey Package No
			2/3 & Dr. S. NH-44 at Lakhipur to Boraitali via Itbhatta, PMGSY Package No.: AS-03-38 (1" & Dr. S. Mh-44)
			6. Rajeswarpur Bus Stand to Saraspur via Sannyashikandi (2nd Km) & Damp; 4th km) 7. Koroikandi to Jabda including
			RCC Bridge approaches (2nd 3rd 8. Karbala Grant(near Kalibari) to Natunpur Grant (1" Km) 9. Nischintapur to Nij-Jalapur-1 (1 & 2 km) 10. NH 44 at Brahmingram to Konapara PMGSY Pkg.NO.AS-03-79 (1" Km.to
			5th Km,8th Km to 10 Km) 11. Chikorkandi to Khelma via Khelma lil to Khelma IV, PMGSY Package No AS-03-781 1
			to 2 Km) 12. Salimabad to Chikorkandi at Khelma V,PMGSY Package No.: AS-03-78(1 & mp; 2 Km) 13. ONGC Road
			at TRK (1" Km,) 14. TRK Road to Sinjuripar (1 & 2 Km) 15. Bihara-V at NH-6 to S.K Road, PMGSY Package
			No.: AS-03-67 (1" to 6th km) 16. Haritikar to Salimabad, PMGSY Package No.: AS-03-65 (3 to 8th Km) 17. Gumrah Leverputa Road to LP School under Khelma Part-II village under BADP (1 km). 18. Craigpark to
			Hanumanthal (1 Km) 19. Gumra Leverputa Road (5th, 6th & Damp; 7th Km.) 20. Gumra Natanpur to Jame Masjid of
		1	the state of the s

1	
	Tarapur under BADP. (1" Km) 21. Batterchak PHE to Anandapur near BSF Camp under BADP (1" & 2 Km) 22. NH-06 at Digarkhal to Natanpur via Rajyeshpur, Kushiarkul & Pirnagar, PMGSY Pkg.No.AS-03-231(7 8,9,11th & 12th Km.) 23. Construction of road from Khelma II to Khelma V(1 & 2nd Km) Under Katigorah & Borkhola
12	Patharighat - MPK Road to Pachim Santipukhri santipukhri MPK Road to Pachim Santipukhri road CD damaged at Ch 1300 m to 1400 mt. on 17/5/2022 as reported by PWD , Chakarmukh Bisnupur PWD Road Charkarmukh Road submerged at length 15.50 km ch from 1st to 2nd km on 17/5/22 as reported by PWD Deptt, MPK to Santipukhri Medical Sub. Centre Road Santipukhri Medical Sub. Centre Road Road submerged , Mangaldoi - NH 15 From saktola to pipiradukan under Mangaldai Revenue Circle. The NH 15 road is submerged due to flood water overflowing. The length of submergence is from Ch. 24.45 to 25.55 and length of submergence is approximately 1100m as of now.The average depth of submergence is 15cm to 50cm as of now as reported by department. Dated 18/05/2022, Naharbari Ganakbari road under PWRD Naharbari Village under Mangaldai Revenue Circle The road is submerged due to flood water. The length of submergence and damage is around 700m as reported by pwrd. Dated 18/05/2022, Outola Bechimari road Ahaka chuburi under Mangaldai Revenue Circle The road is submerged due to flood water. The length of submergence and damage is around 500m as reported by pwrd. Dated 18/05/2022, Rangamati Kaligaon Road Rangamati under Mangaldai Revenue Circle The road is submerged due to flood water. The length of submergence and damage is around 500m as reported by pwrd. Dated 18/05/2022, Kanichuba Patharighat Road Kanichuba under Mangaldai Revenue Circle The road is submerged due to flood
	water. The length of submergence and damage is around 300m as reported by pwrd. Dated 18/05/2022, Chamuapra to CM Dutta bandh road Chamuapra under Mangaldai Revenue Circle The road is submerged due to flood water. The length of submergence and damage is around 700m as reported by pwrd. Dated 18/05/2022, Pipiradukan Dhankhunda road Chotonagaon under Mangaldai Revenue Circle The road is submerged due to flood water. The length of submergence is around 6Km as reported by pwrd. Dated 18/05/2022, Silarkhuti Burhagohai to Pipiradukan road Chotoathiabari under Mangaldai Revenue Circle The road is submerged due to flood water. The length of submergence is around 3Km as reported by pwrd. Dated 18/05/2022., Sipajhar - Bhukatabari Sonapur road (NH to Basachuba) Haldha-Maijeli Bhukatabari Sonapur road (NH to Basachuba) breached at 9.20 km dated 18/05/2022
3	Jonai - PWD territorial road Jonai Bazar to Tinimile Ghat, 150.0 meter side berm got eroded on 18/05/2022 due to Siley River. From Ch.5000.00 M to Ch.5150.00 M As per report received from PWD Territorial Road Sub-Division II, a PWD territorial road Jonai Bazar to Tinimile Ghat 150.0 meter side berm got eroded on 18/05/2022 due to Siley River . To mitigate further damage Bamboo Palasiding, Earth Filling cement bags & Department restoration boulder apron & Department restoration boulder side berm got eroded on 18/05/2022 due to Siley River. From Ch.980.00M to Ch.1100.00M As per report received from PWD Territorial Road Sub-Division II, a PWD territorial road Bahir Siley to Malbhug Mising, under PMGSY Package No.AS04-174,120.00 meter side berm got eroded on 18/05/2022 due to Siley River. To mitigate further damage Bamboo Palasiding, Earth Filling cement bags & Department restoration boulder apron & Department restoration boulder apron & Department restoration son provided to Bera Chapori via Machuwa Camp ,30.00 meter side berm got eroded on 18/05/2022 due to Siley River. From Ch.1110.00 M to Ch.1130.00 M As per report received from PWD Territorial Road Sub-Division II, a PWD territorial road Bridge approach of RCC Br. No.1/1 erosion on Akland to Bera Chapori via Machuwa Camp ,30.00 meter side berm got eroded on 18/05/2022 due to Siley River. From Ch.1110.00 M to Ch.1130.00 M As per report received from PWD Territorial Road Sub-Division II, a PWD territorial road Bridge approach of RCC Br. No.1/1 erosion on Akland to Bera Chapori via Machuwa Camp ,30.00 meter side berm got eroded on 18/05/2022 due to Siley River. To mitigate further damage Bamboo Palasiding, Earth Filling cement bags & Department restoration boulder apron & Department restoration boulder apron & Departm
1	Lakhipur - Lakhipur to Khalisavita Road Near Dhumerghat Bazar under Revenue Village Morichbari Grazing Reserve. The approach road of PWD Dept., erosion right side of Dhumerghat Bridge No. 15/1 by overflowing of River Ghagua. Date: 18-05-2022
r 2	Bihpuria - Karunabari Kehutoli to Dharmapur Block Road PWD(R) At Dharmapur No. 1 Length of Damages as reported by AEE, PWRD, Bihpuria TR SD are- (1)340m from CH.5550-CH.5840 m, Long-93.974432, Lat-27.119383 on 17/05/2022 (2)200m from CH.6350-CH.6550 m, Long-93.981971, Lat-27.117971 on 17/05/2022, Ahmedpur Kutubpur PWD Road to Karunabari Besapatty PWD road No. 2 Islampur The damages of road occurred to embankments, shoulders, hard crust & Damages of approach RCC bridge No. 2/1 due to overflow of Meneha river on 17/05/2022. Average depth of submergence is 0.40m as reported by AEE, PWRD, Bihpuria TR SD
1	Morigaon - Matiparbat Road Matiparbat, Morigaon Killing River over flowing over the road. (18-05-2022)
13	Raha - BANDURA ATI TO SINDURA ATI BANDURA ATI SUBMERGED/ERODED-1750M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, HATIGARH TO BABURAATI HATIGARH SUBMERGED/ERODED-3120M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, HATIGARH TO BALIJURI HATIGARH SUBMERGED/ERODED-2700M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, KAKATIGAON TO SALMARA KAKATIGAON SUBMERGED/ERODED-1800M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, DHARMUKH BAZAR TO SIMALUGURI DHARMUKH SUBMERGED/ERODED-2000M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, JAKARUA BEEL TO UDARVETI JAKARUWA SUBMERGED/ERODED-1900M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, KAKATIGAON RLY GATE TO DABALU BEEL KAKATIGAON SUBMERGED/ERODED-1300M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, KAKATIGAON RLY GATE TO DABALU BEEL KAKATIGAON SUBMERGED/ERODED-1300M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, KAKATIGAON RLY GATE TO DABALU BEEL KAKATIGAON SUBMERGED/ERODED-1300M(APPROX) DATE OF OCCURANCE-17/05/2022 DEPARTMENT NAME-PWRD,RAHA TERRITORIAL ROAD,SUB DIVISION, Kampur - Ghilani to Madhabpara via puthimari, simaluguri Ghilani Ghilani to Madhabpara via puthimari,
	1 1 1 1

			simaluguri at 3rd, 4th, 5th, & Drawp; amp; amp; 6th Km submerged on 17.05.2022. The road belongs to Raha
			Territorial road sub-division.,
			Puthimari to puthimari No 1 Puthimari Puthimari to puthimari road submerged on 17.05.2022. Length-200 m
			the road belongs to Raha territorial road sub-division.,
			Kachua tiniali to satlunga. Kachua Tiniali Kachua tiniali to Satlunga at3rd & 4th Km
			submerged on dated 17.05.2022. The Road belongs to Raha Territorial Road Sub-Division.,
			SH-18 Kampur SH-18 (Kampur -Singimari-Baithalangsu-Segment) approaches of Lutumari RCC Bridge have been
			reoded/settled down badly on dated 17.05.2022. Length-300 m, The Road belongs to Raha Territorial Road Sub-
			Division.,
			Charaihagi -changchaki- bakulaguri road. Charaihagi Charaihagi -changchaki- bakulaguri road submerged on
			dated 17.05.2022. Length- 500m The road belongs to Raha Territorial Road Sub-Division.,
			Missamari to sumeswari colony Missamari Missamari to Someswari Colony submerged on dated 17.05.2022.
			Length-800 m. The road belongs to Raha Territorial road Sub-Division.
			Banekuchi - Makrapar to Sahpur road Sanora ,Kuropar Makrapar to Sahpur road submerge apro. 700 mtr
			.dated on 17/5/2022 report recieved from Gaon Pradhan .,
			Nalbari - Palla Road Gardan School to Balikaria Kharjara As per report received from PWD(Roads) Deptt, due to
			continuous raining, palla road is damaged due to clogging of water. Approximate damage distance is near about
	Nalbari	3	700 Meter. Culvert is required to drain the clogged water Dated : 17/05/2022,
			Paschim Nalbari - Tihu Location Road to Lakhopur Go Puja Khola via Kendubari Village Between Kendubari and
			Lakhopur Submerged for a length = 1000 m Depth of submergence = ave 60 cm As per information received from
			AEE, PWRD on 18/05/2022
			Dhekiajuli - Damage observed at Dhekiajuli town Ward no 8 road near Girls School. length 5-10mtr aprox. dated
			17.5.2022 Near Dhekiajuli Girls School, Dhekiajuli town Ward no 8 ,
			Chariduar - CULVERT NO 1/3 ON NH 15 TO GHOGORATE ROAD DATD 18/05/2022 /3 (M)APPROX CHARIDUAR,
	Sonitpur	4	SONITPUR AS REPORTED BY PWD DEPT ,
		,	KHELMATI TO BORGHULI ROAD BETWEEN CH 1320M TO 1400M DATD 18/05/2022 /3 (M)APPROX CHARIDUAR,
			SONITPUR AS REPORTED BY PWD DEPT ,
			ROAD EMBANKMENT OF RANGAPARA BALIKA VIDYALAYA ROAD DATD 18/05/2022 /LESS THAN 70 (M)
			CHARIDUAR, SONITPUR AS REPORTED BY PWD DEPT
			Khairabari - 1. Dongpara to Mahaliapara Road Purani Bhergaon Damage RCC- Slab culvert. Length: 4m: Date of
			Occurrences: 16.05.2022,
			2. Dudhgarmokha to Thakuriapara to Ranipukhuri Road Near Talibari Chowk Damage RCC- Slab culvert. Length:
			06 (approx.): Date of Occurrence: 16.05.2022,
			3. Ranipukhuri to Rowmari Road Ranipukhuri Damage of 5 row HPC: Length: 12 m (approx.) Date of
			Occurrences: 16.05.2022 ,
			4. Thakuriapara to Gorangpara Road Gorangpara Damage of Hum pipe culvert. Length: 10 m (approx.): Date of
			Occurrence: 16.05.2022,
			· ·
			Kalaigaon - MR road in the middle of Kalaigaon Town I Kalaigaon Town I The road surface has damaged on
			Kalaigaon - MB road in the middle of Kalaigaon Town Kalaigaon Town The road surface has damaged on
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system.,
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022.,
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022.,
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022.,
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022.,
	Udalguri	10	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy
			18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022.,
	Udalguri	99	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022.
			18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy
	Total District	99 Number	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on
	Total	99	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022.
	Total District Barpeta	99 Number	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on
	Total District	99 Number	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022
	Total District Barpeta	99 Number	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road Ist Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excesive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022
	Total District Barpeta Biswanath	99 Number 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on
	Total District Barpeta	99 Number	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m
	Total District Barpeta Biswanath	99 Number 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road 1st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachubil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by
Infractructure	Total District Barpeta Biswanath	99 Number 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022
Infrastructure	Total District Barpeta Biswanath	99 Number 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.5 School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari.
Damaged -	Total District Barpeta Biswanath Darrang	99 Number 1 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022
	Total District Barpeta Biswanath Darrang	99 Number 1 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated
Damaged -	Total District Barpeta Biswanath Darrang	99 Number 1 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road Ist Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated 17.5.2022 Dhekiajuli town Ward no 10 ,
Damaged -	Total District Barpeta Biswanath Darrang Nalbari	99 Number 1 1 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated
Damaged -	Total District Barpeta Biswanath Darrang Nalbari	99 Number 1 1 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated 17.5.2022 Dhekiajuli town Ward no 10 , Dherai majuli Pwd bridge 4/1 approach/guide bund damaged. length 1
Damaged -	Total District Barpeta Biswanath Darrang Nalbari	99 Number 1 1 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road Ist Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated 17.5.2022 Dhekiajuli town Ward no 10 , Dherai majuli Pwd bridge 4/1 approach/guide bund damaged. length 1
Damaged -	Total District Barpeta Biswanath Darrang Nalbari Sonitpur	99 Number 1 1 1 2	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system., Harisinga - Tangla kachubil Road Ist Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.S School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Naibari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated 17.5.2022 Dhekiajuli town Ward no 10 . Dherai majuli Pwd bridge 4/1 approach/guide bund damaged. length
Damaged -	Total District Barpeta Biswanath Darrang Nalbari	99 Number 1 1 1	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system, Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.5 School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated 17.5.2022 Dhekiajuli
Damaged -	Total District Barpeta Biswanath Darrang Nalbari Sonitpur	99 Number 1 1 1 2	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system. Harisinga - Tangla kachubil Road 1st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.5 School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated 17.5.2022 Dhekiajuli town Ward no 10 , Dherai majuli Pwd bridge 4/1 appro
Damaged -	Total District Barpeta Biswanath Darrang Nalbari Sonitpur Udalguri	99 Number 1 1 1 2	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system, Harisinga - Tangla kachubil Road !st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.5 School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Halem - Nh15 bridge Collegeguri Gohpur Town Approach to bridge on NH15 at Gohpur town affected on 17/05/2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated 17.5.2022 Dhekiajuli
Damaged -	Total District Barpeta Biswanath Darrang Nalbari Sonitpur	99 Number 1 1 1 2	18/05/2022 covering a length of around 1000 meters and breadth of 12 inches due to continuous rainfall resulting waterlogging due to absence of drainage system. Harisinga - Tangla kachubil Road 1st Km to Kachubil road near Tangla Due to overflow of river Naika the tangla to Kachubil road eroded around 6.7m on 17th may 2022., Tangla kachubil Road 2nd Km to Kachubil road near Tangla due to excessive rainfall the Tangla to kachunbil road surface damaged around 3.0m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Upper Nalapara Shiva Mandir road No.1 Boromgajuli Road surface damaged due to heavy rainfall approximate damage around 25m on 17th may 2022., Pub-Nalbari to ward no.2 Tangla road Pub- Nalbari the road between pub nalbari to Ward no2 road eroded due to excessive rainfal. around 9963.58m damaged on 17th may 2022., Tangla Babupara Municipalty road Near H.5 School Babupara The municipalty road damaged due to heavy rainfall occured on last few days. approximate damage 4m on 18th may 2022. Details Barpeta - SPT Bridge on Dongarkuchi Village Road to Betbari Dangarkuchi METEKA threatend the SPT Bridge on Dongarkuchi Village Road to Betbari Date of Occurrence : 17.05.2022 Mangaldoi - Approach of Naharbari to Ganakbari bridge Naharbari under Mangaldai Revenue Circle. The approach of Naharbari-Ganakbari bridge towards the Ganakbari side has been severely eroded by a length of 40m (approx) due to which the Kulsi river at other portion seems to b deviated from its original course, as reported by PWRD. Dated 18/05/2022 Paschim Nalbari - RCC br. No. 1/1 on Barbila Lokhopur Road. On Barbila - Lokhopur road via Sarthebari. Information received from AEE, PWRD Department on 18/05/2022 Dhekiajuli - Municipality Rcc bridge approach at Dhekiajuli town Ward No 10 damaged. length 5 Ft aprox dated 17.5.2022 Dhekiajuli town Ward no 10 , Dherai majuli Pwd bridge 4/1 appro

Infrastructure Damaged - Wildlife	Nil	
wiiuiite	District	Other Details
	Bajali	Bajali - Fisheries/Pond vill-kanimara Lat: 26.47951 Long: 91.249792 Area: 0.13 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block , Bajali on 18.05.2022), Fisheries/Pond vill-kanimara Lat: 26.480097 Long: 91.249401Area: 0.13 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block , Bajali on 18.05.2022), Fisheries/Pond vill-kanimara Lat: 26.479925 Long: 91.248982 Area: 0.10 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block , Bajali on 18.05.2022), Fisheries/Pond vill-kanimara Lat: 26.478826 Long: 91.247496 Area: 0.10 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block , Bajali on 18.05.2022), Fisheries/Pond vill-kanimara Lat: 26.478793 Long: 91.247423 Area: 0.19 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block , Bajali on 18.05.2022), Fisheries/Pond vill-Bar Bairagy Lat: 26.49244 Long: 91.246639 Area: 0.06 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block, Bajali on 18.05.2022), Fisheries/Pond vill-Bar Bairagy Lat: 26.491834 Long: 91.246954 Area: 0.06 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block , Bajali on 18.05.2022), Fisheries/Pond vill-Barnalikuchi Lat: 26.49244 Long: 91.23666 Area: 0.10 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block, Bajali on 18.05.2022), Fisheries/Pond vill-Barnalikuchi Lat: 26.485992 Long: 91.238666 Area: 0.13 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block, Bajali on 18.05.2022), Fisheries/Pond vill-Barnalikuchi Lat: 26.485585 Long: 91.23666 Area: 0.19 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block, Bajali on 18.05.2022), Fisheries/Pond vill-Barnalikuchi Lat: 26.485586 Long: 91.235725 Area: 0.05 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block, Bajali on 18.05.2022),
		Fisheries/Pond vill-Barnalikuchi Lat: 26.483384 Long: 91.236225 Area: 0.10 Ha. (Damage occurred on 17.05.2022 and reported by O/o Fishery development Block, Bajali on 18.05.2022) Kalgachia - Culvert Approach Road Damaged As per report received from PWD dept. on 18/05/22, Janata Bazar to
	Barpeta	Shawrachara road one RCC Slab Culvert approach damaged due to heavy rain fall. Location- 26.270532, 90.841267
	Biswanath	Halem - Fisheries/Pond 206 Nos. of ponds affected. Approximate water area affected 26.74 hectares. 17/05/2022, Power Dept. Poles 7 Nos. Of LT poles were damaged on 17/05/2022, Naduar RC part - Fisheries/Pond Six fisheries were submerged, namely 1. Bakul Panikar ,water area- 0.56 Ha 2. Dikorai poriya M.E. School, water area- 0.20 Ha 3. Gram Bikash sewa samiti Nagsankar, water area-0.55 Ha 4. Deep Nath, water area-0.14 Ha 5.Paresh Nath, water area-0.30 Ha 6.Sonmilita H.S.G. Nagshankar, water area-1 Ha; Total area covers- 2.75 Ha. 18/05/2022, Gohpur - Fisheries/Pond A total of 33 Nos. of pond is affected by flood water in Gohpur Circle 5.36 hectares. 17/05/2022 Sonai - Elementary Schools Damaged 1644 NO JANATA LPS 885 NO KAPTANPUR PURNAGRAM LPS 1379 NO RAKARPAR LPS
Infrastructure Damaged - Others	Cachar	1062 NO ISLAMPUR LPS 130 NO JHARAGUL LPS 1365 NO RANGAKHALER PAR LPS 974 MOTINAGAR LPS 75 NO DIDARKUSH T.E. LPS 1334 NO UTTAR DIDARKUSH LPS KAYLASHPUR LPS 1582 NO TUTIRGRAM LPS 1580 NO BARKHALPAR LPS 1000 NO BHAURIKHAL LPS MODUR BAND SEKH PARA LPS 1529 NO JURKHAL LPS INDRAMONI D CHDY TAPOSILI LPS 1000 NO BHAURIKHAL LPS MODUR BAND SEKH PARA LPS 1529 NO JURKHAL LPS INDRAMONI D CHDY TAPOSILI LPS UNDER SONAI RC, Lakhipur - Elementary Schools Damaged \$57 NO LALANGPAR LPS 1103 NO BAHADURPUR LPS PURANLINE LPS GANGAPUR GOVT JBS 97 BADRIPAR LP SCHOOL BAPUJI HINDI LPS BADRIPAR PT-V LP SCHOOL AMADER PATHSALA C NAYAGRAM 911 NO DIGLANG HMAR LPS JIRIGHAT A MITRA MES 1403 NO NINGTHEMKHUN GIRL'S LP under Lakhipur RC, Udharbond - Elementary Schools Damaged 1350 SERAMKHUL LPS, 286 CHALITA KANDI LPS, MAINARBOND LP SCHOOL, 763 NO SURJAMONI LPS, 875 NO CHALITA KANDI LPS, 1332 NO PALANGTIKI LPS, CHAITANYA MES, FULMATI LP SCHOOL, CHAITANYA MES, GOSSAIPUR NEHRU MVS, DAYAPUR PT-1 TUKPARA LPS, 1011 NO KALYANI GRAM LPS, 61 NO MASUAGHAT LPS, DUDHPATIL MVS, 1326 NO CHANDRAPUR LPS, PANGRAM PT-1 LPS, 987 NO RONGPUR LPS, BAHADURPUR LPS, RONGPUR PT-3 LPS, 762 SHYAMA SUNDARI LPS, 735 NO ICHU MIA LPS, 832 BALIGHAT LPS, 1044 NO UDHARGAON LPS, DUDHPATIL MEM PT-3 LPS, 762 SHYAMA SUNDARI LPS, 735 NO ICHU MIA LPS, 832 BALIGHAT LPS, 1044 NO UDHARGAON LPS, DUDHPATIL MEM PT-3 LPS, 076 SHYAMA SUNDARI LPS, 735 NO ICHU MIA LPS, 832 BALIGHAT LPS, 1044 NO UDHARGAON LPS, DUDHPATIL MEM PT-3 LPS, 762 SHYAMA SUNDARI LPS, 735 NO ICHU MIA LPS, 832 BALIGHAT LPS, 1044 NO UDHARGAON LPS, DUDHPATIL MEM PT-3 LPS, 975 SHYAMA SUNDARI LPS, 735 NO ICHU MIA LPS, 832 BALIGHAT LPS, 1044 NO UDHARGAON LPS, DUDHPATIL MEM PT-3 LPS, 975 SHYAMA SUNDARI LPS, 735 NO ICHU MIA LPS, 832 BALIGHAT LPS, 1044 NO UDHARGAON LPS, DUDHPATIL MEM PT-3 LPS, 975 NO LPS, 832 BALIGHAT LPS, 1044 NO UDHARGAON LPS, DUDHPATIL MEM PT-3 LPS, 975 NO LPS, 832 BALIGHAT LPS, 1045 NO LPS, 834 BALIGHAT LPS, 1045 NO LP

PART-IV LPS BUALIPAR NEW LP SCHOOL MUSIUR RAHMAN LPS 166 KOLACHARIRPAR LPS East Kolarcharipar New LPS Muslimabad LPS HAZI FAZLUL HOQUE LPS 589 NO. KANAIGOOL LPS KANAIGOOL NEW LPS 702 NO. HALTORPAR LPS HAZI RAJA MIA MEM BURUNGA MES (A) Kashibon new lps Panighat lps Sabaipur garden lps DC MEMORIAL MES 1077 BALIRBOND LPS SAYALI LPS 511 NUNCHURI LPS 1308 BAURIPARA LPS 1421 PARSHURAM CHETRI LPS 1534 DINANATHPUR LPS BARANUNCHURI NEW LPS 995 HAWARMAH LPS NATURBOND NEW LPS GORAGRAM NEW LPS Dinathpur New LPS Khelma part-1 New LPS Khelma-6 New LPS 303 Kandigram LPS NETAJI LP SCHOOL SURMA VALLEY ME SCHOOL 1611 EAST HARINAGAR LPS 1617 Dhakin Harinagar LPS A.H. BARBHUIYA LPS 1253 TUKERGRAM NUTAN BASTI LPS 810 TUKERGRAM LP SCHOOL 14 CHANDINAGAR LP SCHOOL BHAIRAB BARI LP SCHOOL TAPASIL JANATA LPS KINNAKHAL PUBLIC HIGH SCHOOL EAST SUBODH NAGAR LPS WEST SUBODH NAGAR LPS BORBOND LP SCHOOL 495 JABDA LP SCHOOL 570 SUBODH NAGAR LPS 1008 NO NISCHINTAPUR LPS 279 NO PIRNAGAR LPS DONARPAR LPS RONGPUR SURMA LPS KANDIGRAM LPS 543 No West Jarailtola lps Jarailtola High School Jarailtola G M SR BASIC SCHOOL 31No Vitorgangapur LPS 547 No Gangapur LPS 36 NO. KISHAN NATH L.P SCHOOL 285 no. jarailtala lp school 592 no. Tikarbasti L.P School 510 NO DILURAM PATHSALA 307 NO KALAIN BALIKA VIDYALAYA 816 NO BRAHMANGRAM LPS 537 NO KUNAPARA ASSAMESE LPS CHALIGRAM LPS 1256 SAHADEB JATRAMOYEE LPS KORASHURA LPS Kalibari Pechacherra LPS 857 Magenta Colony LPS 1578 No. Magenta LPS 30 Konapara Garden LPS Konapara Grant MES Bhatgram LPS Ailathal Nunchuri MP LPS CHILLAGRAM LPS Jagadishpur pt I New LPS Jagadishpur pt 3 New LPS Gonipur LPS 1039 BANIMANDIR LPS 427 NO KHALPAR LPS 706 DHOLKANDI LPS 628 NO LARANG PAR LPS 1255 LAMAR GRAM LPS BAISHNAB GRAM NEW LPS 1518 KALINAGAR LPS KHEKMA PART 5 NEW LP SCHOOL MOGLOGORH LPS 975 KHELMA NETAJI LPS GHAKTIR PAR LPS NEW BALESWAR HS SCHOOL BALESWAR ME SCHOOL 1302 NO. JANATA LPS SULTANPUR LP SCHOOL HINDUPARA LPS (UPGRADED) NATANPUR NEW LPS SHILLINGTILLA LPS 627 NO NATANPUR LPS 54 No Batulmara Garden Ips Batulmara nutantilla Ips Baraitali Pt 3 Garden LPs 281 Baraitali LPs BARAITALI PT-4 WEST LPS BARAITALI PT-4 EAST LPS ADARSHA ME SCHOOL BARAITALI PT-V LP SCHOOL 812 NO MONIPUR LPS HILARKANDI LP SCHOOL HILARIKANDI NEW LP SCHOOL 298 NO. LAKHIPUR LP SCHOOL 860 no Bhater chack lps West leverputa LPs 12,no leverputa LPs 1022purba leverputa LPS Sadirkhal MEs 1038 no leverputa saranarthi LPS 1609 Syed pur janata LPS Said pur pt I Lps 1254 no Nehru Memorial LPS Nirdhon colony LPS Leverputa Border MEs 1300 Narapati lps Kalibari lps SANKARDEV PATSHALA 243 No Saidpur Lps Modoni lps 986 No B.P Chaliha lps SAIDPUR JANATA HIGH Saidpur AMTOLA lps 985 NO BIBEKANANDA LPS SWARNA MOYEE LPS 1426 NO. RAM KRISHNA LPS 954 RAJYESWAR PUR LPS Digorkhal High school 935 no Haidori Lps 618 NO MOHADEB PUR LPS SARASWATI VIDYA PITH LPS CHANDI PUR LPS PAIKAN PATSHALA LPS 1021 SARASPUR LPS 320 SARASPUR LPS SARASPUR NEW LPS RAJESWARPUR LPS (UPGRADED) Azizur Rahaman Laskar Lps Uttar Haritikar LPS DAKSHIN SEWTI NAYAGRAM LPS 753 NO. SOUTH BHUBANESWAR NAGAR LPS 1484 NO. KAYARPER LPS MIRJAN ALI CHOUDHURY ME SCHOOL 1388 No Nayagram L.P. School 1487 No Mainarpar L.P. School. 687 No D.K. Nath L.P. School 849 No Niz Katigorah L.P. School Abdul Jalil Choudhury Memorial MES 861 NO RANGHAR LPS 244 NO RONGHAR LPS RONGGHAR PT-3 NEW LPS 387 NO HIYARBOND LPS 882 HIARAPAR LPS 284 NO HIYARBOND LPS RADHA CHARAN MES 596 GOBARDHAN URANG LPS 1084 UTTAR SONAPUR LPS DAKSHIN SONAPUR LPS 726 MORAIHTAL LPS MIDDLE NAYAGRAM NEW LPS 1301 no sinjuripar lps Harangpar new lps Gorolarpar lps NANGBI SINGHA LPS

Patharighat - Fisheries/Pond | In total 16 nos. of pond has been affected with 60.22 Ha water area as reported by Fishery Deptt on 16/5/22 and 17/5/2022,

Power Dept. Poles | In total 19 nos. of pole damaged and conductor snapped at various areas under the Circle as Reported by SDE, APDCL, Sipajhar on 17/5/2022,

Anganwadi Centres Affected | As reported by CDPO, Patharighat 12 nos. of AWC centres partially submerged by flood water on 17/5/2022,

Mangaldoi - Fisheries/Pond | As reported by Fishery Department a total of approximately 1127 fish farmers are affected as of now and total water area affected is 107.16 Ha. (approx),

Power Dept. Poles | As per report received from APDCL approx. 10 nos of poles are damaged due to flood as of now.. Dated 18/05/2022,

Power Dept. Conductors | As per report received from APDCL approx. 4.5 km of HT< conductors are damaged due to flood as of now. Dated 18/05/2022.,

Dalgaon - Fisheries/Pond | as per the report received from Fishery Dev. Officer, Kalaigaon and Dalgaon Dev. Block, 21nos of villages, 667 nos of fish farmers and 130.31Ha water area affected due to flood. dated 18/05/2022,

Sipajhar - Anganwadi Centres Affected | One no namely Khatikuchi Mini as reported by DSW on 18/05/2022,

Power Dept. Poles | Total 6 nos. (5 nos. At Dhalpur and 1 no. pole at Bijulibari) as reported on 18/05/2022,

Power Dept. Conductors | Total 900 mtrs (in Dhlapur 800 mtrs and 100 mtrs at Bijulibari) as reported on 18/05/2022, Fisheries/Pond | Kabeichuba: 1 fishfarmer, 0.20 hectares. Satgharia: 3 nos. Of fishfarmers, 0.50 hectare. Basachuba: 15 nos. Of Fishfarmers, 1 Hectare. Patgirichuba: 100 nos. Of Fishfarmers, 4 hectare (as reported by Fishery Deptt. dated 17/05/2022)

Moran - Damaged RCC Bridge | As per PWD Moran Territorial Road Sub-division report 7th km. of Sensua Naharani Ali, Lat: 27.2239;Long: 94.8039;22; Date: 12th May 2022,

Damaged SPT Bridge | As per PWD Moran Territorial Road Sub-division report 20th km. of Borphukan Ali, Lat: 27.1339; Long: 94.7539;; Date: 13th May 2022,

Chabua - Elementary Schools Damaged | DODHIA ME SCHOOL SUBMERGED as per information received from Inspector of Schools, as on 17.05.2022,

Elementary Schools Damaged | DODHIA KULIGAON LPS SUBMERGED as per information received from Inspector of Schools, as on 17.05.2022.

Elementary Schools Damaged | DODHIA KARMI LPS SUBMERGED as per information received from Inspector of Schools, as on 17.05.2022,

Elementary Schools Damaged | DODHIA TENGABARI LPS SUBMERGED as per information received from Inspector of Schools, as on 17.05.2022,

Anganwadi Centres Affected | DODHIA TENGABARI AWC SUBMERGED as per information received from Social Welfare department as on 16.05.2022,

Anganwadi Centres Affected | DODHIA AWC SUBMERGED as per information received from Social Welfare department as on 16.05.2022,

Health Sub-Centre | DODHIA KULIGAON SUB-CENTRE SUBMERGED as per information received from Jt. director of health department, as on 16.0.52022,

Naharkatia - Elementary Schools Damaged | Due to constant rainfall Bidyamandir LPS under Naharkatia Revenue Circle partially submerged as per report received from Block elementary education office as on 18-05-2022

Darrang

Dibrugarh

Inrigation damaged as on 18/05/2022. GPS Cordinates: Lalitude: 25 971379 Longitude: 90.866769, Matia: Anod Treached The Approach road of Tirgation Department comercting Mussive Islampur with Dohela has been breached by overflowing water of Dudhin River. Total beach length: 40 meter (approx.) as on 18/05/2022. GPS Coordinates: 2.6 0.66602, 90.768088 Rangia: Power Dept. Conductors: I Tronductors around 300m in village Karara Garbhitor was damaged as reported by SS APOL, 350 bib-19, Rangia on 175, 2022. Power Dept. Poles: I A pole was dismaged in village 2 No. Dobok due to rain water on 17.05.2022 as reported by SSD, APOL, 350 bib-19, Rangia on 175, 2022. Power Dept. Transformers: I 2 Nos. Transformer 63 KVa and 100 KVa in village Rangia: Town, adjacent to refer Barlia, near: Bhuria Bas stand was shifted as it was in averager position as reported by 505. APOL, 350 bib-19, Rangia, Power Dept. Poles: I 2 Nos. of 17 pole was damaged in village Pudiana on 17.05.2022 as reported by SSD, APOL, 350 bib-19, Rangia Biburia: Fisheries/Pond I As reported by Asst. Fishery Officer, Karunabari Dev. Block on 18/05/2022. 200 nos. ponds affect at 18 Nos. 10		
Rampia - Power Dest. Conductors I.T conductors around 300m in village Karara Garbhror was damaged as reported by SE APOLS, 30b Div-II, Rangia in 275. 2022. Power Dest. Poles A pole was damaged in village 2 No. Dobok due to rain water on 17.05.2022 as reported by SDE, APOC SUD Div-II, Rangia in 275. 2022. Power Dest. Poles 2 Nos. of I.T pole was damaged and 100 KVa in village Rangia Town, adjacent to river Baralia, near. Bhatra Bus stand was shifted as it was in a very danger position as reported by SSD, APOCL Sub Div-II, Bhatra Bus stand was shifted as it was in a very danger position as reported by SSD, APOCL, Sub Div-II, Bhatra Bus stand was shifted as it was in a very danger position as reported by SSD, APOCL, Sub Div-II, Bhatra Bus and Was shifted as it was in a very danger position as reported by SSD, APOCL, Sub Div-II, Bhatra Bus and Was Alley and the Old Process of SSD, APOCL, Sub Div-II, Bhatra Bus and SSD, APOCL, Sub Div-II, Bhatra Bus ARIA SSD, APOCL, APOCL, APOCL, APOCL, Sub Div-II, Bhatra Bus ARIA SSD, APOCL,	Goalpara	Matia - Road Breaches The approach road of Irrigation Department connecting Muskuri Islampur with Dohela has been breached by overflowing water of Dudhnoi River. Total beach length = 40 meter (approx.) as on 18/05/2022. GPS Coordinates - 26.072092, 90.758726, Irrigation Canal/Scheme Damaged Islampur Point Matia LIS staging has been damaged by increasing water level of Dudhnoi
at No. 1. Dharmapur, 50 nos. ponds affected at No. 2 Kehutoli, and 40 nos. ponds affected at Kehutoli Block, Narapapur - Power Dept. Poles Don 324 vPS cpole uproted at Howardajan due to flood on 17-05-2022, Fisheries/Pond Flood damge ponds - 25 nos Area affected 4.46 ha under Rangoti GP. Fishery dept on 18-05-2022 Raha - Fisheries/Pond VILLAGE-BAJBATARMARI, AREA SUBMERGED-SHAC(APPROX), TOTAL POND/TANK-20, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHENGAIAN, AREA SUBMERGED-3.5HAC(APPROX), TOTAL POND/TANK-15, DATE OF OCCURANC 17/05/2022, Fisheries/Pond VILLAGE-SALMARA, AREA SUBMERGED-3.5HAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANC 17/05/2022, Fisheries/Pond VILLAGE-SALMARA, AREA SUBMERGED-4.5HAC(APPROX), TOTAL POND/TANK-20, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-SALMARA, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-20, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-DALIMBARI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-15, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-DALIMBARI GARNT, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-4, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-4, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-4, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-8, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-8, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHARMUKH AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHARMUKH AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-12, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHARMUKH AREA SUBMERGED-0.5HAC(APPROX), TOTAL POND/TANK-12, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHARMUKH AREA SUBMERGED ON 17/05/2022, DEPARTMENT NAME-PUBLIC HEALTH ENG	Kamrup	Rangia - Power Dept. Conductors LT conductors around 300m in village Karara Garbhitor was damaged as reported by SDE, APDCL, Sub Div-II, Rangia on 17.5.2022, Power Dept. Poles A pole was damaged in village 2 No. Dobok due to rain water on 17.05.2022 as reported by SDE, APDCL, Sub Div-II, Rangia , Power Dept. Transformers 2 Nos Transformer 63 KVa and 100 KVa in village Rangia Town, adjacent to river Baralia, near old Bhutan Bus stand was shifted as it was in a very danger position as reported by SDE, APDCL, Sub Div-I, Rangia on 17/05/2022., Power Dept. Poles 2 Nos. of LT pole was damaged in village Udiana on 17.05.2022 as reported by SDE, APDCL, Sub Div-II,
Raha - Fisheries/Pond VILLAGE-BAJBATARMARI, AREA SUBMERGED-SHAC(APPROX), TOTAL POND/TANK-20, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHENGAJAN, AREA SUBMERGED-3.5HAC(APPROX), TOTAL POND/TANK-15, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-CHARAJURIA, AREA SUBMERGED-3.5HAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-SALMARA, AREA SUBMERGED-4.5HAC(APPROX), TOTAL POND/TANK-20, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-JORDUBA, AREA SUBMERGED-2.0HAC(APPROX), TOTAL POND/TANK-15, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-DALIMBARI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-1, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-4, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-4, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-8, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-6, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-BALIJURI, AREA SUBMERGED-3.2HAC(APPROX), TOTAL POND/TANK-6, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-SEWGURI AREA SUBMERGED-3.2HAC(APPROX), TOTAL POND/TANK-15, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-HARDARIJARANI AREA SUBMERGED-3.2HAC(APPROX), TOTAL POND/TANK-12, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-HARDARIJARANI AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-12, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-HARDARIJARANI AREA SUBMERGED-1.5HAC(APPROX), TOTAL POND/TANK-20, DATE OF OCCURANCE 17/05/2022, Fisheries/Pond VILLAGE-BARDARIJARANI AREA SUBMERGED ON 17/05/2022, DEPARTMENT NAME-PUBLIC HEALTH ENGINEERING, PWSS Damaged CHARAJURIA PWSS SCHEME WAS SUBMERGED ON 17/05/2022, DEPARTMENT NAME-PUBLIC HEALTH ENGINEERING, PWSS Damaged DARAMURIA PWSS SCHEME WAS SUBMERGED ON 17/05/2022, DEP	Lakhimpur	Narayanpur - Power Dept. Poles One 33kv PSC pole uprooted at Howajan due to flood on 17-05-2022.,
ENGINEERING, PWSS Damaged AMTOLA PWSS SCHEME WAS SUBMERGED ON 17/05/2022, DEPARTMENT NAME- PUBLIC HEALTH ENGINEERING, Irrigation Canal/Scheme Damaged LAUPANI LIFT IRRIGATION SCHEMEWAS SUBMERGED ON 17/05/2022, DEPARTMENT NAME-IRRIGATION,	Nagaon	IADIA - FISHORIES/POND VILLAGE-BAJBATARMARI, AREA SUBMERGED-SHAC(APPROX), TOTAL POND/TANK-20, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHENGAJAN, AREA SUBMERGED-3.SHAC(APPROX), TOTAL POND/TANK-15, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHARAJURIA, AREA SUBMERGED-2.SHAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-SALMARA, AREA SUBMERGED-4.SHAC(APPROX), TOTAL POND/TANK-20, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-JORDUBA, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-15, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-DAILMBARI, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-1, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-DAILMBARI GARNT, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-4, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BANDURA ATI, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-4, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BANDURA ATI, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-4, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIURI, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-8, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIURI, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIURI, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIURI, AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-BALIURIA AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHARAJURIA AREA SUBMERGED-1.SHAC(APPROX), TOTAL POND/TANK-10, DATE OF OCCURANCE-17/05/2022, Fisheries/Pond VILLAGE-CHARAJURIA AREA SUBMERGED ON 17/05/2022, DEPARTMENT NAME-PUBLIC HEALTH ENGINEERING, PUBLIC HEALTH ENG

		Banekuchi - Irrigation Canal/Scheme Damaged Burhadia ELIS point 1, 2,3 Village :Kashimpur have submerged on 18/5/2022
		as per report from Irrigation department. Lat 26.512345 and Long 91.440158,
		Culvert Approach Road Damaged Makrapar to Sahpur pwd road appro. 800 mtr. submerged. Dated on 18/5/2022 as per
		report from Gaon Pradhan ,
		Agri Bundh Damaged Sanora to Nakerbari Agree road submerged appr.700 mtr .Dated on 18/5/2022 .As per report from
		Gaon Pradhan.,
		Culvert Approach Road Damaged As per report of PWD department dated on 18/5/2022 Kendukuchi to Gohairkhat road culvert approach damaged .Lat 26.511361 Long 91.420342,
		Culvert Approach Road Damaged As per report of PWD department dated on 18/5/2022 Kendukuchi to Pub Kendukuchi
	Nalbari	apprach damaged and erosion .Lat 26.518797 Long 91.414948,
		Paschim Nalbari - Bridge Approach Road Damaged Approaches damaged of RCC Br. No. 1/1 on Barbila Lokhopur road via
		Sarthebari. Information received from AEE, PWRD Department on 18/05/2022,
		Irrigation Canal/Scheme Damaged Burhadia ELIS Point No. 4, Burhadia ELIS Point No- 5 and Amoni ELIS submerged. As per
		information received from JE, Irrigation Department on 17/05/2022, Tihu - Power Dept. Poles HT pole:6nos, Lat/Long:91.238732/26.419026, Date of Occurance :18/05/2022, information
		received From Official, APDCL, Tihu,
		Power Dept. Conductors Length:800 mts, Lat/Long:91.238732/26.419026, Date of Occurance :18/05/2022, information
		received from official of APDCL, Tihu
		Thelamara - Power Dept. Conductors DATE- 18/05/22, AT 11 KV GARUBANDHA FEEDER AND 11 KV BELSIRI FEEDER, 4
		CONDUCTORS, 19 PIN INSULATORS, 7 DISC INSULATORS, 4 T X-ARMS damage as reported by APDCL,
	Sonitpur	Power Dept. Poles DATE- 18/05/22, AT 11 KV GARUBANDHA FEEDER AND 11 KV BELSIRI FEEDER, 8 POLE DAMAGE, 1 25 KVA DTR damage as reported by APDCL,
		Dhekiajuli - Culvert Approach Road Damaged Damage observed at Pwd culvert approach at Dhekiajuli Ward no 8, near
		Dhekiajuli Girls school dtd 17/05/2022
		Tamulpur - Gully Control Damaged Village-Kusumjuli no 1,Date-17/5/22.Name of infrastructure-RCC Check dam.Breaching of
		earthen bank and periphery bundh, Damaging of boulder pitching at wing wall, infront of head wall and at back side of toe
		wall.Latitude-26.720184,Longtitude-91.619353.Damaged area-Earthen bank-600sqm,Earthen Periphery bundh-400
		sqm,Boulder-150cum, Protection Bundh Damaged Village-Motigaon,Date-17/5/22.Name of infrastructure-Boulder revetment cum
		pitching.leaching of bank soil and displacement of boulder at slopes in some structural part.latitude-26.728782,longtitude-
	Tamulpur	91.626658.Damaged area-Earthen bank-120 sqm,boulder-40cum.,
		Protection Bundh Damaged Village -Kusumjuli No1,Date-17/5/22.Name of infrastructure-Boulder revetment cum
		pitching.leaching of bank soil and displacement of boulder at slopes in some structural part.Latitude-26.719941,Longtitude-
		91.619265.Damaged area-Earthen bank-100 sqm,Boulder-32cum., Protection Bundh Damaged Village-Daimabari,Date-17/5/22.Name of infrastructure-Boulder Revetment cum
		pitching.Leaching of bank soil and displacement of boulder at slopes in some structural part.Latitude-26.718872,Longitude-
		91.618713.Damaged area-Earthen bank-83cum,boulder-27cum
		Udalguri - Bamboo Foot Bridge Bamboo Bridge washed away at Bhairaguri (Dakhin Bhairaguri) road connecting Bhairaguri to
		Bachal Chuburi around 25m in lenght on 17.05.2022. GPS - Lat - 26.659449 Long - 92.061179 ,
		Khairabari - Irrigation Canal/Scheme Damaged Chewni FIS embankment breached at Ch.700.00m of Main Canal; Lon: 91.800163: Lat: 26.636431; Date of Occurance: 17.05.2022,
		Irrigation Canal/Scheme Damaged Kalapani- Jhargaon FIS river embankment breached. Long: 91.854015; Lat: 26.58793; Date
		of Occurrences: 17.05.2022,
	Udalguri	Irrigation Canal/Scheme Damaged Harharia FIS embankment brech at Ch. 30.00m & Ch.200.00m of river: Long:
		91.785069; Lat: 26.665421; Date of Occurrences: 17.05.2022,
		Irrigation Canal/Scheme Damaged Mayakhat FIS river embankment breached at head works. Long: 91.816783, Lat:
		26.626462; Date of Occurrences: 17.05.2022, Harisinga - Culvert Approach Road Damaged orangajuli VCDC to Kalanadi Culvert damaged due to continuous rainfall. on
		17th may 2022. approximate damage 124.8m. Lattitude 26.7731, Longitude 91.7135,
		Damaged RCC Bridge RCC bridge No. 54/4 om MB road near Bhootiachang. on 17th may 2022. Approximate damage 3m.
	District	Details
		Chenga - Roumari Pathar, Roumari Gaon, Kachumara Due to erosion approx. 8 bighas land eroded by the Brahmaputra river
		where 12 nos. houses were damaged .Date-17/05/2022 49, Sarthebari - 1. kawaimari Gha Block &2. Neularbhita 1. The ring bundh of Tihu river eroded approx. 150 m. near Sukur Ali
		house to Aynal Haque house & 2 The ring bundh of Tihu river eroded approx. 80 m. near Suresh Mandal, Nitai Mandal &
	Daws - t -	Guru Das Mandal house. (reported by LM. 18.05.2022) 0,
	Barpeta	Kalgachia - 1. Amguri, 2. Shawrachara Pathar 1. PMGSY Road pakage No. AS-01-88 Kalgachia-Karerkur Parghatt via Amguri
		road formation eroded from chainage 2.250 Km to 2.400 Km due to continous erosion of Beki river(Length=150.00m,
		Width=5.50m, Location- 26.337315, 90.878487). 2. In Shawrachara Pathar 1 no of kutcha house eroded, total Basti land
		eroded- 0B-2K-10L, Family affected-1 and population affected-6 nos. Location coordinates- 26.265169, 90.833959 .Date-18- 05-2022 0
Erosion	Bongaigaon	Boitamari - Bhairab pahar NC Sankarghola to borjuli road under balapara gp. Soil erosion on 17/05/2022 0
		Sonari - Tiok Gaon Erosion on Trolly Road of Tiok Gaon by Teok River dated 17.05.2022 as per the information received from
	Charaideo	WRD on 18.05.2022. 0
	Chirang	Bengtal - Sashipur FV Erosion occurred due to heavy rain on 17-05-2022 by Taklai River on L/B Length = 400m Width = 5.5 m
		Depth = 4.0 m 0
	Darrang	Sipajhar - Khalihoi Pathar- Kiringbori Occured on 15/05/2022 and reported by WRD on 17/05/2022 at 6.23 pm Almost 300 mtrs. (1 bigha 2 katha approx). Erosion is still occuring. 0
		South Salmara Part - Borkalia Surjomoni As information received from concerned BEEO, Chatlarpar M.E School eroded due
	District.	to erosion by river Brahmaputra dated 17-05-2022 to 18-05-2022 at Village-Borkalia Surjomoni (Matifata) under south salmara
	Dhubri	rev Circle Dist Dhubri. Area 3 bigha 2 Katha 10 Lessa Lat-25.94,Long-90.04 0,
		Bilasipara - At village- Suapata pt-i, suapata pt-ii, suapata pt-iii and kajaikata pt-ii recently an erosion have taken place due to

		raising of water level of river Gaurang, The details of the area eroded are given below 1. Name of Village:- Suapata pt-ii, suapata pt-ii, suapata pt-ii, kajaikata pt-ii 2. Date of incident:- 16-05-2022 to 18-05-2022 3. GPS co-ordinates:- a. Lat:- 26. 190792 N & Longitude:- 90.287953 E b. Lat:- 26. 191665 N & Longitude:- 90.272003 E c. Lat:- 26. 199714 N & Longitude:- 90.263234 E d. Lat:- 26. 206359 N & Longitude:- 90.249069 E 4. Land eroded:- Land measuring around 30 Bigha 03 Katha 15 Lessa 5. Population:- 112 nos 112, Agamoni - Village Bholarkhas under Chotoguma GP under Agomani Rev. Circle. Riverine area of River Gangadhar at vill Bholarkhas under Chotoguma GP is getting eroded slowly. Village: Bholarkhas GP: Chotoguma Incident date: 14/05/2022 to 18/05/2022 Time: 12.00pm Land: 0 bigha 2 khata 10 Lessa Population affected: Nil GPS Coordinate: Lat. 26.3078053. Long. 89.8036509 0
	Dibrugarh	Moran - 1)Lachan Gaya Missing Gaon, 2) DRDA Ring Bund at Moina Gaon As per WRD report erosion is occurring at 2 places namely 1)Lachan Gaya Missing Gaon-length of erosion is 700m, Lat N27.3458 Long E95.0004 as on 17.05.2022 2) DRDA Ring Bund at Moina Gaon- Erosion is occurring at the vicinity of DRDA Ring Bund situated at Moina Gaon length of erosion is 50m, Lat N27 16.32 Long E94 49.30 as on 17.05.2022 0, Dibrugarh West - Bhogamur Tiniali As per report received from Assistant Executive Engineer W.R Department, Dibrugarh that Bank damage measuring 1 KM has been observed at Bhogamur Block Gaon Ring Bund on the right bank of river Buridehing as on 17.05.2022 0
	Kamrup (M)	Chandrapur - 1. Hatisila NEAR Ganesh Mandir, 2. Tatimara Erosion occurred on 18/05/2022 at Tatimara nd Hatisila near Ganesh Mandir Report Received- Water Resource Area- both 1.5km approx Hatisila Coordinates- Longitude-91.887997, Latitude- 26.219384 Tatimara Coordinates- Longitude- 91.917294, Latitude-26.243107 0
	Nalbari	Banekuchi - Makrapar (Sandheli) Have seen erosion appro. 90 mtr at the bank of Morapagladia River at Makrapar Sandheli Village near Krishnaguru Ashram dated on 17/5/2022. Report from Gaon Pradhan 90, Tihu - Near Tihu Nadi Bridge Transformer, 250kva(Electrical), APDCL, Dept. Dated: 18/05/2022 0, Ghograpar - 1. Pub-Barsiral, 2. Bangaon 1. As per information received from W.R Department, Erosion have seen at L/B of river Pagladia on 18/05/2022 at village Pub Barsiral (Nakhat), Length - 350 M, Lat - 26.5420, Long - 91.5204 2. As per information received from W.R Department, Erosion have seen at L/B of river Pagladia on 18/05/2022 at village Bangaon (Smashan Ghat), Length - 300 M, Lat - 26.5523, Long - 91.5310 0
	Sivasagar	Demow - Dehing Kalghar Erosion at Dehing bund left bank from Laibeel to Dehingmukh due to heavy rain for a length of 700 metre as on date 18th may 2022. As per report received from WR Department, Demow Sub-Division. 0
	Sonitpur	Dhekiajuli - Heavy erosion observed along the bank of Dheraimajuli by the Belsiri river. Aprox length 300 mts. dated 17.5.22 Dheraimajuli 0, Chariduar - BERAJAN LENGTH 310 KM EROSION OF THE RIGHT BANK OF RIVER JIABHARALI DTD 18/05/2022 0
	Tamulpur	Tamulpur - Ghogapar, Dalangpar, Chauraguri, Hahkata, Bhalukmari, Ghilajar, Sontala. 1. Ghogapar village(date-15/5/22)-Bank erosion on right bank of river Matanga in a reach length = 200m (91.41 E ,26.36 N ,affected area-800 sqm). 2. Dalangpar village(date-15/5/22)- Bank erosion on right bank of river Matanga in a reach length = 250m (91.34 E, 26.38 N, affected area-1250sqm). 3. Chauraguri village(date-15/5/22)- Bank erosion on right bank of river Matanga in a reach length = 200m (91.35 E 26.37 N, affected area-1000 sqm). 4. Hahkata village(date-18/5/22)- Bank erosion on left bank of river Pagladia in a reach length= 150m (91.30 E 26.35 N, affected area-900 sqm) 5.Bhalukmari village(date-18/5/22) - Bank erosion on left bank of river Balti in a reach length= 800m (91.6498E 26.6813N, affected area-7500 sqm) 6. Ghilajhar Village(Masmoria Chupa,date-18/5/22)- Bank erosion on left bank of river Balti in a reach length= 800m (91.655713 E 26.678908 N, affected area-8000sqm). 7. Ghilajhar Village(Paschim Chupa,date-18/5/22)-Bank eroision on left bank of River Balti in a reach length =750 m.(91.649153E 26.685926N, affected area-7500 sqm). 8. Sontola village (date 18/5/22)-Bank eroision on LB of river Borolia in a reach length =150 m(91.640668E 26.580555N, affected area 1500 sqm). 0, Goreswar - 1. West Bank of River Suklai Village Tengajhar 2. West Bank of sub tributary river Naobandha Village bholajhar 1. 17/05/2022 Bank erosion on the west bank of river Suklai at Village Tengajhar (madalbari suba) approximate damage 200m, no active erosion reported on 18/05/2022. 2. As reported by the Range officer Soil conservation Range Goreswar, erosion occurred at the west bank of sub tributary river Naobandha at the protection work of Naobandha Suklai river erosion protection project under RIDF-XXV/2020-21. DATED 17/05/2022. Approx damage 30m. Lat - 26.682681, Long - 91.728410 . No active erosion reported on 18/05/2023 0
	Tinsukia	Sadiya - Majgaon (Amateur) As per information received from concerned gaonpradhan river bank erosion is being observed at majgaon(amarpur) on the North Bank of River datung since 12/05/2022 till 18/05/2022. ,the affected stretch is about 250m. 0, Doomdooma - 1. Village: Phelai NC (Nawkata NC), 2. Village: No. 3 Kordoiguri (Goriyating) 1. Severe erosion is being observed at Phelai(Nawkata) area on the left Bank of River Brahmaputra since 5/04/2022 till 18/05/2022. The affected stretch is about 1500 m. 10 m offset remains as of now from the Brahmaputra Embankment.(Long: 95.523457, Lati:27.745786) 2. River Bank erosion is being observed at No. 3 Kordoiguri on the left Bank of River Dangari since 2/04/2022 till 18/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 200 m in length.(Long: 95.468184, Lati: 27.650410), population affected 122. 0
	Udalguri	Udalguri - Sarbaherua, Udalguri Erosion occured on Left bank of Moradhansir river on 18.5.2022 at Srbaserua around 200m 0, Mazbat - 1. Dafalapota village 2. Tekelibil village 3. Phatasimalu 4. Siprangpara 1. Erosion occurred on L/B of river Pagla at Dafalapota(26.726572, 92.27181) village on 17/5/2022. (Length-258m) 2. Erosion occurred on L/B of river Panchnoi at Phatasimalu village(26.61499, 92.36926) on 17/5/2022. (Length-550m) 3. Erosion occurred on R/B of river Pagla at Tekelibil village(26.4455958, 92.1649905) on 18/5/2022. (Length-600m) 4. Erosion occurred on R/B of river Pagla at Siprangpara village(26.4355958, 92.1749905) on 18/5/2022. (Length-300m) 0, Khairabari - CHABUKDHARA Erosion at Village: Chabukdhara by the Kalpani River on the Right Bank: Length: 140m(approx.): Date of Occurrences: 17.05.2022 2500, Harisinga - No.2 Borengajuli Continuous erosion occurred at No.2 Borengajuli due to river Suklai of length 3m from 15th May to 18th May 2022. 0
	District	Details
	Dima-	Haflong - 1. Pangmol, 2. Hungruum 3. Jinamghat 4. Lisong 5. Hindu Baladhan 6. Christian Baladhan Maibang tunnel partially
Landslide	Hasao	operational 500
ļ	Hailakandi	Hailakandi - Mohanpur Grant under Hailakandi Revenue circle on dated 18/5/22 One PMAY house under construction was
	1	

		partially Damage No casualties . 0
Urban Flood	District	Details
	Darrang	Mangaldoi - Mangaldai town Ward No 1,2,3,4,5,6,7∓8 The river Bega and Mangaldai river is over flooded as such the people residing near river banks and low lying areas affected as on 18/05/2022. And moreover heavy fall also caused water logging problems in ward areas. 1200
	Nalbari	Nalbari - Palla Road(Ward No-11), Collage road(ward no-7), Gopal Bazar(W.N-12), Pushpakpur (W.N-10), Bidyapur(W.N-3) Deviram School Road(W.N-2), Hajo Road(W.N-7) Due to continuous raining urban flood is occurred. Report is received from Lot Mandal Dated: 18/05/2022 2600