

FRIMS Assam



Flood Reporting And Information Management System

					on 19-10-2022 at	4:00 PM			
Particulars	Situation as of	on 19-10-	2022 (in las	t 24 hours)					
Rivers flowing above Danger Level (as per	Rivers flowing above danger level			Nil					
CWC bulletin issued at 8 AM)	Rivers flowing above highest flood level			Nil					
District Affected	No. of Districts Affected	Name o	of Flood Aff	ected Districts		Name of Urban Flood Districts			
	1	Golagha	at						
No. Of Revenue Circles Affected	1								
Name Of	District	Total	Revenue	Circle					
Revenue Circles	Golaghat	1	Bokakhat						
Affected	Total	1							
Villages Affected	District	Total Revenue Circle							
	Golaghat	4	4 (Bokakhat 4)						
	Total 4								
Population And	District	Male	Female	Children	Total Population	Population Details	Crop Area (in Hect.)	Crop Area Details	
Crop Area Affected	Golaghat	0	0	0	0	(Bokakhat 0	101.00	(Bokakhat 101.00)	
	Total	0	0	0	0		101.00		
Relief Camps / Centres Opened	Nil	•							
Inmates In Relief Camps	Nil								
Human Lives Lost - Confirmed	Nil								
Human Lives Lost Confirmed - Death Type	Nil								
Human Lives Lost - Missing	Nil								
Human Lives Lost Missing - Type	Nil								
Animals Affected	Nil								
Animals Washed Away	Nil								
Houses Damaged	Nil								
Rescue Operation	Nil								
Relief Distributed	Nil								
Relief Distributed Others	Nil								
Infrastructure Damaged -	Nil								

	1					
Embankment						
Breached						
Infrastructure						
Damaged -	Nil					
Embankments	INII					
Affected						
Infrastructure	Nil					
Damaged - Road	INII					
Infrastructure						
Damaged -	Nil					
Bridge						
Infrastructure						
Damaged -	Nil					
Wildlife						
Infrastructure						
Damaged -	Nil					
Others						
	District	Details				
	Dibrugarh	Dibrugarh East - Philonuguri Grant 4/152 No ORR Grant (Maijan pucca line) Mild erosion still going on as per report received from Water Resource Deptt as on 19/10/2022 GPS coordinates - 94.988 to 27.514 0				
		DU 1 D 1 D 1 D 1 D 1 D 1 D 1 D 1 D 1 D 1				
		Bihpuria - Puroni Bahgorah (Dhunaguri Embankment) Sudden collapse of slope & crest of				
Erosion		embankment due to erosion on R/B of subansiri river at Dhunaguri embankment at Ch.				
Erosion	Lakhimpur					
Erosion	Lakhimpur	embankment due to erosion on R/B of subansiri river at Dhunaguri embankment at Ch.				
Erosion	Lakhimpur	embankment due to erosion on R/B of subansiri river at Dhunaguri embankment at Ch. 2000m/Ch. 2KM. Erosion length is about 20 meters as reported by AEE, WRD, Bihpuria SD on 19/10/2022. (Restoration measures undertaken by Flexituff Ventures International Limited are ongoing.) As apprehensive measures, 08 nos. of tarpaulins have been distributed to 04				
Erosion	Lakhimpur	embankment due to erosion on R/B of subansiri river at Dhunaguri embankment at Ch. 2000m/Ch. 2KM. Erosion length is about 20 meters as reported by AEE, WRD, Bihpuria SD on 19/10/2022. (Restoration measures undertaken by Flexituff Ventures International Limited are ongoing.) As apprehensive measures, 08 nos. of tarpaulins have been distributed to 04 families whose houses are likely to be shifted. 18				
Erosion	-	embankment due to erosion on R/B of subansiri river at Dhunaguri embankment at Ch. 2000m/Ch. 2KM. Erosion length is about 20 meters as reported by AEE, WRD, Bihpuria SD on 19/10/2022. (Restoration measures undertaken by Flexituff Ventures International Limited are ongoing.) As apprehensive measures, 08 nos. of tarpaulins have been distributed to 04 families whose houses are likely to be shifted. 18 Laharighat - Leruamukh As per report of the Water Resources Dept on 19-10-2022, erosion				
	Morigaon	embankment due to erosion on R/B of subansiri river at Dhunaguri embankment at Ch. 2000m/Ch. 2KM. Erosion length is about 20 meters as reported by AEE, WRD, Bihpuria SD on 19/10/2022. (Restoration measures undertaken by Flexituff Ventures International Limited are ongoing.) As apprehensive measures, 08 nos. of tarpaulins have been distributed to 04 families whose houses are likely to be shifted. 18				
Erosion	-	embankment due to erosion on R/B of subansiri river at Dhunaguri embankment at Ch. 2000m/Ch. 2KM. Erosion length is about 20 meters as reported by AEE, WRD, Bihpuria SD on 19/10/2022. (Restoration measures undertaken by Flexituff Ventures International Limited are ongoing.) As apprehensive measures, 08 nos. of tarpaulins have been distributed to 04 families whose houses are likely to be shifted. 18 Laharighat - Leruamukh As per report of the Water Resources Dept on 19-10-2022, erosion				