

## **FRIMS Assam**



## Flood Reporting And Information Management System

	Assam Daily Flood Report as on 11-06-2022 at 4:00 PM										
Particulars	Situation as on 11-06-2022 (in last 24 hours)										
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Nil										
District Affected	No. of Districts Affected	Name of	nme of Flood Affected Districts				Name of Urban Flood Districts				
	4	Dhemaji, Salmara	Lakhimpu	r, Morigaon	, South						
No. Of Revenue Circles Affected	6										
	District	Total	Revenue								
	Dhemaji	3	Dhemaji	, Sissiborga	on, Gogamukl	1					
Name Of Revenue	Lakhimpu r	1	North Lakhimpur								
Circles	Morigaon	1	Morigao	n							
Affected	South Salmara	1	Mankachar								
	Total	6	_	~ ·							
	<b>District</b> Dhemaji	<b>Total</b> 8	Revenue		aamuld (6)	Ciasibonasan	11)				
Villages	Lakhimpu r	1		( Dhemaji   1 ), ( Gogamukh   6 ), ( Sissiborgaon   1 )  ( North Lakhimpur   1 )							
Affected	Morigaon	6	( Morigaon   6 )								
	South Salmara	19	(Mankachar   19)								
	Total	34									
Population And Crop	District	Male	Femal e	Childre n	Total Populatio n	Population Details		Crop Area (in Hect.)	Crop Area Details		
	Dhemaji	1140	1100	658	2898	( Gogamukh   1834 ), ( Dhemaji   644 ), ( Sissiborgaon   420 )		101.00	( Gogamukh   35.00 ), ( Dhemaji   6.00 ), ( Sissiborgaon   60.00 )		
Area Affected	Lakhimpu r	298	188	114	600	( North Lakhimpur   600 )		0.00	( North Lakhimpur   0.00 )		
	Morigaon	0	0	0	0	( Morigaon	( Morigaon   0 )		( Morigaon   345.00 )		
	South Salmara	0	0	0	0	( Mankachar   0 )		199.00	( Mankachar   199.00 )		
	Total	1438	1288	772	3498			645.00			
Relief	District	Total	Relief C				Relief Distribution Centres				
Camps / Centres Opened	Dhemaji	2	0(Dhemaji   0, Sissiborgaon   0)				2(Dhemaji   1, Sissiborgaon   1)				
	Total	2	0			2					
Inmates In Relief Camps	Nil	il									
Human Lives Lost - Confirmed	Nil Nil										
Human Lives Lost Confirmed -											

Death Type												
Human												
Lives Lost -	Nil											
Missing												
Human												
Lives Lost Missing -	Nil											
Type												
	District	Total	Big	Small	Poultry							
Animals Affected	Dhemaji	700	360	340	0							
	Total	700	360	340	0							
Animals Washed Away	Nil											
Houses Damaged	Nil											
Rescue Operation	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d		
	South				0	0	0	0	0	1		
	Salmara Total				0	0	0	0	0	1		
	Total				U	Cattle	Cattle	U	U			
Relief Distributed	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Feed - Green Fooder (in Q)	Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)				
	Dhemaji	18.11	3.19	0.94	95.76	0.00	0.00	0.00				
	Total	18.11	3.19	0.94	95.76	0.00	0.00	0.00				
Relief		Baby Foo	L	d								
Distributed	District	Liquid		Baby Foo	d Solid Others							
Others Infrastructur	Dhemaji         0.00-Q         0.00-Q											
e Damaged - Embankmen t Breached	Nil											
Infrastructur	District	Numbe r	Details	Details								
e Damaged - Embankmen t Affected	Lakhimpu r	1	B/Bamb		as been obser			nua Village   R on) of Singra R				
	Total	1	, ,									
	District	Numbe	Details	Datoile								
	District	r										
Infrastructur e Damaged - Road	Dhemaji	1	Causewa no .AS-0	<b>Dhemaji</b> - L034-Seujiapathar - Yedotgaon PWD road   Seujia pathar   Today on 11:06/2022, Causeway breached (L-20.00m) occurred at L034-Seujiapathar - Yedot Gaon Road (PMGSY Package no .AS-04-209A)								
	Kamrup	1	nagarber	Nagarbera - Hekra to nagarbera road   Village -Nagarbera   Road submergence of the road namely nagarbera to hekra road had taken place on 9-6-2022 and the same has been reported by EE PWD Boko territorial road sub division dated 10-6-2022								
	South Salmara	3	Mankac NEC roa Mankach The deta Phutiman way, side damaged	Mankachar - 1. Bansali NEC road to Puthimari Bazar road, 2. Manjuri ti Niz Chirakhowa road, 3. NEC road to Pahartoli road.   1. Bansali, 2. Manjuri, 3. Thakuranbari   As per report submitted PWRD, Mankachar Territorial Road, Mankachar Division, road damaged due to Flash Flood on 09/06/2022. The details as shown below- 1. Hard crust, side berm and embankment of Bansali NEC road to Phutimari Bazar road submerged and badly damaged from CH. 4100.00 M to 4500.00 M. 2. Carriage way, side berm and embankment of Manjuri to Niz Chirakhowa road damaged submerge and badly damaged from CH. 4500.00 M to 5500.00 M. 3. NEC road to Pahartoli road has been washed out due to Flash Flood.								
	Total	5										
	District	Numbe r	Details	Details								
Infrastructur e Damaged - Bridge	South Salmara	1	Mankachar - 1. Timber bridge No. 1/1 on Kazipur Toppara   1. Chirakhowa Toppara   As per report submitted concerned department PWRD, Mankachar Territorial road Sub- Division, Mankachar and G.P. Secretary, Kalapani GP. The wooden bridge of Kazipur Toppara has been damaged by devastating Flash Flood of Kalo river on 09-06-2022.									

	Total	1							
Infrastructur e Damaged - Wildlife	Nil								
Infrastructur e Damaged - Others	District	Other Details							
	Dima- Hasao	Haflong - Handloom & Textile Deptt   Damage of Retaining wall behind the quarter of Superintendent, Handloom & textiles, Haflong as per report received from o/o the asstt. Director, Handloom and Textiles dated 23/05/2022,  Damaged RCC Bridge   The bridge is not actually damaged but a joint application is received from the nearby residents dated 21/05/2022 that due to the presence of the bridge, water is not able to flow smoothly during rainy season wherein solid wastages are blocked and causing the water flow of the sream stride towards another directions resulting the water to enter in their houses and causing damages to their properties.							
	Goalpara	Balijana - Power Dept. Poles   4 nos. of LT Poles damaged in village Sabaji Baguan (Baruapara). Date of occurrence 06.06.2022. and Final report received from APDCL Department, Lakhipur Electrical Sub Division on 10.06.2022.,  Power Dept. Conductors   LT Conductor of 0.3 Km damaged in village Sabaji Baguan (Baruapara). Date of occurrence 06.06.2022 and Final report received from APDCL Department, Lakhipur Electrical Sub Division on 10.06.2022.							
	South Salmara	<b>Mankachar</b> - Fisheries/Pond   As per report submitted Fishery Department, Mankachar has been damaged due to Heavy Rainfall in Fishery Pond of total 104 Nos. under Mankachar Rev. Circle on 11-06-2022.							
	District	Details							
	Biswanath	<b>Naduar RC part</b> - 2. NO Bhojmari   Severe bank erosion at 2. no Bhojmari area on right bank of river Brahmaputra, length= 800m on 11-06-2022   0							
Erosion	Hailakand i	Algapur - Kalinagar Pt-3, near Katakhal Police Out Post, L/B of river Barak under Algapur Revenue Circle dtd. 08-06-2022   Vertical settlement along with river erosion touching the toe of the embankment / eroded embankment and is progressing further. During draw down stage of river Barak. Damage report as submitted by Water Resource Division, Hailakandi   20000							
	Morigaon	<b>Laharighat</b> - Leruamukh ,Goroimari , Borchapori & Bhajakhaiti   As per report received from Water Resources Dept on 11-6-22, erosion occurred in Leruamukh ,Goroimari , Borchapori & Bhajakhaiti with max erosion at Leruamukh of 4m, goroimari 0m , Borchapori 2m & Bhajakhaiti 2m respectively.   0							
	Sonitpur	Chariduar - MOLAN GAON CHARIDUARREVENUE CIRCLE   LAND ERODED AT MOLANGAON VILLAGE UNDER CHARIDUA RVENUE REVENUE CIRCLE   LENGTH 50 M DTD 11/06/2022   0							
	Tinsukia	Doomdooma - 1. Village: No. 1 Kordoiguri(Darjijan), 2. Village: No. 2 Kordoiguri (Simoluguri Satra).   1. River Bank erosion is being observed at No. 1 Kordoiguri (Dorjijan)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 11/06/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 410 m in length.(Long: 95.450531, Lati: 27.651217), population affected 37. 2. River Bank erosion is being observed at No.2 Kordoiguri (Simoluguri Satra)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 11/06/2022. As per information received from concerned Lot Mandal and WR department officials, the affected stretch is about 462 m in length.(Long: 95.4505, Lati: 27.65196)   0							
Landslide	Nil	701.1000 ; 24th 2.100.170) <sub>[</sub> 0							
Urban Flood	Nil								