

FRIMS Assam



Flood Reporting And Information Management System

			Assam	Daily Flood Report as on 2	21-06-2022 at 4:00 PM					
Particulars	Situation as	on 21-06-2		(in last 24 hours)						
Rivers flowing above Danger	Rivers flowi	ng above d	anger	Kopili (Dharamtul), Bra	hmaputra (Dhubri; Goalpara; Guwahati; Tezpur; Neamatighat)					
Level (as per CWC bulletin issued at 8 AM)	Rivers flowi flood level	ing above h	ighest	Kopili (Kampur)						
	No. of			L						
	Districts Affected	Name of	Flood Affe	ected Districts	Name of Urban Flood Districts					
District Affected	32	Bongaiga Dhemaji, Goalpara, Kamrup, Karimgar Morigaon Sonitpur,	on, Cachar, Dhubri, Di Golaghat, Kamrup (M ij, Kokrajha i, Nagaon, I South Saln	ta, Biswanath, , Chirang, Darrang, , brugarh, Dima-Hasao, Hailakandi, Hojai, f), Karbi Anglong West, ar, Lakhimpur, Majuli, Nalbari, Sivasagar, nara, Tamulpur,	Cachar, Darrang, Goalpara, Karimganj					
No. Of Revenue Circles	121	Tilisukia,	a, Udalguri							
Affected										
	District	Total	Revenue	Circle						
	Bajali	2	Sarupeta,	, Bajali						
	Baksa	3	Barama,	Barnagar RC part, Jalah						
	Barpeta	6		Chenga, Baghbar, Sartheb						
	Biswanath	4		Biswanath, Naduar RC par						
	Bongaigao n	3	Manikpur, Boitamari, Srijangram							
	Cachar	5	Silchar, I	Lakhipur, Sonai, Udharbond, Katigorah						
	Chirang	2	Bijni, Be	ngtal	-					
	Darrang	4	Mangald	oi, Dalgaon, Sipajhar, Path	narighat					
	Dhemaji	3	Jonai, Sis	ssiborgaon, Dhemaji						
	Dhubri	8	Dhubri, A	Agamoni, Gauripur, Chapa	r, Bilasipara, South Salmara Part, Golakganj, Athani					
	Dibrugarh	1	Chabua	•						
	Dima-	1	Haflong							
	Hasao									
Name Of	Goalpara	4		alijana, Lakhipur, Dudhnoi	i					
Revenue	Golaghat	2	1	t, Khumtai						
Circles	Hailakandi	4		Katlicherra, Hailakandi, L	ala					
Affected	Hojai	3		oboka, Lanka	'N I O V I O V I V I O					
	Kamrup Kamrup	3		Goroimari, Kayan, Palashb pur, Sonapur, Dispur	ari, Nagarbera, Chaygaon, Kamalpur, Chamaria, Hajo, North Ghy					
	(M) Karbi Anglong West	1	Donkamo	<u> </u>						
	Karimganj	5	Nilambaa	zar, Patherkandi, RK Naga	r, Badarpur, Karimganj					
	Kokrajhar	4		on, Kokrajhar, Bhawragur						
	Lakhimpu r	6			a, Subansiri, Narayanpur, North Lakhimpur					
	Majuli	2	Uiani Ma	ajuli, Majuli						
	Morigaon	4		Laharighat, Bhuragaon, M	Iorigaon					
	Nagaon	7		Kampur, Kaliabor, Rupahi						
	Nalbari	7		1	Fihu, Barbhag, Paschim Nalbari, Nalbari					
	Sivasagar	1	Sivsagar		,					
	Sonitpur	5		r, Naduar, Thelamara, Dhe	ekiajuli, Tezpur					
				* * *	· · · · · · · · · · · · · · · · · · ·					

	South	2	South Sal	lmara, Manka	achar					
	Salmara				acııaı					
	Tamulpur	2		r, Tamulpur						
	Tinsukia	5		, Doomdoom		: V-1-:				
	Udalguri Total	121	Odalguri,	dalguri, Mazbat, Khairabari, Harisinga, Kalaigaon						
	District	Total	Revenue	evenue Circle						
	Bajali	173		Sarupeta 78), (Bajali 95)						
	Baksa	31				20), (Baganpara 4), (Ja	lah 4)			
	Barpeta	609		145), (Che		Baghbar 141), (Sarthebar		gachia 100), (
	Biswanath	19		Biswanath 1), (Naduar RC part 3), (Halem 15)						
	Bongaigao n	167		Manikpur 2), (Boitamari 56), (Srijangram 109)						
	Cachar	506	(Silchar	126). (Lak	hipur 104). (Sonai 79), (Udharbond	43), (Katig	orah 154)		
	Chirang	8), (Bengtal		(7, (
	Darrang	457), (Sipajhar 69), (Patha	righat 86)			
	Dhemaji	59					<i>8</i> <i>7</i>			
	Dhubri	721	(Dhubri	(Jonai 31), (Sissiborgaon 25), (Dhemaji 3) (Dhubri 62), (Agamoni 88), (Gauripur 62), (Chapar 1), (Bilasipara 201), (South Salma Part 164), (Golakganj 23), (Athani 120)						
	Dibrugarh	1	(Chabua		J1 - // (-	. 1 - 7				
	Dima-	1	Ì	· ·						
	Hasao	1	(Haflong							
	Goalpara	369				khipur 137), (Dudhnoi	1), (Rongjul	i 9)		
	Golaghat	38		Matia 94), (Balijana 128), (Lakhipur 137), (Dudhnoi 1), (Rongjuli 9) Bokakhat 34), (Khumtai 4)						
	Hailakandi	124				(Hailakandi 30), (Lala	35)			
	Hojai	88			a 35), (Lan					
Villages	Kamrup	425		(Rangia 86), (Goroimari 35), (Kayan 28), (Palashbari 17), (Nagarbera 23), (Chaygaon 5), (Kamalpur 103), (Chamaria 60), (Hajo 37), (North Ghy 31)						
Affected	Kamrup (M)	26	(Chandrapur 16), (Sonapur 8), (Dispur 2)							
	Karbi Anglong West	5	(Donkamokam 5)							
	Karimganj	454	(Nilamba	azar 187), (Patherkandi	36), (RK Nagar 166), (Badarpur 46), (Karimganj 19)		
	Kokrajhar	30	(Bagriba	ri 30)	-		•			
	Lakhimpu	58	(Bihpuri	a 4), (Dhak	kuakhana 11), (Nowboicha 24), (Su	bansiri 2), (]	Narayanpur 12), (
	r			khimpur 5)						
	Majuli	30		•	Majuli 17)					
	Morigaon	268				(Bhuragaon 56), (Morig) (BH 145) (
	Nagaon	306	Samaguri	17)	• • • • • •	Kaliabor 2), (Rupahi 5				
	Nalbari	310	Nalbari	17), (Nalba	•), (Banekuchi 5), (Tihu	19), (Barbh	nag 37), (Paschim		
	Sivasagar	9	(Sivsaga							
	Sonitpur	109	(Charidu	ar 13), (Na	aduar 4), (T	helamara 9), (Dhekiajul	i 29), (Tezp	ur 54)		
	South Salmara	80	· ·		, (Mankachar	43)				
	Tamulpur	30			mulpur 12)					
	Tinsukia	20			mdooma 11)					
	Udalguri	46	(Udalguı	ri 13), (Ma	zbat 4), (Kł	nairabari 4), (Harisinga	12), (Kalaiga	aon 13)		
	Total	5577								
	District	Male	Female	Children	Total Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details		
	Bajali	160560	125205	30105	315870	(Sarupeta 155870), (Bajali 160000)	460.00	(Sarupeta 460.00), (Bajali 0.00)		
Population And Crop Area Affected	Baksa	8937	6991	6067	21995	(Barnagar RC part 21038), (Baska 0), (Barama 105), (Baganpara 0), (Jalah 852)	452.00	(Barnagar RC part 410.00), (Baska 0.00), (Barama 0.00), (Baganpara 0.00), (Jalah 42.00)		
	Barpeta	509455	480838	261066	1251359	(Barpeta 180839), (Chenga 154483), (Baghbar 370497), (Sarthebari 335837), (27601.00	(Barpeta 870.00), (Chenga 2693.00), (Baghbar 18983.00), (Sarthebari 2028.00),		

	ı	T	ı		1	1	1
							(Kalgachia 1823.50
					Barnagar 11011)), (Barnagar 1203.50
Biswanath	0	0	0	0	(Gohpur 0), (Naduar RC part 0), (Halem 0), (Biswapath 0)	443.50	(Gohpur 0.00), (Naduar RC part 22.50), (Halem 411.00), (Biswanath 10.00)
Bongaigao n	81398	71666	83006	236070	(Srijangram 166318), (Manikpur 2780), (Boitamari 66972)	172.00	(Srijangram 0.00), (Manikpur 172.00), (Boitamari 0.00)
Cachar	84281	78662	53908	216851	(Silchar 42782), (Lakhipur 19800), (Sonai 62200), (Udharbond 4950), (Katigorah 87119)	41.00	(Silchar 0.00), (Lakhipur 0.00), (Sonai 41.00), (Udharbond 0.00), (Katigorah 0.00)
Chirang	1217	1059	1259	3535	(Bijni 1451), (Bengtal 2084)	2444.90	(Bijni 2444.90), (Bengtal 0.00)
Darrang	243968	204349	99104	547421	(Mangaldoi 125007), (Dalgaon 185900), (Sipajhar 155764), (Patharighat 80750)	9626.50	(Mangaldoi 2838.00), (Dalgaon 3795.50), (Sipajhar 1593.00), (Patharighat 1400.00)
Dhemaji	15547	12511	9621	37679	(Jonai 20042), (Sissiborgaon 17078), (Dhemaji 559)	7079.50	(Jonai 6158.50), (Sissiborgaon 912.00), (Dhemaji 9.00)
Dhubri	214071	196434	184203	594708	(Dhubri 53248), (Agamoni 1190), (Gauripur 0), (Chapar 690), (Bilasipara 130503), (South Salmara Part 265395), (Golakganj 301), (Athani 143381)	8978.83	(Dhubri 711.00), (Agamoni 0.00), (Gauripur 695.10), (Chapar 1018.20), (Bilasipara 0.00), (South Salmara Part 3769.00), (Golakganj 378.00), (Athani 2407.53)
Dibrugarh	1567	1240	1050	3857	(Chabua 3857)	2.50	(Chabua 2.50)
Goalpara	137325	104210	42833	284368	(Matia 13546), (Balijana 99311), (Lakhipur 171429), (Dudhnoi 82), (Rongjuli 0)	1376.50	(Matia 614.00), (Balijana 762.50), (Lakhipur 0.00), (Dudhnoi 0.00), (Rongjuli 0.00)
Golaghat	11878	10977	3677	26532	(Bokakhat 26532), (Khumtai 0)	96.00	(Bokakhat 80.00), (Khumtai 16.00)
Hailakandi	36237	20345	19608	76190	(Algapur 54241), (Hailakandi 6611), (Lala 14000), (Katlicherra 1338)	106.00	(Algapur 42.00), (Hailakandi 16.00), (Lala 29.00), (Katlicherra 19.00)
Hojai	39556	30214	10028	79798	(Hojai 44019), (Doboka 27378), (Lanka 8401)	2273.00	(Hojai 1022.00), (Doboka 436.00), (Lanka 815.00)
Kamrup	195449	135236	69529	400214	(Rangia 71800), (Goroimari 0), (Kayan 38122), (Nagarbera 0), (Chaygaon 0), (Kamalpur 146310), (Chamaria 0), (Hajo 122138), (Palashbari 219), (North Ghy 21625)	4044.40	(Rangia 798.50), (Goroimari 600.00), (Kayan 407.00), (Nagarbera 245.00), (Chaygaon 144.00), (Kamalpur 694.90), (Chamaria 95.50), (Hajo 610.00), (Palashbari 274.50), (North Ghy 175.00)
Kamrup (M)	3445	1713	605	5763	(Chandrapur 0), (Guwahati 0), (Sonapur 5483), (Dispur 280)	541.50	(Chandrapur 173.00), (Guwahati 0.00), (Sonapur 368.50), (Dispur 0.00)
Karbi Anglong West	1256	1257	1496	4009	(Donkamokam 4009)	0.00	(Donkamokam 0.00)
Karimganj	74435	44338	28876	147649	(Patherkandi 6883), (RK Nagar 11000), (275.20	(Patherkandi 0.00), (RK Nagar 0.00), (
	Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Goalpara Golaghat Hailakandi Hojai Kamrup (M) Karbi Anglong West	Bongaigao 81398 Cachar 84281 Chirang 1217 Darrang 243968 Dhemaji 15547 Dhubri 214071 Dibrugarh 1567 Goalpara 137325 Golaghat 11878 Hailakandi 36237 Hojai 39556 Kamrup 195449 Karbi Anglong West 1256	Bongaigao n 81398 71666 Cachar 84281 78662 Chirang 1217 1059 Darrang 243968 204349 Dhemaji 15547 12511 Dhubri 214071 196434 Dibrugarh 1567 1240 Goalpara 137325 104210 Golaghat 11878 10977 Hailakandi 36237 20345 Hojai 39556 30214 Kamrup 195449 135236 Kamrup (M) 3445 1713 Karbi Anglong West 1256 1257	Bongaigao n 81398 71666 83006 Cachar 84281 78662 53908 Chirang 1217 1059 1259 Darrang 243968 204349 99104 Dhemaji 15547 12511 9621 Dhubri 214071 196434 184203 Dibrugarh 1567 1240 1050 Goalpara 137325 104210 42833 Golaghat 11878 10977 3677 Hailakandi 36237 20345 19608 Hojai 39556 30214 10028 Kamrup 195449 135236 69529 Kamrup (M) 3445 1713 605 Karbi Anglong West 1256 1257 1496	Bongaigao n 81398 71666 83006 236070 Cachar 84281 78662 53908 216851 Chirang 1217 1059 1259 3535 Darrang 243968 204349 99104 547421 Dhemaji 15547 12511 9621 37679 Dhubri 214071 196434 184203 594708 Dibrugarh 1567 1240 1050 3857 Goalpara 137325 104210 42833 284368 Golaghat 11878 10977 3677 26532 Hailakandi 36237 20345 19608 76190 Hojai 39556 30214 10028 79798 Kamrup 195449 135236 69529 400214 Kamrup (M) 3445 1713 605 5763 Karbi Anglong West 1256 1257 1496 4009	Biswanath O	Burnagur 11011

	Kokrajhar	5207	4758	2509	12474	Badarpur 3 Nilambazar Karimganj (Gossaigao Kokrajhar Bhawraguri Bagribari	(177960), (16440) 160), (10), (0.00	Badarpur 275.20), (Nilambazar 0.00), (Karimganj 0.00) (Gossaigaon 0.00), (Kokrajhar 0.00), (Bhawraguri 0.00), (Bagribari 0.00)
	Lakhimpu r	23450	18022	15373	56845	(Nowboich (Narayanpu North Lakh 7336), (Bi 5875), (Di 729), (Su 2692)	na 40213), ur 0), (impur hpuria nakuakhana	1142.30	(Nowboicha 644.30), (Narayanpur 0.00), (North Lakhimpur 38.00), (Bihpuria 0.00), (Dhakuakhana 387.00), (Subansiri 73.00)
	Majuli	5768	5027	6608	17403	(Ujani Maj Majuli 174		402.20	(Ujani Majuli 132.84), (Majuli 269.36)
	Morigaon	39907	37708	25837	103452	(Mayong Bhuragaon Morigaon Laharighat	39292), (61723), (15788.00	(Mayong 14000.00), (Bhuragaon 832.00), (Morigaon 855.00), (Laharighat 101.00)
	Nagaon	159419	148340	149622	457381	(Nagaon 5 Kampur 2: Rupahi 0) 137000), (5287), (Ka), (Dhing	59500), (, (Raha Samaguri aliabor 497	17122.02	(Nagaon 218.00), (Kampur 8320.00), (Rupahi 118.00), (Raha 7938.02), (Samaguri 252.00), (Kaliabor 35.00), (Dhing 241.00)
	Nalbari	145214	132501	117323	395038	(Ghograpar (Banekuch (Tihu 645 Barbhag 1 Paschim Na 47121), (N 12500), (E 269330)	i 16530), 55), (1500), (albari Valbari	1973.60	(Ghograpar 718.00), (Banekuchi 80.00), (Tihu 200.00), (Barbhag 83.50), (Paschim Nalbari 554.00), (Nalbari 338.10), (Barkhetri 0.00)
	Sivasagar	1046	802	302	2150	(Sivsagar	2150)	30.00	(Sivsagar 30.00)
	Sonitpur	7906	11608	8147	27661	(Naduar 0 Chariduar Thelamara Dhekiajuli Tezpur 46	929), (1264), (20841), (27)	2902.90	(Naduar 66.00), (Chariduar 69.00), (Thelamara 120.00), (Dhekiajuli 1920.00), (Tezpur 727.90)
	South Salmara	56232	51234	62745	170211	(South Sali 139183), (31028)	Mankachar	891.00	(South Salmara 692.00), (Mankachar 199.00)
	Tamulpur	15156	12336	2106	29598	(Goreswar Tamulpur		500.00	(Goreswar 0.00), (Tamulpur 500.00)
	Tinsukia	2247	2246	1972	6465	(Tinsukia Doomdoom		1312.83	(Tinsukia 1268.33), (Doomdooma 44.50)
	Udalguri	4004	2856	2647	9507	(Udalguri Mazbat 61 Khairabari Harisinga Kalaigaon	0), (88), (1746), (227.00	(Udalguri 0.00), (Mazbat 0.00), (Khairabari 0.00), (Harisinga 146.00), (Kalaigaon 81.00)
	Total	228613 8	195468 3	1301232	5542053			108306.18	
	District	Total	Relief Ca				Relief Dist	ribution Cent	res
	Bajali	116		eta 9, Bajal	i 11)			a 1, Bajali 9.	5)
	Baksa	2	2(Barama		105.5	11 110	0(Barama		ID 11 10 0 1 1 1
Relief	Barpeta	147	Sartheba	ri 9, Barnag	nga 37, Bagl ar 0)	hbar 10,	7, Barnaga	ar 1)	, Baghbar 0, Sarthebari
Camps / Centres	Biswanath Bongaigao	76	0(Halem 32(Manil		amari 2, Srij	angram	2(Halem 2	-	ri 5, Srijangram 39)
Opened	n		27) 139(Silch	nar 57, Lakh	nipur 22, Son	nai 14,	` ^		0, Sonai 0, Udharbond
	Cachar Chirang	155	Udharbo	nd 1, Katigo 4, Bengtal 2	orah 45)	. ,	0, Katigoral	h 16)	, , , , , , , , , , , , , , , , , , , ,
					gaon 1, Sipa	ihar 7			on 20, Sipajhar 11,
	Darrang	108	Patharigh		saon 1, sipa	g.:.a. _/ ,	Patharighat		on ₁ 20, orpajnar 11,

	Dl::	(0(1:10 6::110)		C(I: 5	Sissiborgaon	11)			
	Dhemaji	6	0(Jonai 0, Sissiborgaon 0)	1.20				A (1		
	Dhubri	60	36(Dhubri 2, Chapar 1, Bilasipara Athani 4, South Salmara Part 0)	a 29,		1, Chapar 0, lmara Part 23	Bilasipara 0, 3)	, Athani		
	Dima-	32	27(Haflong 27)		5(Haflong 5)					
	Hasao			1.445		70(Matia 0, Balijana 29, Lakhipur 41)				
	Goalpara	156	86(Matia 5, Balijana 40, Lakhipu	r 41)), Lakhipur 4	1)		
	Golaghat	15	0(Bokakhat 0)	0)	15(Bokakh					
	Hailakandi	15	0(Algapur 0, Hailakandi 0, Lala			9, Hailakand				
	Hojai	64	45(Hojai 31, Doboka 14, Lanka	,		7, Doboka 7,		77 1 10		
	Kamrup	117	85(Rangia 23, Kayan 19, Kamalp Hajo 6, North Ghy 12)	our 25,	32(Rangia North Ghy		Kamalpur 25	, Hajo 0,		
	Karbi Anglong West	4	0(Donkamokam 0)		4(Donkamo	okam 4)				
	Karimganj	131	46(Patherkandi 3, Badarpur 20, K 23, Nilambazar 0, RK Nagar 0)	Karimganj		andi 19, Bada : 23, RK Nag	arpur 16, Kari ar 24)	imganj 3,		
	Lakhimpu r	21	0(Bihpuria 0, Nowboicha 0, Suba Narayanpur 0, North Lakhimpur			a 3, Nowboic r 1, North Lal	ha 10, Suban khimpur 1)	siri 6,		
	Majuli	6	0(Majuli 0)	<u> </u>	6(Majuli 6		animpur (1)			
	Morigaon	21	0(Mayong 0, Bhuragaon 0, Morig	raon (1)	, , ,	/	on 1, Moriga	on [7]		
	Nagaon	147	56(Nagaon 26, Kampur 17, Raha				40, Raha 39			
	Nagaon	147	103(Barkhetri 4, Banekuchi 9, Ti				hi 0, Tihu 0			
	Nalbari	135	Barbhag 20, Paschim Nalbari 21, 29, Ghograpar 0)	Nalbari	0, Paschim 11)	Nalbari 18, N	Nalbari 0, Gho	ograpar		
	Sonitpur	39	1(Dhekiajuli 1, Chariduar 0, Thel Tezpur 0)	amara 0,	38(Dhekiaj Tezpur 16		duar 5, Thelai	mara 4,		
	South Salmara	35	0(South Salmara 0, Mankachar 0)	35(South S	almara 8, Ma	nkachar 27)			
	Tamulpur	43	19(Goreswar 6, Tamulpur 13)		24(Goreswa	ar 12, Tamulı	our 12)			
	Udalguri	28	15(Udalguri 5, Mazbat 6, Harisin Kalaigaon 2, Khairabari 0)	ga 2,	13(Udalguri 11, Mazbat 0, Harisinga 0, Kalaigaon 0, Khairabari 2)					
	Total	1687	862		825	o, Khanabari	12)			
	Total	1007	002		023			Person		
							Pregnant /			
	District	Total	Revenue Circlewise	Male	Female	Children	Lactating Mother	with Disabilit y		
	District Bajali	Total 2326		Male 988	Female	Children 255	Lactating			
			Revenue Circlewise (Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69)				Lactating Mother	Disabilit y		
	Bajali	2326	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0),	988	1014	255	Lactating Mother 64	Disabilit y 5		
	Bajali Baksa	2326	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0),	988	1014	255	Lactating Mother 64 0	Disabilit y 5		
Inmates In	Bajali Baksa Barpeta Bongaigao n Cachar	2326 69 88018 8776 24343	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0), (Baghbar 2044) (Srijangram 7061), (Manikpur 1059), (Boitamari 656) (Silchar 10468), (Lakhipur 3250), (Sonai 1940), (Udharbond 70), (Katigorah 8615)	988 30 31230 4014 10375	1014 36 34449 3545 8776	255 3 22253 1128 5190	Lactating Mother 64 0 84 89	Disabilit y 5 5 0 2 0 2		
Relief	Bajali Baksa Barpeta Bongaigao	2326 69 88018	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0), (Baghbar 2044) (Srijangram 7061), (Manikpur 1059), (Boitamari 656) (Silchar 10468), (Lakhipur 3250), (Sonai 1940), (Udharbond 70), (Katigorah 8615) (Bijni 569), (Bengtal 741)	988 30 31230 4014	1014 36 34449 3545	255 3 22253 1128	Lactating Mother 64 0 84	Disabilit y 5 5 0 2 0		
	Bajali Baksa Barpeta Bongaigao n Cachar	2326 69 88018 8776 24343	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0), (Baghbar 2044) (Srijangram 7061), (Manikpur 1059), (Boitamari 656) (Silchar 10468), (Lakhipur 3250), (Sonai 1940), (Udharbond 70), (Katigorah 8615)	988 30 31230 4014 10375	1014 36 34449 3545 8776	255 3 22253 1128 5190	Lactating Mother 64 0 84 89	Disabilit y 5 5 0 2 0 2		
Relief	Bajali Baksa Barpeta Bongaigao n Cachar Chirang Darrang	2326 69 88018 8776 24343	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0), (Baghbar 2044) (Srijangram 7061), (Manikpur 1059), (Boitamari 656) (Silchar 10468), (Lakhipur 3250), (Sonai 1940), (Udharbond 70), (Katigorah 8615) (Bijni 569), (Bengtal 741) (Dalgaon 1670), (Patharighat 0), (Mangaldoi 1056), (Sipajhar	988 30 31230 4014 10375 491	1014 36 34449 3545 8776	255 3 22253 1128 5190 312	Lactating Mother	Disabilit y 5 0 2 0 2 5		
Relief	Bajali Baksa Barpeta Bongaigao n Cachar Chirang Darrang	2326 69 88018 8776 24343 1310 4643	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0), (Baghbar 2044) (Srijangram 7061), (Manikpur 1059), (Boitamari 656) (Silchar 10468), (Lakhipur 3250), (Sonai 1940), (Udharbond 70), (Katigorah 8615) (Bijni 569), (Bengtal 741) (Dalgaon 1670), (Patharighat 0), (Mangaldoi 1056), (Sipajhar 1917) (Dhubri 190), (Agamoni 0), (Gauripur 0), (Bilasipara 6171), (South Salmara Part 0), (Golakganj 0), (Athani 667),	988 30 31230 4014 10375 491 1712	1014 36 34449 3545 8776 442 1676	255 3 22253 1128 5190 312 1179	Lactating Mother	Disabilit y 5 5 0 0 2 5 4		
Relief	Bajali Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhubri	2326 69 88018 8776 24343 1310 4643	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0), (Baghbar 2044) (Srijangram 7061), (Manikpur 1059), (Boitamari 656) (Silchar 10468), (Lakhipur 3250), (Sonai 1940), (Udharbond 70), (Katigorah 8615) (Bijni 569), (Bengtal 741) (Dalgaon 1670), (Patharighat 0), (Mangaldoi 1056), (Sipajhar 1917) (Dhubri 190), (Agamoni 0), (Gauripur 0), (Bilasipara 6171), (South Salmara Part 0), (Golakganj 0), (Athani 667), (Chapar 40) (Haflong 1663) (Matia 1431), (Balijana 22020), (Lakhipur 9940), (Dudhnoi 0), (Rongjuli 0)	988 30 31230 4014 10375 491 1712	1014 36 34449 3545 8776 442 1676	255 3 22253 1128 5190 312 1179	Lactating Mother	Disabilit y 5 5 0 0 2 2 5 4 0 0		
Relief	Bajali Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhubri Dima- Hasao	2326 69 88018 8776 24343 1310 4643 7068	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0), (Baghbar 2044) (Srijangram 7061), (Manikpur 1059), (Boitamari 656) (Silchar 10468), (Lakhipur 3250), (Sonai 1940), (Udharbond 70), (Katigorah 8615) (Bijni 569), (Bengtal 741) (Dalgaon 1670), (Patharighat 0), (Mangaldoi 1056), (Sipajhar 1917) (Dhubri 190), (Agamoni 0), (Gauripur 0), (Bilasipara 6171), (South Salmara Part 0), (Golakganj 0), (Athani 667), (Chapar 40) (Haflong 1663) (Matia 1431), (Balijana 22020), (Lakhipur 9940), (Dudhnoi 0), (Rongjuli 0) (Algapur 0), (Hailakandi 0),	988 30 31230 4014 10375 491 1712 2195 588	1014 36 34449 3545 8776 442 1676	255 3 22253 1128 5190 312 1179 1853	Lactating Mother	Disabilit y 5 5 0 0 2 2 5 4 0 0 1		
Relief	Bajali Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhubri Dima- Hasao Goalpara	2326 69 88018 8776 24343 1310 4643 7068	(Sarupeta 1702), (Bajali 624) (Barnagar RC part 0), (Baganpara 0), (Baska 0), (Jalah 0), (Barama 69) (Barpeta 82772), (Chenga 1180), (Sarthebari 2022), (Kalgachia 0), (Barnagar 0), (Baghbar 2044) (Srijangram 7061), (Manikpur 1059), (Boitamari 656) (Silchar 10468), (Lakhipur 3250), (Sonai 1940), (Udharbond 70), (Katigorah 8615) (Bijni 569), (Bengtal 741) (Dalgaon 1670), (Patharighat 0), (Mangaldoi 1056), (Sipajhar 1917) (Dhubri 190), (Agamoni 0), (Gauripur 0), (Bilasipara 6171), (South Salmara Part 0), (Golakganj 0), (Athani 667), (Chapar 40) (Haflong 1663) (Matia 1431), (Balijana 22020), (Lakhipur 9940), (Dudhnoi 0), (Rongjuli 0)	988 30 31230 4014 10375 491 1712 2195 588 13488	1014 36 34449 3545 8776 442 1676 3020 618	255 3 22253 1128 5190 312 1179 1853 400 8441	Lactating Mother	Disabilit y 5 5 0 0 2 2 5 4 0 0 1 1 22		

	Kamrup	12569	(Kayan (Nagarbe (Kamalpı	2960), (Gord 1597), (Palas era 0), (Chay ur 3053), (C 3013), (No	shbari 0), ygaon 0), Chamaria	5681	4617	2188	73	10
	Karimganj	11309	(Nilamba (Badarpu	zar 0), (RK ar 1630), (Pa imganj 9594	therkandi	4584	4488	2234	3	0
	Nagaon	15188	(Dhing (Nagaon	r 0), (Rupah 0), (Samagur 8508), (Kar aha 1700)	i 0),	5790	5311	3934	140	13
	Nalbari	21121	(Ghograp 1503), (T 1746), (P	par 0), (Band Tihu 1248), (Paschim Nalb 5500), (Barl	(Barbhag ari 10914),	9374	8471	2967	291	18
	Sonitpur	170	(Charidua (Thelama 170), (Te	ar 0), (Nadu ara 0), (Dhel zpur 0)	ar 0), kiajuli	46	78	40	6	0
	Tamulpur	2307	1186)	ar 1121), (T	•	813	777	690	27	0
	Udalguri	1674	(Udalgur	430), (Khai i 738), (Har alaigaon 52)	isinga	724	681	262	7	0
	Total	262155				106432	100116	54352	1171	84
	District	Total	Male	Female	Children	Revenue C	irclewise			
	Darrang	1	1	0	0			oi 1), (Pathar	ighat 0), (Sip	aihar 0)
Human	Kamrup	3	2	0	1	(Chamaria (Kamalpur (Palashbari	0), (Chaygao 0), (Kayan 0), (Rangia	on 0), (Goroi: 0), (Nagarber 1)	mari 0), (Haj a 0), (North 0	o 1), Ghy 1),
Lives Lost - Confirmed	Karimganj	1	0	0	1	(Badarpur 0), (RK Na		nj 0), (Nilam	bazar 1), (Pa	therkandi
	Tamulpur	1	1	0	0	(Goreswar	0), (Tamulpı	ur 1)		
	Udalguri	1	0	0	1		0), (Kalaiga	on 0), (Khaira	abari 1), (Ma	zbat 0),
	Total	7	4	0	3					
Human	District	Total	Flood Death	General Drownin g (Non Flood)	Landslide					
Lives Lost	Darrang	1	1	0	0					
Confirmed -	Kamrup	3	3	0	0					
Death Type	Karimganj	1	1	0	0					
J	Tamulpur	1	1	0	0					
	Udalguri	1	1	0	0					
	Total	7	7	0	0					
	District	Total	Male	Female	Children	Details				
Human Lives Lost - Missing	Kamrup	1	1	0	0	(Chamaria (Kamalpur		on 0), (Goroin 0), (Nagarber 0)		
	Total	1	1	0	0					
Human	District	Total	Flood	Non Flood						
Lives Lost	Kamrup	1	1	0						
Missing - Type	Total	1	1	0						
	District	Total	Big	Small	Poultry					
	Bajali	119296	75449	33367	10480					
	Baksa	16290	9472	5754	1064					
	Barpeta	864648	351884	161869	350895					
	Biswanath	35373	25438	9935	0					
Animals Affected	Bongaigao n	17479	10101	7378	0					
	Cachar	36985	27985	9000	0					
	Chirang	7245	3590	2240	1415					
	Darrang	291705	174501	72699	44505					
	Dhemaji	21499	14595	6904						
	Duemaji	Z1499	14393	0904	0					

	Dhubri	560798	303637	208461	48700					
	Dibrugarh	450	355	95	0					
	Goalpara	76496	55002	12707	8787					
	Golaghat	2000	1200	800	0					
	Hailakandi	20065	7355	5340	7370					
	Hojai	81303	31413	17120	32770					
	Kamrup	446273	382696	45794	17783					
	Kamrup									
	(M)	9904	6640	3264	0					
	Karimganj	23822	10294	2518	11010					
	Kokrajhar Lakhimpu	24436	8644	3792	12000					
	r	36616	18248	8946	9422					
	Morigaon	106062	37663	16132	52267					
	Nagaon Nalbari	111984	53005	35959 125882	23020 37341					
		318600	155377							
	Sonitpur South	34193	23201	10992	0					
	South Salmara	285895	114287	79087	92521					
	Tamulpur	110756	29267	20575	60914					
	Total	366017 3	193129 9	906610	822264					
	District	Total	Big	Small	Poultry					
	Baksa	1	0	1	0					
Animals	Barpeta	3	2	1	0					
Washed	Bongaigao	59647	39278	20369	0					
Away	n		0							
	Nalbari	3	0	3	0					
	Total	59654	39280	20374	0		l	T	0.4	
	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
	Barpeta	56	0	56	101	0	101	0	0	0
	Chirang	2	0	2	0	0	0	0	0	0
	Darrang	12	6	18	0	0	0	0	0	0
Houses Damaged	Lakhimpu r	13	0	13	0	0	0	0	0	0
Damageu	Majuli	1	0	1	0	0	0	0	0	0
	Sivasagar	1	0	1	0	0	0	0	0	0
	Sonitpur	0	0	0	6	1	7	0	0	0
	Tamulpur	600	89	689	1600	87	1687	0	0	0
	Udalguri	20	0	20	5	0	5	0	0	0
	Total	705	95	800	1712	88	1800	0	0	0
	District	Agency	~		Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopte rs Deployed	Person Evacuate d By Helicopte rs	Medical Team Deploye d
	Bajali	SDRF			1	0	0	0	0	0
		NDRF, SI		·						
	Barpeta		amilitary fo cal Admini	orce, Circle	44	546	124	0	0	27
Rescue	Bongaigao n	Local Peo Circle Off	ple, Count fice/Local		18	0	0	0	0	7
_		Administration Army/Paramilitary force, Circle Office/Local Administration, Civil Defence/Trained Volunteers, Fire & Emergency Services (F&ES), Local People, NDRF, Police, SDRF, Water Resources Department			18	515	16	0	0	18
	Chirang				2	0	0	0	0	6
	Darrang	People, N	amilitary fo DRF, SDR cal Admini		16	500	0	0	0	4

	Dhemaji	Fire & En (F&ES)	nergency S	ervices	10	0	0	0	0	0
	Dhubri	Circle Off Administr		orce	46	143	172	0	0	10
	Dima- Hasao	Civil Defe Volunteer	ence/Trainers, Police, V	ed Vater	0	0	0	0	0	15
	Goalpara				0	0	0	0	0	18
	Hojai	_	amilitary fo DRF, Coun		33	0	0	0	0	21
	Kamrup	(F&ES), S Association force, ND	RF	intain aramilitary	20	586	30	0	0	27
	Karimganj	SDRF, Lo	cal People		11	100	45	0	0	1
	Lakhimpu r				0	0	0	0	0	2
	Majuli				0	0	0	0	0	14
	Morigaon	relief distr Emergence	ne boat dep ribution., F cy Services	ire & (F&ES)	13	103	116	0	0	3
	Nagaon	(F&ES), S	nergency S SDRF, Circ cal Admini ople	ele	14	1038	0	0	0	18
	Nalbari	Circle Off Administr	fice/Local ation, SDF	lF	4	7	80	0	0	11
	Sonitpur				2	0	0	0	0	3
	South	Circle Off			25	113	150	0	0	3
	Salmara	Administr	ration nergency S	orvices						
	Udalguri	(F&ES), S		ei vices	1	1	0	0	0	5
	Total				278	3652	733	0	0	213
						Cattle	Cattle			
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Feed - Green Fooder (in Q)	Feed - Wheat Bran (in Q)	Cattle Feed	- Rice Bran (in Q)
	District Bajali	Q) 2370.70	Q) 843.00	Q) 61.00		Green Fooder	Wheat Bran (in	Cattle Feed 0.00	- Rice Bran (in Q)
	Bajali Baksa	Q) 2370.70 0.99	Q) 843.00 0.17	Q) 61.00 0.50	L) 24640.20 5.00	Green Fooder (in Q) 0.00 0.00	Wheat Bran (in Q) 2513.39 0.00	0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta	Q) 2370.70 0.99 2882.70	Q) 843.00 0.17 598.84	0.50 0.50 175.57	24640.20 5.00 57.00	Green Fooder (in Q) 0.00 0.00	Wheat Bran (in Q) 2513.39 0.00 6325.00	0.00 0.00 0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath	Q) 2370.70 0.99	Q) 843.00 0.17	Q) 61.00 0.50	L) 24640.20 5.00	Green Fooder (in Q) 0.00 0.00	Wheat Bran (in Q) 2513.39 0.00	0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n	Q) 2370.70 0.99 2882.70 0.00 1237.52	843.00 0.17 598.84 0.00 233.57	61.00 0.50 175.57 0.00 70.01	24640.20 5.00 57.00 0.00 2135.04	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00	0.00 0.00 0.00 0.00 0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang	Q) 2370.70 0.99 2882.70 0.00 1237.52 14.86	843.00 0.17 598.84 0.00 233.57 2.59	61.00 0.50 175.57 0.00 70.01	24640.20 5.00 57.00 0.00 2135.04 87.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 130.00	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00	0.00 0.00 0.00 0.00 0.00 0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang	Q) 2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12	843.00 0.17 598.84 0.00 233.57 2.59 652.68	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 130.00 0.00	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 1189.20	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00	- Rice Bran (in Q)
Relief Distributed	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima-	Q) 2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12	843.00 0.17 598.84 0.00 233.57 2.59 652.68	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 130.00 0.00	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 1189.20	- Rice Bran (in Q)
Relief Distributed	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao Goalpara	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76 110.21	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78 20.15	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16 6.05	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00 604.35	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00 631.32	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao Goalpara Golaghat Hailakandi	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76 110.21 274.60	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78 20.15 50.92 171.37	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16 6.05 15.27	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00 604.35 1527.75 3390900.1	Green Fooder (in Q) 0.00 0.00 0.00 0.00 130.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00 631.32 0.00	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00 0.00 4.70	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao Goalpara Golaghat	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76 110.21 274.60	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78 20.15 50.92	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16 6.05 15.27 51.16	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00 604.35 1527.75 3390900.1 6	Green Fooder (in Q) 0.00 0.00 0.00 0.00 130.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00 631.32 0.00 2.58	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00 4.70	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao Goalpara Golaghat Hailakandi Hojai Kamrup Kamrup (M)	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76 110.21 274.60 893.08 220.00	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78 20.15 50.92 171.37 33.30	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16 6.05 15.27 51.16	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00 604.35 1527.75 3390900.1 6 528.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00 631.32 0.00 2.58	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00 4.70 0.00 75.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao Goalpara Golaghat Hailakandi Hojai Kamrup (M) Karbi Anglong West	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76 110.21 274.60 893.08 220.00 1876.97 0.00	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78 20.15 50.92 171.37 33.30 375.65 0.00	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16 6.05 15.27 51.16 9.75 99.61 0.00 5.44	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00 604.35 1527.75 3390900.1 6 528.00 10069.26 0.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 130.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00 631.32 0.00 2.58 0.00 2968.25 80.00	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00 4.70 0.00 75.00 0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao Goalpara Golaghat Hailakandi Hojai Kamrup Kamrup (M) Karbi Anglong West Karimganj	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76 110.21 274.60 893.08 220.00 1876.97 0.00 94.16 2008.99	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78 20.15 50.92 171.37 33.30 375.65 0.00 18.13	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16 6.05 15.27 51.16 9.75 99.61 0.00 5.44 86.84	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00 604.35 1527.75 3390900.1 6 528.00 10069.26 0.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00 631.32 0.00 2.58 0.00 2968.25 80.00 0.00	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00 4.70 0.00 75.00 0.00 0.00 0.00	- Rice Bran (in Q)
	Bajali Baksa Barpeta Biswanath Bongaigao n Chirang Darrang Dhemaji Dhubri Dima- Hasao Goalpara Golaghat Hailakandi Hojai Kamrup (M) Karbi Anglong West	2370.70 0.99 2882.70 0.00 1237.52 14.86 3605.12 416.65 4456.69 18.76 110.21 274.60 893.08 220.00 1876.97 0.00	843.00 0.17 598.84 0.00 233.57 2.59 652.68 77.49 825.36 1.78 20.15 50.92 171.37 33.30 375.65 0.00	0) 61.00 0.50 175.57 0.00 70.01 0.87 196.59 23.26 247.66 0.16 6.05 15.27 51.16 9.75 99.61 0.00 5.44	24640.20 5.00 57.00 0.00 2135.04 87.00 19443.00 496.89 879.50 89.00 604.35 1527.75 3390900.1 6 528.00 10069.26 0.00	Green Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 130.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	Wheat Bran (in Q) 2513.39 0.00 6325.00 2140.50 120.00 0.00 25.00 0.00 2036.64 0.00 631.32 0.00 2.58 0.00 2968.25 80.00	0.00 0.00 0.00 0.00 0.00 0.00 1189.20 0.00 0.00 0.00 4.70 0.00 75.00 0.00 0.00	- Rice Bran (in Q)

	Majuli	273.59	52.21	15.66	1566.18	0.00	0.00	0.00	
	Morigaon	590.00	104.91	33.48	0.00	0.00	500.00	0.00	
	Nagaon	2830.44	530.10	159.03	0.00	0.00	0.00	0.00	
	Nalbari	1807.89	453.32	108.52	10861.00	0.00	0.00	0.00	
	Sonitpur	228.74	42.41	13.19	0.00	0.00	1243.82	0.00	
	South Salmara	2227.83	417.75	125.32	5.85	0.00	558.00	0.00	
	Tamulpur	596.58	110.40	33.16	64.29	0.00	0.00	490.00	
	Udalguri	64.45	12.32	3.70	369.61	0.50	56.80	0.00	
	Total	29339.7 5	6046.3 8	1554.99	3466192.3	130.50	19633.70	2864.50	
	District	Baby Foo	d Liquid	Baby Food	l Solid	Others			
	Bajali	0.00-Pkt, 0.00-Q		875.00-Pkt				es; Biscuit-515.00-Pkt; Sanitary tary Napkin-10.00-Pkt	
	Baksa	0.00-Pkt		3.00-Pkt				t -14.00-Pkt; Mosquito coil -14.00-Pkt	
	Barpeta	0.00-Q, 0.00-Pkt		1000.00-Pi		Tarpauline-	-2500.00-Piec	00-Pieces; Drinking water-2500.00-L; es; Biscuits-40.00-Pkt; 1. Tarpaulin - Horlics-118.00-Pieces	
	Biswanath	0.00-Q		0.00-Q					
	Bongaigao n	597.00-Pl	ĸt	0.00-Q, 343	38.00-Pkt	Sanitary Pa 140.00-Piec	d-756.00-Pkt ces	chira-19.50-Kg; jaggery-3.90-Kg; ; Horlicks-246.00-Pkt; Tarpaulin-	
	Cachar	0.00-Q		0.00-Q			od Packet -72		
	Chirang	0.00-Q		6.00-Pkt, 0		Sanitary Na	apkin-81.00-P	kt; Mosquito net-50.00-Pieces	
	Darrang	0.00-Q		50.00-Pkt	ces, 0.00-Q,			; 0-0.00-Q; candles-500.00-Pkt	
	Dhemaji	0.00-Q		0.00-Q			148.00-Pieces	nitary Nepkin-10.00-Pkt; Candle-	
	Dhubri	0.00-Q, 31.00-Pkt		0.00-Q		10.00-Pkt; M.Coil-10.00-Pkt; Temporary Bathroom-2.00-Pieces; Water pouch -12500.00-Pieces; Bleaching Packet-1500.00-Pkt; Halogen Tablet-5000.00-Pieces; HTW-13.00-Pieces; Temporary Toilet Constructed-11.00-Pieces; Temporary Bathroom Constructed-15.00-Pieces; Water Pouches Distributed-15000.00-Pkt; Bleaching Packet Distributed-5500.00-Pkt; Halogen tablet-17000.00-Pieces; Tarpaulin -7470.00-Pieces; 0-0.00-Q			
Relief	Dima- Hasao	0.00-Q		0.00-Q		Milk-16.00-L; Potato-8.10-Q; Onion-4.13-Q; Biscuit-112.00-Pkt; Candle-48.00-Pkt; Match Box-89.00-Pkt; Mosquito Repellent-24.00-Pkt			
Distributed Others	Goalpara	0.00-Q		0.00-Q		Mosquito Coil-1329.00-Pkt; Match Box-1174.00-Pkt; Candle-1293.00-Pkt; Bleaching Powder-5.00-Kg			
	Golaghat	0.00-Q		0.00-Q			211.00-Pieces		
	Hailakandi	874.00-Pl	kt, 0.00-Q	0.00-Q		Wheat Bran		npken-100.00-Pieces; Candle-500.00-	
	Hojai	0.00-Q		0.00-Q		Chira-3.00- 130.00-Pkt: L; beclchin 108.00-L; V	-Q; Gur-1.50- ; Sanitary Nap g powder-14. Water-1440.00	Q; Water bottle-2760.00-L; Candle- bkin-235.00-Pkt; Amual Taza-348.00- 00-Kg; Biscuits-75.00-Pkt; Amual - 0-L; Sanitary Pads-105.00-Pkt; Phenyl- powder-47.00-Pkt; Chira-720.00-Kg	
	Kamrup	40.00-Pkt	e, 0.00-Q	140.00-Pkt	, 0.00-Q	20.00-Pkt; Pouch-3000	Sanitary Napl	Q; Mosquito Coil-100.00-Pkt; Candle- kin-22.00-Pkt; Phenyl-30.00-Q; Water arching Powder-100.00-Kg; Tarpaulin- 8.40-Q	
	Kamrup (M)	0.00-Q		0.00-Q		0-0.00-Q			
	Karbi Anglong West	0.00-Q		0.00-Q					
	Karimganj	200.00-Q Pkt	, 60.00-	0.00-Q		Mosquito C	Coil-20.00-Pkt	;; Candle-20.00-Pkt; 0-0.00-Q	
	Kokrajhar	31.60-L, (0.00-Q	0.00-Q			7.00-Kg; Sani 00-Pkt; 0-0.00	tary Napkins-193.00-Pkt; Good Day)-Q	
	Lakhimpu r	0.00-Q, 6	90.00-L	0.00-Q, 365	5.00-Kg		5.00-Pieces; ta	rpaulin-310.00-Pieces; Tarpaulin -	
	Majuli	0.00-Q		0.00-Q		Tarpaulin-1		-Pkt; Halogen tab-2000.00-Pieces; Water Pouch-3000.00-Pkt; Halogen	

	Morigaon	0.00-Q, 69	930.00-	0.00-Q, 6930.00-Pkt	0-0.00-Q; Sanitary Napkin-100.00-Q				
	Nagaon	10680.00- 0.00-Q, 20		11704.00-Pkt, 0.00-Q	Tarpaulin-31.00-Pieces; Drinking Water-8000.00-Pkt; Helogen Tablet-2000.00-Pieces; HTW-4.00-Pieces; Toilet-4.00-Pieces; Mosquito Coil-621.00-Pkt; Candle-621.00-Pkt; Sanitary Napkin-570.00-Pkt				
	Nalbari	0.00-Q		0.00-Q	0-0.00-Q				
	Sivasagar	246.50-L		375.10-Kg	Sanitary Napkin-619.00-Pkt; Chemical Pakt-450.00-Pkt				
	South Salmara	0.00-Q 0.00-Q		0.00-Q 0.00-Q, 153.00-Kg	Tarpaulin -2499.00-Pieces; Sanitary Napkin-1500.00-Pieces; Mosquito Net-200.00-Pieces; H. Light-200.00-Pieces; Dragon Light-2.00-Pieces; Milk Packet-1500.00-Pieces; Biscuit-1500.00-Pieces; Biscuit-57.00-Pkt; Candal-33.00-Pkt; M.Box-11.00-Pkt; Nepkin-15.00-Pkt; Dusbin-2.00-Pieces; Charger Light-9.00-Pieces; Amul -11.42-L; Horlicks-30.00-Kg				
	Tamulpur	0.00-Q		0.00-Q, 45.75-Kg					
	Udalguri	0.00-Q, 42	2.00-Pkt	166.00-Pkt, 0.00-Q	Sanitary Pad-958.00-Pkt; Tarpaulin-242.00-Pieces; Match Box-20.00-Pkt; Candle-30.00-Pkt; sanitary Pad-40.00-Pkt				
	District	Numbe r	Details						
Infrastructur e Damaged - Embankmen t Breached	Baksa	7	Lat - 91.: Laphaku: 91.31429 Query ha - 91.3853 Jorthan F 91.34285 2 No. Bh 91.30611 Khalijan Paoraput - 26.6854	324814), chi Majorsupa embankmen 92), twk to Dighaldonga Medica 394), Rivulet embankment on 18/ 57), togpara Jorthan embankmen 10), Embankment on 18/06/202 ha embankment on 18/06/202	River: Deojora 18/06/2022 Belguripathar (Long - 26.637334, at on 18/06/2022 Laphakuchi (Long - 26.639684, Lat - al Chawk at , on 18/06/2022 B- Block (Long - 26.709273, Lat - 26.70922 Bhogpara Pub Doomni supa (Long - 26.717356, Lat - 20.70922 2 No. Bhogpara (Long - 26.673865, Lat - 22 1 No. Bhogpara (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022 2 No. Bhogpara near Amarsing Basumatary house (Long - 26.685105, Lat - 91.334953), 2022				
	Jorhat	1		eok - Left ring bund of river Mudoijan or Puthinadi at Tangani Tangani Date: 21-06-2022 pproximate length 15 feets. (Long - 94.250891, Lat - 26.464669)					
	Total	8		-					
Infrastructur e Damaged - Embankmen ts Affected	Nil								
	District	Numbe r	Details						
Infrastructur e Damaged - Road	Bajali	11	report is - 0.00000 Patsala C approxim Pathsala, 1.Nityana Nalana received 0.000000 Dubihalo PWD, Pa Bisnupur This repo (Long - C Ratanpur AEE, PW 0.000000 Kundapa report is - 0.00000 Khutargu received 0.000000	received from AEE, PWD, 20, Lat - 0.000000), Golibhandha Road Titkata nately 375 meter. This report dated 20/06/2022 (Long anda Panbari Road 2. Nitya Affected length approxima from AEE, PWD, Patachard), Lat - 0.000000), and Dubi Affected length atacharchi, TR sub-division to Bamakhata Kedubari 20000000, Bamakhata Bhogpur Atava Atacharchi, TR sub-division to Transport of the stack of the sub-division of the	atacharkuchi Affected length approximately 1360 meter. This Patacharchi, TR sub-division, Pathsala, dated 20/06/2022 (Long jhe and Bhethua Road embankment erosion. Affected length part is received from AEE, PWD, Patacharchi, TR sub-division, -0.000000, Lat -0.000000), ananda Patsala 3. Nolana Belona 1. Nityananda 2. Patsala 3. ately 2.3 KM, 3.95 KM and 2.6 KM respectively. This report is rechi, TR sub-division, Pathsala, dated 20/06/2022 (Long - approximately 1.89 KM. This report is received from AEE, approximately 1.89 KM. This report is received from AEE, approximately 1.89 KM. This report is received from AEE, approximately 300.00 mtr respectively. PWD, Patacharchi, TR sub-division, Pathsala, dated 20/06/2022 (Eng - 0.000000), Lat - approximately 0.9 KM. This report is received from the pathsala, dated 20/06/2022 (Long - 0.000000), Lat - approximately 1.6 KM respectively. This approximately 1.6 KM respectively.				

0.00-Q, 6930.00-

		To 000000 T 0 000000
		0.000000, Lat - 0.000000), Bayanpara to Bhogpur Bamakhata Affected length approximately 0.2 KM This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala, dated 20/06/2022 (Long - 0.000000, Lat - 0.000000)
Baksa	15	Barnagar RC part - Barua house to Upen Das House Road Simlaguri As per report received from Asst ex Engineer PWD Salbari on 21/06/2022 the road is submerged and damaged due to heavy rainfall. (Long - 0.000000, Lat - 0.000000), Baska - Belguripathar Bamunpara to Laphakuchi Majorsupa Village Road 18/06/2022 Laphakuchi (Long - 26.637368, Lat - 91.312989), Uzirbari to Gaonrajasthan road Uzirbari (Long - 26.641964, Lat - 91.302562), Pub-Athiabari to Pamuapathar road on 18/06/2022 Pub-Athiabari (Long - 26.599019, Lat - 91.289765), Rampur Nathkuchi Supa to Barimukh road on 18/06/2022 Rampur (Long - 26.623891, Lat - 91.311398), Ulubari to Sadherisupa road on 18/06/2022 Ulubari (Long - 26.624095, Lat - 91.250135), Hatirtari to Bebejiapara Village Road CC Block on 18/06/2022 Hatirtari (Long - 26.586497, Lat - 91.284460), Chutiapara LP School to Bebejiapara Village Road on 18/06/2022 Chutiapara (Long - 26.583923, Lat - 91.273237), Tihu Chawk to Athiabari main road on 18/06/2022 Chutiapara (Long - 26.586958, Lat - 91.269935), Athiabari to Sarumanipur Major Supa Village Road - Deojora rivulet bridge aproach road broken on 18/06/2022 SaruManikpur (Long - 26.609217, Lat - 91.264367), Katnipara Boro Suba to Saru Manikpur Village road on 18/06/2022 Katnipara (Long - 26.586958, Lat - 91.269935), Chemethiapara Village Road, Chemetiapara to Athiabari on 18/06/2022 Chemethiapara (Long - 26.610700, Lat - 91.271464), Tihu to Doomni PWD Road to Bennabari LP School Village Road on 18/06/2022 Bennabari (Long - 26.610700, Lat - 91.271464), Tihu to Doomni PWD Road to Bennabari LP School Village Road on 18/06/2022 Bennabari (Long - 26.6104045, Lat - 91.271464), Tihu to Doomni PWD Road to Bennabari LP School Village Road on 18/06/2022 Bennabari (Long - 26.6104045, Lat - 91.271464),
		91.403176), Khamrihgaon Village Road on 18/06/2022 Khamrigaon (Long - 26.666809, Lat - 91.388701)
		Chenga - Chenga Bahari Road to sarudia road Bahari, Sarudia submerged, average depth0.55 m, reported by PWD, Roads Barpeta date-21/6/2022 (Long - 0.000000, Lat - 0.000000), Bahari Bhagawat than to Bhella Tarabari road via Niz Bahari and Haripur road, package No. AS-01-462 Bahari, Tarabari, Haripur, Niz bahari submerged, reported by PWD, Roads Barpeta date-
Barpeta	20	462 Bahari, Tarabari, Haripur, Niz bahari submerged, reported by PWD, Roads Barpeta date-21/6/2022 (Long - 0.000000, Lat - 0.000000), Chenga to Nagaon Sarthebari Road (Signature project) Chenga submerged, reported by PWD, Roads Barpeta date-21/6/2022 (Long - 0.000000, Lat - 0.000000), Batgaon Haripur Road Batgaon, Haripur submerged, reported by PWD, Roads Barpeta date-21/6/2022 (Long - 0.000000, Lat - 0.000000), Pathimari to Khamkheyali bazar road Pathimari submerged, one breach occured, average depth35.00 m, reported by PWD, Roads Barpeta date-21/6/2022 (Long - 0.000000, Lat - 0.000000), Chata to Garemari Road Chata submerged, reported by PWD, Roads Barpeta date-21/6/2022 (Long - 0.000000, Lat - 0.000000), Baghbar - Barpeta Mandia pwd road to Barpalli road flood Submarged at chainage 2nd, 3rd, 4th & 5th km. Barpalli Date of Damage- 21.06.2022 Type of Damage- Surface & Both side Shoulder damaged Damage Length- 2100 m. Reported by Pwd Deptt. (Long - 90.905895, Lat - 26.294007), FAA Medical college to Medhirtary road flood Submarged at chainage 2nd, 3rd & 4th km. Jotigaon, Medhirtary Date of Damage- 21.06.2022 Type of Damage- Surface & Both side Shoulder damaged Damage Length- 1200 m. Reported by Pwd Deptt. (Long - 90.960822, Lat - 26.313183), Gobindapur Gurala Milan Bazar road flood submarged at chainage 1st & 2nd km. Gurala Date of Damage- 21.06.2022 Type of Damage- Surface & Both side Shoulder damaged Damage Length- 630 m. Reported by Pwd Deptt. (Long - 90.903998, Lat - 26.275818), Kandapara Bazar to Gobindapur PMGSY road flood Submarged at chainage 1st & 2nd km. Kandapara Date of Damage- 21.06.2022 Type of Damage- Surface ,Both side Shoulder & Culvert damaged Damage Length- 950 m. Reported by Pwd Deptt. (Long - 90.926523, Lat - 26.302805), Barpeta Mandia road to Kopoha Medhirtary road flood Submarged at chainage 1st, 2nd, & 3rd km. kopoha te of Damage- 21.06.2022 Type of Damage- Surface & Both side Shoulder damaged Damage Length- 1800 m. Reported by

Chiran	g 5	21, damaged details- L=18m, B=3m. Coordinates- 26.386722, 90.894602 3. const. of Ring bundh st frm Maznur Rahman house to Kaurjahi border via Eusab Bazar AAP1594 under MGNREGA for 2020-21. damaged details- L=25m, coordinates- 26.372052, 90.896195. 4.Reparing of road st from Hajrat Ali house to Sariatpur Kabarsthan, viil-Kabarsthan, damaged details- L=30m, W=4m, H=1.5m, coordinates- 26.2632369, 90. 859937. 5. const of rd with sand gravel st frm Nuru Miya house to Abdul Jalil house via Amser house, vill- Showpur, damaged details- L=20m, W=4m, H= 1.80m, coordinates- 26.323168, 90.867438. 6. Const. of Paver block road st frm SH2 to Sabur Uddin house at vill Udmari, damaged details-L=15m, W=4m, H=0.60m, coordinates- 26.32998, 90.864127. (Long - 0.000000, Lat - 0.000000) Bijni - Bijni Kuklung Road Silbari Abadipara As reported by PWD, Bijni (R&B) Sub Division, embankment eroded at 10th KM at Silbari Abadipara of Bijni Kuklung road on 16-06-2022. Length=3.00 mtr, Breadth=2.00 mtr, Depth=0.90 mtr. (Long - 90.671227, Lat - 26.582819), Bijni Batabari Mongolian to Malipara Road at 9th KM As reported by PWD, Bijni (R&B) Sub Division, road embankment eroded at 9th Km of Bijni Batabari Mongolian to Malipara road on 18-06-2022. Length=8.00 mtr, Breadth=2.50 mtr, Depth=3.00 mtr. (Long - 90.629744, Lat - 26.548358), Bowpara Charegaon Village Road Bowpara Charegaon village road at 1st KM As reported by PWD, Bijni(R&B) Sub Division, road embankment washed out at 1st KM of Bowpara Charegaon road on 14-06-2022. Length=8.50 mtr, Breadth=8.60 mtr, Depth=1.80 mtr. Longitude=90.806112 Latitude=26.565581. (Long - 90.806112, Lat - 26.565581),
		Bengtal - South Simlaguri FV Road South Simlaguri FV As reported by BDO, Sidli Chirang Dev. Block, South Simlaguri FV Road damaged on 16-06-2022. L-134.48 m B- 2.26 m B- 1.5 m. (Long - 90.416925, Lat - 26.739995), Palashguri CC Block road Palashguri As reported by BDO, Sidli Chirang Dev. Block, Palashguri CC Block road damaged on 16/06/2022, L- 89.98m B- 3.25m D- 1.5m (Long - 90.521355, Lat - 26.636262)
Darran	g 23	Mangaldoi - NH 15 to Stadium Road under PWRD . under Mangaldai Revenue Circle as reported by PWRD NH 15 to Stadium Road under PWRD is submerged under flood water and the length of submergence is 500 mtr. approx. Dated 20-6-2022 (Long - 92.030000, Lat - 26.440000), Denial Path (Ward No. 2) under PWRD under Mangaldai Revenue Circle as reported by PWRD Denial Path (Ward No. 2) is submerged under flood water and the length of submergence is 300 mtr. approx. Dated 20-6-2022 (Long - 92.030000, Lat - 26.440000), M M Road at Rajghat under PWRD under Mangaldai Revenue Circle as reported by PWRD M M Road at Rajghat is submerged under flood water and the length of submergence is 1500 mtr. approx. Dated 20-6-2022 (Long - 91.970000, Lat - 26.480000), Culvert damage at MM Road under PWRD under Mangaldai Revenue Circle as reported by Culvert damage at MM Road under PWRD under Mangaldai Revenue Circle as reported by PWRD M M Road at Hollowchowka under PWRD under Mangaldai Revenue Circle as reported by PWRD M M Road at Hollowchowka is submerged under flood water and the length of submergence is 100 mtr. approx. Dated 20-6-2022 (Long - 91.960000, Lat - 26.480000), R. K Road at Hollowchowka is submerged under flood water and the length of submergence is 100 mtr. approx. Dated 20-6-2022 (Long - 91.960000, Lat - 26.480000), Niz Mangalbesa to MB Road under PWRD under Mangaldai Revenue Circle as reported by PWRD Niz Mangalbesa to MB Road under PWRD under Mangaldai Revenue Circle as reported by PWRD Niz Mangalbesa to MB Road under PWRD under Mangaldai Revenue Circle as reported by PWRD Niz Mangalbesa to MB Road is submerged under flood water and the length of submergence is 500 mtr. approx. Dated 20-6-2022 (Long - 92.030000, Lat - 26.470000), Barangabari to Ramhari Road under PWRD under Mangaldai Revenue Circle as reported by PWRD Niz Mangalbesa to MB Road is submerged under flood water and the length of submergence is 900 mtr. approx. Dated 20-6-2022 (Long - 92.020000, Lat - 26.47

Kanaichuba Patharughat Road at Jhargaon, Janaramchowk under PWRD | under Mangaldai Revenue Circle | as reported by PWRD Kanaichuba Patharughat Road at Jhargaon, Janaramchowk is submerged under flood water and the length of submergence is 900 mtr. approx. Dated 20-6-2022 | (Long - 91.968000, Lat - 26.466000), Sareng Chuburi to MM Road (PMGSY) under PWRD | under Mangaldai Revenue Circle | as reported by PWRD Sareng Chuburi to MM Road (PMGSY) is submerged under flood water and the length of submergence is 800 mtr. approx. Dated 20-6-2022 | (Long - 91.000000, Lat - 26.000000), Banglagarh Jaberikuchi PMGSY Road under PWRD | under Mangaldai Revenue Circle | as reported by PWRD Banglagarh Jaberikuchi PMGSY is submerged under flood water and the length of submergence is 700 mtr. approx. Dated 20-6-2022 | (Long - 91.000000, Lat - 26.000000), Bridge approach at Tangni Kalaigaon Road under PWRD | under Mangaldai Revenue Circle | as reported by PWRD Bridge approach at Tangni Kalaigaon under PWRD is damaged due to flood water . Dated 20-6-2022 | (Long - 92.067000, Lat - 26.554000), MM Road to Dhula Chapai Connecting Road under PWRD | under Mangaldai Revenue Circle | as reported by PWRD MM Road to Dhula Chapai Connecting Road is submerged under flood water and the length of submergence is 500 mtr. approx. Dated 20-6-2022 | (Long - 91.000000, Lat -26.000000), Kachomari to C.M. Dutta Bundh under PWRD | under Mangaldai Revenue Circle | as reported by PWRD Kachomari to C.M. Dutta Bundh is submerged under flood water and the length of submergence is 200 mtr. approx. Dated 20-6-2022 | (Long - 91.000000, Lat - 26.000000), Sipajhar - Lenga Kurua PWD Road cum Embankment | Lenga Kurua | Breached at Lenga Kurua PWD Road cum Embankment on 19/06/2022 | (Long - 0.000000, Lat - 0.000000), Patharighat - Khatara Bherua road | Khatara to Bherua | Major breach (L= 25m) on Khatara Bherua road at ch 500m as reported by PWD on 21.6.2022 | (Long - 91.853803, Lat - 26.465098) Bilasipara - BILASIPARA TO SANKOSH NH POINT VIA SAGUNMARI DUBACHURI PMGSY ROAD.PACKAGE NO. AS-05-214(.)SIDE BUM & HARD CRUST DAMAGED BY GAURANG RIVER FLOOD WATER | BILASIPARA TO SANKOSH NH POINT VIA SAGUNMARI DUBACHURI PMGSY ROAD. | DAMAGED DUE TO FLOOD 13-06-2022 to 17-06-2022 | (Long - 90.178874, Lat - 26.207207), MAMABAZAR TO BUSIR CHAR (SAGUNMSRI PT-I) ROAD (.)SIDE BUM & HARD CRUST DAMAGED BY GAURANG RIVER FLOOD WATER | MAMABAZAR TO BUSIR CHAR | DAMAGED DUE TO FLOOD 13-06-2022 to 17-06-2022 | (Long - 90.205662, Lat - 26.217618), KADAMTOLA PT-I TO KADAMTOLA PT-II ROAD (.)SIDE BUM & HARD CRUST DAMAGED BY GAURANG RIVER FLOOD WATER | KADAMTOLA PT-I TO KADAMTOLA PT-II ROAD | DAMAGED DUE TO FLOOD 13-06-2022 to 17-06-2022 | (Long - 90.210358, Lat -26.227330). GUTIPARA PT-IV TO NAYERALGA GAURANG GHAT ROAD (,) SIDE BERM & HARD CRUST DAMAGED BY GAURANG RIVER FLOOD WATER | GUTIPARA PT-IV TO NAYERALGA GAURANG GHAT ROAD | DAMAGED DUE TO FLOOD 13-06-2022 to 17-06-2022 | (Long - 90.172442, Lat - 26.166780), NH-31 TO PASUARKHAL PT-II ROAD (,) SIDE BUM & HARD CRUST DAMAGED BY GAURANG RIVER FLOOD WATER | NH-31 TO PASUARKHAL PT-II ROAD | DAMAGED DUE TO FLOOD 13-06-2022 to 17-06-2022 | (Long - 90.177292, Lat - 26.231777), NH-31 TO PASUARKHAL PT-III ROAD (.) SIDE BUM & HARD CRUST DAMAGED BY GAURANG RIVER FLOOD WATER | NH-31 TO PASUARKHAL PT-III ROAD | DAMAGED DUE TO FLOOD 13-06-2022 to 17-06-2022 | (Long - 90.183680, Lat - 26.229694), Dhubri 14 3RD KM OF BS ROAD TO JOGIRMAHAL -II (.) ROAD SUBMERGED AT 1STN & 2ND KM ROAD SURFACE AND SIDE BERM DAMAGED INSTREACHES DUE TO FLOOD WATER OF RIVER SANKOSH | 3RD KM OF BS ROAD TO JOGIRMAHAL -II | DAMAGED DUE TO FLOOD 14-06-2022 to 20-06-2022 | (Long - 90.158323, Lat - 26.240382), 16th KM OF BS ROAD TO KASIARTARI SUBMERGED AT 1ST KM ROAD SURFACE AND SIDE BERM DAMAGED DUE TO FLOOD OF HEL RIVER | 16th KM OF BS ROAD TO KASIARTARI SUBMERGED AT 1ST KM ROAD | DAMAGED DUE TO FLOOD 14-06-2022 to 20-06-2022 | (Long - 90.126462, Lat - 26.329208), DHANPUR TO BARKUTI ROAD SUBMERGED AT 1ST KM ROAD SURFACE AND SID E BERM DAMAGED DUE TO TIPKAI RIVER | DHANPUR TO BARKUTI ROAD | DAMAGED DUE TO FLOOD 14-06-2022 to 20-06-2022 | (Long - 90.152357, Lat - 26.307139), 1ST KM OF BS ROAD TO SONKOSH ROAD SUBMERGED AT 1ST & 2ND KM ROAD SURFACE, SIDE BERM AND HP CULVERT APPROACH DAMAGED DUE TO SONKOSH RIVER | 1ST KM OF BS ROAD TO SONKOSH ROAD | DAMAGED DUE TO FLOOD 14-06-2022 to 20-06-2022 | (Long - 90.153418, Lat - 26.227277), 3RD KM OF BS ROAD TO BAMUNI ROAD (BARGARIR PAR TO DAMUMARA) SUBMERGED AT 1ST & 2ND KM SIDE BERM AND ROAD SURFACE DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER | 3RD KM OF BS ROAD TO BAMUNI ROAD | DAMAGED DUE TO FLOOD 14-06-2022 to 20-06-2022 | (Long - 90.150736, Lat - 26.239622), 6TH KM OF BS ROAD TO CHORUARBITA (AMBARI TO CHORUARBITA) ROAD SUBMERGED AT 4TH KM SIDE BERM ERROTED AND ROAD SURFACE DAMAGED DUE TO FLOOD OF HELL RIVER | 6TH KM OF BS ROAD TO CHORUARBITA | DAMAGED DUE TO FLOOD 14-06-2022 to 20-06-2022 | (Long - 0.000000, Lat - 26.292235),

		Athani - NH-31 AT PANBARI TO KAUNBARI PMGSY ROAD (.) PACKAGE NO. AS-05-
		43(.)SIDE BUM & HARD CRUST DAMAGED FROM CH. 0.00M TO CH. 2500.00M BY FLOOD WATER OF TIPKAI RIVER NH-31 AT PANBARI TO KAUNBARI PMGSY ROAD Due to
		flood water on dated 14/06/2022 to 21/06/2022 (Long - 26.154481, Lat - 90.060288),
		TOPPARA JHAUPARA TO DALANERALGA ROAD(,) SIDE BUM &HARD CRUST DAMAGED BY TIPKAI RIVER FLOOD WATER TOPPARA JHAUPARA TO
		DALANERALGA ROAD Due to flood water on dated 14/06/2022 to 21/06/2022 (Long - 26.164513, Lat - 90.086609)
		Tingkhong - 1)Khowang Grant Sisu Ali 2)Tower Tinali to Ouguri Road 3)Swatonibam Kurmi Bosti
		Road 1)Khowang Grant Sisu Ali Village-Khowang Grant Length-1.5 km Lat-27.235617 & long- 95.095727 As per reports from PWD on 16-06-22, due to recent heavy and continuous rainfall the
		above roads are severely damaged on 20-05-22 2)Tower Tinali to Ouguri Road Village-Chareng
Dibrugarh	3	pather Length-2.0 km Lat-27.24921 & Long-95.08821 As per reports from PWD on 16-06-22, due to recent heavy and continuous rainfall the above roads are severely damaged on 20-05-22
		3)Suratonibam Kurmi Bosti road Village-Suratonibam Length-2.0 km Lat-27.235617&Long-
		95.06655 As per reports from PWD on 16-06-22, due to recent heavy and continuous rainfall the
		above roads are severely damaged on 20-05-22 (Long - 95.066550, Lat - 27.235617) Matia - Matia to Simlitola Road & approach of Bridge No-6/1. PMGSY PKG NO-AS.07.405 Matia
		Affected length = 6.500 Km & average depth of submergence = 0.740 m and bridge approach
		damaged (as on 20/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.892608, Lat - 26.069894),
		Garomari to Nabagata Simlitola Road Garomari Affected length = 0.750 Km & average depth of
		submergence = 0.700 m as on 20/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.878614, Lat - 26.080833),
		Pokalagi to Garoporatori Road Pokalagi Affected length = 0.470 Km & average depth of
		submergence = 0.530 m (as on 20/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.854535, Lat - 26.080395),
		Nayapara to Bahati Road Bahati Affected length = 0.620 Km & average depth of submergence =
		0.520 m (as on 20/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.835763, Lat - 26.082284),
		Forest Gate to Krishnai Road Forest Gate Affected length = Km & average depth of submergence
		= 0.740 m and road hard crust, side berm, embankment damaged (as on 20/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.652907, Lat -
		26.122957),
		Domoni to Bahati via Dalgoma Road (PMGSY Pkg No -AS-07-404 Domoni Affected length = 0.400 Km & average depth of submergence = 0.500 m (as on 21/06/2022) as reported by PWRD,
		Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.832695, Lat - 26.090784),
Goalpara	11	Balijana - Dwarka Gossaigadhowa Road Dwarka Gossaigadhowa Road embankment eroded at Ch 1.5 KM & breached at Ch. 2.70 KM Information received from PWD R Dept. Report received from
		Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 20.06.2022
		(Long - 90.488087, Lat - 26.036500), Milan Nagar PWD Road Milan Nagar Date of occurrence 17.06.2022 Length affected- 0.200 Km
		Average depth of submergence- 0.300 m Traffic disrupted from 17.06.2022 to 20.06.2022 Road hard
		crust, side berm & embankment damaged Report received from Department- PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara on 20.06.2022 (Long - 90.617348, Lat -
		26.160725),
		Chandamari to Kokira Garopara, PMGSY PKG No- AS.07.338 Chandamari Date of occurrence 18.06.2022 Length affected- 0.320 Km Average depth of submergence- 0.300 m Traffic disrupted
		from 18.06.2022 to till date Road hard crust, side berm & embankment damaged Report received
		from Department- PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara on 21.06.2022 (Long - 90.585630, Lat - 26.059769),
		Dudhnoi - Mowamari To Bandarshee Pt. II Road Mowamari The road of length of 0.030 km got
		affected with water submergence depth of 0.230m. 1 No. of culvert of the road got damaged dated 20/06/2022- Information received from PWRD department, Dudhnoi & Goalpara East Territorial
		Road Division, Goalpara (Long - 90.728826, Lat - 25.955485),
		Rongjuli - BARBARI TO KANKATA ROAD PARTIALLY SUBMERGED ROAD KANKATA PT.I AS PER REPORTED BY JE PWD (RR). REPORTED DATE: 21/06/2022 REPORTING
		TIME:03:34 PM VIA WHATSAPP MESSAGE (Long - 90.916150, Lat - 26.056260)
		Algapur - N.H. To Serishpur Road, Under Algapur Revenue Circle on 21.06.2022. 60 cm Submerged (Long - 92.553692, Lat - 24.677659),
		N.C.P.W.D Road To Tolley line via Paul Para Under Algapur Revenue Circle on 21.06.2022. Ch.
		200.00m to Ch. 3000.00, 60 CM Innudated (Long - 92.606982, Lat - 24.632064), N.H. Narainpur Ferry Ghat Road Under Algapur Revenue Circle on 21.06.2022. Ch. 0.00m ton
Hailakandi	16	3000.00 m Damaged Run off water submerged (Long - 92.642262, Lat - 24.801932),
		T01 Kalinagar Pt. VIII to Block Boundary Mohanpur R.A. P.M.G.S.Y Under Algapur Revenue Circle on 21.06.2022. Ch. 11900.00m to Ch. 12150.00m Submerged and eroded (Long -
		92.657511, Lat - 24.799499),
		Algapur Tinali to Narainpur Ferryghat Under Algapur Revenue Circle on 21.06.2022. 3rd Km to
		2nd Km Submerged and eroded (Long - 92.604919, Lat - 24.755548),

	_	
		Katlicherra - T06-A Road from T5 Abdullapur to Block Boundary Tantoo, Under Katlicherra
		Revenue Circle on 21.06.2022. Ch. 250.00 to Ch. 2792.00 m Full length submerged Bridge
		approach washed away (Long - 92.553575, Lat - 24.523969),
		L038-A Road from T2 at 63rd KM of NH 154 to Sultanicherra Grant Under Katlicherra Revenue
		Circle on 21.06.2022. H.P. Culvert H.P Culvert Damaged (Long - 92.536923, Lat - 24.370582),
		Hailakandi - MRLO7-Hailakandi Ratanpur Road to Lakhiswar via Bilpar Under Hailakandi
		Revenue Circle on 21.06.2022 3620.00m to 3990.00m, 1700.00 to 2150.00m Damage of
		Embankment based and surface course (Long - 92.578673, Lat - 24.698031),
		Bishnighar PWD Road Under Hailakandi Revenue Circle on 21.06.2022 Ch 820.00 m to ch.910.00
		Inudated (Long - 92.584734, Lat - 24.699933),
		Bilpar Dhumkar PWD Road Under Hailakandi Revenue Circle on 21.06.2022 ch.515.00 m
		Inundated (Long - 92.579437, Lat - 24.688641),
		TO9 Narainpur Chandipur Road Under Hailakandi Revenue Circle on 21.06.2022 Ch.530.00,880.00
		&5920.00 Inundated (Long - 92.543473, Lat - 24.702584),
		T03- Ratanpur Pt-I to Bondukmara GrantUnder Hailakandi Revenue Circle on 21.06.2022 2m to
		3rdm Full length submerged Bridge approach washed awat (Long - 92.638008, Lat - 24.659324),
		Gastola Borbond Road Under Hailakandi Revenue Circle on 21.06.2022 Ch. 500m to 2000m
		Inundated by flood water (Long - 92.571093, Lat - 24.673083),
		Matijuri to Nityandapur Under Hailakandi Revenue Circle on 21.06.2022 Depth of submergence
		=60 cm Ch. 200.00m to Ch.3000.00m Inundated (Long - 92.606982, Lat - 24.716923),
		Town Project E- Road Under Hailakandi Revenue Circle on 21.06.2022 Depth of submergence =20
		cm Ch. 100.00m to Ch.200.00m Inundated (Long - 92.565886, Lat - 24.682024),
		Lala - Lala Town Road under Lala Revenue Circle on 21.06.2022 1st KM & 2nd KM Water
		Logging (Long - 92.605233, Lat - 24.567520)
		Titabor - Bandarchaliha Road Paninora Gaon Damaged occurred due to continuous rainfall.
Jorhat	1	Length-10 M. Source- PWD Jorhat, Titabar & Dergaon Territorial Road Division. Date- 21.06.2022
		(Long - 94.273454, Lat - 26.563426)
		Rangia - Haradutta Biradutta Road Vill- Rangia Town near Rangia Municipality Haradutta
		Biradutta Road in Rangia Town is partially damaged due to submergence as per report of AEE,
		PWD, NKT, Roads, Rangia on 20.06.2022 (Long - 0.000000, Lat - 0.000000),
		Kanikuchi Road Village Kanikuchi near SPT Bridge Kanikuchi Road in vill Kanikuchi was
		damaged due to submergence as per report of AEE, PWD, NKT, Roads, Rangia on 20.06.2022
		(Long - 91.598572, Lat - 26.382534),
Kamrup	4	Chamaria - Neoldoba Batiamari Neoldoba Road submerged of the road namely Neoldoba
		batiamari had taken place on dated 20.06.2022 and the same has been reported by JE, PWD, Boko
		territorial road sub-division on dated 20.06.2022 (Long - 91.156191, Lat - 26.096008),
		Dekachange to Jaokatadia, AS-11-681 Dekachange Road submerged of the road namely
		Dekachang to Jaokatadia, AS-11-681, had taken place on dated 20.06.2022 and the same has been
		reported by JE, PWD, Boko territorial road sub-division on dated 20.06.2022 (Long - 91.118153,
		Lat - 26.104305)
		Patherkandi - Bhubrighat Road to Adamtilla Bhubrighat CC block road has been washed out by
Karimganj	1	flood water at Bhubrighat on 20/06/2022 as reported by AEE, PWD(T/R), Patharkandi. Approx
		length is 1200meter. (Long - 92.285971, Lat - 24.622236)
		Gossaigaon - Amlaiguriroad to Kashiabari Kashiabari AS REPORT RECEIVED FROM AEE
		PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN IMMEDIATE
		RESTORATION ON AMLAIGURI PMGSY ROAD TO KASHIABARI BALAGAON ROAD
		SUBMERGE & ROAD FORMATION DAMAGED FROM 1 TO 2 KM (Long - 0.000000, Lat -
		0.00000),
		BALLAMJHORA TO SRIRAMPUR ROAD BALLAMJHARA AS REPORT RECEIVED FROM
		AEE PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN
		IMMEDIATE RESTORATION ON BALLAMJHORA TO SRIRAMPUR ROAD SUBMERGE
		AND ROAD FORMATION DAMAGED FROM 1 KM TO 3 KM (Long - 0.000000, Lat -
		0.000000),
		BALLAMJHORA SSB CAMP TO SRIRAMPUR ROAD BALLAMJHORA AS REPORT
		RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO
Kokrajhar	25	HEAVY RAIN IMMEDIATE RESTORATION ON BALLAMJHORA SSB CAMP TO
3		SRIRAMPUR ROAD BADLY ERODED BY SINDRI RIVER (L= 300.00 M) (Long - 0.000000,
		Lat - 0.000000),
		SARAIBIL TO AMLAIGURI SARAIBIL AS REPORT RECEIVED FROM AEE PWD RR
		KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN IMMEDIATE
		RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO AMLAIGURI BORO BOSTI ROAD
		SUBMERGE AND ROAD FORMATION DAMAGED. (Long - 0.000000, Lat - 0.000000),
		JANALIGAON TO BONGAON JANALIGAON AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN IMMEDIATE
		RESTORATION ON KACHUGAON SANKOSH ROAD AT JANALIGAON TO BONGAON
		SUBMERGE AND ROAD FORMATION DAMAGED 1 AND 2 KM (Long - 0.000000, Lat -
		0.000000),
		SANKOSH ROAD TO LAPAKANKAR, BONGAON BONGAON AS REPORT RECEIVED
		FROM AEE PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN
1		THE THE TAX AMERICAN SERVING S

IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO LAPAKANKAR, BONGAON ROAD SUBMERGE & ROAD FORMATION DAMAGED FROM 1 KM TO 3 KM. | (Long - 0.000000, Lat - 0.000000), Bhawraguri - SAPATGRAM BAMUNIGAON PAT-II & IV VILLAGE ROAD | BAMUNIGAON | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 20-06-2022 IMMEDIATE RESTORATION OF SAPATGRAM BAMUNIGAON PART I & IV VILLAGE ROAD EMBANKMENT AND WASHED OUT. | (Long - 0.000000, Lat - 0.000000), SATYAPUR TULSHIBIL ROAD | TULSHIBIL, PANIJANI PT I BHUMKA | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 ERODED SOME STRETCHES ON SATYAPUR TULSHIBIL ROAD | (Long - 0.000000, Lat -0.000000), Dotma - Fakiragram-Serfanguri SH Road to Guabari | Vill- Guabari | AS REPORED BY DOTMA REVENUE CIRCLE Damage of PWD road by Flood at Guabari village, Fakiragram-Serfanguri PWD Road to Guabari ON 21.06.2022 | (Long - 0.000000, Lat - 0.000000), Totpara-Jogdai PWD Road | Vill- Kaljhar | AS REPORED BY DOTMA REVENUE CIRCLE Damage of PWD road by Flood Totpara-Jogdai PWD Road to Kaljhar Khan Para ON 21.06.2022 | (Long - 0.000000, Lat - 0.000000), Bahadur-Athiabari Village Road | Vill- Athiabari | AS REPORED BY DOTMA REVENUE CIRCLE Damage of village Road by Flood Bahadurpara to Athiabari Village Road ON 21.06.2022 | (Long -0.000000, Lat - 0.000000). Jogdoi village Road | vill- Jogdai | AS REPORED BY DOTMA REVENUE CIRCLE Damage of road by Flood Jogdoi village road to Jogdoi paddy field ON 21.06.2022 | (Long - 0.000000, Lat -0.000000). Fakiragram College Para Road | Vill- Fakiragram College Para Road | AS REPORED BY DOTMA REVENUE CIRCLE Damage of approach road by Flood at Fakiragram College Para ON 21.06.2022 | (Long - 0.000000, Lat - 0.000000), Fakiragram-Kokrajhar Road | Vill- Kartabari, Pochagarh | AS REPORED BY DOTMA REVENUE CIRCLE Damage of PWD road by Flood at Kartabari, Pochagarh Fakiragram-Kokrajhar Road ON 21.06.2022 | (Long - 0.000000, Lat - 0.000000), Monakocha village Road | Vill- Monakocha | AS REPORED BY DOTMA REVENUE CIRCLE Damage of water outlet and village road at Monakocha village, Fakiragram ON 21.06.2022 | (Long-0.000000, Lat - 0.000000), Hekaipara village road | Vill- Hekaipara | AS REPORED BY DOTMA REVENUE CIRCLE Damage of PWD road and erosion of the road by Flood at Hekaipara ON 21.06.2022 | (Long - 0.000000, Lat -0.000000),Guabari to Khorida Sandla Pt.II PWD Road. | Vill- Khorida Sandla Pt.II | AS REPORED BY DOTMA REVENUE CIRCLE Damage of PWD Road by Flood Fakiragram Guabari PWD Road to Khorida Sandla Pt.II ON 21.06.2022 | (Long - 0.000000, Lat - 0.000000), AS REPORED BY DOTMA REVENUE CIRCLE Totpara Jogdoi PWD Road to Railway Line at Guabari ON 21.06.2022 | Vill- Guabari | AS REPORED BY DOTMA REVENUE CIRCLE Damage of Road by Flood at Totpara Jogdoi PWD Road to Railway Line at Guabari Village ON 21.06.2022 | (Long - 0.000000, Lat - 0.000000), Bagribari - Bhalukjhora to Marsuljhora PWD Road | Marshuljhora | As reported by AEE PWD RR on 20/6/22, the road has been eroded. | (Long - 0.000000, Lat - 0.000000), Lalmati to Tumbagan Bazar PWD Road | Lalmati | As reported by AEE PWD RR on 20/6/22, the road has been washout | (Long - 0.000000, Lat - 0.000000), Kurshakati Bazar to Daldoli Pangkhardol Road | Kurshakati | As reported by AEE PWD RR on 20/6/22, the road has been washout | (Long - 0.000000, Lat - 0.000000), Khoraghat to Jalabila Road | Jalabila | As reported by AEE PWD RR on 20/6/22, road has been eroded in some stretches at Ch.400M, 50M, 800M, and 1800M | (Long - 0.000000, Lat - 0.000000), Snanghat to Jalabila Road | Snanghat | As reported by AEE PWD RR on 20/6/22, road has been eroded in some stretches at Ch.500M and Ch.1800M | (Long - 0.000000, Lat - 0.000000), Araiani Pt-I to Mahamaya Mandir Via Rajapara Pt-II | Rajapara Pt-II | As reported by AEE PWD RR on 20/6/22, road has been eroded washout at Ch.700M | (Long - 0.000000, Lat - 0.000000), Pastibari Chilkikhata Road | Chilkikhata | As reported by AEE PWD RR on 21/6/22, road has been eroded at Ch. 200M | (Long - 0.000000, Lat - 0.000000) Bihpuria - NH-15 at Laluk Kachajuli road | Ch.4900.00m to Ch.5100.00m | The road Submerged and side erosion as reported by AEE, PWRD, Bihpuria TRSD on 21/06/2022 | (Long - 93.896166, Lat - 27.152331), Ahmedpur Daulatpur to Pava E & D Dyke Part-I | Ch. 200.00 m to Ch. 2000.00 m | Road over topped and submerged for a depth of 0.30m damaging hard crust, shoulder, and road as reported by AEE, PWRD, Bihpuria TRSD on 21/06/2022 | (Long - 93.958469, Lat - 27.066826), Lakhimpu Ahmedpur Kutubpur to Gorchiga PWD road at Daulatpur | Ch.1800.00 m to Ch. 2100.00 m | Road over topped and submerged for about 0.30m depth, damaged hard crust, shoulder, and road embankment. Embankment damaged for a length of 50.00m as reported by AEE, PWRD, Bihpuria TRSD on 21/06/2022 | (Long - 93.978413, Lat - 27.081326), Subansiri - Gogamukh Majuli E&D to Bamgaon | As reported by the Dhakuakhana Territorial Road Division the Gogamukh Majuli E & D to Bamgaon Tiniali Road is Submerged at 1st KM (Ch. 400M

	1	
		to 700 M) (L=300M) on 20/06/2022 (Long - 0.000000, Lat - 0.000000), Kekuri Madhupur to Balijan Kachari as reported by the Dhakuakhana Territorial Road Division the Road from Kekuri Madhupur to Balijan Kachari Road is Subway Submerged (L= 60 M) (Long - 0.000000, Lat - 0.000000)
Morigaon	15	Mayong - Jagibhakatgaon Road 1st Km Ch.100m to Ch.400m as reported by PWD Morigaon district territorial road division on 21/06/22 (Long - 0.000000), Lat - 0.000000), T03 to Balimukh Pgr road Submerged 1st to 6th km As reported by PWD Morigaon district territorial road division on 20/06/22 (Long - 92.178000, Lat - 26.219000), 04M 25 to Gagalmari Pam 1st km As reported by PWD Morigaon district territorial road division on 20/06/22 (Long - 92.167000, Lat - 26.288000), Dhekiphala Karatipam part road 1st km Submerged as reported by PWD Morigaon district territorial road division on 20 06 22 (Long - 92.165000, Lat - 26.280000), Burgaon to 1no Baramari from ch 1250 to 1645 1250 to 1645 As reported by PWD Morigaon district territorial road division on 20 06 22 (Long - 92.098000, Lat - 26.272000), Sidhaguri - Garubandha road 2nd km As reported by PWD Morigaon district territorial road division on 20/06/22 (Long - 92.098000, Lat - 26.272000), T-11 to Sukutiputa Habi 2nd 3rd 4th km As reported by PWD Morigaon district territorial road division on 20 06 22 (Long - 92.186000, Lat - 26.25000), Oujari- Garmari - Gagalmari Road Submerged at 8th km As reported by PWD Morigaon district territorial road division on 20 06 22 (Long - 92.188000, Lat - 26.288000), Hariabori SC village to Tetelital 1st 2nd 3rd km As reported by PWD Morigaon district territorial road division on 20 06 22 (Long - 92.188000, Lat - 26.270000), Chotogorjan Karchuwabori road to Sildubi -Gagalmari 1st and 2nd km As reported by PWD Morigaon district territorial road division on 20 06 22 (Long - 92.188000, Lat - 26.270000), Lat - 20.000000, Lat - 20.000000, Sildubi -Gagalmari Kharkharijaan Road 1st km As reported by PWD Morigaon district territorial road division on 20 06 22 (Long - 92.195000, Lat - 26.270000), Sildubi -Gagalmari Kharkharijaan Road 1st km As reported by PWD Morigaon district territorial road division on 20 06 22 (Long - 92.195000, Lat - 26.270000), Sildubi -Gagalmari Road
Nagaon	67	Garmari Gagalmari Road submerged at 8th KM (Long - 92.208140, Lat - 26.288200) Nagaon - Bebjia Palnam Than to Birah Bebejia railgate Bebejia, Nagaon Bebjia Palnam Than to Birah Bebejia railgate, damaged/submerged , Length-250.00m to 380.00m. Depth-200m to 300m reported by Nagaon Territorial Road Sb-Division, Nagaon, dated-21/06/2022, L (Long - 0.000000, Lat - 0.000000), Nonoi Dakhinpat Road to Pubkurabahi road PMGSY Pkg AS19148 Nonoi Dakhinpat Road to Pubkurabahi Nonoi Dakhinpat Road to Pubkurabahi road PMGSY Pkg AS19148, Submerged/damaged for a length of 400m depth of watr 400mm to 900mmreported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/2022 (Long - 0.000000, Lat - 0.000000), Dakhinpat Nonoi Road (NgMN), Dakhinpat Nonoi Dakhinpat Nonoi Road (NgMN) Submerged/damaged, length of 2 to 6km, depth of watr 300mm to600mmreported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 (Long - 0.000000, Lat - 0.000000), Nagaon Dakhinpat to Kampur Road Dakhinpat to Kampur Nagaon Dakhinpat to Kampur Road, Submerged/damaged for a length 13th to 18km depth - 500mm to 1000mm reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 (Long - 0.000000, Lat - 0.000000), Nagaon Dakhinpat road to Burhaguhainthan Dakhinpat road to Burhaguhainthan Nagaon Dakhinpat road to Burhaguhainthan Dakhinpat road to Burhaguhainthan Nagaon Dakhinpat road to Burhaguhainthan, Submerged/damaged, for a length 2500m, depth - 300mm to400mm reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 (Long - 0.000000, Lat - 0.000000), Nagnon Dakhinpat road to Burhaguhainthan Dakhinpat road to Kachoriguri Road, Submerged/damaged, for a length 2200m, depth - 300mm to400mm reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 (Long - 0.000000, Lat - 0.000000), Dakhinpat road to Rangalomukh road Rangalomukh Dakhinpat road to Rangalomukh road, Submerged/damaged, for a length 200mm, depth - 300mm to 500mm repor

Tulsimukh to Rangalumukh Road | Nagaon Sadar Rev. Circle | Tulsimukh to Rangalumukh Road, pkg no AS19 280, submerged for a length 1400m depth of water 300mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Buragohain Than village to Kachuriguri Link road | Nagaon Sadar Rev. Circle | Buragohain Than village to Kachuriguri Link road, submerged for a length 1200m depth of water 300mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Dakhinpat Kampur road to Pachim Borkola Gaon | Nagaon Sadar Rev. Circle | Dakhinpat Kampur road to Pachim Borkola Gaon, pkg no AS19 292, submerged for a length 600m depth of water 300mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Buragohain Than village to Rangolumukh road | Nagaon Sadar Rev. Circle | Buragohain Than village to Rangolumukh road, Pkg. No AS19295, submerged for a length 400m depth of water 200mm to 300mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

NH 36 to Pakhimoria Muslim gaon East, Pkg. No AS19287, submerged for a length 400m depth of water 200mm to 400mm. | Nagaon Sadar Rev. Circle | NH 36 to Pakhimoria Muslim gaon East, Pkg. No AS19287, submerged for a length 400m depth of water 200mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000), Deodhar Chariali to Moukhaiti Village road | Nagaon Sadar Rev. Circle | Deodhar Chariali to Moukhaiti Village road, Pkg. No AS19515, submerged for a length 1500m depth of water 200mm to 300mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Ranthali Jalahgaon to Ranthali Rajabheti Road | Nagaon Sadar Rev. Circle | Ranthali Jalahgaon to Ranthali Rajabheti Road, Pkg. No AS19 212, submerged for a length 1600m depth of water 300mm to 600mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Borkola Sing Gaon to Borkola adarsha Gaon | Nagaon Sadar Rev. Circle | Borkola Sing Gaon to Borkola adarsha Gaon, Pkg. No AS19 212, submerged for a length 1650m depth of water 300mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Ghagorial Gaon Hospita Approach road, submerged for a length 550m depth of water 300mm to 500mm. | Nagaon Sadar Rev. Circle | Ghagorial Gaon Hospita Approach road, submerged for a length 550m depth of water 300mm to 500mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Deorigaon MV School to Nonoi Dakhinpat Road | Nagaon Sadar Rev. Circle | Deorigaon MV School to Nonoi Dakhinpat Road, submerged for a length 800m depth of water 300mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Ranthali Rajabheti to Pakhimoria Block Office | Nagaon Sadar Rev. Circle | Ranthali Rajabheti to Pakhimoria Block Office, submerged for a length 1000m depth of water 300mm to 600mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000).

Nagaon Dakhinpat Road to Madhupur village | Nagaon Sadar Rev. Circle | Nagaon Dakhinpat Road to Madhupur village Part I & Part II, Pkg. No AS19108, submerged for a length 1320m depth of water 300mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Ghagorial Gaon to Uriagaon | Nagaon Sadar Rev. Circle | Ghagorial Gaon to Uriagaon, Pkg. No AS19148 (including bridge package AS19 227), submerged for a length 720m depth of water 300mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Dakhinpat Kampur road to Dakhinpat Nonoi road via Bechamari | Nagaon Sadar Rev. Circle | Dakhinpat Kampur road to Dakhinpat Nonoi road via Bechamari(SOPD), submerged for a length 450m depth of water 300mm to 400mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Nagaon Dakhinpat Road to Aphutoli | Nagaon Sadar Rev. Circle | Nagaon Dakhinpat Road to Aphutoli, Pkg. No AS19 596, submerged for a length 1050m depth of water 300mm to 600mm reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Badyatup Namghar to Ratnapur Bye lane II | Nagaon Sadar Rev. Circle | Badyatup Namghar to Ratnapur Bye lane II(UR), submerged for a length 150m depth of water 200mm to 300mm reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000).

Amulapatty RCC bridge(Lover Bridge) to SH-3(UR) | Nagaon Sadar Rev. Circle | Amulapatty RCC bridge(Lover Bridge) to SH-3(UR), submerged for a length 100m depth of water 200mm to 300mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Jakhalabandha Satra Road | Nagaon Sadar Rev. Circle | Jakhalabandha Satra Road, submerged for a

length 120 m depth of water 200mm to 300mm reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Anandaram Baruah Road | Nagaon Sadar Rev. Circle | Anandaram Baruah Road(Cow Path), submerged for a length 200 m depth of water 200mm to 300mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000), Rudra Ram Bordoloi Road(ADP College road) | Nagaon Sadar Rev. Circle | Rudra Ram Bordoloi

Rudra Ram Bordoloi Road(ADP College road) | Nagaon Sadar Rev. Circle | Rudra Ram Bordoloi Road(ADP College road), submerged for a length 130 m depth of water 200mm to 300mm. reported by Nagaon Territorial Road Road Sub-Division, Nagaon, dated-21/06/202 | (Long - 0.000000, Lat - 0.000000),

Kampur - L023-NH 36 SINGRABASTI TO URIAGRANT RANGOLO ROAD | Kampur Rev. Circle | L023-NH 36 SINGRABASTI TO URIAGRANT RANGOLO ROAD, PMGSY, PACKAGE NO. AS-19-371 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

L067-CHANGKHOLA TO GARUKHUNDA VIA DAMAIHOGI DAPARA RD | Kampur Rev. Circle | L067-CHANGKHOLA TO GARUKHUNDA VIA DAMAIHOGI DAPARA RD, PMGSY, PACKAGE NO. AS-19-396. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

DAKHIN CHANGEHAKI TO TOPAKUCHI VIA GARUBAT AND KUHIMARI NO 2 | Kampur Rev. Circle | DAKHIN CHANGEHAKI TO TOPAKUCHI VIA GARUBAT AND KUHIMARI NO 2, PMGSY, PACKAGE NO. AS-19-417 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), L059-DAKHINJAR BORGAON TO AMDUBI VIA DAKHIN AMARI | Kampur Rev. Circle | L059-DAKHINJAR BORGAON TO AMDUBI VIA DAKHIN AMARI, PMGSY, PACKAGE NO. AS-19-424 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

L042-KK ROAD MAHONIATI TO KACHAIKHANIA RD | Kampur Rev. Circle | L042-KK ROAD MAHONIATI TO KACHAIKHANIA RD, PMGSY, PACKAGE NO. AS-19-445 Submerged/Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

GARUBANDHA TO BARAPAM | Kampur Rev. Circle | GARUBANDHA TO BARAPAM, PMGSY, PACKAGE NO. AS-19-446. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

PUTHUIMARI TO RADHA NAGAR, PMGSY, PACKAGE NO. AS-19-457 | Kmapur Rev. Circle | PUTHUIMARI TO RADHA NAGAR, PMGSY, PACKAGE NO. AS-19-457. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

PRAMILA ATI TO BALIGAON | Kampur Rev. Circle | PRAMILA ATI TO BALIGAON, PMGSY, PACKAGE NO. AS-19-553 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

L080-LUTUMARI LONGJUP RD TO TANGIABANGAON | Kampur Rev. Circle | L080-LUTUMARI LONGJUP RD TO TANGIABANGAON, PMGSY, PACKAGE NO. AS-19-635. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

L048-DK ROAD PARALIGURI TO ATI KAMPUR | Kampur | L048-DK ROAD PARALIGURI TO ATI KAMPUR, PMGSY, PACKAGE NO. AS-19-362 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), GARUBANDHA TO DABBLONG, PMGSY, PACKAGE NO. AS-19-421 | Kampur Rev. Circle | GARUBANDHA TO DABBLONG, PMGSY, PACKAGE NO. AS-19-421. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

L088-KSB ROAD TO PACHIM BIRINATI, PMGSY, PACKAGE NO. AS-19-425 | Kampur Rev. Circle | L088-KSB ROAD TO PACHIM BIRINATI, PMGSY, PACKAGE NO. AS-19-425. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

MAIKOLONG TO GAURANGA ATI | Kampur Rev. Circle | MAIKOLONG TO GAURANGA ATI, PMGSY, PACKAGE NO. AS-19-429. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), SIMALUGURI TO MARISUTI, PMGSY, PACKAGE NO. AS-19-435 | Kampur Rev. Circle | SIMALUGURI TO MARISUTI, PMGSY, PACKAGE NO. AS-19-435. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

MISSAMARI TO GAURANGAPAR | Kampur Rev. Circle | MISSAMARI TO GAURANGAPAR, PMGSY, PACKAGE NO. AS-19-436 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

SIMALUGURI TO PRAMILA BASTI | Kampur Rev. Circle | SIMALUGURI TO PRAMILA BASTI, PMGSY, PACKAGE NO. AS-19-461 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), PUTHIMARI TO PUTHIMARI I | Kampur Rev. Circle | PUTHIMARI TO PUTHIMARI I, PMGSY,

PACKAGE NO. AS-19-634 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R)

Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), L068-KUMBHI DUBI TO CHIRAPATHAR | Kampur Rev. Circle | L068-KUMBHI DUBI TO CHIRAPATHAR, PMGSY, PACKAGE NO. AS-19-462 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NAGAON-DAKHINPAT-KAMPUR ROAD TO KOLAIKHUWA | Kampur Rev. Circle | NAGAON-DAKHINPAT-KAMPUR ROAD TO KOLAIKHUWA, PMGSY, PACKAGE NO. AS-19-305. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

L074-RENGBANG GRANT TO PATIAPAM, PMGSY, PACKAGE NO. AS-19-368 | Kampur Rev. Circle | L074-RENGBANG GRANT TO PATIAPAM, PMGSY, PACKAGE NO. AS-19-368 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

RANGALOO TO SENGMARA GAON Road | Kampur Rev. Circle | RANGALOO TO SENGMARA GAON Road Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

K.K. ROAD TO BUKLUNG GAON | Kampur Rev. Circle | K.K. ROAD TO BUKLUNG GAON Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

BAMUNIGOSAIN THAN TO NOIPAM VIA BENGENA ATI | Kampur Rev. Circle | BAMUNIGOSAIN THAN TO NOIPAM VIA BENGENA ATI Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000).

SENGMORA ROAD TO KACHUPIT | Kampur Rev. Circle | SENGMORA ROAD TO KACHUPIT Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

BORHULA TO TELIA ATI ROAD | Kampur Rev. Circle | BORHULA TO TELIA ATI ROAD Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

KAMPUR JAMUNAMUKH ROAD AT 1ST TO 3RD KM. | Kampur Rev. Circle | KAMPUR JAMUNAMUKH ROAD AT 1ST TO 3RD KM. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), THE APPROACH OF THE RCC BRIDGE NO. 8/1 BREACHED AT KATHIATOLI KAMPUR ROAD (SH-17) | Kampur Rev. Circle | THE APPROACH OF THE RCC BRIDGE NO. 8/1 BREACHED AT KATHIATOLI KAMPUR ROAD (SH-17) ON 18TH OF JUNE,2022 DUE TO 2ND WAVE OF FLOOD Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur

Pachim Tetelisora tp Polosa | Kampur Rev. Circle | Pachim Tetelisora tp Polosa Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Pachim Tetelisora to Kekuribari | Kampur Rev. Circle | Pachim Tetelisora to Kekuribari Submerged/Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000), Lat - 0.000000).

KK Road to Kalikhuwa via Pachim Tetelisora. | Kampur Rev. Circle | KK Road to Kalikhuwa via Pachim Tetelisora. Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Pachim Nambor Lalunggaon | Kampur Rev. Circle | Pachim Nambor Lalunggaon Submerged/Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Rangaloo to Gosaikhat | Kampur Rev. Circle | Rangaloo to Gosaikhat Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

SOLMARI TO KAKOLIR SUK, PKG NO: AS-19-595 | Kampur Rev. Circle | SOLMARI TO KAKOLIR SUK, PKG NO: AS-19-595 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

KSB Road to Madhapara Jeetgaon | Kampur Rev. Circle | KSB Road to Madhapara Jeetgaon, PMGSY, Package No. AS-19-409 Submerged/ Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Topakuchi to Haldhiati | Kampur Rev. Circle | Topakuchi to Haldhiati, PMGSY, Package No. AS-19-399. (Bridge Approach completely damaged). Submerged / Damaged Dtd-20.06.2022 Reported by PWD(R) Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Raha - Phulaguri to Uttar Petborha | Raha Rev. Circle | Phulaguri to Uttar Petborha road breach total length- 25 M Dtd-21.06.2022 reported by PWD Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Saragaon to Dewbali | Raha Rev. Circle | Saragaon to Dewbali eroded at 1st KM L- 150 M Dtd-21.06.2022 reported by PWD Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Khaigarh Meteka Dighaldori Phulaguri road | Raha Rev. Circle | Khaigarh Meteka Dighaldori Phulaguri road breach total length-50 M Dtd-21.06.2022 reported by PWD Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000)

Ghograpar - Namati Lakshmi Mandir Road | Namati | As per PWRD Report, Namati Lakshmi Mandir Road has been damaged on 20/06/2022, Length - 200 M | (Long - 0.000000, Lat - 0.000000), Barkhetri - hamlakur chowk to jugarbori via kurabahi | hamlakur | submerged, length 1200m as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat -0.000000). ghoga uttar supa chowk to ghoga2 road | ghoga | submerged length 700m and erosion 200m as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat -0.000000), loharkatha bezkuchi road | loharkatha | submerged length 1.5km as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat - 0.000000), balikuchi chowk to lautola via ghoga2 | balikuchi | submerged 1km and erosion 400m as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat - 0.000000), chakirghat to adabari ib road | chakirghat | submerged 1km as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat - 0.000000), dagapara to kurabari road | dagapara | submerged 1.60km as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat - 0.000000), ahata bakrikuchi road | ahata bakrikuchi | submerged 800m as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat - 0.000000), narayanpur pubchowk to lauthari road | lauthari | submerged 400m as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat - 0.000000), naptipara village road | naptipara | submerged 1100m as reported by AEE, PWRD, Barkhetri teritorial sub Div on 20/06/2022 | (Long - 0.000000, Lat - 0.000000), Banekuchi - Kaithalkuchi to Burinagar Road | Kaithalkuchi | As per report of Gaon Pradhan the road is submerged due to flood on 18/06/2022 | (Long - 0.000000, Lat - 0.000000), Rajakhat Banekuchi to Madhupur Road | Madhupur | As per report of PWRD Deptt, the road is submerged due to flood on 18/06/2022 | (Long - 0.000000, Lat - 0.000000), Silakuti to Sokojala Road | Silakuti | As per report of PWRD Deptt, the road is submerged due to flood on 18/06/2022 | (Long - 0.000000, Lat - 0.000000), Tihu - PATIKARA ROAD,KATHALMURA ROAD,NAMSALA ROAD,KAUREHAGI-KASKURI ROAD ,OUKURI ROAD DAMAGED | 42 NO JALKHANA-BHATHUWAKHANA GP | LENGTH:6.5 KM(APPROX), INFORMATION RECEIVED FROM BDO, P&RD, DATE OF DAMAGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), MATRHURAPUR ROAD, RATANPUR ROAD, TOUMARI ROAD, RANAKUCHI ROAD, JAMUNATTARI ROAD, | 43 NO MATHURAPUR GP | LENGTH:7 KM(APPROX), INFORMATION RECEIVED FROM BDO, P&RD, DATE OF DAMAGED :17/06/2022 | (Long - 0.000000, Lat - 0.000000), NAMATI ROAD,BAMUNBARI ROAD,NIZ NAMATI ROAD,1 NO NATHKUCHI ROAD,2NO NATHKUCHI ROAD, | 44NO NATHKUCHI GP | LENGTH:7 KM(APPROX),INFORMATION RECEIVED FROM BDO,P&RD, DATE OF DAMAGED: 17/06/2022 | (Long - 0.000000, Lat -0.000000), BHOJKUCHI HARIBHANGA ROAD, BALI-BARPIT ROAD, BALI-UTTAR BALI ROAD, HARIBHANGA-MAKHIBAHA ROAD, HARIBHANGA-JALKHANA ROAD. | 45NO PASHIM NAMABARBHAG GP | LENGTH:8 KM(APPROX), INFORMATION RECEIVED FROM BDO,P&RD, DATE OF DAMAGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), GOBARADAL-SATHIKUCHI ROAD,SATHIKUCHI ROAD,GOBARADAL-BARAMA ROAD,GOBARADAL ROAD ,BAKUWAJARI ROAD, BARBHAGJARI ROAD,GOBARADAL-DAHKAUNIYA ROAD, | 46 NO PUB NAMBARBHAG GP | LENGTH:10 KM(APPROX), INFORMATION RECEIVED FROM BDO, P&RD, DATE OF DAMAGED :17/06/2022 | (Long - 0.000000, Lat - 0.000000), KATHALKUCHI TO HARIBHANAG VIA BALI ROAD BREACHED | BALI | LENGTH:70 MTS (APPROX), INFORMATION RECEIVED FROM PWD(R), BARAMA, DATE OF DAMAGED :17/06/2022 | (Long - 0.000000, Lat - 0.000000), BHOJKUCHI ROAD SUBMERGED | BHOJKUCHI,HARIBHANGA | LENGTH:2 KM (APPROX), INFORMATION RECEIVED FROM JE, PWD(R), BARAMA, DATE OF SUBMERGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), SIALMARI RCC BRIDGE APPROACH ROAD DAMAGED(BRIDGE NO 3/1) | BALI | LENGTH:500 MTS (APPROX), INFORMATION RECEIVED FROM JE, PWD(R), BARAMA, DATE OF SUBMERGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), HARIBHANGA PWD ROAD SUBMERGED | HARIBHANGA | LENGTH: 1.5 KMS. (APPROX), INFORMATION RECEIVED FROM JE, PWD(R), BARAMA, DATE OF SUBMERGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), TIHU FEEDER ROAD | TIHU | LENGTH:1 KMS TO 3.5KM (APPROX),INFORMATION RECEIVED FROM JE, PWD(R), PATACHARUCHI DIVISION , DATE OF SUBMERGED :17/06/2022. | (Long - 0.000000, Lat - 0.000000), TIHU AKHARA ROAD | TIHU | LENGTH:0 KMS TO 3 KM (APPROX),INFORMATION RECEIVED FROM JE,PWD(R),PATACHARUCHI DIVISION, DATE OF SUBMERGED :17/06/2022. 1 CULVERT DAMAGED | (Long - 0.000000, Lat - 0.000000),

KAUREHAGI -KASKURI ROAD | JALKHANA | LENGTH:0 KMS TO 1 KM

(APPROX), INFORMATION RECEIVED FROM JE, PWD(R), PATACHARUCHI DIVISION,

Nalbari

38

DATE OF SUBMERGED: 17/06/2022.BRIDGE APPROCH 2/1 DAMAGED | (Long - 0.000000), Lat - 0.000000). TIHU-KAUREHAGI ROAD | TIHU | LENGTH:0 KMS TO 1 KM (APPROX),INFORMATION RECEIVED FROM JE,PWD(R),PATACHARUCHI DIVISION, DATE OF SUBMERGED :17/06/2022 | (Long - 0.000000, Lat - 0.000000), GHOPA TO KHETRAOARA ROAD | MAHIBAHA/JALKHANA | LENGTH:0 KMS TO 1 KM (APPROX), INFORMATION RECEIVED FROM JE, PWD(R), PATACHARUCHI DIVISION, DATE OF SUBMERGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), TIHU -SATHEBARI ROAD (NATHKUCHI TO JALKHANA ROAD) | TIHU | LENGTH:6,7, & 8 KM (APPROX), INFORMATION RECEIVED FROM JE, PWD(R), PATACHARUCHI DIVISION, DATE OF SUBMERGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), KANIMARA -NANNATTARI ROAD | NIZKHANA | LENGTH:0 KMS TO 1.3 KM (APPROX), INFORMATION RECEIVED FROM JE, PWD(R), PATACHARUCHI DIVISION, DATE OF SUBMERGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), TIHU COLLEGE APPROACH ROAD | TIHU | LENGTH:700 MTS (APPROX),INFORMATION RECEIVED FROM JE,PWD(R),PATACHARUCHI DIVISION, DATE OF SUBMERGED :17/06/2022 | (Long - 0.000000, Lat - 0.000000), TIHU-DUMNI ROAD | TIHU | LENGTH:4000 MTS TO 5200 MTS (APPROX),INFORMATION RECEIVED FROM JE, PWD(R), PATACHARUCHI DIVISION, DATE OF SUBMERGED :17/06/2022 | (Long - 0.000000, Lat - 0.000000), JALKHANA-BHATHUWAKHANA ROAD | JALKHANA/BHATHUWAKHA | LENGTH: 1.5 KMS (APPROX),INFORMATION RECEIVED FROM JE,PWD(R),PATACHARUCHI DIVISION , DATE OF SUBMERGED: 17/06/2022 | (Long - 0.000000, Lat - 0.000000), Paschim Nalbari - Nalbari Palla road near DPS School. | Panigaon | Side bern and hard cv net damage. Information received from PWRD on 21/06/2022. | (Long - 0.000000, Lat - 0.000000), Bihampur to Kakaya via Kamrup College. | Chamata | Required 4.00 m slab culvert to drain. Information received from PWRD on 21/06/2022. | (Long - 0.000000, Lat - 0.000000), Nalbari Palla road to Samannay Chowk to Masterpara. | Chamata | Road surface damage. Information received from PWRD on 21/06/2022. | (Long - 0.000000, Lat - 0.000000), Kaihati link road to Barkoihati via Bharali Supa | Kaihati | Submerged from ch 0.00 to 500.00 m. Information received from PWRD on 21/06/2022. | (Long - 0.000000, Lat - 0.000000), Purni Barpit Road | Purni | Washed away for a length of 30.00 m at 4th Km. Side berm and hard surface also damage. Information received from PWRD on 21/06/2022. | (Long - 0.000000, Lat -0.000000). Nalbari - PURBABHARATI ROAD | NALBARI | AS PER REPORT OF PWRD ROAD SURFACE DAMEGED LENGTH 1.00KM DATED :18/06/2022 | (Long - 0.000000, Lat -Goreswar - Kashubari- Naokata - Pathurighat road | Village Niz- Jhargaon | As report received from PWD dept on dated 21/06/2022, SPT bridge approach both side washed away, approx damage 6 m. | (Long - 91.710233, Lat - 26.638450). Rangia- Chenimara- Barghuli Road | Village Chenimara, Bihapara | As report received from PWD Dept. on 21/06/2022. Hard crust and shoulder washed away due to over flow of flood water. | (Long -91.624184, Lat - 26.477050). Khandikar- Chirakhundi Road | Village Khandikar Bihapara | As report from PWD dept on 21/06/2022, Slab culvert approach and road embankment eroded, approx 50 m. | (Long - 91.382519, Lat - 26.275367), Madalbari- Betagaon Road | Village - Chenigaon | As report received from PWD Dept. on 21/06/2022, SPT bridge washed away along with approaches. | (Long - 91.403069, Lat - 26.362384), Goreswar- Barphukankhat PMGSY road | Village Barphukankhat | As report received from PWD Dept on 21/06/2022, Hard crust and shoulder eroded. | (Long - 91.450116, Lat - 26.321253), Goreswar- Baygola Road | Hajalpara | As report received from PWD Dept on 21/06/2022, Hard crust and shoulder eroded | (Long - 91.768424, Lat - 26.520025), Goreswar- Khoirabari road | Village - Cheuni, Rangmahal | As report received from PWD Dept on Tamulpur 34 21/06/2022, RCC bridge approach eroded and side slope and shoulder eroded. | (Long - 91.441250, Lat - 26.322190). Maharipara- Pukhuripar Road | Village Pukhuripar | As report received from PWD Dept on 21/06/2022, RCC bridge approach washed away. | (Long - 91.692253, Lat - 26.582063), Baghdoba- Harijora Road | Village Harijora | As report received from PWD Dept on 21/06/2022, RCC slab culvert washed away | (Long - 91.768424, Lat - 26.520025), Baghdoba- Barkachula Road | Barkachula village | As report received from PWD Dept on 21/06/2022, Bamboo foot bridge along with embankment washed away. | (Long - 91.693065, Lat -26.546734), Kerpavitha- Singimari Road | Singimari Village | As report received from PWD Dept on 21/06/2022, road embankment with hard crust washed away. | (Long - 91.460785, Lat - 26.332482), Ulubari- Baribandha road | Dhepargaon (Ulubari Suba) Village | As report received from PWD Dept on 21/06/2022, RCC box cell along with approaches washed away | (Long - 91.382170, Lat -26.282160), Rangia- Latibari Road | Village Gurmow | As report received from PWD Dept on 21/06/2022, road hard crust damaged. | (Long - 91.384200, Lat - 26.352800),

	1		
			Tamulpur Goreswar Road Balabari As report received from PWD dept on 21/06/2022, Road embankment got damaged (Long - 91.411263, Lat - 26.333381),
			Tamulpur - LAOPARA TO BARIMOKHA ROAD. ON DATED 21-06-22 LAOPARA DUE TO
			HEAVY RAIN, FLOOD DAMAGED A SUBCULVERT AT TEBITOLA. EROISION DAMAGE
			10M. (Long - 90.381000, Lat - 26.404200),
			BARALIA DAKHIN SUBA, ON DATED 21-06-22 KALAKUCHI EROISION DAMAGE 1KM. (Long - 91.535730, Lat - 26.571842),
			PUNIA TO GHAGRAPAR ROAD. ON DATED 21-06-22 PUNIA EROISION DAMAGE 100M
			(Long - 0.000000, Lat - 0.000000),
			RANGIA LATIBARI TO GURMOW ROAD. ON DATED 21-06-22 GURMOW EROISION
			DAMAGE 100M (Long - 91.384200, Lat - 26.452900),
			KAWLI ROAD NEAR CHANDANPUR S.S.B CAMP KAWLI . ON DATED 21-06-22 KAWLI
			EROISION DAMAGE 50M (Long - 91.374000, Lat - 26.452900), KAWLIPUR TO SINGIMARI ROAD. ON DATED 21-06-22 KAWLI EROISION DAMAGE
			80M (Long - 91.598000, Lat - 26.744000),
			KUMARIKATA TO KAWLI ROAD. ON DATED 21-06-22 KUMARIKATA EROISION
			DAMAGE 100M (Long - 91.608830, Lat - 26.759451),
			BARBILA CHAWK TO BARBILA DAKHIN SUBA UNDER SOPD-G. ON DATED 21-06-22
			BARBILA EROISION DAMAGE 1KM (Long - 91.533168, Lat - 26.503000), RANGIA DHAMDHAMA ROAD TO NAMSUDRA LP SCHOOL CHOWKMARI. ON DATED
			21-06-22 GHOGRAPAR EROISION DAMAGE 700M (Long - 91.574715, Lat - 26.585449),
			BARANGABARI TO SURABARI ROAD UNDER SOPD-G. ON DATED 21-06-22 GHOGMARI
			EROISION DAMAGE 50M (Long - 91.595436, Lat - 26.623456),
			KAULIPAR 1 NO. ON DATED 21-06-22 KAWLI EROISION DAMAGE 75M (Long -
			91.612065, Lat - 26.753482), RAPAMA DHAMDHAMA TAMUL PUR ROAD, ON DATED 21.06.22 TAMUL PUR L
			BARAMA DHAMDHAMA TAMULPUR ROAD. ON DATED 21-06-22 TAMULPUR EROISION DAMAGE 4.5KM (Long - 91.561010, Lat - 26.605720),
			JHARGAON CHAWK TO MEREGAON VILL AND PALASHBARI. ON DATED 21-06-22
			JHARKONA EROISION DAMAGE 250M (Long - 91.635945, Lat - 26.582820),
			MOTUNGA CHAWK TO NARAYANPUR CHAWK SIDHINATHPUR. ON DATED 21-06-22
			KAWLI EROISION DAMAGE 700M (Long - 91.374640, Lat - 26.447000),
			PATKIJULI DAHARPUR ROAD. ON DATED 21-06-22 PAHARPUR EROISION DAMAGE 750M (Long - 91.461945, Lat - 26.788031),
			KUMBHIJAR TO GAGAN CHAWK ROAD. ON DATED 21-06-22 PAHARPUR EROISION
			DAMAGE 20M (Long - 91.657270, Lat - 26.724000),
			ANANDA BAZAR TO HAHKATA ROAD. ON DATED 21-06-22 ANANDA BAZAR
			EROISION DAMAGE 200M (Long - 91.507228, Lat - 26.597230),
			TAMULPUR GORESWAR ROAD. ON DATED 21-06-22 GANDHIBARI EROISION DAMAGE 50M (Long - 91.855745, Lat - 26.583164),
			KEKRIKUCHI TO BOROLIPAR. ON DATED 21-06-22 KEKRIKUCHI EROISION DAMAGE
			150M (Long - 91.613092, Lat - 26.547540),
			NIZ-DEFELI TO JOKMARI ROAD. ON DATED 21-06-22 KEKRIKUCHI EROISION
			DAMAGE 150M (Long - 91.610290, Lat - 26.543275)
			Khairabari - 1. Howly Chuba to Mazgaon Road At Latakhat HPC of length about 10 M (approx.)
			was damaged on 18.06.2022, due to the pressure exerted by the overflowing of flood water. (Long - 91.523600, Lat - 26.375600),
			2. Kuhiarkuchi to Maldangpara Road At Maldangpara HPC of length about 10 M (approx.) was
			damaged on 18.06.2022, due to the pressure exerted by the overflowing of flood water. (Long -
			91.796951, Lat - 26.523733),
			Harisinga - Chenipara vilage road Chenipara Village road damaged at Chenipara village due to heavy rainfall around 7.8 m on 17th June 2022 (Long - 91.942200, Lat - 26.686500),
			Bhergaon Borongajuli road Balishitha the road from Bhergaon to Borongajuli eroded due to heavy
	1111	0	rainfall on 16th June 2022. (damaged 6m) (Long - 91.825400, Lat - 26.728000),
	Udalguri	8	Nonaipara to Garuajhar road Garuajhar The Nonopipara road to Garuajhar eroded due to heavy
			rainfall on 20th June 2022. (3.6m damaged) (Long - 91.879300, Lat - 26.837500),
			Uttar Garuajhar to Nonaikhuti road Nonaikhuti The road from Uttar Garuajhar to Nonaikhuti completly eroded for which the road communication disrupted on 20/06/2022 (3.1m Damaged)
			(Long - 91.879800, Lat - 26.827500),
			tangla Deor road Palahgarh The Tangla Deoar road eroded due to heavy rainfall on 19/06/2022.
			(3.8m Damaged) (Long - 91.564700, Lat - 26.392400),
			Kalaigaon - Bholabari High School Chowk to Bholabari Bazar link Road Bholabari The HPC
			including road surface damaged on 21/06/2022 due heavy current of flood water from river Kulshi covering a length of 200 meters and breadth of 8 meters. (Long - 92.078813, Lat - 26.643233)
	Total	316	covering a rengin of 200 meters and ofeatin of 6 meters. [(Long - 92.076613, Lat - 20.043255)
		Numbe	Dataila
Infrastructur	District	r	Details
e Damaged -	De:-1.		Bajali - SPT BR No. 1/1 Khelangpara Bogapara road SPT Bridge no. 1/1 has been washed away.
Bridge	Bajali	9	Affected length and depth approximately 2.5 meter and 2.2 meter respectively. This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala- dated- 20/06/2022 (Long - 0.000000, Lat
	•	1	nom red, 1 mb, 1 attoriation, 1 is sub-arrision, 1 attisata- uateu- 20/00/2022 (LUIIg - 0.000000, Lât

		0.000000		
		- 0.000000), Soitemari village approach Soitemari Affected length 1.85 KM.This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala- dated - 20/06/2022 (Long - 0.000000, Lat - 0.000000),		
		0.000000), SPT Bridge no. 3/1 Haderi Nityananda Road washed away. Approximate length and depth are 2.5 m and 2.8 m respectively. This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala dated - 20/06/2022 (Long - 0.000000, Lat - 0.000000),		
		SPT Bridge no.1/1 Kaharpara Pokha Road This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala dated - 20/06/2022 (Long - 0.000000, Lat - 0.000000),		
		RCC Bridge no. 4/1 Upar Noi Ulua Road This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala dated - 20/06/2022 (Long - 0.000000, Lat - 0.000000),		
		RCC Bridge Hakartup Ghat This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala dated - 20/06/2022 (Long - 0.000000, Lat - 0.000000),		
		RCC Bridge no.1/1 Ratanpur Bamakhata Road This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala dated - 20/06/2022 (Long - 0.000000, Lat - 0.000000), SPT Bridge no. 1/1 Lachitnagar This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala dated - 20/06/2022 (Long - 0.000000, Lat - 0.000000),		
		SPT Foot bridge no. 1/1 Swahid Pronoy Kalita road This report is received from AEE, PWD, Patacharchi, TR sub-division, Pathsala dated - 20/06/2022 (Long - 0.000000, Lat - 0.000000)		
		Dotma - Thaigirguri wooden Bridge Vill- Thaigirguri AS REPORED BY DOTMA REVENUE CIRCLE Damage of wodden bridge by Flood at Thaigirguri village ON 21.06.2022 (Long - 0.000000, Lat - 0.000000), Angthihara Wooden Bridge Vill- Angthihara AS REPORED BY DOTMA REVENUE CIRCLE		
	Kokrajhar	Damage of wooden bridge by Flood at Angthihara Village ON 21.06.2022 (Long - 0.000000, Lat - 0.000000), Bagribari - Bridge No.1/1 Kurshakati (Satra) PWD Road to Alokjhar Mahamaya Dham Road As reported by AEE PWD RR on 20/6/22, the bridge and road has been damaged (Long - 0.000000, Lat		
	_	- 0.000000)		
	Morigaon	Mayong - Approaches of RCC bridge no 1/1 Sildubi -Gagalmari to Kharkharijaan As reported by PWD Morigaon district territorial road division on 20/06/22 (Long - 92.195000, Lat - 26.277000)		
	Nagaon	Raha - Raha Chaki Railway Bridge Raha Chaki Date of Occurrence-20/06/2022 Eroded-near the bridge Department-Railway Department (Long - 0.000000, Lat - 0.000000)		
	Nalbari	Paschim Nalbari - RCC Br. No. 1/1 on Bagurihati Chatimapara road Bagurihati Approches damage. Information received from PWRD on 21/06/2022 (Long - 0.000000, Lat - 0.000000), Nalbari - RRC BR NO. 1/1 ON PATKATA TO DHEKIABARI ROAD PATKATA TO DHEKIABARI ROAD As per report of PWRD department RRC BR NO. 1/1 ON PATKATA TO DHEKIABARI ROAD APPROCH DAMEGED ON 18/06/2022 (Long - 0.000000, Lat - 0.000000)		
	Tamulpur	Tamulpur - SUBWAY OF BRIDGE NO 7/1 OVER RIVER BAROLIA AT JHARKONA. ON DATED 21-06-22 JHARKONA SUBWAY BROKEN. (Long - 91.644148, Lat - 26.589782), UTTAR GAIBERA ROAD BRIDGE. ON DATED 21-06-22 UTTAR GAIBERA DAMAGE 10M (Long - 91.633831, Lat - 26.541830)		
	Udalguri	Harisinga - Nonoi RCC Bridge TB road purani tangla The Nonoi RCC bridge damaged on 18/06/2022. (5.1m damaged) (Long - 91.535200, Lat - 26.392000), Huduma Bridge pub nalbari bridge approach at Huduma bridge on 17/06/2022. (6m damaged) (Long - 91.897700, Lat - 26.655600)		
	Total	20		
	District	Wildlife affected under protected areas description		
Infrastructur e Damaged - Wildlife	Golaghat	(Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 8 are inundated), Bokakhat Range (Out of 7 camps 2 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 21-06-2022.		
	Morigaon	Mayong - Pobitora WLS out of a total 25 no of camps Affected 17 and inundated 14nos of camps as reported by Range Officer PWLS on 21/06/22		
	District	Other Details		
	Bajali	Sarupeta - Power Dept. Poles Pole damaged at Taltol,roumari tanglipara and bharegaon(Reported by SDE,pathsala electrical subdivision on 21/6/2022), Power Dept. Conductors Conductor snapped at Taltol,roumari tanglipara and bharegaon(Reported by		
Infrastructur e Damaged -		SDE, pathsala electrical subdivision on 21/6/2022), Power Dept. Transformers 1 nos of 250K va transformer damaged at village Dakhin bati (Reported by		
		Power Dept. Transformers 1 nos of 250Kva transformer damaged at village Dakhin hati (Reported by SDE,pathsala electrical subdivision on 21/6/2022), Bajali - Fisheries/Pond Total no of villages- 33. Total no of ponds affected(approx)-451 nos. Total w/a		
Others	Baksa	(ha)affected(approx)-60.9 ha, dated 20/06/2022 Baska - Culvert Approach Road Damaged Bhalukdonga to Ulubari Village Road slab culvert damaged at Village Nalbari, on 18/06/2022, Coordinate: 26.580762, 91.328052,		
		Culvert Approach Road Damaged Seriesbari Belguripathar road to Laphakuchi Thamna Village Road at village Belguripatharon 18/06/2022. Co-ordinate: 26.645089, 91.330170,		
		Culvert Approach Road Damaged Bogapara to Ambari paddy field road at village Belguripathar on 18/06/2022, Co0rdinate: 26.646895, 91.325158, Culvert Approach Road Damaged Bhurkuchi to Puran Mushalpur road at village Belguripathar on 18/06/2022,		

Co-ordinate: 26.638373, 91.328703, Culvert Approach Road Damaged | Puranamushalpur mohorisupa Village Road culvert at village Mushalpur, 18/06/2022, Co-ordinate: 26.625486, 91.320347, Culvert Approach Road Damaged | Dighaldonga to dakhinsupa Village Road slab culvert at village dakhinsupa, 18/06/2022 Coordinate: 26.647193, 91.381628, Culvert Approach Road Damaged | Narayanpur Simliguri to 2 No. Narayanpur Village Road at village Narayanpur, Cordinate: 26.676814, 91.345569 Date: 18/06/2022, Culvert Approach Road Damaged | Narayanpur Goybari to Motipur vote centre road at village Motipur, Coordinate: 26.679545, 91.365304 Date: 18/06/2022, Culvert Approach Road Damaged | National Highway to Mushlim Spupa at village B- Block. Coordinate: 26.712783, 91.397251, Date: 18/06/2022, Culvert Approach Road Damaged | 1 No. Bhogpara to 2 No. Bhogpara road slab culvert, Date: 18/6/2022, Coordinate: 26.685463, 91.332424, Culvert Approach Road Damaged | 2 No. Bhogpara to paddy field road culvert, Date:18/06/2022, Co-ordinate: 26.682574, 91.340555 Chenga - Anganwadi Centres Affected | 98 nos. Anganwadi centre partially affected under Chenga ICDS Project, reported by CDPO on 20/06/2022, 5 nos. Anganwadi centre partially affected under Gomafulbari ICDS project, reported by CDPO on 21/6/2022, **Sarthebari** - Fisheries/Pond | 199, Kalgachia - Protection Bundh Damaged | As per report received frm BDO rupshi on 20/06/22, due to heavy rainfall and flood const of Flood protection bundh st frm Wazed Ali house to Kalam Ali house at vill-Showpur, coordinates- 26.33553, 90.878125, Agri Bundh Damaged | As per report received frm BDO rupshi on 20/06/22, due to heavy rainfall and flood, Barpeta const. of Agril bundh frm Abed ALi house to east side Nowsad Ali house at vill Chandmama gaon, damaged details- L=10m, B=5m, H=2m., Fisheries/Pond | As per report received frm Fishery dept on 21/06/22, total 1059 nos of ponds submerged within the jurisdiction of Kalgachia Rev Circle as on today and total water are of water body submerged- 227.36 Ha., Barnagar - Fisheries/Pond | As per report of the Fishery demonstrator, Sorbhog on 20/06/2022 total 63.39 Hectar of Fish Farm affected., Anganwadi Centres Affected | As per received from CDPO, Sorbhog on 20/06/2022, Two nos of AWC namely 33 No. Madhya Balabhita ICDS {roject and 35 No. Balabhita Pacchim AWC affected Manikpur - Anganwadi Centres Affected | 1)133 No.Moukhowa Pachim,2) 105 No.Garoleti, 3) 32 No.Dhupuri-II, 4) 253 No.Jharbari Bangalipara (Mini),5) 254 No.Charpara (Mini), 6) 156 No.Mandal & Char Para,7) 104 No.Dhupuri-I, 8) 157 No.Maji Para, 9) 151 No.Raina Para, 10) 152 No.Lungjhar nama Para, 11) 106 No.Salmara, 12) 34 No.Lungihar, 13) 161 No.Barbakhra Bazar, 14) 33 No.Barbakhra, 15) 160 No.Khayerguri, 16) 159 No.Barbakhra Pachim, 17) 31 No.Supariguri-II,18) 37 No.Nowapara-II,19) 155 No.Nowapara Pub Dakhin, 20) 255 No.Madhya Para (Mini), 21) 153 No.Pub Nowapara, 22) 36 No.Nowapara-I, 23) 158 No.Nowapara Pachim Para, 24) 154 No.Bhatipara Muslim Para, 25) 35 No.Bhatipara, 26) 173 No.Bechimari Dakhin Para, 27) 59 No.Bashbari-5, 28) 244 No.5 No Bashbari Manas Dakhin Par, 29) 118 No.6 No Bashbari, 30) 245 No.6 No Bashbari Uttar Dakhin (Mini), 31) 60 No.7 no Bashbari, 32) 117 No.4 No Bashbari, 33) 243 No.Bashbari Pubpara, 34) 116 No.3 No bashbari, 35) 242 No.Bashbari Pachim, 36) 58 No.Bashbari-II, 37) 241 No 2 Bashbari Uttar, 38) 168 No.2 No Bashbari Uttar, 39) 248 No.Salabila Hazi Para, 40) 172 No.Bashbari-1, 41) 61 No. Aolaguri, 42) 167 No. Salabila-1 Pachim Para, 43) 62 No. Salabila, 44) 246 No. Salabila Pachim, 45) 57 No.Bashbari-1, 46) 169 No.Bashbari-1 Madhya Para, 47) 63 No.Salabila-3, 48) 247 No.Salabila Sibir-c, 49) 249 No.3 no Salabila Pub, 50) 170 No.Salabila Sibir (B), 51) 171 No.Salabila Sibir (A), 52) 250 No.Salabila Charpara, 53) 76 No.Adlaguri, 54) 240 No.Adlaguri Pachim Para, 55) 134 No.Adlaguri Purani Para, 56) 78 No.Jhawbari, 57) 82 No.Shoulmari, 58) 239 No.Nowagaon Dakhin, 59) 77 No.Nowagaon Dakhin, 60)136 No.Pub Nowagaon, 61) 137 No.Uttar Nowagaon, 62) 135 No.Abadi Dakshin, 63) 80 No.Abadi, 64) 42 No.1 No Bhandara, 65) 162 No.Kumargaon, 66) 163 No.Bhandara Gempara, 67) 39 No.3 No Bhandara, 68) 40 No.5 no Bhandara, 69) 109 No.6 No Bhandara, 70) 108 No.4 No. Bhandara, 71) 38 No.2 No Bhandara, 72) 165 Bongaigao No.Bhandara Charpara, 73) 164 No.Bhandara reserve Para, 74) 41 No.3 No Jamdaha, 75) 110 No.4 No Jamdaha, 76) 111 No.6 No Jamdaha, 77) 94 No.Moutara, 78) 258 No. Gerukabari Raybasti, 79) 178 No.Goraimari Bhatipara, 80) 127 No.Janakalyan, 81) 175 No.Panchayat Para, 82) 14 No.Dawkijhar, 83) 177 No.Dawkijhar Barman Para, 84) 97 No. Hapachara, 85) 191 No. hapachara Pub, 86) 193 No. Garugaon pub (Mini), 87) 188 No.Garugaon sibir-1, 88) 194 No.Garugaon Sibir-A, 89) 195 No.Garugaon Sibir-B, 90) 186 No.kurshakata, 91) 100 No.Nachanguri-3, 92) 125 No.Jaraguri-2, 93) 184 No.Jaraguri Uttar, 94) 185 No.Jaraguri Pub, 95) 124 No.Jaraguri-3, 96) 187 No.Dakhin Para, 97) 256 No.Bridhabashi (Mini), 98) 99 No.Bridhyabashi, 99) 189 No.Chakrasila, 100) 103 No.Garugaon-1, 101) 98 No.Garugaon, 102) 190 No.Barman para, 103) 192 No.Dankinamari Pub, 104) 102 No.Dankinamari, 105) 101 No.Dawkijhar-2, 106) 174 No.Dawkijhar uttar Pachim, 107) 10 No.Chauraguri, 108) 176 No.Pathalipara, 109) 259 No.Dakhin Para (Mini) As per report received from Dist Social welfare office, Bongaigaon date-21.06.2022, Fisheries/Pond | Total 3 Nos pond. 1) 1 No Salabila- 2 Nos, 2) 2 No Salabila-1 No. as per report received from DFDO, Bongaigain date-21.06.2022, Boitamari - Anganwadi Centres Affected | 1)148 No Moligaon Kochpara, 2)15 No Moligaon Rabhapara, 3)147 No Barkhata Nayapara,4) 234 Ikrabari Pub 5)183 No Barkhata Chomerighuli, 6) 7 No Majpara Bhatipara Tilapara, 7) 22 No Salbari, 8) 175 No Salbari Nathpara, 9) 24 No Talguri, 10) 27 No Kayethpara Pt II, 11) 28 No Kayethpara Pt III, 12) 26 No Kayethpara Pt I, 13) 144 No Kayethpara Pt IV, 14) 179 No Kayethpara Barili Mandir, 15) 177 Balirchar Paschim, 16) 178 No Palashbari, 17) 25 No Dhaknabari, 19) 40 No Dhaknabari Adarshagaon, 20) 143 No Dhaknabari Ujazpara, 21) 173 No Rabhapara, 22) 174 No Ghonapara, 22) 41 No

Beparipara, 23) 32 No Dhalakhata, 24) 146 No Panchagaon Mainaguri, 25) 63 No Silmaguri, 26) 237 No Nayagaon Muslimpara, 27) 30 No Falimari, 28) 81 No Goraimari 29) 206 No Colonypara, 30) 210 No Haripani, 31) 77 No Chalantapara Pt V, 32) 207 No Mowamari, 33) 114 No Kabaitary Pt I, 34) 228 No Pubpara Chuburi, 35) 230 No Bayetipara, 36) 115 No Kabaitary Pt II, 37) 116 No Kabaitary Pt III, 38) 160 No Ghonapara, 39) 229 No Burirchar, 40)113 No Kabaitary, 41) 31 No Namapara, 42) 232 No hanifortila, 43) 117 No Kabaitary Pt IV, 44)161 No Kabaitary Pt VII, 45)122 No Bharalkundi Pt II, 46)93 No Bhutkura Pt I, 47) 92 No Bhutkura, 48) 94 No Bhutkura Pt II, 49) 96 No Iswarjhari, 50) 97 No Iswarjhari NC, 51) 98 No Iswarjhari Pt I, 52) 99 No Iswarjhari PtII, 53) 219 No Hokodoba NC, 54) 140 No Birching Holongarchar, 55) 199 Hokodoba Paschim, 56) 95 Bhutkura Pt III, 57) 34 Hokodoba Pt I as per report received from Dist. Social Welfare Officer, Bongaigaon date-20.06.2022,

Elementary Schools Damaged | 1) 704 No. Purani Majer Alga L.P. School as per report received from DEEO, Bongaigaon date-21.06.2022,

Fisheries/Pond | Total 3 Nos of pond. 1) Borkhata- 3 Nos, Srijangram - Anganwadi Centres Affected | 1) 117No. Kacharipety Pt-III South, 2) 118No. Kacharipety Pt-III North, 3) 119No. Kacharipety Pt-II, 4) 120No. 2No. Holdibari S, 5) 153No. Nararvita Pt-I North, 6) 168No. Baregarh (S), 7) 79No. Madrassapara Jopea AWC, 8) 100No. Golapara Pt-I, 9) 101No. Gonabinna North, 10) $102 No.\ Banglapara, 11)\ 103 No.\ Golapara\ (SC),\ 12)\ 104 No.\ Golapara\ Pt-III,\ 13)\ 142 No.\ Golapara\ Pt-IV\ uttar$ pub, 14) 143No. Pub Char Gonabinna, 15) 144No. Gonabinna Golapara Pt-IV, 16) 145No. Golapara Pt-III East, 17) 146No. Pachim Golapara Pt-II, 18) 232No. Soulmari North and Charpara Pt-II, 19) 242No. North Boraichala, 20) 243No. Harirchar Pt-II, 21) 244No. Harirchar Pt-I Bogulamari, 22) 245No. Madrassapara AWC, 23) 246No. Madrassapara (A) AWC, 24) 248No. Golapara Pt-III Uttar Pub AWC, 25) 249No. Golapara Pt-I East AWC, 26) 250No. Golapara Pt-I East (A), 27) 32No. 5No. & 6No. Char, 28) 39No. Barjana Pt-I, 29) 40No. Barjana Pt-II, 30) 41No. Choto Barjana, 31) 42No. Arimara, 32) 43No. Barjana Pt-III, 33) 61No. Nararvita Pt-II AWC, 34) 62No. Nararvita - III AWC, 35) 63No. Rangapani AWC, 36) 65No. Simlabari AWC, 37) 125No. Piradhara South AWC, 38) 128No. Piradhara - I AWC, 39) 82No. Kokila Pt-I, 40) 83No. Kokila Moulabipara, 41) 84No. Kokila Nayapara, 42) 85No. Kokila Majpara, 43) 86No. Kokila Majerchar, 44) 87No. Kokila Bazar, 45) 105No. Numberpara Pt-III, 46) 106No. Numberpara Pt-II, 47) 107No. Numberpara Pt-I, 48) 108No. Chakla Pt-I, 49) 109No. Chakla Pt-II, 50) 110No. Chakla Pt-III, 51) 156 no Pokaloga South, 52) 157No. Soulmari, 53) 159No. Kokila Majpara North, 54) 182 No Kokila Bhuyanpara AWC, 55) 229 No Kokila Madhyapara Majpara South, 56) 230No. Kokila Ghonapara AWC, 57) 231No. Kokila Ghonapara A AWC, 58) 233 No Npt II South North Nodipar & Charpara, 59) 48 Ambari Baregarh, 60) 169 Ambari Batenpara, 61) 92 Santoshpur Pt- II, 62) 123 Tapattary East, 63) 132 Dumuria Pt-II, 64) 137 Bhadaipara & Dumuria Pt-I, 65) 139 Parerchar Pt-III, 66) 76 Na-Satra- East, 67) 77No. Baraichala Bhuyapara AWC ,68) 78No. Kalikura Pt-I & Mulbari, 69) 80 NO Harirchar Bogulamari, 70) 81No. Kalikura Pt-II AWC, 71) 94No. Balarchar North AWC, 72) 95No. Balarchor South AWC, 73) 96No. Matraghola East AWC, 74) 97No. Matraghola West AWC, 75) 98No. Purba Jopea AWC, 76) 99No. Balarchar Pub AWC, 77) 154No. Jopea Bhuyapara AWC, 78) 155No. Mulbari AWC, 79) 161No. 3 No Balachar AWC, 80) 183No. Matraghola Middle AWC, 81) 234No. Matrghola South AWC, 82) 235No. Materghola South AWC. 83) 236No. Matraghola Pub & Uttar AWC, 84) 237No. Balarchor AWC, 85) 238No. Balarchor Uttar A AWC, 86) 239No. Balarchor & 2 no Balarchor AWC, 87) 247No. Baraichala Uttar AWC, 88) 56No. Kahibari Balarpet, 89) 111No. Tilpukhuri, 90) 148No. 1 No. Haldibari, 91) 166No. Balerpet North, 92) 210No. 1 & 2 No. Kahibari, 93) 211No. 1 & 2 No. Kahibari (A), 94) 212No. Tentorpur Balarpet South, 95) 221No. Deotary West (A), 96) 223No.Kirtanpara Sajalpara Char(A), 97) 163 Chechapani Balajani, 98) 68No. Kushbari Pt-II & I, 99) 69No. Mererchar Dubachuri, 100) 70No. Dubachuri Pt-II, 101) 71No. Bharalipara SC, 102) 126No. Lotibari, 103) 1 No Parerchar, 104) 2 No Parerchar Gaon, 105) 3 No Pahatoli, 106) 6 No Bamungaon Zila Karagar. 107) 7 No Bamungaon Pt-II, 108) 84 No Parerchar ME School, 109) 9 No Khudra Narikola (mini), 110) 11 No Pahartoli (mini), 111) 41 No Bowalimari, 112) 45 No Nuldoba Neheru Club, 113) 46 No Haripur East, 114) 47 No Haripur SC, 115) 55 No Amguri SC Gaon, 116) 96 No Amguri Pt-I,117) 97 No Mowamari Hirarvita, 118) 105 No Ganesh Mandir, 119) 127 No Bowalimari Hirapara, 120) 128 No Duramari Kothalguri, 121) 129 No Amguri Pt-I (Janarpara), 122) 19 No Kawalipara (mini), 123) 20 Patirghola (mini), 124) 21 No Pachim Amguri (mini), 125) 24 No Latibari Pt-I, 126) 25 No Latibari Pt-I, 127) 26 No Natun Piradhara, 128) 28 No Uttar Tapattary, 129) 29 No Dakhin Tapattary, 130) 30 No Piradhara GP, 131) 31 No Bahulapara LP School, 132) 130 No Latibari Pachim, 133) 131 No Pub Para Latibari, 134) 132 No Piradhara North (Khalpara), 135) 133 No Latibari Pt-I, 136) 2 No Golapara (mini), 137) 3 No New Piradhara Colony(Min), 138) 33 No Uttar Bharilipara, 139) 34 No Dakhin Bharilipara, 140) 35 No Pachim Bharalipara, 141) 5 No Baghekhati Chor (Mini), 142) 17 No Malegarh Part-I, 143) 18 No 5 No Char, 144) 19 No Tinkonia Pt II, 145) 19 No Tinkonia Pt II, 146) 20 No Uttar Gobindapur, 147) 21 No Dakhin Gobindapur, 148) 101 No 6 No Char, 149) 102 No Kalibari Tinkonia, 150) 103 No Melegarh Bhatipara, 151) 104 No Malegarh Sadhupara, 152) 106 No Malegrah Namani, 153) 119 No Malegrah Pt-II, 154) 120 No Kandhipar, 155) 121 No 6 No Bahir Char, 156) 85 No Mohanpur, 157) 86 No Mohanpur Muslimpara, 158) 87 No Kabaitary Part-II, 159) 90 No Bhokuwamari, 160) 93 No Besimari, 161) 13 No Pub Kunjani Beel (Mini), 162) 14 No Namapara (Mini), 163) 15 No Uttar Khoragaon (Mini), 164) 16 No Kharagaon Hazipara (mini), 165) 9 No Piradhara LP School, 166) 52 No Batabari SC, 167) 7 No Lachit Nagar (Mini), 168) 73 No Rajaipani Khuwa Beel, 169) 74 No Jharpara LP School, 170) 75 No Jharpara Pt-II, 171) 76 No Lengtisinga Bazar, 172) 77 No Lengtisinga Kali Mandir, 182) 78 No Dalanbhanga, 183) 79 Janermukh, 184) 80 No Dalan Bhanga LP School, 185) 81 No Bhadaipara, 186) 82 No Dumuria, 187) 83 No Janata Bazar, 188) 37 No Simlabari Pt-II, 189) 38 No Nararvita Pt-II, 190) 39 No Ghoramara, 191) 108 No Simlabari Pt-I Weast, 192) 109 No Simlabari Pt-I Pub, 193) 110 No Simlabari Dholaghasa, 194) 62 No Dumerguri Pt-II East, 196) 63 No Dumerguri Pt-II, 197) 64 No Sontoshpur Pt-II North, 198) 65 No Dakhin Santoshpur, 199) 66 No Dumerguri Pt-III, 200) 67 No Sontoshpur Mazipara, 201) 68 No Dumerguri SC, 202) 69 No Dumerguri River Colony, 203) 70 No Dumerguri Mazumdarpara, 204) 71 No

Dumerguri Uttarpara, 205) 72 No Dumerguri Dakhinpara, 206) 13 No Mererchar, 207) 14 No Paltan Bazar, 208) 111 No Kushbari Pt-II, 209) 124 No Dubachuri Dangipara, 210) 125 No Marerchar Puranapara, 211) 57 No Uttar Modhuphal Gaon, 212) 60 No Arimara as per report received Dist. Social Welfae, Bongaigaon date-21.06.2022, Elementary Schools Damaged | Dakhin Boraichala L.P School as per report received from DEEO, Bongaigaon 21.06.2022, Fisheries/Pond | Total 12 Nos pond. 1) Shimalabari Pt.I- 3 Nos, 2)Simlabari- 2 nos, 3) Balarpet- 2nos, 4)Kokila-4 Nos, 5) Tilpukhuri- 1 No.as per report received from DFDO, Bongaigaon date- 21.06.2022 Bijni - Bridge Approach Road Damaged | As reported by PWD, Bijni (R&B) Sub Division, Bridge approach damaged at Br. No. 7/2 of Borobazar Bhabanipur road at 7th KM. Length=15 mtr, Breadth=5.00 mtr, Depth=4.50 mtr. Longitude=90.616294 Latitude=26.590612. Date of Occurrence=16-06-2022., Culvert Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, 1000mm dia double HP Culvert approach eroded at 14th KM (Ch.13400.00 m)/at Ballimari Mofiya Bazar of Patiladoha Panbari Road. Length=20.00 mtr, Breadth=3.500 mtr, Depth=2.00 mtr. Longitude=90.827763 Latitude=26.579051. Date of occurrence=17-06-2022., Culvert Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, RCC Box Culvert approach eroded and RCC Box Culvert (Size 3.00 m x 3.00 m, 1-cell opening) damaged at 14th KM(Ch.13600.00m)/ at Ballimari of Patiladoha Panbari Road. Length=8.00 mtr, Breadth=2.00 mtr, Depth=3.00 mtr. Longitude=90.828954 Latitude=26.579413. Date of occurrence=17-06-2022, Bridge Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, Bridge approach damaged at Br No 1/1 at 1st KM of Bijni Batabari Mongolian road to Pachalabari road. Length=5.00 mtr, Breadth=5.00 mtr, Depth=3.00 mtr. Longitude=90.636665 Latitude=26.555102. Date of occurrence=18-06-2022, Culvert Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, Culvert approach eroded(Box culvert size, 2.00 mx2.00m single cell) at 1st km of Oxiguri Daranga road to Rowmari road. Length=2.00 mtr, Breadth=1.00mtr, Depth=2.00 mtr. Longitude=90.694187, Latitude=26.618177. Date of occurrence=18-06-2022, Culvert Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, Culvert approach eroded (Box culvert size 2.00mx2.00m, single cell) at 1st KM of Oxiguri Daranga road to Rowmari Road. Length=2.00 mtr, Breadth=2.00mtr, Depth=2.00mtr. Longitude=90.694119 Latitude=26.618088. Date of occurrence=18-06-2022, Culvert Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, Culvert approach eroded (Sab culvert size, 10.00 m span) at 2nd KM of Oxiguri Daranga road. Length=3.00mtr, Breadth=2.50 mtr, Depth=2.00 mtr. Longitude=90.6795532 Latitude=26.607241. Date of occurrence=18-06-2022, Culvert Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, Culvert approach eroded (Box culvert sixe, 3.00 mx 3.00m, single cell) at 3rd KM of Oxiguri Daranga road. Length=3.00mtr, Chirang Breadth=2.00 mtr, Depth=3.00 mtr. Longitude=90.683.383 Latitude=26.607086. Date of occurrence=18-06-2022. Bridge Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, Bridge approach eroded at RCC Bridge No 1/1 at 1st KM of Mongolian Bazar to Kathalguri road on 18-06-2022. Length=25 mtr, Breadth=3 mtr, Depth= 3.50 mtr. Longitude=90.628899 Latitude=26.541274, Culvert Approach Road Damaged | As reported by PWD, Bijni(R&B) Sub Division, approach eroded at slab culvert No 3/1 (Slab culvert size 4.00 m span) at 3rd KM at Thandabil bridge), Length=4.00 mtr, Breadth= 5.00 mtr. Depth= 3.00 mtr. Longitude=90.844018 Latitude=26.594863. Date of occurrence=18-06-2022... Bamboo Foot Bridge | As reported by PWD, Bijni(R&B) Sub Division, bamboo foot bridge washed away at Dwiswm Dong of Damrang Bazar to Choto Amguri road. Length=25 mtr, Breadth=3.00 mtr. Longitude=90.616355 Latitude=26.616829. Date of occurrence=18-06-2022... Bengtal - Agri Bundh Damaged | As repoted by BDO, Sidli Chirang Dev. Block Mathauri Bundh damaged at village Basbari (Thaikajora VCDC) on 16/06/2022, L-126.99m B-4m D-2.12m, Lat-26.239133 Long-90.402397, Irrigation Canal/Scheme Damaged | As repoted by BDO, Sidli Chirang Dev. Block Irrigation canal cum Mathaori road damaged at village M Dakhingaon (Thaikajora VCDC) on 16/06/2022, L- 136.3m B- 4.25m D-1.43m, Lat- 26.642085 Long- 90.402052, Irrigation Canal/Scheme Damaged | As repoted by BDO, Sidli Chirang Dev. Block Irrigation canal mathaori damaged at village Darogaon (Ashrabari VCDC) on 15/06/2022, L- 20m B- 1.6m D- 0.75m, Lat- 26.620399 Long-90.396213, Bamboo Foot Bridge | As reported by BDO, Sidli Chirang Dev. Block, Bamboo bridge damaged at village No.2 Aiepowali (Tukrajhar VCDC) on 16/06/2022, L-13m B-2.23m D-3m Lat- 26.678232 Long- 90.4845, Irrigation Canal/Scheme Damaged | As repoted by BDO, Sidli Chirang Dev. Block, Irrigation canal damaged at village Palashguri (Ouguri VCDC) on 16/06/2022, L- 5.64m B- 4.31m D- 2.89m, Lat- 26.636477 Long-90.523657, Agri Bundh Damaged | As repoted by BDO, Sidli Chirang Dev. Block, Aie chara mathaori bund damaged at village Digoldong (Ouguri VCDC) on 16/06/2022, L- 7.16m B- 2.86m D- 3.54m Lat- 26.9242 Long- 90.499601 Dalgaon - Elementary Schools Damaged | Rangagara Chapari Lps is badly damaged in the erosion of the Dhansiri river dated 21.06.2022, Sipajhar - Fisheries/Pond | Total no. of farmers affected 570 & Total water area affected 43 Hectare-dated Darrang 21/06/2022, Power Dept. Poles | APDCL poles damaged 11 nos. -dated 21/06/2022, Power Dept. Conductors | Conductors : 9 KM appx damaged - dated 21/06/2011, Patharighat - PWSS Damaged | Dipila PWSS distribution piped line damaged due to flood as reported by JE

1		DHE on 21.6 2022
		PHE on 21-6-2022 Chabua - Elementary Schools Damaged DODHIA ME SCHOOL SUBMERGED AS PER INFORMATION
		RECEIVED FROM EDUCATION DEPT. ON 21/6/2022 N27 36.390 E95 13.651,
		Elementary Schools Damaged DODHIA KULIGAON LPS SUBMERGED AS PER INFORMATION
		RECEIVED FROM EDUCATION DEPT. ON 21/6/2022 N27 35.845 E95 13.227,
		Elementary Schools Damaged DODHIA KARMI LPS SUBMERGED AS PER INFORMATION RECEIVED
		FROM EDUCATION DEPT. ON 21/6/2022 N 27 36.032 E95 14.787,
		Elementary Schools Damaged DODHIA TENGABARI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 21/6/2022 N27 36.652 E95 14.237,
		Elementary Schools Damaged DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION
		RECEIVED FROM EDUCATION DEPT ON 17/6/2022 N27 36.462 E95 14.673,
		Anganwadi Centres Affected DODHIA KULIGAON AWC SUBMERGED AS PER INFORMATION
		RECEIVED FROM SOCIAL WELFARE DEPT. ON 21/6/2022 N27 35.845 E 95 13.227,
		Anganwadi Centres Affected DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION
		RECEIVED FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27 36.652 E95 14.237, Anganwadi Centres Affected DODHIA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM
		SOCIAL WELFARE DEPT ON 21/6/2022 N27 36.390 E95 13.651,
		Anganwadi Centres Affected UPPER GEREKI AWC SUBMERGED AS PER INFORMATION RECEIVED
		FROM SOCIAL WELFARE DEPT. ON 21/6/2022 N27 33.942 E95 15.125,
	Dibrugarh	Anganwadi Centres Affected DODHIA CHALBIL AWC SUBMERGED AS PER INFORMATION
	Dioragam	RECEIVED FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27. 5714 E95. 2346,
		Anganwadi Centres Affected RONGMOLA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27 33'33.40" E95 11'47.26",
		Anganwadi Centres Affected 1 NO. MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED
		FROM SOCIAL WELFARE DEPT ON 21/6/2022 N2733'48. 87" E13'18. 49",
		Anganwadi Centres Affected 2 NO. MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED
		FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27 33' 50.38" E95 13' 16.90",
		Anganwadi Centres Affected MULUKGHAT MIRIGAON AWC SUBMERGED AS PER INFORMATION
		RECEIVED FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27 33'52.36" E95 13'15.74", Anganwadi Centres Affected TENGABARI-MIRIGAON AWC SUBMERGED AS PER INFORMATION
		RECEIVED FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27 33'52.88" E95 13' 14.42",
		Anganwadi Centres Affected GEREKI NEPALI AWC SUBMERGED AS PER INFORMATION RECEIVED
		FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27 33'50.76" E95 15'26.01",
		Anganwadi Centres Affected KULIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 21/62/22 N27 35.860 E95 13.460,
		Anganwadi Centres Affected DODHIA ROMAI AWC SUBMERGED AS PER INFORMATION RECEIVED
		FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27 36.450 E95 13.782,
		Anganwadi Centres Affected CHALBIL AISUNG CHAPORI AWC SUBMERGED AS PER INFORMATION
		RECEIVED FROM SOCIAL WELFARE DEPT ON 21/6/2022 N27 34.890 E95 13.563
		Haflong - Road Breaches Damage of Mupa Naiding village Approach Road due to erosion as per info received from PWRD, Maibang Division dated 21/06/2022,
		Road Breaches Damage of Langting - Mailu Road due to landslide as per info received from PWRD, Maibang
	Dima-	Division dated 21/06/2022,
	Hasao	Road Breaches Damage of Gunjung - Maibang Road due to landslide as per info received from PWRD,
		Maibang Division dated 21/06/2022, Elementary Schools Damaged Damage of School premises of Boro Haflong LPS due to landslide as per report
		received from the School Head Teacher dated 21/06/2022
		Bokakhat - Elementary Schools Damaged Jugonia Deodia LPS,Gutung MES,No2. Borbali Lohore Garumora
		LPS,Bhulukaguri bamunchapori LPS,Majdolopa LPS,Kathonibari LPS,Misamari Chapori LPS,Siyal Suburi
	Golaghat	LPS, Kemeri LPS, Alengmari Chuburi LPS, Tazang Kutum LPS, Dhansiri Hanchora LPS, 1 No. Riri LPS, 2 No.
		Riri LPS,Pub Dhansiri LPS,Nikori Sambhuram miri mes,baraikhuwa chapori lps,boraikhuwa baligaon lps, baligaon lps,Gutung MES,Bhalukaguri Bamun Chapori LPS got patially damaged on 19.06.2022
		Hojai - Irrigation Canal/Scheme Damaged Dated 20/06/2022 Canal D3 submerged under water as reported
		Assistant Executive Engineer, Hojai Division Irrigation at village Gopal Nagar with GPS Coordinates 26.020 N
		andd 92.8723 E,
		Elementary Schools Damaged ASHINAGAR 18300301202 SIDESWARPUR SARALA LPS Sub Merged
		17/06/DAKHIN ASHINAGAR BALIKA LPS2022, Elementary Schools Damaged ASHINAGAR 18300301001 DAKHIN ASHINAGAR BALIKA LPS
	Hojai	submerged on dated 17/06/2022,
		Elementary Schools Damaged ASHINAGAR 18300301301 ASHINAGAR MEM submerged on dated
		17/06/2022,
		Elementary Schools Damaged BARAFUTI 18300301601 PASHIM JUGIJAN ADARSHA LPS submerged on
		dated 17/06/2022, Elementary Schools Damaged BARAFUTI 18300301401 BALIRAM PATHAR LPS submerged on dated
		17/06/2022,
		Elementary Schools Damaged BARAFUTI 18300301501 BARAFUTI LPS submerged on dated 17/06/2022,
		Elementary Schools Damaged BARAFUTI 18300301502 JOGIRPAR LPS submerged on dated 17/06/2022,
		Elementary Schools Damaged BARAFUTI 18300301602 PASHIM JUGIJAN BENGALI LPS on dated 17/06/2022,
		1770012022,

Elementary Schools Damaged | BARAFUTI 18300301801 PUB JAUGIJAN NEHARU LPS submerged on dated 17th june, 22, Elementary Schools Damaged | BARAFUTI 18300301802 PUB JUGIJAN LPS submerged on dated 17/06/2022, Elementary Schools Damaged | BARAFUTI 18300308001 KANDHULIMARI LPS submerged on dated 17/06/2022. Elementary Schools Damaged | BARAFUTI 18300317702 FAKALIGAON LPS submerged on dated 17/06/2022, Elementary Schools Damaged | BARPUKHURI 18300301903 BISWARPARA NEW LPS submerged on dated 17/06/2022, Elementary Schools Damaged | BHIMARALI 18300303501 LANKAJAN JAMUNAASIT LPS submerged on dated 17/06/2022, Elementary Schools Damaged | BHIMARALI 18300303502 KAPILIPAR NATUN BAZAR MKB submerged on dated 17/06/2022, Elementary Schools Damaged | BHIMARALI 18300303505 NEHRU AZAD AD. LP submerged on dated 16/06/2022. Secondary Schools Damaged | BHIMARALI 18300303506 JAMUNASIT PRE SR MADRASSA submerged on dated 17/06/2022, Elementary Schools Damaged | HAYONG 18300305203 SOLMARI ADARSHA ME submerged on dated 17/06/2022, Elementary Schools Damaged | warregeding 18300305401 Warregeding ME School submerged on dated 17/06/2022. Elementary Schools Damaged | Hayong 18300315901 HAYANG GAON LP submerged on dated 17/06/2022, Elementary Schools Damaged | Kandulimari 18300308002 DOBOKA NALA LPS submerged on dated 17/06/2022. Doboka - PWSS Damaged | Village Erakapili, Latitide 26.054000° & Longitute 92.444400° on dated 20/06/2022, Elementary Schools Damaged | BHELOWGURI PATHER MADYAM KHANDA L.P & BHELOWGURI PATHAR LPS under Bhelowguri Cluster on dated 17/06/2022, Elementary Schools Damaged | CHANG MAJI MIKIR PAR NEW LPS & SRI SRI SANKARDEV CHANGMAJI LP under Changmaji Cluster on dated 17/06/2022, Elementary Schools Damaged | 1) 337 NO. JUNGLE BLOCK LPS, 2) 1003 NO. MAJORKANDI LPS, 3) UTTAR JUNGLE BLOCK LPS, 4) JUNGLE BLOCK HS, 5) PATI DAIYA LPS, 6) CHARLOCK ADARSHA LPS, 7) BINNAKANDI MES, 8) 554 NO. JUGIJAN LPS, 9) JUGIJAN GAON NEW LPS, 10) BORJAN LPS, 11) BINNAKANDI LPS,12) BANGAON LPS under Charlock Cluster on dated 17/06/2022, Elementary Schools Damaged | 1) JANATA LPS, 2) RABINDRA VIDYAMANDIR HS, 3) AMIR UDDIN MAQTAB S, 4) JAMINI DEVI MVS, 5) JAMUNAMUKH HSS, 6) KATHKATIA LAHARI LP, 7) 430 NO.BALIRAM GAON LPS, 8) BISHNUNAGAR LPS & 9) KALIBARI LP under Jamunamukh Cluster on dated 17/06/2022, Elementary Schools Damaged | 1) ELASI DEWRI LPS, 2) PUB GARALI ANUSUCHITA JATI LP, 3) 274 NO. GARALI LP, 4) PUB B.H.A.W CHOWDHURY L.P, 5) PUB GARALI ANUSUCHITA JATI ME, 6) KANDHULIMARI MEM, 7) KANDHULIMARI LP, 8) NAGAYANPAM LPS, 9) PATIA PATHAR LPS, 10) DEKERUA LPS & 11) VERVERI LPS under Nagayapam Cluster on dated 17/06/2022, Elementary Schools Damaged | 1) PASHIM BEDUATI BALIKA LPS, 2) BEDUATI LPS, 3) 933 NO. MORAGANG LPS & 4) CHALIHA LP under Nikharimukh Cluster on dated 17/06/2022, PWSS Damaged | Gopinath coloney Pwss Submerged on 21-06-2022 Patherkandi - Power Dept, Poles | 09 nos, of electric pole has broken due to soil erosion and flood water at Khasia Punjee, Churaibari on 18/06/2022 as reported by SDE, APDCL, Lowairpoa Sub-Division, Power Dept. Transformers | Flood water caused damaged to a transformer at village- Defolala on 19/06/22, Karimganj coordinates are lat-24.614647,long-92.283506, as reported by SDE, APDCL, Patharkandi. RK Nagar - Fisheries/Pond | Under 56 revenue village 1100 fisharies measuring area 195.90 hector was damaged as reported by SDO Fishary Debolopment officer, Karimganj on date 21/06/2022 Gossaigaon - Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 IMMEDIATE RESTORATION ON RAIMONA TO DUMBAJHAR ROAD HP CULVERT NO. 1/1 DAMAGED022 DUE TO HEAVY RAIN. Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON GHAKSA TO SANKOSH RIVER HP CULVERT NO. 1/2 DAMAGED, Bhawraguri - Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 20-06-2022 IMMEDIATE RESTORATION OF MOYAMARI TO LUCHUTBIL ROAD CULVERT NO 1/1,1/2,1/3 & HARD CRUST Kokrajhar DAMAGED., Road Breaches | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 20-06-2022 IMMEDIATE RESTORATION OF BORAGARI TO NARENGURI VIA KOLABARI ROAD FORMATION BREACHED AT 2ND KM BY 30.00 M LENGTH, Bridge Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 20-06-2022 IMMEDIATE RESTORATION OF SALBARI TO BASIRCHOR VILLAGE ROAD WOODEN BRIDGE APPROACH EROSION & DAMAGED.,

Damaged SPT Bridge | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 20-06-2022 IMMEDIATE RESTORATION OF BORAGARI TO NARENGURI VIA KOLABARI ROAD WOODEN BR. NO.2/1 DAMAGED., Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 17-06-2022 HP CULVERT 1/1 & 1/3 HAVE BEEN DAMAGED NH 31 (C) TO PERIPUR VILLAGE ROAD, Washed away Culverts | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 CULVERT NO 2/1 HAS BEEN DAMAGED ON SAMAIJHORA TO SATYAPUR TULSHIBIL ROAD VIA KACHUA VILLAGE ROAD, Damaged RCC Bridge | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 BRIDGE NO 2/1 HAS BEEN DAMAGED ON SAMAIJHORA TO SATYAPUR TULSHIBIL ROAD VIA KACHUA VILLAGE ROAD, Damaged RCC Bridge | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 BRIDGE NO 1/1 HAS BEEN DAMAGED ON BHUMKA NO I BAZAR TO BHUMKA VILLAGE ROAD., Damaged RCC Bridge | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 BRIDGE NO 1/1 HAS BEEN DAMAGED ON BHUMKA NO I BAZAR TO BHUMKA NO 2 ROAD., Washed away Culverts | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 HP CULVERT NO 1/6 HAS BEEN DAMAGED ON BHOWRAGURI TO KACHUA CHARIALI VIA MOKRAMBIL ROAD, Bridge Approach Road Damaged | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 BRIDGE NO 1/1 BOTH SIDE APPROACHES HAS BEEN DAMAGED ON BALAPARA PT II DUDUMARI VILLAGE, Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 CULVERT NO 1/1 WITH ROAD SURFACE HAS BEEN DAMAGED ON BALAPARA PT I TO BORAIBARI VILLAGE ROAD, Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, GOSSAIGAON DUE TO FLOOD AND INCESSANT RAINFALL TILL 18-06-2022 APPROACHES CULVERT NO 1/1 HAS BEEN DAMAGED ON BALAPARA PT I TO BALAPARA PT II MARKET, Dotma - Culvert Approach Road Damaged | AS REPORED BY DOTMA REVENUE CIRCLE Damage of culvert by Flood at East Saragaon village ON 21.06.2022., Culvert Approach Road Damaged | AS REPORED BY DOTMA REVENUE CIRCLE Damage of Culvert by Flood at Angthihara by Rangaichara River ON 21.06.2022, Bagribari - Washed away SPT Bridge | As reported by AEE PWD RR on 20/6/22, foot bridge has been washout on Bhalukjhora PWD Road to Tumbagan Road, Culvert Approach Road Damaged | As reported by AEE PWD RR on 20/6/22, HP Culvert approach has been damaged on Lalmati to Tumbagan Road, Washed away SPT Bridge | As reported by AEE PWD RR on 20/6/22, foot bridge has been washout on Pastibari to Futanipara Road, Culvert Approach Road Damaged | As reported by AEE PWD RR on 20/6/22, culvert has been damaged on Khoraghat to Jalabila Road at Ch.2000M, Culvert Approach Road Damaged | As reported by AEE PWD RR on 21/6/22, HPC culvert No.2/2 and road of Kazigaon to Bashbari Road has been damaged, Bridge Approach Road Damaged | As reported by AEE PWD RR on 21/6/22, both side approaches of Bridge No..3/1 on Tipkai Tulshijhora Road have been damaged, Bridge Approach Road Damaged | As reported by AEE PWD RR on 21/6/22, both side approaches of Bridge No..2/1 on Tipkai Khangkhraibari Road has been damaged Bihpuria - Protection Bundh Damaged | Approximately 50 meters of the protection bundh at Rangajan-Padmapur area of Uttar Laluk GP has been breached due to the increasing water level of Gabharu river on 20/06/2022 under Karunabari Development Block, Bamboo Foot Bridge | Approximately 12 meters of the bamboo footbridge connecting Thikajan to Pilkhana PWRD has been washed away due to increasing water level of Bogoli river on 20/06/2022 under Karunabari Development Block, Dakhin Laluk GP, lat-27.13859, long-93.914596, Anganwadi Centres Affected | As reported by CDPO, Karunabari ICDS Project on 20/06/2022- Dhekiajuli Christian AWC, Madhya Kutubpur AWC, Ahmedpur Block (A) AWC, Ruhul Chuburi AWC, Barek Para AWC, Lakhimpu Kutubpur B AWC, 4 no. Dharmapur AWC, Dharmapur Block B AWC, Eusuf Chuburi AWC were submerged due to flood ., Bamboo Foot Bridge | NH-15 to Phukuriporia road at Ch.1200.00 m the footbridge Submerged due to flood as reported by AEE, PWRD, Bihpuria TRSD on 21/06/2022. long-93.95424, Lat-27.129777, **Dhakuakhana** - Fisheries/Pond | 1.69 Hectare Ponds/Tanks affected on 20th June, 2022 (10 numbers family)| Report submitted by Fishery Development Officer, Dhakuakhana., Kadam - Damaged RCC Bridge | Due to incessant rain and raising of water level the approaches of RCC BR. NO.1/1 on NH-15 near Padumoni Than to No-2 Katorichapori Road is damaged. dated 20/06/2022, reported by Executive Engineer, PWRD, Dhakuakhana Majuli - Anganwadi Centres Affected | 2 nos of AWC submerged on 20/06/2022. 1. Ujani Jokaibowa AWC 2. Majuli Thanaguri mini AWC Mayong - Fisheries/Pond | Kasari gaon, Gagalmari area Total pond affected -06 as reported by FDO, Mayong on Morigaon 20 06 22,

PWSS Damaged | Boha Ganesh Mandir PWSS Deep Tube well totally submerged as reported by PHED, Morigaon on 21/06/22. lat:26.180. long: 92.131, Morigaon - Fisheries/Pond | (20-06-2022) As per Fishery Dev Officer(Bhurbandha), 15 nos of ponds affected due to flood. Nagaon - Road Breaches | Nagaon Dakhinpat road to Madhupur village ,breached occurred for a length of 10 m at 1st km. reported by nagaon Territorial Road Sub-Division Nagaon dated-21/06/2022, Irrigation Canal/Scheme Damaged | Alengi satra, Kolongpar, Damaged/Submerged, pump house reported by Nagaon Subdivison (irrigation) Nagaon, dated-21/06/2022, Irrigation Canal/Scheme Damaged | Dakarghat Left, Damaged/Submerged, pump house & Command area reported by Nagaon Subdivison (irrigation) Nagaon, dated-21/06/2022, Irrigation Canal/Scheme Damaged | Majulipathar DTWS, 1No. Jalah, Damaged/Submerged, pump house & Command area reported by Nagaon Subdivison (irrigation) Nagaon, dated-21/06/2022, Irrigation Canal/Scheme Damaged | Deudhar DTWS, ranthali rajabheti, Damaged/Submerged, pump house & Command area reported by Nagaon Subdivison (irrigation) Nagaon, dated-21/06/2022, Irrigation Canal/Scheme Damaged | Pub Jalah DTWS, jalah Gaon, Damaged/Submerged, pump house & Command area reported by Nagaon Subdivison (irrigation) Nagaon, dated-21/06/2022, Irrigation Canal/Scheme Damaged | Bebejia to Mohmoria,,Sukutaputa Lumati, Damaged/Submerged, pump house & Command area reported by Nagaon Subdivison (irrigation) Nagaon, dated-21/06/2022, Irrigation Canal/Scheme Damaged | Solar Powered MDtw Scheme at Dakhinpat, Tulshimukh Nagaon Khuchgaon, Damaged/Submerged, pump house & Command area reported by Nagaon Subdivison (irrigation) Nagaon, dated-21/06/2022, Irrigation Canal/Scheme Damaged | TW Points under PMKSY HKKP Phase-1, Damaged/Submerged, Total-930 Points reported by Nagaon Subdivison (irrigation) Nagaon, dated-21/06/2022, Kampur - Power Dept. Poles | Total-29 nos. pole damaged under kampur Rev. Circle Reported by APDCL Kathiatoli Dtd-20.06.2022, Power Dept. Conductors | Total-5 KM conductor damaged under kampur Rev. Circle Reported by APDCL Kathiatoli Dtd-20.06.2022, Power Dept. Transformers | Total-6 nos. DTR damaged under kampur Rev. Circle Reported by APDCL Kathiatoli Dtd-20.06.2022, Public Health Centre (PHC) | Total-20 nos. health center damaged/submerged under Kampur Rev. Circle reported by health department Dtd-20.06.2022, PWSS Damaged | 3 nos. PWSS damaged under Kmapur Rev. Circle Reported by PHE Department, Dtd-PWSS Damaged | Total-331 nos. Filter Unit, Staging with Distribution Line, Centrifugal Pump damaged under kampur rev. Circle Reported by PHE Department, Dtd-20.06.2022 Ghograpar - Fisheries/Pond | As per report received from fishery dept. on 20/06/2022, total 1639 nos. of ponds and Tanks of Fishery are affected, water area 220.03 H, Road Breaches | As per information received from PWRD, on 20/06/2022 NH31 to Khudra Katla Barkuchi (Khudia Rangafali Road breached have seen, Length - 30 M, Handloom & Textile Deptt | As per Handloom & Textile Deptt, on 20/06/2022 18 (Eighteen) numbers of weavers has been affected., Barkhetri - Irrigation Canal/Scheme Damaged | barnibari DTWIS POINT NO1, 2, 3 AT BARNIBARI VILLAGE, MUKALMUA stwis AT MUKALMUA VILL, DAULASAL DTWIS POINT NO1, 2, 4 AT DAULASAL VILL, TEGHERITTARY MDTWIS AT TEGHERITTARY VILL, JAYSAGAR MDTWIS AT JAYSAGAR VILL, SOLAR POWERED MDTWIS 5 POINTS AT MUKALMUA, KALARDIA, CHANDA, BORTOLA, BAKRA PATHAR, BEJPARA PATHAR, DAMDAMA MDTWIS 3 PONTS, HOWEVER DAMAGES MAY BE OVSERVE AFTER RECESSION OF WATER AS REPORTED BY AEE IRRIGATION, BARKHETRI SUB DIV ON 21/06/2022, Handloom & Textile Deptt | 15 NOS WEAVERS HOUSE AFFECTED AT JAYSAGAR, PARTIALDAMAGE OF LOOMS, ACCESESORIES FRAM LOOM, LOOMS FAST, WEAVEN CLOTH AND RUNNING WARP AS REPORTED BY DEMONSTRATOR HANDLOOM AND TEXTILE BARKHETRI ON 21/06/2022, Tihu - Elementary Schools Damaged | 22 NOS LPS SUBMERGED UNDER PUB NALBARI ELEMENTARY Nalbari EDUCATION BLOCK. INFORNMATION RECEIVED FROM BEEO. Dtaed: 17/06/2022, Agri Bundh Damaged | AGRIBANDH DAMAGED AT MAKHIBAHA ,LENGH :4 KM(APROX), INFORMATION RECEIVED FROM BDO, TIHU, DATE: 17/06/2022, Handloom & Textile Deptt | TOATAL SUBMERGED WEAVER: 450 NOS AS PER REPORT DEMONSTRATOR, H& TEXTILE DEPT. Dtaed: 17/06/2022, Health Sub-Centre | SUBMERGED JALKHANA MPHC AS PER REPORT SUBMITTED BY DY SUPERINTENDENT, TIHU FRU, & GB, JALKHANA Dtaed: 17/06/2022, Culvert Approach Road Damaged | 4 NOS OF CULVERT DAMAGED (TIHU-AKHARA LINK ROAD) AS PER REPORT SUBMITTED BY JE, PWD(R), BARAMA .DAMAGED ON 18/06/2022., Barbhag - Elementary Schools Damaged | 24 Nos. of School's fully & Partially Damaged due to flood. The report received from BEEO, Pub. Nalbari on 20/06/2022, Paschim Nalbari - Fisheries/Pond | 1229 nos. of farmer families fisheries with 337.35 Ha area submerged and affected due to flood and heavy rainfall. Information received from Fishery Deptt. on 21/06/2022, Power Dept. Conductors | 55.5 Km conductor damage occurred at village Amoni, Sahpur Nadla, Pokhura, Kathla, Sukekuchi, Lokhopur, Solmara, Dahudi, Badesila, Barhelacha, Barbila and Gamerimuri due to flood. Information received from APDCL Department on 16/06/2022., Power Dept. Poles | 261 nos. of LT and HT Poles were affected by flood at village Amoni, Sahpur Nadla,

		Pokhura, Kathla, Sukekuchi, Lokhopur, Solmara, Dahudi, Badesila, Barhelacha, Barbila and Gamerimuri.
		Information received from APDCL Department on 16/06/2022., Handloom & Textile Deptt 80 nos. weavers family affected. Damage of loom accessories, woven cloths etc.
		Information received from handloom and textile dept. on 21/06/2022
		Thelamara - Washed away Culverts DUE TO TERRITORIAL RAIN IN ARUNACHAL PRADESH AND
	Sonitpur	ASSAMFOR LAST SEVERAL DAYS SURGING WATER OF CANEL HAS BEEN WASHED AWAY OF
		HP CULVERT NO 4/2 ON 18TH JUNE ON BATASIPUR TO ABHOI CENTRE ROAD AT HIJUGURI
		REPOTED BY PWD DHEKIAJULI DTD 21/06/2022,
		Culvert Approach Road Damaged DUE TO TERRITORIAL RAIN IN ARUNACHAL PRADESH AND
		ASSAMFOR LAST SEVERAL DAYS SURGING WATER BELSIRI RIVER HAS BEEN DAMAGED RCC
		BOX CULVERT NO 2/1 WITH APPROACH ON 18TH JUNE ON NH-15 TO THELAMARA ROHINIBIL
		ROAD REPOTED BY PWD DHEKIAJULI DTD 21/06/2022,
		Dhekiajuli - Fisheries/Pond As reported, total of 6.31 ha of fisheries affected at Katalupathar village under
		Dhekiajuli Block. dated 20.6.22
		Udalguri - Washed away Culverts Slab Culvert washed away and road eroded Bhalukmari to Purani Goraibari
		as 26-192 around 10m on 19.06.2022. GPS – Lat-26.733485 Long- 92.115715,
		Washed away Culverts RCC Box Culvert Damaged at No. 5 Majuli to Nalbari road on 19.06.2022. GPS - Lat-
		26.779395 Long- 92.1801,
		Khairabari - Road Breaches Breach occurred on 18.09.2022 at Majgaon Doloipara on Dalangghat Brzbhagati
		road. The road communication is totally disrupted and the road was closed for all types of vehicle. GPS
		Coordinates: Lat- 26.3256 Long: 91.5259, Length: 15 M (approx.),
		Power Dept. Poles As per reported by the department, LT & HT poles were damaged on 18.06.2022 and 19.06.2022, at villages namely Jalukbari, Dakhin Nalbari & Purani Bhergaon, under Khoirabari Revenue Circle.,
	1	Power Dept. Conductors As per reported by the department, LT, HT & 33KV conductors were snapped on
		18.06.2022 and 19.06.2022, due to heavy rainfall and flood at various villages namely Jalukbari, Dakhin Nalbari,
		Purani Bhergaon, Kukurakata, Thakuriapara, Saikiapara, Rangagaon, Umananda, Kuhiarkuchi, Banderigaon,
		Latakhat, Barakhat, Khoirabari, Rangajulikhat & Gopchachuba, under Khoirabari Revenue Circle.,
	Udalguri	Harisinga - Power Dept. Poles LT and HT poles at village Dakhin Nalbari, majuli Basti, Kachubil, Borongajuli,
		dharamjuli Jungle, Suklai, Jalukbari, Chaibari Duinodirmukh, Paneri TE, NC Bhutiachang, Chaotalpara,
		Samrang, , Dimakuchi Kulchi river, damaged on 18 /06/2022 and 19/06/2022. under Tangla electrical sub-
		division,
		Power Dept. Conductors Conductors were snapped at various places like Villages Suklai, Dharamjuli jungle,
		Samrang, Corramore TE, Chaotalpara, NC Bhutiachang, Paneri TE, Duinodirmukh, Dakhin kalikhula, Chaibari,
		Jalukbari, Kulshi river, Dimakuchi, Garuajhar, Kukurakata, Garuajhar, Bengbari, bhollakash, Purandia,
1		
		Jabangahabi, Gopchachuba, dakhin Nalbari, Pujakhola, Mazgaon, Samrang, Hahinigaon kalikhola, Uttar
		Jabangahabi, Gopchachuba, dakhin Nalbari, Pujakhola, Mazgaon, Samrang, Hahinigaon kalikhola, Uttar Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical
		Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division,
		Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to
		Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters
	District	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917)
	District	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details
	District Baksa	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022,
		Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0
		Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues.
	Baksa	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr .erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr.
	Baksa Bongaigao	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr .erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200,
	Baksa	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the
	Baksa Bongaigao	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total
	Baksa Bongaigao	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the
	Baksa Bongaigao	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28
	Baksa Bongaigao	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0,
	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under
Erosion	Baksa Bongaigao	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m .As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-
Erosion	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang , Erosion occurred due to heavy rain at Ulta
Erosion	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx), 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang , Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage
Erosion	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang , Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length- 105.07m, Breadth-3.78m, depth- 3.1m (Long-90.492916, Lat-26.546856). 0
Erosion	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length:: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang, Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length: 105.07m, Breadth-3.78m, depth-3.1m (Long-90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform
Erosion	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date-21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length:: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang, Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details, Length: 105.07m, Breadth-3.78m, depth-3.1m (Long-90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang at village:udmari pt-III, Kajaikata pt-II under
Erosion	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date-21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang, Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length: 105.07m, Breadth-3.78m, depth- 3.1m (Long- 90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang at village:udmari pt-III, Kajaikata pt-II under Bilashpara Revenue Circle. A field visit in this connection
Erosion	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang , Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length- 105.07m, Breadth-3.78m, depth- 3.1m (Long- 90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang at village:udmari pt-III, Kajaikata pt-II under Bilasipara Revenue Circle. A field visit in this connecti
Erosion	Baksa Bongaigao n Chirang	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thunkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang , Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length- 105.07m, Breadth-3.78m, depth- 3.1m (Long- 90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang at village:udmari pt-III, Kajaikata pt-II under Bilasipara Revenue Circle. A field visit in this connecti
Erosion	Baksa Bongaigao n	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang, Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length- 105.07m, Breadth-3.78m, depth- 3.1m (Long- 90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang
Erosion	Baksa Bongaigao n Chirang	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx), 10, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang , Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length - 105.07m, Breadth-3.78m, depth-3.1m (Long-90.492916, Lat-26.54686). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang at village:udmari pt-III, Kajaikata pt-II under Bilasipara Revenue Circle. A field visit in this connection has
Erosion	Baksa Bongaigao n Chirang	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr .erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx), 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang, Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length 105.07m, Breadth-3.78m, depth-3.1m (Long-90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang at village:udmari pt-III, Kajaikata pt-II under Bilasipara Revenue Circle. A field visit in this connection ha
Erosion	Baksa Bongaigao n Chirang	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr. erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx). 0. Sidii - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang, Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur-Bilashpur VCDC on 15-06-2022, damage details , Length- 105.07m, Breadth-3.78m, depth-3.1m (Long- 90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang at village:udmari pt-III, Kajaikata pt-II under Bilasipara Pt-III, Kajaikata pt-II was observed that continuou
Erosion	Baksa Bongaigao n Chirang	Naobandha, Corramor. Nepalikhuti, Bengbari, Hatigarh on 18/06/2022 and 19/06/2022 under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge Temporary bamboo fooy bridge washed away on 21/06/2022 on Bhehugri to Rupatal Bagisha link road due to heavy current from the river Noa. Length of the bridge is around 80 meters (Lot 26.621012 & Long91.0975917) Details Baska - Goldingpara Gully erosion at village Goldingpara, (Ulubari) near Jaycharan Boro house on 18/06/2022, Area eroded: 2 Bighas 0 Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr .erosion continues. date-21.06.2022 Erosion Took Place due to river Aie 39 ft. Date-21.06.2022/Erosion due to Aie River 210 mtr. Date-21.06.2022 2200, Srijangram - Balachar pt II Erosion has taken place at Balarchar Part II on Today the 21th June 2022 on the river bank of river Manas in a length of 300m. As a result, 5 nos. Of families got affected /eroded. Total population affected 28 nos. date- 21.06.2022 28 Bijni - Khujurapguri As reported by Chirang WR Division, Kajalgaon, erosion of khujurapguri DRDA embankment due to river Aie(L/B) on 20-06-2022. Length=750 mtr(Approx), Breadth=6.70 mtr(Approx), Depth=6.70 mtr(Approx), 0, Sidli - Thumkubari, Bilashpur As reported by BDO Sidli Chirang, Land erosion occurred at Thumkubari under Sidli VCDC on 16-06-2022. Damage Details:: Length :: 460M Breadth:3.44M Depth: 3.45 M, (Long-90.457642, Lat-26.531083). As reported by BDO Sidli Chirang, Erosion occurred due to heavy rain at Ulta Kunda Pachim Bilashpur near Malek Omar ali House under Satipur- Bilashpur VCDC on 15-06-2022, damage details , Length 105.07m, Breadth-3.78m, depth-3.1m (Long-90.492916, Lat-26.546856). 0 Bilasipara - udmari pt-III, Kajaikata pt-II With reference to the subject cited above, I have the honour to inform you that, recently erosion has taken place by the river Gaurang at village:udmari pt-III, Kajaikata pt-II under Bilasipara Revenue Circle. A field visit in this connection ha

Dibrugarh		Dibrugarh West - Kachamari and Notun Bolai Village As per report received from Executive Engineer, WR Division on 21.06.2022 that damage for around 300 m at Kachamari village and 300 m (approx) at Natun bolai village has been observed during flood period. Name of the Dyke:- Tengakhat bund on the R/B of river Buridehing from Jokai R.F. to old A.T. road . Chainage:- From ch 7100m to 7450m From ch 8850m to 9150m, Lat. 94.553 Long:-27.191 0		
	Kamrup	Palashbari - Futuri 1No. Spur at Futuri suffered erosion due to river Bramhaputra on 20-06-2022 at around 3PM. About 10m in length and 3m width of spur got eroded. Report submitted by Water Resource department		
	Kokrajhar	Dotma - 1. Vill- Nowerbhita, 2. Vill- Umanagar 1. Dated: 21/06/2022 Bank erosion by river Longa at village Nowerbhita, Nowerbhita LP School to South Nowerbhita village. Erosion of length 300M (Approx.) 2. Date: 21/06/2022 Bank erosion by river Gongia at village Umanagar. Erosion of length 700M (Approx.) 67		
	Lakhimpu r	Bihpuria - Dikrong L/B embankment of Bongalmora PGR (Balichapori) Active erosion observed at Ch. 15000 km on 21/06/2022 due which 03 nos. of families residing near the river bank have been shifted to other safe locations. Restoration measures are undertaken by WRD, Bihpuria Sub-division. 22		
	Majuli	Majuli - Rayati Erosion occurred at Rayati village under Ahataguri mouza on 20/06/2022. 27		
	Morigaon	Laharighat - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori As per report received from the Water Resources Dept on 21/06/2022, erosion is observed in areas like Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori with maximum erosion of 1 m in Leruamukh, 1 m in Goroimari , 4 m in Bhajaikhati gaon & 6 m in Barchapori 0		
	Nalbari	Tihu - TIHU AKHARA LINK ROAD TO JAYHARI PITAR THAN ,SATHIKUCHI , LENGTH 400 MTS(APPROX),DATE :19/06/2022,INFORMATION RECEIVED FROM JE, PWD(R),BARAMA 0		
	Sonitpur	Dhekiajuli - Dheraimajuli As reported by Water Res Dept, severe bank erosion observed at right bank of Belsiri river embankment at Dherai Majuli from CH3700m to 3916m. date 20.6.22 0		
	Tinsukia	Sadiya - 8th mile, Koilabasti, Lakhimpuria, Amarpur Gaon 1. Erosion at 8th mile by Kundil river under the bridge since 16/06/2022 to 21/06/2022 as per report received from the concerned Gaon Pradhan. Stretch area is 04 m. Location (27°52′02″N, 95°45′36″E). 2. Active erosion is reported from Koilabasti area by Kundil river since 16/06/2022 to 21/06/2022 by concerned Gaon Pradhan. Stretch area is 10 m. Location (27°50′48.8″N, 95°42′45.2″E). 3. Active erosion is reported from Lakhimpuria area by Kundil river since 16/06/2022 to 21/06/2022 by concerned Gaon Pradhan. Stretch area is 5 m. 4. Active erosion is reported from Amarpur Gaon by Dibang river since 16/06/2022 to 21/06/2022 by concerned Gaon Pradhan. Stretch area is 10 m. 0		
	District	Details		
	Hailakandi	Hailakandi - chalk chandpur,Severely Damaged Under Hailakandi Revenue Circle on 21.06.2022 No casualties 5		
Landslide	Kamrup (M)	Guwahati - Kailashpur Kharghuli, Nijarapara Chandmari Two Releif Camp opened at 1.Nabagraha Sisu vidlaya, 2. baidik school , total inmates in relief camp 23, the Landslide Occurred on 15/06/2022 & Camps are still open till today (21/06/2022) 0		
	Karimganj	Patherkandi - Duhalia Pt-2, A kutcha house is partially damaged dtd. 20-06-2022. 6		
	District	Details		
Urban Flood	Cachar	Silchar - Linkroad, National Highway road point, Ambicapatty, Church Road, Chandicharan Road, Bilpar, Public School Road, Subhas Nagar, Sonai Road, N.S. Avenue, Premtala, Chengkuri Rood, Malugram, Kanakpur, Tarapur Chandmari, Itkhola, Ghoniala, Meherpur Due to incessant rainfall, closure of sluice gates and over- topping of Embankments in many areas in and around Silchar Town on dated 21.06.2022 12201		
	Darrang	Mangaldoi - Ward No. 2,4 The water logging due to river bega is reciding .Dated 21-6-2022 8000		
	Goalpara	Lakhipur - Lakhipur Town Ward No. 1,2,3,4,5,6,8,9&10 Due to Urban flood in Lakhipur Town Ward No. 1,2,3,4,5,6,8,9&10 got affected. The Date of Occurrence of Urban flood on 16.06.2022 to till date i.e 21.06.2022 7512		
	Karimganj	RK Nagar - ward no 1 2 3 4 6 7 10 Continuous Urban Flood from 20th April 2022 - 21st April 2022, total 306 family effected 1377		