

FRIMS Assam





			Ass	am Daily Flood Report as on 1	9-05-2022 at 4:00 PM					
Particulars	Situation as or	n 19-05-2022	2 (in last 24	hours)						
Rivers	Rivers flowing	g above dang	ger level	Kopili (Dharamtul), Disang (Nanglamuraghat), Brahmaputra (Neamatighat)					
flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing level	g above high								
	No. of Districts Affected	Name of F	nme of Flood Affected Districts Name of Urban Flood Districts							
District Affected	27	Cachar, Da Dima-Hasa Kamrup (M Kokrajhar,	Bajali, Baksa, Barpeta, Biswanath, Bongaigaon, Cachar, Darrang, Dhemaji, Dhubri, Dibrugarh, Dima-Hasao, Goalpara, Hailakandi, Hojai, Kamrup, Kamrup (M), Karbi Anglong West, Karimganj, Kokrajhar, Lakhimpur, Majuli, Morigaon, Nagaon, Valbari, Sonitpur, Udalguri							
No. Of Revenue Circles Affected	75	, , , ,								
	District	Total	Revenue	Circle						
ĺ	Bajali	1	Bajali							
	Baksa	1	Baksa							
	Barpeta	4		, Baghbar, Kalgachia, Chenga						
	Biswanath	4		n, Naduar RC part, Gohpur, Hal	em					
	Bongaigaon	2		, Srijangram						
	Cachar	5		, Udharbond, Silchar, Lakhipur	; Sonai					
	Darrang	4		Patharighat, Mangaldoi, Sipajh						
	Dhemaji	3		Daigaon, Patnarignat, Mangaidoi, Sipajnar Dhemaji, Jonai, Sissiborgaon						
	Dhubri	4		Gauripur, Dhubri, Chapar, Athani						
	Dibrugarh	1	Chabua	•						
	Dima-									
	Hasao	1	Haflong							
	Goalpara	4	Matia, Rongjuli, Lakhipur, Balijana							
	Hailakandi	1	Algapur							
Name Of	Hojai	3	0 1	Lanka, Doboka, Hojai						
Revenue	Jorhat	1	Jorhat Eas							
Circles	Kamrup	4		ayan, Chamaria, Nagarbera						
Affected	Kamrup									
	(M)	2	Dispur, Cl	handrapur						
	Karbi Anglong West	1	Donkamokam							
Ì	Karimganj	2	Karimganj, Badarpur							
	Kokrajhar	2		ri, Bagribari						
	Lakhimpur	4		himpur, Bihpuria, Nowboicha,	Narayanpur					
	Majuli	2		ani Majuli						
	Morigaon	2	Mayong, l							
	Nagaon	3		Raha, Nagaon						
	Nalbari	6		Barbhag, Nalbari, Tihu, Ghogi	1					
	Sonitpur	5		a, Dhekiajuli, Tezpur, Naduar,	Chariduar					
	Udalguri	3	Udalguri,	Khairabari, Kalaigaon						
	Total	75 To 4 1	D	C! I						
	District	Total	Revenue							
	Bajali	6	(Bajali 6							
	Baksa	1	(Baksa 1	·	11 170 (71 170)					
	Barpeta	198		ri 26), (Kalgachia 57), (Ba						
	Biswanath	31		th 6), (Naduar RC part 4),	(Gonpur 11), (Halem 10)					
Villages	Bongaigaon	81		nr 7), (Srijangram 74)	Airmal 16 \ (\text{Sens: 142 \ \ (\text{V.c.} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
Affected	Cachar	319			chipur 16), (Sonai 43), (Katigorah 113)					
	Darrang	153		45), (Mangaldoi 46), (Pat						
	Dhemaji	28		2), (Sissiborgaon 14), (Dhe						
	Dhubri	61		13), (Gauripur 15), (Dhubr	1 5), (Athani 28)					
	Dibrugarh	2	(Chabua	2)						
	Dima- Hasao	5	(Haflong	[5]						

	Goalpara	143	(Matia 2	28), (Balijana	43), (Rongjul	i 15), (Lakhipur 57)					
	Hailakandi 3 (Algapur 3)										
	Hojai	78	(Lanka	11), (Doboka	23), (Hojai 4	14)					
	Kamrup	51	(Kayan	9), (Rangia 2	24), (Chamaria	15), (Nagarbera 3)					
	Kamrup	9	(Chandra	nur I 0)							
	(M)	,	(Chandra								
	Karbi Anglong West	5	(Donkamokam 5)								
	Karimganj	13	(Karimganj 8), (Badarpur 5)								
	Kokrajhar	39		i 37), (Bhaw							
	Lakhimpur	64			•	Bihpuria 24), (North Lakhin	npur 2)				
	Majuli	15		11), (Ujani M		1 // /	1 , ,				
	Morigaon	125		73), (Moriga	J						
	Nagaon	184			73), (Kampur	98)					
	Nalbari	97				pari 11), (Tihu 5), (Paschi	m Nalbari 15)	, (Ghograpar 17)			
	Sonitpur	56	(Tezpur	15), (Thelama	ara 13), (Dhel	kiajuli 17), (Naduar 2), (C	Chariduar 9)				
	Udalguri	23	(Khairaba	ari 5), (Kalai	gaon 14), (Ud	lalguri 4)					
	Total	1790									
	District	Male	Female	Children	Total Population	Population Details	Crop Area (in Hect.)	Crop Area Details			
	Bajali	19	13	4	36	(Bajali 36)	0.00	(Bajali 0.00)			
	Baksa	0	0	0	0	(Baksa 0)	2.50	(Baksa 2.50)			
	Barpeta	0	0	0	0	(Sarthebari 0), (Chenga 0), (Kalgachia 0), (Baghbar 0)	5537.30	(Sarthebari 282.50), (Chenga 1471.00), (Kalgachia 967.00), (Baghbar 2816.80)			
	Biswanath	wanath 5082		2849	12354	(Biswanath 1434), (Naduar RC part 1450), (Gohpur 3608), (Halem 5862)	1815.00	(Biswanath 713.00), (Naduar RC part 204.00), (Gohpur 662.00), (Halem 236.00)			
	Bongaigaon	0	0	0	0	(Manikpur 0), (Srijangram 0)	1730.00	(Manikpur 67.00), (Srijangram 1663.00)			
	Cachar	60640	54629	44515	159784	(Katigorah 110575), (Udharbond 1205), (Silchar 30000), (Lakhipur 7899), (Sonai 10105)	5550.00	(Katigorah 3052.00), (Udharbond 146.00), (Silchar 1238.00), (Lakhipur 293.00), (Sonai 821.00)			
	Darrang	26066	21982	13688	61736	(Dalgaon 3977), (Patharighat 26433), (Mangaldoi 30860), (Sipajhar 466)	10378.90	(Dalgaon 7441.50), (Patharighat 385.40), (Mangaldoi 2259.00), (Sipajhar 293.00)			
	Dhemaji	315	260	69	644	(Jonai 0), (Sissiborgaon 0), (Dhemaji 644)	431.85	(Jonai 303.60), (Sissiborgaon 116.25), (Dhemaji 12.00)			
Population And Crop Area Affected	Dhubri	0	0	0	0	(Gauripur 0), (Dhubri 0), (Athani 0), (Chapar 0)	1228.41	(Gauripur 534.00), (Dhubri 67.00), (Athani 471.41), (Chapar 156.00			
	Dibrugarh	1949	1490	1148	4587	(Chabua 4587)	3.50	(Chabua 3.50)			
	Dima-	323	323	365	1011	(Haflong 1011)	0.00	(Haflong 0.00)			
	Hasao Goalpara	0	0	0	0	(Matia 0), (Balijana 0), (Rongjuli 0), (6867.00	(Matia 1750.00), (Balijana 722.50), (
	_					Lakhipur 0)		Rongjuli 300.00), (Lakhipur 4094.50)			
	Hailakandi	870	660	320	1850	(Algapur 1850)	13.00	(Algapur 13.00)			
	Hojai	52951	34360	10059	97370	(Lanka 3852), (Doboka 53838), (Hojai 39680)	5447.00	(Lanka 650.00), (Doboka 1231.00), (Hojai 3566.00)			
	Kamrup	24	19	14	57	(Chamaria 0), (Nagarbera 0), (Kayan 1907.20 Ka		(Chamaria 1468.50), (Nagarbera 99.50), (Kayan 68.20), (Rangia 271.00)			
	Kamrup (M)	0	0	0	0	(Chandrapur 0)	778.00	(Chandrapur 778.00)			
	Karbi Anglong West	611	611	773	1995	(Donkamokam 1995)	7.00	(Donkamokam 7.00)			
	Karimganj	4576	3698	3757	12031	(Karimganj 10004), (Badarpur 2027)	11.20	(Karimganj 0.00), (Badarpur 11.20)			
	Kokrajhar	0	0	0	0	(Bagribari 0), (Bhawraguri 0)	246.40	(Bagribari 241.90), (Bhawraguri 4.50)			
	Lakhimpur	1907	1534	1935	5376	(Nowboicha 915), (Narayanpur 0), (777.70	(Nowboicha 0.00), (Narayanpur 549.70), (

							62), (North		Bihpuria 21		
						Lakhimpur 1499) (Majuli 0), (Ujani			North Lakhin		
	Majuli	0	0	0	0	Majuli 0)	, (Ujani	286.43	(Majuli 255.08), (Ujani Majuli 31.35)		
	Morigaon	373	356	165	894	(Mayong 0 Morigaon 8		6038.19	(Mayong 4680.00), (Morigaon 1358.19)		
	Nagaon	143382	128870	58989	331241	(Kampur 237158), (Raha 79305), (Nagaon 11865.94 14778)			(Kampur 5600.00), (Raha 4867.94), (Nagaon 1398.00)		
	Nalbari	4294	3406	1219	8919	(Barbhag 0), (Barkhetri 0), (Nalbari 0), (Tihu 7964), (Paschim Nalbari 955), (Ghograpar 0)		1296.10	(Barbhag 173.00), (Barkhetri 840.00), (Nalbari 30.60), (Tihu 36.00), (Paschim Nalbari 152.00), (Ghograpar 64.50)		
	Sonitpur	2391	2325	1855	6571			1752.00	(Naduar 15 Tezpur 222. Thelamara 1 Dhekiajuli 1 Chariduar 7	00), (80.00), (123.00), (
	Udalguri	5462	3950	1720	11132	Khairabari 2	Harisinga 0), ((Harisinga 0), (nairabari 289), (ulaigaon 8922), ((Khairabari 0. Kalaigaon 0.0		0.00), (.00), (
	Total	311235	262909	143444	717588			63970.62			
	District	Total	Relief Ca		0)			Disgraph 16)	3		
	Biswanath	8		1, Biswanath ond 1, Lakhii	0) pur 11, Sonai	6. Silchar l		Biswanath 6) nd 0, Lakhipur	2. Sonai 0 Si	lchar 0	
	Cachar	114	35, Katigo	orah 32)			Katigorah 2	Katigorah 27)			
	Darrang Dhemaji	24	1(Patharig		n 0, Mangaldo	i 0)	23(Patharighat 3, Dalgaon 14, Mangaldoi 6) 1(Dhemaji 1)				
	Dima-	6					1(Dnemaji 1) 6(Haflong 6)				
	Hasao		0(Haflong								
Relief Camps	Hailakandi Hojai	62	1(Algapur 57(Dobok	: 1) a 11, Hojai 4	6. Lanka 0)		0(Algapur 0) 5(Doboka 0, Hojai 4, Lanka 1)				
/ Centres	Kamrup	1	1(Rangia		o, Lunka 0)		0(Rangia 0)	• •	1/		
Opened	Karbi Anglong West	4		nokam 0)			4(Donkamokam 4)				
	Karimganj	15		ır 6, Karimgar	•		9(Badarpur 0, Karimganj 9)				
	Lakhimpur	5			ia 0, North Lal	khimpur 0)	0) 5(Nowboicha 1, Bihpuria 2, North Lakhimpur 2) 89(Nagaon 2, Kampur 52, Raha 35)				
	Nagaon Sonitpur	104	15(Nagao 0(Tezpur	n 5, Kampur	10, Raha 0)		89(Nagaon 4(Tezpur 4)		Raha 35)		
	Udalguri	10			ri 0, Kalaigaon	10)	10(Khairabari 2, Udalguri 2, Kalaigaon 6)				
	Total	359	167	uri jo, o uurgur	1 0, 1201013011	10)	192				
	District	Total		Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disability	
	Biswanath	30		h 0), (Naduar 0), (Halem 30		10	17	3	0	0	
	Cachar	27795	(Katigoral (Lakhipur (Udharbor	n 19360), (Silo 0), (Sonai 10 nd 76)	char 7346), 013),	10132	9945	7689	22	7	
Inmates In	Darrang	66	(Patharigh (Sipajhar	at 66), (Mang	aldoi 0),	10	40	13	1	2	
Relief Camps	Hailakandi	125	(Algapur	125)		45	62	18	0	0	
	Hojai	43811), (Doboka 13	891), (Hojai	24995	14360	4438	16	2	
	Kamrup	40), (Nagarbera	0), (Rangia	17	12	10	1	0	
	Karimganj	607	(Badarpur	(607)		326	197	58	26	0	
	Nagaon	7824	(Kampur	2737), (Raha	0), (Nagaon	4154	2986	626	52	6	
	Total	80298	5087)			39689	27619	12855	118	17	
Human Lives	District	Total	Male	Female	Children	Revenue Cir		1			
Lost -	Nagaon	1	1	0	0	(Kampur 1)	, (Nagaon 0),	(Raha 0)			
Confirmed	Total	1	1	0 General	0						
Human Lives Lost Confirmed -	District	Total	Flood Death	Drowning (Non Flood)	Landslide						
Death Type	Nagaon	1	1	0	0						
Human Lives	Total District	1 Total	1 Male	0 Female	0 Children	Details					
Lost -	Nagaon	2	2	0	0		, (Nagaon 0),	(Raha 0)			
				<u> </u>		_ (pur 2)	, (·1 v/			

Missing	Total	2	2	0	0						
Human Lives	District	Total	Flood	Non Flood							
Lost Missing	Nagaon	2	2	0	<u>*</u>						
- Type	Total	2	2	0							
	District	Total	Big	Small	Poultry						
	Barpeta	24273	12004	7269	5000						
	Biswanath	6250	4969	1281	0						
	Cachar Darrang	15618 124994	10118 58904	5500 25180	40910						
	Darrang	92	58	34	0						
	Dibrugarh	1599	1412	187	0						
	Goalpara	1053	588	465	0						
Animals	Hailakandi	200	65	30	105						
Affected	Hojai	13829	3164	1647	9018						
	Kamrup	14114	5972	3834	4308						
	Karimganj	942	578	364	0						
	Lakhimpur	8132	4308	3124	700						
	Nagaon	76849	44502	21465	10882						
	Nalbari	23375	10425	11150	1800						
	Sonitpur Udalguri	2321 71	1669 10	652 16	0 45						
	Total	313712	158746	82198	72768						
Animals	Total	313/12	150/40	02190	72708						
Washed Away	Nil										
-	District	Fully	Fully	Fully	Partially	Partially	Partially	Others	Others	Others	
	Cachar	Kuccha 3000	Pukka 670	Total 3670	Kuccha 22000	Pukka 1789	Total 23789	Huts 1500	Cattle Shed 550	Total 2050	
Houses	Dima-	3000	070	3670	22000	1789	23769	1300	330	2030	
Damaged	Hasao	135	233	368	0	0	0	0	0	0	
	Kamrup	4	0	4	10	0	10	0	3	3	
	Total	3139	903	4042	22010	1789	23799	1500	553	2053	
	District	Agency			Boats Deployed	Person Evacuated By Boats	Animal Evacuated By Boats	Helicopters Deployed	Person Evacuated By Helicopters	Medical Team Deployed	
Rescue	Cachar	Circle Office/Local Administration, Civil Defence/Trained Volunteers, NDRF, Police, SDRF, Water Resources Department, Army/Paramilitary force, Fire & Emergency Services (F&ES), Local People, Inland Water Transport			20	2140	0	0	0	37	
Operation	Darrang	SDRF	una muter i	runsport	1	27	0	0	0	8	
Operation	Dima-		***								
	Hasao	Army/Para	military for	ce	0	0	0	2	105	0	
	Hojai	SDRF, Co			94	3062	126	0	0	8	
	Kamrup	1 copie, m	, 5000		0	0	0	0	0	1	
	Nagaon		cle Office/L	ocal	15	2000	0	0	0	4	
	Total	Administra	ation		130	7229	126	2	105	58	
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed -	Rice Bran (in (
	Biswanath	88.02	16.96	3.63	363.06	0.00	93.00	0.00			
	Cachar	656.90	114.14	38.78	943.51	0.00	40.00	0.00			
	Darrang	385.80	73.36	22.08	2209.10	0.00	0.00	43.80			
D. I. C	Dibenaji	11.17	1.93	0.57	57.96	0.00	0.00	0.00			
Relief Distributed	Dibrugarh Dima-	0.00 16.00	0.00	0.00	0.00	0.00	112.50 0.00	0.00			
	Hasao Hailakandi	0.00	0.00	0.00	0.00	0.00	19.00	0.00			
	Hailakandi Hojai	360.80	64.96	19.50	1948.62	0.00	0.00	0.00			
	Kamrup	0.44	0.08	0.02	2.40	0.00	0.00	0.00			
	Karbi Anglong West	13.13	2.40	0.72	0.72	0.00	0.00	0.00			
	Karimganj	17.03	3.14	0.94	0.00	0.00	0.00	0.00			
	Lakhimpur	24.83	4.55	1.36	136.00	0.00	0.00	283.05			

	Nagaon	4046.33	770.81	237.12	0.00	0.00	1229.37	0.00	
	Nalbari	0.00	0.00	0.00	0.00	0.00	251.00	0.00	
	Sonitpur	0.00	0.00	0.00	0.00	0.00	146.56	0.00	
	Udalguri	64.26	11.65	3.50	349.53	0.00	0.00	0.00	
	Total	5684.71	1064.48	328.37	6020.90	0.00	1891.43	326.85	
	District	Baby Food	1	Baby Food		Others	1071.43	320.03	
	Biswanath	0.00-Q	u Elquiu	0.00-Q	Sonu	Candle-16 9.00-Pkt; S	Candle-16.00-Pkt; Mosquito Repellent Coil-12.00-Pkt; Match Box-9.00-Pkt; Sanitary Pad-30.00-Pkt; Hand Wash-16.00-Pieces; Soap-		
	Cachar	0.00-Q		0.00-Q			d-70.00-Pkt; Mo	Q; Jaggery-0.30-Q rtien-800.00-Pkt; Candle-800.00-Pkt; Match	
	Darrang	0.00-Q		0.00-Q, 90.0	00-Pkt		500.00-Pieces		
	Dhemaji	0.00-Q		0.00-Q			155.00-Pieces		
	Dibrugarh	0.00-Q		0.00-Q					
	Dima- Hasao	20.00-L		0.00-Q					
Relief	Hailakandi	0.00-Q		0.00-Q					
Distributed Others	Hojai	0.00-Q, 0.0	00-Pkt	0.00-Q, 1849	9.00-Kg			s; Tarpaulin-1060.00-Pieces; Chira-31.88-Q; 40.00-L; Water-1245.00-L	
	Kamrup	0.00-Q		0.00-Q			G,		
	Karbi Anglong West	0.00-Q		0.00-Q					
	Karimganj	23.00-Pkt,	0.00-Q	0.00-Q, 60.0	00-Pkt	Chira-215.	.60-Kg; Gur-36.	10-Kg; chira-0.55-Q; Gur-0.10-Q	
	Lakhimpur	0.00-Q		0.00-Q			<u> </u>		
	Nagaon	0.00-Q, 10	0.00-Pkt	0.00-Q, 5000 400.00-Pkt	00.00-ml,	0-0.00-Pkt	:		
	Nalbari	0.00-Q		0.00-Q					
	Sonitpur	0.00-Q		0.00-Q					
	Udalguri	0.00-Q, 52	6.00-Pkt	0.00-Q, 224.	.00-Pkt	Sanitary Pa	ad-345.00-Pkt; 0	00-0.00-Q	
	District	Number	Details						
			Morigaoi	- Earthen che	ck bund at Ma	iparbat Area 1	9-05-2022 Ma	tiparbat, Morigaon At 4:10AM, at the site of	
Infrastructure Damaged -	Morigaon	1	was const	onstruction site of a sluice gate at Matiparbat Area near Killing Kapili junction an earthen check bandh ructed to avoid submergence of the work site and adjoining areas from flood water of Killing river. Due vater level the Earthen check bandh collapsed due to overtopping of flood water.					
Embankment Breached	Udalguri	1	Kalaigaon - Embankment at No 2 Singri breached on 19/05/2022 caused by erosion			rimari in the I	/B of river Noa	No 2 Singrimari The embankment has vering a length of approximately 12 meters	
	Total	2	and bread	tn of 5 ft.					
	District	Number	Details						
	District	Number		ni - Bega FIS ı	ınder Irrigation	Department	Rhangurichuha	under Mangaldai Rev. Circle Bega river FIS	
Infrastructure Damaged -	Darrang	1	left side g	Mangaldoi - Bega FIS under Irrigation Department Bhangurichuba under Mangaldai Rev. Circle Bega river FIS left side guide bank damage due to rising water level of river Bega. The approximate length of damage is 50m as of now as reported by Irrigation Department. Dated 19/05/2022					
Embankment	Karbi		Donkamokam - Taradubi Market to Namtardubi L.P School Taradubi West karbi Anglong Taradubi						
Affected	Anglong West	1		Embankment was affected due to high wave of Flood Water was affected on 17/05/2022 at an approx 50 metres each at 5 different place.					
	Total	2		paret					
	District	Number	Details						
Infrastructure Damaged - Road	Barpeta	13	Barpeta - Dongarkuhi Kaljhar Road Dangarkuchi Submerged & road surface damage(60.00 m) 18.05.2022 , Recived from PWD Road, Barpeta , Kahibari to Barpeta Doulashal road via Majkuchi village (As-01-460) Kahibari Side berm & har (7.00 m) DOO: 18.05.2022 , Recived from PWD Road, Barpeta , Barpeta Patbaushi Keotkchi Road Barpeta Town Side berm & hard crust of the approach of RCC (6 m) DOO: 18.05.2022 , Recived from PWD Road, Barpeta , Bagodi Bhairaguri Road via Panichilla Bagodi Side berm eroded & hard crust damage (17.00 m) 18.05.2022 , Recived from PWD Road, Barpeta , Nagao Khardhara road to Kharuapara Road Nagaon Side berm eroded & hard crust damage (15.18.05.2022 , Recived from PWD Road, Barpeta , Barpeta Doulashal road Barpeta Hard crust damage (290.00 m) DOO: 18.05.2022 , Recived from Barpeta Hard crust damage (290.00 m) , Bhella Tatikuchi Road Bhella Side berm eroded & hard crust damage (10.00 m) DOO: 18.05.202 from PWD Road, Barpeta , Sonkuchi Jogirpam via Donakuchi Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 , Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 Recived Road Sonkuchi 2 Nos. breach occurred DOO: 18.05.2022 Recived Road Sonkuchi 2 Nos. brea					Kahibari Side berm & hard crust damage crust of the approach of RCC Br. 1/1 damage chard crust damage (17.00 m) DOO: ded & hard crust damage (15.00 m) DOO: DO: 18.05.2022 , Recived from PWD Road, lige (10.00 m) DOO: 18.05.2022 , Recived	
	Biswanath 1 Cachar 22		Duttakuch PWD Roa Old NT ro Recived f Sartheba Sarthebar Gomura, 1 Halem - C on 18/05/2 Udharbo	nd, Barpeta, oad at Howly to rom PWD Roa ri - 1. Sartheba to Karakuchi Batia, Rampur, Ghahigaon to E 2022 nd - APPROA	own near Oil Dad, Barpeta, ari to Pathsala I PWD road app, Bungaon, Kar Boranipathar C	epo Howly T PWD road (Dr rox. 75 m. 3. 1 akuchi, Neula Ghahigaon Gh	Cown Road sub- r. Jinaram Path) Neularbhita - Ka rbhita, Kayakucl nahigaon to Bora of road from T08	merged (20.00 m) DOO: 18.05.2022, Recived from merged (20.00 m) DOO: 18.05.2022, approx. 450 m. & DOO: 18.05.2022, approx. 450 m. & DOO: 18.05.2022 approx. 450 m. &	
	<u> </u>		runjee via	i וויף וייי ו	ounagar Molle	mg rungee A	APPROACHES (OF BRIDGE NO.1/2 of road from T08 -	

Mollong Pungee to Chirir Par Khasia Punjee via Diphu to Suibunagar, Package No.AS-03-155, eroded, As per report received from PWD Silchar Udharbond (T) division. As on 19.05.2022, APPROACHES OF BOX CULVERT AT CH. 1820.00 M of Rural Road from L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and US Durganagar | Diksa Bhuban Nagar and US Durganagar | APPROACHES OF BOX CULVERT AT CH. 1820.00 M of Rural Road from L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and US Durganagar in Cachar District, Package No. AS-03-166, eroded. As per report received from PWD Silchar Udharbond (T) division. As on 19.05.2022, LAISONG RAJABAZAR ROAD | LAISONG | LAISONG RAJABAZAR ROAD AT CH.21400.00 M TO CH.21475.00 M AND CH.22600.00 M TO CH.22650.00M SIDE BERM DAMAGED.As per report received from PWD Silchar Udharbond (T) division. As on 19.05.2022, Silchar - Sonal -Sunabarighat Road | Sunabarighat | Sonal -Sunabarighat Road covering a road length of 1300.00m Ch.6700.00m to Ch.6000.00m) newly submerged, As per report received from PWD (T) Road Division, As on Silchar Hailakandi Road to Tarutajbar Road | Tarutajbar | Silchar Hailakandi Road to Tarutajbar Road PMGSY Package No A503181 covering a road leanth of 300.00 (Ch 0.00m to Ch.200.00 & Ch. 200.00 & Ch. 20 900.00m) submerged. As per the report received from PWD (T) Road Division, As on 19.05.2022, Dalu Moiner Bondh Road | Dalu Moiner Bondh | Dalu Moiner Bondh Road (3rd 4th and 5th km) under PMGSW(AS-03-240) Stretch of Submerge. As per the report received from PWD (T) Road Division, As on 19.05.2022., Silchar Kalain Road | Kalain | Silchar Kalain Road (8th to 9th Km) Under SOPD Stretch of Submerge. As per the report received from PWD (T) Road Division, As on 19.05.2022., Laburbondh Haldskouri Road | Laburbondh | Laburbondh Haldskouri Road (2nd and 3rd) Stretch of Submerge. As per the report received from PWD (T) Road Division, As on 19.05.2022., TRK Road | TRK | TRK Road (2nd and 7th) Stretch of Submerge. As per the report received from PWD (T) Road Division, As on 19.05.2022., S.K.Road to Raj Nagar (Salchapra) | Raj Nagar | S.K.Road to Raj Nagar (Salchapra) (2nd and 7th km) Under SOPD Stretch of Submerge. As per the report received from PWD (T) Road Division, As on 19.05.2022., NH S3 to TRK Road Via Hatirhar (Salchapra) | Hatirhar (Salchapra) | NH S3 to TRK Road Via Hatirhar (Salchapra) (1st to 4th km) Stretch of Submerge. As per the report received from PWD (T) Road Division, As on Lakhipur - POILAPOOL TO KUMBIRGRAM ROAD | PALLORBOND | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022, NH 37 AT PALLORBOND TO LAKHIPUR | PALLORBOND | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022. NH37 TO POLLARBOND FACTOR, (PACKAGE NO AS-03-251). | POLLARBOND | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022, CHOTOMAMDA AT LRA ROAD TO SONAI R.C.C BRIDGE (MDR) | CHOTOMAMDA | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022, SRIBAR LAKHIPUR ROAD | SRIBAR | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022, BINNAKANDI TO SILGHAT(PACKAGE NO. AS-03-237) | BINNAKANDI | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022, HAZARIGRAM TO KALAPANI ROAD, (PACKAGE NO. AS-03-248). | HAZARIGRAM | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022, JELLURA TO NH-37 AT JIRIGHAT CH 5700.00M TO CH. 6100.00M (PACKAGE AS-03-2221 | JIRIGHAT | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022, NH-53 AT JIRIGHAT TE TO LALPANI VIA BHAGKHAL KAPAKHAL AND MIRPUR, CH 3" KM, 4 KM, 6 KM (PACKAGE NO. AS-03-252) | LALPANI | As per the report received from PWD Lakhipur Civil Subdivision, Lakhipur, As on 19.05.2022, NH-53 TO CHISEL PUNJEE, CH. 500.00M TO CH 700.00M, CH. 2500.00M TO 2800.00M CH.3350.00M TO CH 3390.00M (Land Slip) | CHISEL PUNJEE | As per the report received from PWD Lakhipur Civil Sub-division, Lakhipur, As on 19.05.2022, TARAPUR TO UTTAR SONPUR, CH.100.00M TO CH. 400 00M, CH.700.00M TO CH 900.00M. CH 2100,00M TO CH. 2500.00M | UTTAR SONPUR | As per the report received from PWD Lakhipur Civil Subdivision, Lakhipur, As on 19.05.2022 Patharighat - santipukhri Milanpur Harimandir Road | Milanpur | Road submerged at Ch 0m to 500 m on 18/5/22, Hirapara to Samala Road | Athkuria | Road submerged at Ch 200m to 1200 m on 18/5/22, Mangaldoi - Barthekerabari to NH-15 road | Barthekerabari under Mangaldai Revenue Circle. | The road is submerged due to flood water. The length of submergence is 1KM (approx.) as of now as reported by PWRD. Dated 19/05/2022... Pipiradukan to Patalsingpara road | Patalsingpara under Mangaldai Revenue Circle. | The road is submerged due to flood water. The length of submergence is 1KM (approx.) as of now as reported by PWRD. Dated 19/05/2022., NH 15 to Telipara road | Telipara under Mangaldai Revenue Circle. | The road is submerged due to flood water. The length of submergence is 700m (approx.) as of now as reported by PWRD. Dated 19/05/2022., Mangaldai Stadium road | Mangaldai Town under Mangaldai Revenue Circle. | The road is submerged due to flood water. The length of submergence is 800m (approx.) as of now as reported by PWRD. Dated 19/05/2022., Darrang 13 Denial Path | Mangaldai Town under Mangaldai Revenue Circle. | The road is submerged due to flood water. The length of submergence is 400m (approx.) as of now as reported by PWRD. Dated 19/05/2022., Baghmara to NH-15 road | Baghmara under Mangaldai Revenue Circle. | The road is submerged due to flood water. The length of submergence is 350m (approx.) as of now as reported by PWRD. Dated 19/05/2022., Udaipur Path | Medhipara under Mangaldai Revenue Circle. | The road is submerged due to flood water. The length of submergence is 400m (approx.) as of now as reported by PWRD. Dated 19/05/2022., Manoighat maroi road | Niz-Rangamati under Mangaldai Revenue Circle. | The road is submerged due to flood water. The length of submergence is 600m (approx.) as of now as reported by PWRD. Dated 19/05/2022., $\mathbf{Sipajhar}$ - Bhuktabari Sonapur road submerged length 6 to 8 km Depth 0.50 m. & submerged length 9 to 11 km depth 1.00 m. & Breaching at 9 yo 10 km | Bhuktabari Sonapur road | reported by PWRD on 18/05/2022 at 5 pm, Tinisuti Malibari road submerged length 0 m to 1st km, depth 0.50 m. | Malibari | Reported by PWRD on 18/05/2022 at 5 pm,

		Haldha Maijeli road submerged length 100 m. Depth 0.45 m. Haldha-Maijeli Reporte by PWRD on 18/05/2022
Dhemaji	1	at 5 pm Jonai - PWD territorial road Kuligaon to Naharbandana under PMGSY Package No. As-04-28, 30.00 meter Culvert approaches (both side) got eroded and also over topped on 19/05/2022 due to Rajakhana River. From Ch.7100.00 M to 7400.00 M As per reports received from PWRD, Jonai Territorial Road Sub- Divsion-II, Jonai, a PWD territorial road Kuligaon to Naharbandana under PMGSY Package No. As-04-28, 30.00 meter Culvert approaches (both side) got eroded and also over topped on 19/05/2022 due to Rajakhana River.
Goalpara	4	Lakhipur - Fulgassa to Gossaidubi Road Near Gossaidubi Petrol Pump The approach road of PWD Dept. Fulgassa to Gossaidubi has been partially affected due to overflowing of rain water as on dated 18-05-2022, Balijana - Dakurvita firing camp to Hurkakuchi Dakurvita firing camp to Hurkakuchi Due to heavy rainfall road from Dakurvita firing camp to Hurkakuchi got overtopped and eroded in the different stretches of road formation up to a depth of 2.00M for length of 130.00M as on dated 18-05-2022, Banjalijhar School Road Bangalijhar Due to heavy rain, water overtopped on the road surface of Banjalijhar School Road and damaged / eroded road side berm as on dated 18-05-2022., Balijana Borjhara Road Balijana Borjhara Road Due to rain water of Ajagar heel site and overtopped on Balijana Borjhara Road at 5th KM and damaged / eroded road side berm as on dated 18-05-2022.
Hailakandi	1	Algapur - Package No. AS-09-58 Ch. 5480M to 4200M North Narainpur Pt-I to Block Boundary Mohanpur R.A. under Algapur Revenue Circle dtd. 18.05.2022 Erosion of dyke Embankment due to rise of water Level of river Katakhal
Lakhimpur	6	Dhakuakhana - Narayanpur Chapori to Ghilaguri road is overtopped at Ch. 1.54 KM. Length: 25M. on 19/05/2020 Juiepura , Bihpuria - Ahmedpur Kutubpur to Fatehpur PWD Road Between Bongalmora and Fatehpur road Length of Damage 400m from CH.2300m to CH.2700m on 19/05/2022 as reported by AEE, PWRD, Bihpuria TRSD, Fatehpur to Pandhowa Tinialia via Pava Chariali road Between Fatehpur and Pandhowa Length of damage 500m from CH.3400m to CH.3900m on 19th May 2022 as reported by AEE, PWRD, Bihpuria , Kutubpur(Monu Pradhani Tiniali) to Dharmapur Block Kutubpur- Dharmapur Block Length of damage CH. 0.00m to CH. 1100m on 19th May 2022 as reported by AEE, PWRD, Bihpuria, Fatehpur to Karunabari Block Road via Juba Nagar Fatehpur to Karunabari Road Length of damages as on 19th May 2022 are- 1)300m from CH. 0.00m to CH.300m, lat-27.091, long-93.991 2) 390m from CH. 310m to CH.700m,lat-27.091, long-93.991 3) 400m from CH. 1110m to CH. 1500m, lat-27.092, long-93.989 4) 850m from CH. 2100m to 2950m, lat-27.095, long-93.970, Nowboicha - Pandhowa Tinali to Garsiga Road Pandhowa Approach road of RCC Bridge no. 10/1 between Pandhowa and Garsiga, Length of damage- 30m at Chainage 9600.00m on 19/05/2022
Morigaon	1	Mayong - Road from Amlighat Sonaikuchi Road to Gova submerged at 1st and 2nd kms Near Rail Neer Water Plant Road Submerged on dtd.19/05/22
Nagaon	5	Kampur - Kampur Kathiatoli Road (SH-17) Mahaniaati Kampur to Kathiatoli Road Submerged and one culvert breached approx 10 m in between Mahaniaati to Manohargaon on dated 19.05.2022. The road belongs to PWD Roads Nagaon, Barhampur & Dagaon Dakhinpat Road Mahgariaati Kampur to Nagaon Dakhinpat Road submerged on dated 18.05.2022. The road belongs to PWD Roads Nagaon, Barhampur & Dagaon Dakhinpat Road submerged on dated 18.05.2022. The road belongs to PWD Roads Nagaon, Barhampur & Dagaon Pathinpatic Submerged on dated dept., Tetelisara to Patiapam via Majarati Majarati Tetelisara to Patiapam via Majarati submerged on dated 18.05.2022.he road belongs to PWD Roads Nagaon, Barhampur & Dagaon; Dagaon; Rupohohat dept., Nagaon - Nonoi - Dakhinpat-Kurabahi-Baithalangso Road Nonoi, Nagaon Nonoi - Dakhinpat-Kurabahi-Baithalangso Road, Length-8Km, Date-18/5/2022, Department-PWD, Nagaon Territorial Road Sub-Division, Nagaon, Nagaon-Dakhinpat-Kampur-Baithalangso Road Dakhinpat, Nagaon Nagaon-Dakhinpat-Kampur-Baithalangso
Nalbari	3	Road ,Length-18Km. Date-18/5/2022, Department-Barhampur Territorial Road Sub-Division, Kampur Nagaon Nalbari - Nalbari Bahjani to Pub Kalakuchi Road Nalbari Bahjani to Pub Kalakuchi Road at Marnoipar As per W.T msg vide Memo No-1137-44 dated 18.05.2022 received from PWD(Roads)Deptt, Nalbari, Approx 200 meter side berm eroded at marnoipar in Nalbari Bahjani to Pub Kalakuchi road due to rain water, Nalbari Bahjani to Pub Kalakuchi Road Nalbari Bahjani to Pub Kalakuchi Road As per W.T msg vide Memo No-1137-44 dated 18.05.2022 received from PWD(Roads)Deptt, Nalbari, Approx 200 meter Nalbari Bahjani to Pub Kalakuchi road submerged due to rain water, Charminar Chowk to NH-31 approach road Jaggannath Bhatta's house to Anjan Bhatta's house of Village Barsarkuchi approach road of Charminar Chowk to NH-31 sumberged As per W.T msg vide Memo No-1137-44 dated 18.05.2022 received from PWD(Roads)Deptt, Nalbari, Approx 100 meter Jaggannath Bhatta's house to Anjan Bhatta's house of Village Barsarkuchi approach road of Charminar Chowk to NH-31 sumberged due to rain water
Sonitpur	5	Dhekiajuli - Natunpam to NH-52 L23 Road under PMGSY package no AS-22-168 severely damaged as reported by PWD roads deptt. length 8mtr aprox. dated 18.5.22 Natunpam , As reported by PWRD Barchalla Territorial road Sub Div. Natun Singri to Dhiraimajuli road submerged by 30 cm for a stretch of 300.00M at 2nd KM. Dated 18.5.22 Natun Singri, Kalistan to Dhiraimajuli link road , Irrigation canal damaged due to surging agricultural water at Moila Ali to Napam pathar link road along Asom jyoti College Pwd road, Dhekiajuli. dtd 19.5.22 Moila Ali - Napam Pathar link road , Tezpur - Na Ali to Muwamari Road Na-Ali to Muwamari road, Muwamari Kachari dated 19/05/2022. As reported by PWD Roads dept. Hume pipe approach damaged no. 1/2., Paruwa to Tezpur University Road Parmaighuli Dated 19/05/202. As reported by PWD Roads dept. a stretch of 20.00 m on left side of Paruwa to Tezpur University road at Parmaighuli is damaged.
Udalguri	12	Udalguri - Road eroded at Udalguri Barbengra road around 10m on 18.05.2022. Barbengra, Udalguri , No. 2 Simuluguri (Kajiamati) road near PHE water supply tank washed away around 15m on 18.05.2022. Kajiamati, Udalguri , Rangagara Mohanpur to Kajiamati PWD road washed away around 30m on 18.05.2022. Rangagara, Udalguri , Khairabari - No 1. Bainara to Barnadipara No.1 Bainara RCC- Slab culvert including approaches damaged. Length: 10M (approx.) Date of occurrence: 18.05.2022, Thakuriapara Main Road to Umanada Goibari VCDC RCC- Box culvert damaged. Length: 10M (approx.) Date of occurrence: 18.05.2023,

			Kacharidag to MPK Road Bhergaon Road embankment including ICBP Hard Cruste erroded for about 200 M (approx.) in stretches Date of occurance: 18.05.2022, Kalaigaon - Kalaigaon rangamati Road at 2nd Km No 2 Kalaigaon The road surface has badly damaged on 19/05/2022 due to overflowing of flood water covering a length of around 300 meters and breadth of 12 inches					
			approximately., MB road at CH. 17th KM No 2 Singrimari The road surface has severely damaged on 19/05/2022 due to overflowing of flood water and waterlogging covering a length of around 70 meters and breadth of 10 inches, Majarchuba Amguri Chowk to Amguri Shiva Mandir Chowk Road No 2 Amguri The road surface has completely damaged at 1st km due to overflowing of flood water on 19/05/2022 covering a length of around 180					
			meters and breadth of 15 inches, Garubandha Gomthapara PMGSY link road near Bokrajhar Chowk Khas Bokrajhar and Uttar Bokrajhar The road surface has completely damaged on 19/05/2022 due to overflowing of flood water covering a length of around 300 meters and breadth of 18 inches at different parts of the road.,					
			The road connecting Barjhar Bagisha to Ramhari. Barjhar bagisha The road has breached at the both end of a Hume Pipe Culvert on 19/05/2022 due to heavy current of flood water over the road covering a length of around 15 meters and breadth of 5 meters approximately., The MGNREGA road near Mahaliajhar LP School Barjhar Bagisha The road has breached at several places on					
	Total	87	19/05/2022 due to overflowing of flood water covering a length of around 30 meters and breadth of 4 ft					
	Total District	8/ Number	Details					
Infrastructure Damaged -	Sonitpur	1	Dhekiajuli - Pwd Bridge approach on NH-15 damaged due to incessent rains near Dhekiajuli town, Prashanti					
Bridge	Total	1	Guest House. dated 19.5.22. aprox area 2 mtr Near Prshanti guest House					
Infrastructure Damaged -	Nil	1						
Wildlife	1111							
	District	Other Det						
			sheries/Pond Vill-Barbairagy, Lat:26.484886 Long:91.246033 Area: 0.25 Ha (Damage occurred on 17/05/2022 port is received from Fishery Developemnt Block Officer, Bajali),					
			Pond Vill-Barbairagy, Lat:26.485315 Long:91.245406 Area: 0.07 Ha (Damage occurred on 17/05/2022 and this secived from Fishery Developemnt Block Officer, Bajali),					
		Fisheries/F	20nd Vill-Barbairagy , Lat:26.485322Long:91.245199Area: 0.10 Ha (Damage occurred on 17/05/2022 and this					
		Fisheries/F	ceived from Fishery Developemnt Block Officer,Bajali), Pond Vill-Barbairagy, Lat:26.485503 Long:91.246064 Area: 0.05 Ha (Damage occurred on 17/05/2022 and this					
		-	ceived from Fishery Developemnt Block Officer, Bajali), Pond Vill-Barnalikuchi, Lat: 26.485494 Long: 91.239816 Area: 0.10 Ha (Damage occurred on 17/05/2022 and this					
		report is re	ceived from Fishery Development Block Officer, Bajali),					
			Pond Vill-Barnalikuchi , Lat:26.485845 Long:91.24095 Area: 0.06 Ha (Damage occurred on 17/05/2022 and this seeived from Fishery Development Block Officer, Bajali),					
			Fisheries/Pond Vill-Barnalikuchi , Lat:26.484947 Long:91.241315 Area: 0.07 Ha (Damage occurred on 17/05/2022 and this report is received from Fishery Development Block Officer, Bajali),					
		Fisheries/F	Pond Vill-Barnalikuchi , Lat: 26.483196 Long: 91.238425 Area: 0.10 Ha (Damage occurred on 17/05/2022 and this secived from Fishery Development Block Officer, Bajali),					
		Fisheries/F	20nd Vill-Barnalikuchi , Lat:26.492552 Long:91.239554 Area: 0.07 Ha (Damage occurred on 17/05/2022 and this					
		Fisheries/F	ceived from Fishery Development Block Officer, Bajali), Pond Vill-Barnalikuchi, Lat: 26.492767 Long: 91.240721 Area: 0.04 Ha (Damage occurred on 17/05/2022 and this					
		Fisheries/F	ceived from Fishery Development Block Officer, Bajali), Pond Vill-Barnalikuchi, Lat: 26.490786 Long: 91.238621 Area: 0.50 Ha (Damage occurred on 17/05/2022 and this					
			ceived from Fishery Development Block Officer, Bajali), Pond Vill-Barnalikuchi, Lat: 26.490466 Long: 91.23873 Area: 0.05Ha (Damage occurred on 17/05/2022 and this					
Infrastructure Damaged -			ceived from Fishery Development Block Officer, Bajali), Pond Vill-Barnalikuchi, Lat: 26.490306 Long: 91.239116 Area: 0.05 Ha (Damage occurred on 17/05/2022 and this					
Others	Bajali	report is re	ceived from Fishery Development Block Officer, Bajali), Pond Vill-Barnalikuchi, Lat: 26.489693 Long: 91.238811 Area: 0.05 Ha (Damage occurred on 17/05/2022 and this					
		report is re	ceived from Fishery Development Block Officer, Bajali),					
		report is re	Pond Vill-Barnalikuchi, Lat:26.489475 Long:91.23831 Area: 0.05 Ha (Damage occurred on 17/05/2022 and this seeived from Fishery Development Block Officer, Bajali),					
			Pond Vill-Barbhaluki, Lat:26.482191 Long:91.248065 Area: 0.05 Ha (Damage occurred on 17/05/2022 and this secived from Fishery Development Block Officer, Bajali),					
			Pond Vill-Barbairagy, Lat: 26.482129 Long: 91.248522 Area: 0.10 Ha (Damage occurred on 17/05/2022 and this secived from Fishery Development Block Officer, Bajali),					
		Fisheries/F	Pond Vill-Barbairagy , Lat:26.485355 Long:91.245495 Area: 0.05 Ha (Damage occurred on 17/05/2022 and this accived from Fishery Development Block Officer, Bajali),					
		Fisheries/F	20nd Vill-Barbairagy , Lat: 26.484301 Long: 91.247955 Area: 0.10 Ha (Damage occurred on 17/05/2022 and this					
			ceived from Fishery Development Block Officer, Bajali), Pond Vill-Barbairagy, Lat: 26.484182 Long: 91.248392 Area: 0.07 Ha (Damage occurred on 17/05/2022 and this					
			ceived from Fishery Development Block Officer, Bajali), Pond Vill-Barbairagy, Lat: 26.483124 Long: 91.243771 Area: 0.10 Ha (Damage occurred on 17/05/2022 and this					
		report is re	ceived from Fishery Development Block Officer, Bajali), Canal/Scheme Damaged Vill-Barbairagy, Lat: 26.483765 Long: 91.247427 Area: 0.10 Ha (Damage occurred on					
		17/05/2022	2 and this report is received from Fishery Development Block Officer, Bajali),					
			Pond Vill-Barbairagy, Lat:26.483765 Long:91.247427 Area: 0.07 Ha (Damage occurred on 17/05/2022 and this secived from Fishery Development Block Officer, Bajali),					
		Fisheries/F	Pond Vill-Barbairagy, Lat: 26.48414 Long: 91.24747 Area: 0.42 Ha (Damage occurred on 17/05/2022 and this seeived from Fishery Development Block Officer, Bajali),					
		Fisheries/F	20nd Vill-Barbairagy , Lat: 26.485081 Long: 91.246623 Area: 0.14 Ha (Damage occurred on 17/05/2022 and this					
		report is re	ceived from Fishery Development Block Officer, Bajali),					

		Fisheries/Pond Vill-Kanimara, Lat:26.477087 Long:91.262959 Area: 0.53 Ha (Damage occurred on 17/05/2022 and this report is received from Fishery Development Block Officer, Bajali), Fisheries/Pond Vill-Kanimara, Lat:26.478335 Long:91.246241 Area: 0.13 Ha (Damage occurred on 17/05/2022 and this report is received from Fishery Development Block Officer, Bajali)
	Barpeta	Sarthebari - Anganwadi Centres Affected 1. 78 No. Erartari AWC, 2. Kawaimari 6 No. Block AWC, Pakabetbari, 3. 34 No. Bagrirtari AWC, 4. 32 No. Khudra Faladi AWC, 5. 30 No. Kathalbhuri AWC, 6. 57 No. Joshodar Pam AWC, 7. 87 No. AWC, 8. 75 No. Fulbari AWC, 9. 213 No. Neularbhita AWC, 10. 104 No. AWC, 11. 99 No. AWC, 12. 150 No. AWC (all are
_		submerged)Report recived from CDPO Sarukhetri & Diego pakabetbariDate-19-05-2022
	Biswanath	Gohpur - Culvert Approach Road Damaged Sukurbari to Nigam Bishnu Borah Road 19-05-2022 (Report from PWD), Culvert Approach Road Damaged NH15 to Bilatia Road 19-05-2022 (Report from PWD), Halem - Bamboo Foot Bridge Bamboo foot bridge affected at Tetonpukhuri village on 18/05/2022. Location: 26.858028, 93.484713
	Cachar	Katigorah - Health Sub-Centre Gangapur Sub Centre, Lathimara-I Sub Centre, Lathimara-II HWC, Chandinagar HWC, Zabda Sub Centre, Baraitoll, Digabar Sub Centre, Khelma HWC, Saidpur HWC, Gumra MSC, Mohadevpur HWC, Nayagram Sub Centre under Katigorah Circle, Public Health Centre (PHC) Jalalpur Block PHC, Digorkhal PHC under Katigorah RC
	Darrang	Dalgaon - Fisheries/Pond as per report received from Fishery Dev. Officer, Kalaigaon and Dalgaon Dev. Block 23 nos of villages, 717 nos of Fish farmers and 140.64 Ha water area affected under Dalgaon Revenue Circle dated 19-05-2022, Patharighat - Anganwadi Centres Affected in total 05 nos. of AWC affected as reported by CDPO on 19/5/2022, Fisheries/Pond in total 1622 nos of Pond & Fisheries submerged covering 132.42 Ha area as reported by Fishery Deptt, PWSS Damaged in total 01 nos of PWSS affected/submerged viz. Borbori PWSS, as reported by PHE Deptt. on 18/5/2022, Mangaldoi - Anganwadi Centres Affected As reported by CDPO Pachim Mangaldai ICDS Project a total of 18 AWC is affected due to flood. Dated 19/05/2022., Power Dept. Poles As reported by APDCL 2 Nos. of HT poles are damaged due to flood. Dated 19/05/2022., Power Dept. Conductors As reported by APDCL 0.8km of conductor is damaged due to flood. Dated 19/05/2022., Fisheries/Pond As reported by fishery department a total of 1326(approx.) Nos. of fish farmers are affected and 120.86Ha(approx.) water area is affected. Dated 19/05/2022., Sipajhar - Fisheries/Pond as reported by Fishery Deptt. total 7 nos. of villages have been affected. total fishfarmers 177 nos.
	Dibrugarh	and total water area 10.1 Hactre as on dated 19-05-2022 Chabua - Anganwadi Centres Affected Dodhia AWC SUBMERGED as per information received from Social Welfare Department as on 16.05.2022, Anganwadi Centres Affected Dodhia Tengabari AWC Submerged as per information received from Social Welfare Department as on 16.05.2022, Health Sub-Centre Dodhia Kuligaon Health Sub-centre Submerged as per information received from Jt. director of health departments, as on 16.05.2022, Elementary Schools Damaged Dodhia ME School Submerged as per information received from Inspector of Schools, as on 17.05.2022, Elementary Schools Damaged Dodhia Kuligaon LPS Submerged as per information received from Inspector of Schools, as on 17.05.2022, Elementary Schools Damaged Dodhia Karmi LPS Submerged as per information received from Inspector of Schools, as on 17.05.2022, Elementary Schools Damaged Dodhia Tengabari LPS submerged as per information received from Inspector of Schools, as on 17.05.2022, Elementary Schools Damaged Dodhia Tengabari LPS submerged as per information received from Inspector of Schools, as on 17.05.2022
	Hojai	Doboka - Irrigation Canal/Scheme Damaged Two nos. motor pump and whole canal system submerge up to 5 feet at Nikhari LIS Pt No. 1 at village Dekerua dated 19-05-2022, Irrigation Canal/Scheme Damaged Two nos. motor pump and whole canal system submerge up to 5 feet at Nikhari LIS Pt No. 2 at Bherbher dated 19-05-2022, Irrigation Canal/Scheme Damaged Two nos. motor pump and whole canal system submerge up to 5 feet at Nikhari LIS Pt No. 3 at Bherbheri dated 19-05-2022, Irrigation Canal/Scheme Damaged Two nos. motor pump and whole canal system submerge up to 5 feet at Nikhari LIS Pt No. 4 at Bherbher dated 19-05-2022, Irrigation Canal/Scheme Damaged Two nos. motor pump and whole canal system submerge up to 5 feet at Nikhari LIS Pt No. 5 at village Dekerua dated 19-05-2022, Irrigation Canal/Scheme Damaged Two nos. motor pump and whole canal system submerge up to 5 feet at Nikhari LIS Pt No. 5 at village Dekerua dated 19-05-2022, Irrigation Canal/Scheme Damaged Two nos. motor pump and whole canal system submerge up to 5 feet at Jamuna lis (Baliram Pathar) at village Baliram dated 19-05-2022, Irrigation Canal/Scheme Damaged Controller is submerged and damage (PMKSY Pt No. 3) at village Patidoya dated 19-05-2022, Irrigation Canal/Scheme Damaged Controller is submerged and damage (PMKSY Pt No. 26) at village Bhedauati dated 19-05-2022, Irrigation Canal/Scheme Damaged Controller is submerged and damage (PMKSY Pt No. 28) at village Jugijan dated 19-05-2022, Irrigation Canal/Scheme Damaged Controller is submerged and damage (PMKSY Pt No. 34) at village Patiapamja Pathar dated 19-05-2022, Irrigation Canal/Scheme Damaged Controller is submerged and damage (PMKSY Pt No. 34) at village Nagayapam dated 19-05-2022, Irrigation Canal/Scheme Damaged Controller is submerged and damage (PMKSY Pt No. 43) at village Nagayapam dated 19-05-2022, Irrigation Canal/Scheme Damaged Controller is submerged and damage (PMKSY Pt No. 43) at village Nagayapam dated 19-05-2022, Power Dept. Conductors HT Conductor (Racco
	Kamrup	Rangia - Bamboo Foot Bridge A locally (public) made bamboo foot bridge over river Noona in village Khopnikuchi was washed away on 17.05.2022 as per report received from concerned Lot Mandal, Bamboo Foot Bridge A locally (public) made bamboo foot bridge over river Noona in village Issapur was washed away on

	17.05.2022 as per report received from concerned Lot Mandal
Kokrajhar	Bagribari - Bridge Approach Road Damaged AS REPORTED BY ASSTT. EXE. ENG. GOSSAIGAON RURAL ROAD SUB-DIVISION, GOSSAIGAON BRIDGE NO. 3/2 ON CHESAPANI TO MONGLAJHORA ROAD BOTH SIDE APPROACHES AND BRIDGE HAVE BEEN DAMAGED ON 18/05/2022, Road Breaches AS REPORTED BY ASSTT. EXE. ENG. GOSSAIGAON RURAL ROAD SUB-DIVISION, GOSSAIGAON GOMBARIGHAT TO MONGLAJHORA ROAD SUBMERGED ON 18/05/2022
Lakhimpur	Subansiri - Bamboo Foot Bridge The Subway of Bamboo Bridge No. 1/1 is submerged (L- 75M) and the existing Bamboo Bridge is damaged (L- 45M) on Chakuli to Akhoiphutia Road on 18/05/2022, Bamboo Foot Bridge The Subway of Bamboo Bridge No. 1/1 is submerged (L- 100M) and the existing Bamboo Bridge is damaged (L- 125M) on Kekuri Madhupur to Chelajan Kachari Road on 18/05/2022, Dhakuakhana - Bamboo Foot Bridge Bridge no. 2/2 at Narayanpur Chapori to Ghilaguri road (Ch.1.66KM) is damaged. Length: 60M. on 19/05/2022, Bihpuria - Bridge Approach Road Damaged Approach road of RCC Bridge no. 8/1 at CH. 7950 m on 19 May 2022 as reported by AEE, PWRD, Bihpuria
Majuli	Ujani Majuli - Power Dept. Poles village affected- Chikari gaon. 2 nos. of HT poles inclined at ground level due to raincut o Haldhibari Besamora E&D on Dtd.19-05-2022
Nagaon	Kampur - Culvert Approach Road Damaged Kampur to Kathiatoli Road Submerged and one culvert breached approx 10 m i between Mahaniaati to Manohargaon on dated 19.05.2022. The road belongs to PWD Roads Nagaon, Barhampur; and Rupohohat dept.
Nalbari	Barkhetri - Bridge Approach Road Damaged Due to incessant rain the side berms of rcc BRIDGE APPROACHES OF rcc brno.8/1 on Hajo Mukalmua Daulasal road at Adabari damaged with holes below hard crust. east side br approach damage 28r west side br. approach damage 38m as p[er information received from PWRD on 18/05/2022., Nalbari - Elementary Schools Damaged 1)Jaha Serabari ME school 2)PUSPAKPUR ADARSHA LPS 3)KALAFAKIRTOL. MOKTAB LPS 4)HAIDAR ALI ADARSHA LPS 5)NALBARI ADARSHA LPS 6)NALBARI HIGH SCHOOL 7)DEVIRAM PATHSALA HSS 8)Devudutta Sarma Lps 9)574 Bhuvaneswari LP 10)mazdiya lp 11)NALBARI PRACTISING SCHOOL 12)NO 1 JR BASIC SCHOOL 13)NALBARI SATRA MVS 14)MNC BALIKA BIDYAPITH 15)656 Tilana Lp SCHOOL 16)Alengidal Lp SCHOOL Report is received from Block Elementary Educational Officer, Pub Nalbari Block on 19.05.2022. These 16 nos schools are submerged due to rain water, Tihu - Elementary Schools Damaged Submerged the schools under Pub Nalbari Education Block. The name of the schools a 1. Nizkhana MES, date of submerged:17/05/2022, Lat& Long:26.462761/91.253944, 2.Dakhin Bhojkuchi LPS, date of submerged:18/05/2022, Lat &Long:26.4965/91.265831.The information received from BEEO, Pub Nalbari. , Handloom & Textile Deptt The nos of weavers(submerged their weaving instruments)at Bhojkuchi: 25 nos, Khudra Makhibaha:20nos, Saktipara:20nos, Jalkhana-1:25 nos, Jalkhana -2:25nos, Bhathuwakhana:20nos as per information received from Demonstrator, Tihu Circle, H &T Dept. , Paschim Nalbari - Handloom & Textile Deptt Looms ,accessories and weaven cloth of 26 Numbers of weavers in Lokhopur & Kendubari village are affected . Information received from Handloom & Textile Department on 19/05/2022.
Sonitpur	Thelamara - Road Breaches Date-18/05/2022, Surging water of Arasuti river has damaged the embankment, shoulder upto hard crust of PMSGY road package NO AS-22-201 on Thelamara to Arasuti Road at Ch. 410 m to 450 m as reported by PWD(ROADS) deptt., Road Breaches Date-18/05/2022, Surging water of Dighalijan river has damaged the embankment, shoulder upto hard crust o PMSGY road package NO AS-22-187 on Kacharigaon to Ulubari Road at Ch. 1000 m to 1070 m as reported by PWD(ROADS) deptt., Bridge Approach Road Damaged Date-18/05/2022, Surging water of Bengenajuli river has damaged the approach of RCC Bridge no. 3/2 at Nabil Pathar side of PMSGY PACKAGE NO. AS-22-58 ON Nabil Pathar to Dhankhana road as reported by PWD(ROADS) deptt., Culvert Approach Road Damaged Date-19/05/2022, The slab culvert (No.1/1) approach damaged on Jahamari Nabil road as reported by PWD roads deptt., Dhekiajuli - Fisheries/Pond As reported by Fishery dept. 61 nos of farmers are affected due to catchment area flooding of fisheries/ponds at 2No Pirakata and Mora pachnoi villages. dated 19.5.22, Culvert Approach Road Damaged As reported by PWRD Barchalla Territorial road Sub Div. Box cell culvert no 10/2 approach damaged along Palash Pathar to 5No Singri TE road. Dated 18.5.22, Culvert Approach Road Damaged As reported by PWD Dhekiajuli Territorial road Sub Div. one side of RCC culvert no 1/2 damaged due to surging water of Ghagra river along Ghagra Kachari to Panchnoi Nepali road near Dherai TE. Dated 18.5.22, Culvert Approach Road Damaged As reported by PWD Dhekiajuli Territorial road Sub Div. one side of RCC culvert no 7/4 an 14/1 damaged due to surging water of Mora Suti along Sirajuli to Sopai Pathar road near Lahbari and Balisuti. Dated 18.5.22, Culvert Approach Road Damaged As reported by PWD Dhekiajuli Territorial road Sub Div. one side of RCC culver no 1/2 damaged Approach Road Damaged As reported by PWD Dhekiajuli Territorial road Sub Div. One side approach of narrow bridge no 1/1 damaged due to surging water
Udalguri	Udalguri - Culvert Approach Road Damaged Approach road of DHPC washed away completely at Kajiamati to Ranipukhur road at Kajiamati village around 15m on 18.05.2022. GPS - Lat - 26.66591 Long - 92.11946, Damaged SPT Bridge Approach road eroded and SPT Bridge damaged at Pakribari Bhergaon road at Pakribari village around 30m on 18.05.2022. GPS - Lat - 26.72532 Long - 92.15424, Gully Control Damaged Gully Control Structure got damaged around 18m due to flood water at Mohanpur village on 18.05.2022. GPS - Lat - 26.670531 Long - 92.093566, Protection Bundh Damaged River training project got affected by flood at Barnagaon Village around 15 meters on 18.05.202 GPS - Lat - 26.709096 Long - 92.074319, Irrigation Canal/Scheme Damaged Erosion of left canal embankment at Ch. 750.00m and Ch. 8090.00m of B4M Canal at Manjabarim, Gerua, Batabari & Tamulbari villages on 18.05.2022. GPS - Lat - 26.807245 Long - 92.02604 & Lat - 26.741123 Long - 92.03589., Irrigation Canal/Scheme Damaged Erosion of canal embankment at Ch. 1730.00m of D1B3M canal at Khawrang village on

IR.05.2022_GFS - Lat - 26.794038 Long - 92.068869 ,	& 100M. Lat: 6, Long: Lat: 29.543259, guide bundh 66105, Long.: ted by SDO,
Rhairabari - Irrigation Canal/Scheme Damaged Dongpara FIS: left canal embankment breached at CH. 30M 26:6455388. Long: 91.83399812: Date of Occurrence: 18.05.2022. Irrigation Canal/Scheme Damaged Dingdong Nodi Bundha FIS: outfall damaged at CH. 70M. Lat: 26:668946 91.91614999: Date of Occurrence: 18.05.2022. Irrigation Canal/Scheme Damaged Binara FIS: w/s. & d/s right side guide bundh canal embankment breached Long: 91.819085: Date of Occurrence: 18.05.2022. Irrigation Canal/Scheme Damaged Suklaipara FIS Aqueduct damage and canal lining damage at CH. 35M & damage. Lat: 26.558951 Long: 91.790477: Date of Occurrence: 18.05.2022. Irrigation Canal/Scheme Damaged Kalpani FIS road crossing culvert above irrigation canal damage. Lat: 26.598951 Long: 91.845042: Date of Occurrence: 18.05.2022. Irrigation Canal/Scheme Damaged Kalpani FIS road crossing culvert above irrigation canal damage. Lat: 26.591.845042: Date of Occurrence: 18.05.2022. Irrigation Canal/Scheme Damaged Kalpani FIS road crossing culvert above irrigation canal damage. Lat: 26.591.845042: Date of Occurrence: 18.05.2022. Irrigation Canal/Scheme Damaged Kalpani FIS road crossing culvert above irrigation canal damage. Lat: 26.591.845042: Date of Occurrence: 17.05.222. Kalpani Rational Rationa	6, Long: Lat: 29.543259, guide bundh 66105, Long.: ted by SDO,
91,91614999: Date of Occurrence: 18.05.2022, Irrigation Canal/Scheme Damaged Bainara FIS: u's & d's right side guide bundh canal embankment breached Long: 91,819085: Date of Occurrence: 18.05.2022, Irrigation Canal/Scheme Damaged Suklaipara FIS Aqueduct damage and canal lining damage at CH. 35M & damage. Lat: 26.558961. Long: 91,790477: Date of Occurrence: 18.05.2022, Irrigation Canal/Scheme Damaged Kalpani FIS road crossing culvert above irrigation canal damage. Lat: 26.58961. Long: 91,845042: Date of Occurrence: 18.05.2022 District Details Sarupeta - Mairambhita (village: Puthimari) Erosion at pahumara right bank,9.00 KM at Mairambhita (Repo Water Resource Department.Bajali on 18.05.2022) 10 Barama - 1, Bongaon 2, Kaljhar 3, Barsimaluguri 1, L/B embankment erosion caused by Tihu river at a stretch long (Lat: 26.550085, Lon: 91.271539) Date of occurrence: 1705/22 2. R/B embankment behind B ed college by Mora Pagladia river at a stretch of 400 meters long (Lat: 26.55516, Lon: 91.359211) Date of occurrence: 16.05/22 0 Baghbar - Niz Baghbar village Today one shiv temple is eroded away by the river Brahmaputra at Niz Baghb Moreover 4 nos of PMAY house also eroded due to the rapid erosion. The details of the houses are- House own ID 1.Rajib ch. Basumatary 18.73753 Z.Khagen Boro 1173865 3.Kandhuri Boro 2014087 4.Kamobak Boro 118 Report) 19-05-2022 30. Chenga - Kachumara K Approx. 18 bighas land eroded by the river Brahmaputra and 9 nos. houses were damerosion, reported by Gaon Pradhan and lot mandal on dtd-18/05/2022 54 Biswanath - 1. Singimari 2. Bhojmari 3. Natungaon 4. Kumolia 5. Borbeel 6. Tengabari 1. Bank erosion observed at 18 humbari to 80,3135871 5.Bank erosion observed at 18 humbari area on I/ Bank of river Borgang 19.05.2022 Lat-26.69 31.6531329 4. Bank erosion observed at 18 humbari area on I/ Bank of river Borgang 19.05.2022 Lat-26.69 31.266963 (Report from Water Resource Division) 0. Naduar RC part - Bhojmari Bank crosion observed at phulbari to bhojmari	Lat: 29.543259, guide bundh 66105, Long.: ted by SDO,
Long: 91.819085: Date of Occurrence: 18.05.2022, Irrigation Canal/Scheme Damaged Suklaipara FIS Aqueduct damage and canal lining damage at CH. 35M & damage. Lat.: 26.558951 Long.: 91.790477: Date of Occurrence: 18.05.2022, Irrigation Canal/Scheme Damaged Kalpani FIS road crossing culvert above irrigation canal damage. Lat: 26.5 91.845042: Date of Occurrence: 18.05.2022 District Details Bajali Sarupeta - Mairambhita (village: Puthimari) Erosion at pahumara right bank.9.00 KM at Mairambhita (Repo Water Resource Department.Bajali on 18.05.2022.) 0 Barama - 1. Bongaon 2. Kaljhar 3. Barsimaluguri 1. L/B embankment erosion caused by Tihu river at a stretch long (Lat: 26.550085, Lon: 91.271539) Date of occurrence: 17/05/22. 2. R/B embankment behind B.ed college by Mora Pagladia river at a stretch of 400 meters long (Lat: 26.559429, Lon: 91.42327) 1 occurrence: 16/05/22 0 Baghbar - Niz Baghbar village Today one shiv temple is eroded away by the river Brahmaputra at Niz Baght Moreover 4 nos of PMAY house also eroded due to the rapid erosion. The details of the houses are- House own ID 1.Rajib ch. Basumatary 1837153 2.Khagen Boro 1173865 3.Kandhuri Boro 2014087 4.Kamobak Boro 118 Report) 19-05-2022 30, Chenga - Kachumara K Approx. 18 bighas land eroded by the river Brahmaputra and 9 nos. houses were dan erosion, reported by Gaon Pradhan and lot mandal on did-18/05/2022 54 Biswanath - 1. Singimari 2. Bhojmari 3. Natungaon 4. Kumolia 5. Borbeel 6. Tengabari 1. Bank erosion observed at Secure Division 26.66828272, Long. 93.0809834 3. Bank erosion observed at Brahmaputra 19.05.2022. Lat-2.66. 93.16531329 4. Bank erosion observed at Ryamath to Natungaon 1.70.5.2022. Lat-2.66. 93.165931. S. Bank erosion observed at Brahma tho Naturagon 1.70.5.2022. Lat-2.66. 93.266963 (Report from Water Resource Division) 0, Naduar RC part - Bhojmari Bank erosion observed at Brahma tho Naturagon 1.70.5.2022. Lat-2.66. 93.266963 (Report from Water Resource Division) 0, Manikpur - Bhandra At Bhandra for a	guide bundh 66105, Long.: tted by SDO,
Irrigation Canal/Scheme Damaged Suklaipara FIS Aqueduct damage and canal lining damage at CH. 35M & damage. Latt.: 26.558951 Long.: 91.790477: Date of Occurrence: 18.05.2022. Irrigation Canal/Scheme Damaged Kalpani FIS road crossing culvert above irrigation canal damage. Latt. 26.5 91.845042: Date of Occurrence: 18.05.2022. District Details Bajali Sarupeta - Mairambhita (village: Puthimari) Erosion at pahumara right bank, 9.00 KM at Mairambhita (Repowart Resource Department, Bajali on 18.05.2022.) 0 Barama - 1. Bongaon 2. Kaljhar 3. Barsimaluguri 1. L/B embankment erosion caused by Tihu river at a stret long (Lat: 26.559085, Lon: 91.271539) Date of occurrence: 17/05/22.2. R/B embankment behind B.ed college by Mora Pagladia river at a stretch of 400 meters long (Latt. 26.53516, Lon: 91.359211) Date of occurrence: 16/05/22] 0 Baghbar - Niz Baghbar village Today one shiv temple is eroded away by the river Brahmaputra at Niz Baghh Moreover 4 nos of PMAY house also eroded due to the rapid erosion. The details of the houses are- House own ID 1.Rajib ch. Basumatary 1837153.2.Khagen Boro 1173865.3.Kandhuri Boro 2014087.4.Kamobak Boro 118. Report) 19-05-2022 30. Chenga - Kachumara K Approx. 18 bighas land eroded by the river Brahmaputra and 9 nos. houses were damerosion, reported by Gaon Pradhan and lot mandal on dtd-18/05/2022 54 Biswanath - 1. Singimari 2. Bhojmari 3. Natungaon 4. Kumolia 5. Borbeel 6. Tengabari 1. Bank erosion obseto to singimari 17.05.2022 Latt. 26.67436, Long - 93.08098334 3. Bank erosion observed at Biswanath to Natungaon .17.05.2022, Latt-26.69 93.16531329 4. Bank erosion observed at Brobeel, Orya Basti area on L/Bank of river Brahmaputra 19.05.2022. Latt-26. 93.16531329 4. Bank erosion observed at Brobeel, Orya Basti area on L/Bank of river Borgang 19.05.2022. Latt-26. 93.26993 (Report from Water Resource Division) 0. Naduar RC part - Bhojmari Bank erosion observed at Tengabari area on R/ Bank of river Brahmaputra 19.05.2022. Latt-26. 93.26993 (Report from Water	66105, Long.: tted by SDO,
Irrigation Canal/Scheme Damaged Kalpani FIS road crossing culvert above irrigation canal damage. Lat: 26.5	rted by SDO, th of 250 meters
District Bajali Sarupeta - Mairambhita (village: Puthimari) Erosion at pahumara right bank,9.00 KM at Mairambhita (Repo Water Resource Department,Bajali on 18.05.2022) 0	th of 250 meters
Barama - 1. Bongaon 2. Kaljhar 3. Barsimaluguri 1. L/B embankment erosion caused by Tihu river at a stretch long (Lat: 26.550085, Lon: 91.271539) Date of occurrence: 17/05/22 2. R/B embankment behind B.ed college by Mora Pagladia river at a stretch of 400 meters long (Lat: 26.53516, Lon: 91.359211) Date of occurrence: 16 embankment erosion caused by Buradiya river at a stretch of 15 meters long (Lat: 26.559429, Lon: 91.42327) I occurrence: 16/05/22 0 Baghbar - Niz Baghbar village Today one shiv temple is eroded away by the river Brahmaputra at Niz Baghb Moreover 4 nos of PMAY house also eroded due to the rapid erosion. The details of the houses are- House own ID 1.Rajib ch. Basumatary 1837153 2.Khagen Boro 1173865 3.Kandhuri Boro 2014087 4.Kamobak Boro 118. Report) 19-05-2022 30, Chenga - Kachumara K Approx. 18 bighas land eroded by the river Brahmaputra and 9 nos. houses were dan erosion, reported by Gaon Pradhan and lot mandal on dtd-18/05/2022 54 Biswanath - 1. Singimari 2. Bhojmari 3. Natungaon 4. Kumolia 5. Borbeel 6. Tengabari 1. Bank erosion observed at singimari. 17.05.2022 Lat- 26.674836, Long - 93.099541 2. Bank erosion observed at Phulbari to Bhojmari 1 26.66852872, Long- 93.08098334 3. Bank erosion observed at Biswanath to Natungaon .17.05.2022, Lat- 26.69 93.158871 5.Bank erosion observed at Kumolia Area on R/ Bank of river Brahmaputra 19.05.2022 Lat- 26.69 93.158871 5.Bank erosion observed at Borbeel, Oriya Basti area on L/ Bank of river Borgang 19.05.2022 Lat- 26.69 93.293993 6. Bank erosion observed at Tengabari area on R/ Bank of river Borgang 19.05.2022 Lat- 26.69 93.266963 (Report from Water Resource Division) 0, Naduar RC part - Bhojmari Bank erosion observed at phulbari to bhojmari area. 19-05-2022 Latitude26.66 26.667126N; Longitude 93.0809833E to 93.071357E 0. Halem - Madhya Chattrang Erosion observed on the right bank of river Chattrang at Madhya Chattrang by 30 (10 per report received from W.R. sub-division Abhayapuri. 0, Srijangram - Dubachuri At Du	th of 250 meters
long (Lat: 26.550085, Lon: 91.271539) Date of occurrence: 17/05/22 2. R/B embankment behind B.ed college by Mora Pagladia river at a stretch of 400 meters long (Lat: 26.53516, Lon: 91.359211) Date of occurrence: 16 embankment erosion caused by Buradiya river at a stretch of 15 meters long (Lat: 26.559429, Lon: 91.42327) loccurrence: 16/05/22 0 Baghbar - Niz Baghbar village Today one shiv temple is eroded away by the river Brahmaputra at Niz Baghb Moreover 4 nos of PMAY house also eroded due to the rapid erosion. The details of the houses are - House own ID 1.Rajib ch. Basumatary 1837153 2.Khagen Boro 1173865 3.Kandhuri Boro 2014087 4.Kamobak Boro 118. Report) 19-05-2022 30. Chenga - Kachumara K Approx. 18 bighas land eroded by the river Brahmaputra and 9 nos. houses were dan erosion, reported by Gaon Pradhan and lot mandal on dtd-18/05/2022 54 Biswanath - 1. Singimari 2. Bhojmari 3. Natungaon 4. Kumolia 5. Borbeel 6. Tengabari 1. Bank erosion obset to singimari.17.05.2022 Lat- 26.674836, Long - 93.099541 2. Bank erosion observed at Phulbari to Bhojmari 1 26.668852872, Long- 93.08098334 3. Bank erosion observed at Biswanath to Natungaon .17.05.2022, Lat-26.69 93.135871 5.Bank erosion observed at Rumolia Area on R/Bank of river Brahmaputra 19.05.2022, Lat-26.69 93.135871 5.Bank erosion observed at Borbeel, Oriya Basti area on I/Bank of river Borgang 19.05.2022 Lat-26.69 3.266963 (Report from Water Resource Division) 0, Naduar RC part - Bhojmari Bank erosion observed at phulbari to bhojmari area. 19-05-2022 Latitude26.66 26.667126N; Longitude 93.0809833E to 93.071357E 0, Halem - Madhya Chattrang Erosion observed at phulbari to bhojmari area. 19-05-2022 Latitude26.66 26.667126N; Longitude 93.0809833E to 93.071357E 0, Manikpur - Bhandra At Bhandra for a reach of about 700m on L/B of Aie due to bank erosion. Date of Incider report received from W.R. sub-division Abhayapuri. 0, Srijangram - Dubachuri At Dubachuri with affected reach of about 1000m due to severe bank erosion on	
by Mora Pagladia river at a stretch of 400 meters long (Lat: 26.53516, Lon: 91.359211) Date of occurrence: 16 embankment erosion caused by Buradiya river at a stretch of 15 meters long (Lat: 26.559429, Lon: 91.42327) I occurrence: 16/05/22 0 Baghbar - Niz Baghbar village Today one shiv temple is eroded away by the river Brahmaputra at Niz Baght Moreover 4 nos of PMAY house also eroded due to the rapid erosion. The details of the houses are- House own ID 1.Rajib ch. Basumatary 1837153 2.Khagen Boro 1173865 3.Kandhuri Boro 2014087 4.Kamobak Boro 118. Report) 19-05-2022 30, Chenga - Kachumara K Approx. 18 bighas land eroded by the river Brahmaputra and 9 nos. houses were dan erosion, reported by Gaon Pradhan and lot mandal on dtd-18/05/2022 54 Biswanath - 1. Singimari 2. Bhojmari 3. Natungaon 4. Kumolia 5. Borbeel 6. Tengabari 1. Bank erosion obseto to singimari.17.05.2022 Lat- 26.674836, Long - 93.099541 2. Bank erosion observed at Phulbari to Bhojmari 26.66852872, Long- 93.08098334 3. Bank erosion observed at Biswanath to Natungaon .17.05.2022, Lat-26.693.135871 5.Bank erosion observed at Borbeel, Oriya Basti area on I./ Bank of river Borgang 19.05.2022, Lat-26.93.266963 (Report from Water Resource Division) 0, Naduar RC part - Bhojmari Bank erosion observed at phulbari to bhojmari area. 19-05-2022 Latitude26.66 26.667126N; Longitude 93.0809833E to 93.071357E 0, Halem - Madhya Chattrang Erosion observed on the right bank of river Chattrang at Madhya Chattrang by 30 0 Manikpur - Bhandra At Bhandra for a reach of about 700m on L/B of Aie due to bank erosion. Date of Incider report received from W.R. sub-division Abhayapuri. 0, Srijangram - Dubachuri At Dubachuri with affected reach of about 1000m due to severe bank erosion on R/F Manas under Srijangram Circle . Date of incident 18.05.2022 as per report received from W.R. sub-division Al DATE: 17/05/2022 0	
Barpeta Moreover 4 nos of PMAY house also eroded due to the rapid erosion. The details of the houses are- House own ID 1.Rajib ch. Basumatary 1837153 2.Khagen Boro 1173865 3.Kandhuri Boro 2014087 4.Kamobak Boro 118-Report) 19-05-2022 30, Chenga - Kachumara K Approx. 18 bighas land eroded by the river Brahmaputra and 9 nos. houses were damerosion, reported by Gaon Pradhan and lot mandal on dtd-18/05/2022 54 Biswanath - 1. Singimari 2. Bhojmari 3. Natungaon 4. Kumolia 5. Borbeel 6. Tengabari 1. Bank erosion observed in singimari. 17.05.2022 Lat- 26.674836, Long - 93.099541 2. Bank erosion observed at Phulbari to Bhojmari 1 26.66852872, Long- 93.08098334 3. Bank erosion observed at Biswanath to Natungaon .17.05.2022, Lat-26.6 93.135871 5.Bank erosion observed at Kumolia Area on R/ Bank of river Brahmaputra 19.05.2022, Lat-26.9 33.135871 5.Bank erosion observed at Tengabari area on L/ Bank of river Borgang 19.05.2022 Lat-26.9 3.266963 (Report from Water Resource Division) 0, Naduar RC part - Bhojmari Bank erosion observed at phulbari to bhojmari area. 19-05-2022 Latitude26.66 26.667126N; Longitude 93.0809833E to 93.071357E 0, Halem - Madhya Chattrang Erosion observed on the right bank of river Chattrang at Madhya Chattrang by 30 0 Manikpur - Bhandra At Bhandra for a reach of about 700m on L/B of Aie due to bank erosion. Date of Incide per report received from W.R. sub-division Abhayapuri. 0, Srijangram - Dubachuri At Dubachuri with affected reach of about 1000m due to severe bank erosion on R/F Manas under Srijangram Circle . Date of incident 18.05.2022 as per report received from W.R. sub-division Al Tamu Gaon Erosion at 1st KM of Kanu lukhurakhan road by flood of Tiok River. (Pwd Roz DATE:17/05/2022 0	/05/22 3. R/B Date of
Biswanath - 1. Singimari 2. Bhojmari 3. Natungaon 4. Kumolia 5. Borbeel 6. Tengabari 1. Bank erosion obset to singimari.17.05.2022 Lat- 26.674836, Long - 93.099541 2. Bank erosion observed at Phulbari to Bhojmari 1 26.66852872, Long- 93.08098334 3. Bank erosion observed at Biswanath to Natungaon .17.05.2022, Lat- 26.69 3.16531329 4. Bank erosion observed at Kumolia Area on R/ Bank of river Brahmaputra 19.05.2022, Lat- 26.93.135871 5.Bank erosion observed at Borbeel, Oriya Basti area on L/ Bank of river Borgang 19.05.2022 Lat- Long- 93.293993 6. Bank erosion observed at Tengabari area on R/ Bank of river Borgang 19.05.2022 Lat- 26.93.266963 (Report from Water Resource Division) 0, Naduar RC part - Bhojmari Bank erosion observed at phulbari to bhojmari area. 19-05-2022 Latitude26.66 26.667126N; Longitude 93.0809833E to 93.071357E 0, Halem - Madhya Chattrang Erosion observed on the right bank of river Chattrang at Madhya Chattrang by 30 0 Manikpur - Bhandra At Bhandra for a reach of about 700m on L/B of Aie due to bank erosion. Date of Incidence of the per report received from W.R. sub-division Abhayapuri. 0, Srijangram - Dubachuri At Dubachuri with affected reach of about 1000m due to severe bank erosion on R/E Manas under Srijangram Circle . Date of incident 18.05.2022 as per report received from W.R. sub-division Ab DATE:17/05/2022 0	er name PMAY
to singimari.17.05.2022 Lat- 26.674836, Long - 93.099541 2. Bank erosion observed at Phulbari to Bhojmari 1 26.66852872, Long- 93.08098334 3. Bank erosion observed at Biswanath to Natungaon .17.05.2022, Lat-26.69 93.16531329 4. Bank erosion observed at Kumolia Area on R/ Bank of river Brahmaputra 19.05.2022, Lat-26.99 93.135871 5.Bank erosion observed at Borbeel, Oriya Basti area on L/ Bank of river Borgang 19.05.2022 Lat-Long- 93.293993 6. Bank erosion observed at Tengabari area on R/ Bank of river Borgang 19.05.2022 Lat-26.93.266963 (Report from Water Resource Division) 0, Naduar RC part - Bhojmari Bank erosion observed at phulbari to bhojmari area. 19-05-2022 Latitude26.66 26.667126N; Longitude 93.0809833E to 93.071357E 0, Halem - Madhya Chattrang Erosion observed on the right bank of river Chattrang at Madhya Chattrang by 30 0 Manikpur - Bhandra At Bhandra for a reach of about 700m on L/B of Aie due to bank erosion. Date of Incide per report received from W.R. sub-division Abhayapuri. 0, Srijangram - Dubachuri At Dubachuri with affected reach of about 1000m due to severe bank erosion on R/E Manas under Srijangram Circle . Date of incident 18.05.2022 as per report received from W.R. sub-division Ab DATE:17/05/2022 0	aged due to
93.266963 (Report from Water Resource Division) 0, Naduar RC part - Bhojmari Bank erosion observed at phulbari to bhojmari area. 19-05-2022 Latitude26.66 26.667126N; Longitude 93.0809833E to 93.071357E 0, Halem - Madhya Chattrang Erosion observed on the right bank of river Chattrang at Madhya Chattrang by 30 0 Manikpur - Bhandra At Bhandra for a reach of about 700m on L/B of Aie due to bank erosion. Date of Incidence per report received from W.R. sub-division Abhayapuri. 0, Srijangram - Dubachuri At Dubachuri with affected reach of about 1000m due to severe bank erosion on R/F Manas under Srijangram Circle. Date of incident 18.05.2022 as per report received from W.R. sub-division Abhayapuri. O, Sapekhati - No.1 Kanu Gaon Erosion at 1st KM of Kanu lukhurakhan road by flood of Tiok River. (Pwd Road DATE:17/05/2022 0	7.05.2022 Lat- 8860483, Long- 681659, Long- 26.825918,
Bongaigaon Manikpur - Bhandra At Bhandra for a reach of about 700m on L/B of Aie due to bank erosion. Date of Incide per report received from W.R. sub-division Abhayapuri. 0, Srijangram - Dubachuri At Dubachuri with affected reach of about 1000m due to severe bank erosion on R/F Manas under Srijangram Circle . Date of incident 18.05.2022 as per report received from W.R. sub-division Al Charaideo Sapekhati - No.1 Kanu Gaon Erosion at 1st KM of Kanu lukhurakhan road by flood of Tiok River. (Pwd Road DATE: 17/05/2022 0	5852872N to
Manas under Srijangram Circle . Date of incident 18.05.2022 as per report received from W.R. sub-division Al Charaideo Sapekhati - No.1 Kanu Gaon Erosion at 1st KM of Kanu lukhurakhan road by flood of Tiok River.(Pwd Roa DATE:17/05/2022 0	
DATE:17/05/2022 0	hayapuri. 0
Erosion Dhuhri - Silohagri Pt-Lunder Dhuhri Rev. Circle I recently an erosion have taken place due to raising of water	
Brahmaputra. The details of the area eroded are given below 1. Name of Village:- Silghagri Pt-I 2. Date of inci 2022 to 19-05-2022 3. Land eroded:- Land measuring around 6 Bigha 0 Katha 0 Lessa 0, Bilasipara - At vill:- Sonaluguri at Vill: Sonaluguri under Bilasipara Revenue Circle. During the enquiry, it h that the riverine area of River Hell is getting eroded badly. The details of the area eroded are given below 1. Na Sonaluguri 2. Date of incident:- 16-05-2022 and 18-05-2022 3. GPS co-ordinates:- Lat:- 26. 359836N & Longi E 4. Land eroded:- Land measuring around Bigha 02 Katha 10 Lessa 5. Population:- 13 nos 13, Agamoni - Village Kaimari Pt-I under Kaimari GP under Agomani Rev. Circle. • Name of the village: Kaimari GP. • Name of River: Gangadhar. • Date of Incident: 15th May'2022 to 19th May'2022. • Time: 1.00	as been found ume of Village:- tude:- 90.168403 ri Pt-I under PM. • GPS Co-
Goalpara ordinates: Lat: 26.307824, Long: 89.803718 • Land: 0B-1K-10L. • Population and household damage: No dam Matia - Baladmari Char Pt-IV Left bank erosion of river Jaljali at Baladmari Char Pt-IV. Total length affected (approx.) as on 19/05/2022 0	
Kamrup Rangia - Rangia, Ward No. 8 Erosion is taking place for a stretch of about 250 m near Solmari Markaz, Rang on 18.05.2022 as per report received from AE, Water Resource Dept., Rangia. 0	ia Town, W/N-8
Kamrup (M) Chandrapur - 1)hatisila near ganesh mandir 2) tatimara Information received from water resource on 17.05.2 (M) km approx both Hatisila longitude:- 91.887997,latitude:- 26.219384 Tatimara longitude:- 91.917294 latitude:-	
Bihpuria - 1)Kathalguri Mishing gaon 2)Bongalmora PGR 3)No. 2 Dhagharia-Madhupur area 1)Active erosi L/B of Dikrong river for a reach of 200m as reported by AE, WRD, Bihpuria on 19th May 2022, long 93.9273 2)Active erosion observed near the embankment at Bongalmora PGR, approx. 12 m of land eroded as reported Lot Mandal on 19/05/2022, Lat 227.05392, long 93.92726 3) Active erosion observed at No. 2 Dahgharia-Mad approx. 10 Bighas of land has been eroded since 17th May 2022, lat-26.980224, long-93.97548 0, Kadam - Dirgha Majgaon(Dumba Basti), No 1 Boginadi P.G.R.(Khurachuk) and Bodhakara (Moghuachuk) occurred due to the increasing of water level of the river Dirgha and Subansiri. eroded area 1 hectare (Approx) in Majgaon (Dumba Basti), 1 hectare (Approx) in No1 Boginadi PGR (Khurachuk) and 0.13 hectare(Approx) in I Moghuachuk from 16/05/2022 to 19/05/2022. 0	
Majuli - 1. Kolani gaon under Luit-Khabolu GP 1. Erosion occured at Kolangi gaon under Luit-Khabolu GP 1. Land area eroded: Lentgh- 1.5 km, Breadth- 1.5 mtr. Lat-94.16465 Long -27.04418 0	on observed on l, lat-27.053697 by concerned hupur area Erosion is n Dirgha
Barkhetri - bhangnamri river bank erosion of river brahmaputra at bhangnamari. length 50m approx. date 19, of families and 3 fair price shps shifted due to erosion. Jio & Airtel Mobile tower affected due to erosion. 0, Nalbari - vill_ Khat Katara As per WR Deptt Report on 18.05.2022, erosion took place at village khat katara river Pagaldia. Approximate length of erosion is 65.00 Meter 0, Ghograpar - Keherua, 4 No. Sagarkuchi, Borajol 1. As per information received from W.R department erosion.	on observed on l, lat-27.053697 by concerned hupur area Erosion is n Dirgha

		the L/B of river Pagladia on 19/05/2022 at village Keherua (Near Sonamati Ghat), Length - 200 M, Lat - 26.5134, Long - 91.4953 2. As per information received from W.R department erosion have seen at the L/B of river Pagladia on 19/05/2022 at
		village4 No. Sagarkuchi (Dekatola), Length - 150 M, Lat - 26.5151, Long -91.5026 3. As per information received from W.R department erosion have seen at the R/B of river Noona on 19/05/2022 at village Borajol (Noonapar), Length - 250 M, Lat -
		26.4740, Long -91.5730 0
	Sivasagar	Sivsagar - Deogharia Sloughing and river erosion has been occurred from 16-05-2022 to 19-05-2022 for a length of 10 Mtrs. at Dikhow left bank from Namdungoutfall to Dikhow at Deogharia under Sivasagar Revenue Circle. As per report received from WR Department, Sivasagar 0, Demow - Bairagibor Village Erosion at Sepon-Sunpura road near Desang river for a length of 15.4 metre due to heavy rain from 18/5/2022 to 19/5/2022 under Demow Revenue Circle. The report has been submitted by PWD(Roads) division ,Demow.
		0
	Sonitpur	Dhekiajuli - Monmohinipur Tea Estate Heavy erosion on going along the Monmohinipur TE due to rising water of the Sopai (Gadhajuli) river leading to heavy damage of Tea Estate land and property. (6 numbers of tea garden katcha quarters washed away). length of damage aprox 300mtrs. Dated 18.5.22 0
	South Salmara	Mankachar - Berabhanga PT-II As per reported water resource department and APDCL department has been eroded 2 nos. of Electricity Pillar due to erosion river site at Berabhanga Pt-II. Appx. 300M. 0
	Tamulpur	Goreswar - East Bank of River Borolia at Village Lahapara 17/05/2022 erosion occurred at the East Bank of River Borolia at Village Lahapara approximate damage as reported by Water Resource department 300m. Palliative measures taken by Water Resource. No erosion reported on 19/05/2022. 0
		Sadiya - 1.Majgaon (Amarpur) 2. Koilabasti 1. River Bank erosion is being observed at Majgaon (Amarpur) on the North Bank of River datung since 12/5/2022 till 19/5/2022. As per information received from concerned Gaon Pradhan, the affected stretch is about 280m. 2. Active erosion is reported from Koilabasti area by Kundil river since 12/5/2022 till 19/5/2022. As per report received from the WR department and concerned Gaon Pradhan, the affected stretch is about 50m. (Long:95°42'45.2"E, Lati:27°50'48.8"N) 0,
	Tinsukia	Doomdooma - 1. Village: Phelai NC (Nawkata NC), 2. Village: No. 3 Kordoiguri (Goriyating) 1. Severe erosion is being observed at Phelai (Nawkata) area on the left Bank of River Brahmaputra since 5/04/2022 till 19/05/2022. The affected stretch is about 1500 m. 10 m offset remains as of now from the Brahmaputra Embankment. (Long: 95.523457, Lati:27.745786) 2. River Bank erosion is being observed at No. 3 Kordoiguri on the left Bank of River Dangari since 2/04/2022 till 19/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 200 m in
	Udalguri	length.(Long: 95.468184, Lati: 27.650410),Population affected 122. 0 Udalguri - 1. Madhabgoahain, 2. Koupati 1. Erosion Ocured on Left Bank from Moradhansiri river at Madhabgohain village around 150m on 19.5.2022. GPS - Lat - 26.64238 Long- 92.20051. 2. Erosion and overtoping of flood water from river Moradhansir on the both bank at Kauopati village around 500m on 19.5.2022. GPS - Lat - 26.57793 Long- 92.24349 0, Mazbat - 1. No. 2 Mazgaon 2. Khagrabil 1. Erosion occurred on L/B from river Pagla at village No.2 Mazgaon on 18-5-2022(26.4416,92.164868) length- 200m 2. Erosion occurred on L/B from river Pagla at village Khagrabil on 18-5-2022(26.462966, 92.13374) length- 220m 0, Kalaigaon - No 2 Singrimari Severe erosion in the L/B of river Noa on 19/05/2022 covering a length of around 250 meters and breadth of 4 meters due to heavy current of the river. 50, Harisinga - 1. Tangla Municipalty Ward No.2, (2) Atterikhat Jungle village near Milan LP school. (3) Lakhipara (Niz Harisinga) 1. Erosion occurred at Tangla Municipalty ward no.2 by river Naika approximate length 40ft and breath 25m on 19th May 2022. immediate restoration needed from the concern department otherwise house of Mr Pranjit Boro may demolished very soon. (Longitude 91.5436 / Latitude 26.3911) 2. An oblique channel has developed of U/S of Milan LP school in Atterikhat Jungle village by the river Suklai approximate 100 ft. on 16th may 2022. Immediate measures should be take by concern department otherwise the new river channel which is only 30ft. away from the School building of Milan LP school. so, anytime the school may demolished very soon. (Longitude 91.7984 / Latitude 26.7263) 3. Erosion occurred on R/B of Lakhi river at Lakhipara village approximate 250 m. on 18/05/2022. (Longitude 91.9956/ Longitude 26.7213) 0
	District	Details
Landslide	Dima- Hasao	Haflong - Huonveng, ND Raji and many more villages Assessment under process 0
	District	Details
	Darrang	Mangaldoi - Mangaldai town Ward No 1,2,3,4,5,6,7&8 The people affected due to waterlogging and flooding of river Bega as on dated 19-05-2022. 1200
Urban Flood	Jorhat	Jorhat East - 3 no block and 9 no block Due to heavy rainfall Urban Water logging at DCB road and Sonari Gaon on 19/05/2022 16
	Kamrup (M)	Dispur - Hatigaon, Wireless, Keraikuchi, Kahilipara Partial Water-logging took place on 19/05/2022 0
		_