

FRIMS Assam



Flood Reporting And Information Management System

Particulars	Situation as	on 18-06-2		Daily Flood Report as on 24 hours)	10-00-2022 at 4.00 F.W				
Rivers flowing above	Rivers flowi			Beki (Road Bridge), Mar (Nh Road Crossing), Ko	Beki (Road Bridge), Manas (Nh Road Crossing), Pagladiya (Nt Road Crossing), Puthimari (Nh Road Crossing), Kopili (Dharamtul), Jia-Bharali (Nt Road Crossing), Brahmaputra (Dhubri; Tezpur; Neamatighat)				
Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowi flood level	ng above h	ighest	Kopili (Kampur)					
1111)	No. of Districts Affected	Name of	Flood Affe	cted Districts	Name of Urban Flood Districts				
District Affected	32	Bongaiga Dhemaji, Goalpara (M), Karl Kokrajha Nagaon,	on, Cachar, Dhubri, Dil , Golaghat, Di Anglong r, Lakhimpu Nalbari, Siv	a, Biswanath, Chirang, Darrang, brugarh, Dima-Hasao, Hojai, Kamrup, Kamrup West, Karimganj, ır, Majuli, Morigaon, asagar, Sonitpur, South Finsukia, Udalguri	Barpeta, Darrang, Goalpara, Hailakandi, Kamrup (M), Nalbari, Udalguri				
No. Of Revenue Circles Affected	118		r						
	District	Total	Revenue	Circle					
	Bajali	2	Bajali, Sa	Bajali, Sarupeta					
В	Baksa	5	Baska, Ja	Baska, Jalah, Baganpara, Barnagar RC part, Barama					
	Barpeta	6	Baghbar,	Kalgachia, Chenga, Barpe	eta, Barnagar, Sarthebari				
	Biswanath	1	Halem						
	Bongaigao n	5	Manikpu	Manikpur, Boitamari, Bongaigaon, Dangtol, Srijangram					
	Cachar	5	Silchar, k	Silchar, Katigorah, Udharbond, Lakhipur, Sonai					
	Chirang	3		Sidli, Bijni, Bengtal					
	Darrang	4		Patharighat, Mangaldoi, S					
	Dhemaji	4		Gogamukh, Sissiborgaon,					
	Dhubri	7	Dhubri, C	Gauripur, South Salmara Pa	art, Bilasipara, Golakganj, Athani, Chapar				
	Dibrugarh	3	Naharkat	ia, Chabua, Dibrugarh We	st				
	Dima- Hasao	1	Haflong						
Name Of	Goalpara	4	Matia, Ba	ia, Balijana, Lakhipur, Rongjuli					
Revenue	Golaghat	1	Khumtai						
Circles	Hailakandi	1	Hailakan						
Affected	Hojai	3	1	ojai, Doboka					
	Kamrup	9	Rangia, E	Boko, Chaygaon, Kayan, G	oroimari, Kamalpur, Palashbari, North Ghy, Hajo				
	Kamrup (M)	3	Sonapur,	Guwahati, Dispur					
	Karbi Anglong West	1	Donkamo	okam					
	Karimganj	5	Badarpur	, Patherkandi, Karimganj,	Nilambazar, RK Nagar				
	Kokrajhar	5		uri, Gossaigaon, Dotma, K					
	Lakhimpur	6			North Lakhimpur, Kadam, Nowboicha				
	Majuli	2		Ijani Majuli					
	Morigaon	4		n, Mayong, Laharighat, M					
	Nagaon	5		Samaguri, Raha, Kampur,					
	Nalbari	7	_ ·		hi, Barkhetri, Paschim Nalbari, Barbhag				
	Sivasagar	2	Demow,						
	Sonitpur	4	Thelamar	a, Chariduar, Dhekiajuli, T	Teznur				

	South Salmara	2	Mankach	ar, South Salı	mara					
	Tamulpur	2	Goreswai	, Tamulpur						
	Tinsukia	1	Doomdoo							
	Udalguri	5			Mazbat, Kalai	gaon, Harisinga				
	Total	118								
	District	Total	Revenue	Circle						
	Bajali	173	(Bajali	95), (Sarupe	eta 78)					
	Baksa	67	(Baska	17), (Jalah	7), (Baganp	ara 7), (Barnagar RC par	rt 20), (Bara	ma 16)		
	Barpeta	584	(Baghbar	Baghbar 121), (Kalgachia 99), (Chenga 50), (Barpeta 145), (Barnagar 34), (Sarthebari						
	Biswanath	5	(Halem	5)						
	Bongaigao n	147	(Manikp	ur 72), (Bo	oitamari 3), ((Bongaigaon 4), (Dangto	ol 36), (Srija	angram 32)		
	Cachar	90	(Silchar	11), (Katig	orah 64), (I	Udharbond 4), (Lakhipur	: 5), (Sonai	6)		
	Chirang	29), (Bengtal			,		
	Darrang	374	(Dalgaor	1 92), (Path	narighat 59),	(Mangaldoi 165), (Sipa	ijhar 58)			
	Dhemaji	85	(Dhemaj	i 5), (Goga	mukh 32), (Sissiborgaon 14), (Jona	i 34)			
	Dhubri	439	(Dhubri		pur 44), (S	outh Salmara Part 83), (1		1), (Golakganj 8), (
	Dibrugarh	7				Pibrugarh West 1)				
	Dima-				1 // (2	5				
	Hasao	11	(Haflong	[11]						
	Goalpara	284	(Matia '	77), (Balijar	na 99), (Lak	thipur 94), (Rongjuli 14	1)			
	Golaghat	4	(Khumta	i 4)						
	Hojai	97	(Lanka	15), (Hojai	58), (Dobol	ka 24)				
	Vammun	283	(Rangia	78), (Boko	17), (Chay	gaon 5), (Kayan 28), (Goroimari 1:	5), (Kamalpur 76), (
Villages	Kamrup	263	Palashbai	ri 3), (Nort	h Ghy 23), ((Hajo 38)				
Affected	Kamrup (M)	32	(Chandra	(Chandrapur 8), (Sonapur 5), (Guwahati 7), (Azara 3), (Dispur 9)						
	Karbi									
	Anglong	10	(Donkan	nokam 10)						
	West									
	Karimganj	152				, (Karimganj 3), (Nilam				
	Kokrajhar	178				5), (Dotma 34), (Kokraj				
	Lakhimpur	166		ri 10), (Bil 12), (Nowl		Dhakuakhana 6), (Naray	yanpur 10), (North Lakhimpur 53),		
	Majuli	41	(Majuli	32), (Ujani	Majuli 9)					
	Morigaon	108	(Bhuraga	on 11), (M	Iayong 74),	(Laharighat 2), (Moriga	on 21)			
	Nagaon	150				aha 29), (Kampur 102)		2)		
	Nalbari	364		oar 71), (Ti 25), (Barbha		albari 71), (Banekuchi 1	19), (Barkhet	ri 115), (Paschim		
	Sivasagar	25		6), (Sivsag	<u> </u>					
	Sonitpur	118	(Thelama	ara 33), (C	hariduar 30), (Dhekiajuli 26), (Tezp	our 29)			
	South					•				
	Salmara	55	(Mankac	nar 37), (S	outh Salmara	[18)				
	Tamulpur	46		ar 29), (Ta	mulpur 17)					
	Tinsukia	18		ooma 18)						
	Udalguri	149	(Khairab	ari 23), (U	dalguri 38),	(Mazbat 25), (Kalaigao	n 49), (Hari	singa 14)		
	Total	4291								
	District	Male	Female	Children	Total Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details		
	Bajali	178500	139200	34850	352550	(Bajali 160000), (520.00	(Bajali 0.00), (
	Dajan	170300	137200	J-0J0	332330	Sarupeta 192550)	320.00	Sarupeta 520.00)		
Population			(Barnagar RC part (Barnagar RC part							
And Crop	D 1	1.4001	11151	7.50	22010	22064), (Baska 1140	740.07	498.00), (Baska		
Area	Baksa	14001	11151	7658	32810), (Jalah 3317), (748.07	35.07), (Jalah 147.00		
Affected						Baganpara 4855), (), (Baganpara 43.00),		
						Barama 1434)		(Barama 25.00)		
						(Kalgachia 105700), (Chenga 121150), ((Kalgachia 1822.50), (Chenga 1256.00), (
	Barpeta	306120	267810	157114	731044	Barpeta 105228), (13771.33	Barpeta 6230.00), (
						Barnagar 9865), (Barnagar 1757.50), (
	<u>I</u>	<u>I</u>	<u>I</u>							

					Sarthebari 335837), (Sarthebari 1860.33), (
D : 1	0.51	602	5.45	2001	Baghbar 53264)	20.50	Baghbar 845.00)
Biswanath	851	693	547	2091	(Halem 2091)	38.50	(Halem 38.50)
Bongaigao n	45834	40938	26140	112912	(Manikpur 103609), (Bongaigaon 0), (Dangtol 0), (Srijangram 8718), (Boitamari 585)	2413.50	(Manikpur 1946.00), (Bongaigaon 196.50), (Dangtol 271.00), (Srijangram 0.00), (Boitamari 0.00)
Cachar	9805	8759	4343	22907	(Silchar 4570), (Katigorah 17871), (Udharbond 96), (Lakhipur 80), (Sonai 290)	0.00	(Silchar 0.00), (Katigorah 0.00), (Udharbond 0.00), (Lakhipur 0.00), (Sonai 0.00)
Chirang	5294	5328	4150	14772	(Bijni 9082), (Sidli 2808), (Bengtal 2882)	2871.50	(Bijni 2871.50), (Sidli 0.00), (Bengtal 0.00)
Darrang	145525	126716	81971	354212	(Dalgaon 122440), (Patharighat 75294), (Mangaldoi 120007), (Sipajhar 36471)	7463.70	(Dalgaon 3795.50), (Patharighat 1181.20), (Mangaldoi 1572.00), (Sipajhar 915.00)
Dhemaji	13454	12822	6558	32834	(Gogamukh 17117), (Sissiborgaon 7721), (Jonai 4462), (Dhemaji 3534)	4521.50	(Gogamukh 510.00), (Sissiborgaon 405.00), (Jonai 3565.50), (Dhemaji 41.00)
Dhubri	7805	7970	4564	20339	(Dhubri 0), (Gauripur 0), (South Salmara Part 12655), (Bilasipara 6545), (Golakganj 66), (Athani 503), (Chapar 570)	4870.70	(Dhubri 478.00), (Gauripur 265.30), (South Salmara Part 2069.00), (Bilasipara 0.00), (Golakganj 0.00), (Athani 1040.20), (Chapar 1018.20)
Dibrugarh	2883	2213	1593	6689	(Chabua 6667), (Dibrugarh West 22), (Naharkatia 0)	6.14	(Chabua 5.70), (Dibrugarh West 0.00), (Naharkatia 0.44)
Goalpara	106795	78708	35472	220975	(Balijana 93322), (Lakhipur 122317), (Matia 5336), (Rongjuli 0)	1400.50	(Balijana 762.50), (Lakhipur 0.00), (Matia 614.00), (Rongjuli 24.00)
Golaghat	0	0	0	0	(Khumtai 0)	26.00	(Khumtai 26.00)
Hojai	63889	47920	13526	125335	(Lanka 12494), (Hojai 88148), (Doboka 24693)	3344.00	(Lanka 791.00), (Hojai 2227.00), (Doboka 326.00)
Kamrup	87703	73221	57229	218153	(Rangia 50242), (Chaygaon 0), (Kayan 38122), (Boko 0), (Goroimari 0), (Kamalpur 26362), (Palashbari 0), (North Ghy 463), (Hajo 102964)	3737.85	(Rangia 594.00), (Chaygaon 144.00), (Kayan 358.00), (Boko 10.45), (Goroimari 165.50), (Kamalpur 492.90), (Palashbari 198.00), (North Ghy 58.00), (Hajo 1717.00)
Kamrup (M)	8110	6095	358	14563	(Chandrapur 0), (Sonapur 0), (Guwahati 863), (Azara 0), (Dispur 13700)	219.00	(Chandrapur 0.00), (Sonapur 219.00), (Guwahati 0.00), (Azara 0.00), (Dispur 0.00)
Karbi Anglong West	5285	5286	5736	16307	(Donkamokam 16307)	0.00	(Donkamokam 0.00)
Karimganj	27491	18362	6401	52254	(RK Nagar 30425), (Badarpur 50), (Patherkandi 1335), (Karimganj 3151), (Nilambazar 17293)	200.00	(RK Nagar 200.00), (Badarpur 0.00), (Patherkandi 0.00), (Karimganj 0.00), (Nilambazar 0.00)
Kokrajhar	24771	20763	9158	54692	(Bagribari 22829), (717.79	(Bagribari 284.49), (

						Bhawraguri Gossaigaon Dotma 237	987), (705), (Bhawraguri 101.80), (Gossaigaon 0.00), (Dotma 331.50), (
	Lakhimpur	54316	36830	22688	113834	Kokrajhar (Narayanpu North Lakh 51619), (N 37898), (S 5257), (Bi 17271), (Dhakuakhar Kadam 11	ur 0), (impur Iowboicha ubansiri hpuria na 629), (1232.95	Kokrajhar 0.00) (Narayanpur 0.00), (North Lakhimpur 161.00), (Nowboicha 313.30), (Subansiri 317.00), (Bihpuria 339.80), (Dhakuakhana 30.00), (Kadam 71.85)
	Majuli	0	0	0	0	(Majuli 0 Majuli 0)), (Ujani	631.37	(Majuli 539.02), (Ujani Majuli 92.35)
	Morigaon	0	0	0	0	(Bhuragaon Mayong 0 Morigaon Laharighat), (0), (1707.00	(Bhuragaon 311.00), (Mayong 750.00), (Morigaon 545.00), (Laharighat 101.00)
	Nagaon	84443	75599	81149	241191	(Samaguri Raha 3386 Kampur 20 Nagaon 15 Kaliabor 3	53), (05026), (548), (5174.74	(Samaguri 88.00), (Raha 273.74), (Kampur 4730.00), (Nagaon 56.00), (Kaliabor 27.00)
	Nalbari	70124	60509	34773	165406	(Ghograpar (Tihu 144 Nalbari 12 Banekuchi Paschim Na 31329), (B 11500), (B	r 41171), 70), (500), (43820), (dbari Barbhag	6531.30	(Ghograpar 606.00), (Tihu 367.00), (Nalbari 338.10), (Banekuchi 165.00), (Paschim Nalbari 554.00), (Barbhag 83.50), (Barkhetri 4417.70)
	Sivasagar	46	51	21	118	(Sivsagar Demow 0		148.50	(Sivsagar 80.00), (Demow 68.50)
	Sonitpur	23915	21389	24639	69943	(Thelamara Chariduar Dhekiajuli Tezpur 36	57261), (7365), (2773.80	(Thelamara 683.00), (Chariduar 435.00), (Dhekiajuli 1465.10), (Tezpur 190.70)
	South Salmara	2823	2689	1332	6844	(Mankacha South Salm	ır 43), (405.00	(Mankachar 405.00), (South Salmara 0.00)
	Tamulpur	12329	10406	4230	26965	(Goreswar Tamulpur		220.00	(Goreswar 0.00), (Tamulpur 220.00)
	Tinsukia	4455	3682	2641	10778	(Doomdoo:	ma 10778	302.88	(Doomdooma 302.88
	Udalguri	36452	25393	17399	79244	(Khairabar Udalguri 1 Mazbat 95 Kalaigaon Harisinga	1035), (25), (49671), (458.20	(Khairabari 0.00), (Udalguri 0.00), (Mazbat 0.00), (Kalaigaon 458.20), (Harisinga 0.00)
	Total	134301 9	111050 3	646240	3099762			66455.82	
	District	Total	Relief Ca					ribution Cent	res
	Bajali	43		33, Saruper			1(Bajali 0,	, Sarupeta 1)	
	Baksa	17	0)		ara 1, Baram		6(Baska 0	, Baganpara 1	, Barama 1, Jalah 4)
	Barpeta	63	57(Cheng	ga 18, Barpe	eta 33, Sartho	ebari 6)	6(Chenga	3, Barpeta 0,	Sarthebari 3)
Relief	Bongaigao n	29	24(Manil	apur 3, Boit	amari 3, Srij	angram 18)	5(Manikpur	r 5, Boitamari	i 0, Srijangram 0)
Camps /	Cachar	4		2, Katigora				1, Katigorah (
Centres	Chirang	20		12, Bengtal		11		Bengtal 0, Sie	
Opened	Darrang	43	Sipajhar	3)	righat 3, Mar		Sipajhar 4)	hat 3, Mangaldoi 0,
	Dhemaji	23	0(Dhema Jonai 0)	,	ukh 0, Sissi	oorgaon 0,	23(Dhemaji Jonai 4)	i 2, Gogamuk	h 13, Sissiborgaon 4,
	Dhubri	42	42(Bilasi	para 33, Go	lakganj 1, A	thani 4,	0(Bilasipara	a 0, Golakgan	ıj 0, Athani 0, Chapar
	Dima-	26	Chapar 4				0) 1(Haflong	1)	
<u> </u>	Dillia-	20	23(11a110)	15 43)			1(114110118	1)	

	Hasao									
	Goalpara	72	44(Matia 3, Balijana 20, Lakhipu				Lakhipur 21)	1		
	Hojai	56	46(Hojai 34, Doboka 12, Lanka			10(Hojai 0, Doboka 4, Lanka 6)				
	Kamrup	25	15(Rangia 7, Kamalpur 3, North (Hajo 3, Kayan 0)		10(Rangia 1, Kamalpur 0, North Ghy 2, Hajo 1, Kayan 6)					
	Kamrup (M)	12	3(Guwahati 2, Dispur 1)	9(Guwahati	i 4, Dispur 5	5)				
	Karbi Anglong West	5	0(Donkamokam 0)	5(Donkamo	okam 5)					
	Karimganj	8	2(Badarpur 1, Patherkandi 1, Kari	imganj 0)	6(Badarpur	0, Patherkan	di 0, Karimga	ınj 6)		
	Kokrajhar	37	28(Bhawraguri 1, Gossaigaon 4, 1 Kokrajhar 6, Bagribari 9)	Dotma 8,		uri 8, Gossaig 0, Bagribari	gaon 1, Dotma 0)	a 0,		
	Lakhimpur	32	0(Subansiri 0, Bihpuria 0, Dhakua North Lakhimpur 0, Kadam 0, No 0)				ia 6, Dhakuak lam 1, Nowbo			
	Nagaon	13	13(Raha 2, Kampur 7, Nagaon 4	.)	0(Raha 0,	Kampur 0, N	agaon 0)			
	Nalbari	81	74(Ghograpar 2, Tihu 18, Nalbari Banekuchi 17, Paschim Nalbari 1 11)	0, Barbhag		ar 3, Tihu 0, Nalbari 0, Ba	Nalbari 4, Ba arbhag 0)	nnekuchi		
	Sonitpur	52	2(Chariduar 1, Dhekiajuli 1, Thel Tezpur 0)	amara 0,	50(Charidu Tezpur 1)	ar 21, Dhekia	ajuli 11, Thela	amara 17,		
	Tamulpur	36	17(Goreswar 7, Tamulpur 10)			ar 11, Tamul _l	our 8)			
	Tinsukia	4	4(Doomdooma 4)		0(Doomdoo					
	Udalguri	73	33(Udalguri 11, Mazbat 9, Kalaig Harisinga 4, Khairabari 0)	gaon 9,	Harisinga	i 0, Mazbat 5, Khairabari	0, Kalaigaon 5)	30,		
	Total	816	514		302	1		_		
	District	Total	Revenue Circlewise	Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y		
	Bajali	5722	(Bajali 4060), (Sarupeta 1662)	2418	2633	578	77	16		
	Baksa	1243	(Jalah 0), (Barnagar RC part 0), (Baska 964), (Baganpara 75), (Barama 204)	417	510	306	10	0		
	Barpeta	26537	(Baghbar 0), (Kalgachia 0), (Chenga 2311), (Barpeta 23603), (Barnagar 0), (Sarthebari 623)	10608	8947	6959	22	1		
	Bongaigao n	4911	(Bongaigaon 0), (Dangtol 0), (Srijangram 3671), (Manikpur 760), (Boitamari 480)	2455	1889	520	47	0		
Inmates In	Cachar	111	(Silchar 46), (Katigorah 65), (Udharbond 0), (Lakhipur 0), (Sonai 0)	49	36	26	0	0		
Relief Camps	Chirang	3603	(Sidli 0), (Bijni 3440), (Bengtal 163)	1597	1268	715	23	0		
Camps	Darrang	7156	(Dalgaon 1670), (Mangaldoi 4474), (Sipajhar 511), (Patharighat 501)	2655	2465	2011	24	1		
	Dhubri	7290	(Dhubri 0), (Gauripur 0), (South Salmara Part 0), (Bilasipara 6545), (Athani 503), (Golakganj 66), (Chapar 176)	2261	2893	2115	21	0		
	Dima- Hasao	1630	(Haflong 1630)	583	620	369	57	1		
	Goalpara	12132	(Balijana 5945), (Lakhipur 5603), (Rongjuli 0), (Matia 584)	5336	4072	2588	116	20		
	Hojai	37785	(Lanka 0), (Hojai 35404), (Doboka 2381)	19881	17142	755	4	3		
	Kamrup	3714	(Boko 0), (Chaygaon 0), (Kayan 0), (Goroimari 0), (Palashbari 0), (Rangia 2069), (Kamalpur 588), (North Ghy	2044	1145	511	14	0		

			174\ /**	· 1000						
			174), (Ha	-						
	Kamrup			pur 0), (Son						
	^	87	(Guwaha	ti 77), (Azar	ra 0),	42	26	19	0	0
	(M)		(Dispur	10)						
				ndi 12), (Ka	arimgani					
	Karimganj	28		Nagar 0), (Ba		8	8	11	1	0
	Karinganj	20	16)	ιαgαι U), (D	adarpur	o o	0	11	1	
			,							
				guri 89), (Go						
	Kokrajhar	11128	736), (Do	otma 6451),	(Kokrajhar	5197	4259	1560	100	12
			1733), (B	1733), (Bagribari 2119)						
			(Kaliaboi	r 0), (Samag	uri 0).					
	Nagaon	4488	*	20), (Kampui	• //	1681	1633	1156	15	3
	ivagaon	4400			1 1 / 11),	1001	1033	1130	13	3
			(Nagaon				-			
				502), (Banekı						
				ri 0), (Pasch						
	Nalbari	18876	2836), (B	Sarbhag 999)),	6709	7958	3917	246	46
			(Ghograp	oar 276), (Na	albari					
			4716)							
				ar 0), (Dhek	iaiuli 500)					
	Sonitpur	500	(Tezpur		rajuri 500),	155	222	122	1	0
					1 1					
	Tamulpur	2095		ar 1167), (Ta	amuipur	607	612	873	3	0
	•		928)							
	Tinsukia	2123	(Doomdo	oma 2123)		863	777	415	68	0
			(Khairab	ari 0), (Udal	guri 1395).					
	Udalguri	5206		1710), (Kala		2293	1787	945	181	0
	Caargain	====		1710), (Kaia Iarisinga 609			1.0,	1		
	Total	156365	1772), (1.	larisinga 00.	·)	67859	60902	26471	1030	103
			N/-1-	E1-	Cl. 1.1			204/1	1030	103
	District	Total	Male	Female	Children	Revenue C		100 00	10) (81	
	Barpeta	2	1	0	1				0), (Chenga	0),
	Burpeta	_	•	Ü	-		1), (Sarthel			
	Darrang	1	1	0	0	(Dalgaon	0), (Mangald	loi 0), (Pathar	righat 1), (Sip	ajhar 0)
Human	Hailakandi	1	1	0	0	(Katlicherr	a 1)			
Lives Lost -					_	`		ani () (Nilan	nbazar 1), (Pa	therkandi l
Confirmed	Karimganj	2	0	0	2	0), (RK Na		anj 0), (Milan	10azai 1), (1 a	unci kandi
Commined								10) (D 11		1.0)
	Nalbari	1	1	0	0			•	etri 0), (Ghog	rapar 0),
					_), (Paschim l			
	Sonitpur	1	0	0	1				ur 0), (Thelar	mara 0)
		1 8			_					mara 0)
	Sonitpur		0	0	1					mara 0)
	Sonitpur		0 4	0 0 General	1 4					mara 0)
	Sonitpur		0 4 Flood	0 0 General Drownin	1					mara 0)
	Sonitpur Total	8	0 4	0 0 General Drownin g (Non	1 4					nara 0)
Human	Sonitpur Total District	8 Total	0 4 Flood Death	0 0 General Drownin g (Non Flood)	1 4 Landslide					mara 0)
Human Lives Lost	Sonitpur Total District Barpeta	Total	0 4 Flood Death	0 0 General Drownin g (Non Flood) 0	1 4 Landslide					mara 0)
Lives Lost	Sonitpur Total District Barpeta Darrang	8 Total	0 4 Flood Death	0 0 General Drownin g (Non Flood)	1 4 Landslide					mara 0)
Lives Lost Confirmed -	Sonitpur Total District Barpeta	Total	0 4 Flood Death	0 0 General Drownin g (Non Flood) 0	1 4 Landslide					mara 0)
Lives Lost	Sonitpur Total District Barpeta Darrang Hailakandi	7 Total 2 1 1 1	0 4 Flood Death	0 0 General Drownin g (Non Flood) 0	1 4 Landslide 0 0 1					mara 0)
Lives Lost Confirmed -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj	7 Total 2 1 1 2 2	0 4 Flood Death 2 1 0	0 0 General Drownin g (Non Flood) 0 0 0	1 4 Landslide 0 0 1 2					mara 0)
Lives Lost Confirmed -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari	7 Total 2 1 2 1 1 2 1	0 4 Flood Death 2 1 0 0	0 0 General Drownin g (Non Flood) 0 0 0 0	1 4 Landslide 0 0 1 2 0 0					mara 0)
Lives Lost Confirmed -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur	7 Total 2 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0 4 Flood Death 2 1 0 0 1	0 0 General Drownin g (Non Flood) 0 0 0 0 0	1 4 Landslide 0 0 1 2 0 0 0					mara 0)
Lives Lost Confirmed -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total	Total 2 1 1 2 1 1 8	0 4 Flood Death 2 1 0 0 1 1 5	0 0 General Drownin g (Non Flood) 0 0 0 0 0 0 0	1 4 Landslide 0 0 0 1 2 0 0 0 3	(Chariduar				mara 0)
Lives Lost Confirmed -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur	7 Total 2 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0 4 Flood Death 2 1 0 0 1	0 0 General Drownin g (Non Flood) 0 0 0 0 0	1 4 Landslide 0 0 1 2 0 0 0	(Chariduar Details	1), (Dhekia	juli 0), (Tezp		mara 0)
Lives Lost Confirmed -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total	Total 2 1 1 2 1 1 8	0 4 Flood Death 2 1 0 0 1 1 5	0 0 General Drownin g (Non Flood) 0 0 0 0 0 0 0	1 4 Landslide 0 0 0 1 2 0 0 0 3	(Chariduar Details		juli 0), (Tezp		mara 0)
Lives Lost Confirmed -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali	8 Total 2 1 1 2 1 1 8 Total 1	0 4 Flood Death 2 1 0 0 1 1 5 Male	0 0 General Drownin g (Non Flood) 0 0 0 0 0 Female	1 4 Landslide 0 0 0 1 2 0 0 0 3 Children 0	(Chariduar Details (Bajali 1),	1), (Dhekia	juli 0), (Tezp		mara 0)
Lives Lost Confirmed - Death Type	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai	7 Total 2 1 1 2 1 1 8 7 Total	0 4 Flood Death 2 1 0 0 1 1 5 Male 1	0 0 General Drownin g (Non Flood) 0 0 0 0 Female 0	1 4 Landslide 0 0 1 2 0 0 3 Children	(Chariduar Details (Bajali 1),	1), (Dhekia	juli 0), (Tezp		mara 0)
Lives Lost Confirmed - Death Type	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi	7 Total 2 1 1 2 1 1 8 7 Total 1 4	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0	0 0 General Drownin g (Non Flood) 0 0 0 0 Female 0 1	1 4 Landslide 0 0 0 1 2 0 0 0 3 Children 0 3	Chariduar Details (Bajali 1), (Doboka 0	(Sarupeta 0), (Hojai 4)	juli 0), (Tezp		mara 0)
Lives Lost Confirmed - Death Type	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong	8 Total 2 1 1 2 1 1 8 Total 1	0 4 Flood Death 2 1 0 0 1 1 5 Male 1	0 0 General Drownin g (Non Flood) 0 0 0 0 Female 0	1 4 Landslide 0 0 0 1 2 0 0 0 3 Children 0	(Chariduar Details (Bajali 1),	(Sarupeta 0), (Hojai 4)	juli 0), (Tezp		mara 0)
Lives Lost Confirmed - Death Type Human Lives Lost -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi	7 Total 2 1 1 2 1 1 8 7 Total 1 4	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0	0 0 General Drownin g (Non Flood) 0 0 0 0 Female 0 1	1 4 Landslide 0 0 0 1 2 0 0 0 3 Children 0 3	Chariduar Details (Bajali 1), (Doboka (Donkamol	(Sarupeta (0)), (Hojai 4)	juli 0), (Tezp	ur 0), (Thelar	
Lives Lost Confirmed - Death Type	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West	8 Total 2 1 1 2 1 1 8 Total 1 4 1	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1	0 0 General Drownin g (Non Flood) 0 0 0 0 Female 0 1	1 4 Landslide 0 0 0 1 2 0 0 0 3 Children 0 3 0	Chariduar Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1)	juli 0), (Tezp		
Lives Lost Confirmed - Death Type Human Lives Lost -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar	7 Total 2 1 1 2 1 1 8 7 Total 1 4	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0	0 0 0 General Drownin g (Non Flood) 0 0 0 0 0 Female 0 1	1 4 Landslide 0 0 0 1 2 0 0 0 3 Children 0 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West	8 Total 2 1 1 2 1 1 8 Total 1 4 1	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1	0 0 General Drownin g (Non Flood) 0 0 0 0 Female 0 1	1 4 Landslide 0 0 0 1 2 0 0 0 3 Children 0 3 0	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar Tamulpur	8 Total 2 1 1 2 1 1 8 Total 1 4 1	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 1	0 0 0 General Drownin g (Non Flood) 0 0 0 0 0 Female 0 1	1 4 Landslide 0 0 1 2 0 0 3 Children 0 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar Tamulpur Total	8 Total 2 1 1 2 1 1 8 Total 1 1 1 1 1 1 8	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1 1 4	0 0 0 General Drownin g (Non Flood) 0 0 0 0 0 Female 0 1 0 0 0 1	1 4 Landslide 0 0 0 1 2 0 0 3 Children 0 3 0 0 0 0 3 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost - Missing	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar Tamulpur Total District	8 Total 2 1 1 2 1 1 8 Total 1 4 1 1 1 8 Total	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1 1 4 Flood	0 0 General Drownin g (Non Flood) 0 0 0 0 0 0 Female 0 1 0 0 1 Non Flood	1 4 Landslide 0 0 0 1 2 0 0 3 Children 0 3 0 0 0 0 3 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost - Missing	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar Tamulpur Total District Bajali	8 Total 2 1 1 2 1 1 8 Total 1 4 1 1 8 Total 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1 1 4 Flood 1	0 0 0 General Drownin g (Non Flood) 0 0 0 0 0 0 Female 0 1 0 0 1 Non Flood 0	1 4 Landslide 0 0 0 1 2 0 0 3 Children 0 3 0 0 0 0 3 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost - Missing Human Lives Lost	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar Tamulpur Total District Bajali Hojai	8 Total 2 1 1 2 1 1 8 Total 1 4 1 1 1 8 Total	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1 1 4 Flood	0 0 General Drownin g (Non Flood) 0 0 0 0 0 0 Female 0 1 0 0 1 Non Flood	1 4 Landslide 0 0 0 1 2 0 0 3 Children 0 3 0 0 0 0 3 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost - Missing Human Lives Lost Missing -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar Tamulpur Total District Bajali	8 Total 2 1 1 2 1 1 8 Total 1 4 1 1 8 Total 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1 1 4 Flood 1	0 0 0 General Drownin g (Non Flood) 0 0 0 0 0 0 Female 0 1 0 0 1 Non Flood 0	1 4 Landslide 0 0 0 1 2 0 0 3 Children 0 3 0 0 0 0 3 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost - Missing Human Lives Lost	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar Tamulpur Total District Bajali Hojai	8 Total 2 1 1 2 1 1 8 Total 1 4 1 1 8 Total 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1 1 4 Flood 1	0 0 0 General Drownin g (Non Flood) 0 0 0 0 0 0 Female 0 1 0 0 1 Non Flood 0	1 4 Landslide 0 0 0 1 2 0 0 3 Children 0 3 0 0 0 0 3 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	
Lives Lost Confirmed - Death Type Human Lives Lost - Missing Human Lives Lost Missing -	Sonitpur Total District Barpeta Darrang Hailakandi Karimganj Nalbari Sonitpur Total District Bajali Hojai Karbi Anglong West Kokrajhar Tamulpur Total District Bajali Hojai Karbi Anglong Karbi Anglong Karbi Anglong Karbi Kokrajhar	8 Total 2 1 1 2 1 1 8 Total 1 4 1 1 1 4 1 4 4 4 4 4 4 4 4 4 6 6 7 7 8 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8	0 4 Flood Death 2 1 0 0 1 1 5 Male 1 0 1 1 4 Flood 1 4	0 0 0 General Drownin g (Non Flood) 0 0 0 0 0 0 Female 0 1 0 0 1 Non Flood 0 0	1 4 Landslide 0 0 0 1 2 0 0 3 Children 0 3 0 0 0 0 3 3	Details (Bajali 1), (Doboka ((Donkamol	(Sarupeta 0), (Hojai 4) kam 1) 1), (Bhawra 0)	juli 0), (Tezp))), (Lanka 0) guri 0), (Doti	ur 0), (Thelar	

	Kokrajhar	1	1	0						
	Tamulpur	1	1	0						
	Total	8	8	0						
	District	Total	Big	Small	Poultry					
	Bajali	100886	56719	29567	14600					
	Baksa	17170	10214	6956	0					
	Barpeta	601542	243350	131213	226979					
	Bongaigao n	147206	20089	10422	116695					
	Chirang	2715	840	595	1280					
	Darrang	222250	126603	62347	33300					
	Dhemaji	58744	21164	12773	24807					
	Dhubri	221706	138040	83666	0					
	Dibrugarh	1754	1477	277	0					
	Goalpara	52634	32520	11725	8389					
Animals	Hojai	99612	35185	19927	44500					
Affected	Kamrup	355253	204549	31909	118795					
	Kamrup (M)	5485	3850	1635	0					
	Kokrajhar	50185	20554	10386	19245					
	Lakhimpur	39307	24406	10876	4025					
	Nagaon	50788	29062	13002	8724					
	Nalbari	218783	105134	86759	26890					
	Sonitpur	9021	5668	3143	210					
	South Salmara	271672	104987	74164	92521					
	Tamulpur	18761	5721	6437	6603					
	Udalguri	8986	4677	3487	822					
	Total	255446 0	119480 9	611266	748385					
	District	Total	Big	Small	Poultry					
	Baksa	12	0	12	0					
Animals	Goalpara	5	0	5	0					
Washed	Nagaon	2	2	0	0					
Away	Sonitpur	2	0	2	0					
	Udalguri	10	10	0	0					
	Total	31	12	19	0					
	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
	Baksa	6	1	7	1	0	1	0	0	0
Houses	Darrang	30	0	30	0	0	0	0	0	0
Damaged	Kamrup (M)	0	0	0	0	3	3	0	0	0
	Sonitpur	10	5	15	10	3	13	4	0	4
	South	6	0	6	0	0	0	0	0	0
	Salmara					_				
	Total District	Agency	6	58	Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d
	Bajali	Army/Para SDRF, NI	amilitary fo DRF	orce,	6	203	0	0	0	0
Rescue	Baksa	Army/Par	amilitary fo	orce	2	50	0	0	0	1
Operation	Barpeta		re & Emerg		28	1584	994	0	0	0
	Darberg		F&ES), SD		20	1304)) +	U	U	U
	Bongaigao n	Boat, Eng Office/Loc	ple, SDRF, ine Boat, C cal Admini	ircle	28	230	0	0	0	13
	Chirang	Circle Off Administr HQ Chapi	ation, SDR	F, SSB	5	514	0	0	0	10

	Darrang	Defence/T	amilitary for Trained Vol	unteers,	19	1629	0	0	0	5
	Dhemaji		nergency Se		1	0	0	0	0	0
	Dhubri	Circle Off	rice/Local ration, SDR	ıF	2	24	0	0	0	1
	Dima- Hasao	Volunteer Services (Departmen	mergency ORF, Water	0	0	0	0	0	15
	Goalpara		nergency Se	ervices	4	236	77	0	0	14
	Hojai	SDRF, Ar force, Loc Fire & En (F&ES), O	rmy/Parami cal People, I nergency Se Country Bo	NDRF, ervices	55	2990	122	0	0	3
	Kamrup	Emergenc NDRF, SI	ration, Fire y Services	(F&ES),	14	549	8	0	0	9
	Kamrup (M)	Circle Off Administr Emergenc		& (F&ES),	1	0	0	0	0	0
	Karbi Anglong West	SDRF			2	0	0	0	0	0
	Karimganj	SDRF			2	0	0	0	0	0
	Kokrajhar				0	0	0	0	0	16
	Lakhimpur				0	0	0	0	0	4
	Nagaon	(F&ES), S			3	560	0	0	0	0
	Nalbari	Army/Par NDRF, SI	amilitary fo DRF	orce,	7	72	20	0	0	11
	South Salmara				0	0	0	0	0	1
	Tamulpur	Office/Loc Fire & En (F&ES), S	cal Admini nergency Se SDRF, local	ervices l NGO	10	451	0	0	0	1
	Udalguri	Fire & En (F&ES), N	nergency Se NDRF	ervices	2	10	0	0	0	0
	Total				191	9102	1221	0	0	104
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)		- Rice Bran (in Q)
	Bajali	55.06	28.09	2.21	216.22	0.00	0.00	0.00		
	Baksa	179.76	34.43	10.33	813.05	0.00	0.00	0.00		
Relief	Barpeta	9017.57	1732.2 6	913.42	26.00	0.00	5314.00	0.00	-	
Distributed	Bongaigao n	203.25	39.53	10.98	1097.75	0.00	1398.00	0.00		
	Cachar	8.80	1.85	0.53	52.00	0.00	0.00	0.00		
	Chirang	92.50	17.60	5.28	512.92	0.00	0.00	0.00		
	Darrang	1024.80	210.89	82.77	4227.00	0.00	0.00	922.75		
	Dhemaji	467.17	83.39	25.02	2372.87	0.00	160.50	0.00		
	Dhubri	105.17	19.42	5.83	582.51	0.00	950.54	0.00		
	Dima-									

	Coster	20.71	2 77	1 14	112 22	0.00	0.00	0.00
	Goalpara	20.71	3.77	1.14	113.22	0.00	0.00	0.00
	Hojai	300.00	7.80	3.25	156.00	0.00	0.00	60.00
	Kamrup	206.06	67.51	19.98	1997.68	0.00	1494.00	0.00
	Kamrup	0.60	0.10	0.02	2.00	0.00	0.00	0.00
	(M)	0.60	0.10	0.03	3.00	0.00	0.00	0.00
	Karbi							
	Anglong	129.56	24.46	7.34	7.34	0.00	0.00	0.00
	West	123.30	21.10	7.31	7.51	0.00	0.00	0.00
	Karimganj	13.00	1.20	0.50	0.00	0.00	0.00	0.00
	Kokrajhar	56.51	10.38	3.12	311.58	4.50	0.00	0.00
	Lakhimpur	549.12	101.78	30.53	3137.88	0.00	0.00	126.30
	Nagaon	22.17	4.04	1.21	0.00	0.00	0.00	0.00
	Nalbari	277.67	62.08	19.93	1993.00	0.00	0.00	0.00
	Sonitpur	506.45	95.66	28.62	0.00	0.00	226.40	0.00
	Tamulpur	363.20	64.01	19.43	393.09	0.00	0.00	0.00
	Udalguri	461.50	87.19	20.02	186.59	0.00	0.00	0.00
		14061.8	2697.5					
	Total	9	6	1211.53	18205.70	4.50	9543.44	1109.05
	District	Baby Foo	-	Baby Food	l Colid	Others		
		-					951 00 O	41 17 00 D:
	Bajali	0.00-Q, 0.	.00-1111	0.00-Q, 0.0	00-1111			ndle-17.00-Pieces
	D 1	0.00.0	00 DI :	0.00.0.47	00 DI :			(g; Biscuit-643.00-Pkt; Candel-643.00-
	Baksa	0.00-Q, 0.	.00-Pkt	0.00-Q, 47	.00-Pkt		-5.00-Pkt; B1	scuits -82.00-Pkt; Mosquito coil -2.00-
						Q		
	Barpeta	0.00-Pkt,	0.00-0	11.00-Pkt,	0.00-0		pkins -200.00	Pkt; Candle -50.00-Pkt; Mosquito coil
	Darpeta	0.00-1 Kt,	0.00-Q	11.00-1 Kt,	0.00-Q	-50.00-Pkt		
	Donosioso	2042.00 E	01-+ 0 00			Tarpaulin-6	00.00-Pieces	; Mother horlicks -25.00-Pkt; Sanitary
	Bongaigao	2043.00-F		2043.00-Pl	kt, 450.00-Q	Pad-474.00	-Pkt; Tarpaul:	in -460.00-Pieces; candle-372.00-Pkt;
	n	Q, 568.80	-L			matches -10	0.00-Pkt; chira	a-1.62-Q; gur-0.30-Q
	Cachar	0.00-Q		0.00-Q			·	
						Tarnaulin-6	23 00-Pieces	; Candle-295.00-Pkt; Mosquito Coil-
	Chirang	0.00-Q		0.00-Q, 42	00-Pkt	•		Pieces; Sanitary Napkin-48.00-Pkt;
	Cinitalig	0.00 Q		0.00 Q, 12	.00 T Kt	Match Box-		rices, Builtary Trapkin Tolog Tike,
	Dorrang	0.00-Q, 0.	00 Dlst	0.00-Q, 44	9 00 Dlet		150.00-Piece	0
	Darrang		.00-F Kt	~	0.00-FKt	•		
	Dhemaji	0.00-Q		0.00-Q		•		; Tarpaulin -490.00-Pieces
	Dhubri	375.00-Pk	ct, 0.00-Q	0.00-Q, 26	.00-Pkt			oil-60.00-Pkt; M.Box-60.00-Pieces;
						_		sanitary napkins-90.00-Pkt
	Dibrugarh	0.00-Q		0.00-Q		Tarpaulin -2		
	Dima-							0-L; Potato-30.00-Kg; Onion-6.00-Kg;
	Hasao	0.00-Q		0.00-Q		Biscuit-42.0	00-Pkt; Candl	e-18.00-Pkt; Match Box-6.00-Pkt;
	Hasao					Mosquito R	epellent-12.0	0-Pkt
Relief	Coolmono	0.00-Q		0.00-Q		Chira-1.93-	Q; Gur-0.34-	Q; Mosquito Coil-252.00-Pkt; Match
Distributed	Goalpara	0.00-Q		0.00-Q		Box-252.00	-Pkt; Candle-	-252.00-Pkt; Tarpaulin-1118.00-Pieces
Others		0.00.0		0.00.0		Amul Taza-	-156.00-L; W	ater-240.00-L; Sanitary Pad-65.00-Pkt;
	Hojai	0.00-Q		0.00-Q		Water Bottl	e-1320.00-L	•
								quito Coil-40.00-Pkt; Sanitary Napkin-
	Kamrup	73.00-Pkt	. 0.00-О	73.00-Pkt,	O.00-O		,	00-Pieces; Candle-15344.00-Pkt;
	r	, , , , , , , , , , , , , , , , , , , ,	, (Candel-20.0	•	
	Kamrup							s; Bread-50.00-Pkt; Biscuit-50.00-Pkt;
	(M)	0.00-Q		0.00-Q		Candle-5.00		s, bread-50.00-1 kt, biscuit-50.00-1 kt,
	Karbi					Candic-3.00	/ I Kt	
		0.00-Q		0.00.0				
	Anglong	0.00-Q		0.00-Q				
	West	0.00.0		0.00.0		0.000.0		
	Karimganj	0.00-Q		0.00-Q		0-0.00-Q		
								fatch Box-430.00-Pieces; CANDLE-
								ES-3.90-Kg; MOTHER HORLICKS-
				0.00-Q, 46	.50-Kg.	~		7.00-Pkt; SANITARY NAPKIN-
	Kokrajhar	0.00-Q		12.00-Pkt	,			ANITIZER-2.00-L; SOAP-398.00-
	1			12.00 T Kt				OWDER-10.00-Kg; Biscuit-54.00-Pkt;
						Candle-34.0	00-Pkt; Match	n Box-15.00-Pkt; Mosquito Coil-84.00-
	1						oap-84.00-Pie	
						Suji 1/2 kg-	30.00-Pkt; H	orlicks 500 g-14.00-Pkt; concentrated
	I al-1-1-	0.00.0		0.00 0.64	00 Di-4			me-76.00-Q; Tarpaulin-113.00-Pieces;
	Lakhimpur	0.00-Q		0.00-Q, 64	.UU-PKI			Feed)-28.00-Q; Halogen Tablet-
	1							(Baby Food)-60.00-Pieces; 0-0.00-Q
	Nagaon	500.00-Pk	ct.	500.00-Pkt	-			V-1.00-Pieces
L	1.000011	2 3 3 3 3 1 K		200.00 I Kt	•		m, 111 V	

	Nalbari	0.00-Q		0.00-Q	Masquto Coil-186.00-Pkt; Candle -372.00-Pkt; Wheat Bran-1036.00-Q						
	Sonitpur	0.00-Q		0.00-Q	0-0.00-Q						
	Tamulpur	3.00-Pkt,	0.00-Q	0.00-Q							
	Udalguri	0.00-Q, 6	00.00-Pkt	0.00-Q, 0.00-Pkt	Candles-20.00-Pkt; Match Box-20.00-Pkt; Disposal Plates-60.00-Pkt; Diaposal Glass-12.00-Pkt; Mosquito Coil-20.00-Pkt						
	District	Numbe r	Details								
	Darrang	3									
Infrastructur e Damaged - Embankme	Lakhimpur	2	at Bolom 0.000000 1 No. Pac (20Mtr, 3 Developm	Nowboicha - Pabha River Panchayat Bund Boloma Pabha River Panchayat Bund breached (20Mt Boloma on 18.06.2022. Report received from Nowboicha Block Development Office (Long000000, Lat - 0.000000), No. Pachnoi Ujoni Side Bund 1 No. Pachnoi Ujoni 1 No. Pachnoi Ujoni Side Bund breached 20Mtr, 30Mtr and 10 Mtr) at 1 No. Pachnoi on 17.06.2022. Report received from Nowboicha Block Development Office (Long - 0.000000, Lat - 0.000000)							
nt Breached Sonitpur	Sonitpur	1	embankn	nent breached from Ga	0m Village- Bhara Singri(Channel 3700-3920m) Belsiri L/Bank ruduba to Sotipahar due to river Belsiri on 17/06/2022 as reported by 18/06/2022. (Long - 0.000000, Lat - 0.000000)						
	Tamulpur	1	Goreswa	r - Nathkuchi East Bar	nk Village Nathkuchi Dated 17/06/2022 breached at east m damage (Long - 91.701165, Lat - 26.619793)						
	Total	7		• •							
	District	Numbe	Details								
	District	r									
	Bajali	1			ment halgirighat Erosion at embankment occurred as per the report Division on 18/06/2022. (Long - 91.161453, Lat - 26.548016)						
	Darrang	2									
	Kamrup	1	under Ka moment.	yan Rev. Circle. Repor (Long - 0.000000, La							
	Kokrajhar	1	Embankr	Bagribari - Tipkai River Embankbent Balapara Bazar AS REPORTED BY CO BAGRIBARI, Embankment of Tipkai Rive from Kuarpar Idgahmath to Lalmati Pt-I village boundary has been ffected ON 18-06-2022 (Long - 0.000000, Lat - 0.000000)							
	Lakhimpur	1	migration	at Bogolijan 8th KM	8th KM of Ranganadi Left Bank embankment Bogalijan Bank of Ranganadi Left Bank embankment as repoted by Water Resources Divn. on 17-06-2022. (Long - 0.000000, Lat - 0.000000)						
Infrastructur e Damaged - Embankme nt Affected	Nalbari	5	embankn water lev Pagaldia in village (Long - Banekuc affected of Barbhag 5.80 km - 91.4400 L/B of riv Subdivisi	nent at river Pagaldia in el of river Pagaldia Da Embankment Kordoin Kordoitala is affected 0.000000, Lat - 0.0000 hi - Nadla Chanel (Kalue to rising river wate - B/Dyke on R/b of riv As per report submitte 100, Lat - 26.320000), ver Baralia Dokoha, Fon, Mukalmua on 18/0	naikhunda Jan) Kaithalkuchi Nakerbari point This Embankment is er on 17/06/2022 (Long - 26.454214, Lat - 91.322836), ver Pagladia Bihdia. At Bijulighat to Adabari form Ch 0.00 Km to ed by Mukalmua W.R. Subdivision, Mukalmua on 18/06/2022 (Long Raitkuchi, Dusutimukh As per report submitted by Mukalmua W.R. 06/2022 (Long - 91.480000, Lat - 26.320000)						
	Sivasagar	3	of emban Date of C Division, Desang been obseriver slop occurrence Demow. Desang beobserved embankn	kment due to rise of wo Occurrence: 17/6/2022 Demow. (Long - 94. und right bank from B erved at Desang bund r ee of the embankment l ee: 17/6/2022 to 18/6/2 (Long - 94.706047, L und right bank from B at khamun area for a leaent. Date of occurrence	nk from Jalukoni to Nangalamara. Aithan Severe damage to the toe rater level of river Desang has been observed for a length of 150 metre. to 18/6/2022. The report has been received from Water Resource 791940, Lat - 27.001111), ahgarh to AT road Ekoratoli Severe damage of the embankment has right bank from Bahgarh to AT road for a length of 10 km. A part of has been washed away by strong current of Desang river. Date of 2022. The report has been recieved from Water Resource division, at - 27.044366), ahgarh to AT road. Khamun Damage to the embankment has been ength of 150 metre. River bank has already touched the toe of the ce; 17/6/2022. The report has been recieved from Water Resource 28710, Lat - 27.038470)						
T. C.		Numbe	D								
Infrastructur	District	r	Details								
e Damaged - Road	Bajali	11	-	_	d Maduri chowk the road is breached.length 30 meter and depth 5 m PWD Roads on 18/06/2022 (Long - 91.228334, Lat - 26.579264),						

	1		muh rahahari ta halana raad lauh rahahari laha raad ia hasaahad laa-at-10 aa-taa-ad-1-ad-4
			pub rehabari to belona road pub rehabari the road is breached.length 18 meter and depth 4 meter.this report is received from PWD Roads on 18/06/2022 (Long - 91.233662, Lat - 26.609664),
			Hudukhata Naosali road pachim rehabari the road is breached.length 10 meter and depth 1
			meter.this report is received from PWD Roads on 18/06/2022 (Long - 91.211319, Lat - 26.617265),
			Cheuni sariali to naosali pub rehabari the road is breached.length 12 meter and depth 4 meter.this
			report is received from PWD Roads on 18/06/2022 (Long - 91.212635, Lat - 26.617456),
			patacharkuchi to rampur tongarkur the road is breached.length 14meter and depth 4 meter.this
			report is received from PWD Roads on 18/06/2022 (Long - 91.235795, Lat - 26.483302),
			Sarupeta - gohain kamal ali mazgaon report received from concerned LM on 18/06/2022 (Long -
			91.010000, Lat - 26.470000),
			sarupeta to bhawanipur pwd road kalbari report received from concerned LM on 18/06/2022
			(Long - 91.060000, Lat - 26.470000),
			sarupeta to mechpara pmgsy road mechpara report received from concerned LM on 18/06/2022
			(Long - 91.060000, Lat - 26.490000),
			chauliabari to dolor pothar pmgsy road bangti report received from concerned LM on 18/06/2022
			(Long - 91.110000, Lat - 26.530000),
			chaauliabari to medhikuchi road medhikuchi report received from concerned LM on 18/06/2022 (Long - 91.100000, Lat - 26.540000),
			mazgaon to sarupeta pmgsy road pata report received from concerned LM on 18/06/2022 (Long -
			91.020000, Lat - 26.470000)
		†	Baska - 1.DUE TO HEAVY RAIN MUSHALPUR TO BATHOPURI (RABI BORO) ROAD
			DAMAGED ON DT. 16/06/2022 Mushalpur (Long - 26.659798, Lat - 91.347813),
			2.DUE TO HEAVY RAIN DAKHIN AHOPA TO DOOMNI ROAD AT AHOPA DAMAGED ON
			DT 16/06/2022 Ahopa (Long - 26.701379, Lat - 91.308213),
			11.DUE TO HEAVY RAIN NIKASHI TO BHUTANKHUTI (DHNSHREEPUR) ROAD ERODED
	Baksa	6	ON DT.16/06/2022 Dhanshripur (Long - 26.744596, Lat - 91.381114),
			12.DUE TO HEAVY RAIN DAKHIN ULUBARI TO BASISHTA ROAD DAMAGED ON DT.
			16/06/2022 Ulubari (Long - 26.624077, Lat - 91.429656),
			DUE TO HEAVY RAIN DIGHALDONGA TO QUERY CHAWK LINK ROAD DAMAGED ON
			DT 15/06/2022 B Block (Long - 26.708577, Lat - 91.388976),
			Thamna Rampur Road Erosion Laphakuchi (Long - 26.636927, Lat - 91.309757) Baghbar - 1. Takakata to Jaurimari Road Pkg No As-01-265 Kaonerchar Date of Damage- 16-06-
			2022 Type of Damage-shoulder & H/C damage Damage length-Ch.300m to 4050=3500m Reported
			by- PWD Dept. (Long - 90.984785, Lat - 26.259765),
			2. Bhatnapaity to Kopahtoli via Kadomtola Road Pkg no As-01-216 Kopahtoli Date of Damage-
			16-06-2022 Type of Damage-shoulder & H/C damage Damage length- Ch 250m to 5000m)=4250m
			Reported by- PWD Dept. (Long - 90.994786, Lat - 26.269865),
			3. Mandia Dapnasing Parghat road to 2 no Bardoloni via Jalimuddin house 2 no Bardoloni Date of
			Damage- 16-06-2022 Type of Damage-shoulder & H/C damage Damage length- 150m to
			550m=400m Reported by- PWD Dept. (Long - 90.996756, Lat - 26.269568),
			4. Agmondia chariali to Bamundongra road Pkg no As-01-277 Bamundongra Date of Damage- 16-
			06-2022 Type of Damage-shoulder & H/C damage Damage length- ch.300m to 2050m=1000m
			Reported by- PWD Dept. (Long - 90.999756, Lat - 26.268976), 5. Barakata Chariali to Niz Baghbar Via Satbhita ME School Pkg no As-01-205 Satbhitha Date of
			Damage- 16-06-2022 Type of Damage-shoulder & H/C damage Damage length- ch. 550m to
			4500m=1430 m Reported by- PWD Dept. (Long - 90.989757, Lat - 26.265878),
			6. Nabanoor MEM to Dapnasingh road Pkg no As-01-240 Dapnasing Date of Damage- 16-06-2022
			Type of Damage-shoulder & H/C damage Damage length- 1300m Reported by- PWD Dept. (Long -
	Barpeta	46	90.989757, Lat - 26.265878),
	Durpeta	10	Kalgachia - CCMC road(vill road) vill-Rampur As per report received from BDO on 17/06/22,
			Const. of surface drain from CCMC road culvert to Azahar Ali house at vill Rampur under 15 FC for
			the year 2020-21(1st inst).(damaged length=20m, B=1.45m, H=1.10m) (Long - 90.806588, Lat -
			26.296435), Haldhia to Chakla road at Haldhia Gaon As per report received from BDO on 17/06/22, const of rd
			from Haldhia dakshinpara tiniali to Chakla HS school at vill- Haldhia Gaon(damaged length= 300m,
			B=1.5m, H=1.2m) (Long - 90.844767, Lat - 26.394165),
			Asadia madrassa to rezzak ali house road at vill- Haldhia pather As per report received from BDO
			on 17/06/22, due to heavy rainfallconst of rd from Asadia madrassa to rezzak ali house road at vill-
			Haldhia pather(Damaged length=200m, B=1.3m, H=0.8m) (Long - 90.863113, Lat - 26.406094),
			Earthen field bundh vill-shawrachar As per report received from BDO on 17/06/22, due to heavy
			rainfall const of Earthen field bundh fr Rofsed Miah house to Hassen Miah house.(Damaged length=
			70m, B=4m, H=1.20m) (Long - 90.824785, Lat - 26.274686),
			Earthen field bundh vill- Shawrachara As per report received from BDO on 17/06/22, due to heavy
			rainfall cons of earthen filed bundh st frm Nurul Islam house to Abdul Goni house.(Damaged
			length=50m, W= 4m, H=1.50m) (Long - 90.821648, Lat - 26.269853),
			Paver block road fr SH2 to udmari at vill-udmari As per report received from BDO on 17/06/22, due to heavy rainfall const of paver block rd from SH2 to Subur Uddin house at Udmari.(Damaged
L	j	1	due to neary rannan const or paver block to from 5112 to 500m Oddin house at Odinan.(Damaged

		I
		length= 20m) (Long - 0.000000, Lat - 0.000000), Barpeta - Bagodi Bhoiraguri road Bagodi Road submerged 400.00 PWRD Barpeta 18.06.2022
		(Long - 91.060559, Lat - 26.453647),
		Bagodi Bhoiraguri road to panichila Bagodi Road submerged PWRD Barpeta 18.06.2022 (Long - 91.130355, Lat - 26.350949),
		Barnagar - Dahalapara to Dakhin Chandamari Road Dahalapara As per WT Message received from Ex. Enge, PWD Sorbhog & Jania Terr Road Divn, Barpeta Road on 18/06/2022 road is damaged (Long - 90.804698, Lat - 26.438906),
		Balapet village road Balapet As per WT Message received from Ex. Enge, PWD Sorbhog & Jania Terr Road Divn, Barpeta Road on 18/06/2022 road is submerged. (Long - 90.817725, Lat -
		26.436530), Uttar Ganakgari to JNV road Ketekibari As per WT Message received from Ex. Enge, PWD Sorbhog & Jania Terr Road Divn, Barpeta Road on 18/06/2022 surface of the road is damaged. (Long - 90.893176, Lat - 26.479038),
		Ahompathar Road Ahompathar As per WT Message received from Ex. Enge, PWD Sorbhog & Jania Terr Road Divn, Barpeta Road on 18/06/2022 road is submerged. (Long - 90.871056, Lat - 26.575021),
		Ahom pathar village Road from Satyajit goswami house to Himangshu House Ahompathar As per WT Message received from Ex. Enge, PWD Sorbhog & Jania Terr Road Divn, Barpeta Road on 18/06/2022 road is submerged. (Long - 90.808670, Lat - 26.515058),
		Ahom Pathar village road to Doulgobinda mandir Ahompathar As per WT Message received from Ex. Enge, PWD Sorbhog & Jania Terr Road Divn, Barpeta Road on 18/06/2022 surface of the road is damaged. (Long - 90.863718, Lat - 26.515058),
		Santoradaha Deka Thakur to Ganesh mandir Road Santoradaha As per WT Message received from Ex. Enge, PWD Sorbhog & Jania Terr Road Divn, Barpeta Road on 18/06/2022 surface of the road is damaged. (Long - 90.859587, Lat - 26.513019),
		Sanotaradaha PMGSY road to Ganesh Mandir Road Santoradaha As per WT Message received from Ex. Enge, PWD Sorbhog & Jania Terr Road Divn, Barpeta Road on 18/06/2022 surface of the road is damaged. (Long - 90.859681, Lat - 26.515180)
Biswanath	1	Naduar RC part - Sootea to Saraijonia hospital Saraijonia As per report received from Ex. Engineer PWD Biswanath on dated 17/06/2022; rising water level of Mornoi caused side erosion of the road from Sootea to Saraijonia hospital at CH. 500.00m for a length of about 50.00 m. The average width and depth of side erosion are 2.00 m and 1.95m respectively. (Long - 93.038375, Lat - 26.739870)
		2800.00 m. Approach of SPT Br. No. 3/1 damaged. as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.837096, Lat - 26.416021), Manasghat Sakisali road Manasghat Sakisali road Road submerged from 0.00 m to 4000.00 m. Road embankment and surface damaged.as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.825635, Lat - 26.429281), Moukhowa to NH31 via Borbila PMGSY road Moukhowa to NH31 via Borbila PMGSY road Road submerged, road embankment damaged at 2nd & 4th km.as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.803532, Lat - 26.486329), Roha Chakla Kokila road Roha Chakla Kokila road Road embankment damaged 0.00 m to 1500.00 m, as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.850469, Lat - 26.431137), Chakla Kirtanpara road Chakla Kirtanpara road Road embankment damaged at 2nd & 3rd km. Existing foot bridge washed away at 3rd km, as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.824201, Lat - 26.386238),
Bongaigao n	28	Manikpur Bashbari road Manikpur Bashbari road Road embankment damaged, road submerged at 1st to 3rd km, as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.793017, Lat - 26.432893), Chakla Kirtanpara road Chakla Kirtanpara road Road embankment damaged, road submerged at 4th km, as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.814485, Lat - 26.388385), Dangaigaon Kirtanpara road Dangaigaon Kirtanpara road Erosion of side slopes, damage of hard crust from Ch. 1650.00 m to Ch. 2100.00 m, as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.742584, Lat - 26.435906), Bagariguri Paragaon road. Bagariguri Paragaon road. Road Embankment partly brached on
		bagariguri Paragaon road.as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.851518, Lat - 26.526966), Patiladoha Panbari road Patiladoha Panbari road Road Embankment partly breached patiladoha panbari road at 1st km as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.801294, Lat - 26.491663), Patiladoha panbari road Patiladoha panbari road Road embankment submerged on patiladoha
		panbari road (From ch. 3.00m to Ch.500.00m) average of water depth 1.2 mtr as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.801298, Lat - 26.491682), Boitamari - Salbari Bongaigaon road Salbari Bongaigaon road Road surface at 1st, 2nd, 3rd & 4th km. as per report by PWRD Bongaigaon Date 17.06.2022 (Long - 90.512049, Lat - 26.363329),

Ī			Bongaigaon - Bongaigaon Bhakarivita road Bongaigaon Bhakarivita road Hard crust damaged at
			Ch. 1200.00 m, as per report by PWRD Bongaigaon dated 17.06.2022 (Long - 90.551487, Lat -
			26.469746),
			Dangtol - Pachim Bhadragaon to Pub Bhadra road Pachim Bhadragaon Embankment damaged at Ch. 1700.00 m, as per report by PWRD Bongaigoan date on 17.06.2022 (Long - 90.446058, Lat - 26.425242)
			26.425242), Fulkumari Durgamari road Fulkumari Durgamari road Road submaged at various stretches at 1st &
			2nd km as per report by PWRD Bongaigoan date on 17.06.2022 (Long - 90.451269, Lat -
			26.369066), Paltan Bazar to Hollaguri road Paltan Bazar Approach of RCC Bridge No. 1/1 damaged at Ch.
			388.00 m. Road embankment damaged at few stretches from Ch. 1900.00 m to Ch. 2200.00 m as per
			report by PWRD Bongaigoan date on 17.06.2022 (Long - 90.411193, Lat - 26.386156), Pachim Bhadragaon to Pub Bhadra road Pachim Bhadragaon to Pub Bhadra road Culvert approach
			damaged at Ch. 917.00 m as per report by PWRD Bongaigoan date on 17.06.2022 (Long - 90.446238, Lat - 26.422346),
			Talguri Basugaon road Talguri Basugaon road Approach of RCC Bridge No. 12/1 damaged at Ch.
			11200.00 m, as per report by PWRD Bongaigoan date on 17.06.2022 (Long - 90.443078, Lat - 26.417910),
			Srijangram - Barbhanga to Lungai Hill road Barbhanga to Lungai Hill road Road submerged at 1st
			km. Average submergence depth 20 cm as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.706332, Lat - 26.326415),
			Kushbari Dubachari road Kushbari Dubachari road About 50 m road part washed away at 1st km as
			per report PWRD Bongaigaon dated 17.06.2022, (Long - 90.710801, Lat - 26.276748), Kabaitari Abhayapuri road Kabaitari Abhayapuri road Landslide occurred at 10th km, as per report
			PWRD Bongaigaon dated 17.06.2022 (Long - 90.647618, Lat - 26.262098),
			Abhayapuri Pachania road Abhayapuri Pachania road Road submerged at 5th, 6th & 12 km.
			Average submergence depth 30 cm, Latitude: 26.300526, Longitude: 90.631375 Latitude:
			26.290852, Longitude: 90.625627, as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.625651, Lat - 26.290847),
			Besimari Tinkonia road Besimari Tinkonia road One HP Culvert damaged at 2nd km,as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.616881, Lat - 26.271403),
			SH2 at Rangapani SH2 at Rangapani Road submerged from Ch. 39300.00 m to Ch. 39700.00 m.
			Average submergence depth 25 cm. 80 m length road shoulder damaged as per report PWRD
			Bongaigaon dated 17.06.2022 (Long - 90.471200, Lat - 26.184700),
			SH2 to Simlabari Pt-I village road SH2 to Simlabari Pt-I village road Road submerged from Ch. 400.00 m to Ch. 450.00 m. Average submergence depth 25 cm. Side shoulder damaged. as per report
			PWRD Bongaigaon dated 17.06.2022 (Long - 90.794794, Lat - 26.317913),
			Tulungia Bhatipara road Tulungia Bhatipara road Culvert damaged along with errosion of
			approaches, Road surface damaged at Ch. 500.00 m. as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.644851, Lat - 26.371280),
			17.00.2022 (Long - 90.044631, Lat - 20.371280), Nowagaon Rangapani road Nowagaon Rangapani road Road embankment damaged, breach
			occurred at 6th & 7th km, as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.814076, Lat - 26.375956),
			Nowagaon Rangapani road Nowagaon Rangapani road Road embankment damaged, approach of
			SPT Br.No.10/1 damaged, as per report PWRD Bongaigaon dated 17.06.2022 (Long - 90.797440, Lat - 26.346487)
			Lakhipur - NH-53/37 Labankhal near Lalpani NH-53/37 road at Labankhal near Lalpani damaged,
	Cachar	1	as per report received from PWD NH Division, as on dated 18.06.2022 (Long - 0.000000, Lat - 0.000000)
			Sidli - 1. Maigaon Thuribari village Road Thuribari As reported by PWD Chirang (R&B) Division, ICBP road embankment damaged at Thuribari village on 16-06-2022. Damage Details: Length:4m,
			Breadth:4M, Depth: 1 M. (Long - 90.482581, Lat - 26.477791),
			2. Dwimuguri to Polashguri Road Kajalgaon As reported by PWD Chirang (R&B) Division, ICBP
			road embankment breached out at Kajalgaon on 17-06-2022. Damag Details: Length:13M, Breadth:
			8M, Depth:4M (Long - 90.487260, Lat - 26.525209), 3. Tulunga Nwgwr village Road Chapaguri As reported by PWD Chirang (R&B) Division, Road
			embankment breached out at Chapaguri on 17/06/2022. Damage Details: Length:18m, Breadth: 6m,
	Chirang	8	Depth:1M (Long - 90.552226, Lat - 26.507927),
	Cintailg		4. Maujijhora to Serfanguri Road Serfanguri As reported by PWD Chirang (R&B) Division, Road
			embankment eroded at Serfanguri on 17/06/2022. Damage Details: Length:30m, Breadth: 2m, Depth: 5 M. (Long - 90.459040, Lat - 26.635107),
			5. Kadamtola to NH 31 C PMGSY Road Pub Ankorbari As reported by PWD Chirang (R&B)
			Division, Road embankment breached out at Ch. 2778M on 17/06/2022. Damage Details: Length:8m,
			Breadth: 4m, Depth: 1.8 M. (Long - 90.514356, Lat - 26.557982),
			6. Tirimary Village Road Tirimary As reported by PWD Chirang (R&B) Division, Road Embankment breached out at Tirimary on 17/06/2022. Damage Details: Length: 10M, Breadth: 7.5M,
			Depth: 2.5M. (Long - 90.402422, Lat - 26.497278),
	i		,

		7. Lauripara Highway link Road Shyamthaibari As reported by PWD Chirang (R&B) Division,
		Road Embankment breached out at Shyamtaibari on 16/06/2022. Damage Details: Lenght:12m,
		Breadth: 8M, Depth: 2.8M. (Long - 90.390007, Lat - 26.558665), Bijni - Bangaljhora Sariali to Bangaljhora road At 1st Km (from ch 500.00m to ch 750.00 m) As
		reported by PWD, Bijni(R&B) Sub-Division, road surface washed away. Length=250 mtr,
		Breadth=6.50 mtr, Depth=0.30 mtr. Date of Occurrence=17-06-2022 (Long - 90.721232, Lat -
Darrang	3	26.529558)
Darrang	3	Dhemaji - Jiadhal Chariali to Jiadhal College PWD road, from ch.350.00m to ch.500.00m and
		ch.500.00m to ch.600.00m. Jiadhal Chariali to Jiadhal College Today on 18/06/2022, Road hard crush partially damage with earthen shoulde at ch.350.00m to ch.500.00m and ch.500.00m to
		ch.600.00m. right and left side of the embankment of the road and road breached at ch.400.00m and ch.480.00 m (Long - 94.512185, Lat - 27.438882),
		E&D Dyke cum road breached on NH-15 to Dihiri Chapori E&D Dyke cum road breached on NH-15 to Dihiri Chapori Today on 18/06/2022, E&D Dyke cum road breached on NH-15 to Dihiri
		Chapori breached at ch.550.00m &ch.530.00m with a lenght 50.00m(2Nos) (Long - 94.512850, Lat - 27.438882),
		Amulguri Kachari gaon to Naruathan PMGSY road, from ch.1300.00m to ch.1500.00m and
		Ch.1000.00m to Ch.1200.00m. Amulguri Kachari gaon to Naruathan PMGSY road Today on 18/06/2022, PC and SC road surface damaged at Amulguri Kachari gaon to Naruathan PMGSY road,
		from ch.1300.00m to ch.1500.00m and Ch.1000.00m to Ch.1200.00m. (Long - 94.503803, Lat - 27.418380),
Dhemaji	7	Sissiborgaon - PWD road Bormuria Arney to No.2 Nalbari Road. Bormuria Arney to No.2 Nalbari
		Road. Damaged the side shoulder, head crust from Ch.2200.00M to Ch.2200.002700.002900.00 Around length 430.00Meters by the River Tangani on 18/06/2022 (Long - 94.780212, Lat -
		27.554331), PWD road from Mechaki Tangani Gaon road to Kareng Gaon Road. Mechaki Tangani Gaon road to
		Kareng Gaon PWD road Damaged with the box Culvert approach, side shoulder, hard crust
		anongwith BT surface. around length 100meters on 18/06/2022 (Long - 0.000000, Lat - 0.000000), NH-515. Jalakiasuti, Silapathar NH-515. Jalakiasuti, Silapathar NH-515 Damaged Heavy erosion
		of shoulder on right hand side upto hard Crust on 17-06-2022 around length 100meters. (Long -
		94.765842, Lat - 27.613491),
		Jonai - PWD territorial road Bridge approach (left side) 20.00 meters at Tako to Barang Saraibari partially damaged on 17/06/2022 by Burisuti water channel. From Ch.3300.00M to Ch.3350.00M
		As per report received from PWRD, Jonai Territorial Road Sub-Division-II, Jonai a PWD territorial
		road Bridge approach (left side) 20.00 meters at Tako to Barang Saraibari got partially damaged on 17/06/2022 by Burisuti water channel. (Long - 95.082091, Lat - 27.717907)
		South Salmara Part - Salkata Bhagnikanda Road Salkata As per information received from
		PWRD and Field enquiry made by LM on 17/6/22 Said road has been submerged and damage due to flood water /rainfall at several stretches. (Long - 0.000000, Lat - 0.000000),
		Ambari Bhuyanpara Road Ambari As per information received from PWRD and Field enquiry
		made by LM on 17/6/22 Said road has been submerged and damage due to flood water /rainfall at
		several stretches. (Long - 0.000000, Lat - 0.000000), Salkata dhanerkuti Road Salkata As per information received from PWRD and Field enquiry made
		by LM on 17/6/22 Said road has been submerged and damage due to flood water /rainfall at several
		stretches. (Long - 0.000000, Lat - 0.000000),
		Bilasipara - BILASIPARA AMDANIGHAT TO KATHALDI PT-III ROAD(.) SUBMERGED AT DIFFERENT STETCHES AT IST. KM & DAMAGES THE APPROACH OF RCC BOX
		CULVERT NO.1/1 DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG Dated
		(13/06/2022 to 17/06/2022) BILASIPARA AMDANIGHAT TO KATHALDI PT-III ROAD (Long - 90.231672, Lat - 26.221948),
DI I '	22	UDMARI SALKOCHA ROAD(.) SUBMERGED AT 1ST.2ND.3RD& 4TH KM &HARD CRUST
Dhubri	32	DAMAGES AT SEVERAL STRECHES DUE TO HIGH RISE FLOOD WATER OF RIVER
		GAURANG Dated (13/06/2022 to 17/06/2022) UDMARI SALKOCHA ROAD (Long - 90.235265, Lat - 26.272680),
		UDMARI SALKOCHA ROAD TO UDMARI PART-V ,PMGSYPACKAGE NO. AS-05-130(,)
		SUBMERGE AT 1ST KM& 2ND KM DUE TO HIGH RISE FLOOD WATER OF RIVER
		GAURANG Dated (13/06/2022 to 17/06/2022) UDMARI SALKOCHA ROAD (Long - 90.238532, Lat - 26.281365),
		SUAPATA PTIII TO NAYERALGA PTIII ROAD(,) (PMGSY PACKAGE NO. AS-05-25)
		SUBMERGED FULLY ROAD SURFACE DAMAGES&WASHED AWAY THE APPROACHES OF RCC BRIDGE NO. 9/1,14/1 & 14/2 DUE TO HIGH RISE FLOOD WATER OF RIVER
		BRAHMAPUTRA Dated (13/06/2022 to 17/06/2022) SUAPATA PTIII TO NAYERALGA PT
		III ROAD (Long - 90.197590, Lat - 26.160141),
		MAYERCHAR PART-I TO NAYERALGA PT-IIIROAD(,) (PMGSY PACKAGE NO. AS-05-26) SUBMERGED FULLY ROAD SURFACE DAMAGES & WASHED AWAY THE APPROACHES
		OF SPT. BRIDGE NO. 2/1,2/2&3/1 DUE TO HIGH RISE FLOOD WATER OF RIVER

BRAHMAPUTRA Dated (13/06/2022 to 17/06/2022) | MAYERCHAR PART-I TO NAYERALGA PT-IIIROAD | | (Long - 90.221753, Lat - 26.147802),

GHUNGHUNIKHATA PT-II TO MOLANDUBI ROAD, PMGSY PACKAGE NO. AS-05-105(,)SUBMERGED AT 1ST.2ND& 3RDKM,SIDE BERM ERRODED DUE TO FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | GHUNGHUNIKHATA PT-II TO MOLANDUBI ROAD | | (Long - 90.192303, Lat - 26.323716),

UDMARI SALKOCHA ROAD TO KAMAKHYA MANDIR AT BARAIBARI ROAD(,)SUBMERGED THE ROAD &DAMAGESAPPROACHES OF HPC NO. 1/1 & 1/2 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | UDMARI SALKOCHA ROAD | | (Long - 90.244019, Lat - 26.280541),

NH-31 (SURJYAKHATA PT-II TO GOPIGAON PT-I ROAD(,)PMGSY PACKAGE NO. AS-05-119,DAMAGED APPROACHES OF HPC NO. 2/1 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | SURJYAKHATA PT-II | | (Long - 90.225974, Lat - 26.266957),

NH-31 AT HAKAMA TO UDMARI NARIA PAHAR KALBHAIRAB MANDIR ROAD(,) SUBMERGED FULLYDUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | NH-31 AT HAKAMA | | (Long - 90.250710, Lat - 26.247409), 4TH KM OF K.K.H. ROAD TO KATHALDI PT-II ROAD(,) SUBMERGEDAT 1STKM & SIDE BERM ERRODED IN STRETCHES ALL ALONG THE ROAD&APPROACHES OF RCC BR. NO. 1/1 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | 4TH KM OF K.K.H. ROAD TO KATHALDI PT-II ROAD | | (Long - 90.218616, Lat - 26.201409),

5TH KM OF K.K.H. ROAD TO BABURHAT BAZAR ROAD(,) DAMAGES SIDE BERM IN SEVERAL STRETCHES DUE TO FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | BABURHAT BAZAR ROAD | | (Long - 90.209557, Lat - 26.198867), MAYERCHAR BAZAR TO NOONKHOWAPARA MASJID ROAD (,) DAMAGES THE APPROACHES OF SPT.BRIDGE NO. 1/1 & SIDE BERM ERRODED DUE TO FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | MAYERCHAR BAZAR | | (Long - 90.186536, Lat - 26.143796),

6TH KM OF KKH ROAD TO BHERAKHOWA HUSSAINIA MADRASSAROAD(,) SIDE BERM ERODED AT 1ST. KM DUE TO FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | 6TH KM OF KKH ROAD TO BHERAKHOWA HUSSAINIA MADRASSAROAD | | (Long - 90.220340, Lat - 26.194908),

BILASIPARA HAKAMA ROAD(,)SUBMERGED &HARD CRUST DAMAGES & SIDE BERM ERRODED IN SOME STRETCHES, DUE TO FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | BILASIPARA HAKAMA ROAD | | (Long - 90.256802, Lat - 26.250568),

BILASIPARA BANIAPARA IMMERSION GHAT ROAD(,) SUBMERGED & DAMAGESSIDE BERM ATSOME STRETCHES DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | BILASIPARA BANIAPARA IMMERSION GHAT ROAD | | (Long - 90.255696, Lat - 26.236326),

BILASIPARA BATAPARA ROAD(.)ROAD SUBMERGED & SURFACE DAMAGES IN STRETCHES DUE TO HEAVY RAIN& HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | BILASIPARA BATAPARA ROAD | | (Long - 90.230510, Lat - 26.228482),

ANNANDANAGAR TO BANDHABPARA ROAD(.)ROAD SUBMERGED & SURFACE DAMAGES IN STRETCHES DUE TO HEAVY RAIN & HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | ANNANDANAGAR TO BANDHABPARA ROAD | | (Long - 90.218212, Lat - 26.226655),

CHINAMARI PARGHAT TO TILAPARA BAZAR ROAD(.)ROAD SURFACE DAMAGES IN STRETCHES DUE TO HEAVY RAIN & HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | CHINAMARI PARGHAT | | (Long - 90.251683, Lat - 26.308743), BHASANIGAON TO SILGARA KOKRAJHAR ROAD VIA CHINAMARI PMGSY PACKAGE NO.AS-05-204(.)ROAD SIDE BERM DAMAGES IN STRETCHES & HPC NO. 1/1 DAMAGED DUE TO HEAVY RAIN & HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | BHASANIGAON | | (Long - 90.263520, Lat - 26.323305),

KHUDIGAON PT-I TO KOKRAJHAR DISTRICT BOUNDARY JIAGURI ROADPMGSY PACKAGE NO.AS-05-122(.)ROAD SURFACE DAMAGES IN STRETCHES DUE TO HEAVY RAIN & HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | KHUDIGAON PT-I | | (Long - 90.281991, Lat - 26.280649),

NH-31 AT JAMDUAR PART-I ROAD(.)ROAD SUBMERGED &SIDE BERM DAMAGES IN STRETCHES DUE TO HEAVY RAIN& HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | JAMDUAR PART-I ROAD | | (Long - 90.279005, Lat - 26.232869), NH-31 AT HAKAMA TO ANDURJHARROAD(.)ROAD SUBMERGED &SURFACE DAMAGES IN STRETCHES DUE TO HEAVY RAIN& HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) | HAKAMA TO ANDURJHARROAD | | (Long - 90.257558, Lat - 26.250739),

APPROACHES OF RCC BRIDGE NO. 11, 6 of DUE TO HIGH RISE HOUGH SOFT WAS GRAND AND AND AND AND AND AND AND AND AND			NAYERALGA GAURANGGHAT TO GUTIPARA PT-IV ROAD(,) (PMGSY PACKAGE NO. AS-05-41) SUBMERGED AT DIFFERENT STRETECHES ROAD SIDE BERM DAMAGES,THE
4-9) SUBMERGED AT DIFFERENT STRETICHES ROAD SIDE BERM DAMAGES, WASHED AWAY AT CHOSO M, DIET ON HIGH RISE FLOOD WATER OF RIVER GAURANG ATTREAL Damed (13/06/2022) to 17/06/2022) MAYERCHAR PI-VII [Long-90.184465, Lat-26.167563) LAKHHGAN LOTKO APMAR MOAD), KIND SUBMERGED SUBME BERM DAMAGES IN STRETCHES DUE TO HEAVY RAINE RIGHT ELOOD WATER OF RIVER GAURANG Dated (13/06/2022) to 17/06/2022) ANALYSHAR RAR ROAD [Long-90.22233, Lat-26.273892), SUAPATA PART-I KAJAIKATA PART-I ROAD/JROAD SUBMERGED & FORMATION DAMAGES IN STRETCHES DUE TO HEAVY RAINE RIGHT H-LOOD WATER OF RIVER BREAHMAPUTER Dated (13/06/2022) to 17/06/2022) SUAPATA PART-I KAJAIKATA PART-I ROAD [Long-90.28185], Lat-26.201845). SSESSARGAON IB. TO PAROURAROAD [Long-91.201867] (20/2018) SSESSARGAON IB. TO PAROURAROAD [Long-90.201867] (20/2018) HERODED DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) SISSASKAGAON IB. TO PAROURAROAD [Long-90.201867] (20/2018) HERODED DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) MASANERALGA HIGH SCHOOL TO HATIPOTA PT-II ROAD / SIDE BERM DAMAGED APPROACHES OF HEVEN OLY DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022) MASANERALGA HIGH SCHOOL TO HATIPOTA PT-II ROAD [Long-90.271875], at-26.201754], FUTISHARI GHUNGHUNIKHATA ROAD/SIDE BERM DAMAGED & APPROACHES OF BOX CELL-CLIVAPER NO. 11 & 92 IDUE TO HIGH BLOOD WATER OF RIVER GAURANG Dated (13/06/2022) MASANERALGA HIGH SCHOOL TO HATIPOTA PT-II ROAD [Long-90.2138], at-26.327923] Matia-Narapati PWD Road Narapati Alfected length - 0.400 Km and average depth of submeragene - 0.500 m (so no 17/06/2022), and benchmarkens; die berm, had crust damaged Long-90.21381, at-26.327923] Matia-Narapati PWD Road Narapati Alfected length - 0.400 Km and average depth of submeragene - 0.500 m (so no 17/06/2022). Read benabankens; die berm, had crust damaged Long-90.21381, at-26.327804, at-26.32880, at-26.32880, at-26.32880, at-26.32880, at-26.32880, at-26.32880, at-26.32880, at-26.32880, at-26.32880, a			· · · · · · · · · · · · · · · · · · ·
Dated (13:06:2022) in 17:06:2022) MYFRCHAR PT-VII (Long. 9:018:446; Lar. 26:16756), LAKIIGAN CHOKAPARA RAOAD, (NADA D'SUBMERGEDE SIZED BERM DAMAGES IN STRETCHES DUE TO HEAVY RAINS HIGH FLOOD WATER OF RIVER GAURANO Dated (13:06:02022) to 17:06:2022) [LAKHIGAN CHANPARA RAOAD (Long. 9:0.22332, Lat -26:273892), SLAPATA PART-I KAJAIKATA PART-I ROADD, ROAD SUBMERGED & PORNATION DAMAGES IN STRETCHES DUE TO HEAVY RAINS HIGH FLOOD WATER OF RIVER BRAHMAPUTRA Dated (13:06:0222) [SIMPATA PART-I HANATA PART-I ROAD] (Long. 9:02:18185, Lat -26:201845), SLESSARGAON IB. TO PAROURAROADD, PMGSY PACKAGE NO. AS-05-205-SIDE BERM ERRODED DUE TO HIGH FLOOD WATER OF RIVER ROAD (Long. 9:02:1855, Lat -26:201845), SLESSARGAON IB. TO PAROURAROADD, PMGSY PACKAGE NO. AS-05-205-SIDE BERM ERRODED DUE TO HIGH FLOOD WATER OF RIVER GAURANO Dated (30:06:2022) [J.17:06:2022)] SHESSARGAON IB. TO PAROURAROADD (Long. 9:02:1855), LAT-26:301754), PMGS (Long. 9:02:1755, Lat -26:201754), LAT-26:1755, LAT-26:201755, LAT-26:			42) SUBMERGED AT DIFFERENT STRETECHES ROAD SIDE BERM DAMAGES,WASHED
(13)06/2022 to 17)06/2022 [JEAKHIGAND CHOKAPARA ROAD (Long - 90) 222332, Lat - 26.273892). SUAPATA PART-I KAJAIKAT PART-I ROAD(),ROAD SUBMERGED & FORMATION DAMAGEN, IN STRETCHEN BUTTO HANDY RAIN& HIGH HIGH OOD WATER OF RIVER BRAHMAPUTRA Dated (13)06/2022 to 17/06/2022) [SUAPATA PART-I KAJAIKATA PART-I ROAD(), ROAD SUBMERGED & FORMATION DAMAGEN, IN STRETCHEN BUTTO HANDY RAIN& HIGH HIGH OOD WATER OF RIVER BRAHMAPUTRA DAted (13)06/2022 to 17/06/2022) [SUAPATA PART-I KAJAIKATA PART-I ROAD DE LOT HIGH FLOOD WATER OF RIVER GAURAND Dated (13)06/2022 to 17/06/2022) [SUAPATA PART-I KAJAIKATA PART-I ROAD DE TO HIGH FLOOD WATER OF RIVER GAURAND Dated (13)06/2022 to 17/06/2022) [MSSASARGAON I.B. TO PAROURAROAD [1] (J. ong - 90.203651, Lat - 26.301625), MASANERALGA HIGH SCHOOL TO HATTPOTA FT-IR ROAD MAGGED APPROACHES OF HICH ON 1/1 D. U. TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13)06/2022 to 17/06/2022) [PUTKBARA HIGH SCHOOL TO HATTPOTA FT-IR ROAD [1] (Long - 90.271/55, Lat - 26.201754). FUTKBARA GHINNOHUSHKHATA ROAD(),SIDE BERM DAMAGED & APPROACHES OF BOX CELL CLT-VERT NO. 1/1 & 16 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13)06/2022 to 17/06/2022) [PUTKBARA HIGH SCHOOL TO HATTPOTA FT-IR ROAD [1] (Long - 90.23183, Lat - 26.337933) Matia - Narapati PWD ROAD [Narapati Affected length - 0.400 Km and average depth of submergence - 0.500 m (s. on 17.06/2022). Road Embankment, side berm, hard crust damaged [Long - 90.37840] [Long - 90.37840] [Long - 90.27840] [Long			Dated (13/06/2022 to 17/06/2022) MAYERCHAR PT-VII (Long - 90.184465, Lat - 26.167563), LAKHIGANJ CHOKAPARA ROAD(.)ROAD SUBMERGED &SIDE BERM DAMAGES IN
SUAPATA PART-I KAJAIKATA PART-I ROADI, ROAD SUBMIRGEGE & FORMATION DAMAGES IN STRICTURES DUE: TO HEAVY RAINE HIGH FLOOD WATER OF RIVER BRAHMAPUTRA Dated (13/06/2022) to 17/06/2022) SUAPATA PART-I KAJAIKATA PART-I ROADI (Long. 9-02.8185 S. Lat. 9-2.0218545). SESSARGAON I.B. TO PAROURAROADI, PMGSY PACKAGE NO. AS-05-205, SIDE BIRRIN ERRODED DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022) SESSARGAON I.B. TO PAROURAROADI (Long. 9-02.03561. Lat. 2-2.361252), MASANERALGA HIGH SCHOOL. TO HATIPOTA PT-II ROADI, SIDE BIRRIN DAMAGED ATPROACHES OF HEV. NO. 1/1 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022) in 17/06/2022) MASANERALGA HIGH SCHOOL. TO HATIPOTA PT-II ROADI (Long. 90/2071755, Lat. 2-6.201754), FUTKIBARI GHUNGHUNIKHATA ROADI, SIDE BERM DAMAGED & APPROACHES OF BOX CEIL. CULIVER NO. 1/1 & 49 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022) to 17/06/2022) PUTKIBARI GHUNGHUNIKHATA ROADI) (Long. 90/213183, Lat. 2-6.237293) Matúa - Narapati PWD Road Narapati Affected length = 0.400 Km and average depth of submergence = 0.500 m (as on 17/06/2022). Side berm damaged as reported by PWRD. Dudhoin of submergence = 0.500 m (as on 17/06/2022). Side berm damaged as reported by PWRD. Dudhoin of Goalpara East Territorial Road Division, Goalpara Laffected length = 0.200 Km and average depth of submergence = 0.500 m (as on 17/06/2022). Side berm damaged as reported by PWRD. Dudhoin & Goalpara East Territorial Road Division, Goalpara Laffected length = 0.200 Km and average depth of submergence = 0.500 m (as on 17/06/2022). Side berm damaged as reported by PWRD, Dudhoin & Goalpara East Territorial Road Division, Goalpara Laffected length = 0.200 Km and average depth of submerged en company of the provided propriet of the Security of the			(13/06/2022 to 17/06/2022) LAKHIGANJ CHOKAPARA ROAD (Long - 90.222332, Lat -
SESSARGAON I.B. TO PAROURAROAD(JPMGSY PACKAGE NO. AS-05-205.SIDE BERM ERRODED DUE TO HIGH FILODO WATER OF RIVER GAURANG Dated (13:06:2022 to 17:06:2022) ISSSSARGAON I.B. TO PAROURAROAD (1.d.mg90.2035c1, Lat26.361/323), MASANERALGA HIGH SCHOOL TO HATHOTA PT-II ROAD(), SIDE BERM DAMAGED APPROACHES OF HPC NO. 17 DUE TO HIGH FILODO WATER OF RIVER GAURANG Dated (13:06:2022 to 17:06:2022) MASANERALGA HIGH SCHOOL TO HATHOTA PT-II ROAD (1.d.mg90.217355, Lat26.201754), FUTKIBARI GHUNGHUNIKHATA ROAD(), SIDE BERM DAMAGED & APPROACHES OF BOX CTLL CULVERT NO. 1/1 & 49 DUE TO HIGH FILODO WATER OF RIVER GAURANG Dated (13:06:2022 to 17:06:2022) FUTKIBARI GHUNGHUNIKHATA ROAD(), SIDE BERM DAMAGED & APPROACHES OF BOX CTLL CULVERT NO. 1/1 & 49 DUE TO HIGH FILODO WATER OF RIVER GAURANG Dated (13:06:2022 to 17:06:2022) FUTKIBARI GHUNGHUNIKHATA ROAD (1.d.mg90.213183, Lat26.3729233) Matia Narpati PWD Road Narpati Affected length = 0.400 Km and average depth of submergence = 0.500 m (as on 17:06:2022). Road Embankment, side berm, hard crust duranged (Long90.705262, Lat26.036800), Leta to Guabara Hood Long90.705262, Road Embankment, side berm, hard rost duranged (Long90.705262, Lat26.036800), Leta to Guabara Hood Long90.704222). Road Embankment, side berm, hard rost duranged (Long90.704222). Road Embankment, side berm, hard average depth of submergence = 0.500 m (as on 17:06:2022). Road Embankment, side berm, hard rost duranged (Long90.70422). Road Embankment, side berm and average depth of submergence = 0.500 m (as on 17:06:2022). Road Embankment PWRD, Dudhio & Gool Bankment Road Division, Gool Bankment Road Division, Gool Bankment Road Division, Gool Bankment Road Division, Gool Bankm			SUAPATA PART-I KAJAIKATA PART-I ROAD(.)ROAD SUBMERGED & FORMATION DAMAGES IN STRETCHES DUE TO HEAVY RAIN& HIGH FLOOD WATER OF RIVER BRAHMAPUTRA Dated (13/06/2022 to 17/06/2022) SUAPATA PART-I KAJAIKATA PART-I
APPROACHES OF HPC'NO, 1/1 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (33062022 to 1706/2022) [MASANERALGA HIGH SCHOOL TO HATIPOTA PT-II ROAD (Long - 90.271755, Lat - 26.201754), FUTKIBARI GHUNGHUNIKHATA ROAD (Long - 90.271755, Lat - 26.201754), FUTKIBARI GHUNGHUNIKHATA ROAD (Long - 90.2718183, Lat - 26.237293) Matia - Narapati PWD Road Narapati Affected length = 0.400 Km and average depth of submergence = 0.500 m (as on 17.06/2022). Road Embankment, side berm, hard crust damaged (Long - 90.705262, Lat - 26.936800), Lela to Guabara Road Lela Affected length = 0.400 Km and average depth of submergence = 0.500 m (as on 17.06/2022). Road Embankment, side berm, hard crust damaged (Long - 90.705262, Lat - 26.936800), Lela to Guabara Road Lela Affected length = 0.800 Km and average depth of submergence = 0.600 m (as on 17.06/2022). Road Embankment, side berm, hard crust damaged (Long - 90.705262, Lat - 26.036800), Lela to Guabara Road Lela Affected length = 0.200 Km and average depth of submergence = 0.600 m (as on 17.06/2022). Road Breached as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.742499, Lat - 26.0056248), Upartola Dohela to Hirapara Road Upartola Affected length = 0.200 Km and average depth of submergence = 0.500 m (as on 17.06/2022). Road Breached as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.742499, Lat - 26.0550022) Rangia - Danish Ali Road Village Barkukuria Danish Ali road is partilly damaged as the road is fully submerged for a stretch of 2 km as per report of AEE, PWD NKT, Roads, Rangia on 17.06/2022 (Long - 0.00000), Lat - 0.00000), Kayan - Bagalis road near Choumukha Bazar chowk, Dubhi Balisatra road near Bathan, Garamsung Gorput road, Kamalputh Morowa road at Baranghati Bokultol, Kayan Rampith road side berm and one culvert damaged. Kayan Revenue Circle, Date: 17.06/2022. Reported by PWRD Ha) Division. GPS co-ordinates couldn't be provided at the moment.			SESSARGAON I.B. TO PAROURAROAD(,)PMGSY PACKAGE NO. AS-05-205,SIDE BERM ERRODED DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) SESSARGAON I.B. TO PAROURAROAD (Long - 90.203561, Lat - 26.361252),
FUTKIBARI GHUNGHUNIKHATA ROAD_(SIDE BERM DAMAGED & APPROACHES OF BOX CELL. CUL.YRET NO. 11.4 & 50 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) FUTKIBARI GHUNGHUNIKHATA ROAD (Long - 90.213183, Lat - 26.337923) Matia - Narapati PWD Road Narapati Affected length = 0.400 Km and average depth of submergence = 0.500 m (as on 17/06/2022), Road Embankment, side berm, hard crust damaged (Long - 90.705262, Lat - 26.036800), Lela to Guabari Road Lela Affected length = 0.800 Km and average depth of submergence = 0.600 m (as on 17/06/2022). Side berm damaged as reported by PWRD, Dudhoni & Goalpara East Territorial Road Division, Goalpara (Long - 90.70548), Upartola Dohela to Hirapara Road Upartola Affected length = 0.200 Km and average depth of submergence = 0.500 m (as on 17/06/2022), Road Breached as reported by PWRD, Dudhoni & Goalpara East Territorial Road Division, Goalpara (Long - 90.786417, Lat - 26.059022) Rangia - Danish Ali Road Village Barkukria Danish Ali road is partilly damaged as the road is fully submerged for a stretch of 2 km as per report of AEE, PWD NF, Roads, Rangia on 17.06.2022 (Long - 0.000000, Lat - 0.000000), Kayan - Bagals road near Choumukha Buzar chowk, Dhuhi Balisatra road near Bathan, Garamsung Gorput road, Kamalpur Morowa road at Baranghati Bokultol, Kayan Kampith road side berm and one culvert damaged. Kayan Revenue Circle. Date: 17/06/2022. Reported by PWRD hajo Division. GPS co-ordinates couldn't be provided at the moment. (Long - 0.00000), Kamalpur - Kamalpur Borka Road Vill-Ramalpur Total length of road 8 KM, Submerged at 4th.5th & 6th KM & Depth of submerged.45 on 17/06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.334810, Lat - 91.668256). Bathan road part 1 Vill-Bathan Total length of road 4.687 KM, Submerged length 910 M & Depth of submerged of M on 17/06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Lon			APPROACHES OF HPC NO. 1/1 DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) MASANERALGA HIGH SCHOOL TO HATIPOTA PT-II ROAD
Matia - Narapati PWD Road Narapati Affected length = 0.400 Km and average depth of submergence = 0.500 m (as on 17/06/2022). Road Embankment, side berm, hard crust damaged (Long 90.705262, Lat 26.036800), Lel a to Guabari Road Lela Affected length = 0.800 Km and average depth of submergence = 0.600 m (as on 17/06/2022). Side berm damaged as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long 90.74249), Lat 26.006248), Upartoia Dohela to Hirapara Road Upartola Affected length = 0.200 Km and average depth of submergence = 0.500 m (as on 17/06/2022). Road Breached as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long 90.786417, Lat 26.059022) Rangia - Danish Ali Road Village Barkukuria Danish Ali road is partilly damaged as the road is fully submerged for a stretch of 2 km as per report of AEE, PWDN NKT, Roads, Rangia on 17.06.2022 (Long 0.000000), Lat 0.000000), Lat 0.0000000), Lat 0.0000000), Lat 0.0000000), Lat 0.0000000, Lat 0.0000000), Lat 0.0000000, Lat 0.00000000, Lat 0.0000000, Lat 0.0000000, Lat 0.0000000, Lat			FUTKIBARI GHUNGHUNIKHATA ROAD(,)SIDE BERM DAMAGED & APPROACHES OF BOX CELL CULVERT NO. 1/1 & ½ DUE TO HIGH FLOOD WATER OF RIVER GAURANG Dated (13/06/2022 to 17/06/2022) FUTKIBARI GHUNGHUNIKHATA ROAD (Long -
submergence = 0.500 m (as on 17/06/2022). Road Embankment, side berm, hard crust damaged (Long - 90.705262, Lat - 26.036800), Lela to Guabari Road Lela Affected length = 0.800 Km and average depth of submergence = 0.600 m (as on 17/06/2022). Side berm damaged as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.7042499, Lat - 26.006248), Upartola Dohela to Hirapara Road Upartola Affected length = 0.200 Km and average depth of submergence = 0.500 m (as on 17/06/2022). Road Breached as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.786417, Lat - 26.059022) Rangia - Danish Ali Road Village Barkukuria Danish Ali road is partilly damaged as the road is fully submerged for a stretch of 2 km as per report of AEE, PWD NKT, Roads, Rangia on 17.06.2022 (Long - 0.000000, Lat - 0.000000), Kayan - Bagals road near Choumukha Bazar chowk, Dhuhi Balisatra road near Bathan, Garansung Gorput road, Kamalpur Morva road at Barnaghati Bokultok, Kayan Kampith road side berm and one culvert damaged. Kayan Revenue Circle. Date: 17/06/2022. Reported by PWRD Hajo Division. GPS co-ordinates couldn't be provided at the moment. (Long - 0.000000, Lat - 0.000000), Kamalpur - Kamalpur Borka Road Vill-Kamalpur Total length of road 8 KM, Submerged at 4th,5th & 6th KM & Depth of submerged.45 on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.324351, Lat - 91.168256), Bathan road part 1 Vill-Bathan Total length of road 4.687 KM, Submerged length 3.5 KM & Depth of submerged and (Long - 26.354810, Lat - 91.181437), Malibari high school to padumpukhuri part 1 Vill-Malibari Total length of road 1.268 KM, Submerged length 900 M & Depth of submerged a.60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.337873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.41 KM, Submerged			
Martin M			submergence = 0.500 m (as on 17/06/2022). Road Embankment, side berm, hard crust damaged (Long - 90.705262, Lat - 26.036800),
Upartola Dohela to Hirapara Road Upartola Affected length = 0.200 Km and average depth of submergence = 0.500 m (as on 17/06/2022). Road Breached as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.786417, Lat - 26.059022) Rangia - Danish Ali Road Village Barkukuria Danish Ali road is partilly damaged as the road is fully submerged for a stretch of 2 km as per report of AEE, PWD NKT, Roads, Rangia on 17.06.2022 (Long - 0.000000), Kayan - Bagals road near Choumukha Bazar chowk, Dhuhi Balisatra road near Bathan, Garamsung Gorput road, Kamalpur Morowa road at Baranghati Bokultol, Kayan Kampith road side berm and one culvert damaged. Kayan Revenue Circle. Date: 17/06/2022. Reported by PWRD Hajo Division. GPS co-ordinates couldn't be provided at the moment. (Long - 0.000000), Kamalpur - Kamalpur Borka Road Vill-Kamalpur Total length of road 8 KM, Submerged at 4th,5th & 6th KM & Depth of submerged.45 on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.324351, Lat - 91.668256), Bathan road part 1 Vill-Bathan Total length of road 4.687 KM, Submerged length 3.5 KM & Depth of submerged. 75 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.354810, Lat - 91.811437), Malibari high school to padumpukhuri part 1 Vill-Malibari Total length of road 1.268 KM, Submerged length 900 M & Depth of submerged.60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.357847, Lat - 91.795740), Malibari high school to padumpukhuri part 2 Vill-Malibari Total length of road 1.19 KM, Submerged length 1 KM & Depth of submerged.60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged	Goalpara	3	m (as on 17/06/2022). Side berm damaged as reported by PWRD, Dudhnoi & Goalpara East
fully submerged for a stretch of 2 km as per report of AEE, PWD NKT, Roads, Rangia on 17.06.2022 (1.cng - 0.000000), Lat - 0.000000), Kayan - Bagals road near Choumukha Bazar chowk, Dhuhi Balisatra road near Bathan, Garamsung Gorput road, Kamalpur Morowa road at Baranghati Bokultol, Kayan Kampith road side berm and one culvert damaged. Kayan Revenue Circle. Date: 17/06/2022. Reported by PWRD Hajo Division. GPS co-ordinates couldn't be provided at the moment. (Long - 0.000000, Lat - 0.000000), Kamalpur - Kamalpur Borka Road Vill-Kamalpur Total length of road 8 KM, Submerged at 4th.5th & 6th KM & Depth of submerged.45 on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.324351, Lat - 91.668256), Bathan road part 1 Vill-Bathan Total length of road 4.687 KM, Submerged length 3.5 KM & Depth of submerged.75 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.354810, Lat - 91.811437), Malibari high school to padumpukhuri part 1 Vill-Malibari Total length of road 1.268 KM, Submerged length 900 M & Depth of submerged.60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375847, Lat - 91.795740), Malibari high school to padumpukhuri part 2 Vill-Malibari Total length of road 1.19 KM, Submerged length 15 KM & Depth of submerged.60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.64 KM, Submerged length 950 M & Depth of submerged.60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.367159, Lat - 91.800542) Chandrapur - gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE , PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali t			submergence = 0.500 m (as on 17/06/2022). Road Breached as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.786417, Lat - 26.059022)
Kayan - Bagals road near Choumukha Bazar chowk, Dhuhi Balisatra road near Bathan, Garamsung Gorput road, Kamalpur Morowa road at Baranghati Bokultol, Kayan Kampith road side berm and one culvert damaged. Kayan Revenue Circle. Date: 17/06/2022. Reported by PWRD Hajo Division. GPS co-ordinates couldn't be provided at the moment. (Long - 0.000000), Lat - 0.000000), Kamalpur - Kamalpur Borka Road Vill-Kamalpur Total length of road 8 KM, Submerged at 4th,5th & 6th KM & Depth of submerged.45 on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.324351, Lat - 91.668256), Bathan road part 1 Vill-Bathan Total length of road 4.687 KM, Submerged length 3.5 KM & Depth of submerged .75 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.354810, Lat - 91.811437), Malibari high school to padumpukhuri part 1 Vill-Malibari Total length of road 1.268 KM, Submerged length 900 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375847, Lat - 91.795740), Malibari high school to padumpukhuri part 2 Vill-Malibari Total length of road 1.19 KM, Submerged length 1 KM & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796718), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of			fully submerged for a stretch of 2 km as per report of AEE, PWD NKT, Roads, Rangia on 17.06.2022
GPS co-ordinates couldn't be provided at the moment. (Long - 0.000000, Lat - 0.000000), Kamalpur - Kamalpur Borka Road Vill-Kamalpur Total length of road 8 KM, Submerged at 4th,5th & 6th KM & Depth of submerged.45 on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.324351, Lat - 91.668256), Bathan road part 1 Vill-Bathan Total length of road 4.687 KM, Submerged length 3.5 KM & Depth of submerged .75 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.354810, Lat - 91.811437), Malibari high school to padumpukhuri part 1 Vill-Malibari Total length of road 1.268 KM, Submerged length 900 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375847, Lat - 91.795740), Malibari high school to padumpukhuri part 2 Vill-Malibari Total length of road 1.19 KM, Submerged length 1 KM & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.367159, Lat - 91.800542) Chandrapur - gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 Date - 15/06/2022 (Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Balapara Bazar to Jalabila village Road Jalabila ON 18-06-2022 (Long -			Gorput road, Kamalpur Morowa road at Baranghati Bokultol, Kayan Kampith road side berm and one
Kamrup Namrup PWD North KMP Territorial road division rangia (Long - 26.324351, Lat - 91.668256), Bathan road part 1 Vill-Bathan Total length of road 4.687 KM, Submerged length 3.5 KM & Depth of submerged .75 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.354810, Lat - 91.811437), Malibari high school to padumpukhuri part 1 Vill-Malibari Total length of road 1.268 KM, Submerged length 900 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375847, Lat - 91.795740), Malibari high school to padumpukhuri part 2 Vill-Malibari Total length of road 1.19 KM, Submerged length 1 KM & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.367159, Lat - 91.800542) Chandrapur - gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 Date - 15/06/2022 (Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Balapara Bazar to Jalabila village Road Jalabila ON 18-06-2022 (Long -			GPS co-ordinates couldn't be provided at the moment. (Long - 0.000000, Lat - 0.000000),
of submerged .75 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.354810, Lat - 91.811437), Malibari high school to padumpukhuri part 1 Vill-Malibari Total length of road 1.268 KM, Submerged length 900 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375847, Lat - 91.795740), Malibari high school to padumpukhuri part 2 Vill-Malibari Total length of road 1.19 KM, Submerged length 1 KM & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.367159, Lat - 91.800542) Chandrapur - gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 Date- 15/06/2022 (Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Balapara Bazar to Jalabila village Road Jalabila ON 18-06-2022 (Long -			PWD North KMP Territorial road division rangia (Long - 26.324351, Lat - 91.668256),
Submerged length 900 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375847, Lat - 91.795740), Malibari high school to padumpukhuri part 2 Vill-Malibari Total length of road 1.19 KM, Submerged length 1 KM & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.367159, Lat - 91.800542) Chandrapur - gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 Date- 15/06/2022 (Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Balapara Bazar to Jalabila village Road Jalabila ON 18-06-2022 (Long -	Kamrup	11	of submerged .75 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.354810, Lat - 91.811437),
Submerged length 1 KM & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.375873, Lat - 91.796018), NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.367159, Lat - 91.800542) Chandrapur - gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 Date- 15/06/2022 (Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Balapara Bazar to Jalabila village Road hs been affected at Jalabila ON 18-06-2022 (Long -			Submerged length 900 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive
NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North KMP Territorial road division rangia (Long - 26.367159, Lat - 91.800542) Chandrapur - gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 Date- 15/06/2022 (Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Balapara Bazar to Jalabila village Road hs been affected at Jalabila ON 18-06-2022 (Long -			Submerged length 1 KM & Depth of submerged .60 M on 17.06.2022 as per report of the Executive
Kamrup (M) Chandrapur - gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 Date- 15/06/2022 (Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Balapara Bazar to Jalabila village Road hs been affected at Jalabila ON 18-06-2022 (Long -			NH-52 to Dumnichowki Vill-Dumnichowki Total length of road 1.641 KM, Submerged length 950 M & Depth of submerged .60 M on 17.06.2022 as per report of the Executive Engineer PWD North
Kamrup (M) Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 Date- 15/06/2022 (Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Balapara Bazar to Jalabila village Road hs been affected at Jalabila ON 18-06-2022 (Long -			
(Long - 92.001066, Lat - 26.231869) Bagribari - Balapara Bazar to Jalabila village Road Jalabila As reported by concerned LR staff, Kokrajhar 1 Balapara Bazar to Jalabila village Road hs been affected at Jalabila ON 18-06-2022 (Long -		1	Iinformation received from AEE ,PWD(R)Jagiroad sub division lat: 26.231869 long: 92.001066 gobhali to nalini path(PM GSY Pkg NO AS 11613)Submerged at 2nd and 3rd KM. Iinformation
Kokrajhar 1 Balapara Bazar to Jalabila village Road hs been affected at Jalabila ON 18-06-2022 (Long -			(Long - 92.001066, Lat - 26.231869)
	Kokrajhar	1	Balapara Bazar to Jalabila village Road hs been affected at Jalabila ON 18-06-2022 (Long -

		Subansiri - Gogamukh to Ghilamara Road As reported by the Dhakuakhana Territorial Road
Lakhimpi	r 5	Division, Ghilamara the Road from Gogamukh to Ghilamra Road (SH-22) is overtopped at 18th KM, (L= 30M) on 17/06/2022 (Long - 0.000000, Lat - 0.000000), Chakuli to Basudevthan Road As reported by the Dhakuakhana Territorial Road Division, Ghilamara the Road from Chakuli to Basudevthan Road is submerged at 2nd Km (CH. 1150M to CH. 1350 M), (L= 5M) on 17/06/2022 (Long - 0.000000, Lat - 0.000000), Bihpuria - Road from 65/68 Grant to Meneha At Ch. 35.00 m Road embankment and shoulders are eroded and damaged badly due to flood water spillover on 18th June 2022 as reported by AEE, PWD R, Bihpuria TRSD (Long - 93.922991, Lat - 27.089794), North Lakhimpur - Dhalghat Ghunasuti (DK) Road. Dhalghat Due to incessant rain heavy erosion occurred at chainage 6900.00m on Dhalghat Ghunasuti (DK) Road as repoted by PWD Territorial Road Divn., North Lakhimpur Divn. on 17-06-2022. (Long - 0.000000, Lat - 0.000000), Kadam - The road NH-15 at Boginadi to Khalihamari road is damaged including previously executed temporary protection work from CH.500.00M to CH.550.00M(L=50.00M) informed by PWD Road, date 18/06/2022 NH-15 at Boginadi to Khalihamari Damaged due to heavy rainfall (Long -
		27.322964, Lat - 94.158255)
Majuli	3	Majuli - Bhakat Chapori road and Birinabari road Bhakat Chapori - GPS location: 26.95666667° Longitude 94.09500000° Birinabari - GPS location: Lattitude 26.92611111° Longitude 94.10777778° 1. Bhakat Chapori road submerged in stretch of 30m and 60m on 18.06.2022 in approx 80 cm depth. 2. Side slope erosion at Birinabari road on 18.06.2022 due to incessant rain. (Long - 0.000000, Lat - 0.000000), Ujani Majuli - Bogaon to Salmora road Bongaon Bongaon to Salmora road submerged on 18.06.2022 due to rising of water level of river Brahmaputra (Long - 94.290306, Lat - 26.953365)
		Bhuragaon - Barduba Tup to Pachali Road Baraduba Tup Badly damaged by due to incessant rain
Morigaor	7	on 17-06-2022 (Long - 26.397233, Lat - 92.233563), Taptola to Barunguri Raod Taptoal Eroded by Heavy rainfall at Chainage 2650.00 M on 17-06-2022 (Long - 26.346693, Lat - 92.172517), Tengaguri Falihamari Road Dhakin Tengaguri Eroded & Damaged side berm and hardcrust at 1st and 2nd KM due to incessant rain on 17-06-2022 (Long - 26.398708, Lat - 92.277199), Mayong - Sildubi -Gagalmari pt-II 2nd & 6th km Road Submerged as reported by PWD Morigaon district territorial road division on 17/06/22 (Long - 92.129000, Lat - 26.267000), Karatipam Bazar to Chotogarjan Road Submerged at 2nd km Road Submerged as reported by PWD Morigaon district territorial road division on 17/06/22 (Long - 92.170000, Lat - 26.278000), Morisutiup to Murkata No.1 road submerged at 3rd and 4th km Road Submerged as reported by PWD Morigaon District Territorial Road Division on 18/06/22 (Long - 92.043000, Lat - 26.269000), Morigaon - KHANDAJAN BAKORICHAPARI SINGIMARI ROAD (18-06-2022) KHANDAJAN, MORIGOAN As per PWD, Road Territorial Division, Erosion occured due to 2nd wave of flood at approach of the culvert no.1/1 of "KHANDAJAN BAKORICHAPARI SINGIMARI " road under PMGSY PKG No. AS-17-88 (Long - 92.306365, Lat - 26.230976)
		Kampur - Kampur to Kathiatoli Manohar Gaon Subway breached on dated 17.06.2022 L-45 M at
Nagaon	1	Manohar Gaon constructed for emergency services after 1st wave of flood on the Kampur Kathiatoli Road by Barhampur Territorial Road Division. (Long - 0.000000, Lat - 0.000000)
Nalbari	31	Nalbari - BBNG to Bhuyarkuchi Road Bhuyarkuchi As per the report received from PWRd deptt vide memo no 1782 dates 17.06.2022 BBNG to Bhuyarkuchi bridge approach damaged due to flood (Long - 0.000000, Lat - 0.000000), Kharjara Road Kharjara As per the report received from PWRD deptt vide memo no 1782 dates 17.06.2022 Kharjara road side berm eroded due to flood (Long - 0.000000, Lat - 0.000000), Barkura Road Barkura road via Jagadish Sarma House to Munin Talukdar and Via Bijoy Sarma to end of Rabin Sarma house Kazipara road As per the report received from PWRD deptt vide memo no 1782 dates 17.06.2022 barkura road via Jagadish Sarma House to Munin Talukdar and Via Bijoy Sarma to end of Rabin Sarma house Kazipara road due to flood water (Long - 0.000000, Lat - 0.000000), Amayapur Bhadra Road amayapur As per the report received from PWRD deptt vide memo no 1981-87 dates 17.06.2022 , amayapur Bhadra road submerged due to rain water (Long - 0.000000, Lat - 0.000000), Majdia Terechia Road majdia As per the report received from PWRD deptt vide memo no 1981-87 dates 17.06.2022 , Majdia Terechia road submerged due to rain water (Long - 0.000000, Lat - 0.000000), Hajo Nalbari Road Alingidal kabarsthan to Tilana LP school As per the report received from PWRD deptt vide memo no 1981-87 dates 17.06.2022 , Hajo Nalbari road at Alengidal kabarsthan to Tilana LP schoolsubmerged due to rain water (Long - 0.000000), Hajo Nalbari Road Choudhury suburi to tilana Harimandir As per the report received from PWRD deptt vide memo no 1981-87 dates 17.06.2022 , Hajo Nalbari road at Choudhury suburi to tilana Harimandir submerged due to rain water (Long - 0.000000, Lat - 0.000000), Hajo Nalbari Road Bala Mugkuchi as per the report of PWRD, Hajo Nalbari Road at Bala Mugkuchi Road submerged due to rain water PORD, Collage Balajan road balajan As per the report of PWRD, Collage balajan road is submerged due to

ı	1	,
		rain water Dated: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Shyama Rai Mandir Namati Road Shyam rai Mandir As per the report of PWRD, Namati Road at
		Shyamrai Mandir to Bishuhari Than Submerged due to flood Dated: 17/06/2022 (Long - 0.000000,
		Lat - 0.000000), Bidyapur Bye Lane no 17 Bidyapur As per the report of PWRD, Bidyapur bye lane submerged due
		to rain water Dated: 17/06/2022 (Long - 0.000000, Lat - 0.000000),
		Kumarikata to Niz Bahjani road Niz Bahjani As per the report received from PWRD, Kumarikata to Niz Bahjani road submerged due to rain water Dated: 17/06/2022 (Long - 0.000000, Lat -
		0.000000),
		Jaha to Charia Road Jaha As per the report received from PWRD, Jaha to Charia road submerged due to rain water Dated: 17/06/2022 (Long - 0.000000, Lat - 0.000000),
		NH-31 to Katla Barkuchi Road Katla Barkuchi As per the report received from PWRD, NH-31 to
		Katla Bqarkuchi Road submerged due to flood Dated: 17/06/2022 (Long - 0.000000, Lat - 0.000000),
		Deharkalakuchi to Makaldaba road Deharkalakuchi As per the report received from PWRD, Deharkalakuchi to Makaldaba Road submerged due to rain water Dated: 17/06/2022 (Long -
		0.000000, Lat - 0.000000),
		DC bunglow approach road dc cunglow as per the report from PWRD, DC bunglow approach road
		submerged and culvert damaged, Dated: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Sariyahtoli to NH 32 road sariyahtali as per the report from PWRD, Sariyahtoli to NH-32 road
		submerged due to flood, Dated: 17/06/2022 (Long - 0.000000, Lat - 0.000000),
		Planetarium approach Road sariyahtali as per the report received from PWRD, Nalbari Planetarium approach road, sariyahtali submerged due to flood Dated: 17/06/2022 (Long - 0.000000, Lat - 0.000000),
		Barkhetri - galdighla village road galdighla due to flood water it is submerged,, length 180m as
		reported by AEE,, PWRD, Barkhetri territorial sub div on 18/06/2022 (Long - 0.000000, Lat - 0.000000),
		kuriha sungorbori road kuriha sungorbori due to flood water it is submerged,, length 1450m as reported by AEE,, PWRD, Barkhetri territorial sub div on 18/06/2022 (Long - 0.000000, Lat - 0.000000),
		gopalthan to darmon borosupa road naptipara nadirpar overtopped due to incessant rain, length
		1500m as reported by AEE,, PWRD, Barkhetri territorial sub div on 18/06/2022 (Long - 0.000000, Lat - 0.000000),
		Barbhag - Barbari Nanoi Narapra Road Dated : 18/06/2022 Near Nanoi LP School Washed away
		and eroded Dated : 18/06/2022 (Long - 0.000000, Lat - 0.000000), Coil INdustry Road Katpuha Overtop. Death : 40mm Length : 1.90 K.M. Dated : 18/06/2022
		(Long - 0.000000, Lat - 0.000000),
		Ulabari M.V. Road Ulabari Overtop. Death : 30mm Length : 1 K.M. Dated : 18/06/2022 (Long - 0.000000, Lat - 0.000000),
		Hajo Nalbari Road to Bhabanipur Bhabanipur Overtop. Death : 30mm Length : 300 mtr Dated :
		18/06/2022 (Long - 0.000000, Lat - 0.000000), Arikuchi Loharkatha to Bhabanipur Arikuchi Overtop. Death : 45mm Length : 1 K.M. Dated :
		18/06/2022 (Long - 0.000000, Lat - 0.000000),
		Bezkuchi to Dekarkhat Dekarkhat Overtop. Death : 75mm Length : 1.90 K.M. Dated : 18/06/2022 (Long - 0.000000, Lat - 0.000000),
		Marowa satra to Marowa Hatkhola Marowa Overtop. Death : 40mm Length : 1. K.M. Dated :
		18/06/2022 (Long - 0.000000, Lat - 0.000000) Thelamara - NH15 TO THELAMARA ROHINIBILL ROAD ROHINIBILL As reported by PWD
		Dhekiajuli Territorial Road Sub-division on 18/06/2022, due to surging water of Belsiri river has
		damaged the embankment, shoulder uoto hard crust on 16th June 2022 on NH-15 to Thelamara Rohinibill road is submerged at CH 1000.00M to 1250.00M and at CH. 1500M to 1700M. (Long -
		0.000000, Lat - 0.000000),
		Chariduar - NH 15 BALIPARA TO LAKHIMPUR ROAD DTD 18/06/2022 CHARIDUAR
		REVENUE CIRCLE (Long - 92.780621, Lat - 26.822363), NH 15 BAMUNGOLA TO MANSIRI CENTRE ROAD DTD 18/06/2022 CHARIDUAR
Sonitpur	7	REVENUE CIRCLE (Long - 92.788867, Lat - 26.756859),
]	UROHILOGA TO MANSIRI ROAD DTD 18/06/2022 CHARIDUAR REVENUE CIRCLE
		TUBUKJHAR TO BAMUNGOLA ROAD DTD 18/06/2022 CHARIDUAR REVENUE CIRCLE
		(Long - 92.799099, Lat - 26.897557), GUDAMGHAT MIRI TO NH 15, 18TH MILE 3370.M TO 3460 M ERODED DTD 18.06.2022
		CHARIDUAR REVENUE CIRCLE (Long - 92.793387, Lat - 26.794587),
		Tezpur - Napam Via Bhalukjarani Road Solmara dated:18/06/2022. As reported by PWD (Roads)
		Borguri Solmara napamVia Bhalukjharani newly completedpmgsy road of package no AS-22-675 at ch from 30m to ch 300m 9part B. Length affected 270.00 m (Long - 92.800180, Lat - 26.690117)
South	6	Mankachar - 1.Hallidayganj Mankachar Road 2.Dhanua PMGSY Road 3.Jangal Chariali PMGSY
Salmara		Road 4.H.K Road 5.Diara kalapani Road 6.Sadullabari Kalapani Road 1.Halidaganj to Mankachar

	1	1	
			2.Dhanua 3.Jangal Chariali 4. Kalair Alga 5. Diara to Kalapani. 6.Sadullabari To Kalapani. As per report submitted PWRD Mankachar Territorial Road sub-Division Mankachar road damaged due to heavy rain fall on 16/06/22. The details as shown below:- 1.Road surface of halliday ganj Mankachar Road has badly damaged due to heavy rain. 2. HM Road to Dhanua PMGSY road has submerged from 1st KM to 4th by flash flood water. 3. Road surface and side berm of PMGSY road Jangal Chariali to Puthimari Bazar has damaged due to heavy rain . 4. Road surface and side berm of road from H.K road to Kalairalga has damaged due to heavy rain . 5. Road surface and side berm of Diara kalapani has damaged due to heavy rain fall. 6. Road surface and side berm of sadullabari kalapani road has damaged due to heavy rain fall. (Long - 25.595986, Lat - 89.918953)
	Total	219	
	District	Numbe	Details
	District	r	
	Bajali	2	Sarupeta - puran bhabanipur to sarupeta bridge, puran bhabanipur report received from concerned LM on 18/06/2022 (Long - 91.310000, Lat - 26.290000), luwashur to sarupeta road sarupeta report received from concerned LM on 18/06/2022 (Long - 91.060000, Lat - 26.490000)
Infrastructur e Damaged - Bridge	Morigaon	1	Morigaon - RCC Bridge No. 1/1 over river Killing 18/06/2022 Kuthuribagisa Bridge approaches of RCC Bridge No. 1/1 over river Killing on NH-37 to Kuthuribagisa Road eroded. (Long - 92.297482, Lat - 26.089079)
	Nalbari	1	Nalbari - RCC Br No 1/1 Patkata Dhekiabari road as per the report of PWRD, RCC BR no 1/1 on Patkata Dhekiabari Road approach damaged Dated: 17/06/2022 (Long - 0.000000, Lat - 0.000000)
	Sonitpur	1	Dhekiajuli - Keherukhanda to Katalu Dub PWD road Rcc bridge approach damaged due to water action. dated 17.6.22 Keherukhanda to Katalu Dub PWD road Rcc bridge approach damaged due to water action. dated 17.6.22 (Long - 92.533161, Lat - 26.724542)
	Total	5	
Infrastructur	District	Wildlife a	affected under protected areas description
e Damaged - Wildlife	Morigaon		- Pobitora WLS Out of a total of 25nos of Camp 15nos of camps were affected and 2nos of camps were as reported by Range Officer PWLS on 18/06/2022
	District	Other De	etails et al. 1 de la company de la comp
Infrastructur e Damaged - Others	Baksa	Mayong - Pobitora WLS Out of a total of 25nos of Camp 15nos of camps were affected and 2nos of camps were inundated as reported by Range Officer PWLS on 18/06/2022 Other Details Baska - Culvert Approach Road Damaged DUE TO HEAVY RAIN SUZIT NARZARY ROAD AT 2NO KATLIGAON RAVA SUPA SLAB CULVERT APPROACHE DAMAGED ON DT. 16/06/2022 91°21'37.31"E 26°38'49.07"N at Village Katligaon Rabha Supa, Culvert Approach Road Damaged DUE TO HEAVY RAIN SILPATA TO POLASH CHAWK VIA DWIMUGURI ROAD CULVERT APPROACHE DAMAGED ON DT. 16/06/2022 91°21'43.83"E 26°41'3.83"N at Village Motipur DWIMUGURI, Culvert Approach Road Damaged DUE TO HEAVY RAIN KAREMURA TO NIKASHI ROAD HP CULVERT DAMAGED ON DT. 16/06/2022 91°18'3.83"E 26°34'23.34"N at Village Choudhiritrop, Culvert Approach Road Damaged DUE TO HEAVY RAIN BATHOPURI TO KOLA CHAWK ROAD SLAB CULVERT DAMAGED AT MOTIPUR ON DT. 16/06/2022 91°21'30.05"E 26°40'36.68"N at Village Amarabati, Culvert Approach Road Damaged DUE TO HEAVY RAIN GARAMDEW TO BHEBARI ROAD AT PATABARI SUPA CULVERT APPROACHE DAMAGED ON DT. 16/06/2022 91°21'30.05"E 26°40'1.21"N at Village Geramdeu, Culvert Approach Road Damaged DUE TO HEAVY RAIN GARAMDEW TO AMRAGURI ROAD CULVERT APPROACHE DAMAGED ON DT. 16/06/2022 91°18'14.66'2"E 26°40'1.21"N at Village Geramdeu, Culvert Approach Road Damaged DUE TO HEAVY RAIN GARAMDEW TO AMRAGURI ROAD CULVERT APPROACHE DAMAGED ON DT. 16/06/2022 91°18'12.39"E 26°39'56.91"N at Village Garamdew Amraguri, Culvert Approach Road Damaged DUE TO HEAVY RAIN UZIRBARI SLAB CULVERT APPROACHE ERODED ON DT. 15/06/2022 91°18'7.58"E 26°38'3.138"N at Village Ujirbari, Culvert Approach Road Damaged ROAD & CULVERT SIDE DAMAGED AT L36 to SANGBAN KHUTI ROAD UNDER PMGSY ON DT. 15/06/2022 91°21'40.45"E 26°37'25.75"N at Village Bunbari, Culvert Approach Road Damaged ROAD & CULVERT DAMAGED ON NUSHALPUR TO PURAN MUSHALPUR ROAD AT ATHIABARI ON DT.15/06/2022 91°17'21.66"E 26°35'55.01"N at Village Laphakuchi, Culvert Approach Road Damaged Moshalpur to Thomas Road Slab culvert 1 slab damaged an	

2022 Co-ordinate 26.657936, 91.287310, Irrigation Canal/Scheme Damaged | Ghogla (Laphakuchi) FIS- U/S afflux bund is partially affected, 17-06-2022 Co-ordinate 26.63383, 91.306015, Irrigation Canal/Scheme Damaged | Puran Goldingpara FS- Gate damaged and D/S afflux bund with protection work is affected, 17-06-2022 Co-ordinate 26.595483, 91.319597 Baghbar - Elementary Schools Damaged | 1349 NO BHERA LPS IS Eroded (18-6-2022), Kalgachia - Anganwadi Centres Affected | As per report received from CDPO office on 17/06/22(evening) total 41 nos of AWC are submerged by ongoing flood, they are- 1. 116 No Bartari(B), Bartari 2. 119 no chandmama(A), chandmama 3.174 No. Garalipam(C), Garalipam, 4.170 No Rampur(D), Rampur, 5. 168 No Bonghugi (D), Bonghugi, 6. 128 No Jawrimari (A), Jaurimari, 7. 13 No Guileza (A), 8. 12 No Guileza (A), 9.14 No Guileza(c), 15. 50 No Dimapur(A), 16. 153 No Dimapur(B), 17. 47 No Ginialguri(A), 18. 208 No Gunialguri(E), Gunialguri, 19. 45 No Kalgachia(C), Kalgachia, 20. 206 No Kalgachia Uttar, Kalgachia, 21. 151 No Kalgachia(E), Kalgachia, 22. 49 No Gunialguri(C), Gunialguri, 23. 140 No Lachanga(E), Lachanga, 24. 142 No Bachimari(B), Bechimari, 25. 22 No Lachanga(A), Lachanga, 26. 25 No Lachanga (D), Lachanga, 27. 244 No Kaurjahi Pub Char, Kaurjhi, 28. 27 No Bechimari (A), Bechimari, 29. 197 No srirampur (B), Srirampur, 30. 33 No Srirampur, Srirampur, 31. 200 No Galia(D), Galia, 32. 245 No Kasukati Char, Kasukati, 33. 27 No Bechimari(A), Bechimari, 34. 199 No Bechimari(C), 35. 31 No Golia (B), galia, 36. 32 No Kasukati, Kasukati, 37. 159 No Balarpather(D), Balarpather, 38. 64 No Balarpather (A), Balarpather, 39. 73 No Dabandia (B), Dabandia, 40. 270 No Langla Paschim, Langla, 41. 84 No Bagulamari(B), Bagulamari., Barpeta Health Sub-Centre | As per report received from health dept on 18/06/22, due to heavy rain total 3 nos of SC are submerged, they are- 1. Monakacha SC, Monakacha, 2. Pub Galia SC, Galia, 3. Charcharia SC, Charcharia, Protection Bundh Damaged | As per report received from health dept on 18/06/22, due to heavy rain total 2 nos of flood protection bundh damaged- 1. Flood protectio bundh st frm Sanowar Hussain to Rahij Uddin house at vill- Kharballi. (damaged length=70m, B=3.75m, H=1.5m, coordinates-26.357375, 90.891429 & 2. Flood protection bundh st frm Somesh Uddin house to Aynal Hoque house at vill- Shawrachara. (Damaged length=30m, W=4m, H=3m).), Fisheries/Pond | As per report received from Fishery dept on 18/06/22, total 400 nos of Fishery(Ponds) are submerged(inundated) as on today within the jurisdiction of Kalgachia circle, Chenga - Fisheries/Pond | Approx. 117.60 hac. water Area affected, approx. 343 nos. Fish pond affected reported by fishery deptt. On 18.6.22, Barnagar - Sericulture Deptt. Damaged | As per report received from Sericulture demonstrator 4335 nos of Keseru Plant is affected (18-6-2022), Sarthebari - Fisheries/Pond | 52 (18-6-2022) Manikpur - Culvert Approach Road Damaged | RCC slab culvert no 4/2 (Size length = 6.00m) collapsed on patiladoha panbari road. as per report PWRD Bongaigaon dated 17.06.2022, Culvert Approach Road Damaged | Box culvert size 2.00m X 2.00m single opening culvert approaches partlybreached on khursamari PMGSY road as per report PWRD Bongaigaon dated 17.06.2022, Culvert Approach Road Damaged | Box culvert size 2.00m X 2.00msingle opening culvert approaches partly brached on bagariguri paragaon road.as per report PWRD Bongaigaon dated 17.06.2022, Fisheries/Pond | Total 67 Nos pond (Bashbari No 1 -66 nos pond & Bashbari no VI -1 no pond) as per report Bongaigao DFDO Bongaigaon dated 18.06.2022, Boitamari - Fisheries/Pond | Total 8 nos of pond, (1). Korea Pahar-1 no pond, (2) Kabaitari Pt-VI-3 nos pond, (3) Chalantapara Pt-I-3 nos pond, (4) Barkhat-1 no pond as per reported by District Fishery Dev. Officer Bongaigaon dated 18.06.2022, Srijangram - Fisheries/Pond | Total 40 nos of Pond (1) Balarpet -28 nos pond, (2) Balarchar-1 no Pond, (3) Huramara Pt-2-1 no Pond, (4) Golapara Pt-IV-1 no pond, (5) Chakla Pt-I-3 nos Pond, (6) Topgaon Pt-I-3 Nos Pond, (7) Charipunia 1 no Pond, (8) Nararvita Pt-IV-1 no Pond, & (9) Santoshpur Pt-III- 1 no Pond.as per reported by District Fishery Dev. Officer Bongaigaon dated 18.06.2022 Udharbond - Power Dept. Poles | HT/LT composite line & pole damaged at Baghehar near Gobindapur as per Cachar report received from APDCL Udharbond Sub-Divission on 18.06.2022 Sidli - Bridge Approach Road Damaged | As reported by PWD Chirang (R&B) Division, On Goragaon to Salbari PMSGSY Road RCC Bridge Approach damaged at Goragaon on 17/06/2022. Damage Details: Length:8M, Breadth: 3M, Depth: 2.5M. (Long:90.375173, Lat:26.558062), Washed away Culverts | As reported by PWD Chirang (R&B) Division, RCC Culvert No. 1/1 Damaged of Madhyam Runikhata Limbu Basti road at Runikhata on 17/06/2022. Damage Details: Length: 5M, Breadth: 3.5M. Long:90.551032 Lat:26.558622, Road Breaches | As reported by PWD Chirang (R&B) Division, HP Culvert Approach Road of Silgara village road breached out at Rabhapara on 16/06/2022. Damage Details: Length: 8 M, Breadth: 6M, Depth:1.5m Chirang (Long:90.464888 Lat:26.421633), Washed away Culverts | As reported by PWD Chirang (R&B) Division, HP Culvert of Kajalgaon Bengtal Road damaged at Ch. 47000m (Kodamtoli) on 16/06/2022. Damage Details: Length:5M Breadth: 2.5 (Long:90.495592 Lat:26.563544), Power Dept. Conductors | As reported by SDE, BESD-I APDCL, 1.5 km (Simlaguri-0.5km, Kinaborgaon-0.8km, and Petelagaon-0.2km) conductor damaged on 15/06/2022, Power Dept. Poles | As reported by SDE, BESD-I APDCL, 3 nos. of 7.5 m pole and 2 nos. of 9.75m pole damaged on 15/06/2022 at Kinaborgaon and Petlagaon village., Power Dept. Transformers | As reported by SDE, BESD-I APDCL, 1 no. of 63kVA transformer damaged at

	Kinaborgaon on 15/06/2022,
	Irrigation Canal/Scheme Damaged As reported by Irrigation Department Sidli Division, Ghorabandha FIS
	irrigation Canal embankment damaged at Amlaiguri village on 16/06/2022. Damage Details: Length: 5M,
	Breadth: 2.5M depth: 1.8 M (Long:90.4556270 Lat: 26.575982),
	Bijni - Bridge Approach Road Damaged As reported by PWD Bijni(R&B) Sub Division, bridge approach of Br. No 1/1 eroded at 1st KM of Bagargaon Gundamara road. Length=70.00 mtr, Breadth=8.0 mtr, Depth=6.00 mtr.
	Date of Occurrence=16-06-2022,
	Culvert Approach Road Damaged As report by PWD Bijni(R&B) Sub Division, H.P. Culvert approach eroded
	at 1st Km (Ch 1500.00m) of Bangaljhora sariali to Bangaljhora road. Length=8.00 mtr, Breadth=2.00 mtr,
	Depth=2.50 mtr. Date of Occurrence=17-06-2022,
	Bengtal - Irrigation Canal/Scheme Damaged As reported by Soil Conservation Dept. Subaijhar LDP damaged
	on 18-06-2022, L-127m B-12m D-1.5m, Lat- 26.594446 Long-90.498086,
	Irrigation Canal/Scheme Damaged As reported by Soil Conservation Dept. Domgaon Water Harvesting Project damaged on 18-06-2022, L-115m B-4.5m D-1.4, Lat- 26.58552 Long-90.502833
	Patharighat - PWSS Damaged 2 PWSS affected as reported by JE PHE,
	Mangaldoi - Power Dept. Poles 10 nos of poles are damaged dated 18.06.2022,
	Handloom & Textile Deptt 111 nos weiver affected as repoted by Handloom & Textile dated 18.06.2022,
	Sipajhar - Power Dept. Poles 18,
Darrang	Power Dept. Conductors 20 km approx,
	Fisheries/Pond Total number of fish farmers affected (approximately) - 550 nosTotal water area affected (approximately) - 41 Hac,
	Handloom & Textile Deptt weavers affected 151, loom accessories 5, no. of warp 151,
	Sericulture Deptt. Damaged 75 nos.
	Chabua - Health Sub-Centre DODHIA KULIGAON HEALTH SUB-CENTRE SUBMERGED AS PER
	INFORMATION RECEIVED FROM HEALTH DEPT. ON 18/6/2022 Coordinates-N27 35.835 E95 13.266,
	Elementary Schools Damaged DODHIA ME SCHOOL SUBMERGED AS PER INFORMATION RECEIVED
	FROM EDUCATION DEPT. ON 18/6/2022 N27 36.390 E95 13.651, Elementary Schools Damaged DODHIA KULIGAON LPS SUBMERGED AS PER INFORMATION
	RECEIVED FROM EDUCATION DEPT. ON 18/6/2022 N27 35.845 E95 13.227,
	Elementary Schools Damaged DODHIA KARMI LPS SUBMERGED AS PER INFORMATION RECEIVED
	FROM EDUCATION DEPT. ON 18/6/2022 N 27 36.032 E95 14.787,
	Elementary Schools Damaged DODHIA TENGABARI LPS SUBMERGED AS PER INFORMATION
	RECEIVED FROM EDUCATION DEPT. ON 18/6/2022 N27 36.652 E95 14.237,
	Elementary Schools Damaged DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT ON 18/6/2022 N27 36.462 E95 14.673,
	Anganwadi Centres Affected DODHIA KULIGAON AWC SUBMERGED AS PER INFORMATION
Dibrugarh	RECEIVED FROM SOCIAL WELFARE DEPT. ON 18/6/2022 N27 35.845 E 95 13.227,
	Anganwadi Centres Affected DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 18/6/2022 N27 36.652 E95 14.237,
	Anganwadi Centres Affected DODHIA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 18/6/2022 N27 36.390 E95 13.651,
	Elementary Schools Damaged MOHMORA HINDI LPS SUBMERGED AS PER INFORMATION
	RECEIVED FROM EDUCATION DEPT. ON 18/06/2022. N27 34'5.0514" E95 10'23.7144",
	Elementary Schools Damaged MIRIGAON LPS SUBMERGED AS PER INFORMATION RECEIVED FROM
	EDUCATION DEPT. ON 18/06/2022. N27 30'44.51" E95 12'49.41",
	Anganwadi Centres Affected UPPER GEREKI AWC SUBMERGED AS PER INFORMATION RECEIVED
	FROM SOCIAL WELFARE DEPT. ON 18/6/2022 N27 33.942 E95 15.125, Anganwadi Centres Affected DODHIA CHALBIL AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 18/6/2022. N27. 5714 E95. 2346
	Haflong - Road Breaches Nablaidisa - Hajadisa Road blocked due to landslide as per info received from PWRD
	dated 18/06/2022,
	Road Breaches Mahur - Laisong Road blocked due to landslide as per info received from PWRD dated
Dima-	18/06/2022, Road Breaches Gunjung - Maibang Road blocked due to landslide as per info received from PWRD dated
Hasao	18/06/2022,
	Road Breaches Retzawl - Amranagar Road blocked due to landslide as per info received from PWRD dated
	18/06/2022,
	Road Breaches
	Lanka - PWSS Damaged Dakhin Laskarpathar PWSS submarged on 17/06/2022,
	PWSS Damaged Manduli PWSS submarged on 17/06/2022,
	PWSS Damaged Uttar Laskar Pathar PWSS submarged on 17/06/2022, PWSS Damaged Dublpng PWSS submarged on 17/06/2022,
Hojai	PWSS Damaged Simlai pather PWSS submarged on 17/06/2022,
<i>3</i> ···	Hojai - PWSS Damaged Warigeding PWSS submarged on 17/06/2022,
	PWSS Damaged Alinager PWSS submarged on 17/06/2022,
	PWSS Damaged Solmarijan PWSS submarged on 17/06/2022,
	PWSS Damaged Fatehpur PWSS submarged on 17/06/2022,

	PWSS Damaged Ashinager PWSS submarged on 17/06/2022,
	PWSS Damaged Raikata PWSS submarged on 17/06/2022,
	PWSS Damaged Greater Kachari basti PWSS submarged on 17/06/2022,
	PWSS Damaged Hawaipur PWSS submarged on 17/06/2022, PWSS Damaged Pubnandalal pur PWSS submarged on 17/06/2022,
	Doboka - PWSS Damaged Patiapam PWSS submarged on 17/06/2022,
	PWSS Damaged Jungle Block PWSS submarged on 17/06/2022,
	PWSS Damaged Chanjmaji Goan PWSS submarged on 17/06/2022,
	PWSS Damaged Borjhari Majgoan PWSS submarged on 17/06/2022,
	PWSS Damaged Patia pather PWSS submarged on 17/06/2022,
	PWSS Damaged Nagayapam PWSS submarged on 17/06/2022,
	PWSS Damaged Changujrai PWSS submarged on 17/06/2022,
	PWSS Damaged Bheluguri Pather PWSS submarged on 17/06/2022
	Rangia - Fisheries/Pond Total 71 ponds are affected amounting to water area 7.81 Ha as per report of FDO, Rangia on 17.6.2022,
	Bridge Approach Road Damaged Approach road to Bridge No. 3/1 on Chepti Bihdia Road in village chepti was damaged as per report of AEE, PWD NKT Roads, Rangia on 17.06.2022,
	Kayan - Power Dept. Poles 6 nos. Date: 17/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL,
Kamrup	Rangia.,
	Power Dept. Conductors 2.23 km. Date: 17/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL,
	Rangia.,
	Irrigation Canal/Scheme Damaged Bordonga Batakuchi ELIS, Dhuhi ELIS (Bathan PC), Dhuhi ELIS
	(Chamukha PC), Dhuhi ELIS (Lahkarpara PC). Date: 17/06/2022. Reported by EE, Hajo-Jalukbari Division (Irrigation)
	Chandrapur - Power Dept. Poles Power Dept. Poles. 08 nos. of electric poles have been damaged due to heavy
	rainfall that occured on 14/06/2022 at Ganeshpur, Chandrapur, Daimuguri, Garobasti,
	Power Dept. Poles Power Dept. Poles. 02 nos. of electric poles have been damaged due to heavy rainfall that
	occured on 16/02/2022 at Bonda, Panikhaiti Gaon, Chandrapur Road,
	Power Dept. Poles Power Dept. Poles. 09 nos. of electric poles have been damaged due to heavy rainfall on
	17/06/2022 at Nizarapara, Chandrapur NTC, Akashi Nagar brhind NTC, Baghdhora tila,
	Guwahati - PWSS Damaged 500 KVA Transformer of GU & AEC WSS has been brust due to thunderstrom on
	14/06/2022,
	Secondary Schools Damaged Panbazar HS School, Gotanagar Nambari H School, Bengali HS School, Jalukbari
	HS School, Ulubari HS School, Baidik Ashram LP School, Sadilapur LP School due to Flood on 15/06/2022,
	Road Breaches GS Road- Approach of Ulubari Fly over, Service Road, Bhangagarh Fly Over, Ch. 170.00mm to Ch 4250.00mm, MG Road, Lamb Road, CK Agarwala Road, GMCH approache Road, Lachit Nagar Main Road,
	Rajgarh Main Road, B.Baruah Road, Rajgarh link Road, Lachit Lane, KC Sen Road, Manipuri East Road 1 and
Kamrup	East Road 2, Rup Nagar, Birubari, Pub Sarania Bylane 4, Krishna Nagar Main Road, Raj Bhawan approach
(M)	Road, RGB Road, Niligiri Path North Jyoti Nagar, Lankeswr Road, Ganesh Mandir Path North Jyotinagar,
(=-=)	Lankeswar Haridev Nagar Road due to Flood on 15/06/2022,
	Anganwadi Centres Affected Baragaon Mikirghuli, Anil Nagar, Ganesh Nagar,
	Dispur - PWSS Damaged A part of distribution network of Satgaon Kalyankuchi PWSS DURING FLOOD ON
	16/06/2022,
	Road Breaches Janapath Main Road entire road surface damaged, Tarun Nagar Bylane 5 adjuscent to Bharalu
	River due to Flood on 16/06/2022,
	Road Breaches Mother terasa road surface damaged 16/06/2022,
	Anganwadi Centres Affected Dakhin Beltola, Majopara, Arundhuti Basishtha, Swargapur, Arungiri Basishtha,
	Pilling Katta, Beherbari, Sunkuchi Borsojai, Sagalpara, Ahom Gaon, Sijubari, Latakata, LN Bezboruah, Basishtha Bijoypur, Narakasur, Narbam LP School, Kahilipara Mikir Basti, Adagudown Dhopolia, Carbon Gate
	2 No. Mothghoria, 2 No Mothghoria, Bhupendra Nagar, Lakhipur, Pathor quqrry MS, 1 No Mothghoria, 1 No
	Mothghoria Santi Nagar, Baikuntha Nagar, Tol Chachal, Dwaraka Nagar, Aziz Nagar, Juripar, Sathgaon Ambari,
	Karanachal, Upper Hengerabari, Japorigog, Rukmini Nagar AWS partially damaged on 16/06/2022
	Bagribari - Culvert Approach Road Damaged As reported by LR staff, approaches of five nos. of culverts at
Kokrajhar	Bisubasra, Kuarpar LPS, Lalmati-Borogaon, Silbari High School and Bhutanergaon on Joypur to Silbari Road
	has been damaged ON 18-06-2022
	Subansiri - Bridge Approach Road Damaged As reported by the Dhakuakhana Territorial Road Division,
	Ghilamara the approach of RCC Br. No. 3/1 over river Bhimpara on Khajua Tiniali to Basudevthan Road is
	Damaged (L= 7M) on 17/06/2022,
	Bridge Approach Road Damaged As reported by the Dhakuakhana Territorial Road Division, Ghilamara the
	approach of RCC Br. No. 5/1 over River Kilakili on Khajua Tiniali to Basudevthan Road is Damaged (L= 5M)
Lakhimpur	on 17/06/2022, North Lakhimpur - Power Dept. Poles 8.5 mtr 19 nos. as reported by APDCL, North Lakhimpur Divn. on 17-
	06-2022.,
	Power Dept. Poles 7.5 mtr 36 nos. as reported by APDCL, North Lakhimpur Divn. on 17-06-2022.,
	Power Dept. Conductors 21.65 km approx. as reported by APDCL, North Lakhimpur Divn. on 17-06-2022.,
	Nowboicha - Power Dept. Conductors 20.3 KM conductor damaged under Nowboicha Electrical Sub-division
	on 17.06.2022. Report received from Nowboicha Electrical Sub-division,
	-

Majuli - Agri Bundh Damaged Due to rising water level of the river Submain; split over topping on a agriculture bund al Buliokaibowa guon on 18.06.2022. GPS location: Latitude 7.034196* Longitude 94.1806619. Majuli Majuli - Anganwadi Centres Affected 10 nos of Anganwadi centres parially submerged on 18.06.2022. 1. Besamona AWC, 2. Borhuskapathar AWC, 3. Salmona Borbuska AWC, 4. Ujani Kumargaon AWC, 5. Salmona Majura Silmara Silma		Power Dept. Poles LT Pole-7 Nos. and HT Pole- 2 Nos. damaged under Nowboicha Electrical Sub-division on
agriculture bund at Balijokaibwa gano ni 18/06/2022, IPS location: Latitude 27/03/19/6* Longitude Majuli 1, 18/05/61*, Ujani Majuli - Anganwadi Centres Affected 10 nos of Anganwadi centres partially submerged on 18/06/2022, Ujani Majuli - Anganwadi Centres Affected 10 nos of Anganwadi centres partially submerged on 18/06/2024. West and the Samora AWC, 2. Borbukapathar AWC, 3. Salman Borbuka AWC, 4. Ujani Kurangana AWC, 5. Borbuka AWC, 6. Salmara Borbuka AWC, 8. Namoni Surioniana AWC, 9. Belguri Kurangana Handa Mayor 10. 10 no. 10/20/2022. Morganon Burangan - Health Sub-Centre [Nalmari SID Nurse Quarter crosted due incessant rain on 17-06-2022. Magaon Rada - Veterinap / Popul Infastraticume Magargano State dispensary has been submerged on 18/06/2022. Gloograpar - Irrigation Canal Scheme Dumaged As per Information received from Irrigation department, at village Poichara, Canal Dumage, Aproche road Damage on 17/06/2022. Irrigation Canal Scheme Dumaged As per Information received from Irrigation department, at village Kundargano. Canal Damage, Aproche nod damage on 17/06/2022. Irrigation Canal Scheme Dumaged As per Information received from Irrigation department, at village Nimua Latina. Canal damage on 17/06/2022. Irrigation Canal Scheme Dumaged As per Information received from Irrigation department, at village Nimua Latina. Canal damage on 17/06/2022. Fisheries-Pond As per Fishery report received from fishery department, on 17/06/2022, Nos of submerged ponds and tusks 21 fore, water are 28. 8 H. Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malijara to Industry chowk culvert damaged due to rain water Dated. 17/06/2022. Culvert Approach Road Damaged as per the report from PWRD, Malijara to Industry chowk culvert damaged due to rain water Dated. 17/06/2022. Irrigation Canal Scheme Damaged as per the report from PWRD, Malijara to Industry chowk culvert damaged due to flood Dated. 17/06/2022. Irrigation Canal Scheme Damaged as per the report of Hand loo		17.06.2022. Report received from Nowboicha Electrical Sub-division
Majuli Ujani Majuli - Angamwadi Centres Affected 10 nos of Anganwadi centres partially submerged on 18 06.0022		agriculture bund at Balijokaibowa gaon on 18.06.2022. GPS location: Lattitude 27.034196° Longitude
Kutumchuk AWC, 10. 1 no. Jogi gaon AWC	Majuli	Ujani Majuli - Anganwadi Centres Affected 10 nos of Anganwadi centers partially submerged on 18.06.2022. 1. Besamora AWC, 2. Borbukapathar AWC, 3. Salmora Borbuka AWC, 4. Ujani Kumargaon AWC, 5. Borbuka
Morigano		•
Raha - Veterinary Deptt Infrastructure Magurgaon State dispensary has been submerged on 18/06/2022	Morigaon	* *
Ghograpar - Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Poichara, Canal Damage, boring damage, approch road damage on 17/06/2022, Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Poichara, Canal Damage, Approch road Damage on 17/06/2022, Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Kundargaon, Canal Damage, Approch road damage on 17/06/2022, Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Nimua Latima, Canal damage on 17/06/2022, Irrigation Canal/Scheme Damaged As per free of the propert received from Irrigation department, at village Nimua Latima, Canal damage on 17/06/2022, Pisheries/Pond As per Fishery perport received from fishery department, on 17/06/2022, Nos of submerged pond and tanks 216 aos., water area 28.8 H, Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged due to rain water Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Handloom & Textile Deptr As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, analbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery department, and point plated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point)		
village Poichara. Canal Damage, boring damage, approch road damage on 17/06/2022. Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Poichara, Canal Damage, Approch road Damage on 17/06/2022. Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Kundargaon, Canal Damage, Approch road damage on 17/06/2022. Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Nimua Latima, Canal damage on 17/06/2022. Fisheries Pond As per Fishery report received from fishery department, on 17/06/2022, Nos of submerged pond and tanks 216 nos, water area 28 48 H. Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged due to rain water Dated: 17/06/2022. Culvert Approach Road Damaged as per the report from PWRD, kharjara to nalbari bahjani road culvert damaged due to rain water Dated: 17/06/2022. Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022. Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept. Nalbari Haripur DTWIS damaged due to flood Dated: 17/06/2022. Handloom & Textile Depti As per the report from Irrigation Dept. Nalbari Haripur DTWIS damaged due to flood and rain water, Dated: 17/06/2022. Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022. Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022. Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022. Irrigation Canal/Scheme Damaged Chatamar Bib Dated: 17/06/2022. Irrigation Canal/Scheme Damaged Chatamar Bib Sasaraguri AWC, s Nos Rupahimukh AWC; 143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Headmaria - Culvert Approach Road Damaged Chatamaria Bib Assaraguri AWC, s Nos Rupahimukh AWC; 143 Nos. Rupahimukh	Tuguon	
Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Poichara, Canal Damage, Approch road Damage, and 1706/2022, Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Nimua Latima, Canal damage on 1706/2022, Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Nimua Latima, Canal damage on 1706/2022, Fisheries/Pond As per Fishery perot received from fishery department, on 17.06/2022, Nos of submerged pond and tanks 216 nos., water area 28.8 H. Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged due to rain water Dated: 17.06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17.06/2022, Univert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17.06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to rain water Dated: 17.06/2022, Handloom & Textile Deptil As per the report of Hand Ioom & Textile department, total 34 nos artisans are affected due to flood Dated: 17.06/2022, Handloom & Textile Deptil As per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to flood Dated: 17.06/2022, Handloom & Textile Deptil As per the report from Irrigation Dated 17.06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSK (Hatimat Point) Dated: 17.06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSK (Hatimat Point) Dated: 17.06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarakuchi DTWISk, Point of) Dated: 17.06/2022, Irrigation Canal/Scheme Damaged Chatama Flabated: 17.06/2022, Irrigation Canal/Scheme Damaged Chatama Flabated: 17.06/2022, Irrigation Canal/Scheme Damaged Chatama Flabated: 17.06/2022, Irrigation Canal/Scheme Damaged Chatama Cham		
Canal Damage. Approch road Damage on 17/06/2022, Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Kundargaon, Canal Damage, Approch road damage on 17/06/2022. Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Nimua Latima, Canal damage on 17/06/2022. Fisheries-Pond As per Fishery report received from fishery department, on 17/06/2022, Nos of submerged pond and tanks 216 nos, water area 28 As H, Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barputhuri par road culvert damaged due to rain water Dated: 17/06/2022. Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged Dated: 17/06/2022. Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022. Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to food Dated: 17/06/2022. Handdoom & Textile Deptt As per the report of Hand Ioom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022. Fisheries/Pond as per the report received frishery department, nalbari total 856 fish farmers family affected due to flood Dated: 17/06/2022. Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Ehs Dated: 17/06/2022. Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022. Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022. Fisheries/Pond 21 Ponds affected as per report submitted by Asst. Executive Engineer, PWD Societ Territorial Road Asst. According to the Asst. Ass		
Irrigation Canal/Scheme Damaged Ås per Information received from Irrigation department, at village Numargaon, canal Damage, Approach road damage on 17/06/2022, Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Nimua Latima, Canal damage on 17/06/2022, Pisheries/Pond As per Fishery report received from Irrigation department, at village Nimua Latima, Canal damage on 17/06/2022, Fisheries/Pond As per Fishery report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged As per the report from PWRD, Malipara to Industry chowk culvert damaged Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Calvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to rain water Dated: 17/06/2022, Handloom & Textile Depti As per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to from Dated: 17/06/2022, Handloom & Textile Depti As per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water. Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSK (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSK (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Fis Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Fis Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Fis Dated: 17/06/2022 Sivasagar Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC, 143 Nos. Rapahimukh AWC are submerged on 18-06-2022, three rows of hume pipe culvert approach of culvert No.21 at ch. 1200.0008 got fully washed dam		
Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Nimua Latima, Canal damage on 17/06/2022, Fisheries-Pond As per Fishery report received from fishery department, on 17/06/2022, Nos of submerged pond and tanks 216 nos., water area 28.8 H. Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged due to rain water Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, kharjara to nalbari bahjani road culvert damaged Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Handloom & Textile Depti As per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to flood Dated: 17/06/2022, Handloom & Textile Depti As per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to flood and rain water, Dated: 17/06/2022, Handloom & Textile Depti As per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Barbhag: Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Sivasagar Sivasagar Sivasagar As a submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged. Lation Proposal Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali t		
Latima, Canal damage on 17/06/2022, Fisheries/Pond As per Fishery report received from fishery department, on 17/06/2022, Nos of submerged pone and tanks 216 nos., water area 28.8 H, Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged due to rain water Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, kharjara to nalbari bahjani road culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to flood Dated: 17/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Than Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Than Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022 Sivasagar Sivasagar Sivasagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC, 143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, three rows of hume pipe culvert approach of culvert No-2/1 at ch. 1200.00M got fully washed damaged. Charlduar - Fisheries/Pond GulDAMGHAT, GUDAMGHATMIR, GUDAMGHAT KACHAR, PAKBIL, RANGAJAN M		Kundargaon, Canal Damage, Approch road damage on 17/06/2022,
Fisheries/Pond As per Fishery report received from fishery department, on 17/06/2022, Nos of submerged pond and tanks 216 nos., water area 28.8 H. Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged due to rain water Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to rain water Dated: 17/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood and rain water, Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Els Dated: 17/06/2022, Sivasgar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC, 143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Sivasgar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC, 143 Nos. Rupahimukh AWC are submerged on 18-06-2022. Trebamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, the culvert approach of culvert No.2/1 at ch. 1200.000 got fully washed damaged. As per report by brish ponds inundated in 8 Reps. 12 As per report by PWD Roads possibility of Nalmar		Irrigation Canal/Scheme Damaged As per Information received from Irrigation department, at village Nimua
and tanks 216 nos., water area 28.8 H. Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged due to rain water Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, kharjara to nalbari bahjani road culvert damaged due to rain water Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to flood Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood abted: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Saragari Awc, 8 Nos Rupahimukh AWC, 143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.271 at ch. 1200.000 Mg of fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHAT IRRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAM MRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, P		
Nalbari - Culvert Approach Road Damaged As per report received from PWRD, Malikuchi to Terechia Barpukhuri par road culvert damaged due to rain water Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, kharjara to nalbari bahjani road culvert damaged Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to rain water Dated: 17/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022, Handloom & Textile Deptt As per the report from Irrigation Dated: 18/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood and rain water, Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Shood Sangued As Point of Point 6) Dated: 17/06/2022 **Sivasagar** **Sivasagar** **Sivasagar** **Sivasagar** **Alexandaria** **Thelamara** - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PwD Soote Thelamara** - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PwD Soote Textification of Point 18/10/16/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066		
Nalbari Nalbari Culvert Approach Road Damaged as per the report from PWRD, kharjara to nalbari bahjani road culvert damaged Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to flood Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to flood Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELS (Bathimari Point) Dated: 11/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022 Sivasgar		
Nalbari Culvert Approach Road Damaged as per the report from PWRD, kharjara to nalbari bahjani road culvert damaged Dated: 17/06/2022,		
Nalbari damaged Dated: 17/06/2022, Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to flood Dated: 17/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Thedamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged. Chariduur - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.77093 Long 92.956455, Lat 26.77093 Long 92.956557, Lat 26.77093 Long 92.956455, Lat 26.77093 Long 92.956557, Lat 26.77093 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.77066 Long 92.9566557, Lat 26.77066 L		
Culvert Approach Road Damaged as per the report from PWRD, Malipara to Industry chowk culvert damaged due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged due to flood Dated: 17/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Saveraged As reported by Evaluation Saveraged Saveraged Saveraged As reported by Evaluation Saveraged Saveraged Chariduar Saveraged Saveraged As reported by Evaluation Saveraged Saverage	Nalhari	
due to rain water Dated: 17/06/2022, Irrigation Canal/Scheme Damaged as per the report from Irrigation Dept, Nalbari Haripur DTWIS damaged du to flood Dated: 17/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Ty/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Sivasagar Sivasagar Sivasagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC,143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M gof fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARH PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.77066 Long 92.948288). Dhekiajuli to Panchnoi Pwd road, dated 17.6.22. Tezpur - Fisheries/Pond Da	runour	
to flood Dated: 17/06/2022, Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood and rain water, Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS(Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS(Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS(Point 6) Dated: 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.000 got fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Banga along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Cul		
Handloom & Textile Deptt As per the report of Hand loom & Textile department, total 34 nos artisans are affected due to flood Dated: 17/06/2022, Fisheries/Pool as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Tisherived proof 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Sivasagar Sivasagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC, 143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 21 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828). Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangal along Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village, dated		
affected due to flood Dated: 17/06/2022, Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAIAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabar to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.77033 Long 92.94828), Sonitpur Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Banga along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village. dated 18.6.22, Texpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads		to flood Dated: 17/06/2022,
Fisheries/Pond as per the report received fishery department, nalbari total 856 fish farmers family affected due to flood and rain water, Dated: 17/06/2022, Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Sivasagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC,143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED. Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022, (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Banga along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village. dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.06.202. As reported by PWD (Roads) both sideof a cluvert		
to flood and rain water, Dated: 17/06/2022, Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022 Sivasgar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC, 143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged., Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabar to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Sonitpur Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangal along Dhekiajuli to Panchnoi Pwd road. dated 17.6.222, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukiharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Da		
Barbhag - Irrigation Canal/Scheme Damaged Baharghat ELIS (Garakhia Than point) Dated : 17/06/2022, Irrigation Canal/Scheme Damaged Baharghat ELSS (Hatimari Point) Dated : 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated : 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated : 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS (Point 6) Dated : 17/06/2022 Irrigation Canal/Scheme Damaged Chatama FIS Dated : 17/06/2022. Sivsagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC, 143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022. (the 2014 roded and culvert no. 3/1 of NH-15 Kathabar to Bamunbari road settle down on 17/06/2022. (the 2014 roded and culvert no. 3/1 of NH-15 Kathabar to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557 Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Banga along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22. Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by FWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submit		
Irrigation Canal/Scheme Damaged Baharghat ELSS(Hatimari Point) Dated : 17/06/2022, Irrigation Canal/Scheme Damaged Chatama Flas Dated : 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated : 17/06/2022 Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated : 17/06/2022 Sivasagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC,143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabar to Bamunbari road settle down on 17/06/2022, (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557 Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Banga along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 South Salmara		
Irrigation Canal/Scheme Damaged Chatama Chamarkuchi DTWIS(Point 6) Dated: 17/06/2022, Irrigation Canal/Scheme Damaged Chatama FIS Dated: 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated: 17/06/2022		
Irrigation Canal/Scheme Damaged Chatama FIS Dated : 17/06/2022, Fisheries/Pond 21 Ponds affected as per report by Fishery dept. Dated : 17/06/2022 Sivsagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC,143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged., Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Sonitpur Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangal along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village. dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Culvert Approach Road Damaged Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been sub		
Sivasagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC,143 Nos. Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged. Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022, (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Sonitpur Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangai along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village. dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Oulverts The RCC slab culvert at Charanpara		
Rupahimukh AWC are submerged on 18-06-2022 Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged., Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangai along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022. Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8 M (appro		
Thelamara - Culvert Approach Road Damaged As reported by PWD Roads Dept, Barchalla Territorial Road Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged., Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangai along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was wasshed away on 17.06.2022, creating breach. Length : 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in	Civeseger	Sivsagar - Anganwadi Centres Affected 152 Nos Saraguri AWC, 8 Nos Rupahimukh AWC,143 Nos.
Sub-Division, Barchalla on 18/06/2022, three rows of hume pipe culvert approach of culvert No.2/1 at ch. 1200.00M got fully washed damaged., Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangal along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 South Salmara Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani ender Mankachar Dev. Block on 17-06-2022. Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was wasashed away on 17.06.2022, creating breach. Length : 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in	Sivasagar	
1200.00M got fully washed damaged., Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangal along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village. dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 South Salmara Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06-2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, ir		
Chariduar - Fisheries/Pond GUDAMGHAT, GUDAMGHATMIRI, GUDAMGHAT KACHARI, PAKBIL, RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Sonitpur Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangal along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
RANGAJAN MIRI, ROWMARI, BERAJAN, MANSIRI, SINGHAGHARI PONDS ARE ENUNDATED, Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabari to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangal along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length : 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Naduar - Culvert Approach Road Damaged As per report submitted by Asst. Executive Engineer, PWD Soote Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabart to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557, Lat 26.770293 Long 92.942828), Sonitpur Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Banga along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length : 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Territorial Road Sub-Division on 17/06/2022, the culvert no. 2/1 eroded and culvert no. 3/1 of NH-15 Kathabar to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557). Lat 26.770293 Long 92.942828), Sonitpur Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Banga along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
to Bamunbari road settle down on 17/06/2022. (Lat 26.770593 Long 92.956455, Lat 26.77066 Long 92.956557. Lat 26.770293 Long 92.942828), Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Banga along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Sonitpur Dhekiajuli - Culvert Approach Road Damaged PWD culvert approach partially damaged at Narengkati Bangal along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
along Dhekiajuli to Panchnoi Pwd road. dated 17.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Culvert Approach Road Damaged Culvert approach partially damaged along a village road at Balisuti Bangali village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in	Sonitpur	
village . dated 18.6.22, Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Culvert Approach Road Damaged Culvert approach partially damaged along Sirajuli to Hugrajuli road at Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Mazrowmari village. dated 18.6.22, Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Tezpur - Fisheries/Pond Dated: 18/06/2022. As reported by Fishery Dept. 41 no. of families were affected by Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 South Salmara Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Fish ponds inundated in Baghsung, Solmara, Bhalukjharoni, Parmaighuli. Total W/A (Ha) 11.70 (approx), Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Culvert Approach Road Damaged Dated: 18/06/2022. As reported by PWD (Roads) both sideof a cluvert damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 South Salmara Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
damaged at Besseria Village infron of GREF office. Lat: 26.65961 Long: 92.74604 South Salmara Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
South Salmara Mankachar - Irrigation Canal/Scheme Damaged As per report submitted Irrigation Department, Rangapani F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapan under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
F.I.S Canal portion and Command area of the scheme have been submerged under water in village of Rangapani under Mankachar Dev. Block on 17-06-2022 Khairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in	Courth	
 Whairabari - Washed away Culverts The RCC slab culvert at Charanpara on Barakhat to Tangla Bhergaon Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in 		
Road was waashed away on 17.06.2022, creating breach. Length: 8M (approx.). Coordinates: Lat- 26.3710 Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in	Samilara	
Udalguri Long-91.5318, Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
Power Dept. Poles Due to continuous rain and flood, 8 nos. of LT & HT poles were damaged on 17.06.2022, in		
	Udalguri	
i the villages namely: Pachim inargaon, Balisitha, Dollichilha, Chanbari & Barnadilhar		
the vinages namely. I definit shangash, Banshina, Boulettaou, Chanbart & Banadijhar.,		the villages namely: Pachim Jhargaon, Balisitha, Doulchuba, Chanbari & Barnadijhar.,

		Power Dept. Conductors Due to continuous rain and flood, HT, LT & 33KV conductors were snapped on 17.06.2022, at various places namely: Pachim Jhargaon, Balisitha, Doulchuba, Chanbari Nalbari & Nonaikhuti
	District	Details
	Baksa	Jalah - Alengamari On 18 June 2022, Approx 600 meter left bank of river beki has been eroding by river beki at
	- Danisa	alengamari. 60
	D. (Kalgachia - Haldhia pather As per report received from BDO rupshi on 17/06/22(evening) const. of rd from
	Barpeta	Mannan driver house to Haldhia resrve LPS at Haldhia Pather road eroded by river Pokalagi(river channel)(area eroded length=300.00m, B=1.45m, H=1.10m) 0
		Naduar RC part - No-2 Gosaichapori Bank erosion is observed at vill. No-2 Gosaichapori by the river
	Biswanath	Ghiladhari. Approximately length of land 45m and breadth 3m have been eroded on 18-06-2022 0
		Sidli - Ghoppara, Chotto Patargaon As reported by WRD Chirang, 2 nos. of Erosion occurred:: 1. As reported
		by WRD Chirang, Severe bank erosion, Gully erosion occurred of river Champamati on its L/B on 17/06/2022 at
		Ghoppara village near Mozabari. Damage Details: Length: 450 M, Breath: 5 M, Depth: 4M (Long: 90.383108
	Chirang	Lat: 26.536485). 2. As reported by WRD Chirang, Active bank erosion on L/B of river Suthi on 18/06/2022 at
		Chotto Patargaon village near LP School. Damage Details: Lenght:250M, Breadth: 6Mm Depth: 3.5M (Long: 90.414579 Lat:26.535179) 0,
		Bengtal - Malivita Shahipur SSB Camp L-400m B-20m D-4m portion of Left Bank eroded by river Taklai on
		18-06-2022 0
		Chapar - Jalokura Erotion took place at Jalokura Village by the river Champabati under Chapar Revenue
		Circle. Around 02B-3K-10L of land has been eroded so far. dated 17-06-2022 0,
		Agamoni - Village- Bholarkhas under Chotoguma GP Riverine area of River Gangadhar at vill Bholarkhas
		under Chotoguma GP is getting eroded. The breaches of the embankment has been extended upto 400 mtrs (approx). Village: Bholarkhas River: Gangadhar GP: Chotoguma Incident date: 17/06/2022 to 18/06/2022 Time
	Dhubri	: 3.00 pm Land : 0 bigha 2 khata 10 Lessa Household affected : 21 Population affected : 105 The affected
		families has shifted their houses by themselves. GPS Coordinate: Lat. 26.3078053. Long. 89.8036509 Due to the
		sudden rise of water level rescue operation was carried out using two nos of engine boat hired from local sources
		at village Belguri. The water level of river Gangadhar is below danger level. Total nos of rescued animals = 23
		Total nos of human population rescued = 33 105
		Naharkatia - 1)Namrup Krishnaguru Sakha Sewa Ashram. 2) Namrup T.E.1no Division(Near Namrup College). 3) Namrup T.E 5 no. division. 4) Namrup T.E.Nodikinar field. As report received from AE, Naharkatia WR
		division dated 18-06-2022, Bank erosion observed at different reaches along the right bank river Desang
		1)Namrup Krishnaguru Sakha Sewa Ashram,Long 27°11′ 12.71″N lat 95°20′16.47″E, for a length of 350m 2)
	Dibrugarh	NamrupT.E.1no Division(Near Namrup College) Long 27.11'25.85N,Lat 95.19'57.35"E, for a length of 250.00m
Erosion		3)Namrup T.E. 5.no Division,Long 27°11'30.17"N lat 95°19'26"E for a length of 275.00m. 4)Namrup Nodikinar
		field.Long 27°11'24.08" N lat 95°19'22.35"E for a length of 125.00 m. 0, Chabua - Gereki Nepali Village Flood damage occurred at Gereki Nepali Village with reach length 20 mtrs
		Coordinates- N27 34'12.22" E95 14'46.06" As reported by WRD on 18/6/2022 4
	Dima-	Haflong - Thaijuwari Bridge Road completely washed away adjacent to the bridge for a length of about 2-3
	Hasao	metres as per info received from local residents dated 18/06/2022 0
		Lala - Rajyeswarpur pt-2 (Nityanandapur pt-2) under Lala Revenue Circle, Date- 13/06/2022 Severly damaged
	Hailakandi	due to vertical settlement and sloughening during the last wave of flood and at the time of draw -down stage of
		river Katakhal on its right bank. Reach lenght-200m 4000
	Kamrup	Chaygaon - JUGIBARI After field visit by WR dept, Gaon Pradhan, Field Officer (DM) it was seen that an erosion of 20-25 m span at the bank of river kolohi at 17/6/2022 around 8:30 AM. 0
		Bhawraguri - MOKRAMBIL, BAMUNIGAON, DEMDEMA, NABRAPARA NABINAGAR, RIMIJHIMI,
		KACHUKATA, FALUGURI AS REPORTED BY INCHARGE CONTROL ROOM GOSSAIGAON WATER
		RESOURCE SUB-DIVISION 1. SEVERE BANK EROSION OBSERVED AT VILLAGE MOKRAMBIL OF
		RIVER JOYMA ON L/B LENGTH 250 M ON 16-06-2022 2. SEVERE BANK EROSION OBSERVED AT
		VILLAGE BAMUNIGAON OF RIVER GONGIA ON R/B LENGTH 1000 M ON 16-06-2022 3. SEVERE BANK EROSION OBSERVED AT VILLAGE DEMDEMA NABRAPARA OF RIVER GONGIA ON L/B
	Kokrajhar	LENGTH 300 M ON 16-06-2022 4. SEVERE BANK EROSION OBSERVED AT VILLAGE NABINAGAR
		OF RIVER GONGIA ON L/B LENGTH 300 M ON 16-06-2022 5. SEVERE BANK EROSION OBSERVED
		AT VILLAGE RIMIJHIMI OF RIVER GONGIA ON R/B LENGTH 550 M ON 16-06-2022 6. SEVERE BANK
		EROSION OBSERVED AT VILLAGE KACHUKATA OF RIVER GONGIA ON R/B LENGTH 600 M ON 16-
		06-2022 7. SEVERE BANK EROSION OBSERVED AT VILLAGE FALUGURI OF RIVER GONGIA ON R/B
		LENGTH 450 M ON 17-06-2022 0 Laharighat - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori As per report received from the Water
		resources dept. On 18-06-2022, erosion is observed in areas like Leruamukh, Goroimari, Bhajaikhati gaon &
	Morigaon	Barchapori area. With maximum erosion of 1 m in Leruamukh, 0m in Goroimari , 3 m in Bhajaikhati gaon & 3 m
		in Barchapori. 0
		Tihu - Culvert Erosion (Partially) Pub Barjar as on 16-06-2022 AS per report GB Culvert Erosion Pub Barjar
	N. 11 .	as on 16-06-2022 0,
	Nalbari	Barkhetri - larkuchi and kaplabori b/dyke on R/B of river Brahmaputra from adabari to kukarjan damaged due to erosion at larkuchi(26.262321N 91.257011E), length 500m, and at Kaplabori(26.2638N 91.29038344E) length
		300m as reported by AEE, WRD, Mukalmua on 18/06/2022 0
	Sonitpur	Thelamara - Village- Bangalgaon Date- 18/06/2022, Length of erosion-60x 50 metres approx as reported by
	~ 3Pui	1 To the state of

		concerned LM on 18/06/2022. 0,
		Chariduar - BANK EROSION AT BHOBOLA GAON BONGALI DTD 18/06/2022 CHARIDUAR
		REVENUE CIRCLE 0,
		Tezpur - saru Pakhiyajhar Dated: 18/06/2022 erosion is observed on the leftbank of Ghagara river at Saru
		Pakhiyajhar village. Length 50 M (approx) 0
		Margherita - 1. Namdang Bashbari Active erosion is going on the South bank side of Buridihing river at Namdang Basbari since 17/06/2022 till 18/06/2022 As per report received from the Field Officer Margherita, the stretch area is 3000m. 10,
	Tinsukia	Sadiya - 1. 8th mile. 2. koilabasti 1. Erosion at 8th mile by Kundil river under the bridge since 16/06/2022 to 17/06/2022 as per report received from the concerned Gaon Pradhan. Stretch area is 02 m. Location (27°52'02"N, 95°45'36"E). 2. Active erosion is reported from Koilabasti area by Kundil river since 16/06/2022 to 17/06/2022 by concerned Gaon Pradhan. Stretch area is 04 m. Location (27°50'48.8"N, 95°42'45.2"E). 10
	Udalguri	Khairabari - Dhupguri (Subari) Severe erosion by Mora Suklai River at Dhopguri (subari) village near Batho
	District	Mandir to Paddy field. Length: 400 M (approx.) Date of Occurrence: 17.06.2022 500 Details
		Sonai - Bhubandhar Pt-I 2 Nos of House Severely Damage due to Incessant Rain today at around 9:30 AM As
	Cachar	reported by LR Staff of Sonai Revenue Circle on dated 18.06.2022. 7
	Dima-	Haflong - 1.) Landslide at Surat Nagar, Haflong Landslide at Surat Nagar, Haflong as per info received from
	Hasao	local dated 18/06/2022 0
	Goalpara	Balijana - Paharatoli village (ward no. 1 & 2) and kharmuza Paharatoli village (ward no. 1 & 2) and kharmuza is in grip of landslide due to which many families are affected. The date of occurrence is 16.06.2022 till date. 153
		Algapur - Burniebrese T.E under Algapur Revenue Circle Dtd. 18.06.2022 A landslide reported at around
		10.30am house of Anjan Das prtially damaged 5,
	Hailakandi	Katlicherra - Dinonathpur Pt. I under Katlicherra Revenue Circle on DTD. 18/06/2022 A landslide occurred at Dinonathpur Pt. I under Katlicherra Revenue Circle on DTD. 18/06/2022 at 7.30 am where a boy namely Bahar Uddin Mazumder was died in the said incident. Area of landslide - Length- 30 meter, Breadth - 20 meter 1
Landslide	Kamrup (M)	Chandrapur - occured at Kharghuli N.C(ramching chapori).no casulaty,the residents were asked to immediately vacate the area and move to safe location. Landslide occured on 18/06/2022. Partial Damage. No casualty 0, Sonapur - Amching Jorabat Landslide occurred near Ananda Das's house. The family was evacuated from the site immediately and shifted to safer place. Date- 18/06/2022 4,
		Guwahati - Pub Sarania, Joypur Kharghuli Landslide incident occured on 18-06-2022 7, Dispur - Hengrabari Landslide incident occured on 18/06/2022 at Hengrabari, near Nabajyoti Club: Deepak Choudhury's residence suffered partial damage and Abani Chetia Bora Sin's residence is partially damaged and could collapse anytime. Both the families are asked to vacate the area immediately. Partial Damage. No Casualty 8
	Karimganj	Badarpur - Anglar Bazar, Borthal Pt-X, Mohakal Pt-VI, Bargool, Harinadik, Borthal Pt-IX, Baniargool On 18-06-2022 due to incessant Rainfall landslide occurred at various locations also causing damages to Anglar Bazar Public High School. Approx. 15 nos. of houses have been damage 102, Patherkandi - Duhalia Pt-4 A landslide occurred on 18/06/2022 at village Duhalia Pt-4, PS-Patharkandi 22, Karimganj - Sanibari due to heavy rain landslide occurred at sanibari on 18/06/2022 10, Nilambazar - Baniargool dated on 18/06/2022 landslide occurred at the above village where one minor girl
		named Hamida Begam D/o. Jamil Ahmed, aged about 10 years found dead. 6, RK Nagar - Bakalkandi 1 no died and 3 nos . Injured and Hospitalized, dated on 18/06/2022. 4
	South	Mankachar - 1. Borkona As per report gaon pradhan took place of occurrence Borkona 3 nos families house
	Salmara	dameged due to land slide on 18/06/22 16
	District	Details Permagner Permate Pood I due to continuous rain (From 16.6.2022 to 18.6.2022) 5800
	Barpeta Darrang	Barnagar - Barpeta Road due to continuous rain (From 16-6-2022 to 18-6-2022) 5800 Mangaldoi - Ward No. 1,2,3,4,5,6,7,8,9,10 due to rising of water level of river Bega and other rivers 25000
	2 1111111111111111111111111111111111111	Balijana - Goalpara Town Ward no. 3,4,5,6,7,8,10,11,12,13,14, & 17 Goalpara Town Ward no.
Urban Flood	Goalpara	3,4,5,6,7,8,10,11,12,13,14, & 17 Partially affected affected due to urban flood the occurred on 16.06.2022 1423, Lakhipur - Lakhipur Town Ward No. 1,2,3,4,5,6,8,9&10 Due to Urban Flood in Lakhipur Town Ward No. 1,2,3,4,5,6,8,9&10 got affected. The Date of Occurence of Urban Flood on 16.06.2022 to till Date i.e 18.06.2022 7512
	Hailakandi	Hailakandi - Ward no-11,12,2,13,3,7,8,4, Due to heavy rain on 18.06.2022 submerged roads/ houses in urban area. 650
	Kamrup (M)	Guwahati - BG Colony maligaon Partial water logging on 18-06-2022 0, Dispur - Rukminigaon, Keraikuchi, Sawkuchi, Jatia, Hatigaon, Baghorbari, Hengrabari waterlogging on 18/06/2022 0
	Nalbari	Nalbari - Hajo Road, Palla Road , Circuit House Road, Bidyapur. MNC Collage Road, Forest Office Road, Gopal Bazar, Sarathi Road, Collage Road, Nagira Chowk, Udaypur as per LM report above mentioned places are faced urban flood due to continuous raining, Dated: 18/06/2022 2500
	Udalguri	Udalguri - Udalguri Town Overtopping of goloni river water to nearby houses in Udalguri Town area on 17.06.2022 432