

FRIMS Assam



Flood Reporting And Information Management System

				Daily Flood Report as on	19-06-2022 at 4:00 PM						
Particulars	Situation as	tuation as on 19-06-2022 (in last 24 hours)									
Rivers flowing above Danger	Rivers flowi level	ng above d	anger		nas (Nh Road Crossing), Pagladiya (Nt Road Crossing), Puthimari pili (Dharamtul), Subansiri (Badatighat), Brahmaputra (Dhubri; atighat)						
Level (as per CWC bulletin issued at 8 AM)	Rivers flowi flood level	ng above h	ighest	Kopili (Kampur)							
,	No. of Districts Affected			ected Districts	Name of Urban Flood Districts						
District Affected	33	Bongaiga Dhemaji, Goalpara Jorhat, K West, Ka Majuli, N Sivasaga	on, Cachar Dhubri, Di , Golaghat, amrup, Kar rimganj, Ko Iorigaon, N	ta, Biswanath, , Chirang, Darrang, brugarh, Dima-Hasao, Hailakandi, Hojai, nrup (M), Karbi Anglong okrajhar, Lakhimpur, Jagaon, Nalbari, South Salmara, Udalguri	Barpeta, Cachar, Darrang, Goalpara, Kamrup (M), Karimganj, Nalbari, Udalguri						
No. Of Revenue Circles Affected	127		put, 1 moukid, Oddiguii								
	District	Total	Revenue	Circle							
	Bajali	2		arupeta, Bajali							
	Baksa	5		Barama, Baska, Baganpara, Barnagar RC part, Jalah							
	Barpeta	6	Barpeta,	Barpeta, Baghbar, Kalgachia, Sarthebari, Barnagar, Chenga							
	Biswanath	4	Gohpur, Halem, Naduar RC part, Biswanath								
	Bongaigao n	3	Manikpu	pur, Boitamari, Srijangram							
	Cachar	5	Katigoral	n, Silchar, Lakhipur, Sonai,	Udharbond						
	Chirang	3	Sidli, Ber	ngtal, Bijni							
	Darrang	4	Mangaldo	oi, Dalgaon, Sipajhar, Patha	arighat						
	Dhemaji	4	Sissiborg	aon, Dhemaji, Jonai, Goga	mukh						
	Dhubri	8	Dhubri, C	Gauripur, South Salmara Pa	rt, Chapar, Athani, Bilasipara, Golakganj, Agamoni						
	Dibrugarh	1	Chabua								
N Of	Dima- Hasao	1	Haflong								
Name Of Revenue	Goalpara	4	Balijana,	Lakhipur, Matia, Rongjuli							
Circles	Golaghat	3		Khumtai, Bokakhat							
Affected	Hailakandi	4		di, Katlicherra, Lala, Algap	our						
	Hojai	3		ojai, Doboka							
	Jorhat	2	Jorhat Ea								
	Kamrup	9	Rangia, C	Goroimari, Kayan, Palashba	ari, Chamaria, Chaygaon, Hajo, North Ghy, Kamalpur						
	Kamrup (M)	3	Guwahati	i, Dispur, Sonapur							
	Karbi Anglong West	1	Donkamo								
1	Karimganj	5		, Patherkandi, Karimganj, I							
	Kokrajhar	5		uri, Gossaigaon, Bagribari,							
	Lakhimpur	6			hpuria, Kadam, Subansiri, Nowboicha						
1	Majuli	2		Jjani Majuli							
1	Morigaon	4		n, Laharighat, Bhuragaon, M							
	Nagaon	5		Raha, Kaliabor, Nagaon, S	-						
	Nalbari 7 Ghograpar, Tihu, Banekuchi, Paschim Nalbari, Barkhetri, Barbhag, Nalbari										

	Civana	1 2	Domesti	Civagaar				
	Sivasagar	5	Demow,		Naduar Th-1	amara, Tezpur		
	Sonitpur South	3	Dilektaju	ıı, Cılarıduar,	inaduar, The	amara, rezpur		
	Salmara	2		mara, Manka	nchar			
	Tamulpur	2		, Tamulpur	·		·	
	Tinsukia	2		, Doomdoom				
	Udalguri	5	Udalguri,	Khairabari,	Harisinga, Ka	laigaon, Mazbat		
	Total	127						
	District	Total	Revenue					
	Bajali	173		a 78), (Baj				
	Baksa	46				npara 8), (Barnagar RC)		
	Barpeta	614	(Barpeta 64)	145), (Baş	ghbar 141),	(Kalgachia 100), (Sarthe	ebari 135), (Barnagar 29), (Chenga
	Biswanath	60	(Gohpur	14), (Hale	m 36), (Nac	duar RC part 3), (Biswan	ath 7)	
	Bongaigao n	88	(Manikp	ur 5), (Boi	tamari 20), ((Srijangram 63)		
	Cachar	313	(Katigora	ah 154), (S	ilchar 65), (Lakhipur 20), (Sonai 6	0), (Udharbo	ond 14)
	Chirang	26	(Sidli 3), (Bengtal	7), (Bijni 1	.6)		
	Darrang	394	(Mangalo	doi 165), (]	Dalgaon 92)	, (Sipajhar 57), (Pathari	ghat 80)	
	Dhemaji	107	(Sissibor	gaon 25), (Dhemaji 5)	, (Jonai 39), (Gogamukł	n 38)	
	Dhubri	645	(Dhubri	52), (Gauri	ipur 49), (S	outh Salmara Part 126), (, (Agamoni 31)		(Athani 120), (
	Dibrugarh	4	(Chabua		nakganj 0+)	, (Agamom 51)		
	Dima-	11	(Haflong	· · · ·				
	Hasao	207			11: 1105)	(M.: 176) (D.: 111	14)	
	Goalpara	327				(Matia 76), (Rongjuli	14)	
	Golaghat	26			ntai 4), (Bo		`	
	Hailakandi	20 104	(Hailakandi 11), (Katlicherra 1), (Lala 3), (Algapur 5)					
	Hojai Jorhat	104	(Lanka 16), (Hojai 53), (Doboka 35) (Jorhat East 7), (Teok 3)					
Villages	Jornat	10				Kayan 28), (Palashbari	24) (Chamar	ria 12) (Chaygaan 5
Affected	Kamrup	328				Kayan 28), (Falasilban Kamalpur 68)	24), (Chama	11a 12), (Chaygaon 3
	Kamrup (M)	25	(Guwaha	nti 2), (Cha	ndrapur 8),	(Dispur 10), (Sonapur	5)	
	Karbi							
	Anglong	6	(Donkan	nokam 6)				
	West	225	(D. 1	110) (D	1 1 1:100) / IZ - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	1 101)	(DIC)
	Karimganj), (Karimganj 19), (Nila		
	Kokrajhar	129), (Bagribari 106), (Kok thana 7), (Bihpuria 38)		
	Lakhimpur	172	Subansiri	3), (Nowb	oicha 44)	mana /), (Binpuria 38)	, (Kadam 11), (Narayanpur 17), (
	Majuli	48			Majuli 16)			
	Morigaon	174				(Bhuragaon 20), (Mayo		
	Nagaon	229				liabor 3), (Nagaon 26),		
	Nalbari	331		par 81), (T 37), (Nalba		anekuchi 19), (Paschim N	Nalbari 25), ((Barkhetri 69), (
	Sivasagar	14		5), (Sivsag				
	Sonitpur	189	(Dhekiaj	uli 66), (C	hariduar 33)	, (Naduar 1), (Thelamar	ra 33), (Tezp	our 56)
	South Salmara	69	(South S	almara 37),	(Mankachar	32)		
	Tamulpur	46	(Goreswa	ar 29), (Ta	mulpur 17)			
	Tinsukia	23			ndooma 22)			
	Udalguri	151				(Harisinga 8), (Kalaiga	on 56), (Ma	zbat 9)
	Total	5137						
					Total		Crop	
	District	Male	Female	Children	Populatio n	Population Details	Area (in Hect.)	Crop Area Details
Population And Crop	Bajali	177700	137200	33400	348300	(Sarupeta 188300), (Bajali 160000)	520.00	(Sarupeta 520.00), (Bajali 0.00)
Area Affected	Baksa	12418	9851	7721	29990	(Barnagar RC part 22064), (Barama 1450), (Baska 835), (Baganpara 3941), (543.00	(Barnagar RC part 480.00), (Barama 7.00), (Baska 0.00), (Baganpara 41.00), (
						Jalah 1700)		Jalah 15.00)

Barpeta	523403	505127	247579	1276109	(Barpeta 214076), (Baghbar 370497), (Kalgachia 198692), (Sarthebari 335837), (Barnagar 8857), (Chenga 148150)	27907.00	(Barpeta 779.00), (Baghbar 18983.00), (Kalgachia 1823.50), (Sarthebari 2014.00), (Barnagar 1757.50), (Chenga 2550.00)
Biswanath	8559	6670	4419	19648	(Gohpur 2889), (Halem 16247), (Naduar RC part 0), (Biswanath 512)	1379.50	(Gohpur 536.00), (Halem 571.00), (Naduar RC part 22.50), (Biswanath 250.00)
Bongaigao n	8316	6675	4218	19209	(Manikpur 12360), (Srijangram 0), (Boitamari 6849)	321.00	(Manikpur 321.00), (Srijangram 0.00), (Boitamari 0.00)
Cachar	55541	51692	38589	145822	(Katigorah 87108), (Silchar 28390), (Lakhipur 2925), (Sonai 25602), (Udharbond 1797)	0.00	(Katigorah 0.00), (Silchar 0.00), (Lakhipur 0.00), (Sonai 0.00), (Udharbond 0.00)
Chirang	4168	3223	2745	10136	(Sidli 599), (Bijni 6823), (Bengtal 2714)	3322.20	(Sidli 368.50), (Bijni 2922.50), (Bengtal 31.20)
Darrang	165089	145177	83703	393969	(Mangaldoi 125007), (Dalgaon 123940), (Sipajhar 58537), (Patharighat 86485)	8380.00	(Mangaldoi 2328.00), (Dalgaon 3795.50), (Sipajhar 256.50), (Patharighat 2000.00)
Dhemaji	16990	15547	8436	40973	(Sissiborgaon 11196), (Jonai 9126), (Gogamukh 17117), (Dhemaji 3534)	7175.50	(Sissiborgaon 730.00), (Jonai 5941.50), (Gogamukh 467.00), (Dhemaji 37.00)
Dhubri	46720	37962	21884	106566	(Dhubri 0), (Gauripur 0), (South Salmara Part 96013), (Chapar 570), (Athani 1695), (Bilasipara 7422), (Golakganj 866), (Agamoni 0)	8656.83	(Dhubri 564.00), (Gauripur 535.60), (South Salmara Part 2394.00), (Chapar 1018.20), (Athani 2289.03), (Bilasipara 0.00), (Golakganj 962.50), (Agamoni 893.50)
Dibrugarh	2870	2204	1593	6667	(Chabua 6667)	5.60	(Chabua 5.60)
Goalpara	129415	96748	40105	266268	(Balijana 98319), (Lakhipur 161317), (Matia 6632), (Rongjuli 0)	3630.50	(Balijana 762.50), (Lakhipur 2227.00), (Matia 614.00), (Rongjuli 27.00)
Golaghat	2537	1911	691	5139	(Dergaon 33), (Bokakhat 5106), (Khumtai 0)	57.00	(Dergaon 0.00), (Bokakhat 31.00), (Khumtai 26.00)
Hailakandi	1496	1024	407	2927	(Hailakandi 1300), (Lala 550), (Katlicherra 145), (Algapur 932)	25.00	(Hailakandi 0.00), (Lala 0.00), (Katlicherra 0.00), (Algapur 25.00)
Hojai	54276	41359	13111	108746	(Lanka 12494), (Hojai 68874), (Doboka 27378)	2785.00	(Lanka 815.00), (Hojai 1534.00), (Doboka 436.00)
Jorhat	174	116	102	392	(Jorhat East 321), (Teok 71)	0.00	(Jorhat East 0.00), (Teok 0.00)
Kamrup	110225	95076	49968	255269	(Rangia 76850), (Goroimari 0), (Kayan 38122), (Chamaria 0), (Chaygaon 0), (Kamalpur 27382), (Palashbari 0), (Hajo 101164), (North Ghy 11751)	4535.40	(Rangia 680.00), (Goroimari 559.00), (Kayan 358.00), (Chamaria 92.50), (Chaygaon 144.00), (Kamalpur 468.90), (Palashbari 305.50), (Hajo 1787.00), (North Ghy 140.50)

	Kamrup (M)	5490	5010	255	10755	(Guwahati 455), (Chandrapur 0), (Dispur 10300), (Sonapur 0)	219.00	(Guwahati 0.00), (Chandrapur 0.00), (Dispur 0.00), (Sonapur 219.00)
	Karbi Anglong West	2716	2717	9181	14614	(Donkamokam 14614)	66.00	(Donkamokam 66.00)
	Karimganj	46164	30972	11668	88804	(RK Nagar 34425), (Badarpur 10833), (Patherkandi 5250), (Karimganj 13150), (Nilambazar 25146)	225.00	(RK Nagar 225.00), (Badarpur 0.00), (Patherkandi 0.00), (Karimganj 0.00), (Nilambazar 0.00)
	Kokrajhar	17249	14369	6892	38510	(Bagribari 22884), (Bhawraguri 2659), (Gossaigaon 542), (Kokrajhar 483), (Dotma 11942)	284.49	(Bagribari 284.49), (Bhawraguri 0.00), (Gossaigaon 0.00), (Kokrajhar 0.00), (Dotma 0.00)
	Lakhimpur	55675	38399	22527	116601	(North Lakhimpur 51619), (Narayanpur 0), (Nowboicha 37898), (Dhakuakhana 1358), (Bihpuria 21027), (Kadam 0), (Subansiri 4699)	1318.15	(North Lakhimpur 161.00), (Narayanpur 0.00), (Nowboicha 313.30), (Dhakuakhana 50.00), (Bihpuria 640.35), (Kadam 46.50), (Subansiri 107.00)
	Majuli	0	0	0	0	(Majuli 0), (Ujani Majuli 0)	660.94	(Majuli 424.80), (Ujani Majuli 236.14)
	Morigaon	26898	25817	16104	68819	(Morigaon 42068), (Bhuragaon 26751), (Mayong 0), (Laharighat 0)	2439.00	(Morigaon 750.00), (Bhuragaon 658.00), (Mayong 930.00), (Laharighat 101.00)
	Nagaon	128371	115759	120329	364459	(Kampur 221738), (Raha 119133), (Nagaon 22690), (Samaguri 459), (Kaliabor 439)	15058.14	(Kampur 7800.00), (Raha 6932.14), (Nagaon 86.00), (Samaguri 185.00), (Kaliabor 55.00)
	Nalbari	102383	89657	42753	234793	(Ghograpar 58214), (Tihu 44605), (Banekuchi 39093), (Paschim Nalbari 49621), (Barbhag 11500), (Nalbari 12500), (Barkhetri 19260)	5916.30	(Ghograpar 718.00), (Tihu 367.00), (Banekuchi 161.00), (Paschim Nalbari 554.00), (Barbhag 83.50), (Nalbari 338.10), (Barkhetri 3694.70)
	Sivasagar	2846	2752	694	6292	(Sivsagar 6292), (Demow 0)	85.90	(Sivsagar 60.00), (Demow 25.90)
	Sonitpur	24583	21971	24623	71177	(Naduar 0), (Dhekiajuli 6260), (Chariduar 55743), (Thelamara 4954), (Tezpur 4220)	4469.70	(Naduar 50.50), (Dhekiajuli 2876.60), (Chariduar 171.00), (Thelamara 646.00), (Tezpur 725.60)
	South Salmara	31373	25725	14330	71428	(South Salmara 71016), (Mankachar 412)	405.00	(South Salmara 0.00), (Mankachar 405.00)
	Tamulpur	11351	10721	5474	27546	(Goreswar 20177), (Tamulpur 7369)	983.20	(Goreswar 183.20), (Tamulpur 800.00)
	Tinsukia	5237	4343	3427	13007	(Tinsukia 76), (Doomdooma 12931)	379.08	(Tinsukia 8.85), (Doomdooma 370.23)
	Udalguri	27632	21975	15615	65222	(Udalguri 11035), (Mazbat 1039), (Khairabari 2514), (Harisinga 2078), (Kalaigaon 48556)	5617.00	(Udalguri 5103.00), (Mazbat 0.00), (Khairabari 10.00), (Harisinga 0.00), (Kalaigaon 504.00)
	Total	180786 5	156774 9	852543	4228157		107370.43	
Relief	District	Total	Relief Ca	amp		Relief Distr	ribution Cent	res

Camps /	Bajali	66	47(Sarupeta 9, Bajali 38)		19(Sarupeta	a 1, Bajali 1	8)		
Centres	Baksa	22	6(Barama 3, Baska 3, Barnagar R				Barnagar RC p		
Opened	Barpeta	94	82(Barpeta 33, Baghbar 4, Sarthe Chenga 32)	bari 13,	12(Barpeta 4)	0, Baghbar	0, Sarthebari	8, Chenga	
	Bongaigao n	66	32(Manikpur 3, Boitamari 3, Srija	angram 26)	34(Manikpur 5, Boitamari 2, Srijangram 27)				
	Cachar	107	88(Katigorah 17, Silchar 57, Lakl Sonai 7, Udharbond 1)	nipur 6,	19(Katigorah 0, Silchar 0, Lakhipur 0, Sonai 19, Udharbond 0)				
	Chirang	12	12(Bengtal 1, Bijni 11)			0, Bijni 0)			
	Darrang	30	19(Mangaldoi 9, Dalgaon 1, Sipa Patharighat 5)	jhar 4,	11(Mangaldoi 0, Dalgaon 0, Sipajhar 0, Patharighat 11)				
	Dhemaji	10	0(Sissiborgaon 0, Dhemaji 0, Jone Gogamukh 0)	ai 0,		gaon 2, Dher	naji 1, Jonai	3,	
	Dhubri	43	43(Chapar 3, Athani 4, Bilasipara Golakganj 1)	. 35,			Bilasipara 0, C	Golakganj	
	Dibrugarh	3	0(Chabua 0)		3(Chabua	3)			
	Dima- Hasao	29	25(Haflong 25)		4(Haflong				
	Goalpara	100	59(Balijana 26, Lakhipur 30, Mat	ia 3)	41(Baliiana	a 11. Lakhipu	r 30, Matia 0))	
	Hailakandi	16	8(Hailakandi 5, Algapur 3, Katlic Lala 0)				0, Katlicherr		
	Hojai	61	47(Hojai 33, Doboka 14)), Doboka 14)		
	Kamrup	53	26(Rangia 9, Hajo 3, North Ghy Kamalpur 10, Kayan 0)	4,	27(Rangia 10, Kayan		orth Ghy 11,	Kamalpur	
	Kamrup (M)	6	2(Guwahati 2)		4(Guwahat				
	Karbi Anglong West	6	0(Donkamokam 0)		6(Donkamokam 6)				
	Karimganj	73	30(Badarpur 10, Patherkandi 1, K 19, Nilambazar 0, RK Nagar 0)	arimganj	43(Badarpur 8, Patherkandi 4, Karimganj 0, Nilambazar 6, RK Nagar 25) 24(Gossaigaon 0, Bagribari 4, Kokrajhar 0, Dotma 17, Bhawraguri 3)				
	Kokrajhar	40	16(Gossaigaon 2, Bagribari 9, Ko Dotma 2, Bhawraguri 0)	krajhar 3,					
	Lakhimpur	12	0(North Lakhimpur 0, Dhakuakhar Bihpuria 0, Nowboicha 0)	na 0,	12(North L		Dhakuakhana	1,	
	Nagaon	33	33(Kampur 17, Raha 5, Nagaon	11)	_	0, Raha 0, N			
	Nalbari	120	111(Ghograpar 3, Tihu 20, Banek Paschim Nalbari 21, Barbhag 20, 30)		9(Ghograpar 5, Tihu 0, Banekuchi 0, Paschim Nalbari 0, Barbhag 0, Nalbari 4)				
	Sivasagar	7	0(Sivsagar 0)		7(Sivsagar				
	Sonitpur	26	2(Dhekiajuli 1, Chariduar 1, Thel Tezpur 0)	amara 0,	24(Dhekiaj Tezpur 5)		ıar 0, Thelam	ara 17,	
	Tamulpur	42	22(Goreswar 8, Tamulpur 14)			ar 9, Tamulpı			
	Tinsukia	10	4(Doomdooma 4, Tinsukia 0)	. 16		oma 4, Tinsul		1.0	
	Udalguri	60	30(Udalguri 10, Harisinga 5, Kala Mazbat 9, Khairabari 0)	aigaon 6,	Mazbat 0,	ri 22, Harising Khairabari 4	ga 4, Kalaigao)	on 0,	
	Total	1147	744		403			D	
	District	Total	Revenue Circlewise	Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y	
	Bajali	6439	(Sarupeta 1662), (Bajali 4777)	2718	2983	628	93	17	
	Baksa	681	(Baganpara 0), (Barnagar RC part 0), (Jalah 0), (Barama 305), (Baska 376)	293	289	91	8	0	
Inmates In Relief Camps	Barpeta	13178	(Barpeta 7253), (Kalgachia 0), (Sarthebari 2706), (Barnagar 0), (Chenga 1604), (Baghbar 1615)	5528	5021	2494	116	19	
	Bongaigao n	8367	(Boitamari 586), (Srijangram 7021), (Manikpur 760)	3915	3358	1012	82	0	
	Cachar	13259	(Katigorah 1962), (Silchar 10468), (Lakhipur 108), (Sonai 677), (Udharbond 44)	5570	4878	2809	0	2	
	Chirang	3384	(Sidli 0), (Bengtal 224), (Bijni 3160)	1623	1197	546	18	0	

Lives Lost Confirmed - Death Type	District	Total	Flood Death	Drownin g (Non Flood)	Landslide					
Human	Total	9	6	0 General	3					
	Udalguri	1	0	0	1	(Harisinga (Udalguri		on 0), (Khaira	abarı 0), (Maz	zbat [0),
	Karimganj	1	1	0	0	0), (RK Na	gar 0)	anj 0), (Nilam		
Lives Lost - Confirmed	Kamrup	1	1	0	0	(Kamalpur (Rangia 0	0), (Kayan)	on 0), (Goroin 0), (North Gh	y 0), (Palashb	pari 0),
Human	Cachar	3	2	0	1	(Udharbon	d 0)	ur 0), (Silchar		
	Barpeta	2	1	0	1	(Kalgachia	0), (Sartheb		-	
	Bajali	1	1	0	0		, (Sarupeta 0			
	District	Total	Male	Female	Children	Revenue C	1			
	Total	186424	, , (110			82648	72645	29722	1283	126
	Udalguri	3864	(Udalgur	ari 0), (Mazl i 1689), (Ha llaigaon 101	risinga	1629	1290	826	118	1
	Tinsukia	1223		oma 1223)		540	400	263	20	0
	Tamulpur	2790	(Goreswa 1583)	nr 1207), (Ta	amulpur	813	797	1156	24	0
	Sonitpur	617	(Dhekiaji 117), (Na 0), (Tezp		nelamara	221	252	138	6	0
	Nalbari	29965	(Paschim (Barkheti	562), (Banekt Nalbari 109 ri 0), (Barbh 5500), (Gho	914), ag 1746),	13993	11542	3918	467	45
	Nagaon	8715	(Kampur (Nagaon		na 296),	3362	3056	2263	31	3
	Kokrajhar	3416	(Bhawrag 542), (Ba (Kokrajh	guri 0), (Gos gribari 2125 ar 483), (Do	ssaigaon 5), otma 266)	1267	1169	953	23	4
	Karimganj	10304	(Nilamba (Badarpu	zar 0), (RK r 959), (Patl imganj 9303	Nagar 0), herkandi	4162	4096	2045	1	0
	Kamrup (M)	42	(Chandra	pur 0), (Dis 0), (Guwah	pur 0),	25	10	7	0	0
	Kamrup	6059	(Palashba (Chaygao 2454), (R	ari 0), (Kaya ari 0), (Chan on 0), (Kama angia 2015) Torth Ghy 53	naria 0), alpur), (Hajo	2928	1913	1200	17	1
	Hojai	39405	(Lanka ((Doboka	0), (Hojai 35 3419)	5986),	20534	17781	1080	8	2
	Hailakandi	1323	(Katliche	rra 0), (Lala ndi 772), (A		554	412	357	0	0
	Goalpara	16754		6962), (Lak Iatia 584), (7529	5782	3264	148	31
	Dima- Hasao	1628	(Haflong	1628)		583	620	369	55	1
	Dhubri	8234	(Dhubri Salmara l (Bilasipa	0), (Gauripu: Part 0), (Ath ra 7422), (A 149), (Golak	nani 597), gamoni 0),	2366	3469	2379	20	0
	Darrang	6777		loi 4474), (I ipajhar 0), (•	2495	2330	1924	28	0

	Bajali	1	1	0	0					
	Barpeta	2	2	0	0					
	Cachar	3	0	0	3					
	Kamrup	1	1	0	0					
	Karimganj	1	1	0	0					
	Udalguri	1	1	0	0					
	Total	9	6	0	3					
	District	Total	Male	Female	Children	Details				
	District	Total	Maic	Female	Ciliuren		(Lakhim	r (O) (Silch	ar 0), (Sonai	1)
	Cachar	1	1	0	0	(Udharbon	d 0)	ii 0), (Siicii	ai 0), (3011ai	1),
Human	Dibrugarh	4	4	0	0	(Chabua 4				
Lives Lost -	Hojai	1	1	0	0		l), (Hojai 0),			
Missing	Tamulpur	1	1	0	0	(Goreswar	0), (Tamulp	ır 1)		
	Udalguri	1	1	0	0	(Harisinga (Udalguri		on 0), (Khai	rabari 0), (Ma	azbat 0),
	Total	8	8	0	0	(Odaiguri)	1)			
	District	Total	Flood	Non Flood						
**	Cachar	1	1	0						
Human	Dibrugarh	4	4	0						
Lives Lost	Hojai	1	1	0						
Missing - Type	Tamulpur	1	1	0						
1 ypc	Udalguri	1	1	0						
	Total	8	8	0						
	District	Total	Big	Small	Poultry					
	Bajali	97784	55857	28477	13450					
	Baksa	26641	12461	9880	4300					
	Barpeta	826509	358676	163327	304506					
	Biswanath	1174	884	290	0					
	Cachar	15080	12450	2630	0					
	Chirang	9839	4360	2588	2891					
Г	Darrang	218987	129201	61201	28585					
	Dhemaji	60050	24387	13945	21718					
	Dhubri	336739	213779	122960	0					
	Dibrugarh	1754	1477	277	0					
	Goalpara	56618	35565	12266	8787					
	Golaghat	450	380	70	0					
	Hailakandi	1771	690	261	820					
Animals	Hojai	71962	35185	19927	16850					
Affected	Kamrup	379431	219160	41476	118795					
	Kamrup	3710	2450	1260	0					
	(M)	26656	12067	5,000	19000					
	Kokrajhar	36656	12967 28318	5689	18000 4153					
	Lakhimpur Morigaon	44537 38000		12066 2500						
		57189	5500 30563	17288	30000 9338					
	Nagaon Nalbari	303964	132024	109180	62760					
	Sonitpur	31793	16482	15101	210					
	South	31/93								
	Salmara	271672	104987	74164	92521					
	Tamulpur	21971	10577	10119	1275					
	Udalguri	13749	6662	6265	822					
	Total	292803 0	145504 2	733207	739781					
	District	Total	Big	Small	Poultry					
	Chirang	66	0	5	61					
Animals	Kamrup	743	41	75	627					
Washed	Nalbari	1	1	0	0					
Away	Sonitpur	2	0	2	0					
	Total	812	42	82	688					
Houses	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle	Others Total
Damaged	Domests					1			Shed	12
	Barpeta	2	0	2	6	4	10	0	12	12

	Darrang	50	0	50	0	0	0	0	0	0
	Kamrup	0	0	0	25	10	35	0	0	0
	Kamrup	0	0	0	1	1	2	0	0	0
	(M)	U	U	U	1	1	2	U	U	U
	Lakhimpur	6	0	6	11	0	11	0	0	0
	Sonitpur	39	3	42	5	2	7	4	0	4
	Total	97	3	100	48	17	65	4	12	16
	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d
	Bajali	NDRF, S			5	6	0	0	0	0
	Barpeta	Office/Lo Local Peo	-	istration,	49	728	26420	0	0	2
	Bongaigao n	Engine Books Office/Lo	ople, Count oat, Circle ocal Admin		29	0	0	0	0	16
	Cachar	Administr Defence/ Fire & Er (F&ES), 1	fice/Local ration, Civi Γrained Vo mergency S Police, ND sources De	lunteers, ervices RF, SDRF,	13	95	12	0	0	6
	Chirang				3	0	0	0	0	8
	Darrang	People, S Defence/	ramilitary fo DRF, Civil Frained Vo		19	1360	80	0	0	18
	· · ·	NDRF				0	0			2
	Dhemaji	G: 1 Of	C' /T 1		1	0	0	0	0	2
	Dhubri	Administr CHOTOO	fice/Local ration, Poli GUMA GP	ce, SDRF,	10	119	154	0	0	8
Rescue	Dibrugarh	NDRF, S			4	0	0	0	0	0
Operation	Dima- Hasao	Volunteer Services (SDRF, W	ence/Trainders, Fire & E (F&ES), Potater Resou ent, PWD (I	Emergency blice, rces	0	0	0	0	0	15
	Goalpara				0	0	0	0	0	17
	Hojai	People, N	DRF, SDR cy Services		54	2145	152	0	0	1
	Kamrup	Administr Emergend NDRF, S.	fice/Local ration, Fire by Services DRF, ramilitary for	(F&ES),	23	964	0	0	0	12
	Kamrup (M)	Circle Of Administr	fice/Local ration, Local MC, Police	al People,	1	0	0	0	0	0
	Karimganj	Local Pec	ple, SDRF		11	418	25	0	0	0
	Kokrajhar				4	0	0	0	0	4
	Morigaon	presently emergence	e Boat depl standby for	r	2	0	0	0	0	0
	Nagaon	(F&ES), S Office/Lo Local Peo		ele	20	2412	306	0	0	8
	Nalbari	SDRF, N Army/Par	DRF, amilitary f	orce	6	157	33	0	0	15

	Sonitpur	NDRF	NDRF		2	250	0	0	0	2
	South	Circle Of	fice/Local			2.4			0	
	Salmara	Administr	ration		2	24	51	0	0	0
	Tamulpur	Army/Par NDRF, S	amilitary fo	orce,	5	74	0	0	0	1
	Udalguri	Fire & En (F&ES), I	nergency S NDRF	ervices	3	8	0	0	0	0
	Total				266	8760	27233	0	0	135
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder	Cattle Feed - Wheat Bran (in	Cattle Feed	- Rice Bran	(in Q)
	D-:-1:	COE 00	10.25	10.12	907.02	(in Q)	Q)	0.00		
	Bajali	605.98	18.35	12.13	807.92	0.00	1391.20	0.00		
	Baksa	237.50	42.47	12.95	1319.01	0.00	171.04	0.00		
	Barpeta	168.06	31.61	8.30	27.00	0.00	2830.00	0.00		
	Bongaigao n	1242.33	234.48	70.32	6432.50	0.00	881.25	0.00		
	Cachar	174.00	35.37	10.48	1048.00	0.00	0.00	0.00		
	Chirang	129.79	23.28	7.03	718.77	135.00	0.00	0.00		
	Darrang	430.82	110.53	18.85	2105.00	213.25	0.00	221.20		
	Dhemaji	10.20	1.86	0.55	55.89	0.00	217.00	0.00		
	Dhubri	27.65	5.09	10.38	152.61	0.00	3559.63	0.00		
	Dibrugarh	45.36	8.43	2.54	0.00	0.00	0.00	0.00		
	Dima- Hasao	21.00	2.00	1.00	100.00	0.00	0.00	0.00		
	Goalpara	143.04	25.64	7.70	769.14	0.00	1101.26	0.00		
Relief	Golaghat	7.23	1.27	0.38	38.16	0.00	0.00	0.00		
Distributed	Hailakandi	14.87	2.78	0.84	69.71	0.00	0.00	0.00		
Distributed			17.10		216.00	0.00				
	Hojai	0.00		1.75			0.00	81.50 0.00		
	Kamrup	3367.72	484.93	424.39	15654.64	0.00	438.68	0.00		
	Karbi Anglong West	129.56	24.46	7.34	733.85	0.00	0.00	0.00		
	Karimganj	333.57	63.33	17.51	908.89	0.00	0.00	0.00		
	Kokrajhar	897.55	166.74	50.03	5002.05	100.00	887.00	0.00		
	Lakhimpur	156.71	28.27	8.49	848.61	0.00	126.30	150.34		
	Nagaon	141.13	25.57	7.68	0.00	0.00	250.00	0.00		
	Nalbari	70.71	12.52	3.75	375.66	0.00	1036.00	0.00		
	Sivasagar	106.50	18.88	5.66	0.00	0.00	0.00	0.00		
	Sonitpur	8.59	1.59	0.48	0.00	0.00	744.34	0.00		
	South Salmara	66.90	12.36	3.71	37.10	0.00	0.00	0.00		
		631.30	150.78	23.38	206.38	0.00	6.00	0.00		
	Tamulpur									
	Tinsukia	178.79 318.87	32.89	9.83	9.83	0.00	0.00	0.00		
	Udalguri	210.0/	55.60	16.14	1317.18	0.00	0.00	0.00		
	Total	9665.73	1638.1	743.59	38953.90	448.25	13639.70	453.04		
	District	Baby Foo Liquid	od	Baby Food	l Solid	Others				
	Bajali	0.00-ml, (0.00-Q	0.00-ml, 0.	00-Q	700.00-Pkt;	Match Box-1			
Relief Distributed Others	Baksa 0.00-Pkt, 0.00-Q		29.00-Pkt,	0.00-Q	Pkt; Sanitar Candle-101 Pieces; Reg Pieces; Mos	y Napkin-158 0.00-Pkt; Tar ister-12.00-Pi	it -80.00-Pkt; 3.00-Pkt; Mosc paulin-15.00-F ieces; Biscuit-2 7.00-Pkt; Sanit Pkt	quito Net-240 Pieces; Torch 270.00-Pkt; S	.00-Pieces; Light-2.00- oap-335.00-	
	Barpeta	0.00-Q		0.00-Q, 20.	.00-Pkt	coals-502.0 100.00-Pkt;	0-Pkt; Sanitar Candle -100.		0.00-Pkt; Mos	squito coil -
	Bongaigao n	603.00-Pl	kt, 0.00-Q	603.00-Pkt	, 0.00-Q	Pouches-10 Pieces; Mot	00.00-Pkt; To ther Horlicks-	; Temp. HTW/ bilet-9.00-Piece 29.00-Pkt; Sar 2.00-Pkt; Tarpe	es; Tarpaulin- nitary Pad-282	-1470.00- 2.00-Pkt;

					HTW-8.00-Pieces			
	Cachar	0.00-Q		0.00-Q	cook Food-44.00-Pkt			
					Amul Taaza-96.00-Pkt; Biscuits-96.00-Pkt; Sanitary Pads-			
	Chirang	16.00-Pkt	t, 0.00-Q	0.00-Q, 441.00-Pkt	10.00-Pieces; Tarpaulin-705.00-Pieces; Candle-1083.00-Pkt;			
	C			ζ,	Mosquito Net-408.00-Pkt; Mosquito Coil-991.00-Pkt; Sanitary			
					Napkin-300.00-Pkt 0-0.00-Q; tarpauline-300.00-Pieces; candles-50.00-Pkt;			
	Darrang	0.00-Q		0.00-Q, 50.00-Pkt	mosquito coil-30.00-Pkt; sanitary napkin-20.00-Pkt			
					Tarpaulin-161.00-Pieces; Water pouch-4000.00-Pkt; Hand Tube			
	Dhemaji	0.00-Q		0.00-Q	well-26.00-Pieces			
	Dhubri	0.00-Q		0.00-Q, 21.00-Pkt	Tarpauline-250.00-Pieces; Tarpaulin-132.00-Pieces; Chira-3.45-Q; gur-0.65-Q; HTW-5.00-Pieces; Temporary Toilet-2.00-Pieces; Drinking Water-300.00-L; Bleaching powder-25.00-Kg;			
					0-0.00-Q; Sanitary pad-21.00-Pkt; Mother Horlicks-20.00-Pkt			
	Dibrugarh	0.00-Q		0.00-Q	Tarpaulin sheets-10.00-Pieces			
	Dima- Hasao	0.00-Q		15.00-Pkt	Haldi-100.00-Pkt; Milk-100.00-L; Potato-500.00-Kg; Onion-100.00-Kg; Biscuit-700.00-Pkt; Candle-300.00-Pkt; Match Box-100.00-Pkt; Mosquito Repellent-200.00-Pkt; Bathing Soap-100.00-Pieces; Phenyl-50.00-Pieces; Dettol Liquid-100.00-Pieces			
	Goalpara	0.00-Q		0.00-Q	0-0.00-Q			
					Sanitary napkin-40.00-Pkt; Candle-90.00-Pkt; M Coil-120.00-			
	Golaghat	0.00-Q		0.00-Q	Pieces; Matchbox-20.00-Pkt			
	Hailakandi	290.00-Pl	kt	94.00-Pkt	Sanitary Napkin-105.00-Pkt; Candle-65.00-Pkt; Match box-26.00-Pkt			
	Hojai	0.00-Q		0.00-Q	Tarpualin-340.00-Pieces; Water Bottle-3120.00-L; Sanitary pad-75.00-Pkt; Candle-130.00-Pkt; Chira-27.00-Q; Gur-4.50-Q; Amul Taza-336.00-L; Biscuit-324.00-Pkt; Sanitary Pad-65.00-Pkt; Phenyl-5.00-Pieces; Bleaching Powder-5.00-Pkt			
	Kamrup	amrup 335.00-Pkt, 0.00-Q		335.00-Pkt, 0.00-Q	Tarpaulin-800.00-Pieces; 00-0.00-Q; 1. Water Bottle 2. Sanitary Napkins-1500.00-Pkt; Wheat bran-564.00-Q			
	Kamrup (M)	0.00-Q		0.00-Q	Watter -630.00-L; Bread-105.00-Pkt; Biscuit-105.00-Pkt; Tarpoulin-20.00-Pieces			
	Karbi Anglong West	0.00-Q		0.00-Q				
	Karimganj	50.00-Pkt, 100.00- Q 0.00-Q, 0.00-Pkt		Q		1 () ()()=()		
	Kokrajhar					0.00-Q, 248.00-Pkt	Chemical Packets-270.00-Pkt; Halogen Tablets-2300.00-Pieces; Biscuit-7650.00-Pkt; Candle-1507.00-Pkt; Match Box-153.00-Pkt; 0-0.00-Q	
	Lakhimpur	0.00-Q		0.00-Q, 138.00-Pkt	Taurpalin-1055.00-Pieces; Tarpaulin-135.00-Pieces; Concentrate Feed (Cattle Feed)-16.50-Q; Concentrated cattle feed Godrej Supreme-50.50-Q			
	Nagaon	1534.00-I Q	Pkt, 0.00-	1534.00-Pkt, 0.00-Q	M.Coil-160.00-Pkt; Candle-546.00-Pkt; Sanitary Napkin- 100.00-Pkt; Mosquito Coil-226.00-Pkt; Bleaching Powder- 10.00-Pkt; Halogen Tablet-1200.00-Pkt; M. Coil-150.00-Pkt; Match Box-40.00-Pkt			
	Nalbari	0.00-Q		0.00-Q, 140.00-Pkt	Wheat Bran -2048.00-Q; wheat bran-282.00-Q			
	Sivasagar	0.00-Q		0.00-Q	0-0.00-Q			
	Sonitpur	0.00-Q		0.00-Q				
	South Salmara	0.00-Q		0.00-Q	Biskut -122.00-Pkt; Amul-366.00-ml; Sanitary Napkin -117.00- Pkt; Phenyle-135.00-Pieces; B/Powder -270.00-Pkt; Candal- 231.00-Pkt; Match-77.00-Pkt; Dasbin-7.00-Pieces			
	Tamulpur	0.00-Kg		297.50-Kg	wheat bran-10222.00-Kg			
	Tinsukia	0.00-Q		0.00-Q				
	Udalguri	0.00-Q, 2	02.00-Pkt	0.00-Q, 131.00-Pkt	Sanitary Pad-2758.00-Pkt; Tarpaulin-360.00-Pieces; Blanket-300.00-Pieces; Baby Food-150.00-Pkt; Mosquito Net-300.00-Pkt; Rice Bran-454.00-Q			
Infrastructur	District	Numbe r	Details					
e Damaged - Embankme	Bajali	1	WRD Str	ucture) of Kaldia River is	ver at Barnalikuchi village Barnalikuchi Embankment (Non breached at Barnalikuchi village.this report is received from Bajali			
nt Breached	Barpeta	1			(Long - 91.237112, Lat - 26.502939) ilortari Hati, Barpeta, Date-18-06-2022 (Long - 0.000000, Lat -			
	*	<u> </u>	Barpeta - Harijan embankment Bilortari Hati, Barpeta, Date-18-06-2022 (Long - 0.000000, Lat -					

			0.000000)
	Darrang	1	
	Hailakandi	1	Algapur - Dyke along L/B of River Katakhal from Mohanpur Ch 4495 to 4520 village Mohanpur Part-III Under Algapur Revenue Circle on dtd. 19.06.2022 As per report of Water Resources some miscreant has cut the dyke. (Long - 92.635988, Lat - 24.753855)
	Sonitpur	1	Tezpur - emabankment at Bhojkhowa village Bhojkhowa village Dated: 19/06/2022. an embankment on the bank of Marabharali river at Bhojkhowa Gaon constructed by PNRD Dept. by Bhumuraguri Panchayat was damaged at around 2:00 AM. Length 20 m (approx) (Long - 92.831050, Lat - 26.626220)
	Tamulpur	1	Goreswar - Halongbari Puthimari Embankment Village Halongbari Dated 18/06/2022. Left bank embankment breached at Village Halongbari approximately damage 100 m (Long - 91.676329, Lat - 26.548262)
	Udalguri	1	Kalaigaon - Embankment from Parimal Das's house to Sunil Das's house Gerua The embankment has breached on 19/06/2022 due to heavy current of flood water from river Noa in the R/B of the river covering a length of 70 feet and breadth of 12 feet. (Long - 91.981011, Lat - 26.616542)
	Total	7	
	District	Numbe r	Details
	Barpeta	1	Barnagar - RB Embankment at Khatakuchi Khatakuchi As per report received from J.E., WR Dept the embankment was damaged due to rising water of Beki and heavy rainfall. But it is repaired now. Date-18-6-2022 (Long - 26.429720, Lat - 90.892500)
	Darrang	5	
Infrastructur e Damaged - Embankme nt Affected	Dhemaji	4	Dhemaji - Moridhal Dyke from Sarukacharigaon to Sissikalghar Maridhal Dyke from Sarukacharigaon to Sissikalghar Yesterday on 18/06/2022, Slump Down of Country side slope of the embankment occured at Maridhal Dyke from Sarukachari gaon to Sissikalghar , Inbetween ch.11020m to ch.11150m. (Long - 0.000000, Lat - 0.000000), Gogamukh - Kumatiya Left Bank From NH-15 to Gurathali Chapori In between Ch.10000m to Ch.10400m. Severe boiling due to damage of country side slope on 18/06/2022 (Long - 0.000000, Lat - 0.000000), Kumatiya Right Bank Nepalibasti to Gurathali Chapori. In between Ch.12600m to Ch.13590m. Severe boiling due to damage of country side slope on 18/06/2022 (Long - 0.000000, Lat - 0.000000), Kumatiya Right Bank Nepalibasti to Gurathali Chapori. In between Ch.15200m to Ch.16000m. Severe boiling due to damage of country side slope on 18/06/2022 (Long - 0.000000, Lat - 0.000000)
	Kamrup	2	Rangia - Balagaon Embankment Rangia Vill- Balagaon Balagaon Embankment over topped at many locations as per report of AE, WR, Rangia on 18.6.2022 (Long - 91.614617, Lat - 26.463481), Rangia Town Protection Embankment Vill- Tatarkuchi Rangia Town protection Embankment over topped at many locations as per report of AE, WR, Rangia on 18.6.2022 (Long - 91.476083, Lat - 26.476083)
	Karimganj	1	Nilambazar - Bairagichak area Nilambazar As reported by Water Resource dated on 19/02/2022 around 160 mt of bank damages observed near the left bank embankment of river Longai from Patharkandi to Nilambazar. (Long - 92.344125, Lat - 24.741953)
	Total	13	
	District	Numbe r	Details
	Baksa	3	Barama - Barama-Dhamdhama Road At village Alagjar Deulguri Chowk Road completely damaged at length of 10 m approx. 18-06-2022 (Long - 91.376628, Lat - 26.526894), Baganpara - Thakursupa LP school to uzirghat road culvert. Garbhitor The road on dated 15/06/2022 as informed by PWD has been damaged approx 4m due to flash flood. (Long - 91.487282, Lat - 26.573140), Garbhitor idghah maidan Garbhitor On dated 15/06/2022 as informed by PWD has been damaged approx 40m due to flash flood. (Long - 91.482781, Lat - 26.570265)
Infrastructur e Damaged - Road	Barpeta	26	Baghbar - FA Ahmed Medical college to Medhitary road Jati Gaon Medhitary Date of Damage: 16.06.2022 Damage Type: Both side Shoulder Damaged. Reported By: Pwd Deptt. (Long - 90.960972, Lat - 26.313267), Kalgachia - Various 20 nos of road (details mentioned in Remarks) Various places within the Circle (details mentioned in Remarks) As per report received from PWD department on 19/06/2022, total 20 nos of Roads are affected and damaged, they are - 1. Haldia village road has submerged and road surface damaged from Ch. 00.00 m to Ch. 800.00 m (Length = 800.00 m, Avg submerged height = 0.70 cm, location coordinate = 26.403573, 90.85168) 2. MonakosaAmtola road has submerged and road surface damaged from Ch. 1500.00 m to 1700.00 m. (Length = 200.00 m, submerged height = 0.30 cm, and location coordinate = 26.377592, 90.863063) 3. Dewkura to Lachanga road(PMGSY pkg no. AS-01-89) has submerged and surface damaged from Ch, 1300.00 m to 2500.00 m. (Length = 1200.00 m, Avg submerged height = 70 cm, location coordinate = 26.393582, 90.864336) 4. KalgachiaNittalkoran Madrassa to MajjarChor road has submerged and surface damaged from Ch. 300.00 m to Ch. 450.00 m and from Ch. 600.00 m to Ch. 1200.00 m. (Length = 700.00 m Avg.

		submarged height = 0.00 am and leasting =====1in=t= 26.256470,00.964692\5, N. I. i. i. II
		submerged height = 0.90 cm and location coordinate = 26.356478, 90.864683) 5. Nabajyoti college
		approach road to Dakshin GunialguriRoad formation washed away from Ch. 2350.00 m to Ch. 2365.00 m (Length = 15.00 m and width = 3.50 m Avg Height = 2.50 m location coordinate =
		26.351053, 90.899336) 6. Kalgachia to kararkur via amguri road (PMGSY pkg no. AS-01-88) has
		submerged and surface damaged from Ch. 100.00 m to Ch. 250.00 m (Length = 150.00 m Submerged
		Height = 60 cm and location coordinate = 26.355418, 90.880886) 7. Monakosa Dimapur road surface
		damaged from Ch. 00.00 m to 600.00 m (Length = 600.00 m and width = 3.50 m and location
		coordinate = 26.37745, 90.86243) 8. Kalgachia IB approach road Paschim Amguri road submerged
		from Ch. 400.00 m to 1300.00 m (Length = 800.00 m and Avg. submerged Height = 1.00 m and
		location coordinate = 26.35900, 90.870745) 9. One Hume Pipe culvert damaged at Ch. 3.900 m and
		road Side berm damaged at 2nd Km, 3rd Km and 4th Km of Kalgachia to Bamuntary road. (length =
		400.00 m, Avg. Width = 1.80 m and Avg. Height = 1.80 m and location coordinate = 26.332438,
		90.859593) 10. Road surface damaged and road side berm damaged of Sorbhog to Kalgachia road at
		Ch. 7th Km, 9thKm, 10th km, and 11th Km (Length = 500.00 m, Width = 2.00 m and location
		coordinate = 26°23′21.16″N, 90°51′50.55″E) 11. KalgachiaNadiaparaRoad formation damaged at 2nd
		Km and 3rd Km. (Length = 250.00, width = 2.00 m and location Coordinate = 26.358805, 90.856663)
		12. KalgachiaNadiapara road to Dakshin Gunialguri road surface damaged from Ch. 0.00 m to 400.00
		m. (Length = 400.00 m, width = 3.00 m and location coordinate =26.358178, 90.858828) 13. Haldia pather Mill ghar to Bilortari road submerged and surface damaged from Ch.00.00 m to 1900.00 m.
		(Length = 1900.00 m, width = 3.00 m, Submerged Height = 0.800 m and location Coordinate =
		26°24'5.00"N, 90°52'1.60"E) 14. Haldia pather Mill ghar toChakla PMGSY road surface damaged
		from Ch.00.00 m to 400.00 m. (Length = 400.00 m, width = 3.00 m and location Coordinate =
		26°24'6.59"N, 90°51'26.44"E) 15. BarbhitaSewrachara road (PMGSY Pkg. No. AS-01-58) has
		submerged and road surface damaged at 1st Km, 2nd Km, 4th Km, and 5th Km and 8th km. and RCC
		Bridge No. 4/1 approach damaged. (Length = 2500.00 m, Avg. Submerged Height = 0.900 m and
		location coordinate = 26.263617, 90.787762) 16. SPT Bridge No. 2/1 bridge and approach damaged at
		Rampur Boroitoli road. (Bridge Approach Length = 60.00 m, Width = 1.80 m, Height= 2.50 m and
		location coordinate = 26.274437, 90.823299) 17. KadongHatchara road Surface damaged at Ch. 2nd
		Km, 3rd Km, 4th Km and RCC bridge No. 1/1 Approach Damaged. (Length = 3000.00 m, width =
		3.00 m and location coordinate = 26.294013, 90.819317) 18. ChenimariMoinbori Road Surface and
		side berm damaged at 1st Km (damaged Length = 200.00 m) and Road submerged 4th Km, 5th Km. (Submerged length = 600.00 m, Avg. Height = 80.00 cm and location Coordinate = 26.283618,
		90.782678) 19. BarbhitaMahia Road (PMGSY Package No. AS-01-89) road Submerged from Ch.
		1300.00 m to 1700.00 m (Length = 400.00 m and Submerged Height = 1.00 m and location coordinate
		= 26.277271, 90.767375) 20. Kandulia to Garalipam PMGSY road (PKG No. AS-01-59) RCC bridge
		No. 2/1 approach damaged (Length = 150.00 m, Width = 1.80 m and height = 2.00 m) and road
		submerged at 2nd km (Submerged length = 200.00 m, Avg. Depth = 0.80 m and location coordinate =
		26.286593, 90.783173). (Long - 0.000000, Lat - 0.000000),
		Barnagar - Santoradaha Deka Thakur Than to Ahompathar LP School Road Santoradaha &
		Ahompathar As per report received from Ex. Engineer, PWD Sorbhog & Jania Terri Road Divn,
		Barpetaroad on 18/06/2022 surface damage occured. (Long - 0.000000, Lat - 0.000000),
		Noontola village Road Noontola As per report received from Ex. Engineer, PWD Sorbhog & Jania
		Terri Road Divn, Barpetaroad on 18/06/2022 surface damage occured. (Long - 90.860235, Lat -
		26.505140), Noontola LP School to PMGSY Road Noontola As per report received from Ex. Engineer, PWD
		Sorbhog & Jania Terri Road Divn, Barpetaroad on 18/06/2022 surface damage occured. (Long -
		90.860102, Lat - 26.501074),
		Noontola LP School to Rampur Shiv Mandir Noontola As per report received from Ex. Engineer,
		PWD Sorbhog & Jania Terri Road Divn, Barpetaroad on 18/06/2022 surface damage occured. (Long
		- 90.860202, Lat - 26.500999),
		Pachim Rampur Shiv Mandir to PMGSY Road Rampur As per report received from Ex. Engineer,
		PWD Sorbhog & Jania Terri Road Divn, Barpetaroad on 18/06/2022 surface damage occured. (Long
		- 90.809604, Lat - 26.494531)
		Lakhipur - NH 53/37 Lobonkhal Jiribam Road NH 53/37 Lobonkhal Jiribam Road Lenght In 100
		M, As reported by EE PWD NH Division, on dated 19.06.2022. (Long - 0.000000, Lat - 0.000000),
		NH 37 Pallorbond To Lakhipur NH 37 Pallorbond To Lakhipur at Ch 155 As reported by EE PWD Rural Road Division Lakhipur ,on dated 19.06.2022. (Long - 24817278.000000, Lat -
		9293961.000000),
Cachar	4	NH 37 Kunjolaki To Lakhipur NH 37 Kunjolaki To Lakhipur Length 12.9 M As reported by EE
Cacilai	-	PWD Rural Road Division Lakhipur ,on dated 19.06.2022. (Long - 93021013.000000, Lat -
		24801691.000000),
		Lakhipur Swashan Road Swashan Road Lakhipur Swashan Road Length 100 M As reported by EE
		PWD Rural Road Division Lakhipur ,on dated 19.06.2022. (Long - 9300085.000000, Lat -
		24800638.000000)
		Sidli - Hagra bridge to Birhangaon road Bherbery As reported by PWD(R&B) Chirang, Hagra
Chirang	1	bridge to Birhangaon road surface and side shoulders damaged (Ch.300m to 1400m) on 18-06-2022,
]		Damaged details Length-900m, Breadth-4m, depth- 0.30m (Long - 90.559842, Lat - 26.557211)

1	1	
Darrang	33	Dalgaon - RANGAGARAPATHAR TO GHILADHARI ROAD VARIOUS LOCATION OF THE ROAD AT CH.772.00M.CH.6500.00M RANGAGARAPATHAR TO GHILADHARI ROAD HAS BEEN SUBMARGED AT VARIOUS LOCATION ONE CULVERT FULLY ERODED JBREACH OCCURED ABOUT 50.00M.DATE OF OCCURANCE 18:06/2022 (Long - 0.00000). Lat - 0.000000). AND ATE OF OCCURANCE 18:06/2022 (Long - 0.000000). Lat - 0.000000). AND BHUTPUKHURI ROAD AT CH.1020.00M BRACH OCCURED APPROACHES OF THE SLAB CULVERT IN AGAJHAN TO BHUTPUKHURI ROAD HAS BEEN BREACH OCCURED APPROACHES OF THE SLAB CULVERT TO H.1020.00M.DATE OF OCCURANCE 18:06/2022 (Long - 0.000000). Lat - 0.000000]. BARKUR TO SHYAMPUR ROAD BARKUR TO SHYAMPUR ROAD BARKUR TO SHYAMPUR ROAD HAS BEEN SUBMARGED ABOUT THE HEIGHT OF 0.450M .DATE OF OCCURANCE 18:06/2022 (Long - 0.000000). Lat - 0.000000]. BARKUR TO SHYAMPUR ROAD HAS BEEN SUBMARGED ABOUT THE HEIGHT OF 0.450M .DATE OF OCCURANCE 18:06/2022 (Long - 0.000000). Lat - 0.000000]. MPROVEMENT AND UPGRADATION OF ROAD FROM DALGAON TO DHUPGURI VIA DEV PUKHURI UNDER ASOM MALA ERODED AT CH.13+700 KM IMPROVEMENT AND UPGRADATION OF ROAD FROM DALGAON TO DHUPGURI VIA DEV PUKHURI UNDER ASOM MALA ERODED AT CH.13+700 KM ,DATE OF OCCURANCE 18:06/2022 (Long - 0.00000). Lat - 0.000000). KACHOMARI CHOR TO BADLICHOR ROAD SUBMARGED AT VARIOUS LOCATION KACHOMARI CHOR TO BADLICHOR ROAD SUBMARGED AT VARIOUS LOCATION KACHOMARI CHOR TO BADLICHOR ROAD ROAD SUBMARGED AT VARIOUS LOCATION KACHOMARI CHOR TO BADLICHOR ROAD ROAD SUBMARGED AT VARIOUS LOCATION KACHOMARI CHOR TO BADLICHOR ROAD ROAD SUBMARGED FROM KACHOMARI CHAPORI HABI TO NH-52 ROAD ROAD SUBMARGED FROM KACHOMARI CHAPORI HABI TO NH-52 ROAD ROAD SUBMARGED FROM KACHOMARI CHAPORI TO KACHOMARI CHAPORI HABI TO NH-52 ROAD ROAD SUBMARGED FROM KACHOMARI CHAPORI TO KACHOMARI CHAPORI PMGSY ROAD SUBMARGED AFO OCCURANCE 18:06/2022 (Long - 0.000000). Lat - 0.000000). RATHORY TO GHILADHARI ROAD THE HEIGHT OF 0.50M,DATE OF OCCURANCE 18:06/2022 (Long - 0.000000). Lat - 0.000000). LATHORY TO SHAPAY ROAD HAS B
		NO2. MAZGAON TO MADHUPUR ROAD NO2. MAZGAON TO MADHUPUR ROAD SUBMARGED AT CH 1800.00M TO 2100.00M NO2. MAZGAON TO MADHUPUR ROAD HAS BEEN SUBMARGED AT CH 1800.00M TO 2100.00M ABOUT THE DEPTH OF 0.300M,DATE
		OF OCCURANCE 16/06/2022 (Long - 0.000000, Lat - 0.000000), KHETERCHAR NO.1 TO NH-52 ROAD KHETERCHAR NO.1 TO NH-52 ROAD AT CH.2100.00M TO 2200.00M KHETERCHAR NO.1 TO NH-52 ROAD HAS BEEN SUBMARGED(DEPTH=0.200M) & DAMAGED AT CH.2100.00M TO 2200.00M,DATE OF
		OCCURANCE 16/06/2022 (Long - 0.000000, Lat - 0.000000)
Dhemaji	1	Dhemaji - PWD road Rudrasingha Path Rudrasingha path, Dhemaji Circle Yesterday on 18/06/2022, Road surface submerged and damaged due to raiwater at Rudrasingh path from ch.10.00m to ch.220.00m and ch.280.00m tonch.460.00m, length around 390 m (Long - 94.548060, Lat - 27.468890)
Dhubri	59	Dhubri - ROAD SUBMERGED & SIDE BERM PARTIALLY DAMAGED OF ROAD FROM CHAGALCHARA PT-I. TO TIAMARI PT-I PMGSY PACKAGE NO. AS-05-188 FROM 3RD KM TO 5TH KM CHAGALCHARA Dated-16-06-2022 to 19-06-2022 (Long - 0.000000, Lat -

0.000000).

ROAD SUBMERGED & SIDE BERM PARTIALLY DAMAGED OF ROAD FROM DEBOTTAR HASDAHA PT-III TO DEBOTTAR HASDAHA PT-I PMGSY PACKAGE NO. AS-05-187 FROM 3RD KM TO 6TH KM | DEBOTTAR HASDAHA | Dated-16-06-2022 to 19-06-2022 | (Long - 0.000000, Lat - 0.000000),

HARD CRUST, SIDE BERM PARTIALLY DAMAGED ON GAURIPUR KALAHAT ROWA ROAD AT 4TH & 5TH KM | ROWA | Dated-16-06-2022 to 19-06-2022 | (Long - 0.000000, Lat - 0.000000),

Gauripur - ROAD SUBMERGED AND SIDE BERM PARTIALLY DAMAGED ON NH-31 ALOMGANJ TO SILAIRPAR ROAD AT 3RD AND 4TH KM | ALOMGANJ TO SILAIRPAR | Dated-16-06-2022 to 19-06-2022 | (Long - 0.000000, Lat - 0.000000),

SUBMERGED AND SIDE BERM PARTIALLY DAMAGED ON NH31 BOTERTOL GERAMARI PART 5 TO GHAGERALGA ROAD AT 3RD AND 4TH KM | GERAMARI | Dated-16-06-2022 to 19-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM PARTIALLY DAMAGED ON NH-31 GOIBAZAR RLY LEVEL CROSSING TO MADHUSOULMARI PT-II AT 1ST KM & 2ND KM | MADHUSOULMARI | Dated-16-06-2022 to 19-06-2022 | (Long - 0.000000, Lat - 0.000000),

ROAD SUBMERGED ON KHUDIMARI DUMARDAHA KALAHAT BINNACHARA ROAD AT 7TH KM | KHUDIMARI DUMARDAHA KALAHAT | Dated-16-06-2022 to 19-06-2022 | (Long-0.000000, Lat - 0.000000),

Bilasipara - ROAD SUBMERGED AT 1STN & 2ND KM SIDE BERM AND SURFACE DAMAGED DUE TO FLOOD WATER OF RIVER SANKOSH | NH- 31 AT SANKOSH TO GOBARDHANPARA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.177373, Lat - 26.231750),

NH- 31 AT NAYAHAT SOULMARI ROAD SUBMERGED AT 1ST & 2ND & 3RD KM ROAD SURFACE AND SIDE BERM DAMAGED DUE TO FLOOD WATER OF RIVER TIPKAI | NH-31 AT NAYAHAT SOULMARI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.151021, Lat - 26.224878),

NH-13TH KM OF BS ROAD TO DHANPUR ROAD SUBMERGED AT 1ST & 2ND & 4TH KM RCC BOXCELL NO. 1/2, 1/3, & 5/1 APPROACH AND SURFACE DMAGED DUE TO FLOOD OF HEL RIVER | NH-13TH KM OF BS ROAD TO DHANPUR ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.094683, Lat - 26.333953),

SAPATGRAM TO RANGAPANI II ROAD SUBMERGED AT 1ST & 2ND KM ROAD SURFACE AND SIDE BERM DAMAGED DUE TO FLOOD OF HEL RIVER | SAPATGRAM TO RANGAPANI II ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.124906, Lat - 26.340535),

4TH KM OF BS ROAD TO KHEJURBARI PT-I ROAD SUBMERGED 1ST & 2ND ROAD SURFACE AND SID E BERM DAMAGED DUE TO HEL RIVER | 4TH KM OF BS ROAD TO KHEJURBARI PT-I ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.163486, Lat - 26.253255),

6TH KM OF BS ROAD TO PATIMARI ROAD SUBMERGED 1ST KM RCC BRIDGE NO. $\frac{1}{2}$ APPROCHES AND SIDE BERM DAMAGED DUE TO TIPKAI RIVER | 6TH KM OF BS ROAD TO PATIMARI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.152361, Lat - 26.264072),

8TH KM OF BS ROAD TO SALTARI ROAD SUBMERGED 1ST KM SIDE BERM AND ROAD SURFACE DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER | SALTARI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.159867, Lat - 26.290470),

5TH km of BS ROAD TO GUTIPARA ROAD SUBMERGED 1ST, 2ND & 5TH KM SIDE BERM AND SURFACE DAMAGED DUE TO FLOOD OF HEL RIVER | GUTIPARA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.189126, Lat - 26.264232), 3RD km of BS ROAD TO TUSHPARA ROAD SUBMERGED 1ST & 2ND RCC BOXCELL NO. 1/1 APPROCH SIDE BERM AND ROAD SURFACE DAMAGED DUE TO FLOOD OFTIPKAI RIVER | TUSHPARA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.154550, Lat - 26.250852),

9TH KM OF BS ROAD TO BARUAPARA APPROACHES DAMAGED RCC BOXCELL NO.2/1 APPROCH AND SIDE BERM DAMAGED DUE TO FLOOD WATER OF HEL RIVER | BARUAPARA | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.171527, Lat - 26.309103),

6TH KM OF BS ROAD TO CHORUAVITA ROAD SUBMERGED 1ST& 3RD & 4TH SIDE BERM BADLY ERRODED AND SURFACE DAMAGED DUE TO FLOOD WATER OF HEL RIVER | BS ROAD TO CHORUAVITA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.170145, Lat - 26.292235),

NH- 31 AT NAYAHAT TO MURABARI ROAD SUBMERGED 1ST, 2ND & 3RD KM RCC BRIDGE NO. 1/1 APPROACH AND SIDE BERM DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER | MURABARI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.145440, Lat - 26.224397),

2ND KM OF CHORUAVITA ROAD TO ATHIABARI ROAD RCC Br. NO 3/1 APPROCH AND SIDE BERM DAMAGED DUE TO FLOOD WATER OF HEL RIVER | CHORUAVITA ROAD TO ATHIABARI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.223871, Lat - 26.241711),

NH- 31 TO PASUARKHAL PT-II ROAD SUBMERGED 1ST&2ND KM RCC Br. NO 2/1 APPROCH DAMAGED DUE TO FLOOD WATER OF SANKOSH RIVER | PASUARKHAL PT-II ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.177379, Lat - 26.231695),

3RD KM OF BS ROAD AT JOGIRMAHAL TO SALMARA ROAD SUBMERGED 1ST & 2ND RCC Br. NO 2/1 APPROACH DAMAGED DUE TO FLOOD WATER OF SANKOSH RIVER | BS ROAD AT JOGIRMAHAL | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.152627, Lat - 6.250878),

3RD KM OF CHORUAVITA ROAD TO HELAGARI ROAD RCC BOXECELL NO. 2/1 APPROCH AND SURFACE DAMAGED DUE TO FLOOD WATER OF HEL RIVER | CHORUAVITA ROAD TO HELAGARI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.172602, Lat - 26.282303),

4TH KM OF FS ROAD TO ODLARTOL ROAD SUBMERGED 1ST, 2ND & 3RD KM ROAD SIDE BERM AND SURFACE DAMAGED DUE TO FLOOD WATER OF HEL RIVER | FS ROAD TO ODLARTOL ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.166617, Lat - 26.326508),

DHANPUR TO BARKUTI ROAD HP CULVERT APPROACH AND SURFACE DAMAGED DUE TO FLOOD OF HEL RIVER | DHANPUR TO BARKUTI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.150156, Lat - 26.324423),

NH- 31 TO NATUN LAUPARA ROAD SUBMERGED 1ST KM SIDE BERM DAMAGED DUE TO FLOOD OF SANKOSH RIVER | NH- 31 TO NATUN LAUPARA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.184728, Lat - 26.233965), NH- 31 TO PASUARKHAL PT-III ROAD SUBMERGED 1ST KM SIDE BERM AND SURFACE DUE TO FLOOD WATER OF SANKOSH RIVER | NH- 31 TO PASUARKHAL PT-III ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.183066, Lat - 26.232602),

NAYAGHAT TO SAPATGRAM ROAD SUBMERGED 1ST, 2ND & 13TH KM RCC BOXCELL NO. 1/1, RCC Br. NO 4/1 APPROACH DAMAGED AND SIDE ERROTED 7TH AND 13TH KM DUE TO FLOOD WATER OF TIPKAI RIVER | NAYAGHAT TO SAPATGRAM ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.201922, Lat - 26.235027).

15TH KM OF BS ROAD TO SANTIPUR ROAD SID EBERM DAMAGED DUE TO FLOOD OF HEL RIVER | BS ROAD TO SANTIPUR ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.132866, Lat - 26.326258),

8TH KM OF FS ROAD TO CHESAPANI PART-I ROAD SUBMERGED 1ST KM ROAD SURFACE DAMAGED DUE TO FLOOD OF HEL RIVER | FS ROAD TO CHESAPANI PART-I ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.133338, Lat - 26.326320).

8TH OF FS ROAD TO CHESAPANI PART-2 ROAD SUBMERGED 1ST KM ROAD SURFACE AND SIDE BERM DAMAGED DUE TO FLOOD OF HEL RIVER | FS ROAD TO CHESAPANI PART-2 ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.135257, Lat - 26.337128),

FAKIRAGRAM SAPATGRAM ROAD SUBMERGED 1ST, 2ND, 4TH, 9TH& 10TH KM SIDE BERM AND SURFACE DAMAGED DUE TO FLOOD OF HEL RIVER | FAKIRAGRAM SAPATGRAM ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.120595, Lat - 26.332326),

RANIGANJ DHANPUR ROAD RCC Br. NO 1/1 APPROACH AND SIDE BERM DAMAGED DUE TO FLOOD WATER HEL RIVER | RANIGANJ DHANPUR ROAD RCC Br. NO 1/1 APPROACH AND SIDE BERM DAMAGED DUE TO FLOOD WATER HEL RIVER | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.175770, Lat - 26.304300), 15TH KM OF BS ROAD TO DAUTPARA ROAD VIA SANTIPUR ASHRAM SUBMERGED 1ST & 2ND KM SIDE BERM ERROTED AND SURFACE DAMAGED DUE TO FLOOD OF HEL RIVER | BS ROAD TO DAUTPARA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 0.000000, Lat - 0.000000),

DHANPUR PUKHURIPARA ROAD SUBMERGED 1ST KM HPC CULVERT NO. 1/1 DAMAGED OF FLOOD WATER OF HEL RIVER | DHANPUR PUKHURIPARA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.148717, Lat - 26.322693),

6TH KM OF ROAD TO SAULMARI ROAD SUBMERGED 1ST, 2ND & 3RD KM ROAD BREACH AT 2ND KM AND SIDE BERM ERRODED ADN ROAD SURFACE DAMAGED DUE TO FLOOD OF TIPKAI RIVER | SAULMARI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022) | (Long - 90.143633, Lat - 26.262594),

10TH KM OF BS ROAD TO SURIPARA ROAD SURFACE AND SIDE BERM DAMAGED DUE

TO HEAVY RAIN | BS ROAD TO SURIPARA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.154455, Lat - 26.304959),

9TH KM OF BS ROAD TO CHOWGURI ROAD SUBMERGED 1ST, 2ND & 3rd KM RCC CULVERT NO. 1/1 APPROCH WASHED AWAY AND 3RD KM BREACH AND SURFACE DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER | CHOWGURI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.155309, Lat - 26.295845), 3RD KM OF BS ROAD TO TIYAPARA ROAD SUBMERGED 1ST & 2ND KM SIDE BERM DAMAGED DUE TO FLOOD WATER OF SANKOSH RIVER | BS ROAD TO TIYAPARA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.159809, Lat - 26.247138),

NH-31 AT NAYAHAT TO DUBACHURI ROAD SUBMERGED 1ST & 2ND KM SIDE BERM DAMAGED DUE TO FLOOD OF TIPKAI RIVER | NAYAHAT TO DUBACHURI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.152170, Lat - 26.220040),

RATURHAT TO KUWARPAR ROAD SUBMERGED ROAD SURFACE AND SIDE BERM DAMAGED AT 1ST AND 2ND KM DUE TO FLOOD OF TIPKAI RIVER | RATURHAT TO KUWARPAR ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.124573, Lat - 26.266263),

KRISHNAGAR KAZAIKATA HUDURCHAR ROAD (FROM CH. 7000.00M TO CH.8000.00M SIDE BERM ERODED DUE TO RAIN | KRISHNAGAR KAZAIKATA HUDURCHAR ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.186779, Lat - 26.190370).

AZAIKATA HIGH SCHOOL TO NAYERAGLA VILLAGE ROAD SUBMERGED BY RIVER GARUNG (.)5TH KM OF KKH ROAD TO KAZAIKATA PT-V SUBMERGED BY RIVER GARUNG | AZAIKATA HIGH SCHOOL TO NAYERAGLA VILLAGE ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.224027, Lat - 26.225305), KRISHNAGAR KAZAIKATA HUDURCHAR ROAD RCC Br. NO 3/1,4/1,5/1 & 6/1 APPROACHES AND ROAD 1ST ,2ND 3RD,4TH ,5TH 6TH & 7TH KM SURFACE AND SIDE BERM DAMAGED DUE TO FLOOD OF GAURANG RIVER | KRISHNAGAR KAZAIKATA HUDURCHAR ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 26.261889, Lat - 90.185016),

BHELAKOBA PT-III TO BHELOKABA PT-II ROAD SUBMERED 1ST KM ROAD SURFACE AND SIDE BERM DUE TO FLOOD WATER OF TIPKAI RIVER | BHELAKOBA PT-III TO BHELOKABA PT-II ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.109050, Lat - 26.315364),

AAI SAKATI ROAD RCC Br. NO 1/1 BOTH APPROACH BADLY DAMAGED DUE TO FLOOD WATER OF HELL RIVER | AAI SAKATI ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.158305, Lat - 26.342520),

MABAZAR TO SAGUNMMARI PT-IV ROAD SUBMERGED 1ST & 2ND KM RCC Br. NO 1/1 & ½ APPROACH SADE SIDE BERM DAMAGED DUE TO FLOOD OF TIPKAI RIVER | MABAZAR TO SAGUNMMARI PT-IV ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.204980, Lat - 26.218359),

NH- 31 TO BANGALIPARA II ROAD SUBMERGED 1ST KM SIDE BERM AND ROAD SURFACE DAMAGED DUE TO FLOOD OF SANKOSH RIVER | BANGALIPARA II ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.202075, Lat - 26.239828),

BILASIPARA BLOCK DEV OFFICE TO FAKIRAGRAM VIA RANIGANJ SIDE BERM DAMAGED 1ST 2ND 4TH & 4TH KM DUE TO FLOOD WATER HEL RIVER | BILASIPARA BLOCK DEV OFFICE TO FAKIRAGRAM VIA RANIGANJ | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 17-06-2022) | (Long - 90.175770, Lat - 26.304300),

5TH KM OF BILASIPARA FAKIRAGRAM ROAD TO MADANI NAGAR, SUBMERGED AT DIFFERENT STETCHES AT 1ST KM & DAMAGES THE ROAD FORMATION & SIDE BERM DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG | BILASIPARA FAKIRAGRAM ROAD TO MADANI NAGAR | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 18-06-2022) | (Long - 90.223684, Lat - 26.275239),

BILASIPARA SDO CIVIL OFFICE APPROACH, HARD CRUST DAMAGES IN STRECHES DUE TO HEAVY RAIN | BILASIPARA SDO CIVIL OFFICE APPROACH | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 18-06-2022) | (Long - 90.277238, Lat - 26.250776),

NH-31 AT 894TH KM TO BOTERKANDA ROAD, SIDE BERM ERRODED DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG | BOTERKANDA ROAD | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 18-06-2022) | (Long - 90.221801, Lat - 26.244542),

UDMARI PT-III TO GOPIGAON PT-III ROAD, (PMGSY PACKAGE NO AS-05-117) SUBMERGED SOME PLACES & SIDE BERM DAMAGES DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG | UDMARI PT-III TO GOPIGAON PT-III ROAD, | DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 18-06-2022) | (Long - 90.235548, Lat - 26.264281), GAURANGTARI PT-I TO SIMLABARI ROAD, SURFACE DAMAGES DUE TO HIGH RISE FLOOD WATER OF RIVER BRAHMAPUTRA | GAURANGTARI PT-I TO SIMLABARI ROAD |

		DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 18-06-2022) (Long - 90.218274, Lat -
		26.344265), UDMARI SALKOCHA ROAD TO UDMARI PT-IV ROAD, ROAD SUBMERGED & FORMATION DAMAGES & WASHED AWAY AT CH. 250.00 M DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG UDMARI SALKOCHA ROAD TO UDMARI PT-IV ROAD DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 18-06-2022) (Long - 90.240131, Lat - 26.276086),
		BAMUNPARA PT-IV TO KAJAIKATA PT-I ROAD, SUBMERGED & FORMATION DAMAGES AT DIFFERENT STRETCES DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG BAMUNPARA PT-IV TO KAJAIKATA PT-I ROAD DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 18-06-2022) (Long - 90.252150, Lat - 26.229331),
		NAYERALGA PT- II TO NAYERALGA PT-IV ROAD, ROAD FORMATION DAMAGES AT DIFFERENT STRETCES DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG NAYERALGA PT- II TO NAYERALGA PT-IV ROAD DUE TO HIGH RISE FLOOD WATER (13-06-2022) to 18-06-2022) (Long - 90.187870, Lat - 26.165637),
		14TH KM OF SUAPATA PT-III TO NAYERALGA PT-III ROAD TO NAYERALGA PT IV ROAD, SUBMERGED & FORMATION DAMAGES AT DIFFERENT STRETCES DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG SUAPATA PT-III TO NAYERALGA PT-III ROAD DUE TO HIGH RISE FLOOD WATER (13-06-2022 to 18-06-2022) (Long - 90.191220,
Golaghat	1	Lat - 26.161335) Bokakhat - Tinisuti Moriahola Road submerged from ch.900.00m to Ch.1500.00m av. depth 0.20m. on 19.06.2022 Jugania ati and 2 No. Paragonia Goan (Long - 0.000000, Lat - 0.000000)
Hailakandi	1	Katlicherra - Apin Grant to Rongpur Pt. I via Dogor Apin AS-09-088 dated 19.06.2022. Rongpur Pt. I, Paharline Road under katlicherra Revenue Circle dated 19.06.2022. The road is partially damaged due to incessant rainfall. Area Of Damaged - Length- 70 meter, Breadth- 7.5 meter (Long - 92.560165, Lat - 24.501523)
Kamrup	1	Rangia - Niz Borigog Road Vill - Niz Borigog Niz Borigog road partially damaged as it submerged completly. Dated- 18/06/2022 (Long - 0.000000, Lat - 0.000000)
Kokrajhar	54	Bhawraguri - Narayanpur to Bhawraguri Kachugaon Road Narayanpur AS REPORTED BY PWD KACHUGAON RR, Submerged road from 1st Km to 2 KM SPT Bridge no 1/1 & 1/2 have been damaged on Narayanpur to Bhawraguri Kachugaon Road ON 18.06.2022 (Long - 0.000000, Lat - 0.000000), Gossaigaon - BALLAMJHORA TO KUSHUMBIL BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN 1 KM TO 2 KM ON BALLAMJHORA TO KUSHUMBIL ROAD (.) (Long - 0.000000, Lat - 0.000000), DALGAON TO RANIPUR DALGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAINIMMEDIATE RESTORATION OF DOLGAON TO RANIPUR VILLAGE ROAD VIA BORDER ROAD 15 MTRS SUBMERGE (Long - 0.000000, Lat - 0.000000), BOSHGAON TO RAIMONA BOSHGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION OF BOSHGAON TO RAIMONA VIA HOSPITAL ROAD FORMATION DAMAGED AT 1.00 KM (Long - 0.000000, Lat - 0.000000), BOSHGAON TO RAIMONA VIA HOSPITAL ROAD FORMATION DAMAGED AT 1.00 KM (Long - 0.000000, Lat - 0.000000), BOSHGAON TO RAIMONA VIA HOSPITAL ROAD FORMATION DAMAGED AT 1.00 KM (Long - 0.000000, Lat - 0.000000), BOSHGAON TO RAIMONA MOTHAMBIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION OF BOSHGAON TO RAIMONA VIA HOSPITAL TOWARDS MOTHAMBIL ROAD FORMATION DAMAGED AT 600.00 MTRS. (Long - 0.000000), Lat - 0.000000), BALLAMJHARA SINDRINALA BALLAMJHARA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON BALLAMJHARA RAIN RAINGRINALA RIVER RIVER DAMAGED ROAD AND ERODED 300 MTRS. (Long - 0.000000, Lat - 0.000000), Lat - 0.000000, Lat - 0.000000, Lat - 0.000000), GHALSON ON BALLAMJHARA BAZAR TO JIRAMPUR BALLAMJHARA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON BALLAMJHARA BAZAR TO JIRAMPUR ROAD FORMATION BADLY DAMAGED (Long - 0.000000, Lat - 0.000000),

- 0.000000, Lat - 0.000000),

Dotma - Fakiragram rabha para raod | Borjhara River | As REPORTED BY CHAIRMAN FAKIRAGRAM MUNCIPAL BOARD, BOLDER PROTECTION DAMAGED BY FLOOD AT FAKIRAGRAM RABHA PARA ROAD ON 19.06.2022 | (Long - 90.190811, Lat - 26.365751), DINGAON ROAD | DINGAON | As REPORTED BY CHAIRMAN FAKIRAGRAM MUNCIPAL BOARD, 2 NOS CULVERT AT DINGAON VILLAGE UNDER FAKIRAGRAM M.B. ON 19.06.2022 | (Long - 90.199981, Lat - 26.370577),

(Kokrajhar) At District - ADABARI SHYAMTHAIBARI ROAD | ADABARI | AS REPORTED BY ADC CEO DDMA, KOKRAJHAR ADABARI SHYAMTHAIBARI ROAD CH.400M WAS DAMAGED ON 16.06.2022 | (Long - 90.302989, Lat - 26.379454),

SALBARI ABHYAKUTI ROAD | SALBARI | AS REPORTED BY ADC CEO DDMA, KOKRAJHAR SALBARI ABHYAKUTI ROAD CH.1500M WAS DAMAGED ON 17.06.2022 | (Long - 90.332288, Lat - 26.297503),

SALKOCHA LAKHIGANJ ROAD | BAMUNGAON | AS REPORTED BY ADC CEO DDMA, KOKRAJHAR SALKOCHA LAKHIGANJ TO GAURANG BRIDGE(FLORICAN GARDEN) ROAD CH.1500M WAS DAMAGED ON 17.06.2022 | (Long - 90.273994, Lat - 26.269791), NH31C TO NORTH BASHBARI ROAD | BASHBARI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, APPROACHES OF RCC BOCS CULVERT NO 3/2 AND 4/2 ON NH31C TO NORTH BASHBARI ROAD ERRODED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000),

SINGIMARI TO BORGHOPA ROAD | SINGIMARI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, BAMBOO FOOT BRIDGE OVER RIVER HELL ON SINGIMARI TO BORGHOPA ROAD DAMAGED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000).

FS ROAD TO NORTH SINGIMARI VILLAGE ROAD | SINGIMARI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, APPROACHES OF RCC BOX CULVERT NO 1/2 ON FS ROAD TO NORTH SINGIMARI VILLAGE ROAD ERRODED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000),

NEPALPARA TO NARABARI ROAD | NEPALPARA | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, APPROACHES OF RCC BOX CULVERT NO 1/1 ON NEPALPARA TO NARABARI ROAD ERRODED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000),

KOKRAJHAR BAHALPUR ROAD | BAHALPUR | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, APPROACHES OF RCC BRIDGE NO 5/1 ON KOKRAJHAR BAHALPUR ROAD ERRODED ON 16-06-2022 | (Long - 0.000000), Lat - 0.000000).

KOKRAJHAR BAHALPUR ROAD | BAHALPUR | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 9/2, 12/2 AND 13/3 ON KOKRAJHAR BAHALPUR ROAD ERRODED ON 16-06-2022 | (Long - 0.000000), Lat - 0.000000),

SIMBARGAON KALUGAON ROAD | SIMBARGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BRIDGE NO 4/1 ON SIMBARGAON KALUGAON ROAD ERRODED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000),

BALAJAN TINALI JD ROAD TO USHA MATI ROAD | BALAJAN TINALI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT OF CIT OUTLET ON BALAJAN TINALI JD ROAD TO USHA MATI ROAD ERRODED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000),

MUKHIGAON TO HAKMABIL ROAD | MUKHIGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, HP CULVERT NO 1/1 ON MUKHIGAON TO HAKMABIL ROAD ERRODED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000),

NAYEKGAON TO ANJULIPARA ROAD | NAYEKGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, NAYEKGAON TO ANJULIPARA ROAD AT CH 1800M DAMAGED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000),

NAYEKGAON TO KULTUNGPARA ROAD | NAYEKGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, NAYEKGAON TO

KULTUNGPARA ROAD AT CH 3500M TO 3580M DAMAGED ON 16-06-2022 | (Long - 0.000000, Lat - 0.000000),

DOTMA BALAJAN TO NAYAPARA VILLAGE ROAD | DOTMA BALAJAN | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, ROAD ERRODED AT 1ST KM ON DOTMA BALAJAN TO NAYAPARA VILLAGE ROAD ON 16-06-2022 | (Long - 0.000000), Lat - 0.000000),

BARSANGAON TO UTTAR LATAGAON ROAD | BARSANGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, HP CULVERT NO 1/1 ON BARSANGAON TO UTTAR LATAGAON ROAD ERRODED ON 16-06-2022 | (Long - 0.000000), Lat - 0.000000),

NAYEKGAON TO KULTUNGPARA ROAD | NAYEKGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 4/3 ON

NAYEKGAON TO KULTUNGPARA ROAD ERRODED ON $16-06-2022 \mid (Long - 0.000000, Lat - 0.000000),$

PHUTKIBARI KOKRAJHAR ROAD | PHUTKIBARI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, GUIDE BUND OF RCC BRIDGE NO 2/1 ON PHUTKIBARI KOKRAJHAR ROAD DAMAGED ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000),

NAYEKGAON TO CHAKRASHILA ROAD | NAYEKGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, HP CULVERT NO 11/2 ON NAYEKGAON TO CHAKRASHILA ROAD DAMAGED ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000).

OWABARI JAOLIAPARA ROAD | OWABARI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, ROAD AND SIDE SHOULDER DAMAGED AT CH 35M, CH255M AND CH560M ON OWABARI JAOLIAPARA ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000),

AMLAIGURI TO SAMOKHA FOREST BLOCK ROAD | AMLAIGURI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 4/2 DAMAGED ON AMLAIGURI TO SAMOKHA FOREST BLOCK ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000),

MAORIAGAON PAKRIGURI ROAD | MAORIAGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, ROAD DAMAGED AT CH 6600M ON MAORIAGAON PAKRIGURI ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000), ODALGURI ANTHAIBARI ROAD | ODALGURI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 1/2 DAMAGED ON ODALGURI ANTHAIBARI ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000), NH 31C TO MALIGAON FV ROAD | MALIGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC SLAB CULVERT NO 5/1 DAMAGED ON NH 31C TO MALIGAON FV ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000),

HALTUGAON CHANDRAPUR ROAD | HALTUGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 1/4 DAMAGED ON HALTUGAON CHANDRAPUR ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000), KASHIGURI TO MESTABARI ROAD | KASHIGURI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 1/3 DAMAGED ON KASHIGURI TO MESTABARI ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000), NH 31C TO AODANG BAZAR ROAD | AODANG BAZAR | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 5/1 DAMAGED ON NH 31C TO AODANG BAZAR ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000),

NAYEKGAON TO ANJULIPARA ROAD | ANJULIPARA | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BRIDGE NO 2/1 DAMAGED ON NAYEKGAON TO ANJULIPARA ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000), GOPINATHPUR TO FAKIRAGRAM BANARGAON ROAD | GOPINATHPUR | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 2/1 DAMAGED ON GOPINATHPUR TO FAKIRAGRAM BANARGAON ROAD ON 14-06-2022 | (Long - 0.000000, Lat - 0.000000),

PATGAON SIMBARGAON ROAD | PATGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC SLAB CULVERT NO 6/1 ON PATGAON SIMBARGAON ROAD DAMAGED ON 15-06-2022 | (Long - 0.000000, Lat - 0.000000).

SALBARI TO ABHAYAKUTI ROAD | SALBARI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, SPT BRIDGE NO 1/1 INCLUDING APPROACHES ON SALBARI TO ABHAYAKUTI ROAD DAMAGED ON 15-06-2022 | (Long - 0.000000, Lat - 0.000000),

CHETNAGURI VILLAGE ROAD | CHETNAGURI | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, CHETNAGURI VILLAGE ROAD AT CH 500M DAMAGED ON 15-06-2022 | (Long - 0.000000, Lat - 0.000000),

PATGAON SIMBARGAON ROAD | PATGAON | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, PATGAON SIMBARGAON ROAD AT CH 9050M ERRODED ON 15-06-2022 | (Long - 0.000000, Lat - 0.000000),

BHUMKA TO EAST MALIGAON ROAD | BHUMKA | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, BHUMKA TO EAST MALIGAON ROAD AT CH 300M BREACHED ON 15-06-2022 | (Long - 0.000000, Lat - 0.000000),

MOHANPUR TO MALIGAON FV ROAD | MOHANPUR | AS REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 1/1 ON MOHANPUR TO MALIGAON FV ROAD ERRODED ON 15-06-2022 | (Long - 0.000000, Lat - 0.000000),

RAMPHALBIL TO ATHIABARI ROAD | RAMPHALBIL | AS REPORTED BY THE ASSTT.

			EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RAMPHALBIL TO ATHIABARI ROAD AT CH 5300M ERRODED ON 15-06-2022 (Long - 0.000000, Lat - 0.000000),
			SERFNGURI TO KAPURGAON ROAD SERFANGURI AS REPORTED BY THE ASSTT. EXE.
			ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 3/4 ON SERFNGURI TO KAPURGAON ROAD ERRODED ON 15-06-2022 (Long - 0.000000, Lat -
			0.000000),
			NEPALPARA VILLAGE ROAD NEPALPARA AS REPORTED BY THE ASSTT. EXE.
			ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 1/1 ON
			NEPALPARA VILLAGE ROAD ERRODED ON 15-06-2022 (Long - 0.000000, Lat - 0.000000),
			DOTMA BALAJAN ROAD TO DURAMARI VILLAGE ROAD DOTMA BALAJAN AS
			REPORTED BY THE ASSTT. EXE. ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION,
			DOTMA BALAJAN ROAD TO DURAMARI VILLAGE ROAD AT CH 0.00M TO 30.00M
			DAMAGED ON 15-06-2022 (Long - 0.000000, Lat - 0.000000),
			NO 2 JAINARY VILLAGE ROAD NO 2 JAINARY AS REPORTED BY THE ASSTT. EXE.
			ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, RCC BOX CULVERT NO 1/1 ON NO 2
			JAINARY VILLAGE ROAD DAMAGED ON 15-06-2022 (Long - 0.000000, Lat - 0.000000), AMINPARA TO JOTHAIPARA ROAD AMINPARA AS REPORTED BY THE ASSTT. EXE.
			ENGINEER, PWD KOKRAJHAR RR SUB-DIVISION, AMINPARA TO JOTHAIPARA ROAD AT
			CH 150M BREACHED ON 15-06-2022 (Long - 0.000000, Lat - 0.000000),
			BOROBADHA ROAD BOROBADHA AS REPORTED BY ASSTT. EXE. ENG. PWD
			GOSSAIGAON RR, SIDE BERM HAS BEEN DAMAGED ON D.K. ROAD AT BOROBADHA
			CH 35100M ON 15.06.2022 (Long - 0.000000, Lat - 0.000000)
			North Lakhimpur - NLKB to Azarguri Majorchapori road Azarguri 14th KM of NLKB to
			Azarguri Majorchapori road breach at ch.5500.00m on 18-06-2022 (Long - 27.098424, Lat -
			94.056718),
			Bihpuria - Dongibil H.S to 80 No. Solmari Grant At Ch 2450.00m to Ch 4480.00m As reported by AEE, PWRD Bihpuria TRSD also Road- embankment and shoulders and hard crust are eroded &
			damaged badly due to flood water spillover on 19-06-2022 (Long - 93.901327, Lat - 27.060372),
			Laluk Bishrampur to Dhekiajuji Road At RCC Bridge No.4/2 As reported by AEE, PWRD,
	T 111	_	Bihpuria TRSD, Road-RCC Bridge Approach and Road embankment and shoulders and hard crust are
	Lakhimpur	5	eroded & damaged badly due to flood water spillover on 19-06-2022. (Long - 93.926420, Lat -
			27.147247),
			Subansiri - Bolahi PWD road to Siring Gorah As reported by Dhakuakhana Territorial Road
			Division, Ghilamara the Bolahi PWD road to Siring Gorah road is submerged at 1st km(L=100.00m)
			on 19/06/2022 (Long - 0.000000, Lat - 0.000000), Suwani Medak to Yedutgaon Road As reported by Dhakuakhana Territorial Road Division, Suwani
			Medak to yedutgaon road is submerged at1st km(L=150.00m) on 19/06/2022 (Long - 0.000000, Lat
			- 0.000000)
			Majuli - 1. NLK road 2. Major Chapori road 3. Kohardubi to Notun Kulamora Chapori road 4.
			Kaliagaon to Notun Gopalchuk road 5. Rowmora to Koroiguri village via Laguati road 6. Bebejia to
			Major Chpori via Kuli Chapori Road 1. NLK road at Luit-Khabolu 2. Major Chapori road at Major
			Chapori NC 3. Kohardubi to Notun Kulamoa Chapori road at Notun Kulamoa Chapori 4. Kaliagaon to
			Notun Gopalchuk road at Ahataguri 5. Rowmora to Koroiguri village via Laguati road at Rowmora 6. Bebejia to Major Chpori via Kuli Chapori Road at Major Chpori 1. NLK road from ch 10.02 km to
			ch 10.140 km got submerged on 18.06.2022. 2. Slope erosion occurred at Major Chapori road in
			different stretches on 18.06.2022. 3. Kohardubi to Natun Kulamoa Chapori road from ch 450.00m to
	Majuli	7	ch 1060.00m (PMGSY pack no AS 10-232) got submerged on 19.06.2022. 4. Kaliagaon to Notun
			Gopalchuk road at Ahataguri ch 900m to ch 1000m and ch 2000m to 2450m got submerged on
			19.06.2022. 5. Rowmora to Koroiguri village via Laguati road ch 3000m to ch 3150m got submerged
			on 19.06.2022. 6. Bebejia to Major Chapori via Kuli Chapori road was cut off by flood water and
			communication got disrupted due to rise of water level in river Brahmaptra on 19.06.2022. (Long - 0.000000, Lat - 0.000000),
			Ujani Majuli - Dakhinpat Digholigaon road Dakhinpat Digholigaon Dakhinpat Digholigaon road
			from ch 20m to ch 800m in stretches got submerged on 19.06.2022, height approx. 60cm. (Long -
			94.277814, Lat - 26.916954)
			Laharighat - AUTOLABORI CHETUAKHAITI ROAD CHETUAKHAITI As per report of Chief
			Eng PWD roads, Guwaharti by WT massage on 18-06-2022, AUTOLABORI CHETUAKHAITI
			ROAD erodedand damaged side ber and hardcrust. (Long - 92.310600, Lat - 26.389000),
	Morigaon	3	Mayong - Sildubi -Gagalmari Pt-1 Submerged at 2nd 3rd and 6th km As reported by PWD
			Morigaon district territorial road division on 18/06/22 (Long - 91.129000, Lat - 26.267000), Lokpriyo Gopinath Bordoloi Road (SH-3B) 15th Km Submerged as reported by PWD Morigaon
			district territorial road division on 19/06/22 (Long - 92.035000, Lat - 26.235000)
-			Kampur - Road from Charaihagi to Dakhin Changchaki Bakulaguri Kampur Rev. Circle Road
			from Charaihagi to Dakhin Changchaki Bakulaguri affected Length approx 23.00 KM breach
	Nagaon	27	occurred at different location. Dtd-17.06.2022 reported by PWD Raha, Territorial Road Sub-Division.
			(Long - 0.000000, Lat - 0.000000),
			Road from Kachua Tiniali to Satlunga Kampur Rev. Circle Road from Kachua Tiniali to Satlunga

affected Length approx 4 KM breach occurred at 4th KM. Dtd-17.06.2022 reported by PWD Raha, Territorial Road Sub-Division. | (Long - 0.000000, Lat - 0.000000),

Road from Garukhuna to Natun Garukhuna | Kampur Rev. Circle | Road from Garukhuna to Natun Garukhuna Length approx 3.49 KM breach occurred at 1st and 3rd KM. Dtd-17.06.2022 reported by PWD Raha, Territorial Road Sub-Division. | (Long - 0.000000, Lat - 0.000000),

Road from Pachim Kawoimari to Bishnupuri Than | Kampur. Rev. Circle | Road from Pachim Kawoimari to Bishnupuri Than Length approx 1.00 KM breach occurred at 650.00 m and 900.00 m Dtd-17.06.2022 reported by PWD Raha, Territorial Road Sub-Division. | (Long - 0.000000, Lat - 0.000000),

Road from KSB to Gerejaipam Via Kalimandir | Kampur. Rev. Circle | Road from KSB to Gerejaipam Via Kalimandir affected Length approx 3.00 KM Dtd-17.06.2022 reported by PWD Raha, Territorial Road Sub-Division. | (Long - 0.000000, Lat - 0.000000),

Raha - Road from Hatigarh Balijuri Road | Hatigarh | Date of Occurrence-18/06/2022 Submerged-5.80 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000).

Road from Bandura Ati to Sindura Ati | Bandura Ati | Date of Occurrence-18/06/2022 Submerged-1.75 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Road from Hatigarh to Babura Ati | Hatigarh | Date of Occurrence-18/06/2022 Submerged- 3.12 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from Kakatigaon to Kamargaon | Kakatigaon | Date of Occurrence-18/06/2022 Submerged- 5.40 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from Kakatigaon to Salmara via Magurgaon Cheuguri | Salmara | Date of Occurrence-18/06/2022 Submerged- 3.35 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Road from Gaspara to Dalimbari | Gaspara | Date of Occurrence-18/06/2022 Submerged- 2.00 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from SH-17 to Chaparmukh Tini Ali | Chaparmukh TiniAli | Date of Occurrence-18/06/2022 Submerged-0.50 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Road from Petborha to Barkula | Petborha | Date of Occurrence-18/06/2022 Submerged- 3.00 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from Jukuta Khaigarh Road to Midaimari | Jukuta Khaigarh | Date of Occurrence-18/06/2022 Submerged- 1.30 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Road from Kakatigaon Railway Gate to Dablubeel via Padumani | Dablubeel | Date of Occurrence-18/06/2022 Submerged- 2.00 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Road from Jakarua Beel to Udarveti | Jakarua Beel | Date of Occurrence-18/06/2022 Submerged- 2.00 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from Dharmukh Bazar to Simaluguri | Dharmukh | Date of Occurrence-18/06/2022 Submerged- 2.00 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000)

Raha Kampur Road to Bahakabari | Bahakabari | Date of Occurrence-18/06/2022 Submerged-2.00 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from Kampur Road to Pachim Guimari | Pachim Guimari | Date of Occurrence-18/06/2022 Submerged-1.50 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Gaspara to Shirmala | Shirmala | Date of Occurrence-18/06/2022 Submerged- 0.60 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from Rahachaki to Hariamukh | Rahachaki | Date of Occurrence-18/06/2022 Eroded- 300 m (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from NH-27 to Bhatigaon | Bhatigaon | Date of Occurrence-18/06/2022 Eroded- 200 m (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), SH-17 (Kampur-Chaparmukh-Raha) | Chaparmukh | Date of Occurrence-18/06/2022 Submerged- 16 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000), Road from Dharmukh Bazar to Minabazar | Dharmukh | Date of Occurrence-18/06/2022 Submerged- 3.30 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000)

Road from Jukuta Khaigarh road to Cheuguri | Cheuguri | Date of Occurrence-18/06/2022 Submerged- 1.40 Km (Approx) Department- Raha Territorial Road Sub Division | (Long - 0.000000, Lat - 0.000000),

Nagaon - Nonoi Dakhinpat Road to Kurabahi | Nonoi, Nagaon | Nonoi Dakhinpat Road to Kurabahi, Submerged/Damaged reported by Nagaon Territorial Road Division, Dated-19/06/2022, Length-0.00M to 400.0M, Depth-0.60M to 0.80M reported by Barhampur Territorial road division. | (Long - 0.000000, Lat - 0.000000),

Nonoi dakhinpat Road | Nonoi , Nagaon | Nonoi Dakhinpat road submerged on 19/06/2022 and one

slab culver breached (Approx 20M) at 4th KM reported by Barhampur Territorial road division. (Long - 0.000000, Lat - 0.000000) Ghograpar - Ghograpar Tamulpur Road To Milanpur Road | Ghograpar | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length - 500 M | (Long - 0.000000, Ghograpar Tamulpur Road to Farm Chowk Road | Ghograpar | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length - 600 M | (Long - 0.000000, Lat -0.000000), Sathamou Katuria Road | Sathamou, Katuria | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length - 500 M | (Long - 0.000000, Lat - 0.000000), Rangia Dhamdhama Road Beached | Dhamdhama | As per W.T msg Received from PWRD, on 18/06/2022 road breached occured at Rangia-Dhamdhama Road at Ch- 15300, Length of breached -30 M | (Long - 0.000000, Lat - 0.000000), Uttar Barsiral Chataibari Road | Barsiral, Chataibari | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length - 1200 M | (Long - 0.000000, Lat -0.000000), Kaliya Gohain Than road | Kaliya Gohain Than | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length -1.5 KM | (Long - 0.000000, Lat - 0.000000), Ghograpar Tamulpur Road to Panimajkuchi | Panimajkuchi | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length -1.5 KM | (Long - 0.000000, Lat -0.000000), Katakia to Chilling Road | Katakia, Chilling | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length -3.5 KM | (Long - 0.000000, Lat - 0.000000), NH-31 To Khudra Katla Barkuchi (Khudia Ranglafali Road) | Rangafali | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length -5.60 KM | (Long -0.000000, Lat - 0.000000), Namati Lakshmi Mandir Road | Namati | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length -1 KM | (Long - 0.000000, Lat - 0.000000), Ghograpar Tamulpur Road | Ghograpar | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, culvert approach damaged, Length -10 KM | (Long - 0.000000, Lat -0.000000), Pub Barsiral LP School to Ghograpar Tamulpur Road | Pub Barsiral | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, Length -500 M | (Long - 0.000000, Lat -0.000000). Nalbari 53 Uttar Barsiral Chataibari Road Breached | Uttar Barsiral, Chataibari | As per W.T msg Received from PWRD, on 18/06/2022 road breached occured at Uttar Barsiral Chataibari Road at Ch-500,m 700 m, 850 m Length of breached - 100M | (Long - 0.000000, Lat - 0.000000), Chataibari Keherua Road breached | Chataibari Keherua | As per W.T msg Received from PWRD, on 18/06/2022 road breached occured at Chataibari Keherua Road at Ch-700,m 1200 m, Length of breached - 100M | (Long - 0.000000, Lat - 0.000000), Shiva than to Binapani LP School road | Rangafali | As Per W.T msg Received from PWRD, on 18/06/2022 the above road has been submerged, SPT bridge approach damaged, Length -10 KM | (Long - 0.000000, Lat - 0.000000). Paschim Nalbari - Nalbari Palla Road Barmankur to Kathla | Kathla Village | Submerged due to flood for a length of 1500.00 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000), Helacha Kendubari road | Helacha Village | Submerged due to flood for ch 4th Km to 6th km. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat -Barbila chowk to to Lokhopur Road | Barbila | Submerged due to flood for a length of ch 1100 m to ch 1800 m = 700 m. Information received from PWRD via WT message on 16/06/2022 | (Long -0.000000, Lat - 0.000000), Ulubari to Bori Road | Bori village | Submerged due to flood for ch 500 m to ch 800 m = 300 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat -Helacha Hendubari to Lahkarpara. | Helacha village | side berm eroded ch 00 to ch 500 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat -0.000000), Helacha Kendubari to Dalepara | Helacha | Submerged due to flood for ch 00 to ch 500 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat -Helacha Kendubari to Barbila village road | Helacha Kendubari | Submerged due to flood for ch 600 m to ch 800 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000), Solmara Pokhura road to Solmara Gopalthan | Solmara | Submerged due to flood for ch 400 m to ch 700 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat -0.000000),

Solmara Pokhura road to Solmara SC Chupa Namghar | Solmara | Submerged due to flood for ch 0.00 m to ch 400.00 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000), Lat - 0.000000),

Tihu Lachima road to Lokhopur Gopuja Khola via Kendubari. | Lokhopur | Submerged due to flood for ch 0.00 m to ch 1500.00 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000),

Amoni Bhakatpara to Chamata under PMGSY Pkg No. AS-20-169 | Amoni | Submerged due to flood for ch 600 m to 1000.00 and breached at ch 670.00 m. Information received from Dharmapur PR Subdivision , Chamata via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000), Sahpur Kharzara Road under PMGSY Pkg NO. AS- 20-200 | Sahpur | Road submerged due to flood from 50.00 m to 600.00 m. Information received from Dharmapur PR Subdivision , Chamata via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000),

Chamata Rampur Road | Chamata | Submerged frm ch 30.00 m to 150.00 m. Information received from Dharmapur PR Subdivision , Chamata via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000).

Nalana to Hatiputa Road | Hatiputa | Submerged due to flood from ch 0.00 to 308.00 m. Information received from Dharmapur TR Subdivision , Chamata via WT message on 16/06/2022 | (Long - 0.000000), Lat - 0.000000),

Nalbari Palla road to Kaihati | Kaihati | Submerged due to flood from 600.00 m to 1200.00 m. Information received from Dharmapur TR Subdivision , Chamata via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000),

Nalbari Palla road (SH-2) | Nalbari | Submerged at 11th to 12th km. Information received from Dharmapur TR Subdivision , Chamata via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000).

Amoni Bhakatpara under SPA | Amoni | Submerged due to flood from ch 0.00 - CR 500 m. Information received from Dharmapur PR Subdivision , Chamata via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000),

Bharsal SC Supa link Road | Paschim Nalbari RC | Submerged due to heavy rain/flood. Information received from Dharmapur PR Subdivision , PWRD Chamata via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000),

Sahpur Kharzara Road. (Embankment portion) | Sahpur | Overtopped and surface badly damage by river Burhadia due to flood. CH 50.00 m to ch 700.00 m to 908.00 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000),

Chamata Kaithalkuchi road. | Chamata | Submerged length ch50.00 m to 800.00 m, ch1200 m-2100 m, ch3200 m to 5000.00 m Overtopped with depth 0.30 m to 0.70 m. Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000),

THSS | Paschim Nalbari | Submerged due to flood about 2300 m with depth 0.30 to 0.80 m. . Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000), Lat - 0.000000),

Phulguri LP School to Baragopal than. | Phulguri | Road surface damage and Bamboo foot bridge damage due to heavy rain. . Information received from PWRD via WT message on 16/06/2022 | (Long - 0.000000, Lat - 0.000000),

Barkhetri - darangipara to dagapara | dagapara | submerged due to incessant rain, length 500m as reported by AEE, PWRD, Barkhetri Territorial sub Div. on 18/06/2022 | (Long - 0.000000, Lat - 0.000000)

baithabhanga to bardhap | baithabhanga bardhap | submerged due to incessant rain, length 1300m as reported by AEE, PWRD, Barkhetri Territorial sub Div. on 18/06/2022 | (Long - 0.000000, Lat - 0.000000),

soniram mandal road | baithabhanga kandhbari | submerged due to incessant rain, length 150m, RCC Br No 12/1 approach erosion at baithabhanga, and submerged length at kandhbari 900m as reported by AEE, PWRD, Barkhetri Territorial sub Div. on 18/06/2022 | (Long - 0.000000, Lat - 0.000000), ghoga lautola road | ghoga lautola | overtopped 120m and side berm damage 70 m as reported by AEE, PWRD, Barkhetri Territorial sub Div. on 18/06/2022 | (Long - 0.000000, Lat - 0.000000), mugdi ghorathal road | mugdi ghorathal | submerged length 3km, approach of rcc culvert no 1/1 damaged as reported by AEE, PWRD, Barkhetri Territorial sub Div. on 19/06/2022 | (Long - 0.000000, Lat - 0.000000),

hajo mukalmua road submerged | kuriha adabari | submerged by flood water, length 550 m as reported by AEE, PWRD, Barkhetri Territorial sub Div. on 19/06/2022 | (Long - 0.000000, Lat - 0.000000), **Barbhag** - Ranakuchi Village Road (1.2 KM) 0.40Mtr | ranakuchi | as per report Summited by EE PWRD territorial Road Division on 17.06.2022 | (Long - 0.000000, Lat - 0.000000),

Roads under PMGSY package no As -20-191-.As-20-193,as-20-195,As-20-181ane submerged and overtopped 0.60 mtr average depth. | deferent locution | as per report Summited by EE PWRD territorial Road Division on 18.06.2022 | (Long - 0.000000, Lat - 0.000000),

Sonkuriha No.2 to Bhanukuchi Village Road (2.10 Km)0.60 Mtr | sonkuriha | as per report Summited by EE PWRD territorial Road Division on 17.06.2022 | (Long - 0.000000, Lat - 0.000000), Porakuchi to Dingdingi Jypal mandir Road (2KM)0.60 Mtr | Porakuchi | as per report Summited by EE PWRD territorial Road Division on 17.06.2022 | (Long - 0.000000, Lat - 0.000000),

_		1	
			Nalbari Kamarkuchi to Pagladia Embankment infornt of Barbhag Rev. Circle (1KM)0.60 mtr kamarkuchi as per report Summited by EE PWRD territorial Road Division on 17.06.2022 (Long - 0.000000, Lat - 0.000000), Nalbari - Amayapur Chandakuchi road chandakuchi as per report received from PWRD via whatsapp group on 18.06.2022 the amayapur chandakuchi road is damaged due to flood (Long - 0.000000, Lat - 0.000000), deharkaluchi to makaldaba road makaldaba As per the report received from PWRD via whats app group on 19.06.2022 dehar kalakuchi to makaldaba road is submerged due to flood (Long - 0.000000, Lat - 0.000000), Pub Kalakuchi to Makaldaba road pub Kalakuchi As per the report received from PWRD via whats app group on 19.06.2022 Pub kalakuchi to makaldaba road is submerged due to flood (Long - 0.000000, Lat - 0.000000) Chariduar - NH 15 BAMUNGOLA TO MANSIRI CENTRE ROAD (1180.00 M) DTD 19/06/2022 CHARIDUAR (Long - 92.788867, Lat - 26.756859), UROHILOGA TO MANSIRI (1000.00 M) DTD 19/06/2022 CHARIDUAR (Long - 92.620087,
	Sonitpur	5	Lat - 26.897557), BAITHABHANGA BENGALI ROAD (100.00 M) DTD 19/06/2022 CHARIDUAR (Long - 92.798760, Lat - 26.762490), TUBIKIJHAR TO BAMUNGHOLA ROAD(80 M) DTD 19/06/2022 CHARIDUAR (Long - 92.799099, Lat - 26.765376), Tezpur - Bhomora Guri to Bhojkhowa center Bhomoraguri village dated: 19/06/2022. road and
			culvert at bhomoraguri village damaged: length 5 M (approx) (Long - 92.842950, Lat - 26.617750)
	South Salmara	8	South Salmara - Bhangapa Boushkata Road Boushkata As per information received from PWRD and Field enquiry made by LM on 19.06.22 said road has been submerged / damage due to flood water /rainfall at several stretches. (Long - 0.000000, Lat - 0.000000), Khopati to Paikarkandi Road Khopati As per information received from PWRD and Field enquiry made by LM on 19.06.22 said road has been submerged / damage due to flood water /rainfall at several stretches. (Long - 0.000000, Lat - 0.000000), Mankachar - 1.Banshali NEC Road to Puhimari Bazar,2.Majuuri to Niz Chirakhowa,3.Baghapara to Boushkata Road,4.Kalapani to Bengervita Road,5.Hatsingimari to Sukchar Road,6.Dhanu to NEC Road 1.Banshali,2.Manjuri,3.Baghapara,4.Kalapani,5.Sukchar,6.Dhanua As per report Submitted PWRD Mankachar Perriporil Road Sub-Division Mankachar,Road Damage Due to Flash Flood on 18/06/2022.The Details as soon blew:- 1. Banshali NEC Road to Puhimari Bazar Road has submerged from 4th to 5th KM by flash flood water and Breached for a length of 50.00 M AT CH.4600.00M and also damage the ICBP and Road Embankment,2.Monjuri To Niz Chirakhowa Road has Submerged from 2200.00 to 2750.00 N by flash flood water and damage the ICBP side Berm & Road Embankment,3.Baghapara to Boushkata Road has submerged by flash water and damage the ICBP, side berm and road embankment several location.4.Kalapani Bengervita road has submerged by flash water and damaged the road surface embankment several location.5.Road embankment ICBP of Hatsingimari sukchar road has damaged by flash flood water and due to heavy rain fall.6.Bridge Approach on Dhanua to NEC Road has Damaged by flash flood water. (Long - 25.620479, Lat - 89.960717)
	Tamulpur	2	eroision,1500 m. Dated - 18/06/2022 (Long - 91.590000, Lat - 26.600000), Devi nagar to Khairaini PHC road N.K Angarkata,Khairaini 900 m of road washed away with deep eroision on both sides due to sudden heavy current flow of water. Dated - 18/06/2022 (Long - 91.478000, Lat - 26.737000)
	Udalguri	3	Khairabari - 1. Paschim Jhargaon to Gomtha LP School Paschim Jhargaon Road embankment eroded at Paschim Jhargaon on Paschim Jhargaon to Gomtha LP School. Length: 15M (approx.) on 17-06-2022 (Long - 91.854058, Lat - 26.561674), 2. Dudhgarmokha to Selaimari Khoirabari Station Road Oubari Village Road surface eroded at Oubari village on Dudhgarmokha to Selaimari Khoirabari Station Road. Length: 10M (approx.)on 17-06-2022 (Long - 91.481000, Lat - 26.355800), Kalaigaon - Makenji road at Bhehuguri Bhehuguri The road has breached on the bridge RCC bridge approach and communication has bee completely cut off on 19/06/2022 due to heavy current of flood water from river Noa covering a length of around 12 meters and breadth of 12 meters (Long - 91.968291, Lat - 26.609782)
	Total	297 Numbe	
	District	r	Details
Infrastructur e Damaged - Bridge	Barpeta	2	Baghbar - Kandapara to Rupakuchi Connect Bridge Kandapara Date-19-6-2022 washed away. (Long - 0.000000, Lat - 0.000000), Sarthebari - Tihu kalatali RCC Bridge kalatali village Reported by Local Villager on 19/6/2022 (Long - 0.000000, Lat - 0.000000)
	Dhubri	3	Dhubri - HARD CRUST, SIDE BERM & APPROACHED OF BRIDGE NO. 3/1 & 4/1 AND CUL NO. 1/1 PARTAILLY DAMAGED ON JHAGRARPAR KALAHAT ROAD (PMGSY) FROM CH. 400.00 M TO 3400.00 M JHAGRARPAR Dated-16-06-2022 to 19-06-2022 (Long - 0.000000, Lat

		0.000000
	Kokrajhar	- 0.000000), HARD CRUST, SIDE BERM & BRIDGE APROACHES OF BR. NO. 6/1 PARTIALLY DAMAGED ON DHUBRI JHAGRARPAR GAURIPUR (DJG) ROAD FROM 3RD KM TO 7TH KM JHAGRARPAR GAURIPUR Dated-16-06-2022 to 19-06-2022 (Long - 0.000000, Lat - 0.000000), Gauripur - BRIDGE APPROACHES OF SPT BR. NO. 1/1 PARTIALLY DAMAGED ON 5TH KM OF GAURIPUR KALAHAT ROWA ROAD TO BURIRMARI ROAD BURIRMARI Dated-16- 06-2022 to 19-06-2022 (Long - 0.000000, Lat - 0.000000) Dotma - RABHA PARA WOODEN BRIDGE RABHA PARA As REPORTED BY CHAIRMAN FAKIRAGRAM MUNCIPAL BOARD, WOODEN BRIDGE BROKEN AT RABHA PARA VILLAGE WARD NO 4 UNDER FAKIRAGRAM M.B. ON 19.06.2022 (Long - 0.000000, Lat - 0.000000)
	Nagaon	Raha - Bridge No 12/1 over river Kapili Amsoi Dighaliati Date of Occurrence-18/06/2022 Erodedat the approaches. Department- Raha Territorial Road Sub Division (Long - 0.000000, Lat - 0.000000), SPT Foot Bridge over river Kollong Deobali Kakatigaon Date of Occurrence-18/06/2022 Damaged-200 m (Approx) Department- Raha Territorial Road Sub Division (Long - 0.000000, Lat - 0.000000), SPT Foot Bridge over river Haria Dangaribeel Date of Occurrence-18/06/2022 Damaged-300 m (Approx) Department- Raha Territorial Road Sub Division (Long - 0.000000, Lat - 0.000000), Bridge No 2/1 & 3/1 Dharmukh Date of Occurrence-18/06/2022 Eroded- at the approaches. Department- Raha Territorial Road Sub Division (Long - 0.000000, Lat - 0.000000), Bridge No 2/1 Cheuguri Date of Occurrence-18/06/2022 Eroded- at the approaches Department-Raha Territorial Road Sub Division (Long - 0.000000)
	Nalbari	Barkhetri - hajo mukalmua daulasal road br No8/1 adabari Br. approach damaged, length 120m as reported by AEE, PWRD, Barkhetri Territorial sub Div. on 19/06/2022 (Long - 0.000000, Lat - 0.000000) Dhekiajuli - PWD RCC Bridge approach damaged by rising water of Belsiri river at Dherai Mukh.
	Sonitpur	Dated 18.6.22 Dherai Mukh (Long - 92.525200, Lat - 26.633980)
	Udalguri	Kalaigaon - RCC bridge at village Bhehuguri on Makenji road Bhehuguri The bridge approach has completely eroded and washed away on 19/06/2022 due to heavy current of flood water from river Noa covering a length of 12 meters and breadth of 12 meters. (Long - 91.968291, Lat - 26.609782)
	Total	14
	District	Wildlife affected under protected areas description
Infrastructur e Damaged	Golaghat	(Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 14 are inundated) Kaziranga Range (out of 49 camps 6 are inundated) Bokakhat Range (Out of 7 camps 3 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat.
- Wildlife	Morigaon	Mayong - Pobitora WLS Out of a total of 25numbers of camp 15nos of camps are affected and 8nos of camps are inundated as reported by Range Officer PWLS on 19/06/22
	Nagaon	Kaliabor - In Bagori Range out of total 38 nos. of camp 5 nos. of camp and in Burhapahar Range out of total 25 nos. of camp 6 nos. of camp innundated due to flood water Dtd-19.06.2022 as reported by DFO, EAWD
	District	Other Details
	Baksa	Baska - Irrigation Canal/Scheme Damaged Khagrabari Canal eroded at Village Lakshmipur A. Block on 18/06/2022. Co-Ordinate= 26.707607, 91.372947, Baganpara - Bridge Approach Road Damaged On dated 15/06/2022 at Thakursupa to uzirghat bridge approach approx 5m has been eroded due to flash Flood. Longi: 91.4875, latitude: 26.5766
Infrastructur e Damaged - Others	Barpeta	Baghbar - Anganwadi Centres Affected (5 Nos.) Damage Date: 18/06/2022; Reported by CDPO Mandia, Kalgachia - Anganwadi Centres Affected As per report received from CDPO, rupshi on 19/06/2022, total 80 nos of AWC are submerged within the circle area. They are- 1.54 noShawpur (A),2.55no Shawpur (B),3.56 no Shawpur (C) 4.57 no Shawpur (D) 5.58 no Udmari (A) 6.59 no Shariatpur (A) 7.60 no Shariatpur (B) 8.61 no Digjani (A) 9.62 no Digjani(B) 10.63 no Digjani (C) 11.67 no Adipur (A) 12.68 no Aditpur (B) 13.155 no shawpur (E)14. 156 noUdmari (B) 15. 157 no Shariatpur (C) 16.158 no Digjani (D) 17.210 shawpur Char 18. 213 no shariatpur (E) 19. 214 No Digjani (E) 20. 215 no Aditpur (C) 21.256 no shawpur char 22. 257 no shawpur part ii 23 258 no Shariatpur Madhya. 24.259 no Aditpur Dakhsin 25. 260 no Udmari Char 26.263 Digjani Char 27. 47 no Gunialguri (A) 28.48 no Gunialguri (B) 29. 262 no Balarpathe Uttar 30. 53 no Sutir Pather 31.154 No Amguri (C) 32.255 no Amguri Pachim 33. 9 no Bheragann (A) 34. 66 no Balarpather 35.211 nobalar pather36.212 no Balarpather 37.69 no Tapeswara 38. 70 no tapeswara 39.71 no tapeswara40. 160 no Tapeswara 41. 264 no Tapeswara 42.265 no Tapeswara 43. 74 no Nadiapara 44. 218 no Nadiapara 45. 267 noNadiapara 46.72 No Dabandia 47 219 no Dabandia 48.162 no Balagaon 49. 266 no Balagaon Pachim 50. 188 no Jawrimari 51. 293 no Shawrachar Reserve 52.129 no Soilmari 53. 190 no Soilmari 54.297 no Soilmari 55.186 no Shawrachara gaon 56.296 no shawrachara gaon 57.127 no Shawrachara gaon 58. 121no Chikni 59228 no Chikni 60.187no

Anganwadi Centres Affected 16.Date-19-6-2022, Barnagar - Sericulture Deptt. Damaged As per report received from Sericulture Demonstrator 4550 nos o Kesseru plants are affected due to heavy rain Date-19-6-2022 Dangtol - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Mamugaon) as per report received from Power Bongaigaon. Date- 18/06/2022, Power Dept. Poles 5.5 m Pole- 2 Nos. (Location Saonagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 8.5 m Pole- 2 Nos. (Location Tengaigaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) Athugaon- 0.2 K.m., 2)Mamugaon- 0.4 K.m., 3) Nowagaon- 0.2 K.m., 4) Tilpul 0.2 K.m., 5) Tengaigaon. Date- 18/06/2022, Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m., 2) Gurunanak Nagar-0.3 k.m., 3)Betbari-0.2 k.m., 4) Barpa k.m., 5) Shastri Road-0.1 k.m., 6) Jhelkajhar-0.3 k.m., 1) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022. Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022. Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022. Power Dept. Transformers 1 no. (Bocation- BOC Gate) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022. Power Dept. Poles As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-	Dept. churi- com on. ower ra -0.2
Resseru plants are affected due to heavy rain Date-19-6-2022	Dept. churi- com on. ower ra -0.2
Dangtol - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Mamugaon) as per report received from Power Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Saonagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 8.5 m Pole- 2 Nos. (Location Tengaigaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) Athugaon- 0.2 K.m, 2)Mamugaon- 0.4 K.m, 3) Nowagaon- 0.2 K.m, 4) Tilpul 0.2 K.m, 5) Tengaigaon. Date- 18/06/2022, Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaigaon Date- 18/06/2022, Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Delse 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jnelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigaon Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 1	churi- com on. ower ra -0.2
Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Saonagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 8.5 m Pole- 2 Nos. (Location Tengaigaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) Athugaon- 0.2 K.m., 2)Mamugaon- 0.4 K.m., 3) Nowagaon- 0.2 K.m., 4) Tilpublous, 0.2 K.m., 5) Tengaigaon- 0.5 K.m., 6)Saonagaon- 0.3 K.m., 7) Kachuagaon- 0.3 K.m as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaigaon 1 Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m., 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m., 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigaon Date- 18/06/2022. Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept	churi- com on. ower ra -0.2
Bongaigaon. Date- 18/06/2022, Power Dept. Poles 8.5 m Pole- 2 Nos. (Location Tengaigaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) Athugaon- 0.2 K.m., 2)Mamugaon- 0.4 K.m., 3) Nowagaon- 0.2 K.m., 4) Tilpul 0.2 K.m., 5) Tengaigaon- 0.5 K.m., 6)Saonagaon- 0.3 K.m., 7) Kachuagaon- 0.3 K.m as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m., 2) Gurunanak Nagar-0.3 k.m., 3)Betbari-0.2 k.m., 4) Barpa k.m., 5) Shastri Road-0.1 k.m., 6) Jhelkajhar-0.3 k.m., 7)Mechpara-0.3 k.m., 8) Dhola Pukhuri-0.1 k.m., 9) Smashanpara-0.1 k.m., 10)Bhakarivita-0.3 k.m., 11) Mulagaon-0.2 k.m as per report received from Power De Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal	on. ower ra -0.2 ept.
Power Dept. Poles 8.5 m Pole- 2 Nos. (Location Tengaigaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) Athugaon- 0.2 K.m., 2)Mamugaon- 0.4 K.m., 3) Nowagaon- 0.2 K.m., 4) Tilpul 0.2 K.m., 5) Tengaigaon- 0.5 K.m., 6)Saonagaon- 0.3 K.m., 7) Kachuagaon- 0.3 K.m as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m., 2) Gurunanak Nagar-0.3 k.m., 3)Betbari-0.2 k.m., 4) Barpa k.m., 5) Shastri Road-0.1 k.m., 6) Helkajhar-0.3 k.m., 7)Mechpara-0.3 k.m., 8) Dhola Pukhuri-0.1 k.m., 9) Smashanpara-0.1 k.m., 10)Bhakarivita-0.3 k.m., 7)Mechpara-0.3 k.m., 8) Dhola Pukhuri-0.1 k.m., 9) Smashanpara-0.1 k.m., 10)Bhakarivita-0.3 k.m., 11) Mulagaon-0.2 k.m. as per report received from Power Dept. Bongaiga Date- 18/06/2022. Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m., Breadth-8m., Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m., Breadth Depth-2.8 m, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot br	on. ower ra -0.2 ept.
Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) Athugaon- 0.2 K.m, 2)Mamugaon- 0.4 K.m, 3) Nowagaon- 0.2 K.m, 4) Tilpub 0.2 K.m, 5) Tengaigaon- 0.5 K.m, 6)Saonagaon- 0.3 K.m, 7) Kachuagaon- 0.3 K.m as per report received fn Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaigaon Date- 18/06/2022, Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Po Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at slidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Moland road at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222	on. ower ra -0.2 ept.
Power Dept. Conductors 1) Athugaon- 0.2 K.m, 2)Mamugaon- 0.4 K.m, 3) Nowagaon- 0.2 K.m, 4) Tilpub 0.2 K.m, 5) Tengaigaon- 0.5 K.m, 6)Saonagaon- 0.3 K.m, 7) Kachuagaon- 0.3 K.m as per report received fire Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaigaon Date- 18/06/2022, Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigaon Date- 18/06/2022 Cachar Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.67	on. ower ra -0.2 ept.
Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaigaon Date- 18/06/2022, Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 7)Mechpara-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigaon Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-06-2022, Power Dept. Conductors As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	on. ower ra -0.2 ept.
Power Dept. Transformers 1 No. (Location- Athugaon) as per report received from Power Dept. Bongaiga Date- 18/06/2022, Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Cachar Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	ower ra -0.2 ept.
Date- 18/06/2022, Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Popt. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-06-2022, Power Dept. Conductors As reported by PWD bamboo foot bridge washed away at Salbari Molanduroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	ower ra -0.2 ept.
Bongaigaon - Power Dept. Poles 7.5 m Pole- 2 Nos. (Location Bhakarivita) as per report received from Polet. Bongaigaon. Date- 18/06/2022, Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-06-2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molanduroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	ra -0.2 ept.
Power Dept. Poles 7.5 m Pole- 1 No. (Location Mulagaon) as per report received from Power Dept. Bongaigaon. Date- 18/06/2022 , Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	ept.
Bongaigaon. Date- 18/06/2022, Power Dept. Conductors 1) BOC Gate-0.1 k.m, 2) Gurunanak Nagar-0.3 k.m, 3)Betbari-0.2 k.m, 4) Barpa k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-06-2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandur road at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	ept.
k.m, 5) Shastri Road-0.1 k.m, 6) Jhelkajhar-0.3 k.m, 7)Mechpara-0.3 k.m, 8) Dhola Pukhuri-0.1 k.m, 9) Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molanduroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	ept.
Smashanpara-0.1 k.m, 10)Bhakarivita-0.3 k.m, 11) Mulagaon-0.2 k.m as per report received from Power D Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molander road at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	-
Bongaigaon. Date- 18/06/2022, Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaiga Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandur road at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	-
Power Dept. Transformers 1 no. (Location- BOC Gate) as per report received from Power Dept. Bongaigat Date- 18/06/2022 Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	on.
Cachar Udharbond - Power Dept. Poles LT Pole Damaged at Kashipur Borogram due to Soil Erosion under Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18-2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandri road at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	
Udharbond ESD as per report received from APDCL, cachar, as on dated 19.06.2022 Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	
Sidli - Culvert Approach Road Damaged As reported by PWD (R&B) Chirang, NH31 C to Ranchaidham culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	
culvert approach eroded at ch. 3430m on 18-06-2022 at Sidli (Long- 90.439489, Lat-26.508286) Damage Details- Length - 15m, Breadth-8m, Depth-3.5 m, Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	RCC
Washed away Culverts As reported by PWD (R&B) Chirang, Tengnamari Village road HP culvert washed on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molander road at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	
on 18-06-2022 at Tengnamari (Long- 90.411321, Lat-26.484992) Damage Details- Length - 14m, Breadth Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molander road at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	14
Chirang Depth-2.8 m, Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	
Power Dept. Poles As reported by SDE, BESD-II APDCL, 7 nos. of pole washed away at Nepalpara on 18 2022, Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	, 10 111,
Power Dept. Conductors As reported by SDE, BESD-II APDCL, 2.1 km of conductor washed away at Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	-06-
Nepalpara on 18-06-2022, Bengtal - Bamboo Foot Bridge As reported by PWD bamboo foot bridge washed away at Salbari Molandroad at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	
road at Salbari Molandubi on 18-06-2022, Long-90.436989 Lat-26.675222, L-20m B-4m D-3m	
<u> </u>	ıbi
On the second se	area
Darrang affected (approximately) - 173 Hac. as on 19-06-2022 as reported by Fishery Department,	
Patharighat - Power Dept. Poles pole damaged and conductor snapped as reported by SDE on 18.6.2022	
Dhubri - Culvert Approach Road Damaged HARD CRUST, SIDE BERM & CULVERT APPROACH PARTAILLY DAMAGED OF CUL. NO. 1/1 ON DG ROAD AT RLY. LEVEL CROSSING TO TIAMAI	≀I PT₋
II VIA ROYPARA FROM CH. 200.00 M TO 1600.00 M (Dated-16-06-2022 to 19-06-2022),	
Culvert Approach Road Damaged HARD CRUST, SIDE BERM & CULLVERT APPROACH PARTAIL	LY
Dhubri DAMAGED OF CUL. NO. 1/1 ON 4TH KM OF DJG ROAD TO 1384 NO. JHAGRARPAR PT-IV L.P. SCHOOL FROM CH. 400.00 M TO 1650.00 M (Dated-16-05-2022 to 19-06-2022),	
Gauripur - Culvert Approach Road Damaged CULVERT APPROACHES OF CUL. NO. 1/1 DAMAGE)
AND BREACHED (L = 60.00 M) AND SIDE BERM PARTIALLY DAMAGED AT 1ST KM ON 75TH	
OF GAURIPUR KALAHAT ROWA ROAD TO TUNKERDARA ROAD (Dated-16-06-2022 to 19-06-20)	22)
Chabua - Health Sub-Centre DODHIA KULIGAON HEALTH SUB-CENTRE SUBMERGED AS PER INFORMATION RECEIVED FROM HEALTH DEPT. ON 19/6/2022 Coordinates-N27 35.835 E95 13.26	6
Elementary Schools Damaged DODHIA ME SCHOOL SUBMERGED AS PER INFORMATION RECE	
FROM EDUCATION DEPT. ON 18/6/2022 N27 36.390 E95 13.651,	
Elementary Schools Damaged DODHIA KULIGAON LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 19/6/2022 N27 35.845 E95 13.227,	
Elementary Schools Damaged DODHIA KARMI LPS SUBMERGED AS PER INFORMATION RECEI	
Dibrugarh FROM EDUCATION DEPT. ON 19/6/2022 N 27 36.032 E95 14.787,	/ED
Elementary Schools Damaged DODHIA TENGABARI LPS SUBMERGED AS PER INFORMATION	/ED
RECEIVED FROM EDUCATION DEPT. ON 19/6/2022 N27 36.652 E95 14.237, Elementary Schools Damaged DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION	√ED
RECEIVED FROM EDUCATION DEPT ON 18/6/2022 N27 36.462 E95 14.673,	√ED
Anganwadi Centres Affected DODHIA KULIGAON AWC SUBMERGED AS PER INFORMATION	√ED
RECEIVED FROM SOCIAL WELFARE DEPT. ON 18/6/2022 N27 35.845 E 95 13.227, Anganwadi Centres Affected DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION	√ED
RECEIVED FROM SOCIAL WELFARE DEPT ON 19/6/2022 N27 36.652 E95 14.237,	√ED

	Anganwadi Centres Affected DODHIA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 19/6/2022 N27 36.390 E95 13.651, Elementary Schools Damaged MOHMORA HINDI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 18/06/2022. N27 34'5.0514" E95 10'23.7144",
	Elementary Schools Damaged MIRIGAON LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 19/06/2022. N27 30'44.51" E95 12'49.41", Anganwadi Centres Affected UPPER GEREKI AWC SUBMERGED AS PER INFORMATION RECEIVED
	FROM SOCIAL WELFARE DEPT. ON 19/6/2022, Anganwadi Centres Affected DODHIA CHALBIL AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 19/6/2022
Dima-	Haflong - Road Breaches Portion of Dolaichunga - Rekho connecting road washed away due to landslide as per info received from PWRD dated 19/06/2022, Road Breaches Portion of Dittokcherra - Harangajao connecting road washed away due to landslide as per info received from PWRD dated 19/06/2022,
Hasao	Road Breaches Damage of Semkhor - Guilong road at multiple points due to landslide as per info received from loal dated 19/06/2022, Road Breaches Damage of Digrik village approach road due to landslide as per info received from local dated
	19/06/2022 Balijana - Irrigation Canal/Scheme Damaged Brick canal of Saplangkata FIS (Point no. 2) under Goalpara Irrigation Dept. Date of occurrence 18.06.2022. Information received from Goalpara Irrigation Department. GPS:
Goalpara	LAT-26.036264 & LONG- 90.498689, Lakhipur - Washed away SPT Bridge As per report of PWD Roads department, The approach of SPT Bridge No. 2/1 on Lakhipur Tulsibari Road Near Takimari Bazar washed away and communication suspended on 18.06.2022 .Temporary Restoration works in progress. Latitude 26.047121 and Longitude 90.300862
Golaghat	Bokakhat - Agri Bundh Damaged Breach of Check Bund at Dhansiri Temera Gaon (Elengmari) on 18.06.2022
	Hojai - PWSS Damaged Siliguri Basti PWSS Submerged on 18/06/2022, PWSS Damaged Hatimura Dakhin Kenduguri Zone-II PWSS Submerged on 18/06/2022, Power Dept. Conductors Conductor-3 km Pole 20, at Pun Bagari, Baliram pather Hayangaon, Dakhin Bedoati, Warigjendeng, Pun Jugijan, Barafuti, Brajapur, Ahompura, Fakuli, Pachim Jugijan Damaged on 19-06-2022,
Hojai	Doboka - Power Dept. Conductors Conductor = 3 km at village Bheloguri, Bheloguri pathar, Block 48, Borjari gaon, Changjurai, Changmaji Gaon, Changmaji mikirgaon, Changmaji pathar, Charlock, Jamunamukh, Sarupathar, Bedoati, Baliram On 19/06/2022,
	Power Dept. Poles Pole=150, at villages, Bheloguri, Bheloguri pathar, Block 48, Borjari gaon, Changjurai, Changmaji Gaon, Changmaji mikirgaon, Changmaji pathar, Charlock, Jamunamukh, Sarupathar, Bedoati, Baliram On 19/06/2022,
	PWSS Damaged Oksekpather PWSS (Barge Submarged on 18-06-2022 Rangia - Agri Bundh Damaged Many Agribundhs has been submerged and damaged under Rangia Rev Circle
Vomenn	as per report of BDO, Rangia on 18.6.2022, Fisheries/Pond 250 nos. of Ponds affected amounting to water area 28 Ha as per report of FDO, Rangia & FDO, Bihdia,
Kamrup	Kayan - Power Dept. Poles 6nos. Date: 18/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL, Rangia., Power Dept. Conductors 550 m. Date: 18/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL,
17	Rangia
Kamrup (M)	Dispur - Protection Bundh Damaged Bharalu River Guard Wall Breach appx 20 m and water is still seeping inside at Anil Nagar, At Junali oppsite of FINER office the Bharalu gard wall breach on 19/06/2022
	Bhawraguri - Damaged SPT Bridge AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 SPT BRIDGE NO 1/1, 2/1, 2/2, 2/3, 3/1 & 3/2 ON NARENGURI TO GAMBARIBIL ROAD HAS DAMAGED, Damaged SPT Bridge AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 SPT BRIDGE NO 1/1 AT
	JINJHIRIBIL TO LUCHUTBIL ROAD HAS BEEN DAMAGED, Bamboo Foot Bridge AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 BAMBOO BRIDGE NO 1/1 AT PATAKATA SINSILIBARI ROAD HAS BEEN DAMAGED,
Kokrajhar	Damaged SPT Bridge AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 SPT BRIDGE NO 1/2 & 2/1 AT PATAKATA SINSILIBARI ROAD HAS BEEN DAMAGED,
	Bridge Approach Road Damaged AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 APPROACHES OF RCC BRIDGES NO 2/1 ON THANDA BAZAAR TO NARENGURI ROAD DAMAGED, Irrigation Canal/Scheme Damaged AS REPORTED BY AEE, KOKRAJHAR WEST SUB DIVISION
	(IRRIGATION) RAMFALBIL ON 17-06-2022 CAUSED DUE TO FLOOD DAMAGES TO THE AFFLUX BUND U/S AT PATAKATA FIS, Road Breaches AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT
	HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 NARENGURI TO SOULMARI ROAD SUBMERGED AND BREACHED AT 1ST KM (100 M),

Bridge Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 PERMANENT RESTORATION OF ROAD FROM KOCHUGAON TO NOBINAGAR RCC BRIDGE NO 2/2 APPROACH ERODED, Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 PERMANENT RESTORATION OF BHAWRAGURI KACHUGAON PWD ROAD HP CULVERT 15/1 PARTIALLY DAMAGED,

Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 IMMEDIATE RESTORATION OF NH 31 \otimes TO DEMDEMA RABHA VILLAGE AT CH 700 MTS REQUIRED BOX CITY VERT

Bamboo Foot Bridge | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 IMMEDIATE RESTORATION OF NH 31 \odot TO DEMDEMA RABHA VILLAGE AT CH 1600 MTRS RESTORATION OF TEMPORARY FOOT BRIDGE.

Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 IMMEDIATE RESTORATION OF CHORAIDEKA BORO BOSTI BOX CULVERT BOTH SIDE APPROACH DAMAGED, Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 IMMEDIATE RESTORATION OF CHORAIDEKA VILLAGE TO NISHA BOSTI ADIVASHI VILLAGE ROAD. PERMANENT RESTORATION OF RCC BOX CULVERT,

Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 18-06-2022 IMMEDIATE RESTORATION OF CHORAIDEKA TO JANAGAON ADIVASHI VILLAGE ROAD. PERMANENT RESTORATION OF RCC BOX CULVERT .

Gossaigaon - Damaged SPT Bridge | AS REPORT RECEIVED ON DATE 17.06.2022 FROM AEE, PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN THE SPT BRIDGE NO 1/1 ON JMBUGURI TO JIAGURI ROAD HAS BEEN WASHED OUT ON LENGTH 20.00 M(.),

Damaged SPT Bridge | AS REPORT RECEIVED ON DATE 17.06.2022 FROM AEE, PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN THE SPT BRIDGE NO 1/1 ON GURUFELLA SARAIBIL ROAD HAS BEEN PARTIALLY DAMAGED OF LENGTH 15.00 M (.),

Washed away Culverts | AS REPORT RECEIVED ON DATE 17.06.2022 FROM AEE, PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN APPROACHES OF RCC SLAB CULVERT NO. 1/2 DAMAGED HP CULVERT NO 2/2 HAS BEEN WASHED OUT ON GAKSHA POKHIHAGA ROAD TO POKHIHAGA ROAD M(.),

Road Breaches | AS REPORT RECEIVED ON DATE 17.06.2022 FROM AEE, PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN ROAD FORMATION BREACHED OF LEANGTH- 10.00 M AT KATRIBARI VILLAGE ROAD (.).,

Culvert Approach Road Damaged | AS REPORT RECEIVED ON DATE 17.06.2022 FROM AEE, PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN HP CULVERT NO 1/1 HAS BEEN DAMAGED ON LOTAMARI JALESHWARI LINK ROAD (.),

Damaged SPT Bridge | AS REPORT RECEIVED ON DATE 17.06.2022 FROM AEE, PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN THE SPT BRIDGE NO1/1 IS PARTIALLY DAMAGED ON NH 31 (C) TO BHODEAGURI ROAD (.),

Damaged SPT Bridge | AS REPORT RECEIVED ON DATE 17.06.2022 FROM AEE, PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN THE SPT BRIDGE NO 1/1 IS PARTIALLY DAMAGED ON GARDENPUR TO PANBARI KOIMARI LINK ROAD VIA BELGURI,

Bridge Approach Road Damaged | AS REPORT RECEIVED ON DATE 17.06.2022 FROM AEE, PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON JIAGURI SENGMARI ROAD BRIDGE NO.2/8 BADLY DAMAGED,

Bridge Approach Road Damaged | AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF ROAD DAMAGED BRIDGE NO 2/2 ROAD FROM JOYMAGAON (GOMN),

Culvert Approach Road Damaged | AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF ROAD DAMAGED JOYMAGAON KULL RCC BOX CULVERT 2X2 1 CELL

Lakhimpur

North Lakhimpur - Power Dept. Poles | 8.5 meter 16 nos as reported by APDCL NL Division on 19-06-2022, Power Dept. Poles | 7.5 meter 12 nos as reported by APDCL NL Division on 19-06-2022,

Power Dept. Conductors | 27.8 KM Approx as reported by APDCL NL Division on 19-06-2022,

Dhakuakhana - Bamboo Foot Bridge | The bamboo foot bridge no. 2/1 on Tulshijan to No. 2 Tulshijan road (Ch. 1560M)damaged on 18/06/2022.| Bridge Length= 75.00M, Damaged Length= 75.00m. Report submitted by PWD Roads..

Bihpuria - Protection Bundh Damaged | Approximately 100 meters of the bundh has breached at Deori Gokhani Than Kathoni Gaon (Padmapur), Uttar Laluk GP under Karunabari Dev. Block on 19/06/2022,

Fisheries/Pond | 105 nos. ponds affected at No.1 Dharmapur (25 Hectare), 145 nos. ponds affected at Islampur (29 hectare), 115 nos. ponds at Kutubpur (23Hectare), 98 nos. ponds affected at Ahmedpur (18 Hectare), 103 nos.

•	
	ponds affected at Dharmapur Block(26 hectare) on 19/06/2022 as reported by fishery development officer
	Karunabari.,
	Power Dept. Poles 7 nos. of 7.5 mts. PSC pole, 6 nos. 8.5 mts. PSC pole, 1.3 Km conductor damaged at Sonapur
	No.2 and 2 nos. of f 7.5 mts. PSC pole, 0.3 Km conductor damaged at Chichapathar on 18/06/2022 as reported by
	SDE, APDCL, Bihpuria ESD
	Majuli - Irrigation Canal/Scheme Damaged 4 nos. of Irrigation schemes got submerged on 19.06.2022. 1.
	Pabhokhowa Sluice gate at Sumoimari area. 2. STW scheme at Ujani-Namoni Jokaibowa part-1 3. STW scheme
Majuli	at Ujani-Namoni Jokaibowa part-2 4. Solar MDTW scheme at Mohorichuk kordoiguri area,
	Ujani Majuli - PWSS Damaged The distribution of pipe line and FHTC of Doloni Chamoguri village Solar
	powered Mini PWSS under Bongaon GP affected by flood on 19.06.2022
	Bhuragaon - Anganwadi Centres Affected 44 no NIz Chaharia AWC, 269 Jenpari Laokhuwa Chuburi AWC,
	49 No Durangbandi AWC, 266 No. Kubetary AWC, 267 Buwalguri Tribel Chuburi AWC, 325 No Uttar Pavakati
	AWC,112 No 2 No Dighaliati AWC, 424 No Uttar Dighaliati AWC, 50 No Barukati Chaharia AWC submerged
3.6	on flood water on 18-06-2022,
Morigaon	Mayong - PWSS Damaged Raw water pump house submerged at Baha Ganesh Mandir as reported by PHED,
	Morigaon on 19/06/22. lat- 26.181. long- 92.131,
	Irrigation Canal/Scheme Damaged Thengbhanga Kalimandir LIS one side of the main canal wall has fallen
	down i e around 15.00 mts today at 4am during heavy rainfall as reported by JE, Irrigation department Morigaon
	on 19/06/22. lat:26.210. long:92.053
	Kampur - PWSS Damaged Total 15 nos. PWSS damaged under Kampur Rev. Circle Reported by PHE Department Dtd-18.06.2022,
	Power Dept. Transformers 11 nos. transformers damaged under kampur Rev. Circle reported by APDCL
	Kathiatoli Sub division Dtd-18.06.2022,
	Power Dept. Poles 30 nos. poles uprooted under kampur Rev. Circle reported by APDCL Kathiatoli Sub
	division Dtd-18.06.2022,
	Power Dept. Conductors 2.00 KM conductor damaged under kampur Rev. Circle reported by APDCL Kathiatoli
	Sub division Dtd-18.06.2022,
	Raha - Secondary Schools Damaged Pub Darangigaon Anchalik HS has been submerged on 19/06/2022,
	Secondary Schools Damaged Bahakabari HS has been submerged on 19/06/2022,
	Elementary Schools Damaged Chaparmukh Town ME School has been submerged on 19/06/2022,
	PWSS Damaged Charaijuria PWSS was submerged on 18/06/2022 submitted by PHE Department,
	PWSS Damaged Amtola PWSS was submerged on 18/06/2022 submitted by PHE Department,
3.7	PWSS Damaged Chengajan PWSS was submerged on 18/06/2022 submitted by PHE Department,
Nagaon	Power Dept. Poles Kathiatali Electrical Sub Division-10 nos of poles damaged and 10 nos. of poles are
	submerged on 19/06/2022 ,
	Power Dept. Conductors Kathiatali Electrical Sub Division- LT conductor =3.00k damaged and LT
	conductor=3.00k replaced on 19/06/2022,
	Power Dept. Transformers Kathiatali Electrical Sub Division- 1 no. of DTR are damaged and replaced
	19/06/2022,
	Kaliabor - Public Health Centre (PHC) 2Nos. of PWSS affected (Water sources affected) reported by Executive
	Engineer (PHE) Kaliabor Division (Date: 18/06/2022),
	Nagaon - Power Dept. Poles L.T Pole-10 Nos, damaged reported by kathiatoli Electrical Sub-Division, Dated-
	19/06/2022,
	Power Dept. Conductors Conductor-3km damaged reported by kathiatoli Electrical Sub-Division, Dated-
	19/06/2022,
	Power Dept. Transformers DTR-02 and submerged reported by kathiatoli Electrical Sub-Division, Dated-
	19/06/2022 Character Colored Assessed Band Demond LAST was W.T. was Basical from DWDD on 19/06/2022 7 ass
	Ghograpar - Culvert Approach Road Damaged As per W.T msg Received from PWRD, on 18/06/2022 7 nos
	of Culvert has been damaged, Tiby Fisheries (Pond 222 27 heater submerged fishery Land under Tiby P.C. As per report Fishery official as
	Tihu - Fisheries/Pond 232.37 hector submerged fishery Land under Tihu RC . As per report Fishery official as
Nalbari	on 18/062022, Paschim Nalbari - Handloom & Textile Deptt 35 nos. weavers family affected. Damage of loom accessories,
	woven cloths etc. Information received from handloom and textile dept. on 19/06/2022,
	Fisheries/Pond 921 nos. of farmer families fisheries with 184.6 H.A area submerged and affected due to flood
	and heavy rainfall. Information received from Fishery Deptt. on 19/06/2022
	Demow - Anganwadi Centres Affected Sesamukh Napamua Anganwadi centre is submerged on 19-06-2022,
Sivasagar	Sivsagar - Health Sub-Centre Rupahimukh Health Sub Centre is submerged on 18-06-2022,
Sivasagai	Anganwadi Centres Affected Dighal Dariali AWC is submerged on 18-06-2022
	Dhekiajuli - Road Breaches Keherukhanda village road near Binapani LP School damaged due to rising water
	of Gorjuli rivulet. date 18.6.22,
	Road Breaches Village road at Kataludub partially damaged by rising agricultural water. dated 18.6.22,
	Road Breaches Village road at Kataludub partially damaged by rising agricultural water. dated 18.6.22, Road Breaches Village road at Katalupathar partially eroded by Gorjuli rivulet. date 18.6.22,
Sonitpur	Road Breaches Village road at Katalupathar partially eroded by Gorjun rivulet, date 18.6.22, Road Breaches Keherukhand to Singri PWD rural road via Rangagora partially damaged due to rising water of
	an agricultural stream at Keherukhanda gaon. dated 19.6.22,
	chariduar - Health Sub-Centre BALIPARA PHC SUBMERGED IN WATER DUE TO FLOOD DTD
	19/06/2022 26.828512 92.780113
Tamulaur	Goreswar - Culvert Approach Road Damaged Village Pukhuripar Culvert damaged on dated 18/06/2022
Tamulpur	Goreswar - Curvert Approach Koau Damaged Village Pukhuripar Curvert damaged on dated 18/06/2022

		Khairabari - Road Breaches Breach of Length- 6M (approx.) occurred near Ram Narayan Mandir on Gurihati
	Udalguri	Nichilamari Road on 17.05.2022. GPS Coordinates- Lat: 26.611336 Long: 91.786699,
	Odalguii	Fisheries/Pond As per reported by the department approximately 45 farmers were affected in some villages
	District	namely: Harcharapara & Bar-Tangla and approximately 7.5 Ha. of land is affected on 17-06-2022
	District	Details Barama - 1. Alagjar 2. Alagjar 3. Saukuchi 4. Niz Juluki 1. Erosion on L/B of Mora Pagladia river at village
	Baksa	Alagjar near charanpara Shiva Mandir at a length of 100 m approx. Date of occurrence: 18/06/22. Lon: 91.357248 Lat: 26.531607 . 2. Erosion on L/B of Mora Pagladia river at village Alagjar Madhya Alagjar supa at a length of 100 m approx. Date of occurrence: 18/06/22. Lon: 91.362613 Lat: 26.540695 . 3. Erosion on R/B of Mora Pagladia river at village Saukuchi Muslim supa at a length of 500 m approx. Date of occurrence: 18/06/22. Lon: 91.389909 Lat: 26.585368 4. Erosion on L/B of Mora Pagladia river at village Niz Juluki near Circle Office, Barama at a length of 100 m approx. Date of occurrence: 19/06/22. Lon: 91.351969 Lat: 26.521221 0
	Barpeta	Kalgachia - 1. at vill-Paschim Moinbari, 2. at vill- Khudrakhuwa, 3. at vill- Isabpur 1. As per report of concerned LM on 19/06/22, at vill Paschim Moinbari 4 Nos of Kutcha houses are fully eroded by river Beki, land eroded- 2B-0K-00L, population affected- 24 nos. coordinates- 26.251545, 90.755063. 2. As per report of concerned LM on 19/06/22, at vill Khudrakhuwa 6 Nos of PMGY pucca (Half wall- Char piter) houses are fully eroded by river Manas, land eroded- 3B-2K-10L, population affected- 37 nos. coordinates- 26.30052, 90.81155. 3. As per report of concerned LM on 19/06/22, at vill Isabpur 8 Nos of PMGY pucca (Half wall- Char piter) houses are fully eroded by river Manas & Aei, land eroded- 4B-0K-00L, population affected- 43 nos. coordinates- 26.29619, 90.7937. 104
	Bongaigao n	Manikpur - Chouraguri Agril Bundh, 2 no. Bahbari (26 .414420/90.752342), Erosion to place In Bashbari part 2 approach road 100 mtr. & Agril bundh 50 mtr. 5 nos of houses washed away and erosion continues. date-19.06.2022 time 3.45 pm Erosion took place due to river Aie 35 ft. date-19.06.2022/ Erosion due to Aie river 70 Mtr date: 17/06/2022 2200, Srijangram - Jopea Boroichala,(90.768393 26.338034)Kalikura Part I(90.77313 26.350185) and Dubachuri part I(90.711696 26.277567) Due to erosion at Jopea Boroichala 17 nos.nof families got eroded on 18.06.2022. Erosion happens at Jopea Boroichala in length of 1 km approximately. Kalikura: Erosion has occurred in al length of 550 m approx on river bank of Manas as a result 3 nos. of families got eroded due to the said incidence. Dubachuri Part I: Erosion has been going on since last three days in a length of 500 m approx . A PWD road got eroded as a result of which 30 nos. of families got eroded fully. 345
	Chirang	Bengtal - Runikhata Smashan Ghat, Bengtol Kumgujri 1. Erosion at Runikhata Smashan Ghat on both R/B and L/B of River Bhur on 19-06-2022, L-500m B-4m D-2m, (Long-90.381018 Lat-26.649291) 2. Erosion at Bengtol Kumguri on R/B of River Aie on 19-06-2022, L-280m B-8m D-3m, (Lat-26.650693 Long-90.470142) 0
Erosion	Dhubri	Agamoni - Vill: Lohajani under Boterhat GP Riverine area of River Gangadhar at vill Lohajani under Boterhat GP is getting eroded. Village: Lohajani River: Gangadhar GP: Boterhat Incident date: 17/06/2022 to 19/06/2022 Time: 1.00 pm Land: 0 bigha 2 khata 10 Lessa Household affected: 5 Population affected: 29 The affected families has shifted their houses by themselves. GPS Coordinate: Lat. 26.254122. Long. 89.834342 29
	Kamrup	Rangia - Hairandab Erosion had taken place in embankment on the Noona river at hairandab as per report of BDO, Rangia on 18.6.22 0
	Kokrajhar	Bhawraguri - THAKTHAKIPARA, GHONAPARA, MUKULDANG NO I (HORINPUR), DURABIL, KOIMARI AS REPORTED BY IN CHARGE CONTROL ROOM GOSSAIGAON WATER RESOURCE SUB-DIVISION, GOSSAIGAON ON DATED 19/06/2022 1. SEVERE BANK EROSION OBSERVED AT VILLAGE THAKTHAKIPARA OF RIVER GONGIA ON R/B LENGTH 300M. 2. SEVERE BANK EROSION OBSERVED AT VILLAGE GHONAPARA OF RIVER GURUPHELLA ON L/B LENGTH 300M. 3. SEVERE BANK EROSION OBSERVED AT VILLAGE HORINPUR OF RIVER GONGIA ON R/B LENGTH 300M. 4. SEVERE BANK EROSION OBSERVED AT VILLAGE DURABIL OF RIVER GONGIA ON R/B LENGTH 200M. 5. SEVERE BANK EROSION OBSERVED AT VILLAGE DURABIL OF RIVER GONGIA ON R/B LENGTH 200M. 5. SEVERE BANK EROSION OBSERVED AT VILLAGE MARAIN SANTAL BASTI D/S AT NABARD SCHEME OF RIVER GURUPHELLA ON L/B LENGTH 400M. 0, Gossaigaon - VILL: NO.1 KURSHAKATI, NO.2 KANUHPARA, MORNOI TEA GARDEN, RAJADABRI, SINGIMARI, GARDENPUR, NO.2 KURSHAKATI AS REPORTED BY WATER RESOURCE GOSSAIGAON DIVISION ON 18.06.2022 1. SEVERE BANK EROSION OBSERVED AT VILLAGE NO.1 KURSHAKATI (PUMPARA) OF RIVER GURUFELLA ON R/B LENGTH 200M (.) 2. SEVERE BANK EROSION OBSEVED AT VILLAGE NO.2 KANUHARA OF RIVER GURUFELLA ON R/B LENGTH 250M (.) 3. SEVERE BANK EROSION OBSERVED AT VILLAGE NO.2 KANUHARA OF RIVER GURUFELLA ON R/B LENGTH 250M (.) 3. SEVERE BANK EROSION OBSERVED AT VILLAGE NO.2 KANUHARA OF RIVER GURUFELLA ON R/B CONTROL ON R/B LENGTH 250M (.) 5. SEVERE BANK EROSION OBSERVED AT VILLAGE SINGIMARI U/S OF NABARD SCHEME AND D/S OF NABARD SCHEME OF RIVER GURUFELLA ON R/B LENGTH 400M (.) 5. SEVERE BANK EROSION OBSERVED AT VILLAGE SINGIMARI U/S OF NABARD SCHEME AND D/S OF NABARD SCHEME OF RIVER GURUFELLA ON R/B LENGTH 400M (.) 7. SEVERE BANK EROSION OBSERVED AT VILLAGE NO.2 KURSHAKATI (NAOKHOLA) OF RIVER GURUFELLA ON R/B LENGTH 400M (.) 10, (Kokrajhar) At District - ISLAMPUR INDIRA COLONY MAORIAGAON MADHYA KALUGAON 1. AS PER REPORTED BY EXE. ENG. KOKRAJHAR WR DIVISION, BANK EROSION OBSERVED AT VILLAGE INDIRA COLONY REACH LENGTH 250.00M ON L/B OF RIVER GAURANG ON 16-06-2022 3. AS REPORTED BY EXE. E

	1	MAODICAON DUEDDUEDI ON D/D AND DETANI NO 3 CIMI ACUDI CIMI ACUDI DOCACUDION
		MAORIGAON, DHEPDHEPI ON R/B AND BETANI, NO. 2 SIMLAGURI, SIMLAGURI, BOGAGURI ON L/B OF RIVER LONGA ON 16-06-2022 4. AS REPORTED BY EXE. ENG. KOKRAJHAR WR DIVISION, BANK EROSION OBSERVED AT VILLAGE MADHYA KALUGAON REACH LENGTH 250.00M ON R/B OF RIVER SAMUKHA ON 16-06-2022 0
	Lakhimpur	Bihpuria - Dikrong River Bank at Teteliguri As reported by AE of WRD, Bihpuria SD-active erosion reach
	1	observed at Dikrong R/B at Teteliguri(CH.9000m)on 19-06-2022 0 Majuli - Naromari under Ahataguri mouza Erosion occurred at Naromari village under Ahataguri mouza on
	Majuli	18.06.2022. Two families have been shifted from Naromari to the nearest Chapories till now. One family has been shifted to Guria gaon on 18.06.2022 and another one has been shifted to Dolkhuwa gaon on 19.06.2022. 6
	Morigaon	Laharighat - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori As per report received from the Water Resources dept on 19-06-2022, erosion is observed in areas like Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori area with maximum erosion of 2 m in Leruamukh, 2 m in Goroimari , 4 m in Bhajaikhati gaon & 3 m in Barchapori . 0
	Nalbari	Ghograpar - 1. Bhithamal, 2. Sathamou, 3. Sonkuriha, 4. Borajol 1. As per information received from WRD, 0n 18/06/2022, erosion has seen at village Bhithamahal on the R/B of river Noona. Length - 150 M 2. As per information received from WRD, 0n 18/06/2022, erosion has been seen at village Sathamou on the R/B of river Noona. Length - 400 M 3. As per information received from WRD, 0n 18/06/2022, Sloughening occured at
		village Sonkuriha on the R/B of river Noona. Length - 150 M 4. As per information received from WRD, 0n 18/06/2022, Sloughening occured at village Borajol on the R/B of river Noona. Length - 150 M 0 Chariduar - CHARIDUAR BANK EROSION AT BHOBOLA GAON BONGALI DTD 16/06/2022 0,
	Sonitpur	Naduar - Kanyaka farm Heavy erosion observed yesterday dated 19/06/2022 at river Jia bharali L/B near kanyaka. Length 200m breadth 7m 0
	Tamulpur	Tamulpur - village Barialapar,village dowamakha Eroision on l/b of river baralia,225 metres,lat 26.64 long 91.65 Eroision on l/b of river Baralia ,250 metres,Lat 28.66 long-91.66 0
	Tinsukia	Sadiya - 8th mile, koilabasti, lakhimpuria 1. Erosion at 8th mile by Kundil river under the bridge since 16/06/2022 to 19/06/2022 as per report received from the concerned Gaon Pradhan. Stretch area is 04 m. Location (27°52'02"N, 95°45'36"E). 2. Active erosion is reported from Koilabasti area by Kundil river since 16/06/2022 to 19/06/2022 by concerned Gaon Pradhan. Stretch area is 05 m. Location (27°50'48.8"N, 95°42'45.2"E). 0
	Udalguri	19.06.2022. 0, Khairabari - 1. Budura (Majgaon) 2. Budura (Dongpara) 3. Mahaliapara 1. Overflowing flood water from Ghai Dong has eroded / broken the earthen embankment near Narayan Boro's Paddy field. Length and Breadth: 30 M and 3 M (approx.). GPS-Coordinates: Lat: 26.662814 Long: 91.791894 Date of occurrence: 17.06.2022. Population affected- 200 (approx). 2. Severe erosion by Harharia river at Buduragaon (Dongpara) near Tarun Boro's paddy field. Length and Breadth: 60M & 4 M approx. GPS-Coordinates: Lat: 26.65746 Long: 91.789601 Date of occurrence: 17.06.2022. Population affected-300 (approx). 3. 30 M already eroded by Khaplang river at Mahaliapara village near Sarbeswar Boro's house. GPS-Coordinates: Lat: 26.644582 Long: 91.819348 Date of occurrence: 17.06.2022. Population affected-250 (approx) 0
	District	Details
	Cachar	Katigorah - Sewti PT-I Total 2 numbers Pukka Houses (1 Partially & 1 fully house damaged) due to landslide on 19.06.2022 10, Silchar - Rengti Basti, Chibita Bichia Pt-I, Borakhai TE Dhurabond, Chotodudhpatil Total 15 Nos. Kutcha House fully damaged due to Landslide on 19.06.2022 65, Lakhipur - Lalpani Total -5 Nos of Houses, 3 Nos of Kutchua Houses Partially, 2 Nos of Pucca House partially damage due to Landslide on 19.06.202 26, Sonai - Rajnagar & Ganga Nagar Pt. XIII 1. House of Tera Mia Barbhuiya, S/o Lt. Kala Raja Barbhuiya damaged due to landslide at Rajnagar Under Sonai Revenue Circle on 19.06.2022 2. Ganga Nagar Pt. XIII Road got blocked due to landslide Under Sonai Revenue Circle on 19.06.2022 4, Udharbond - Nagadung, Kashia Punjee, Chnadighat Total 4 nos of House, 3 Nos Pucca House Partially Damage, 1 Kuctha Partially Damaged Due to Landslide on 19.06.2022 27
Landslide	Dima- Hasao	Haflong - 1.) Landslide at Digrik village, Haflong 2.) Landslide at Guilong village Due to heavy rain, landslide occurred at Digrik village and Guilong village as per report received from local dated 19/06/2022 0
	Goalpara	Balijana - Bhalikdubi Part II (Barpahar) Landslide occurred in Barpahar Priyanagar LP School Road 12
	Hailakandi	Hailakandi - Ratanpur Pt-1 under Hailakandi Revenue Circle DTD. 18.06.2022 Due to incessant rain 11 nos. of houses are partially damaged. No casualities. 60, Katlicherra - village Alexanderpur grant, Katlicherra dated 19.06.2022 A landslide has been occured at alexanderpur Grant where a kutcha house was partially damaged under Katlicherra Revenue Circle dated 19.06.2022. 2, Lala - Village Lalacherra Due to incessant rain minior landside under lala Revenue circle. Hailakandi on dtd.19.06.2022 2000
	Kamrup (M)	Guwahati - Chitrachal Nabagraha , Kamakhya Nursery Landslide occured on 19/06/2022 5
	Karimganj	Patherkandi - Baitakhal Basti 1 nos of pucca house damaged partially - Dated 19/06/2022 11
Urban	District	Details Permagner Permagner Permagner Permagner 5900 per of population effected due to beauty minfall. Data 10.6.2022 5800
Flood	Barpeta	Barnagar - Barpeta Road Approx 5800 nos of population affected due to heavy rainfall. Date-19-6-2022 5800

	Silchar - Linkroad, National Highway road point, Ambicapatty, Church Road, Chandicharan Road due to
Cachar	
	Town on 19.06.2022 7501
Darran	Mangaldoi - Ward No 1,2,3,4,5,6,7,8,9,10 Due to Heavy Rainfall and water level raising of River Bega and
Darran	others all wards are under water as on 19-06-2022. 25000
	Lakhipur - Lakhipur Town Ward No. 1,2,3,4,5,6,8,9&10 Due to Urban flood in Lakhipur Town Ward No.
Goalpa	ra 1,2,3,4,5,6,8,9&10 got affected. The Date of occurrence of Urban Floodon 16.06.2022 to till Date i.e 19.06.2022.
	Field Officer visited the affected sites. 7512
Kamru	Guwahati - Tetelia Water logging on 19/06/2022 0,
	Dispur - Hatigaon, Sarumotoria, Noonmati Garden, Satgaon, Rukminigaon, Keraikuchi, Sawkuchi, Hengrabari,
(M)	Baghorbari, Jatia waterlogging on 19/06/2022 0
Karimg	anj RK Nagar - word no 6, word no 7 word no 4 word no 10 total 130 house submurged. Dated - 19/06/2022 700
Nalbar	Nalbari - hajo road, collage road, forest office road, affected due to rain water as per report received from LM as
Ivalual	on 19.06.2022 750
Udalgu	Udalguri - Udalguri Town Continuing of over-topping of Goloni river water to nearby houses in Udalguri
Udaigt	Town area from 16-06-2022. 522