

FRIMS Assam



Flood Reporting And Information Management System

Doeti au 1	Cituati	on 24 06 2	Assam Daily Flood 2022 (in last 24 hours)	l Report as on 24-06-2022 at 4:00 P	M						
Particulars	Situation as	on 24-06-2	LUZZ (III IAST Z4 hours)								
Rivers											
flowing	Rivers flow	ing above d	langer level	Kopili (Dharamtul; Kampur), Bral	hmaputra (Dhubri)						
above		8	6	· · · · · · · · · · · · · · · · · · ·	7						
Danger Level (as											
per CWC bulletin				2711							
issued at 8	Rivers flow	ing above h	ighest flood level	Nil							
AM)											
7111)	No. of										
	Districts	Name of	Flood Affected District	ts	Name of Urban Flood Districts						
	Affected	1 (612120 02	110001111100000 2100110		1 (41110 01 010411 11004 21011046						
District		Bajali, Ba	aksa, Barpeta, Biswanath	n, Bongaigaon, Cachar, Chirang,							
Affected				-Hasao, Goalpara, Golaghat,							
	28			rup (M), Karbi Anglong West,	Cachar, Karimganj, Morigaon						
				Morigaon, Nagaon, Nalbari,	, 5 3, 6						
			South Salmara, Tamulp								
No. Of		•	_								
Revenue	93										
Circles	93										
Affected											
	District	Total	Revenue Circle								
	Bajali	2	Sarupeta, Bajali								
	Baksa	3		Baganpara, Barnagar RC part, Jalah							
	Barpeta	6	Barpeta, Baghbar, Barnagar, Kalgachia, Chenga, Sarthebari								
	Biswanath	1	Halem								
	Bongaigao	2	Manikpur, Srijangram	ı							
	n Cachar	5	Katigorah Lakhinur	Silchar, Sonai, Udharbond							
	Chirang	1	Bijni								
	Darrang	4	Sipajhar, Patharighat, Mangaldoi, Dalgaon								
	Dhemaji	4	Jonai, Sissiborgaon, Gogamukh, Dhemaji								
	Dhubri	4	Bilasipara, Dhubri, Ga	Bilasipara, Dhubri, Gauripur, South Salmara Part							
	Dima-	1	Haflong	•							
	Hasao			Haflong							
	Goalpara	3	Matia, Lakhipur, Balijana								
	Golaghat	2	Khumtai, Bokakhat								
Name Of	Hailakand i	4	Katlicherra, Lala, Alg	apur, Hailakandi							
Revenue	Hojai	3	Hojai, Doboka, Lanka	<u> </u>							
Circles Affected	Kamrup	10	J ,	Palashbari, Chamaria, Chaygaon, Kamalpur, North Ghy, Nagarbera, Goroimari							
	Kamrup	2	Sonapur, Chandrapur								
	(M)										
	Karbi Anglong	1	Donkamokam								
	West	1	Donkamokam								
	Karimganj	5	RK Nagar, Karimgani	, Badarpur, Nilambazar, Patherkand	li						
	Lakhimpu	4									
	r			impur, Nowboicha, Subansiri							
	Majuli	2	Ujani Majuli, Majuli	20111							
	Morigaon	4	Bhuragaon, Morigaon								
	Nagaon	6		on, Rupahi, Raha, Samaguri							
	Nalbari	5		phag, Tihu, Barkhetri, Nalbari							
	Sonitpur	3	Thelamara, Dhekiajuli	ı, 1ezpur							
	South Salmara	2	Mankachar, South Sal	mara							
	Tamulpur	1	Tamulpur								
	Udalguri	3	Khairabari, Mazbat, U	Jdalguri							
	C Guiguii										

	Total	93						
	District	Total	Revenue					
	Bajali	16		a 7), (Baja				
	Baksa	28	(Baganp	ara 11), (E	Barnagar RC p	oart 16), (Jalah 1)		
	Barpeta	606	(Barpeta 135)	145), (Ba	ghbar 139),	(Barnagar 18), (Kalgachia	a 100), (Che	enga 69), (Sarthebari
	Biswanath	4	(Halem	4)				
	Bongaigao n	1	(Srijangı	ram 1)				
	Cachar	525	(Katigor	ah 153), (]	Lakhipur 90), (Silchar 150), (Sonai 9	1), (Udharbo	ond 41)
	Chirang	3	(Bijni 3		. <u>r</u>	,,, (,, (· · · /
	Darrang	176	(Sipajha	r 74), (Pat	harighat 25)	, (Mangaldoi 69), (Dalgao	on 8)	
	Dhemaji	62	(Jonai 2	22), (Sissibo	orgaon 16),	(Gogamukh 15), (Dhemaj	i 9)	
	Dhubri	157	(Bilasipa	ara 33), (D	hubri 23), (South Salmara Part 97), (A	Agamoni 4)	
	Dima-	3	(Haflong	r 3)				
	Hasao							
	Goalpara	155		77.		alijana 63), (Rongjuli 8)		
	Golaghat	23	(Khumta	ii 4), (Bok	akhat 19)			
	Hailakand i	49	(Lala 1), (Algapur	17), (Haila	kandi 31)		
Villages	Hojai	45			a 20), (Lank			
Affected	Kamrup	362				ın 28), (Palashbari 5), (C), (Nagarbera 20), (Goroir), (Chaygaon 3), (
	Kamrup (M)	35	•		andrapur 17			
	Karbi							
	Anglong West	2	(Donkan	nokam 2)				
	Karimganj	452	(RK Nac	par 150) (Karimgani 4	0), (Badarpur 62), (Nilam	hazar 187)	(Patherkandi 13)
	Lakhimpu		•		0 0.			(Tudiorkanar 13)
	r	19	(Bihpuri	a 6), (Nort	th Lakhimpur	2), (Nowboicha 9), (Sub	oansiri 2)	
	Majuli	6	(Ujani M	Iajuli 4), (Majuli 2)			
	Morigaon	283	(Bhuraga	aon 27), (N	Morigaon 11	3), (Mikirbheta 12), (May	ong 131)	
	Nagaon	332	(Kampui	r 109), (Dl	ning 13), (N	Nagaon 85), (Rupahi 2), (Raha 117),	(Samaguri 6)
	Nalbari	76				7), (Tihu 8), (Barkhetri	21), (Nalba	ri 28)
	Sonitpur	22	(Thelam	ara 2), (Dl	nekiajuli 17)), (Tezpur 3)		
	South	63	(Mankac	har 26). (S	South Salmara	a 37)		
	Salmara							
	Tamulpur	1	(Tamulp		.10)			
	Udalguri	4	(Mazbat	1), (Udalg	guri [3]			
	Total	3510			Total		Cwan	
	District	Male	Female	Children	Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details
	Bajali	22389	21932	5081	49402	(Sarupeta 20040), (Bajali 29362)	155.00	(Sarupeta 155.00), (Bajali 0.00)
						(Baska 0), (Barnagar		(Baska 0.00), (
	Baksa	12030	8152	5734	25916	RC part 16874), (410.00	Barnagar RC part
	Daksa	12030	0132	3734	23910	Baganpara 9042), (410.00	410.00), (Baganpara
						Jalah 0)		0.00), (Jalah 0.00)
						(Barpeta 95034), ((Barpeta 657.00), (
Population						Baghbar 261212), (Baghbar 18983.00), (
And Crop	Barpeta	353838	334675	188329	876842	Barnagar 13792), (Kalgachia 111563), (27017.00	Barnagar 780.50), (Kalgachia 1823.50),
Area Affected						Chenga 144601), ((Chenga 2693.00),
Affected						Sarthebari 250640)		Sarthebari 2080.00)
	Biswanath	0	0	0	0	(Halem 0)	63.00	(Halem 63.00)
	Bongaigao	<i>c</i> 0	71	16	1.47	(Manikpur 0), ((Manikpur 0.00), (
	n	60	71	16	147	Srijangram 147)	0.00	Srijangram 0.00)
						(Katigorah 96130), ((Katigorah 0.00), (
						Lakhipur 15455), (Lakhipur 77.70), (
	Cachar	107175	96064	73106	276345	Silchar 91050), (Sonai	77.70	Silchar 0.00), (Sonai
						68270), (Udharbond		0.00), (Udharbond
	Chinan -	182	234	127	543	5440) (Bijni 543)	0.00	0.00) (Bijni 0.00)
	Chirang	104	234	14/	J4J	(Dijiii 343)	0.00	(D iliii 0.00)

	1		1		T	I	(Ciil- 1215 00)
Darrang	65488	63634	41629	170751	(Sipajhar 59152), (Patharighat 29572), (Mangaldoi 80600), (Dalgaon 1427)	7472.21	(Sipajhar 1615.00), (Patharighat 703.50), (Mangaldoi 3418.00), (Dalgaon 1735.71) (Jonai 4581.50), (
Dhemaji	15644	14623	10101	40368	(30hai 13439), (Sissiborgaon 13488), (Gogamukh 6453), (Dhemaji 4968)	6351.06	Sissiborgaon 1717.56), (Gogamukh 0.00), (Dhemaji 52.00)
Dhubri	68967	59225	56492	184684	(Bilasipara 42941), (Dhubri 12423), (Gauripur 0), (Athani 0), (South Salmara Part 129320), (Agamoni 0)	4480.00	(Bilasipara 0.00), (Dhubri 711.00), (Gauripur 0.00), (Athani 0.00), (South Salmara Part 3769.00), (Agamoni 0.00)
Goalpara	65836	46103	20159	132098	(Matia 4849), (Lakhipur 78109), (Balijana 49140), (Rongjuli 0)	882.20	(Matia 284.00), (Lakhipur 0.00), (Balijana 598.20), (Rongjuli 0.00)
Golaghat	3199	2988	1566	7753	(Bokakhat 7753), (Khumtai 0)	81.00	(Bokakhat 65.00), (Khumtai 16.00)
Hailakand i	10760	8443	7985	27188	(Katlicherra 0), (Lala 110), (Algapur 18518), (Hailakandi 8560)	138.00	(Katlicherra 0.00), (Lala 42.00), (Algapur 59.00), (Hailakandi 37.00)
Hojai	4860	3243	1658	9761	(Hojai 2841), (Doboka 4860), (Lanka 2060)	1071.00	(Hojai 117.00), (Doboka 139.00), (Lanka 815.00)
Kamrup	196921	122523	82068	401512	(Rangia 12269), (Hajo 166700), (Chamaria 0), (Chaygaon 0), (Kamalpur 188602), (Nagarbera 0), (Goroimari 0), (Kayan 10628), (Palashbari 0), (North Ghy 23313)	3885.44	(Rangia 654.24), (Hajo 781.00), (Chamaria 79.20), (Chaygaon 33.00), (Kamalpur 1045.00), (Nagarbera 200.00), (Goroimari 500.00), (Kayan 344.50), (Palashbari 46.00), (North Ghy 202.50)
Kamrup (M)	1166	780	5	1951	(Sonapur 1951), (Chandrapur 0)	899.50	(Sonapur 726.50), (Chandrapur 173.00)
Karbi Anglong West	488	491	536	1515	(Donkamokam 1515)	0.00	(Donkamokam 0.00)
Karimganj	105165	77523	33723	216411	(RK Nagar 51140), (Badarpur 44571), (Nilambazar 62318), (Patherkandi 1627), (Karimganj 56755)	300.00	(RK Nagar 300.00), (Badarpur 0.00), (Nilambazar 0.00), (Patherkandi 0.00), (Karimganj 0.00)
Lakhimpu r	8230	5808	4343	18381	(North Lakhimpur 3922), (Nowboicha 14125), (Bihpuria 0), (Subansiri 334)	20.00	(North Lakhimpur 0.00), (Nowboicha 0.00), (Bihpuria 0.00), (Subansiri 20.00)
Majuli	0	0	0	0	(Ujani Majuli 0), (Majuli 0)	21.74	(Ujani Majuli 13.76), (Majuli 7.98)
Morigaon	38105	34936	21126	94167	(Bhuragaon 10700), (Morigaon 70742), (Mikirbheta 6784), (Mayong 5941)	11457.00	(Bhuragaon 721.00), (Morigaon 1200.00), (Mikirbheta 436.00), (Mayong 9100.00)
Nagaon	180562	169138	158775	508475	(Kampur 259500), (Nagaon 101991), (Raha 146051), (Samaguri 933), (Dhing 0), (Rupahi 0)	19067.14	(Kampur 8320.00), (Nagaon 728.00), (Raha 9834.14), (Samaguri 148.00), (Dhing 32.00), (Rupahi 5.00)

	Nalbari	42062	38177	27178	107417	(Paschim Nal), (Barbhag Tihu 2202), 50184), (Na	13063), ((Barkhetri	5873.50	(Paschim N 554.00), (E 140.00), (T), (Barkhetr), (Nalbari	Sarbhag Sihu 50.00 i 5019.50	
	Sonitpur	4514	7147	4407	16068	(Thelamara Dhekiajuli 1 Tezpur 0)		1006.00	(Thelamara Dhekiajuli Tezpur 6.0	989.00), (0)	
	South Salmara	52267	49448	32790	134505	(Mankachar South Salmara	a 103940)	830.00	(Mankachar), (South Sa 692.00)	lmara	
	Tamulpur	11	10	4	25	(Tamulpur 2	25)	100.00	(Tamulpur		
	Udalguri	560	333	198	1091	(Khairabari Harisinga 0) 1048), (Kal (Mazbat 43), (Udalguri aigaon 0),	0.00	(Khairabari Harisinga 0 Udalguri 0 Kalaigaon Mazbat 0.0	0.00), (.00), (0.00), (
	Total	136047 9	116570 1	777136	3303316		T	91658.49			
	District	Total	Relief Ca		11.1.17			ribution Cent	res		
	Bajali	21		eta 11, Baja				1, Bajali 8)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	Baksa Barpeta	3 224	171(Barp	para 0, Jalal peta 112, Ba ri 3, Kalgac	ighbar 19, Cl	henga 37,		a 2, Jalah 1] 0, Baghbar nia 41)		Sarthebari	
	Bongaigao n	1	1(Srijang				0(Srijangra				
	Cachar	224	Sonai 4	4, Udharbon	akhipur 22, 3 d 1)	Silchar 63,	0(Katigorah 0, Lakhipur 0, Silchar 0, Sonai 0, Udharbond 0)				
	Chirang	3	3(Bijni :				0(Bijni 0) 71(Sipajhar 43, Mangaldoi 20, Patharighat 1,				
	Darrang	74	Dalgaon	0)	ldoi 2, Patha		Dalgaon 7)			
	Dhemaji	11			aon 0, Dhema	aji 0)		, Sissiborgaon		4)	
	Dhubri	30	9(Bilasip	ara 7, Dhub	ori 2)		21(Bilasipa	ra 21, Dhubr	i 0)		
	Dima- Hasao	34	28(Haflo		17 D.1::	- 14)	6(Haflong		D-1:: ()		
Relief	Goalpara Hailakand	17		andi 3, Alga	r 17, Balijana 14) pur 0)		0(Matia 0, Lakhipur 0, Balijana 0) 14(Hailakandi 8, Algapur 6)				
Camps /	Hojai	37	20(Hojai	12, Dobok	2 8)		17(Hojaj 1	2, Doboka 5)		
Centres Opened	Kamrup	90	51(Rangi		n 10, Kamal _l	our 15, North	39(Rangia 1, Kayan 0, Kamalpur 15, North Ghy 0, Hajo 21, Chamaria 2)				
	Karbi Anglong West	3		mokam 0)			3(Donkamokam 3)				
	Karimganj	114		nganj 26, B kandi 5, RK	adarpur 23, 1 K Nagar 0)	Nilambazar	55(Karimganj 0, Badarpur 23, Nilambazar 7, Patherkandi 0, RK Nagar 25)				
	Lakhimpu r	8	(0)	• •), Nowboicha	8(Bihpuria 2)	5, North Lak	himpur 1, No	wboicha	
	Morigaon	29		1(Morigaon 1, Mayong 0)				on 26, Mayon			
	Nagaon	104		65(Kampur 17, Nagaon 36, Raha 12)				39(Kampur 0, Nagaon 0, Raha 39)			
	Nalbari	23	Nalbari	20(Paschim Nalbari 10, Barbhag 6, Tihu 1, Nalbari 3, Barkhetri 0) 3(Paschir Nalbari					rbhag 0, Tihi	1 0,	
	Sonitpur	2	1(Dhekia	juli 1, Tezp	our 0)		1(Dhekiajul	li 0, Tezpur	1)		
	South Salmara	33	9(Manka	9(Mankachar 9, South Salmara 0)				har 16, South	Salmara 8)		
	Tamulpur	2	1(Tamul	our 1)			1(Tamulpui	r 1)			
	Udalguri	5		ıri 2, Khaira	abari 0)			2, Khairabar	i 1)		
	Total	1126	717				409				
Inmates In Relief	District	Total	Revenue	Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y	
Camps	Bajali	1840	(Sarupeta	a 1808), (Ba	ajali 32)	751	792	245	51	1	
	Barpeta	95631	(Barpeta	80745), (Barnagar 0	aghbar	32084	33696	29502	339	10	

			(Kalgach (Sartheba	ia 0), (Chen ari 288)	nga 3554),					
	Bongaigao n	147	(Manikpu 147)	ur 0), (Srijar	ngram	60	71	16	0	0
	Cachar	107322	(Katigora 3415), (S	ah 44183), (Silchar 2254 (Udharbond	5), (Sonai	41525	38251	27544	0	2
	Chirang	543	(Bijni 5			182	231	127	3	0
	Darrang	1386	(Dalgaon	: 672), (Path 1 0), (Manga	aldoi 714)	420	599	362	3	2
	Dhubri	2779	0), (Atha	ra 1377), (C ni 0), (Soutl (Agamoni C	h Salmara	911	1196	672	0	0
	Dima- Hasao	1922	(Haflong			691	737	437	54	3
	Goalpara	8707	(Balijana	1443), (Lakhi ı 3473), (Ro	ngjuli 0)	3934	3068	1651	46	8
	Hailakand i	810	(Algapur	erra 0), (Lala · 0), (Hailaka	andi 810)	299	243	268	0	0
	Hojai	3392	(Hojai 1 (Doboka	1728), (Lanka 1664)	a 0),	1860	1208	313	10	1
	Kamrup	3118	(Palashba (Chaygao (Nagarbe	537), (Hajo ari 0), (Char on 0), (Kamera 0), (Goro 258), (North	maria 0), nalpur 718), pimari 0),	1204	1293	602	19	0
	Karimganj	13885	2485), (N (Patherka 10858)	ar 0), (Bada Nilambazar 3 andi 185), (I	357), Karimganj	5608	5311	2954	12	0
	Morigaon	175		non 0), (Mor ikirbheta 0),		67	73	33	2	0
	Nagaon	17950	(Kampur	0), (Samagu 4980), (Na (Raha 1510)	gaon	7200	6535	4080	129	6
	Nalbari	5274	(Barbhag	n Nalbari 429 g 730), (Tihu ri 0), (Nalba	u 83),	2383	1922	945	22	2
	Sonitpur	170	(Thelama 170), (Te	ara 0), (Dhel ezpur 0)	kiajuli	46	78	40	6	0
	South Salmara	410	(South Sa 410)	almara 0), (I	Mankachar	152	121	117	20	0
	Tamulpur	25	(Tamulpu			11	10	4	0	0
	Udalguri	302		ari 0), (Hari 0), (Kalaiga ri 302)		133	117	52	0	0
	Total	265788				99521	95552	69964	716	35
	District	Total	Male	Female	Children	Revenue Cir				
	Barpeta	2	0	0	2	(Kalgachia 0	0), (Sarthebar	ri 0)	0), (Chenga 2	
	Cachar	1	1	0	0	(Udharbond	0)		0), (Sonai 1)	
Human Lives Lost -	Dhubri	2	0	0	2	(Gauripur 1)), (South Saln	nara Part 0)	1), (Dhubri (
Confirmed	Karimganj	2	2	0	0	0), (RK Naga	ar 0)		oazar 1), (Path	
	Morigaon	1	1	0	0				neta 0), (Mori	
	Udalguri	2	2	0	0	(Harisinga 0 (Udalguri 1)		ı 0), (Khairal	bari 0), (Maz	bat 1),
	Total	10	6	0	4					
Human	District	Total	Flood	General	Landslide					

Confirmed				g (Non						
- Death				Flood)						
Type	Barpeta	2	2	0	0					
	Cachar	1	1	0	0					
	Dhubri	2	2	0	0					
	Karimganj	2	2	0	0					
	Morigaon	1	1	0	0					
	Udalguri	2	2	0	0					
	Total	10	10	0	0					
Human	Total	10	10	U	U					
Lives Lost -	Nil									
Missing										
Human										
Lives Lost										
Missing -	Nil									
Туре										
	District	Total	Big	Small	Poultry					
	Bajali	13215	8880	2957	1378					
	Baksa	10179	6365	3314	500					
	Barpeta	944626	337321	169224	438081					
	Cachar	29404	22990	6414	0					
	Darrang	254152	132468	77621	44063					
	Dhemaji	6057	4041	2016	0					
	Dhubri	185018	106440	78578	0					
	Goalpara	44920	24726	11661	8533					
	Hojai	35406	13509	4516	17381					
	Kamrup	442964	379084	48880	15000					
Animals	Kamrup	5805	4320	1393	92					
Affected	(M) Karimganj	20372	7486	1876	11010					
	Lakhimpu	21421	8256	6635	6530					
	r Morigaon	107145	39047	19391	48707					
	Nagaon	110486	54734	39504	16248					
	Nalbari	145823	77883	62350	5590					
	Sonitpur	36157	24739	11418	0					
	South	196606	96620	£1000	47000					
	Salmara	186606 259975	86629 133891	51989	47988					
	Total	6	8	599737	661101					
Animals	District	Total	Big	Small	Poultry					
Washed	Barpeta	22	0	22	0					
Away	Nalbari	6	5	1	0					
	Total	28	5	23	0				•	•
	District	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
Houses	Baksa	0	0	0	158	0	158	0	0	0
Damaged	Dhemaji	0	0	0	9	0	9	0	0	0
2	Sonitpur	73	0	73	10	3	13	4	1	5
	Udalguri	0	0	0	59	0	59	0	0	0
	Total	73	0	73	236	3	239	4	1	5
	1000	70		70	200			-	Person	
	District	Agency			Boats Deployed	Person Evacuated By Boats	Animal Evacuate d By Boats	Helicopte rs Deployed	Evacuate d By Helicopte rs	Medical Team Deploye d
Rescue	Bajali				0	0	0	0	0	12
Operation			nergency S Circle Offic ration		48	17	0	0	0	10
	Bongaigao n	Local Peo	ple, Engin	e Boat	1	0	0	0	0	10
	Cachar	Circle Of	fice/Local		35	5911	0	1	0	11

		Defence/I Inland Wa Emergence Local Peo Army/Par NDRF, Po	y Services	lunteers, ort, Fire & (F&ES), orce, F, Water						
	Chirang	resources	, Беригине	110	2	0	0	0	0	3
	Darrang	Local Peo	ple		12	0	0	0	0	25
	Dhemaji	SDRF			1	7	0	0	0	1
	Dhubri	Circle Off Administr	ration		47	94	124	0	0	3
	Dima- Hasao		ence/Trainers, SDRF, N		0	0	0	0	0	15
	Goalpara				0	0	0	0	0	12
	Hailakand i				1	0	0	0	0	3
	Hojai	Local Peo	*		11	0	0	0	0	8
	Kamrup	SDRF, N			12	114	50	0	0	45
	Karimganj	Local Peo	ple, SDRF		18	293	0	0	0	23
	Lakhimpu r				0	0	0	0	0	3
	Majuli				0	0	0	0	0	10
	Morigaon	emergenc	e Boat Star y situation.		7	0	0	0	0	9
	Nagaon				18	60	0	0	0	16
	Nalbari	Circle Off Administr			2	0	0	0	0	43
	Sonitpur				0	0	0	0	0	4
	South Salmara	Circle Off Administr			26	71	64	0	0	11
	Total				241	6567	238	1	0	277
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)		- Rice Bran	(in Q)
	Bajali	0.00	0.00	0.00	4000.00	0.00	2350.68	0.00		
	Baksa Barpeta	159.96 8643.82	31.66 1217.8 2	9.49 309.47	949.00 500.00	0.00	0.00 3318.60	0.00 755.00		
	Cachar Chirang	1128.76 12.98	208.16	34.65 0.71	6213.93 71.00	0.00	0.00	0.00		
	Darrang	1624.03	327.30	102.74	11403.00	0.00	0.00	530.00		
D.I. C	Dhemaji	98.99	18.16	5.44	544.62	0.00	84.38	0.00		
Relief Distributed	Dhubri	27.61	6.02	1.24	150.27	0.00	1751.03	0.00		
Distributed	Dima- Hasao	18.93	2.35	1.86	117.50	0.00	0.00	0.00		
	Hailakand i	329.75	87.22	18.53	1853.40	0.00	0.00	0.00		
	Hojai	151.00	24.90	3.25	550.00	0.00	0.00	25.00		
	Kamrup	811.51	209.82	26.00	7328.83	0.00	787.15	0.00		
	Karbi Anglong West	16.61	5.95	0.94	94.23	0.00	0.00	0.00		
	Karimganj	1248.98	226.82	50.02	30.00	0.00	0.00	0.00		
	Lakhimpu r	0.00	0.00	0.00	0.00	0.00	0.00	638.00		
	Morigaon	1210.79	217.16	65.15	0.00	30.00	0.00	96.00		

	Nagaon	2315.86	201.04	60.31	0.00	0.00	274.70	500.00	
	Nalbari	1785.52	263.52	78.96	4536.76	0.00	48.12	0.00	
	Sonitpur	0.00	0.00	0.00	0.00	0.00	164.18	0.00	
	Udalguri	17.70	3.15	0.94	94.30	0.00	9.20	26.00	
	Total	19602.8 0	3053.4 3	769.70	38436.84	30.00	8788.04	2570.00	
	District	Baby Foo Liquid	od	Baby Food	d Solid	Others			
	Bajali	0.00-Q		0.00-Q, 71	2.00-Pkt	Tarpaulin-286	69.00-Pieces		
	Baksa	0.00-Q, 0	.00-Pkt	0.00-Q, 0.0	00-Pkt	Wheat bran-6	5.00-Q		
	Barpeta	0.00-Q		148.00-Pki	t, 0.00-Q	Suzi-495.00-Kg; Phenyl-500.00-Pieces; candles-1000.00-Pkt; biscuit-10000.00-Pkt; Match box-2600.00-Pieces; Sanitary Napkin-130.00-Pkt; 1. Tarpaulin -3500.00-Pieces; Tarpaulin-8000.00-Pieces; Hand Tube-well(HTW)-209.00-Pieces; HTW installed-114.00-Pieces; Sanitary Napkins-756.00-Pieces; Candle-440.00-Pkt; Drinking water-7250.00-Pieces; Biscuit-1160.00-Pkt; Mosquito Coil-600.00-Pkt; candel-2262.00-Pkt; Tarpulin-3500.00-Pieces; Water Bottle-7000.00-Pieces; Mosquito-1102.00-Pkt; Horlics-145.00-Pieces; Cerelac-350.00-Pkt			
	Bongaigao n	0.00-Q		0.00-Q		Phenyl-3.10-F 24000.00-Piec Mosquito net-	Pkt; Temp. H7 ces; Toilet-53 100.00-Piec	Kg; Halogen Tablets-5950.00-Pkt; FW-69.00-Pieces; Mobile Plant- .00-Pieces; Dustbin-2.00-Pieces; es; Solar Light -30.00-Pieces; Halogen Phenyl-19.50-L; Bathroom-2.00-Pieces	
	Cachar	0.00-Q		0.00-Q					
	Chirang	0.00-Q		0.00-Q		Soap-85.00-P			
	Darrang	0.00-Q		0.00-Q, 20	0.00-Pieces	0-0.00-Q; candles-20.00-Pkt; halogen tablets-500.00-Pieces; drinking water-1000.00-L; phenyl-30.00-Pieces; Tarpaulin-3000.00-Pieces; Mosquito reseller-1000.00-Pkt; Candle-1500.00-Pkt; Matchbox-30.00-Pkt; Tarpaulin -4000.00-Q; Candle Light-1.00-Pkt; Phinyl -132.00-Q			
	Dhemaji	0.00-Q, 0	.00-L	0.00-Q, 0.0	00-Pkt	0-0.00-Q			
Relief	Dhubri	0.00-Q		0.00-Q		water pouches 26.00-Pieces;	s-6000.00-Pkt Pit Latrine-20	Pkt; halogen tablet-1800.00-Pieces; ;; Tarpaulin-1000.00-Pieces; HTW- 6.00-Pieces; Tarpaulin -359.00-Pieces	
Distributed Others	Dima- Hasao	0.00-Q		0.00-Q		113.00-L; Pot 186.00-Pkt; M	ato-497.00-K Iosquito repel	17.50-Kg; Biscuit-996.00-Pkt; Milk- g; Candle-421.00-Pkt; Match box- llent-192.00-Pkt	
	Hailakand i	0.00-Q, 7	1.00-Pkt	0.00-Q, 20.00-Pkt		Pieces; Water Candle-71.00- 1000.00-Piece	Packets-6000 -Pkt; Match B es; Disposable	8500.00-Pieces; Tarpoulin-500.00- 0.00-Pkt; sanitary Napkin-20.00-Pkt; Box-80.00-Pieces; Disposable plate- e Glass-1000.00-Pieces; Soap-71.00- eces; Hand Sanitizer-1.00-Pieces	
	Hojai	0.00-Q		0.00-Q		Water Bottle-1392.00-L; Sanitary Pad-240.00-Pkt; Candle-110.00-Pkt; Phenyl-90.00-Pieces; Amul Taza-216.00-L; Water 480.00-L; Bleaching-12.50-Kg; Phenyl-25.00-Pkt			
	Kamrup	0.00-Q, 20 Pkt	00.00-	0.00-Q	0.00-Q		Water Pouch-5000.00-Q; Black Phenyl-5.00-L; Harpic-3.00-L; Cleaning Mop-3.00-Pieces; Chitranala-0.10-L; 0-0.00-Q; Whea bran-306.20-Q; Tarpuline-1500.00-Q; Candle-200.00-Q; Sanita Napkin-200.00-Pkt		
	Karbi Anglong West	0.00-Q		0.00-Q					
	Karimganj 100.00-Q, 24.00-Pkt Lakhimpu r 0.00-Q		0.00-Q			ablet-5240.00	ndle-24.00-Pkt; Coil-24.00-Pkt; Water D-Pieces; Chemical packets-6250.00- Pkt		
				0.00-Q		Tarpaulin -56	2.00-Pieces		
1	Majuli	0.00-Q		0.00-Q		Halogen Tab-	950.00-Pieces	S	
	Morigaon	0.00-Q		0.00-Q		CANDLE -3200.00-Pieces; HTW -13.00-Pieces; WATER POUCH-8000.00-Pieces; CHEMICAL PACKETS-4400.00-Pieces; CHARGEABLE LIGHT -2000.00-Pieces; Tarpaulin -72.00-Pkt; Restoration of 6nos of existing HTW by PHED -6.0 Pieces			
	Nagaon	45000.00- 0.00-Q	-Pkt,	45000.00-1	Pkt, 0.00-Q			-42010.00-Pkt; Candle-42010.00-Pkt; ces; 0-0.00-Q; Tapulin-1500.00-Pieces	

	Nalbari	0.00-Q		0.00-Q	Tarpaulin-1050.00-Pkt; wheat bran-1284.00-Q					
	Sonitpur	16.00-L, ().00-Q	11.20-Kg, 0.00-Q						
	South Salmara	0.00-Q		0.00-Q	Hand Tube well-16.00-Pieces; Pit Latrine -34.00-Q; HTW-50.00-Pieces					
	Udalguri	0.00-Q		0.00-Q	0-0.00-Q; Sanitary Pad -221.00-Pkt; Candles & Match Sticks-20.00-Pkt; Mosquito Coil-20.00-Pkt; Disposal Plates-60.00-Pkt; Disposal Glass-12.00-Pkt; Soap-68.00-Pieces; Water Can (20Ltrs)-100.00-Pieces; Baby Daipers-500.00-Pkt					
	District	Numbe r	Details Details							
Infrastructu re Damaged - Embankme nt Breached	Nagaon	3	20/06/20 0.000000 Phulagur Departme Phulagur	22 Breach- 50 m Departm 1), i to Uttar Petborha Garm ent-Raha Territorial Road i to Uttar Petborha Garm	ri Deobali Phulaguri Deobali Date of Occurrence from- ent-Raha Territorial Road Sub-Division (Long - 0.000000, Lat - uur Satra Date of Occurrence from- 20/06/2022 Breach 1- 50 m Sub-Division (Long - 0.000000, Lat - 0.000000), uur Satra Date of Occurrence from- 20/06/2022 Breach 2- 50 m Sub-Division (Long - 0.000000, Lat - 0.000000)					
	Total	3								
I f t t	District	Numbe	Details							
Infrastructu re Damaged - Embankme nt Affected	South Salmara	1 1	Mankachar - 1. T/dyke (Embankment) Pipulbari to Diara As per report received from the Assistant Executive Engineer Hatsingimari W.R. Sub-Division, Hatsingimari on 24/06/2022, the T/dyke (Embankment) from Pipulbari to Diara has been damaged due to heavy rain fall and flood water from 0 M to 4500 M. (Long - 25.627060, Lat - 89.925092)							
		Numbe								
	District	r	Details							
	Bajali	3	1200m.T 23/06/20 Pakritol I damaged Division, Golaghat 1000m.T	Bajali - pokha odalguri road damaged.length 1200m pokha odalguri road damaged.length 1200m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Pakritol Dekapara Road side berm damaged.length 500m pakritol to dekapara road side berm damaged.length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Golaghat Dhaneswari Road length 1000m golaghat Dhaneswari road road damaged.length 1000m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000)						
	Baksa	2	Chawk C Lat - 26.' Bhutankl Bhutankl 26.76560	Baska - Doomni to Arnibil Gorom Chawk CC Block road Doomni Doomni to Arnibil Gorom Chawk CC Block road damaged due to flood on 18/06/2022 at village Doomni (Long - 91.316355, Lat - 26.725098), Bhutankhuti LP School to Bhutankhuti Village Road Bhutankhuti Bhutankhuti LP School to Bhutankhuti Village Road damaged on 18/06/2022 at village Bhutankhuti (Long - 91.376203, Lat - 26.765609)						
Infrastructu re Damaged	Barpeta	2	Barpeta - Howly Belguri road Howly Road submerged 700.00 m PWRD Barpeta DOO 17.06.2022 (Long - 90.977138, Lat - 26.434694), Joypur Kawaimari road via Kuthilajar chariali Joypur Side berm eroded & Culvert Damage 2300.00 m PWRD Barpeta DOO 17.06.2022 (Long - 90.951808, Lat - 26.427429)							
- Road	Bongaigao n	7	partially (Long - Dholagae 1500.00r 26.40579 Bageswa ch 200.00 Lat - 26.4 Kasuagae 450.00m 26.41150 Salbari E per repor Manikpi washout (Long - 9 Dangtol	damaged at 4th and 5th Kl 90.373700, Lat - 26.2436 on Ravapara Tilapara Road n as per report received fro (3), ri Temple to Chitkagaon F Om. as per report received (469981), on to Mamugaon Road K as per report from PWRD (3), dongaigaon Road Salbari et received from PWRD, B ur - Gerukabari Kirtanpara around 50.00 mtr.Road ler (0.711862, Lat - 26.38240) - Mulagaon to Chengmari ceived from PWRD, Bong	d Dewangaon About 10 m lenth of Road breached out at chom PWRD, Bongaigaon date- 24.06.2022 (Long - 90.526423, Lat - Road Chitkagaon Side slopes erroded and hard crust damaged at from PWRD, Bongaigaon date-24.06.2022 (Long - 90.565225, Lasuahaon Hard crust damaged and side slopes erroded at ch. 20, Bongaigaon date- 24.06.2022 (Long - 90.491831, Lat - Road embankment erroed by received Tunia at Ch. 8800.00m. as longaigaon date- 24.06.2022 (Long - 90.737730, Lat - 26.435847), a road. Bashbari no 2 Road Embankment eroded by river Aie and light at 10th KM (Bashbari No 2) on Gerukabari Kirtanpara road. 00, Chengmari Embankment and shoulder damaged at 9th km as per laigaon date- 24.06.2022 (Long - 90.511898, Lat - 26.390512)					
	Cachar	2			aigaon date- 24.06.2022 (Long - 90.511898, Lat - ur Road Paillorbond area PWD Road Damage Re					

		Francisch Office Labinus at 24.00 2022 Ld
		From Circle Office Lakhipur on 24.06.2022 (Long - 0.000000, Lat - 0.000000), Dilkush to Laleyan CH 1500 to 3000 PWD Road Damage Report Received From Circle Office Lakhipur on 24.06.2022 (Long - 0.000000, Lat - 0.000000)
Dhemaji	1	Sissiborgaon - PWD road from NH 52 to Kamchi Nagaon Road At Ch 1331.00 M to Ch. 1435.00 M and Ch. 3341.00 M to Ch. 4007.00 M Damaged the road embankment, side shoulder, hard crust along with concrete and ICBP pavement. around Length - 770 Meters on 24-06-2022 (Long - 94.611087, Lat - 27.568348)
Dhubri	27	Bilsipara: -4TH KM BS ROAD TO SOLMARI AZRA ROAD ().SIDE BUM & HARD CRUST DAMAGED BY TIPKA I RIVER FLOOD WATER 4TH KM BS ROAD TO SOLMARI AZRA ROAD 10 SECTION 10 SECTION

T		
		SUBMERGED AT 1ST KM (18-06-2022) HATIDHURA SRIRAMPUR ROAD TO HATIDHURA
		COLLEGE ROAD (Long - 26.221900, Lat - 89.855100),
		ROAD SURFACE DAMAGED FROM 21ST KM OF DK ROAD TOP MADHYAPETLA AT 1ST & 2ND KM (18-06-2022) 21ST KM OF DK ROAD TOP MADHYAPETLA (Long - 26.273500, Lat
		- 89.861000),
		ROAD SURFACE DAMAGED 300.00 M BOTH APPROACHESC OF BOX CULVERT NO. 4/1
		INCLUDING SIDE BERM AND SIDE SHOULDER DAMAGED ON MADHYAPETLA TO
		PATHANERKUTI PMGSY ROAD (18-06-2022) MADHYAPETLA TO PATHANERKUTI
		PMGSY ROAD (Long - 26.273500, Lat - 89.861000),
		DK ROAD TO BALASHI ROAD SUBMERGED FROM 1ST KM TO 2ND KM IN SEVERAL
		STRECHES (18-06-2022) DK ROAD TO BALASHI ROAD (Long - 26.198500, Lat - 89.862600),
		SIDE BERM, SIDE SLOPE AND BRIDGE APPROACHES OF SPT BR. NO. 1/1 DAMAGED OF
		POKALAGAI TO POLASHKANDI ROAD FROM CH.0.00 M TO 100.00 M. (18-06-2022) POKALAGAI TO POLASHKANDI ROAD (Long - 26.346300, Lat - 89.859200),
		DK ROAD TO LOHARPUR SUBMERGED AT 2ND KM DK ROAD TO LOHARPUR (Long -
		26.251300, Lat - 89.853800),
		GRAHAMPUR TO POKALAGI ROAD SUBMERGED AT 1ST & 2ND KM IN SEVERAL
		STRECHES (18-06-2022) GRAHAMPUR TO POKALAGI ROAD (Long - 26.251200, Lat -
		89.853600),
		ROAD SURFACE SIDE SHOULDER BADLY DAMAGED ON TAMACHABAGAN TO
		KALACHANPARA ROAD AT 1ST & 2ND KM (18-06-2022) TAMACHABAGAN TO KALACHANPARA ROAD (Long - 26.313300, Lat - 89.837300),
		Agamoni - ROAD SUBMERGED ON NH-17 NEAR AGOMONI GIRLS SCHOOL TO P.K. ROAD
		VIA SANKARDEVA SISHU NIKETAN AT 1 ST KM (0.15 KM) dtd. 12/06/2022 to 18/06/2022
		NH-17 NEAR AGOMONI GIRLS SCHOOL TO P.K. ROAD VIA SANKARDEVA SISHU
		NIKETAN AT 1 ST KM (0.15 KM) (Long - 0.000000, Lat - 0.000000),
		SIDE BERM DAMAGED ON BBPJ ROAD AT 2nd KM dtd. 12/06/2022 to 18/06/2022. SIDE
		BERM DAMAGED ON BBPJ ROAD AT 2nd KM (Long - 0.000000, Lat - 0.000000),
		SIDE BERM DAMAGED ON RANPAGLIRHAT TO SATRASAL ROAD AT 1ST KM dtd. 12/06/2022 to 18/06/2022. RANPAGLIRHAT TO SATRASAL ROAD AT 1ST KM (Long -
		0.000000, Lat - 0.000000)
		Rangia - Chepti Bihdia Road at Ch 600.00 m Vill- Chepti Chepti Bihdia Road at Ch 600.00 m was
		washed away as per report of AEE, PWD, NKT Roads, Rangia on 22.06.2022 (Long - 91.636262,
		Lat - 26.414157),
		Katrakhat Kendukona Road Vill- Kaniha Dagharia Katrakhat Kendukona Road was damaged as per
		report of AEE, PWD, NKT Roads, Rangia on 22.06.2022 (Long - 26.378128, Lat - 91.626082), Kayan - Morowa Baranghati Road via Dhuhi Hospital Chowk to Kayan Circle Office (breaches 80 m
		and side berm eroded). Damage Date: 16/06/2022. Vill- Dhuhi. Reported by PWRD, Jalukbari &
		Hajo Territorial Road Division on 23/06/2022. GPS co-ordinates couldn't be provided at the moment
		by respective department. (Long - 0.000000, Lat - 0.000000),
		Kumtibari Bathan Road via Irrigation Project (breaches 60 m and side berm eroded). Damage Date:
Kamrup	6	16/06/2022. Vill- Bordongabatakuchi. Reported by PWRD, Jalukbari & Hajo Territorial Road
		Division on 23/06/2022. GPS co-ordinates couldn't be provided at the moment by respective
		department. (Long - 0.000000, Lat - 0.000000), Nabajyoti High School Road (breaches 70 m and side berm eroded). Damage Date: 16/06/2022. Vill-
		Larmagourhati. Reported by PWRD, Jalukbari & Hajo Territorial Road Division on 23/06/2022. GPS
		co-ordinates couldn't be provided at the moment by respective department. (Long - 0.000000, Lat -
		0.000000),
		Kamalpur morowa road (breaches 150 m and side berm eroded). Damage Date: 16/06/2022. Vill-
		Borpulla, Bokultol. Reported by PWRD, Jalukbari & Hajo Territorial Road Division on 23/06/2022.
		GPS co-ordinates couldn't be provided at the moment by respective department. (Long - 0.000000, Lat - 0.000000)
	1	RK Nagar - kadamtala to Bhairabnagar road kadamtala to Bhairabnagar road On the date of report
		20.06.2022 the above said road slip & landslide ,side berm & hard n.crust as per reported by Asstt.
		Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at
		FRIMS on 24-06-2022 (Long - 92.471725, Lat - 24.654947),
		Kadamtala to Aynakhal Road Kadamtala to Aynakhal Road On the date of report 20.06.2022 the
		above said road ddamaged surface, subgrade &shoulder as per reported by Asstt. Executive Engineer
Karimganj	48	,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 (Long - 92.524533, Lat - 24.608520),
raninganj	=0	Bhanga-Anipur NEC road to Dewardarghat Bhanga-Anipur NEC road to Dewardarghat On the date
		of report 20.06.2022 the above said road submerged road surface & boulder appron along side road
		badly damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub-
		Division. The same is being reported at FRIMS on 24-06-2022 (Long - 92.457041, Lat - 24.702389),
		Chandkhani to Pollysree road Chandkhani to Pollysree road On the date of report 20.06.2022 the
		above said road approach of the bridge no 2/1 severely damaged as per reported by Asstt. Executive
	1	Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on

24-06-2022 | (Long - 92.446879, Lat - 24.599457),

Dullavcherra -veterbond road | Dullavcherra -veterbond road | On the date of report 20.06.2022 the above said road approach of the bridge no 2/1 severely damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.435177, Lat - 24.484577),

Anipur-Asimganj road to Nitainagar | Anipur-Asimganj road to Nitainagar | On the date of report 20.06.2022 the above said road submerged road surface, subgrade & shoulder as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub-Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.415496, Lat - 24.561936),

Chargola -Rongpur road | Chargola -Rongpur road | On the date of report 20.06.2022 the above said road approach of the bridge no 28/1 severely damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.396050, Lat - 24.401215),

Chargola -Rongpur road | Chargola -Rongpur road | On the date of report 20.06.2022 the above said road approach of the bridge no 34/3 severely damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.233400, Lat - 24.234800),

Saraspur -Sonbeel road | Saraspur -Sonbeel road | On the date of report 20.06.2022 the above said road slip & landslide ,side berm & hard crust as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.500146, Lat - 24.701176),

Bishnupur -Rakhalbasti road | Bishnupur -Rakhalbasti road | On the date of report 20.06.2022 the above said road slip & landslide ,side berm & hard crust as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.494288, Lat - 24658652.000000),

Kalibaribazar to Gopika Nagar road | Kalibaribazar to Gopika Nagar road | On the date of report 20.06.2022 the above said road bridge approach submerged, eroded on both sides &damaged badly as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.458474, Lat - 24.642731),

Anipur NEC road to Sonaicherra Cha bagan Pt II (PMGSY Pkg No-AS-13-230) | Anipur NEC road to Sonaicherra Cha bagan Pt II (PMGSY Pkg No-AS-13-230) | On the date of report 20.06.2022 the above said road slip & landslide ,side berm & hard crust as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.486847, Lat - 24.651332),

Kadamtala to Sanyashibari road | Kadamtala to Sanyashibari road | On the date of report 20.06.2022 the above said road landslide ,side berm & hard crust as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.469989, Lat - 24.584970),

Anipur -Zamuang NEC road to Roypur (PMGSY Pkg No-AS-13-164) | Anipur -Zamuang NEC road to Roypur (PMGSY Pkg No-AS-13-164) | On the date of report 20.06.2022 the above said road landslide ,side berm & damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.275500, Lat - 24.521943),

Lalbabu Khasia Punjee road | Lalbabu Khasia Punjee road | On the date of report 20.06.2022 the above said road landslide, side berm & hard crust as per reported by Asstt. Executive Engineer, PWRD, Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.473552, Lat - 24.521943),

Anipur NEC road to Netajinagar (PMGSY Pkg No-AS-13-215) | Anipur NEC road to Netajinagar (PMGSY Pkg No-AS-13-215) | On the date of report 20.06.2022 the above said road slip & landslide ,side berm & hard crust damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.478808, Lat - 24.633662),

Saraspur Kalibari bazar to Singua Pt 4 | Saraspur Kalibari bazar to Singua Pt 4 | On the date of report 20.06.2022 the above said road slip & landslide ,culvert approach damaged badly as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.476178, Lat - 24.699063),

KK road to Dolu (PMGSY Pkg No-AS-13-271) | KK road to Dolu (PMGSY Pkg No-AS-13-271) | On the date of report 20.06.2022 the above said road submerged road surface & badly damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.458988, Lat - 24.626488),

KK road to Paschim Baruala (PMGSY Pkg No-AS-13-302) | KK road to Paschim Baruala (PMGSY Pkg No-AS-13-302) | On the date of report 20.06.2022 the above said road approach of the bridge no. 1/3 severely damaged along with road stretches as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.458409, Lat - 24.591360),

Kalyanpur to Samridhipur road | Kalyanpur to Samridhipur road | On the date of report 20.06.2022 the above said road submerged road surface as per reported by Asstt. Executive Engineer ,PWRD

,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.451120, Lat - 24.665707),

Chamela to Singirpar road | Chamela to Singirpar road | On the date of report 20.06.2022 the above said road hard crust damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.460112, Lat - 24.600868),

Pallisree to Bhabanipur | Pallisree to Bhabanipur | On the date of report 20.06.2022 the above said road hard crust damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.444605, Lat - 24.602150),

Chandkhani to Pallisree | Chandkhani to Pallisree | On the date of report 20.06.2022 the above said road hard crust damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.449658, Lat - 24.592220),

Bhairabnagar AD camp to Bharpecha | Bhairabnagar AD camp to Bharpecha | On the date of report 20.06.2022 the above said road hard crust damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.488422, Lat - 24.511320),

Anipur NEC to Saijanagar | Anipur NEC to Saijanagar | On the date of report 20.06.2022 the above said road hard crust & shoulder damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.473023, Lat - 24.598197),

Mangalpur Dalu to Kalibari | Mangalpur Dalu to Kalibari | On the date of report 20.06.2022 the above said road submerged road surface as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.461123, Lat - 24.627528),

Kalibari to Chutokuna | Kalibari to Chutokuna | On the date of report 20.06.2022 the above said road submerged road surface as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.642451, Lat - 24.645194),

Nabingram Sanskriti Parishod to Niznabin SCSP road | Nabingram Sanskriti Parishod to Niznabin SCSP road | On the date of report 20.06.2022 the above said road submerged road surface as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.462365, Lat - 24.641787),

Chorgola -Rongpur road (culvert at Bashkhaltilla) | Chorgola -Rongpur road (culvert at Bashkhaltilla) | On the date of report 20.06.2022 the above said road HP culvert damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.406996, Lat - 24.480024),

Maguracherra TE to Nivia Bazar road (culvert washed away near Moon Jadav house) | Maguracherra TE to Nivia Bazar road (culvert washed away near Moon Jadav house) | On the date of report 20.06.2022 the above said road culvert washed away as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.411814, Lat - 24.398882),

Dakshin Rampur road (PMGSY Pkg No-AS-13-278) | Dakshin Rampur road (PMGSY Pkg No-AS-13-278) | On the date of report 20.06.2022 the above said road s landslide ,culvert washed away as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.407756, Lat - 24.447507),

Singlacherra TE road SOPD (ODS) | Singlacherra TE road SOPD (ODS) | On the date of report 20.06.2022 the above said road side slope totally eroded as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.415076, Lat - 24.449216),

Guramaji road | Guramaji road | On the date of report 20.06.2022 the above said road submerged road suface as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.465007, Lat - 24.628023), Anipur NEC road to Sripur Via Maniknagar | Anipur NEC road to Sripur Via Maniknagar | On the date of report 20.06.2022 the above said road slip & landslide ,side berm & hard crust as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.454985, Lat - 24.628062),

Dullavcherra to Siphacherra road | Dullavcherra to Siphacherra road | On the date of report 20.06.2022 the above said road culvert approach damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.441781, Lat - 24.485927),

CR road near Sugar Mill to Awalala Village | CR road near Sugar Mill to Awalala Village | On the date of report 20.06.2022 the above said road Embankment damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.467210, Lat - 24.571340),

Amtilla Khasia punjee road (PMGSY Pkg No-AS-13-281) | Amtilla Khasia punjee road (PMGSY Pkg

No-AS-13-281) On the date of report 20.06.2022 the above said road slip & landslide, side berm & hard crust as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub-Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.274500, Lat - 24.245100), Veterbond jungle block road (PMGSY Pkg No-AS-13-264) | Veterbond jungle block road (PMGSY Pkg No-AS-13-264) On the date of report 20.06.2022 the above said road landslide, side berm damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub-Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.275500, Lat - 24.282000), Anipur NEC road Jummamahal | Anipur NEC road Jummamahal | On the date of report 20.06.2022 the above said road slip & landslide ,side berm & culvert badly damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.472933, Lat - 24.656382), CR road to Harintilla | CR road to Harintilla | On the date of report 20.06.2022 the above said road side slope damaged badly as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.252130, Lat -Anipur NEC road Jummamahal | Anipur NEC road Jummamahal | On the date of report 20.06.2022 the above said road landslide sideberm damaged badly as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.275500, Lat - 24.282000), Anipur NEC road to Dargarbond jungle block | Anipur NEC road to Dargarbond jungle block | On the date of report 20.06.2022 the above said road slip & landslide ,side berm & hard crust as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.489012, Lat - 24.695798), Netajinagar PWD road to Chakraborty para | Netajinagar PWD road to Chakraborty para | On the date of report 20.06.2022 the above said road landslide, side berm damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.489013, Lat - 24.695798), Anipur - Zamuang road to Bijoypur (PMGSY Pkg No-AS-13-264) | Anipur - Zamuang road to Bijoypur (PMGSY Pkg No-AS-13-264) | On the date of report 20.06.2022 the above said road landslide, side berm damaged as per reported by Asstt. Executive Engineer, PWRD, Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long -92.241200, Lat - 24.202000), Kalinagar to Chandkhani road (PMGSY Pkg No-AS-13-64) | Kalinagar to Chandkhani road (PMGSY Pkg No-AS-13-64) | On the date of report 20.06.2022 the above said road hard crust & shoulder damaged as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub-Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.241300, Lat - 24.202000), Durga Bazar Rankhal | Durga Bazar Rankhal | On the date of report 20.06.2022 the above said road hard crust & land sleep as per reported by Asstt. Executive Engineer ,PWRD ,Ratabari Territorial Road Sub- Division. The same is being reported at FRIMS on 24-06-2022 | (Long - 92.281800, Lat -24.271000), Badarpur - Badarpur Adarkuna Road to Borthal Pt- XII via Nagarsigool (PMGSY Pkg-13-197) | Badarpur Adarkuna Road at 11 KM | On 20-06-22, the AEE, PWRD reported damaged to the said road at 11 KM where multiple damages has been reported including Culvert and landlside also reported at the said road, L=70.00 m. The same is being reported at FRIMS on 24-06-2022 | (Long-24.809538, Lat - 9.531382). Anglarbazar Duttapur Road | Anglarbazar | On 20-06-22, the AEE, PWRD reported damaged to the said road where multiple damages has been reported including surface damge, sub grade and shoulder Culvert also reported at the said road at L=1780 m. The same is being reported at FRIMS on 24-06-2022 | (Long - 24.819720, Lat - 92.483130) Gossaigaon - THAKURPUR | THAKURPUR | AS PER L.M. REPORT DUE TO HEAVY RAINFALL FROM 14TH JUNE TO TILL 17-06.2022 A Village Road from Munu's House to Dingdinga SLUISS Gate (Approx 500mtr) | (Long - 0.000000, Lat - 0.000000), KARLINGPUR | THAKURPUR | AS PER L.M. REPORT DUE TO HEAVY RAINFALL FROM 14TH JUNE TO 17 TH JUNE, 2022 Village Road damaged from Karlingpur to Joypur (Thakurpur) (Long - 0.000000, Lat - 0.000000), MORNOI TEA ESTATE | MORNOI | AS PER L.M. REPORT DUE TO HEAVY RAINFALL FROM 14TH JUNE TO 17 TH JUNE, 2022 Damaged approach road to bridges (Approx 100M) near Big Bunglow Bridge | (Long - 0.000000, Lat - 0.000000), Kokrajhar 13 NO.2 PANBARI | NO.1 PANBARI (SIALMARI) | AS PER L.M. REPORT DUE TO HEAVY RAINFALL FROM 14TH JUNE TO 17 TH JUNE, 2022Road damaged Gurufela to NH 31 (C) to No.2 Panbari Thandabazar Road. Road Erosion at No.1 Panbari (Sialmari) Road Erosion to Alinagar Kopragaon (Approx 70 ft) | (Long - 0.000000, Lat - 0.000000), No.2 Garumarachar | No.2 Garumarachar | AS PER L.M. REPORT DUE TO HEAVY RAIN FROM 14TH JUNE TO 17 TH JUNE A ROAD 15X12 FT PARTIALLY DAMAGED NEAR L. P. SCHOOL , 15X8 FT CULVRERT DAMAGED AND EMBANKMENT DAMAGED 20X15 FT AT VILLAGE NO.2 GARUMARACHAR | (Long - 0.000000, Lat - 0.000000), BOLLAMJHORA | BOLLAMJHORA | AS REPORT RECEIVED FROM AEE PWD RR

ı		WAGINIGA ON SUB DIVIGION ON 20 04 2022 DVID TO DVIGTGG ANTI-VID
		KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO INCESSANT HEAVY RAIN IMMEDIATE RESTORATION OF BOLLAMJHORA ROAD 1/2 CULVERT APPROACHES DAMAGED INCLUDING ROAD REPAIRING (Long - 0.000000, Lat - 0.000000), SRIRAMPUR SRIRAMPUR AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO INCESSANT HEAVY RAIN IMMEDIATE RESTORATION OF SRIRAMPUR ROAD WASHED OUT 800 MTRS. (Long - 0.000000, Lat - 0.000000),
		KUSUMBIL PMGSY ROAD KUSUMBIL AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT KUSUMBIL PMGSY ROAD FROM CH. 00.00M TO 1100.00M FOR THE YEAR 2022-23 (Long -
		0.000000, Lat - 0.000000), KUSUMBIL PMGSY ROAD KUSUMBIL AS REPORT RECEIVED FROM AEE PWD RR
		KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT KUSUMBIL PMGSY ROAD FROM CH. 1105.00M TO 2000.00M FOR THE YEAR 2022-23 (Long - 0.000000, Lat - 0.000000),
		DUMBAJHAR TO RANGAPARA ROAD DUMBAJHAR AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT DUMBAJHAR TO RANGAPARA ROAD FROM CH. 150.00M WITH RCC BOX CULVERT
		2X2=5 CELL FOR THE YEAR 2022-23 (Long - 0.000000, Lat - 0.000000), DUMBAJHAR TO RANGAPARA ROAD DUMBAJHAR AS REPORT RECEIVED FROM AEE
		PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT DUMBAJHAR TO RANGAPARA ROAD FROM CH. 200.00M WITH RCC BOX CULVERT
		2X2=5 CELL FOR THE YEAR 2022-23 (Long - 0.000000, Lat - 0.000000), Bagribari - NH-31 AT KHORAGHAT TO KHAMAR KHORAGHAT AS REPORTED BY EXE.
		ENG PWD BILASHIPARA CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 20.06.2022, NH-31 AT KHORAGHAT TO KHAMAR SUBMERGED AT 1ST AND 2ND KM ROAD SURFACE AND SIDE DAMAGED DUE TO FLOOD WATER OF RIVER TIPKAI (Long -
		90.129107, Lat - 26.214602), NH-31 AT KHORAGHAT TO CHAWGURI KHORAGHAT AS REPORTED BY EXE. ENG
		PWD BILASHIPARA CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 20.06.2022, NH-31 AT KHORAGHAT TO CHOWGURI SUBMERGED AT 1ST, 2ND, 3RD AND 5TH KM SIDE BERM ERRODED AND RCC BOXCELL NO.3/1 BOTH APPROACHES BADLY
		DAMAGED DUE TO FLOOD WATER OF RIVER HEL (Long - 90.120613, Lat - 26.233555) Morigaon - Manipur Patkumoi road (21-06-2022) Manipur As per PWD (Roads), Manipur
		Patkumoi road under submergence for a length of 130m. Submergence depth= 0.20m (Long - 92.264971, Lat - 26.270295), NH-37 to Borbori Road (24-06-2022) Borbori NH-37 to Borbori Road submerged at 1st KM (Long
		- 92.359762, Lat - 26.160130), Mikirbheta - Nagaon Morigaon PWD Road to Sonaruguri via Tangunmara Sonaruguri As reported
Morig	aon 5	by AEE, Batadrava Territorial Road Division, on 23-06-2022, Nagaon Morigaon PWD Road to Sonaruguri via Tangunmara, affected lenght approx, L= 1.20 km (Long - 0.000000, Lat - 0.000000), Sahipukhuri to Sonaruguri via Polashguri Polashguri As reported by AEE, Batadrava Territorial
		Road Division, on 23-06-2022, Sahipukhuri to Sonaruguri via Polashguri affected lenght approx. L= 1.50 km (Long - 0.000000, Lat - 0.000000),
		Niz Kapahera to Polashguri via Tekelagaon Kapahera As reported by AEE, Batadrava Territorial Road Division, on 23-06-2022, Niz Kapahera to Polashguri via Tekelagaon affected lenght approx, L= 0.500 km (Long - 0.000000, Lat - 0.000000)
		Raha - Bebajia Ghahi Dakhinpath Nonoi Chutiagaon Road Ghahi Date of Occurrence- 22/06/2022 Submerged- 20 cm to 80 cm Department-Batadrava Territoria Road Sub-Division (Long - 0.000000, Lat - 0.000000),
		Khaigarh Meteka Dighaldari Deobali Phulaguri Khaigarh Date of Occurrence from- 20/06/2022 Submerged- 100 cm Department-Raha Territorial Road Sub-Division (Long - 0.000000, Lat - 0.000000),
Nagao	n 36	Phulaguri to Uttar Peborha Phulaguri Date of Occurrence from- 20/06/2022 Submerged- 3 Km Department-Raha Territorial Road Sub-Division (Long - 0.000000, Lat - 0.000000), Saragaon to Phulaguri via Deobali Saragaon Date of Occurrence from- 20/06/2022 Submerged- 2.5
		Km Department-Raha Territorial Road Sub-Division (Long - 0.000000, Lat - 0.000000), Rupahitoli to Topakuchi Road Rupahitoli Date of Occurrence from - 20/06/2022 Submerged - 1 Km Department-Raha Territorial Road Sub-Division (Long - 0.000000, Lat - 0.000000),
		Old AT Road Raha Raha Date of Occurrence from- 20/06/2022 Submerged- 400 m Department-Raha Territorial Road Sub-Division (Long - 0.000000, Lat - 0.000000),
		NH 27 to Old AT Road (Raha Bazar Road) Raha Date of Occurrence from 20/06/2022 Submerged-300 m Department-Raha Territorial Road Sub-Division (Long - 0.000000, Lat - 0.000000),

Raha Higher Secondary School Approach Road | Raha | Date of Occurrence from 20/06/2022 Submerged- 200 m Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat -0.000000). Old Transport Syndicate Road | Raha | Date of Occurrence from- 20/06/2022 Submerged- 200 m Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NH 27 to Pub Topakuchi via Khadi Office | Topakuchi | Date of Occurrence from- 20/06/2022 Submerged- 400 m Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat -0.000000), NH 27 to Dubaritoli | Dubaritoli | Date of Occurrence from 20/06/2022 Submerged - 2 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NH 27 to Kollongpar | Kollongpar | Date of Occurrence from- 20/06/2022 Submerged- 1 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NH 37 to Amonikhali Das Chuburi | Amonikhali | Date of Occurrence from 20/06/2022 Submerged-1 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Chaparmukh Sing Gaon Road | Chaparmukh | Date of Occurrence from- 20/06/2022 Submerged- 1.3 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Khaigarh LP School to Amonikhali LP School | Khaigarh | Date of Occurrence from- 20/06/2022 Submerged- 1 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat -0.000000), Bogoriguri to Nutun Bogoriguri | Bogoriguri | Date of Occurrence from- 20/06/2022 Submerged- 1.20 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Garh Maj to Dubaritoli | Garh Maj | Date of Occurrence from 20/06/2022 Submerged-1.50 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Dighaliati to Chaparmukh via Krishnanagar | Dighaliati | Date of Occurrence from 20/06/2022 Submerged- 2.5 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat -0.000000), Dighaliati to Bamunijan | Bamunijan | Date of Occurrence from- 20/06/2022 Submerged- 2 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Dighaliati to Loakhulabori | Laokhulabori | Date of Occurrence from- 20/06/2022 Submerged- 7 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NH 27 to West Kamgaon | Kamgaon | Date of Occurrence from 20/06/2022 Submerged-1.50 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Chaparmukh to Kachua | Kachua | Date of Occurrence from- 20/06/2022 Submerged-1 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Rupohitoli to Kahiguri via Ramjangati | Kahiguri | Date of Occurrence from 22/06/2022 Submerged-5 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Saragaon to Kahiguri | Saragaon | Date of Occurrence from 22/06/2022 Submerged-4 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Gandhibori to Tangunmara | Gandhibori | Date of Occurrence from- 22/06/2022 Submerged-2.4 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Ramjungati to Pashim Palashaguri | Ramjungati | Date of Occurrence from 22/06/2022 Submerged-1.5 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), L079- Pub Saragaon PHE to Pachim Katahguri | Pub Saragaon | Date of Occurrence from 22/06/2022 Submerged-1.42 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat -Dighaliati to Bamunijan | Bamunijan | Date of Occurrence from- 22/06/2022 Submerged-2 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), RBM road to Matharbori | Matharbori | Date of Occurrence from- 22/06/2022 Submerged-0.5 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NH-27 to Kahiguri | Kahiguri | Date of Occurrence from 22/06/2022 Submerged-4 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Rupahitoli Tiniali to Doloi Chuk | Rupahitoli | Date of Occurrence from 22/06/2022 Submerged-0.7 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Chaobori to Owarabat Joysree | Chaobori | Date of Occurrence from 22/06/2022 Submerged 2.5 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Chaobori to Beloguri | Chaobori | Date of Occurrence from 22/06/2022 Submerged-1 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NH-27 to Bhatigaon to Kollong Emankment | Bhatigaon | Date of Occurrence from 22/06/2022 Submerged-0.65 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat -0.000000), Raha Kampur Road to Atigaon | Raha | Date of Occurrence from- 22/06/2022 Submerged-0.64 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Chaparmukh Maruwaripati road | Chaparmukh | Date of Occurrence from 22/06/2022 Submerged-0.55 Km Department-Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000) Paschim Nalbari - B33 Road to Bangaon Jagara Mukalmua Road | Jagara | Damaged. Information 16 received from PWRD Department on 24/06/2022. | (Long - 0.000000, Lat - 0.000000), Nalbari Tihu - SHIV MANDIR TO CREMATION GROUND ROAD | WARD-6,TIHU TOWN |

		A PANCHET A COLUMN A LA PARA CATA DA PANCHA
		LENGTH:100MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000),
		TIHU-AKHARA ROAD WARD-6,TIHU TOWN LENGTH:135MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat -
		0.000000), ROAD NEAR LAKHSI MANDIR WARD-6 ,TIHU TOWN
		LENGTH:117MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF
		SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000),
		IN FRONT OF FRONT OF GAJEN TALUKDAR HOUSE TO KHALIHAGURI LINK ROAD WARD-6,TIHU TOWN LENGTH:120 MTS(APPROX),INFORMATION RECEIVED
		FROMJE,TMB DATE OF SUBMERGED:17/06/2022,CULVERT DAMAGED. (Long - 0.000000, Lat - 0.000000),
		GOPINATH MANDIR ROAD WARD-7,TIHU TOWN
		LENGTH:40MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000),
		LPS ROAD WARD-7,TIHU TOWN LENGTH:25MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000),
		BY LAND FROM FEEDER ROAD TO LT. JATIN GOSWAMI ROAD WARD-7,TIHU TOWN LENGTH:35MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF
		SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000),
		LINK ROAD FROM VETERINARY HOSPITAL ROAD WARD-8,TIHU TOWN LENGTH:260MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF
		SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000),
		BHADRAKUCHI ROAD WARD-8,TIHU TOWN
		LENGTH:230MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF
		SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000),
		LINK ROAD TO CP SCHOOL TO ASSAM OFFICE WARD-8 ,TIHU TOWN LENGTH:170MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF
		SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000),
		LINK ROAD FROM FEEDER ROAD TO AWC WARD-9 ,TIHU TOWN
		LENGTH:70MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF
		SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), SIV MANDIR SUPA ROAD WARD-9,TIHU TOWN
		LENGTH:80MTS(APPROX),INFORMATION RECEIVED FROMJE,TMB DATE OF
		SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000),
		Nalbari - Sondha to Barkura road surface damaged sondha as per the report of PWRD, Nalbari received on 23.06.2022 the above mentioned road is damaged due to flood (Long - 0.000000, Lat -
		0.000000), Sondha satra to Sondha dakshin suburi road damaged Sondha as per the report of PWRD, Nalbari
		received on 23.06.2022 the above mentioned road is damaged due to flood (Long - 0.000000, Lat - 0.000000),
		BBNG to SIRD Office Road SIRD as per the report of PWRD, Nalbari received on 23.06.2022 the above mentioned road is submerged due to flood (Long - 0.000000, Lat - 0.000000)
Total	168	
	168 Numbe	
Total District		Details
	Numbe	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat -
	Numbe	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m.This report
	Numbe	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000),
	Numbe	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat -
	Numbe	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000),
District	Numbe r	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 and 1/2 affected Dhaneswari Ali Road length 500m. This report is received from
	Numbe	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000),
District	Numbe r	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 and 1/2 affected Dhaneswari Ali Road length 500mThis report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), RCC Bridge no 1/1, 1/2, 1/3 and 2/1 damaged tihu dumni road bridge damagedThis report is
District	Numbe r	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 and 1/2 affected Dhaneswari Ali Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), RCC Bridge no 1/1, 1/2, 1/3 and 2/1 damaged tihu dumni road bridge damaged. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000),
District	Numbe r	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 and 1/2 affected Dhaneswari Ali Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), RCC Bridge no 1/1, 1/2, 1/3 and 2/1 damaged tihu dumni road bridge damaged. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000),
District	Numbe r	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 and 1/2 affected Dhaneswari Ali Road length 500m. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), RCC Bridge no 1/1, 1/2, 1/3 and 2/1 damaged tihu dumni road bridge damaged. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), RCC Bridge No. 2/1, 3/2, damaged Bamakhata Kenduguri Road bridge damaged. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), RCC Bridge No. 2/1, 3/2, damaged Bamakhata Kenduguri Road bridge damaged. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Long - 0.000000), RCC Bridge No. 2/1, 3/2, damaged Bamakhata Kenduguri Road bridge damaged. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Long - 0.000000), RCC Bridge No. 2/1, 3/2, damaged Bamakhata Kenduguri Road bridge damaged. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000), RCC Bridge No. 2/1, 3/2, damaged Bamakhata Kenduguri Road bridge damaged. This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000)
District	Numbe r	Details Bajali - SPT Br. 1/1 affected Balatary Bairagy Road affected length 25m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), Bhogeswari Mandir Approach affected patacharkuchi anchali road affected length 300m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 affected Mahabhairav Mandir Road length 500m.This report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), HPC No.1/1 and 1/2 affected Dhaneswari Ali Road length 500mThis report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), RCC Bridge no 1/1, 1/2, 1/3 and 2/1 damaged tihu dumni road bridge damagedThis report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000), RCC Bridge No. 2/1, 3/2, damaged Bamakhata Kenduguri Road bridge damaged.This report is

	Kokrajhar	The App of Culvert No. 3/2 damaged Choibari Manikpur Culvert damagedThis report is received from AEE,PWD,Patacharkuchi TR Sub Division,Pathsala on 23/06/2022. (Long - 0.000000, Lat - 0.000000) Bagribari - Timber Bridge No.2/1 KAZIGAON AS REPORTED BY EXE. ENG PWD DHUBRI CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 22.06.2022, BRIDGE NO 2/1 ON KAZIGAON BAZAR TO SANTIPUR UNDER BAGRIBARI RC WAS DAMAGED (Long - 89.992149, Lat - 26.195046), TIMBER BRIDGE NO.1/1 SILKYKATA AS REPORTED BY EXE. ENG PWD DHUBRI CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 22.06.2022, BRIDGE NO 1/1, 1/2 AND 1/3 ON SILKYKATA TO SUKANJHORA UNDER BAGRIBARI RC WAS DAMAGED (Long - 0.000000, Lat - 0.000000), TIMBER BRIDGE NO.2/2 BONGSHIJHORA AS REPORTED BY EXE. ENG PWD DHUBRI CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 22.06.2022, BRIDGE NO.2/2 ON BONGSHIJHORA TO HARJHORA UNDER BAGRIBARI RC WAS DAMAGED (Long - 89.981079, Lat - 26.257319), TIMBER BRIDGE NO.1/1 TOKRAJHORA AS REPORTED BY EXE. ENG PWD DHUBRI CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 22.06.2022, BRIDGE NO.1/1 ON ADT ROAD TO TOKRAJHORA MAWRIJHORA UNDER BAGRIBARI RC WAS DAMAGED (Long - 90.013160, Lat - 26.195674), SISTI RIVER BRIDGE SANTIPUR AS REPORTED BY EXE. ENG PWD DHUBRI CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 22.06.2022, BRIDGE OVER SISTI RIVER NEAR PUB SANTIPUR LPS UNDER BAGRIBARI RC WAS DAMAGED (Long - 0.000000), TIMBER BRIDGE NO. 4/1 BONGSHIJHORA AS REPORTED BY EXE. ENG PWD DHUBRI CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 22.06.2022, BRIDGE OVER SISTI RIVER NEAR PUB SANTIPUR LPS UNDER BAGRIBARI RC WAS DAMAGED (Long - 0.000000), TIMBER BRIDGE NO. 4/1 BONGSHIJHORA AS REPORTED BY EXE. ENG PWD DHUBRI CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 22.06.2022, BRIDGE OVER SISTI RIVER NEAR PUB SANTIPUR LPS UNDER BAGRIBARI RC WAS DAMAGED (Long - 0.000000), BRIDGE NO. 4/1 BONGSHIJHORA AS REPORTED BY EXE. ENG PWD DHUBRI CIVIL SUB DIVISION TERRITORIAL ROAD DIVISION ON 22.06.2022, BRIDGE NO.4/1, 4/2		
	Udalguri	AND 4/3 ON BONGSHIJHORA TO MONGLAHAT UNDER BAGRIBARI RC WAS DAMAGED (Long - 0.000000, Lat - 0.000000) Kalaigaon - RCC culvert on RK road to Kalaigaon Tengabari link road No 2 Kalaigaon RCC slab culvert has damaged 24/06/2022 resulting in breach of the road due to erosion caused by overflowing		
	_	of flood water from river Noa. Length: 15 meters, breadth: 4 meters (Long - 91.964453, Lat - 26.556291)		
Infrastructu	Total	Wildlife offerted under protected energy description		
re Damaged	District Morigaon	Wildlife affected under protected areas description Mayong - Pobitora WLS 11numbers of camps are inundated as reported by Range Officer PWLS on 24/06/22		
- Wildlife	District	Other Details		
	Bajali	Bajali - Fisheries/Pond No of fishery/ponds=1252, Total W/A= 107.9 Ha as on 24/06/2022, Sericulture Deptt. Damaged 60 Nos of som plant damaged. This report is received from superintendent of sericulture, Bajali, Pathsala, as on 24/06/2022		
	Baksa	Baska - Culvert Approach Road Damaged Dihira Post Office to Bhutankhuti LP School Connecting CC Block approach road to culvert damaged on 18/06/2022 at village Nikashi (Nalbari Supa) Coordinate: 26.74501, 91.373835, Culvert Approach Road Damaged Hume pipe culvert damage at Village (Dhalapara), Chaulkara, PO- Dihira, under Nikashi VCDC, on 18/6/2022, Lat: 26.750705 Long: 91.380129		
Infrastructu re Damaged - Others	Bongaigao n	Bongaigaon - Culvert Approach Road Damaged Naudiapara road, HP Culvert damaged at Ch. 45.00m. Log-90.519986 Lat- 26.4329 as per report received from PWRD, Bongaigaon date- 24.06.2022, Srijangram - Fisheries/Pond Total 8 nos Pond, Purbo Jopea 1 nos Pond Latitude-26.364852, Longitude-90.811263, Tupkarchar 2 nos Pond Latitude-26.350564, 26.350564Longitude-90.749223, 90.749223, Matraghola 4 no Latitude-26.37697,26.376956,26.378404,26.38056 Longitude-90.793699, 90.79378,90.792838,90.79765, Golapara Pt-I 1 no Pond Latitude 26.382212, Longitude-90.779825 reported by Fishery Department, Bongaigaon dated 24.06.2022		
	Darrang	Mangaldoi - PWSS Damaged as reported by PHE department PWSS are damaged/submerged of Bhurargarh Bagharbari, PWSS, No 1 Gerimari PWSS, Bar Athiabari PWSS, Bar Nagaon PWSS, Choto Nagaon PWSS, Kuyapani PWSS, Saikiapara PWSS, Saru Thekerabari PWSS, Bar Thekerabari PWSS, Dariapara PWSS, Prafulla Nagar PWSS, Gerimari PWSS, Gakhirkhowapara PWSS, Pakabangipara PWSS. Dated: 23-6-2022		
	Dhubri	Golakganj - Power Dept. Poles 8 NOS, Power Dept. Transformers 4 NOS, Agamoni - Bridge Approach Road Damaged APPROACHES OF HP CULVERT NO. 4/3 DAMAGED ON KHERBARI BAUSERKUTI ROAD dtd. 12/06/2022 to 18/06/2022, Bridge Approach Road Damaged BRIDGE APPROACHES OF RCC BR. NO. 6/1 & 7/1 DAMAGED ON KGT ROAD dtd. 12/06/2022 to 18/06/2022		
	Dima- Hasao	Haflong - Bamboo Foot Bridge Bridge at Digun Nalla fully damaged thereby causing trouble villagers of Tuicham village on 24/06/2022 as per report from Gaon Burah of Tuicham village, Road Breaches Road damaged at Dongenraji village, Umrangso by lane no 5 on 15/06/2022 as per information recieved from Umrangso Municipal board,		

Goalpara	Matia - Irrigation Canal/Scheme Damaged Islampur Point under Matia LIS, length of bricklined canal damaged = 32 m (as on 22/06/2022) as reported by Irrigation Department, Dudhnoi Goalpara East Division
Hojai	Hojai - Handloom & Textile Deptt 300 weavers are affected on dated 15th June to 20th june 2022 in village of Kenduguri, Dakhin kenduguri, Raikata, nabhanga, Pub nabhanga, taradubi, Kumurakta, Shibpur as reported by Superintendent of Handloom & Textile Department, Hojai Division., Handloom & Textile Deptt Name of SHG/PWCS Dengjali SHG Dakhin Komorakata, Harsringdi SHG Komorakata, Shibrai Kenduguri, Mazandi SHG Komorata, Pragadi SHG Nabhanga, Arati SHG komorakta, Khamaidi BKSS Ltd Komorakata on dated 15 /06/2022.i , Doboka - Power Dept. Poles 35 nos. of Poles damaged at the following villages :- Bheloguri, Bheloguri pathar, Block 48, Borjari gaon , Changjurai, Changmaji Gaon, Changmaji mikirgaon, Changmaji pathar, Charlock, Jamunamukh, Sarupathar, Bedoati, Baliram on dated 24/06/2022, Power Dept. Conductors Conductor = 5.5 km are damaged at the following villages :- Bheloguri, Bheloguri pathar, Block 48, Borjari gaon , Changjurai, Changmaji Gaon, Changmaji mikirgaon, Changmaji pathar, Charlock, Jamunamukh, Sarupathar, Bedoati, Baliram as on dtd. 24/06/2022, Power Dept. Transformers 11 nos. of DTR damaged at the following villages :- Bheloguri, Bheloguri pathar, Block 48, Borjari gaon , Changjurai, Changmaji Gaon, Changmaji mikirgaon, Changmaji pathar, Charlock, Jamunamukh, Sarupathar, Bedoati, Baliram as on dtd. 24/06/2022, Power Dept. Tonsdamar, Bedoati, Baliram as on dtd. 24/06/2022, Power Dept. Conductors 1.3 KM damaged on 17/06/2022, Power Dept. Poles LT poles 7 nos damaged on 17/06/2022, Elementary Schools Damaged SRI KAPILSWATR NATH LPS, SRI KAPILSWATR NATH LPS, HAJI FAJUR RAHMAN LPS, UTTAR FORMARPAR LPS, OKANTU NAZRUL LPS, DAKHIN LASKAR PATHER MEM, PASHIM LASKAR PATHER MEK, 1128 NO. LASKAR PATHER MUKTAB, UTTAR LASKAR PATHER CHAUHAN BASTI LPS, LASKAR PANCHALI MUKTAB, 2000 NO PANCHALI MUKTAB, SIV MANDIR NEW LPS, RASHTRABHASHA LPS, RASHTRABHASHA M.E.S., UTTAR BALUHANDAR LPS Submerged on 17/06/2022, Elementary Schools Damaged SIMLAI PATHER MEM, PASHIM DABLONG 2000 NO MUKTAB, DABLONG A
Kamrup	FORMARPAR PRADIP LPS, OKANTU NEW LPS Submerged on 18/06/2022 Kayan - Washed away Culverts 2 nos. at Borpulla, Bokultol on 16/06/2022. Reported by PWRD, Jalukbari & Hajo Territorial Road Division on 23/06/2022., Power Dept. Poles 2 nos. Reported by Rangia Electrical Sub-Division 2, APDCL, Rangia on 23/06/2022., Power Dept. Conductors 150 m. Reported by Rangia Electrical Sub-Division 2, APDCL, Rangia on 23/06/2022.
Karbi Anglong West	Donkamokam - Fisheries/Pond due flooded at several villages/ place 24 Hect. of Fisheries was Wash away as per report received from fishery Department on 20/06/2022, Protection Bundh Damaged Due to overtopped of Kopili River flood water Bilokso to Taradubi Market Dyke was affected at an approx. length of 25.00 Mtr (92.752315E & 26.019783N) as per report received from E.E, Water Resource Dept on 22/06/2022., Protection Bundh Damaged Due to overtopped of Kopili River flood water Taradubi Ring Bund/Embankment was affected at an approx. length of 2.2KM (92.7748588E & 26.036629N) as per report received from E.E, Water Resource Dept. on 22/06/2022.
Kokrajhar	Gossaigaon - Power Dept. Poles AS PER REPORT RECEIVED FROM SDE GOSSAIGAON ELECTRICAL SUB DIVISION APDCL ON 23.06.2022 DUE TO HEAVY RAINFALL LT POLE-12, HT POLE-10 DAMAGED DURING FLOOD TILL NOW, Power Dept. Conductors AS PER REPORT RECEIVED FROM SDE GOSSAIGAON ELECTRICAL SUB DIVISION APDCL ON 23.06.2022 DUE TO HEAVY RAINFALL LT CONDUCTOR-1.6, HT CONDUCTOR-6.1 DAMAGED DURING FLOOD TILL NOW, Power Dept. Transformers AS PER REPORT RECEIVED FROM SDE GOSSAIGAON ELECTRICAL SUB DIVISION APDCL ON 23.06.2022 DUE TO HEAVY RAINFALL 16KVK-0, 25KVA-4, 63KVA-2, 100KVK-0 DAMAGED DURING FLOOD TILL NOW, Bridge Approach Road Damaged AS PER L.M. REPORT DUE TO HEAVY RAINFALL FROM 14TH JUNE TO 17 TH JUNE, 2022 A Road damaged approach road to bridges (Approx 50M) at Karlingpur Village, Culvert Approach Road Damaged AS PER L.M. REPORT DUE TO HEAVY RAINFALL FROM 14TH JUNE TO 17 TH JUNE, 2022 A Road damaged approach road to Culvert (Approx 05M) at Karlingpur Village, Damaged RCC Bridge AS PER L.M. REPORT DUE TO HEAVY RAINFALL FROM 14TH JUNE TO 17 TH JUNE, 2022 A ROAD BAMAGED AT ANANDAPUR VILLAGE, Bridge Approach Road Damaged As per L.M. Report due to Heavy Rainfall from 14th June to 17th June from Gardenpur to No.2 Hatigarh, approach Road wooden bridge partially damaged at Pagla Rive at No.2 Hatigarh, Irrigation Canal/Scheme Damaged As per L.M. Report due to Heavy Rainfall from 14th June to 17th June Sub Canel damaged due to erosion at Dodere Sluice Gate at Thaigirguri, Culvert Approach Road Damaged As REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO INCESSANT HEAVY RAIN IMMEDIATE RESTORATION OF SRIRAMPUR TO SRIRAMPUR ROAD REPAIRING 4X4= 2 CELL RCC BOX CULVERT., Road Breaches AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO INCESSANT HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED

BALAGAON TO SRIRAMPUR ROAD WASHED OUT CROSSLY BREACHED REPLACE 3X3 = 2 CELL WITH ROAD REPAIR 1 KM,

Damaged RCC Bridge | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BRIDGE NO. 1/1 APPROACH KACHUGAON- SANKOSH PMGSY ROAD TO SURIBARI LP SCHOOL AT THE CH. 150.00M FOR THE YEAR 2022-23 (PART-II), Bridge Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BRIDGE NO. 1/1 APPROACH KACHUGAON - SANKOSH PMGSY ROAD TO SURIBARI LT SCHOOL AT THE CH 150.00 M FOR THE YEAR 2022-23.

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH JANALIGAON MEDICAL SUB- CENTRE & BAZAR ROAD AT THE CH. 300.00M FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH BANGTIJHORA MEDICAL SUB- CENTRE ROAD AT THE CH. 400.00 M FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH BANGTIJHORA MEDICAL SUB- CENTRE ROAD AT THE CH. 440.00 M FOR THE YEAR 2022-23, Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT NO.2 KUSUMBIL LP SCHOOL ROAD AT THE CH. 100.00M FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT NO.2 KUSUMBIL LP SCHOOL ROAD AT THE CH. 135.00M FOR THE YEAR 2022-23,

Bamboo Foot Bridge | As per L.M. report due to heavy rainfall from 14th june to 17th june A wooden bridge damaged at Chengmari Rabha Village near Jambguri High School Over Modati River,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH DAMAGED BALLAMJHORA RABHA BOSTI ROAD AT THE CH. 900.00M FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH DAMAGED BALLAMJHORA RABHA BOSTI ROAD AT THE CH. 950.00M FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH DAMAGED SRIRAMPUR ROAD AT THE CH. 400.00M FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH DAMAGED SRIRAMPUR ROAD AT THE CH. 440.00M FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED RCC BOX CULVERT 3X3=3 CELL JANALIGAON BAZAR ROAD AT THE CH. 100.00 M FOR THE YEAR 2022-23.,

Bridge Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BRIDGE NO. APPROACH DAMAGED KACHUGAON - SANKOSH ROAD FOR THE YEAR 2022-23,

Bridge Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BRIDGE NO. APPROACH DAMAGED KACHUGAON - SANKOSH ROAD FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH DAMAGED ALINAGAR M.E. SCHOOL ROAD AT THE CH. 90.00M FOR THE YEAR 2022-23,

Culvert Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB

DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BOX CULVERT APPROACH DAMAGED ALINAGAR M.E. SCHOOL ROAD AT THE CH. 110.00M FOR THE YEAR 2022-23,

Bridge Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BRIDGE NO. APPROACH DAMAGED GOSSAIGAON- SARIBIL TO BOSHABIL ROAD AT THE CH. 1100.00M FOR THE YEAR 2022-23, Bridge Approach Road Damaged | AS REPORT RECEIVED FROM AEE PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO INCESSANT HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD & FULLY WASHED OUT RCC BRIDGE NO. APPROACH DAMAGED GOSSAIGAON- SARIBIL TO BOSHABIL ROAD AT THE CH. 1150.00M FOR THE YEAR 2022-23, Bhawraguri - Handloom & Textile Deptt | AS REPORTED BY I/C SUPERINTENDENT HANDLOOM AND

Bhawraguri - Handloom & Textile Deptt | AS REPORTED BY I/C SUPERINTENDENT HANDLOOM AND TEXTILES, GOSSAIGAON ON 24/06/2022 DUE FLOOD OCCURRED DURING THE MONTH OF JUNE/2022 TOTAL 80 PIECES GOODS IN PROCESS/FINISHED GOODS WERE LOST.,

(**Kokrajhar**) **At District** - Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, MOJATI RAVAPARA FIS AFFLUX BUND L/S CH50.00M WAS DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, TAMADINGDINGA FLS MAIN CANAL IN 5 LOCATIONS APPROX. CH100M WAS DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, DULIDWISA FLS BOTH SIDE AFFLUX BUND CH50.00M AND GUIDE BUND CH20.00M WAS DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, RAJENDRAPUR FIS MAIN CANAL LINING CH10.00M WAS DAMAGED.

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, KUNTOLA FIS AFFLUX BUND L/S CH50.00M AND D/S GUIDE BUND CH25.00M WAS DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, HARAPUTA FIS LEFT BANK BRICK CANAL APPROX. CH100.00M WAS DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, BALAGAON FIS MAIN CANAL LINING CH450.00M WAS DAMAGED.

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, KHARKHARI FIS R/S AFFLUX BUND CH 25.00M WAS DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, BOROBADHA FIS OUTLET AND CANAL NO.5 WAS FULLY DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, LASKA FIS L/B AND R/B AFFLUX BUND AND GUIDE BUND WAS SEVERELY DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, PATAKATA FIS U/S AFFLUX BUND WAS DAMAGED, Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, MADHUTOLA FIS AFFLUX BUND WAS DAMAGED, Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, DODHERE FIS L/B AND R/B GUIDE BUND WAS DAMAGED, Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. GOSSAIGAON KOKRAJHAR WEST DIVISION IRRIGATION ON 20-06-2022, LONGA FIS L/B CANAL AT CH. 260M AND CH. 280M, BRANCH CANAL AT CH 285M APPROX. 18.00M, LEFT BANK CANAL EMBANKMENT, MAIN CANAL R/B AT CH 4600M CH 3800M WAS DAMAGED,

Bridge Approach Road Damaged | AS REPORTED BY ASSTT. EXE. ENG. PWRD KACHUGAON RR ON 21.06.2022, IMMEDIATE RESTORATION ON 11KM OF FS ROAD RO ROY BASTI ROAD (4 DOTMA ROAD) FORMATION EROSION & DAMAGED CULVERT NO. 1/1 & 1/2, WOODEN BRIDGE WAS DAMAGED,

Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXE. ENG. PWD GOSSAIGAON RR ON 22.06.2022, CULVERT HAS BEEN DAMAGED AT CH500M ON TIPKAI TO MONGLAJHORA ROAD VIA

Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXE. ENG. PWD GOSSAIGAON RR ON 22.06.2022, HPC CULVERT HAS BEEN DAMAGED ON MURSULUHARA PT-II TO LALMATI BAZAR ROAD WAS DAMAGED,

Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXE. ENG. PWD GOSSAIGAON RR ON 22.06.2022, HPC CULVERT HAS BEEN DAMAGED ON MURSULUHARA PT-II TO NOLPANI ROAD WAS DAMAGED,

	Culvert Approach Road Damaged AS REPORTED BY ASSTT. EXE. ENG. PWD GOSSAIGAON RR ON 22.06.2022, HPC CULVERT HAS BEEN DAMAGED ON MURSULUHARA PT-I TO BHALUKIHORA PWD ROAD WAS DAMAGED
	Morigaon - Fisheries/Pond As per Fishery Dev Officer (Mayong) dtd.23-06-2022, Water area affected by
	flood=0.66hect. Damage of embankment and overflow of water at Nellie.,
	Fisheries/Pond As per Fishery Dev Officer (Bhurbandha) dtd.21-06-2022, Water area affected by flood=4hect
	affecting 7 nos. of pond at 1 no Manipur., Mikirbheta - Washed away Culverts As reported by AEE, Batadrava Territorial Road Division, on 23-06-2022,
	RCC Box culvert at 57th km of SH-3 affected (At Tangunmara),
	Irrigation Canal/Scheme Damaged As reported by AEE, Batadrava Sub-division(Irrigation), on 24-06-2022, Pub
Morigaon	Bhakatgaon MDTW (Pt1) at Bamunbori is under flood,
8	Irrigation Canal/Scheme Damaged As reported by AEE, Batadrava Sub-division(Irrigation), on 24-06-2022,
	PMKSY- HKKP(Ph-1) scheme is under flood at Point No. 79,76,77, 78, 82, 88, 94, 87, 89, 91, 92, 84,
	Mayong - Fisheries/Pond Water Area affected 0.25hac, Total no of farmer affected 1 as reported by FDO,
	Mayong on 23/08/22,
	Irrigation Canal/Scheme Damaged Scheme Name - Chotabori PC 1,2,3 Main Canal and branch damaged by
	flood water on 23/06/22 as reported by AEE, Mayong,
	Irrigation Canal/Scheme Damaged Hatigarh LIS affected on 23/06/22 as reported by AEE, Mayong
	Kampur - Power Dept. Poles Total-51 nos. pole damaged under Kampur Rev. Circle reported by APDCL
	Kathiatoli Dtd-23.06.2022, Power Dept. Conductors Total-15 KM. conductor damaged under Kampur Rev. Circle reported by APDCL
	Kathiatoli Dtd-23.06.2022,
	Power Dept. Transformers Total-18 nos.DTR damaged under Kampur Rev. Circle reported by APDCL
	Kathiatoli Dtd-23.06.2022,
	Nagaon - Irrigation Canal/Scheme Damaged IIS from SRB & KRB Dakhinpat (Rt) ILP, Jagila Bebejia,
	Submerged/Damaged,main canal at chainage 5.00m wall got detached, main canal at 200.00 m chainage got
	detached wilth supporting earth breached, branch canal wall at chainage 20.m got detached reported by Raha
	Batadrava Division (irrigation) Dated-24/06/2022,
	Irrigation Canal/Scheme Damaged IIS from SRB & KRB Dakhinpat (Left) ILP, Jagial Bebejia,
	Submerged/damaged, Canals, pump, motor & transformer reported by Raha Batadrava Division (irrigation) Dated-
	24/06/2022,
	PWSS Damaged Deorigaon PWSS, Tulhidewuri,Submerged/damaged-Distribution pipeline, FHTC, reported by PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged Mohmoria PWSS, Dakarghat, Submerged/damaged-Distribution pipeline, FHTC, reported by
	PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged Lomati PWSS, Tulshideuri, Submerged/damaged-Distribution pipeline, FHTC, reported by
	PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged Kurabahi.Tulshideuri, Submerged/damaged-Distribution pipeline , FHTC, reported by PHE
	Nagaon Division, dated-23/06/2022,
	PWSS Damaged Madhupur PWSS, Dakargat, Tulshideuri, Submerged/damaged-Distribution pipeline, FHTC,
NT	reported by PHE Nagaon Division, dated-23/06/2022,
Nagaon	PWSS Damaged Dakhnpat Stara PWSS, Dakhinpat, Tulshideuri, Submerged/damaged-Distribution pipeline, FHTC, reported by PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged Borkola PWSS, Dakhinpat, Tulshideuri, Submerged/damaged-Distribution pipeline, FHTC,
	reported by PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged Ranthali PWSS, Deodhar, Tulshideuri, Submerged/damaged-Distribution pipeline, FHTC,
	reported by PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged Dr. B.R Ambedkar LPS, Tulshideuri ,Tulshideuri ,Submerged/damaged-Filter,
	Staging, Centrifugal Pump Distribution pipeline, FHTC, reported by PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged Jalahgaon PWSS, Deodhar, Submerged/damaged-Distribution pipeline, FHTC, reported by
	PHE Nagaon Division, dated-23/06/2022, PWSS Damaged Pahimoria PWSS, Pakhimoria, Submerged/damaged-Distribution pipeline, FHTC, reported by
	PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged 41 No. hatigarh LPS, Submerged/damaged-Filter unit, staging with distribution line,
	Centrifugal Pump reported by PHE Nagaon Division, dated-23/06/2022,
	PWSS Damaged Pachim Jalah LPS, Deodhar, Submerged/ damaged-Filter unit, staging with distribution line,
	Centrifugal Pump reported by PHE Nagaon Division, dated-23/06/202,
	PWSS Damaged Krishnaikhat LPS,Deodhar, Submerged/ damaged-Filter unit, staging with distribution line,
	Centrifugal Pump reported by PHE Nagaon Division, dated-23/06/202,
	PWSS Damaged Krishnaikhat LPS, Deodhar, Submerged / damaged-Filter unit, staging with distribution line,
	Centrifugal Pump reported by PHE Nagaon Division, dated-23/06/202, Paha Washed away SPT Bridge SPT bridge 1/1 washed away submitted by Paha Tarritorial Boad Sub
	Raha - Washed away SPT Bridge SPT bridge 1/1 washed away submitted by Raha Territorial Road Sub Division Dtd-23.06.2022,
	Washed away Culverts Dighaliati to Bamunijan HP Culvert washed away near Dighaliati Rail Gate submitted by
	Raha Territorial Road Sub Division Dtd-23.06.2022
NT II '	Banekuchi - Irrigation Canal/Scheme Damaged On 19/6/2022 report from Gaon Pradhan Kathalbari Rahuwa
Nalbari	Ban was damaged,

Paschim Nalbari - Handloom & Textile Deptt | 3 nos. of weavers family affected. Damage of loom accessories, weaven cloths etc. Information received from Handloom and Textile Department on 24/06/2022, Barbhag - Irrigation Canal/Scheme Damaged | Bargassa MDTWIS at Bargassa vill, Date : 23/06/2022, Irrigation Canal/Scheme Damaged | Uttarkuchi MDTWIS point No 1 at Uttarkuchi Vill, Date: 23/06/2022, Irrigation Canal/Scheme Damaged | Uttarkuchi MDTWIS Point No 2 at Uttarkuchi vill, Date: 23/06/2022, Irrigation Canal/Scheme Damaged | Barbukia DTWIS at Barbukia vill, Date: 23/06/2022, Irrigation Canal/Scheme Damaged | Kalag pathar MDTWIS at Kalag vill, Date: 23/06/2022, Irrigation Canal/Scheme Damaged | Ukhura pandula MDTWIS at Pandula vill, Date: 23/06/2022, Irrigation Canal/Scheme Damaged | Bijulighat ELIS at Ulabari vill, Date: 23/06/2022, Irrigation Canal/Scheme Damaged | Bijulighat DTWIS at Ulabori vill, Date: 23/06/2022, Tihu - Power Dept. Poles | 4NOS OF LT POLE DAMAGED UNDER BARAMA ELECTRICAL SUB-DIVISION .DATE OF SUBMERGED:17/06/2022.,INFORMATION RECEIVED FROM SDE,BARAMA.6NOS OF LT POLE & 2NOS OF HT POLE DAMAGED UNDER TIHU ELECTRICAL SUB-DIVISION .DATE OF SUBMERGED:17/06/2022., INFORMATION RECEIVED FROM SDE, TIHU, Power Dept. Transformers | 2 NOS (63 KVA&100KVA) OF TRANSFORMER DAMAGED UNDER BARAMA ELECTRICAL SUB-DIVISION .DATE OF SUBMERGED:17/06/2022,,INFORMATION RECEIVED FROM SDE,BARAMA., Power Dept. Conductors | 1.6 KM CONDUCTORS DAMAGED UNDER TIHU ELECTRICAL SUB-DIVISION .DATE OF SUBMERGED:17/06/2022.,INFORMATION RECEIVED FROM SDE,TIHU., Nalbari - Irrigation Canal/Scheme Damaged | as per the report received from Irrigation department, nalbari Haripur DTWIS scheme affected due to flood Date: 22/06/2022, Irrigation Canal/Scheme Damaged | as per the report received from Irrigation department, nalbari Balilesha ELIS (sondha point no2) scheme affected due to flood, Date: 22/06/2022, Irrigation Canal/Scheme Damaged | as per the report received from Irrigation department, nalbari Sondha paikarkuchi DTWIS scheme affected due to flood, Date: 22/06/2022, Handloom & Textile Deptt | As per the report received from Handloom & Textile, Nalbari 14 nos artisans are affected due to flood, Date: 22/06/2022 Thelamara - Culvert Approach Road Damaged | As reported by PWRD BARCHALLA TERRITORIAL ROAD SUB DIVISION, BARCHALLA on 19/06/2022, Patiapukhuri to Amguri PMGSY Road from CH 8350.00 M to 8500.00 M side berm, shoulder, hard crust, culvert approach of culvert no. 9/3 single rows of H.P and 9/4 triple rows of H.P washed away and fully damaged., Damaged RCC Bridge | As reported by PWRD BARCHALLA TERRITORIAL ROAD SUB DIVISION, BARCHALLA on 19/06/2022, Garuduba to Dhiraimajuli road via Belsiri(Both side bridge approach of RCC bridge no 4/1 and Guide bundh damaged., Culvert Approach Road Damaged | As reported by PWRD DHEKIAJULI TERRITORIAL ROAD SUB DIVISION, DHEKIAJULI on 19/06/2022, Dighaljuli river has damaged the both side approach of H.P Culvert Sonitpur no 1/1 on Dighaljuli to Rikamari Bengali PMSGY road (package no AS-22-149)at Dighaljuli Gaon, Damaged RCC Bridge | As reported by PWRD DHEKIAJULI TERRITORIAL ROAD SUB DIVISION, DHEKIAJULI on 19/06/2022, Surging water of Belsiri river has washed away the one side approach of RCC bridge no 2/1 on Dhekipelowa Belsiri T.E connecting NH-52., Washed away Culverts | As reported by PWRD BARCHALLA TERRITORIAL ROAD SUB DIVISION, BARCHALLA on 19/06/2022, H.P Culvert no 2/1 at ch. 1200.00 m has been washed away at Teliagaon to Garuduba road.. **Dhekiajuli** - Fisheries/Pond | As reported by Fishery dept Borsola, affected villages 2no Bosashimalu 11.70 ha. Dumdooma 5.33ha, Singimari Bangali 6.10ha, Borbhagia 3.60ha and Nichalamari 9.50ha, dated 24.6.22 South Salmara - Anganwadi Centres Affected | As per information received from concerned CDPO 72 no Tumnigaon AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long -89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 72 no Tumnigaon AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 73 no Boraikandi AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 74 no Dawakandi AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 75 no Bolakergaon AWWC South has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Salmara Anganwadi Centres Affected | As per information received from concerned CDPO 77 no Kawahagi AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 63 no Telipara AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 65 no Ponditpara AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 68 no Chalipara AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 87 no Patakata khapara AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected | As per information received from concerned CDPO 82 no Tumni Lawkhowa

		AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected As per information received from concerned CDPO 783 no Fershertary AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected As per information received from concerned CDPO 91 no soto Patakata AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected As per information received from concerned CDPO 104 no Simlakandi AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected As per information received from concerned CDPO 127 no M Maderchar AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected As per information received from concerned CDPO 130 no tanergaon AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected As per information received from concerned CDPO 50 no dhenarkuti AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected As per information received from concerned CDPO 124 no Telipara AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945', Anganwadi Centres Affected As per information received from concerned CDPO 124 no Telipara AWWC has been damage due to flood water as on 22 /6/22 area 0B-1K-5L. Lat - 25.863451' Long - 89.989945'
		Khairabari - Irrigation Canal/Scheme Damaged Udmari FIS U/S canal embankment breached at several chainage. Village: Udmari. Length: 10M (approx.) GPS Coordinated: Lat-26.64388 Long- 91.8577 Date. 22.06.2022, Irrigation Canal/Scheme Damaged Mahaliapara FIS erosion at D/S of headwork. Village: Bogpuri. Length: 8 M (approx.). GPS Coordinates: Lat- 26.62406 Long- 91.8484. Date- 22.06.2022, Irrigation Canal/Scheme Damaged Harharia FIS at Dongpara Mail canal embankment at Ch. 172m breached at both side for 10M (approx.). Village: Dongpara. GPS Coordinates: Lat- 26.6624366 Long- 91.785243. Date: 22.06.2022,
	Udalguri	Fisheries/Pond As per reported by the department approx. 185 fish farmers were affected and approx. 27.8 Ha. of water areas was affected in some villages namely, Khagra Gaon, Jamuguri, Mohilapara, Singimari, Borjamuguri, Khoirabari, Chinakona, Kuhiarkuchi, Jhargaon, Bar-Tangla, Harchapara & Jagarnnathjhar, Harisinga - Irrigation Canal/Scheme Damaged 1.FIS from Kulshi river at Palahgarh L/S D/S toe wall 50m breached & river embankment 70m breached, R/S D/S toe wall 20m breached & river embankment 20m breached, boulder protection completly damaged on 17/06/2022. Lat-26.6776 Long-91.9420. (2) Pub Babarikhat FIS R/S D/S boulder protection breached about 30m. Lat- 26.6633 Long-91.8650 on 17/06/2022, Power Dept. Conductors Conductors were snapped at various places like Villages Naobandha, atterikhat, Rajagarh, Nonke sukla, Rajagarh, garuajhar, no2 Garuajhar, Bengbari, Sastrapara, amlaiguri, Burhaguhaithan, Barbari, Pothar, Batiamari, Bhutiajhar, Bongurum, dakhin gejerkuchi, Dharamjuli Junglle, Dimakuchi gaon, Ghewnala, Kachubil, Nepaligaon, Khasiachuba, Letpetkhat, Majuli TE on 23/06/2022 under Tangla
		electrical sub-division, Power Dept. Poles one double pole structure containing underground railway crossing cables and 11kv Dolongghat feeder uprooted at Tangla Town the three pole structure due to loose soil also get damaged due to uprooting three pole structure. on 24/06/2022, Udalguri - Fisheries/Pond As per report by Fishery Department on 24-06-2022, 23 nos. of villages namely Sastrapara, Borigaon, Duamakha, Bornagaon, Tamulbari, Sapkhaity, Ambagaon, Bhairaguri, Dhupguri, Lowdang, Ranipukhuri, Bhutinidoba, Medhipara, Dewrigaon, Aithengjhar, No. 01 Jhargaon, Rangagora, No. 1 Moudubi, Pub Beghapara, Mohanpur, Ekrabari, Aminpara, kajiamati constituting approximately 249 farmers and 32.45 ha. of water bodies are affected.
	District	Details
	Baksa	Baska - Bhogpara, 1 No. Bhogpara Gully erosion at Jorthan Dong and 2 Fishery pond at village Bhogpara on 18/06/2022, Gully erosion at 1 No Bhogpara near Garga Das house (26.68656, 91.335608), Gully erosion at 1 No Bhogpara near Uday Daimary house (26.691553, 91.337569), Gully erosion at 1 No Bhogpara near Dhaneswar Gayari house (26.692664, 91.344363). Date: 18/06/2022 0
Erosion	Biswanath	Biswanath - Rowmari Severe bank erosion Observed at Rowmari area on R/Bank of river Buroi. Length-1000.00m on 24-06-2022 0, Halem - 1. 1 No. Hatijan, 2.Paken 1.As reported by Conerned Lot Mandal, continuous erosion was observed on the L/B of river Brahmaputra from 23/06/2022. Approximate lenght 800m Latitude-26.790692 and Longitude-93.529579. 2. Mild bank erosion observed at Paken area on R/Bank of river Brahmaputra of length-1400m. Latitude-26.4800 N, Longitude-93.3751 E to Latitude-26.4754N, Longitude-93.3730E. on 24-06-2022 0
	Bongaigao n	Manikpur - 3 no nachankuri & Bashbari no 2 Erosion took place in 3 no nachankuri (26.470307, 90.685756) due to river Aie arround 30 mtr.Date-24.06.2022/Erosion Took Place in Bashbari no 2 due to river Aie on Dated-24.06.2022 approx 50 mtr. erode away. 4 Nos of Relief Camp (1).Nagarjhar (Temp.Shelter), (Latitude-26.457903 Longitude-90.753059) (2)Tilpukhuri ME School, (Latitude-26.399571 Longitude-90.753438) (3) 3 No Bashbari LP School, (Latitude-26.426476 Longitude-90.759589) & (4) 2 No Bashbari (Temp Shelter) (Latitude-26.416661 Longitude-90.760288), Inmates in Relief Camps Male-564, Female-502, Children-292, Pregnant/Lactating Mother-3 & Person with Disability-1, Animal Affected-319, Big-285, Small 34. Relief Distribution- Rice (in Q)-34.00, Dal (in Q)6.00, Salt (in Q)-1.80, M.Oil (in L)-180.00-Cattle Feed Wheat Bran (in Q)-26.16. 2100
	Chirang	Bijni - Malipara, No-3 Chikajhora As reported by LM, ongoing erosion of agriculture land at Malipara village due to rain water flowing. Length=12 mtr(approx) Breadth=1.5 mtr(approx) Depth=1.06 mtr(approx). Longitude=90.611911 Latitude=26.575146 Date of occurrence=23-06-2022. As reported by LM, Erosion occurred on 16-06-2022 at No 3 Chikajhora village due to Chika river. Length=402.12 mtr(approx)

		Breadth=159.38 mtr(approx) Depth=1.35 mtr(approx) Longitude=90.753858 Latitude=26.608953. 0
	Darrang	Dalgaon - 1/2 Baruajhar, No.3 Thekerabari,Nadirkash, BarghuliNadirpar as per report received from LM on 24-06-2022 erosion occurred at villages 1/2 Baruajhar, No.3 Thekerabari,Nadirkash, Barghuli and Nadirpar. land about- 18 bigha 4 katha 12 lessa land eroded 0
	Dibrugarh	Tingkhong - 2 no. Rangsuwal village As per report by WRD on 24-06-22 river Disam had eroded 70m(approx.) of distance. Lat:-27.301615, Long:-95.143833 0, Chabua - Gereki & Gereki Nepali Information receiver from WRD 50 m length has been eroded by river Brahmaputra on 24/6/2022. Relief Distribution Centre-2 Nos. 1) Gereki 2) Gereki Nepali GR distributed to 12 nos. of families-RICE-140. 4Kg, DAL-24Kg, SALT-7. 2 Kg. 40
	Golaghat	Dergaon - Ikorani Gaon Damage occurred by river water of Gelabeel River at Ikorani area as reported by Executive Engineer, Jorhat W.R. Division on 24.06.2022 0
	Hailakand i	Lala - Kalacherra Gudamghat road under Lala Rev Circle. Date- 21/06/22 Submerged PWD road 2000
	Kamrup	North Ghy - 1. Satgaon (Howrapar), 2North Guwahati Town(Aswaklanta) 1. Severe bank erosion at Howrapar, Satgaon area of River Barnadi, Lenght about= 400 mtr 2. Bank erosion near Aswaklanta Mandir, North Guwahati Town of River Brahmaputra, length about=220 mtr as reported by Asstt. Executive Engineer, Ghy. East WR Div. erosion observed on 22/06/2022 0
	Kokrajhar	(Kokrajhar) At District - KOMOLACHARA KOTPATA HAKMABIL KHOKSHAGURI ASARIKANDI ARAISOPARA TAZPUR GHORAMARA MOGORMARI AS REPORTED BY EXECUTIVE ENGINEER KOKRAJHAR WR DIVISION ON 24.06.2022, 1. BANK EROSION OBSERVED AT VILLAGES KOMOLACHORA PT-II(CHECHAPANI) (REACH LENGTH-700M), HEKAIPARA(REACH LENGTH-300M) ON R/B OF RIVER GAURANG 2. BANK EROSION OBSERVED AT VILLAGES KOTPARA (REACH LENGTH-400M) ON R/B, RIMIJHIMIGHOP(REACH LENGTH-400M), KHEJURBARI(REACH LENGTH-500M), EAST SARAGAON ON L/B OF RIVER GANGIA 3. BANK EROSION OBSERVED AT VILLAGES EAST HAKMABIL (REACH LENGTH-300M), RAMFALBIL (REACH LENGTH-200M), WEST SIMLAGURI, NAORBHITA, GONGAR JAOFLONG OF RIVER LONGA 4. BANK EROSION OBSERVED AT VILLAGES KHOKSHAGURI NO.2 (REACH LENGTH-500M), SIMLABARI(REACH LENGTH-550M) ON L/B OF RIVER SONKOSH 5. BANK EROSION OBSERVED AT VILLAGES ASARIKANDI(REACH LENGTH-400M), PANIJANI GHOP ON L/B OF RIVER JOYMA 6. BANK EROSION OBSERVED AT VILLAGES ARAISOPARA(REACH LENGTH-300M) ON R/B OF RIVER MALBHOG 7. BANK EROSION OBSERVED AT VILLAGES TAZPUR (REACH LENGTH-250M) ON R/B OF RIVER MODATI 8. BANK EROSION OBSERVED AT VILLAGES GHORAMARA (REACH LENGTH-300M) ON R/B OF RIVER MODATI 8. BANK EROSION OBSERVED AT VILLAGES GHORAMARA (REACH LENGTH-300M) ON R/B OF RIVER MODATI 8. BANK EROSION OBSERVED AT VILLAGES GHORAMARA (REACH LENGTH-300M) ON R/B OF RIVER MODATI 8. BANK EROSION OBSERVED AT VILLAGES GHORAMARA (REACH LENGTH-300M) ON R/B OF RIVER MODATI 8. BANK EROSION OBSERVED AT VILLAGES GHORAMARA (REACH LENGTH-300M) ON R/B OF RIVER MODATI 8. BANK EROSION OBSERVED AT VILLAGES GHORAMARA (REACH LENGTH-300M) ON R/B OF RIVER LENGTH-300M) ON R/B OF RIVER SARALBHANGA 0
	Lakhimpu r	North Lakhimpur - Borbil As per report received North Lakhimur Water Resource Department on 22/06/2022,continuously erosion bank migration for each about 500m at Borbil (In between Ch 1500 m to 2500 m) of Ronaganodi Left Bank embankment . 0
	Majuli	Ujani Majuli - Kamjan Alengi Erosion occurred at Kamjan Alengi on 22/06/2022. Total 9 nos. of families have been shifted to a nearest chapori area on 23/06/2022. 30
	Morigaon	Bhuragaon - Lengribori Lengeribori revenue village affected due to erosion by Brahmaputra river from 20-06-2022 to 24-06-2022 72, Laharighat - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori As per report received from the Water Resources dept on 24-06-2022 , erosion is observed in places like Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori with maximum erosion of 0 m in Leruamukh, 1 m in Goroimari ,2 m in Bhajaikhati gaon & 5 m in Barchapori 0
	Nalbari	Barkhetri - LARKUCHI, 1 No Paschim Kurihamari Rajiv Gandhi LP school EROSION ON B/DYKE ON R/B OF RIVER BRAHMAPUTRA AT LARKUCHI, LENGTH 500M AS REPORTED BY aee, wrd, mUKALMUA on 23/06/2022, as reported by School headmaster 1 No Paschim Kurihamari Rajiv Gandhi LP school on 23/06/2022 0
	Udalguri	Harisinga - 1.Mantikiri, 2.Kathalguri, 3. Jalah 4. Majuli Gaon 5. Bhootbangla the embankment situated at L/B of the river Bhorla at Mantigiri village eroded around 250ft. on 17/06/2022. Lat-26.7226 Long-91.9793. (2) erosion occurred at Kathalguri village on both side of the river Bhorla, around 200/20ft eroded on 23-06-2022. lat-26.7257 long-91.9840 (3)Erosion occurred at the house of Hemchandra Deka due to overflow of river Kulshi around 200ft. Lat-26.6519 long-91.9372 on 23/06/2022. (4)Erosion occurred on both side of the river Bhorla at majuligaon on 18/-6/2022. around 300ft. Lat-26.8347 Long- 91.9462. (5)continuous erosion occurred at Bhootbangla on left bank of the river Nonoi on 20/06/2022 around 500ft. immediate measures needed as soon as possible. Lat-26.4011 Long-91.5359. 0
	District	Details
Landslide	Hailakand i	Hailakandi - Bondukmara Outpost under Hailakandi Revenue Circle on 20.062022 Landslide Near Bondukmara outpost 0
	District	Details
		Silchar - Linkroad, National Highway road point, Ambicapatty, Church Road, Chandicharan Road, Bilpar, Public
Urban Flood	Cachar	School Road, Subhas Nagar, Sonai Road, N.S. Avenue, Premtala, Chengkuri Rood, Malugram, Kanakpur, Tarapur Chandmari, Itkhola, Ghoniala, Meherpur, Public School Road Due to incessant rainfall the closure of sluice gates and over-topping of Embankments in many areas in and around Silchar Town dated 24.06.2022 35000

Karimganj	RK Nagar - Ward No. 1,2,3,4,6,7 TOTAL 306 Nos families affected from date 18.06.2022 to 24.06.2022 1560
Marianan	Morigaon - RAJAGAON (NABHETI, WARD NO 9) On dtd. 21-06-2022, as per Lot Mondol overflow of
Morigaon	floodwater has reached Nabheti Ward no 9 of Morigaon Revenue Town. 1320