


FRIMS Assam





	Assam Daily Flood Report as on 13-07-2022 at 4:00 PM											
Particulars	Situation as on 13-07-2022 (in last 24 hours)											
Rivers flowing above Danger	Rivers flowing above danger level							Nil				
Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above highest flood level							Nil				
District	No. of Districts Affected	Name of	Flood Aff	ected Distric								
Affected	7			ima-Hasao, C Tamulpur	Golaghat,							
No. Of Revenue Circles Affected	10	Morigaon, Nagaon, Tamulpur										
1	District Total Revenue Circle											
1	Cachar	3		h, Lakhipur,	Silchar				·			
1	Chirang	1	Bijni									
Name Of Revenue	Dima- Hasao	1	Haflong									
Circles	Golaghat	1	Bokakhat									
Affected	Morigaon	1	Morigaon									
l	Nagaon	2	Kampur, Raha									
l	Tamulpur	1	Goreswar									
	Total	10										
l	District	Total										
l	Cachar	72	(Katigorah 50), (Lakhipur 11), (Silchar 11) (Bijni 1)									
l	Chirang Darrang	87		ghat 87)								
l	Darrang Dima-											
l	Hasao	5	(Haflong 5)									
Villages	Golaghat	8	(Bokakhat 8)									
Affected	Kamrup	18	(Kayan 18)									
l	Morigaon	117	(Morigaon 117)									
l	Nagaon	8	(Raha 8)									
1	Nalbari	32	(Ghograpar 30), (Barkhetri 2)									
1	Tamulpur	1	(Goreswar 1)									
	Total	349			I m					I		
	District	Male	Femal e	Children	Total Populatio n	-	Population Details		Crop Area (in Hect.)	Crop Area Details		
Population	Cachar	56178	51506	39888	147572	(Katigorah 48234), (Lakhipur 1085), (Silchar 98253)		0.00	(Katigorah 0.00), (Lakhipur 0.00), (Silchar 0.00)			
And Crop Area Affected	Chirang	65	55	33	153	(Bijni 1			0.00	(Bijni 0.00)		
	Golaghat	0	0	0	0	(Bokakh			10.00	(Bokakhat 10.00)		
	Morigaon	42127	41078	17859	101064		(Morigaon 101064)		550.00	(Morigaon 550.00)		
İ	Nagaon	303	116	38	457	457)			91.40	(Kampur 0.00), (Raha 91.40)		
1	Tamulpur	545	402	105	1052	(Goresw	(Goreswar 1052)		0.00	(Goreswar 0.00)		
	Total	99218	93157	57923	250298	_			651.40			
Relief	District	Total	Relief C									
Camps /	Cachar	45	45(Katigorah 20, Lakhipur 1, Silchar 24) 0(Katigorah 0, Lakhipur 0, Silchar 0)					0, Silchar 0)				
Centres	C1 :	1 1	1(Bijni 1) 0(Bijni 0) 17(Haflong 17) 5(Haflong 5)									
Opened	Chirang Dima-	22						5(Haflong	<u>~</u>			

Marigon S		Hasao										
		Morigaon	8	8(Morigaon 8)				0(Morigaon 0)				
Minimate In Record Section S		Total	76					5				
Manach Relief Campa		District	Total	Revenue	e Circlewise		Male	Female	Children	Lactating	with Disabilit	
Campa		Cachar	15117				6714	5670	2733	0		
Dimase		Chirang	153				65	55	33	0	0	
Human Confirment Final Marie Final Marie Final Marie Final Marie	•		1104	(Haflans	- 1104)		205	116	224	20	1	
Total Total Total Male Female Children Revenue Crebes Revenue Crebes Total												
Nagaon 1				(Morigae	on 640)							
Note	Human	District	Total	Male	Female	Children	Revenue Ci	rclewise	l .			
		Nagaon	1	1	0	0	(Kampur 1), (Raha 0)				
Part	Confirmed	Total	1	1	0	0						
Total 1	Lives Lost Confirmed -	District Total Flood Drownin g (Non Flood) Landslide										
Human Lives Lost - Missing Human Lives Lives Lives Lives Lost - Missing Human Lives Live	Death Type				-							
Nil	Цитан	Total	1	1	0	U						
Type	Lives Lost - Missing Human Lives Lost	<u> </u>										
Morigaon 71839 26332 14611 30896 3	_											
Affected Animals Washed Away Nil	Animals					•						
Animals Washed Away	Affected											
Houses Damaged Hous	Washed											
Mouse Damaged Mamrup 0 0 0 0 142 0 142 0 0 88 88 88 Morigaon 0 0 0 0 1100 0 0 0 0			Kuccha	Pukka	Total	Kuccha	Pukka	Total	Huts	Cattle Shed	Total	
Morigaon Nagaon 192 O 192 4781 76 4857 468 780 1248 Nalbari O O O 195 O 195 O 195 Total 203 O 203 7879 86 7965 473 1285 1758 Total 203 O 203 7879 86 7965 473 1285 1758 Total Agency	Houses											
Nagaon 192 0 192 4781 76 4857 468 780 1248 176 180 195 1 2 3 3 1 1 1 1 1 1 1 1	Damaged											
Nalbari O O O O O O O O O					-							
Total 203 0 203 7879 86 7965 473 1285 1758												
Person P					-				473	1285	-	
Circle Office/Local Administration, Local People, Police, Water Resources Department						Deployed	Evacuate d By Boats	Evacuate d By Boats	s Deployed	Evacuated By Helicopter s	Team Deploye	
Dima- Administration, Local People, Police, Water Resources Department		Chirang				0	0	0	0	0	1	
Nagaon Total Total Total Total Nagaon Nagao		Hasao	Administr Police, W	ration, Loc ater Resou								
Relief District Rice (in Q) Dal (in Q) Cattle Feed - Green Fooder (in Q) Cachar Cachar Binar (in Q) Cachar												
Relief Distributed Cachar Dima-Hasao 6.00 0.54 0.16 16.29 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00							_					
Cachar 6.00 0.54 0.16 16.29 0.00 0.00 0.00 Dima- Hasao 50.61 4.82 2.33 252.00 0.00 0.00 0.00						M. Oil (in	Cattle Feed - Green Fooder	Cattle Feed - Wheat Bran (in				
Hasao 50.61 4.82 2.33 252.00 0.00 0.00 0.00	Distributed		6.00	0.54	0.16	16.29	0.00		0.00			
Total 56.61 5.36 2.49 268.29 0.00 0.00 0.00			50.61	4.82	2.33	252.00	0.00	0.00	0.00			
		Total	56.61	5.36	2.49	268.29	0.00	0.00	0.00			

<u> </u>				T					
D I' C	Instrict		Baby Food Baby Food Solid		Others				
Relief Distributed	Cachar	Liquid 0.00-Q		0.00-Q	CANDEL-60.00-Pkt				
Others	Dima-				CANVEL-00.00-FKI				
Culcis	Hasao	0.00-Q		0.00-Q Onion-252.00-Kg					
Infrastructur		1							
e Damaged									
-	Nil								
Embankme									
nt Breached									
	District	Numbe r	Details						
Infrastructur		-	Patherk	andi - Mantrigram Left Ba	ank Mantrigram AEE, Water Resource, Patharkandi reported that				
e Damaged				_	down occurred at left bank of river lonagai at mantrigram (Long -				
-	Karimganj	2		03, Lat - 24.593836),					
Embankme	Kurmigung				AEE, Water Resource, Patharkandi reported that on 05/07/22 due				
nt Affected					at left bank of river lonagai at Pecharghat. (Long - 92.326433, Lat				
	Total	2	- 24.480	8/0)					
		Numbe							
	District	r	Details						
	Darrang	1	Patharighat - Bordulguri Deomornoi Road Deomornoi Road submerged and affected as re						
	Darrang	1			22 at 3.37 p.m (Long - 91.928164, Lat - 26.410416)				
					o Dikhari Kinar Saragfala Road Dikhari Kinar Saragfala As per				
			report of PWD Moran Territorial Road sub- division as on 12/07/2022 due to continuous heavy						
			rainfall Senchowa Naharoni Ali to Dikhari Kinar Saragfala road have shown post flood damages to the newly constructed road. Length affected- 0.150 km, Date of occurance- 29/06/2022. (Long -						
			94.806394, Lat - 27.230758),						
			Tingkhong - Salmari TE to Tinthegia Gaon Road As per reported from PWRD on 12-07-22 due to						
			recent heavy and continuous rain the above road is badly affected for which the road surface are						
			damaged and side berms has been eroded, Revenue Village: No 4 Salmari, Total Length of road-						
					n,Date of occurence-7/1/2022 (Long - 95.102710, Lat -				
			27.270261), MN Road to Basha Gaon As per reported from PWRD on 12-07-22 due to recent heavy and						
			continuous rain the above road is badly affected for which the road surface are damaged and side						
			berms has been eroded,Revenue Village:No 1 Puwalipather,Total Length of road-2.50km,Approx						
			Length Damaged:1.50km,Date of occurence-7/1/2022 (Long - 95.184780, Lat - 27.199707),						
			Kadamoni ME school to OCS No 1 As per reported from PWRD on 12-07-22 due to recent heavy						
			and continuous rain the above road is badly affected for which the road surface are damaged and side						
			berms has been eroded,Revenue Village:No 2 Tipomia Dighalia,Total Length of road-3.30km,Approx Length Damaged:2km,Date of occurence-7/1/2022 (Long - 95.145626, Lat - 27.268002),						
					alia As per reported from PWRD on 12-07-22 due to recent heavy				
Infrastructur					is badly affected for which the road surface are damaged and side				
e Damaged	Dibrugarh		berms has been eroded,Revenue Village:No 2 Saguneswa,Total Length of road-1km,Approx Length						
- Road			Damaged:1km,Date of occurence-7/1/2022 (Long - 95.131903, Lat - 27.247581),						
		23	Nilmoni Dhuwapather Road to Baghmora ME, khanikar Gaon As per reported from PWRD on 12-						
			07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Baghmora, Total Length of						
			road-2km, Approx Length Damaged:1km, Date of occurence-7/1/2022 (Long - 95.154541, Lat -						
			27.174035),						
					rezing Field As per reported from PWRD on 12-07-22 due to				
					ne above road is badly affected for which the road surface are eroded, Revenue Village: No 2 Chapatoli, Total Length of road-				
			_		* * *				
			1km,Approx Length Damaged:1km,Date of occurence-7/1/2022 (Long - 95.153910, Lat - 27.159285),						
					P School As per reported from PWRD on 12-07-22 due to recent				
					ve road is badly affected for which the road surface are damaged				
					evenue Village:Longboi Nahula,Total Length of road-1km,Approx				
					urence-7/7/2022 (Long - 95.172520, Lat - 27.190338),				
					per reported from PWRD on 12-07-22 due to recent heavy and adly affected for which the road surface are damaged and side				
					illage:no 2 Sapkait,Total Length of road-2km,Approx Length				
					7/7/2022 (Long - 95.151721, Lat - 27.201712),				
			Nilmoni	Road to Ukhabam to Majl	ni Chuk As per reported from PWRD on 12-07-22 due to recent				
					ve road is badly affected for which the road surface are damaged				
			and side berms has been eroded,Revenue Village:Majgaon,Total Length of road-3km,Approx Length Damaged:3km,Date of occurence-7/7/2022 (Long - 95.147599, Lat - 27.175537),						
			Noronga	un bagan to 16 no line, Raj	garh TE As per reported from PWRD on 12-07-22 due to recent				

heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Karangoni 18, Total Length of road-2km, Approx Length Damaged: 1.70km, Date of occurence-7/7/2022 | | (Long - 95.126225, Lat - 27.187411), GHANHI PWD ROAD TO MAHMORA PWD ROAD (VIA MAHMORA KAPOHUWA & SIMALUGURI VILLAGE) | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Mahmora Kapahua, Total Length of road-3.50km, Approx Length Damaged: 3.50km, Date of occurence-7/7/2022 | | (Long - 95.192876, Lat - 27.187387), MAHMORA KAPAHUWA ROAD TO CHENI CHUK CONECTING ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Mahmora Kapahua, Total Length of road-0.50km, Approx Length Damaged: 0.50km, Date of occurence-7/7/2022 | | (Long - 95.192097, Lat - 27.187441), MAHMORA PWD TO THULAI PATHER CONECTING ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Thulai, Total Length of road-1km, Approx Length Damaged:1km, Date of occurence-7/7/2022 | | (Long - 95.235080, Lat -27.193990), GHANHI PWD TO DHANAH PATHER LINK ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Thulai, Total Length of road-0.50km, Approx Length Damaged: 0.50km, Date of occurence -8/7/2022 | | (Long - 95.216580, Lat -27.189420). DEROI CHUK NAMGHAR TINIALI TO SISUMORA PM TINIALI LINK ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village:Borkurukani, Total Length of road-1km, Approx Length Damaged:1km, Date of occurence-8/7/2022 | | (Long - 95.195593, Lat - 27.209459), SISUMORA PM ROAD TO NA CHAUDANG PWD CONECTING ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village:Borkurukani, Total Length of road-1.50km, Approx Length Damaged: 1.50km, Date of occurence-8/7/2022 | | (Long - 95.198127, Lat - 27.221961), KABULA PWD ROAD TO KABULA DISANG KENAR NAMGHAR TINIALI ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Kabula, Total Length of road-1.0km, Approx Length Damaged: 1.0km, Date of occurence-8/7/2022 | | (Long - 95.229988, Lat - 27.182133), KABULA DISANG KENAR NAMGHAR TINIALI TO BALIGHAT TINIALI CONECTING ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Kabula, Total Length of road-1.20km, Approx Length Damaged: 1.20km, Date of occurence-8/7/2022 | | (Long - 95.230682, Lat - 27.174530), MAHMORA PWD TO DORONGHI GHAT CONECTING ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Kabula, Total Length of road-1.50km, Approx Length Damaged: 1.50km, Date of occurence - 8/7/2022 | | (Long - 95.221539, Lat -27.175366), SISUMORA SUB-CHENTER TINIALI TO POTICHUK TINIALI CONECTING ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village:Sisumora BorpatherTotal Length of road-1.50km, Approx Length Damaged:1.50km, Date of occurence-8/7/2022 | | (Long - 95.215413, Lat - 27.201898), GHANHI PWD ROAD TO THULAI SRIPURIA MAHMORA PWD CONECTING ROAD | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: Thulai, Total Length of road-2.50km, Approx Length Damaged: 2.50km, Date of occurence-8/7/2022 | | (Long - 95.211892, Lat - 27.190285), Mahmora Road to Geleki Majali | As per reported from PWRD on 12-07-22 due to recent heavy and continuous rain the above road is badly affected for which the road surface are damaged and side berms has been eroded, Revenue Village: 2 No. Chapatoli, Total Length of road-2.0km, Approx Length Damaged: 2.0km, Date of occurence-1/7/2022 | | (Long - 95.156899, Lat - 27.153961) Hajo - Dadara Pacharia Road | Dadara | damaged on 19-06-2022 as reported by PWD (Roads), Hajo | (Long - 0.000000, Lat - 0.000000), Pacharia Barijani Road | Pacharia | damaged on 19-06-2022 as reported by PWD (Roads), Hajo | 5 Kamrup (Long - 0.000000, Lat - 0.000000), Pacharia HawraPar Byelane | Pacharia | damaged on 19-06-2022 as reported by PWD (Roads), Hajo | (Long - 0.000000, Lat - 0.000000), Pacharia Malong | Pacharia | damaged on 19-06-2022 as reported by PWD (Roads), Hajo | (Long-

		0.000000, Lat - 0.000000),
		Singimari Chowkigate Singimari damaged on 19-06-2022 as reported by PWD (Roads), Hajo
		(Long - 0.000000, Lat - 0.000000)
Infrastructur	Total	29
e Damaged - Bridge	Nil	
Infrastructur e Damaged - Wildlife	Nil	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	District	Other Details
	Golaghat	Bokakhat - Culvert Approach Road Damaged Flash water from higher side eroded severely on both side of culvert at.Ch. 480.00M of NH 37 to Bhakot Chapori Rd. Approx.length of erosion 80.00M on 11.07.2022
	Karbi Anglong	Silonijan - Culvert Approach Road Damaged Due to heavy rain on 12/07/2022 culverts no 5/1 on Koilamati to Phangcherop Road washed away under PWD Barpathar Road Div. Location: Balijan Village, Silonijan Revenue Circle, P.S:- Barpathar, Santipur. Lat:-26.347472 Long:-93.739117, Culvert Approach Road Damaged Due to heavy rain on 12/07/2022 culverts no2/1 on Koilamati to Phangcherop Road washed away under PWD Barpathar Road Div. Location: Samelangso Village, Silonijan Revenue Circle, P.S:- Barpathar, Santipur. Lat:-26.359217 Long:-93.756745
	Karbi Anglong West	Donkamokam - Elementary Schools Damaged During second wave of flood that occurred from 16th of june 2022 to 1st of July 2022, Nam Taradubi L.P. School was inundated which causes partial damaged to the school building and furniture. During visit Deputy Commissioner, west Karbi Anglong, and CEO, DDMA on 12th July
Infrastructur e Damaged - Others	Karimganj	2022 the damaged of the school building and furniture was noticed so reported in FRIMS accordingly Badarpur - PWSS Damaged On 12/07/2022, the Asstt. Executive Engineer, PHE, Badarpur Sub-Division, Badarpur submitted post flood damaged report where 55 nos. of PWSS got partially damaged., Patherkandi - PWSS Damaged AEE, PHE, Patherkandi submitted a report on 13/07/22 which state that the components (Pipelines, intake point arrangement, power supply etc.) of 09 nos. of PWSS haa been damaged on 19/06/22 due to flood. The name of PWSS are 1. MOINA PWSS, 2. ERALIGOOI PWSS, 3.BANDARKUNA PWSS, 4.BAROIGRAM PWSS, 5.DUHALIA III PWSS, 6. PATHARKANDI III PWSS, 7.JAMIRALA II PWSS, 8. BALIA PWSS, 9.KALKALIGHAT PWSS.
	Morigaon	Morigaon - Irrigation Canal/Scheme Damaged As per Asst Exec Engg(Irrigation), Morigaon Sub-division, dtd.12-07-2022, Severe erosion has been taking place on the right bank of river kollong in the downstream of RCC bridge at Damal area since 22-06-2022 and eroded the river side slope and a part of embankment near Charaihagi LIS leading to a breach like situation. At present the Pump House and the Transformer area in a vulnerable state and both may collapse at any time if protection work is not carried out immediately., Health Sub-Centre As per Jt. Director of Health Services, dtd.12-07-2022, Health institutes damaged due to flood at 1) Telahi HWC, 2) Thekeraguri SC, 3) Alisinga SC, 4) Matiparbat SC, 5) Damal HWC, 6) Bahakajari HWC, 7) Gunamara SC, 8) Uttar Mikirgaon SC, 9) Tengaguri SC, 10) Kanfala kaliajari SC, 11) Sikabori HWC
	District	Details
	Bongaigao n	Manikpur - Bashbari Part 2 Erosion of around 1300 mtr. had occurred w.ef 17/06/2022 to 30/06/2022.Two (2) Nos of Relief camp opened due to the said erosion (1) Tilpukhuri ME Madrasa "Male=179 Female=165 Child=124 Pregnant=1 Disability=1 Total=470(Latitude-26.39971 Longitude-90.753438) (2)3 no. Bashbari LP School, Male=86 Female=83 Child=77 Pregnant=2 Total=248(Latitude-26.426476 Longitude-90.759589) since 17.06.2022 to till date 01.07.2022/Total Inmates 718. Nachankuri no 3(Temp.Shelter) Male=41 Female=48 Child=73 Total=162(Latitude=26.458454 Longitude=90.662741). Medical Team-2 Nos. Date- 13.07.2022. 880, Srijangram - presently No erosion Due to earlier erosion 2 camps and 2 temporary shelters are still in operation. 1.Santoshpur Part II MV School (inmates 156) 2. Bhaduripara LPS (inmates:103)3. Dubachuri Part I Embankment (inmates:57) 4.Boroichala Temporary Shelter (inmates:110). Medical Team-3 Nos date- 13/07/2022 426
	Dhubri	Chapar - Dhirerchar Pt-I Erosion took place at Dhirerchar Pt-I village from 16-06- 2022 to 06-07-2022. Around 82B-2K-0L of agricultural land has been eroded so far. 0
Erosion	Kamrup	Hajo - Dighalijan Due to erosion by Puthimari river Dighalijan Sluice Gate was effected on 20-06-2022 as reported by Water Resource Ghy East Divsion 0
LIOSIOII	Lakhimpur	Kadam - Bodhakara Bodhakara Sonowal Gaon approximately eroded area 0.08 Hact. by the river Subansiri, informed by concerned GP and LM, dated 13/07/2022 0
	Majuli	Majuli - Kari Chapori Erosion occurred at Kari Chapori on 12.07.2022. Approximately 6 bigha plantation area eroded. 0
	Morigaon	Morigaon - Approach of the Culvert at 2nd KM of the road from Bhoiraguri to Alisinga via Durimari. as on 12/07/2022 As per PWD(Roads), Morigaon, Erosion occurred at approach of the Culvert at 2nd KM of the road from Bhoiraguri to Alisinga via Durimari. Thus, vehicular traffic movement perhaps be restricted for safety and security of road users and road infrastructure. Temporary restoration carried out by PWRD, Morigaon as 0, Mayong - Amlighat , Dabarghat, Dimaruguri Ring Bund, Sorukuloi Ring Bund Amlighat -150m length damaged lat:26.119N long: ,92.275E, Daburghat 450m length erosion lat: 26.628N long:92.16.29E, Dimaruguri Ring Bund at Jagibhakatgaon overtopping of the Dyke, Sorukuloi Ring Bund at Sotabori area nature: overtopping of the dyke. Report submitted by Water Resource Division as on 12/07/2022 0
	South Salmara	South Salmara - Khopati Pt-I As per report received from SDE Apdcl Mankachar 12 Nos of poles and 3 km conductor has been damage due erosion by the river Brahmaputra on date: 13-07-2022. Area Aprox lenth 3 km. 0

	Tinsukia	Doomdooma - Village: No. 2 Na-Barmura (Canopas) River Bank erosion is being observed at No. 2 Na-Barmura (Canopas)on the left Bank of River Brahmaputra since 03/07/2022 till 13/07/2022. As per information received from WR department officials the affected stretch is about 81 m in length. 0			
	District	Details			
Landslide	Karimganj	Karimganj - Vill Pathu, W/N - 08, .P.O Pathu due to heavy rain landslide Occurred at vill Pathu and			
		House of Karuna Moy Nath, ,S/O. Lt - Kokil Nath, was damaged partially on 18/06/2022. 5			
Urban	Nil				
Flood	INII				