

FRIMS Assam



Flood Reporting And Information Management System

			Accen	n Daily Flood Report as on 23-06-2022 at 4:00 P	M					
Particulars	G:44:	22 06 2			IVI					
Rivers	Situation as	on 23-06-2	2022 (in iasi	: 24 nours)						
flowing above Danger	Rivers flowi	ing above d	langer	Kopili (Dharamtul; Kampur), Disang (Nanglar	nuraghat), Brahmaputra (Dhubri)					
Level (as per CWC bulletin issued at 8 AM)	Rivers flowing flood level	ing above h	iighest	ghest Nil						
	No. of Districts Affected	Name of	Flood Affe	ected Districts	Name of Urban Flood Districts					
District Affected	30	Darrang, Golaghat Anglong	Dhemaji, D , Hailakand West, Kari	ta, Biswanath, Bongaigaon, Cachar, Chirang, Phubri, Dibrugarh, Dima-Hasao, Goalpara, i, Hojai, Kamrup, Kamrup (M), Karbi mganj, Lakhimpur, Majuli, Morigaon, Nagaon, buth Salmara, Tamulpur, Tinsukia, Udalguri	Cachar, Karimganj, Morigaon					
No. Of Revenue Circles Affected	103									
	District	Total	Revenue	Circle						
	Bajali	2	Sarupeta	, Bajali						
	Baksa	1	Barnagar	-						
	Barpeta	6		Baghbar, Chenga, Barnagar, Sarthebari, Kalgach	nia					
	Biswanath	1	Halem							
	Bongaigao n	3		Boitamari, Manikpur, Srijangram						
	Cachar	5	Katigoral	Katigorah, Silchar, Sonai, Lakhipur, Udharbond						
	Chirang	2	Bijni, Be							
	Darrang	4		oi, Sipajhar, Dalgaon, Patharighat						
	Dhemaji	3	•	nemaji, Sissiborgaon						
	Dhubri	7		a, Dhubri, South Salmara Part, Athani, Golakgan	ni Gaurinur Agamoni					
	Dibrugarh	2		Dibrugarh West	ij, Guaripur, rigunioni					
	Dima- Hasao	1	Haflong	Diorugum west						
	Goalpara	3	Matia L	akhipur, Balijana						
	Golaghat	2		t, Khumtai						
Name Of Revenue	Hailakand i	4		Hailakandi, Katlicherra, Lala						
Circles	Hojai	3	Hoiai Da	oboka, Lanka						
Affected	Kamrup	10		Palashbari, Hajo, Chaygaon, Nagarbera, Kayan, C	Chamaria, Goroimari, Kamalpur, North Ghy					
	Kamrup (M)	2		Chandrapur	,,,,,,					
	Karbi Anglong West	1	Donkamo	okam						
	Karimganj	5	Nilamba	zar, RK Nagar, Badarpur, Karimganj, Patherkano	li					
	Lakhimpu r	4		North Lakhimpur, Nowboicha, Kadam						
	Majuli	2	Majuli, U	Jjani Majuli						
	Morigaon	4		on, Morigaon, Mayong, Mikirbheta						
	Nagaon	6	•	Dhing, Kampur, Rupahi, Raha, Samaguri						
	Nalbari	6		ar, Paschim Nalbari, Barbhag, Tihu, Barkhetri, N	Jalbari					
	Sonitpur	3	Ų i	ra, Dhekiajuli, Tezpur	· 					
	South Salmara	2		ar, South Salmara						
	Tamulpur	2	Goreswa	r, Tamulpur						
L	P 4			, T						

	Tinsukia	2	Tinsukia	Tinsukia , Doomdooma					
	Udalguri	5	Udalguri,	, Harisinga, I	Khairabari, M	azbat, Kalaigaon			
	Total	103							
	District	Total	Revenue						
	Bajali	120		a 25), (Baj					
	Baksa	25	`	1 // (agar RC part		10) (0 1 1		
	Barpeta	608	(Barpeta 100)	· · · · · · · · · · · · · · · · · · ·					
	Biswanath	6	(Halem	Halem 6)					
	Bongaigao n	23	(Boitama	Boitamari 16), (Srijangram 7)					
	Cachar	549	(Katigor	ah 160), (S	Silchar 147)	, (Sonai 91), (Lakhipur 1	11), (Udharb	ond 40)	
	Chirang	5), (Bengtal					
	Darrang	323), (Dalgaon 15), (Patharig	hat 51)		
	Dhemaji	31			aji 3), (Siss				
	Dhubri	433			hubri 60), (moni 87), (South Salmara Part 164), (Athani 14),	(Golakganj 13), (
	Dibrugarh	2			garh West 1				
	Dima-				garii ((CSC) 1	,			
	Hasao	2	(Haflong	(12)					
	Goalpara	218				alijana 90), (Rongjuli 8)			
	Golaghat	29	(Bokakh	at 25), (Kl	numtai 4)				
	Hailakand i	123	(Algapui	r 67), (Hai	lakandi 25),	(Lala 31)			
Villages	Hojai	65	(Hojai	13), (Dobok	ta 36), (Lar	nka 16)			
Affected	Kamrup	419				Hajo 72), (Chaygaon 3), (Kamalpur 100), (North C		21), (Kayan 28), (
	Kamrup (M)	35			andrapur 17		•		
	Karbi								
	Anglong	1	(Donkan	nokam 1)					
	West								
	Karimganj	463	(Nilamba	azar 187), ((RK Nagar	150), (Badarpur 62), (Kar	imganj 43),	(Patherkandi 21)	
	Lakhimpu r	22	_			2), (Nowboicha 11), (Ka	adam 3)		
	Majuli	16		12), (Ujani					
	Morigaon	270				3), (Mayong 131), (Mikir			
	Nagaon	334				mpur 109), (Rupahi 5), (
	Nalbari	246	62)			i 16), (Barbhag 32), (Tib	ıu 11), (Bar	khetri 118), (Nalbari	
	Sonitpur	32	(Thelam	ara 5), (Dł	nekiajuli 22)), (Tezpur 5)			
	South Salmara	87	(Mankac	har 50), (\$	South Salmara	a 37)			
	Tamulpur	16	(Goresw	ar 14), (Ta	mulpur 2)				
	Tinsukia	7			mdooma 6)				
	Udalguri	26	(Udalgui	ri 17), (Ma	zbat 9)				
	Total	4536				Г	~	T	
	District	Male	Female	Children	Total Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details	
	Bajali	107420	100630	22530	230580	(Sarupeta 69580), (Bajali 161000)	1177.00	(Sarupeta 365.00), (Bajali 812.00)	
Population	Baksa	8624	6308	5547	20479	(Baska 0), (Barama 0), (Barnagar RC part 20479)	410.00	(Baska 0.00), (Barama 0.00), (Barnagar RC part 410.00)	
And Crop Area Affected	Barpeta	426119	379857	226585	1032561	(Barpeta 145377), (Baghbar 299349), (Chenga 150025), (Barnagar 13792), (Sarthebari 250640), (Kalgachia 173378)	27240.00	(Barpeta 880.00), (Baghbar 18983.00), (Chenga 2693.00), (Barnagar 780.50), (Sarthebari 2080.00), (Kalgachia 1823.50)	
	Biswanath	0	0	0	0	(Halem 0), (Gohpur 0)	93.00	(Halem 93.00), (Gohpur 0.00)	
	Bongaigao n	8990	7554	9759	26303	(Boitamari 22385), (Manikpur 0), (0.00	(Boitamari 0.00), (Manikpur 0.00), (

					Srijangram 3918)		Srijangram 0.00)
Cachar	105752	95992	70769	272513	(Katigorah 89156), (Silchar 89156), (Sonai 68100), (Lakhipur 20361), (Udharbond 5740)	0.00	(Katigorah 0.00), (Silchar 0.00), (Sonai 0.00), (Lakhipur 0.00), (Udharbond 0.00)
Chirang	293	351	174	818	(Bijni 561), (Bengtal 257)	0.00	(Bijni 0.00), (Bengtal 0.00)
Darrang	146677	121658	45169	313504	(Mangaldoi 112301), (Sipajhar 138210), (Dalgaon 2725), (Patharighat 60268)	9248.50	(Mangaldoi 2838.00), (Sipajhar 1615.00), (Dalgaon 3795.50), (Patharighat 1000.00)
Dhemaji	9621	7758	6681	24060	(Jonai 15459), (Sissiborgaon 6339), (Dhemaji 2262)	4828.06	(Jonai 4021.50), (Sissiborgaon 787.56), (Dhemaji 19.00)
Dhubri	151989	134764	113192	399945	(Bilasipara 77203), (Dhubri 40824), (South Salmara Part 265395), (Athani 15333), (Golakganj 0), (Gauripur 0), (Agamoni 1190), (Chapar 0)	5281.10	(Bilasipara 0.00), (Dhubri 711.00), (South Salmara Part 3769.00), (Athani 0.00), (Golakganj 106.00), (Gauripur 695.10), (Agamoni 0.00), (Chapar 0.00)
Dibrugarh	1567	1240	1050	3857	(Chabua 3857), (Dibrugarh West 0)	2.50	(Chabua 2.50), (Dibrugarh West 0.00
Goalpara	77178	67592	35240	180010	(Matia 9211), (Lakhipur 98230), (Balijana 72569), (Rongjuli 0)	906.20	(Matia 308.00), (Lakhipur 0.00), (Balijana 598.20), (Rongjuli 0.00)
Golaghat	7866	6755	2177	16798	(Bokakhat 16798), (Khumtai 0)	106.00	(Bokakhat 90.00), (Khumtai 16.00)
Hailakand i	25525	19831	12576	57932	(Algapur 41255), (Hailakandi 7177), (Katlicherra 0), (Lala 9500)	101.00	(Algapur 47.00), (Hailakandi 21.00), (Katlicherra 0.00), (Lala 33.00)
Hojai	15363	11153	4191	30707	(Hojai 7436), (Doboka 18154), (Lanka 5117)	1439.00	(Hojai 178.00), (Doboka 446.00), (Lanka 815.00)
Kamrup	209655	134633	84878	429166	(Rangia 25850), (Hajo 164733), (Chaygaon 0), (Nagarbera 0), (Kayan 25857), (Chamaria 0), (Goroimari 0), (Kamalpur 188602), (Palashbari 2499), (North Ghy 21625)	4361.25	(Rangia 698.50), (Hajo 750.00), (Chaygaon 84.00), (Nagarbera 220.00), (Kayan 344.50), (Chamaria 88.25), (Goroimari 700.00), (Kamalpur 1045.00), (Palashbari 256.00), (North Ghy 175.00)
Kamrup (M)	2656	2055	20	4731	(Sonapur 4731), (Chandrapur 0)	899.50	(Sonapur 726.50), (Chandrapur 173.00)
Karbi Anglong West	90	93	100	283	(Donkamokam 283)	0.00	(Donkamokam 0.00)
Karimganj	131896	103396	45381	280673	(Nilambazar 62318), (RK Nagar 51140), (Badarpur 43433), (Patherkandi 3411), (Karimganj 120371)	3148.00	(Nilambazar 0.00), (RK Nagar 3148.00), (Badarpur 0.00), (Patherkandi 0.00), (Karimganj 0.00)
Lakhimpu r	11120	7701	8093	26914	(North Lakhimpur 3698), (Nowboicha 23216), (Bihpuria 0), (Kadam 0)	0.00	(North Lakhimpur 0.00), (Nowboicha 0.00), (Bihpuria 0.00), (Kadam 0.00)
Majuli	995	671	943	2609	(Majuli 2609), (Ujani Majuli 0)	140.77	(Majuli 126.38), (Ujani Majuli 14.39)

	Morigaon	41980	39463	25040	106483	(Bhuragaon Morigaon 70 Mayong 594 Mikirbheta 3	023), (1), (15020.00	(Bhuragaon 721.00), (Morigaon 1100.00), (Mayong 13090.00), (Mikirbheta 109.00)
	Nagaon	178859	167482	156967	503308	(Nagaon 991 Kampur 2595 Raha 142645 Samaguri 200 Dhing 0), (F	500),(5),(08),(17307.45	(Nagaon 728.00), (Kampur 8320.00), (Raha 8012.45), (Samaguri 182.00), (Dhing 44.00), (Rupahi 21.00)
	Nalbari	127989	117864	106208	352061	(Ghograpar Paschim Nalba), (Barbhag 2 Tihu 1622), 269330), (N	ari 46329 20300), ((Barkhetri	6863.00	(Ghograpar 718.00), (Paschim Nalbari 554.00), (Barbhag 140.00), (Tihu 50.00), (Barkhetri 5019.50), (Nalbari 381.50)
	Sonitpur	6968	11424	7422	25814	(Thelamara 0 Dhekiajuli 25 Tezpur 0)		1232.00	(Thelamara 13.00), (Dhekiajuli 1205.00), (Tezpur 14.00)
	South Salmara	60750	55459	60743	176952	(Mankachar South Salmara		891.00	(Mankachar 199.00), (South Salmara 692.00)
	Tamulpur	4551	2764	1532	8847	(Goreswar 8 Tamulpur 12	5)	125.00	(Goreswar 0.00), (Tamulpur 125.00)
	Tinsukia	573	436	381	1390	(Tinsukia 37 Doomdooma	1014)	49.43	(Tinsukia 29.23), (Doomdooma 20.20)
	Udalguri	2280	1530	940	4750	(Udalguri 0 Harisinga 0) Khairabari 0 Kalaigaon 0	, (), (0.00	(Udalguri 0.00), (Harisinga 0.00), (Khairabari 0.00), (Kalaigaon 0.00), (Mazbat 0.00)
	Total	187334 6	160641 4	1054288	4534048	11700		100869.76	Transcription)
	District	Total	Relief Ca	amp			Relief Distr	ribution Cent	res
	Daiali								
	Bajali	35		eta 11, Baja				a 1, Bajali 2	1)
	Baksa	35 8	0(Barnag	ar RC part	0)		8(Barnagar	RC part 8)	
	Baksa Barpeta		0(Barnag 145(Barp	ar RC part	0) hbar 17, Ch	enga 37,	8(Barnagar 25(Barpeta	RC part 8)	1, Chenga 10,
	Baksa	8	0(Barnag 145(Barp Sarthebar 9(Boitam	ar RC part (eta 80, Bag ri 11, Kalga ari 2, Mani	0) hbar 17, Chechia 0) kpur 3, Srija	ingram 4)	8(Barnagar 25(Barpeta Sarthebari 34(Boitama	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikp	1, Chenga 10, 9) ur 0, Srijangram 33)
	Baksa Barpeta Bongaigao	8 170	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Katig Lakhipur	ar RC part 0 teta 80, Bag i 11, Kalga tari 2, Mani gorah 45, Si 22, Udharb	0) hbar 17, Chochia 0) kpur 3, Srija ilchar 63, Scoond 1)	ingram 4)	8(Barnagar 25(Barpeta Sarthebari 34(Boitama	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpu ah 0, Silchar	1, Chenga 10,
	Baksa Barpeta Bongaigao n	8 170 43	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati Lakhipur 6(Bijni	ar RC part 0 eta 80, Bag ri 11, Kalga ari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, So oond 1)	nngram 4) onai 44,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpu sh 0, Silchar nd 0) Bengtal 0)	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur
	Baksa Barpeta Bongaigao n Cachar	8 170 43 260	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati Lakhipur 6(Bijni	ar RC part 0 eta 80, Bag ri 11, Kalga ari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 ldoi 2, Sipa	0) hbar 17, Chochia 0) kpur 3, Srija ilchar 63, Scoond 1)	nngram 4) onai 44,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpu th 0, Silchar nd 0) Bengtal 0) loi 31, Sipajh	1, Chenga 10, 9) ur 0, Srijangram 33)
	Baksa Barpeta Bongaigao n Cachar Chirang	8 170 43 260 6	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Katig Lakhipur 6(Bijni 2 6(Manga Patharigh 0(Jonai	ar RC part (peta 80, Bag ri 11, Kalga ri 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 Idoi 2, Sipa nat 0) 0, Dhemaji	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga	nngram 4) onai 44,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1) 53(Mangald Patharighat 12(Jonai 1)	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpu th 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur
	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri	8 170 43 260 6 59 12 25	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati Lakhipur 6(Bijni 6(Manga Patharigh 0(Jonai 14(Bilasi	ar RC part 6 peta 80, Bag pi 11, Kalga pari 2, Mani gorah 45, Si 22, Udharb gorah 3, Bengtal 3 para 10, Ohemaji para 10, Oh	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4)	nngram 4) onai 44,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpu sh 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0,
Relief	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh	8 170 43 260 6 59	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati Lakhipur 6(Bijni 6(Manga Patharigh 0(Jonai 14(Bilasi	ar RC part (peta 80, Bag ri 11, Kalga ri 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 Idoi 2, Sipa nat 0) 0, Dhemaji	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4)	nngram 4) onai 44,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpu th 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0,
Camps /	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri	8 170 43 260 6 59 12 25	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati Lakhipur 6(Bijni 6(Manga Patharigh 0(Jonai 14(Bilasi	ar RC part 6 teta 80, Bag ti 11, Kalga tari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 Idoi 2, Sipa tat 0) 0, Dhemaji para 10, Dh ta 0, Dibruga	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4)	nngram 4) onai 44,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikputh 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0,
Camps / Centres	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Dima-	8 170 43 260 6 59 12 25 6	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati, Lakhipur 6(Bijni 1 6(Manga Patharigh 0(Jonai 14(Bilasi 0(Chabua 28(Haflor	ar RC part (peta 80, Bag ri 11, Kalga pari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 Idoi 2, Sipa para 10, Dh n 0, Dibruga ng 28)	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4)	angram 4) onai 44, aon 1,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar 6(Chabua 2 2(Haflong	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpu th 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0,
Camps /	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Dima- Hasao	8 170 43 260 6 59 12 25 6 30	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati, Lakhipur 6(Bijni 1 6(Manga Patharigh 0(Jonai 14(Bilasi 0(Chabua 28(Haflor	ar RC part 6 teta 80, Bag ti 11, Kalga tari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 Idoi 2, Sipa tat 0) 0, Dhemaji para 10, Dh ta 0, Dibruga tag 28) 3, Lakhipu	0) (hbar 17, Chochia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4) arh West 0)	angram 4) onai 44, aon 1,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar 6(Chabua 2 2(Haflong	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikputh 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V 2) 0, Lakhipur 4	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0, 11) West 1)
Camps / Centres	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Dima- Hasao Goalpara Golaghat Hailakand	8 170 43 260 6 59 12 25 6 30 133	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati, Lakhipur 6(Bijni 1 6(Manga Patharigh 0(Jonai 14(Bilasi 0(Chabua 28(Haflo 64(Matia 0(Bokakh	ar RC part (a) teta 80, Bag ii 11, Kalga ii 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 3 3 3 3 3 4 5 5 5 5 5 5 5 5 5	0) (hbar 17, Chochia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4) arh West 0)	angram 4) onai 44, aon 1,	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar 6(Chabua 1 2(Haflong 69(Matia 0 5(Bokakhat	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpu th 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V 2) 0, Lakhipur 4 5)	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0, 11) West 1)
Camps / Centres	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Dima- Hasao Goalpara Golaghat Hailakand i	8 170 43 260 6 59 12 25 6 30 133 5	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati Lakhipur 6(Bijni 6(Manga Patharigh 0(Jonai 14(Bilasi 0(Chabua 28(Haflo 64(Matia 0(Bokakh	ar RC part 6 peta 80, Bag ri 11, Kalga ari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 Idoi 2, Sipa nat 0) 0, Dhemaji para 10, Dh a 0, Dibruga ng 28) 3, Lakhipu nat 0) r 1, Hailaka	0) (hbar 17, Chochia 0) (kpur 3, Srija (ilchar 63, Socond 1) (b) (jhar 3, Dalga (0) (uubri 4) (arh West 0) (r 43, Balijan	angram 4) onai 44, aon 1, a 18)	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar 6(Chabua 1 2(Haflong 69(Matia 0 5(Bokakhat 16(Algapur	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpt th 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V 2) 0, Lakhipur 4 5) 4, Hailakand	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0, 11) West 1) 3, Balijana 26) li 6, Lala 6)
Camps / Centres	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Dima- Hasao Goalpara Golaghat Hailakand	8 170 43 260 6 59 12 25 6 30 133 5	O(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati, Lakhipur 6(Bijni 16(Manga Patharigh O(Jonai 14(Bilasi O(Chabua 28(Haflo 64(Matia O(Bokakh 2(Algapu 28(Hojai 64(Rangi	ar RC part 6 peta 80, Bag ri 11, Kalga pari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 para 10, Dh 1 0, Dibruga para 10, Dh 1 0, Lakhipu para 0) r 1, Hailaka 14, Doboka a 13, Hajo	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4) arh West 0) r 43, Balijan andi 1, Lala a 14, Lanka 2, Kayan 1'	angram 4) onai 44, aon 1, a 18) 0) 0) 7, Kamalpur	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar 6(Chabua 1 2(Haflong 69(Matia 0 5(Bokakhat 16(Algapur 25(Hojai 1 45(Rangia	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpt th 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V 2) 0, Lakhipur 4 5) 4, Hailakand 7, Doboka 6, 1, Hajo 0, K	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0, 11) West 1) 3, Balijana 26) li 6, Lala 6) , Lanka 2) ayan 10, Kamalpur
Camps / Centres	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Dima- Hasao Goalpara Golaghat Hailakand i Hojai Kamrup	8 170 43 260 6 59 12 25 6 30 133 5 18	O(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati, Lakhipur 6(Bijni 16(Manga Patharigh O(Jonai 14(Bilasi O(Chabua 28(Haflo 64(Matia O(Bokakh 2(Algapu 28(Hojai 64(Rangi	ar RC part 6 peta 80, Bag ri 11, Kalga ari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 Idoi 2, Sipa nat 0) 0, Dhemaji para 10, Dh 1 0, Dibruga ng 28) 3, Lakhipu nat 0) r 1, Hailaka 1 14, Doboka a 13, Hajo 1 Ghy 13, Pa	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4) arh West 0) r 43, Balijan andi 1, Lala a 14, Lanka 2, Kayan 1'	angram 4) onai 44, aon 1, aa 18) 0)	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 1 53(Mangald Patharighat 12(Jonai 1 11(Bilasipar 6(Chabua 1 2(Haflong 69(Matia 0 5(Bokakhat 16(Algapur 25(Hojai 1 45(Rangia	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpt th 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V 2) 0, Lakhipur 4 5) 4, Hailakand 7, Doboka 6, 1, Hajo 0, K thy 4, Palash	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0, 11) West 1) 3, Balijana 26) li 6, Lala 6) , Lanka 2)
Camps / Centres	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Dima- Hasao Goalpara Golaghat Hailakand i Hojai Kamrup	8 170 43 260 6 59 12 25 6 30 133 5 18 53 109	0(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati, Lakhipur 6(Bijni 3 6(Manga Patharigh 0(Jonai 14(Bilasi 0(Chabua 28(Haflo 64(Matia 0(Bokakh 2(Algapu 28(Hojai 64(Rangi 19, North 0(Chanda	ar RC part 6 peta 80, Bag ri 11, Kalga ari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 Idoi 2, Sipa nat 0) 0, Dhemaji para 10, Dh 1 0, Dibruga ng 28) 3, Lakhipu nat 0) r 1, Hailaka 1 14, Doboka a 13, Hajo a Ghy 13, Pa rapur 0) mokam 0)	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4) arh West 0) r 43, Balijan andi 1, Lala a 14, Lanka 2, Kayan 1' alashbari 0, 6	angram 4) ana 44, ana 18) 0) 0) 7, Kamalpur Chamaria 0)	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 153(Mangald Patharighat 12(Jonai 1 11(Bilasipar 6(Chabua 2 2(Haflong 69(Matia 0 5(Bokakhat 16(Algapur 25(Hojai 1 45(Rangia 25, North G 3(Chandrap 3(Donkamo	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpt sh 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V 2) 0, Lakhipur 4 5) 4, Hailakand 7, Doboka 6, 1, Hajo 0, K shy 4, Palashl ur 3) okam 3)	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0, 11) West 1) 3, Balijana 26) li 6, Lala 6) , Lanka 2) ayan 10, Kamalpur bari 3, Chamaria 2)
Camps / Centres	Baksa Barpeta Bongaigao n Cachar Chirang Darrang Dhemaji Dhubri Dibrugarh Dima- Hasao Goalpara Golaghat Hailakand i Hojai Kamrup (M) Karbi Anglong	8 170 43 260 6 59 12 25 6 30 133 5 18 53 109 3	O(Barnag 145(Barp Sarthebar 9(Boitam 175(Kati, Lakhipur 6(Bijni : 6(Manga Patharigh O(Jonai 14(Bilasi O(Chabua 28(Haflo: 64(Matia O(Bokakh 2(Algapu 28(Hojai 64(Rangi 19, North O(Chandr 0(Donkar 71(Nilam 38, Pathe	ar RC part 6 beta 80, Bag ci 11, Kalga ari 2, Mani gorah 45, Si 22, Udharb 3, Bengtal 3 ldoi 2, Sipa at 0) 0, Dhemaji para 10, Dh a 0, Dibruga ng 28) 3, Lakhipu nat 0) r 1, Hailaka 14, Doboka a 13, Hajo a Ghy 13, Pa rapur 0) mokam 0) dbazar 5, Ba rkandi 5, R	0) chbar 17, Chechia 0) kpur 3, Srija ilchar 63, Scoond 1) 3) jhar 3, Dalga 0) nubri 4) arh West 0) r 43, Balijan andi 1, Lala a 14, Lanka 2, Kayan 1' alashbari 0, o	angram 4) ana 44, ana 18) 0) 0) 7, Kamalpur Chamaria 0)	8(Barnagar 25(Barpeta Sarthebari 34(Boitama 85(Katigora 0, Udharbor 0(Bijni 0, 153(Mangald Patharighat 12(Jonai 1 11(Bilasipara 6(Chabua 1 2(Haflong 69(Matia 0 5(Bokakhat 16(Algapur 25(Hojai 1 45(Rangia 25, North G 3(Chandrap 3(Donkamo 82(Nilamba Patherkandi	RC part 8) 0, Baghbar 5, Kalgachia ri 1, Manikpt sh 0, Silchar nd 0) Bengtal 0) doi 31, Sipajh 10) 1, Dhemaji 1 ra 0, Dhubri 5, Dibrugarh V 2) 0, Lakhipur 4 5) 4, Hailakand 7, Doboka 6, 1, Hajo 0, K shy 4, Palashl ur 3) okam 3) tzar 22, Bada i 12, RK Nag	1, Chenga 10, 9) ur 0, Srijangram 33) 85, Sonai 0, Lakhipur nar 12, Dalgaon 0, 11) West 1) 3, Balijana 26) di 6, Lala 6) , Lanka 2) ayan 10, Kamalpur bari 3, Chamaria 2) rpur 6, Karimganj 17,

	Majuli	1	0(Majuli 0)		1(Majuli 1	1)			
	Morigaon	24	1(Morigaon 1, Mayong 0, Mikirl	pheta L(I)			13 Mikirbh	eta I 3)	
	Nagaon	98	64(Nagaon 35, Kampur 17, Raha		23(Morigaon 7, Mayong 13, Mikirbheta 3) 34(Nagaon 34, Kampur 0, Raha 0)				
			43(Paschim Nalbari 17, Barbhag				arbhag 0, Tih	u 0.	
	Nalbari	47	Barkhetri 4, Nalbari 2)	-		4, Nalbari 0)	•	1 - 7	
	South	3	1(Dhekiajuli 1)		2(Dhekiaju				
	South Salmara	44	9(Mankachar 9, South Salmara 0))	35(Mankac	har 27, Soutl	n Salmara 8)		
	Tamulpur	16	7(Goreswar 5, Tamulpur 2)		9(Goreswar	r 7, Tamulpu	r 2)		
	Tinsukia	2	0(Tinsukia 0)		2(Tinsukia	• •			
	Udalguri	22	9(Udalguri 3, Mazbat 6)			ri 13, Mazbat	(0)		
	Total	1395	759	1	636	1	T _		
	District	Total	Revenue Circlewise	Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y	
	Bajali	2170	(Sarupeta 2122), (Bajali 48)	906	938	273	52	1	
	Barpeta	110535	(Barpeta 101245), (Baghbar 3222), (Chenga 3554), (Barnagar 0), (Sarthebari 2514), (Kalgachia 0)	35893	36513	37789	337	3	
	Bongaigao n	2233	(Srijangram 366), (Boitamari 656), (Manikpur 1211)	913	757	552	11	0	
	Cachar	71977	(Katigorah 8985), (Silchar 22549), (Sonai 36916), (Lakhipur 3415), (Udharbond 112)	29430	25159	17377	4	7	
	Chirang	818	(Bijni 561), (Bengtal 257)	275	335	204	4	0	
	Darrang	3813	(Sipajhar 1409), (Patharighat 0), (Mangaldoi 734), (Dalgaon 1670)	1390	1356	1038	26	3	
	Dhubri	3396	(Bilasipara 1509), (Dhubri 1887), (South Salmara Part 0), (Athani 0), (Golakganj 0), (Gauripur 0), (Agamoni 0), (Chapar 0)	1161	1430	804	1	0	
	Dima- Hasao	1905	(Haflong 1905)	679	725	433	60	8	
Inmates In Relief Camps	Goalpara	22983	(Matia 1443), (Lakhipur 14476), (Balijana 7064), (Rongjuli 0)	9879	7259	5716	118	11	
	Hailakand i	821	(Algapur 280), (Katlicherra 0), (Hailakandi 204), (Lala 337)	361	290	165	5	0	
	Hojai	6949	(Hojai 4162), (Lanka 0), (Doboka 2787)	3882	2521	544	2	0	
	Kamrup	4919	(Rangia 510), (Palashbari 0), (Hajo 167), (Chaygaon 0), (Nagarbera 0), (Kayan 524), (Chamaria 0), (Goroimari 0), (Kamalpur 1607), (North Ghy 2111)	1765	1938	1197	19	0	
	Karimganj	19634	(Nilambazar 357), (RK Nagar 0), (Badarpur 2522), (Karimganj 16570), (Patherkandi 185)	8055	7075	4491	13	0	
	Morigaon	175	(Bhuragaon 0), (Morigaon 175), (Mayong 0), (Mikirbheta 0)	67	75	33	0	0	
	Nagaon	17675	(Dhing 0), (Rupahi 0), (Samaguri 0), (Nagaon 11185), (Kampur 4980), (Raha 1510)	7018	6428	4094	129	6	
	Nalbari	12252	(Ghograpar 0), (Paschim Nalbari 10086), (Barbhag 1550), (Tihu 173), (Nalbari 250), (Barkhetri 193)	5652	5123	1367	101	9	
	Sonitpur	170	(Thelamara 0), (Tezpur 0), (Dhekiajuli 170)	46	78	40	6	0	
	South	432	(South Salmara 0), (Mankachar	164	126	121	21	0	

	Salmara		432)							
	Tamulpur	993		ar 888), (Ta	mulpur	238	269	484	2	0
	Tamarpar	773	105)	10) (77	1 110	230	20)	707	2	0
	Udalguri	1025		a 0), (Khaii 400), (Kalai		443	365	210	7	0
	Cuarguii	1023	(Udalgur		igaon (0),	143	303	210	,	
	Total	284875				108217	98760	76932	918	48
	District	Total	Male	Female	Children	Revenue Circ				
	Bajali	1	1	0	0	(Bajali 1), (S				
	Barpeta	2	1	0	1	(Baghbar 0), (Barnagar 0), (Barpeta 1), (Chenga 1), (Kalgachia 0), (Sarthebari 0)				
Human Lives Lost -	Cachar	2	2	0	0	(Katigorah 0 (Udharbond), (Lakhipur		0), (Sonai 0),
Confirmed	Dhubri	1	0	0	1	(Agamoni 0)	, (Athani 0).			
	Tamulpur	1	1	0	0	(Goreswar 1)				
	Total	7	5	0	2					
Human Lives Lost	District	Total	Flood Death	General Drownin g (Non Flood)	Landslide					
Confirmed	Bajali	1	1	0	0					
- Death	Barpeta	2	2	0	0					
Туре	Cachar	2	2	0	0					
	Dhubri	1	1	0	0					
	Tamulpur Total	7	1	0	0					
Human Lives Lost - Missing	Nil	1	1	7 0 0						
Human Lives Lost Missing - Type	Nil									
	District	Total	Big	Small	Poultry					
	Bajali	106626	68729	31317	6580					
	Baksa	6853	4077	2630	146					
	Barpeta	100610	347804	193622	464681					
	Biswanath	12094	8810	3284	0					
	Cachar	116717 277748	76059	18388 81410	22270 39263					
	Darrang Dhemaji	6527	157075 4687	1840	0					
	Dhubri	302252	170842	131410	0					
	Dibrugarh	1050	660	390	0					
	Goalpara	109947	70353	23799	15795					
	Golaghat	3800	2300	1500	0					
Animals	Hailakand i	4250	1066	746	2438					
Affected	Hojai	44268	16888	5652	21728		· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·		
	Kamrup	511857	425256	54351	32250					
	Kamrup (M)	20588	11097	6093	3398					
	Karimganj	40723	26025	3688	11010					
	Lakhimpu r	12674	8199	4475	0					
	Morigaon	104695	38047	19141	47507					
	Nagaon	107853	54232	38250	15371					
	Nalbari	226741	103504	94737	28500					
	South Solmon	33627 285895	22846 114287	10781 79087	92521					
	Salmara Tamulpur	34626	12281	10404	11941					
	Total	337751 8	174512 4	816995	815399					
Animals	District	Total	Big	Small	Poultry					

Buryon Buryon 1	Washed	Bajali	60	5	2	53						
Haliskond 1												
National 1		Hailakand	1	1	0	0						
District Fully Fully Fully Fully Fully Furtially F			22	5 17 0								
District Start Path Pa		Total										
Barpeta 15 21 36 0 0 0 0 0 0 0 0 0		District	-	_	-	_	_	_		Cattle	Others Total	
Housest Durninged Chirang 2 0 2 0 0 0 0 0 0 0		Baksa					0	294	·	0		
Damber										_		
Somipur 25								_		_		
Name	Damaged									-		
Timestifical 0						_						
									_	_		
Total S6 26 82 493 1 494 10 6 6 16					-					_		
Bajali									·			
Barpeta Fire & Emergency Services (F&ES), NDRF, SDRF, Crcle (Office/Local Administration) Sometime Points Someti		District				Boats Deployed	Person Evacuated By Boats	Animal Evacuate d By Boats	Helicopte rs Deployed	Person Evacuate d By Helicopte rs	Medical Team Deploye d	
Barpeta		Bajali	E: 0 E			0	0	0	0	0	15	
Rescue Operation		Barpeta	(F&ES), l Office/Lo	NDRF, SD cal Admin	RF, Circle	39	472	0	0	0	16	
Cachar			Administr Fngine Bo	ration, Loc oat	al People,	3	0	0	0	0	11	
Darrang		Cachar	Administra Emergence Local Pec Army/Par Defence/T	ration, Fire by Services ople, Police camilitary for amilitary for	(F&ES), orce, Civil	28	5401	7	1	0	17	
Dhemaji Fire & Emergency Services 2 0 0 0 0 0 0 0 0 0		Chirang				3	0	0	0	0	5	
Diemaji		Darrang				7	100	0	0	0	24	
Rescue Operation		Dhemaji	(F&ES)		ervices	2	0	0	0	0	0	
Dima-		Dhubri	Administr	ration		68	131	124	0	0	7	
Hailakand i SDRF	Operation	Hasao	Volunteer Services (Resources	rs, Fire & E (F&ES), Po s Departme	Emergency blice, Water	0	0	0	0	0	15	
Local People, Fire & Emergency Services (F&ES)						0	0	0	0	0	16	
Hojal Emergency Services (F&ES) 11 0 0 0 0 13						1	25	0	0	0	4	
Kamrup SDRF, Assam Mointaineering Association, NDRF 17 215 30 0 0 25 Karimganj 7 65 0 0 0 14 Lakhimpu r 0 0 0 0 0 0 0 Majuli 0 0 0 0 0 0 4 Morigaon 2 Machine boat standby for emergency situation. 7 0 0 0 0 0 22 Nagaon Fire & Emergency Services (F&ES), SDRF, Circle Office/Local Administration, Local People, NDRF 13 136 0 0 0 0 22		Hojai	Emergeno	cy Services	(F&ES)	11	0	0	0	0	15	
Lakhimpu r 0 0 0 0 0 0 3 Majuli 0 0 0 0 0 0 4 Morigaon 2 Machine boat standby for emergency situation. 7 0 0 0 0 0 22 Nagaon Fire & Emergency Services (F&ES), SDRF, Circle Office/Local Administration, Local People, NDRF 13 136 0 0 0 22			SDRF, As	ssam Moin								
Nagaon Company Compa						7	65	0	0	0	14	
Morigaon 2 Machine boat standby for emergency situation. 7 0 0 0 0 0 22 Nagaon Fire & Emergency Services (F&ES), SDRF, Circle Office/Local Administration, Local People, NDRF 13 136 0 0 0 22		r										
Nagaon emergency situation. Fire & Emergency Services (F&ES), SDRF, Circle Office/Local Administration, Local People, NDRF O 0 0 0 22 13 136 0 0 0 22		Majuli				0	0	0	0	0	4	
Nagaon (F&ES), SDRF, Circle Office/Local Administration, Local People, NDRF		Morigaon	emergenc	y situation		7	0	0	0	0	22	
		Nagaon	(F&ES), S Office/Lo	SDRF, Circ cal Admin	cle istration,	13	136	0	0	0	22	
		Nalbari		-		3	0	50	0	0	1	

		Administr	ation									
	Sonitpur				0	0	0	0	0	4		
	South Salmara	Circle Off Administr			32	56	93	0	0	8		
	Udalguri				0	0	0	0	0	3		
	Total				241	6601	304	1	0	251		
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)		- Rice Bran	(in Q)		
	Bajali	1860.00	395.00	100.64	16638.09	0.00	2159.88	0.00				
	Baksa	126.00	23.95	7.18	718.44	0.00	146.96	0.00				
	Barpeta	7781.55	1611.6 9	355.95	0.00	0.00	6708.80	0.00				
	Bongaigao n	267.07	50.43	15.13	294.54	0.00	294.40	0.00				
	Cachar	2750.27	539.85	174.03	11357.91	0.00	0.00	0.00				
	Chirang	19.62	3.74	0.85	74.95	0.00	0.00	0.00				
	Darrang	932.00	193.60	79.51	6824.00	0.00	60.00	221.24				
	Dhemaji	56.34	10.11	3.02	57.96	0.00	0.00	0.00				
	Dhubri	382.48	71.61	21.49	2637.15	0.00	5338.44	0.00				
	Dibrugarh	0.00	0.00	0.00	0.00	0.00	22.05	0.00				
	Dima- Hasao	4.77	0.42	0.09	33.00	0.00	0.00	0.00				
	Goalpara	205.33	37.36	11.21	1120.86	0.00	69.56	0.00				
Relief	Golaghat	0.00	0.00	0.00	0.00	0.00	0.00	150.00				
Distributed	Hailakand i	289.43	51.31	15.43	1542.95	0.00	15.00	0.00				
	Hojai	638.00	75.94	15.70	1435.00	0.00	0.00		50.00			
	Kamrup	1501.68	306.99	47.70	7937.61	0.00	1579.00	0.00	0.00			
	(M)	0.00	0.00	0.00	0.00	0.00	248.00	0.00				
	Karbi Anglong West	60.11	11.35	3.41	340.56	0.00	0.00	0.00				
	Karimganj	2638.77	491.84	137.94	27.50	0.00	0.00	30.00				
	Lakhimpu r	0.00	0.00	0.00	0.00	0.00	0.00	1462.46				
	Morigaon	149.36	26.66	8.01	167.58	90.00	223.60	0.00				
	Nagaon	523.64	95.45	28.64	2863.53	0.00	200.00		0.00			
	Nalbari	1027.91	183.78	55.08	5509.00	0.00	148.80	0.00				
	Sonitpur	92.07	13.91	5.04	0.00	0.00	353.84	0.00				
	Tamulpur	439.25	25.49	7.65	764.55	0.00	0.00	0.00				
	Tinsukia	5.77	1.12	0.33	33.84	0.00	0.00	0.00				
	Udalguri	289.79	79.30	18.48	1840.41	0.00	22.40	51.00				
	Total	22041.2	4300.9	1112.51	62219.43	90.00	17590.73	1964.70				
	District	Baby Foo Liquid	ou	Baby Food	l Solid	Others	050 00 B:	0 11 25 2	0 DI (3.5	10.00		
	Bajali	0.00-Q		3956.00-Pl	ĸt	Tarpaulin-269 Pkt	950.00-Pieces	; Candle-35.00	U-Pkt; Match	зох-40.00-		
	Baksa	0.00-Q		0.00-Q								
	Barpeta	0.00-Q		0.00-Q, 22	0.00-Pkt	Tarpaulin-850 soap-1000.00	-Pieces; phen	yl-480.00-Pied	ces			
Relief Distributed Others	Bongaigao n	934.00-Pk Q	xt, 0.00-	0.00-Q, 70	.00-Pkt	Chira-216.00- Mosquito net- -110.00-Piece	-330.00-Piece s	s; Solar Light	-40.00-Pieces	; Tarpaulin		
Juicis	Cachar	0.00-Q		0.00-Q		Candle-2700.						
	Chirang	0.00-Q, 64	4.20-Kg	96.00-Pkt,	0.00-Q	Tarpaulin-59. 64.20-Kg; Sug	gar-16.05-Kg					
	Darrang	0.00-Q		330.00-Pkt	, 0.00-Q	Taurpaulin-20 200.00-Pkt	000.00-Pieces	; tarpaulin-184	40.00-Pieces;	candles-		
	Dhemaji	0.00-Q		0.00-Q								
	Dhubri	0.00-Q		0.00-Q, 3.0	00-Pkt	Polyethylene WATER POU		0-Pieces; HT\ RIBUTED-50				

					HALOGEN TABLET DISTRIBUTED-1200.00-Pieces; Tarpoline sheet-3500.00-Pieces; Horliks-6.00-Pkt; Sanitary Napkin-40.00-Pkt; Tarpaulin-5000.00-Pieces; chira-19.12-Q; gur- 3.57-Q; TARPAULIN-216.00-Pieces; MATCH BOX-156.00-Pkt; MOSQUITO COIL-331.00-Pkt; SANITARY NAPKIN-307.00-
					Pkt; CANDLE-331.00-Pkt
	Dibrugarh	0.00-Pkt,	0.00-Q	5091.00-Pkt, 0.00-Q	
	Dima- Hasao	0.00-Q		0.00-Q	Milk-21.00-L; Potato-117.00-Kg; Onion-21.00-Kg; Biscuit-159.00-Pkt; Candle-75.00-Pkt; Match Box-33.00-Pkt; Mosquito Repellent-33.00-Pkt; Phenyl-4.00-Pieces; Dettol-5.00-Pieces
	Goalpara	1503.00-F	Pkt	4509.00-Pkt	Chira-1.18-Q; Gur-0.59-Q; Tarpaulin-1000.00-Pieces
	Golaghat	0.00-Q		0.00-Q	Tarpaulin-40.00-Pieces
	Hailakand i	450.00-PI Q	ct, 0.00-	0.00-Q	Candle-500.00-Pkt; Sanitary Napkin-410.00-Pkt; Match Box-500.00-Pkt; Disposal Plate-600.00-Pieces; Disposal Glass-600.00-Pieces; Soap-500.00-Pieces; Tarpaulin-475.00-Pieces; Water Purification Tablets-25800.00-Pieces; Water Packets-15000.00-Pkt
	Нојаі	0.00-Q		0.00-Q	Sanitary Pad-270.00-Pkt; Water -5976.00-L; Candles-254.00-Pkt; Phenyl-265.00-Pkt; Bleaching powder-122.00-Pkt; Amul Taza-1069.00-L; Water-2328.00-L; Candle-93.00-Pkt; Bleaching Powder-76.00-Pkt; Phenyl-82.00-Pieces; Sanitary Pad-135.00-Pkt; Chira-6.00-Q; Gur-1.00-Q; Bleaching Powder-11.00-Pkt
	Kamrup	0.00-Pkt,	0.00-Q	39.00-Pkt, 0.00-Q	Water Pouch-10000.00-Pkt; Broom & Floor Wiper-2.00-Pieces; Mosquito Coil-1000.00-Pkt; 0-0.00-Q
	Kamrup (M)	0.00-Q		0.00-Q	0-0.00-Q
	Karbi Anglong West	0.00-Q		0.00-Q	
	Karimganj	551.00-PI Q	kt, 0.00-	162.00-Pkt, 100.00-Q	SANITARY NAPKIN-122.00-Pkt; MOSQUITO COIL-60.00-Pkt; BLEACHING POWDER-60.00-Pkt; MATCHBOX-180.00-Pieces; Mosquito Coil-28.00-Pkt; Candle-60.00-Pkt; Water Purification Tablet-13875.00-Pieces; Chemical-4390.00-Pkt; Water Pouch-2585.00-Pkt; 0-0.00-Q
	Lakhimpu r	0.00-Q		0.00-Q	Tarpaulin -2422.00-Pieces
	Majuli	0.00-Q		0.00-Q	Chemical packets-500.00-Pkt; Halogen tab-3500.00-Pieces; Jaggery (Baby food)-51.30-Kg; Flattened Rice (Baby food)- 205.20-Kg; Tonned milk (Baby food)-513.00-Pkt
	Morigaon	0.00-Q		0.00-Q	HTW -30.00-Pieces; WATER PACKETS -1000.00-Q; CHEMICAL PACKETS -1200.00-Q; Tarpaulin -78.00-Pieces
	Nagaon	0.00-Q		0.00-Q	Tarpaulin -1000.00-Pieces; Tarpulin-1000.00-Pieces
	Nalbari	0.00-Q, 2 Pkt	16.00-	0.00-Q	
	Sonitpur	0.00-Q		0.00-Q	
	South				T 40.00 T:
	Salmara	0.00-Q		0.00-Q	Tarpaulin -30.00-Pieces
	Tamulpur	0.00-Q		0.00-Q	
	Tinsukia	0.00-Q		0.00-Q	0-0.00-Q
	Udalguri	0.00-Q		305.00-Pkt, 0.00-Q	Sanitary Pad -1474.00-Pkt; Candles & Match Sticks-245.00-Pkt; Mosquito Coil-267.00-Pkt; Disposal Plates & Glass-190.00-Pkt; Soap-1030.00-Q; Water Bottle-230.00-Pkt; Phenyl-65.00-Pieces; Mask & Sanitizer-2650.00-Pieces; Biscuit-120.00-Pkt; Tarpaulin-372.00-Pieces; candle-90.00-Pkt; sanitary pads-248.00-Pkt; Matches box-8.00-Pkt; tarpaulin-1070.00-Pieces; Blanket-1219.00-Pieces; Tarpauline-346.00-Pieces
	District	Numbe	Details		
Infrastructu re Damaged	Baksa	1	Baska - 1 26.63631	•	ached Chanbarikhuti Date: 18/6/2022 (Long - 91.334030, Lat -
- Embankme nt Breached	Darrang	1	Mangald under Ma embankn	loi - Canal embankment a angaldai Revenue Circle	t extension of Noanadi under irrigation Village Holoichowka as reported by irrigation department their is bridge of Canal adi I/S at several places due to excess flood water of river. Dated: tt - 26.480000)
	Total	2			
Infrastructu re Damaged	District	Numbe r	Details		

- Embankme	Jorhat	1	Teok - Right ring bund of river Puthinadi or Mudoijan. Deodhai Gaon Date: 22-06-2022 Approx. Length- 15 feets. (Long - 94.417392, Lat - 26.792906)
nt Affected	Karimganj	1	Patherkandi - Soulth Bilbari Right Bank South Bilbari As reported by AEE, Water Resource, Patharkandi due to incessant rainfall on 20/06/2022 a slump down occurred on Right Bank of River Longai at South Bilbari. Approx length is 20 meter. (Long - 92.297632, Lat - 24.589442)
	Lakhimpu r	1	Bihpuria - Dikrong L/B embankment at Bongalmora PGR At Kathalguri (14th km) and Balichapori (15th km) As reported by the officials of WRD, Bihpuria SD, severe bank migration is active and continuing from 21/06/2022 at Kathalguri (14th km) and Balichapori (15th km) area of Dikrong L/B embankment. The embankment is in major threat as present available bank margin is only 15 to 20
	Total	3	meters. (Long - 93.930105, Lat - 27.048204)
		Numbe	
	District	r	Details
Infrastructu re Damaged - Road	Bajali	12	Bajali - HuduKhata Naosali Pachim Rihabari This Rood Has Breached. Length 12 m. & Dep. 4m. This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Bamakhata Kenduguri Road, Bamakhata Kenduguri Road, Length 1km, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Pathsala Station Road, Pathsala Length 50m, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Birbira To Bamakhata Road Bamakhata Shoulders Damaged 500m. This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Dumuria Village Road Dumuria Shoulders damaged 150m, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Patacharkuchi Achali Road Patacharkuchi to Anchali Length 3.89km, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Nityananda Panbari Road Nityananda panbari Length 3.150Km, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Nityananda to Pathsala Road Nityananda To Pathsala Length 1.60km, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Anandapur Ghelengpara Road Anandapur Length 1.25Km, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Chaibari To rihabari Road Rihabari Length 1.1 Km, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000), Chaibari To rihabari Road Rihabari Length 3.75Km, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission
	Barpeta	2	Barpeta - Madhulijar Purabharal Road Madhulijar Side berm eroded & Culvert Damage 10.00 m PWRD Barpeta DOO 17.06.2022 (Long - 90.950277, Lat - 26.411631), Howly Joypur Road Howly Side berm eroded & Culvert Damage 10.00 m PWRD Barpeta DOO 17.06.2022 (Long - 90.004030, Lat - 26.453685)
	Darrang	24	Mangaldoi - Naharbari Road under PWRD under Mangaldai Revenue Circle as reported by Naharbari Road under PWRD is submerged under flood water and the length of submergence is 100 mtr. approx. Dated 22-6-2022 (Long - 91.950000, Lat - 26.490000), Outola Road under PWRD under Mangaldai Revenue Circle as reported by Outola Road under PWRD is submerged under flood water and the length of submergence is 300 mtr. approx. Dated 22-6-2022 (Long - 91.960000, Lat - 26.480000), Outola Naharbari Road under PWRD under Mangaldai Revenue Circle as reported by Outola Naharbari Road under PWRD is submerged under flood water and the length of submergence is 100 mtr. approx. Dated 22-6-2022 (Long - 91.960000, Lat - 26.500000), Outola Naharbari Road under PWRD under Mangaldai Revenue Circle as reported by Outola Naharbari Road is submerged under flood water and the length of submergence is 30 mtr. approx. Dated 22-6-2022 (Long - 91.960000, Lat - 26.500000), Outola Road to Motonga Ahaka Road under PWRD under Mangaldai Revenue Circle as reported by Outola Road to Motonga Ahaka Road is submerged under flood water and the length of submergence is 300 mtr. approx. Dated 22-6-2022 (Long - 91.960000, Lat - 26.490000), Naharbari Road under PWRD under Mangaldai Revenue Circle as reported by Naharbari Road under PWRD under Mangaldai Revenue Circle as reported by Naharbari Road under PWRD under Mangaldai Revenue Circle as reported by Naharbari Road to

			Motonga Ahaka Road is submerged under flood water and the length of submergence is 200 mtr.
			approx. Dated 22-6-2022 (Long - 91.960000, Lat - 26.480000),
			Culvert Damage at M.B Road Ch: 10.00 km under PWRD under Mangaldai Revenue Circle as
			reported by Culvert Damage at M.B Road Ch: 10.00 km is submerged under flood water and the
			length of submergence is 20 mtr. approx. Dated 22-6-2022 (Long - 91.000000, Lat - 26.000000), AS-16-72 NH-15 to Monitary PMGSY Road under PWRD under Mangaldai Revenue Circle as
			reported by Culvert Damage at M.B Road Ch: 10.00 km is submerged under flood water and the
			length of submergence is 300 mtr. approx. Dated 22-6-2022 (Long - 91.000000, Lat - 26.000000),
			AS-16-147 Choto Athiyabari to Bordolguri Borochuba PMGSY Road under PWRD under Mangaldai
			Revenue Circle as reported by AS-16-147 Choto Athiyabari to Bordolguri Borochuba PMGSY Road
			is submerged under flood water and the length of submergence is 400 mtr. approx. Dated 22-6-2022
			(Long - 91.920000, Lat - 26.410000),
			AS-16-191 Harinkhuja to RK Road PMGSY Road under PWRD under Mangaldai Revenue Circle
			as reported by AS-16-191 Harinkhuja to RK Road PMGSY Road is submerged under flood water and
			the length of submergence is 700 mtr. approx. Dated 22-6-2022 (Long - 91.000000, Lat - 26.000000),
			AS-16-99 Mangalbesa Road PMGSY Road under PWRD under Mangaldai Revenue Circle as
			reported by AS-16-99 Mangalbesa Road PMGSY Road is submerged under flood water and the length
			of submergence is 600 mtr. approx. Dated 22-6-2022 (Long - 91.000000, Lat - 26.000000),
			Dalgaon - 1. Dharanipur to Shyampur No.4 PMGSY road Dharanipur to Shyampur No.4 PMGSY
			road has been submerged and damaged at CH. 2850 M to 2980 M on 20/06/2022 (Long -
			26.532307, Lat - 92.163290),
			2. No3 Galandikash to Morabega road No3 Galandikash to Morabega road Br. No-1/1 on the river Angsha has been washed away as on 20/06/2022 (Long - 26.574323, Lat - 92.106079),
			3. Dalgaon –Kuwaripukhuri Road Dalgaon –Kuwaripukhuri Road has been breached occurred at CH.
			6330 M to 6345 M as on 20/06/2022 (Long - 26.562847, Lat - 92.137220),
			4. Madhupur to Borghulee road Madhupur to Borghulee road has been rain cut at CH. 0 to 15 M as
			on 20/06/2022 (Long - 26.653686, Lat - 92.175881),
			5. Rangagorapathar to Ghiladhari road Rangagorapathar to Ghiladhari road has been submerged at
			CH.772 M SHPC No.1/1 fully eroded at CH. 6500 breached as on 18-06-2022 (Long - 0.000000,
			Lat - 0.000000),
			6. Nagajan to Bhutpukhuri road Nagajan to Bhutpukhuri road has been breached at approaches of the
			slab culvert at CH. 1020 as on 18-06-2022 (Long - 0.000000, Lat - 0.000000),
			7. Borkur to Shyampur road Borkur to Shyampur road has been submerged about height of 0.45m as
			on 18-06-2022 (Long - 0.000000, Lat - 0.000000),
			Dalgaon to Dhupguri Road Improvement and up gradation of road from Dalgaon to Dhupguri via Dev pukhuri under Asom Mala has been eroded at CH. 700 km as on 18-06-2022 (Long - 0.000000,
			Lat - 0.000000),
			9. Kachomari Char to Badlichar road Kachomari Char to Badlichar road submerged about height 0.4
			m as on 18-06-2022 (Long - 0.000000, Lat - 0.000000),
			10. Kachomari Chapori habi to NH 52 road Kachomari Chapori habi to NH 52 road has been
			submerged as on 18-06-2022 (Long - 0.000000, Lat - 0.000000),
			11. Rowmari Chapori to Kachomari Chapori PMGSY road Rowmari Chapori to Kachomari Chapori
			PMGSY road has been submerged about height of .45m as on 18-06-2022 (Long - 0.000000, Lat -
			0.000000),
			Patharighat - Roinakuchi LP school to Athkuria LP school road PWD road Roinakuchi LP school to
			Athkuria LP school road Breach 20 mt length on Roinakuchi LP school to Athkuria LP school as
			reported by JE on 23.6.2022 (Long - 91.899235, Lat - 26.444089),
			MPK road Tujukpara Breach and CD damaged 20 mt length on MPK road to Tujukpara as reported
			by JE on 23.6.2022 (Long - 91.895586, Lat - 26.446523) Sissiborgaon - PWD road Jonai link road to NH52 via Kalyankendra Road, At Ch 450.00 M to Ch
	Dhemaji	1	490.00 M Damaged the road embankment partially, damaged side shoulder, hard crust along with BT
	2 manuji	1	surface, Around length 40 mts on 22-06-2022 (Long - 94.731321, Lat - 27.585447)
			Bilasipara - SALKOCHA BHELUPARA ROAD (.)PMGSY PACKAGE NO. AS-05-114 DAMAGE
			APPROACHES OF HPC NO. 1/1 & SIDE BERM DUE TO HIGH RISE FLOOD WATER OF
			RIVER GAURANG SALKOCHA BHELUPARA ROAD ROADS HAVE BEEN AFFECTED BY
			THE FLOOD WATER W.E.F. 13/06/2022 TO 18/06/2022 (Long - 90.332578, Lat - 26.228025),
			NH-31 TO BAGULAURA ROAD(.) FORMATION DAMAGES IN STRECHES & EXISTING
			CULVERT DAMAGED DUE TO HIGH FLOOD WATER OF RIVER GAURANG NH-31 TO
			BAGULAURA ROAD ROADS HAVE BEEN AFFECTED BY THE FLOOD WATER W.E.F.
	DI 1 :	40	13/06/2022 TO 18/06/2022 (Long - 90.293722, Lat - 26.216275),
	Dhubri	40	BILASIPARA HAKAMA ROAD TO BARUARJHAR VILLAGE ROAD(,) SIDE BERM
			ERRODED DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG BILASIPARA
			HAKAMA ROAD TO BARUARJHAR VILLAGE ROAD ROADS HAVE BEEN AFFECTED BY THE FLOOD WATER W.E.F. 13/06/2022 TO 18/06/2022 (Long - 90.263126, Lat - 26.243861),
			NH-31 AT SURJYAKHATA TO HAUDERTARY ROAD(,) (PMGSY PACKAGE NO. AS-05-55)
			SIDE BERM DAMAGES DUE TO HIGH RISE FLOOD WATER OF DIPO RIVER NH-31 AT
			SURJYAKHATA TO HAUDERTARY ROAD ROADS HAVE BEEN AFFECTED BY THE
			FLOOD WATER W.E.F. 13/06/2022 TO 18/06/2022 (Long - 90.223965, Lat - 26.259173),
			EXTENSION OF KAJAIKATA HIGH SCHOOL TO ASKARIGHATROAD(,) APPROACHES OF
		•	572

BOXCELL NO. ½ DAMAGES & SIDE BERM ERRODED DUE TO HIGH RISE FLOOD WATER OF RIVER GAURANG | EXTENSION OF KAJAIKATA HIGH SCHOOL TO

ASKARIGHATROAD | ROADS HAVE BEEN AFFECTED BY THE FLOOD WATER W.E.F. 13/06/2022 TO 18/06/2022 | (Long - 90.198980, Lat - 26.183278),

UDMARI SALKOCHA ROAD (.)PMGSY PACKAGE NO. AS-05-209 DAMAGE APPROACHES OF RCC NO. 2/1 DUE TO HIGH RISE FLOOD WATER OF RIVER BRAHMAPUTRA | UDMARI SALKOCHA ROAD | ROADS HAVE BEEN AFFECTED BY THE FLOOD WATER W.E.F. 13/06/2022 TO 18/06/2022 | (Long - 90.337631, Lat - 26.238244),

MAYERCHAR PT-I (GHUNIMARI) VILLAGE ROAD (.)WASHED AWAY AT CH. 70.00 M, 200.00 M & 290.00 M DUE TO HIGH RISE FLOOD WATER OF RIVER BRAHMAPUTRA | MAYERCHAR PT-I (GHUNIMARI) VILLAGE ROAD | ROADS HAVE BEEN AFFECTED BY THE FLOOD WATER W.E.F. 13/06/2022 TO 18/06/2022 | (Long - 90.226997, Lat - 26.148657), **Dhubri** - SIDE BERM AND SID SLOPES DAMAGED AT 1ST KM, 2ND KM & 3RD KM IN STRETCHES ON KACHUARKHASH PT-II (DB ROAD NEA CHANDAKHOLA BRIDGE) TO KACHUARKHASH PT-I | KACHUARKHASH | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

ROAD FORMATION DAMAGED AT 1ST KM ON DURAHATI TISTARPAR ROAD TO DURAHATI BUND CUM ROAD | DURAHATI TISTARPAR | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SID EBERM AND SIDE SLOPES DAMAGED AT 1ST KM IN STRETCHES ON VELAKOBA DURAHATI PWD ROAD TO NAMAGAON ROAD | VELAKOBA DURAHATI | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SID EBERM AND SIDE SLOPES DAMAGED AT 1ST & ND KM IN STRETCHES ON PATAMARI BSF CAMP TO PATAMARI BAZAR | PATAMARI | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM AND SIDE SLOPES DAMAGED AT 1ST KM IN STRETCHES ON KISMATHASDAHA SILGHAGRI ROAD TO DHARMASALA MARKET | KISMATHASDAHA SILGHAGRI ROAD TO DHARMASALA | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

ROAD FORMATION AND SIDE BERM DAMAGED AT 1ST & 2ND KM IN STRETCHES ON HARIALI ROAD TO BALADOBA PT-II ROAD | BALADOBA | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM AND SIDE SLOPE DAMAGED AT 1ST KM IN STRETCHES ON KISMATHASDAHA PT-I TO KACHUARKHASR PT—II ROAD | KISMATHASDAHA PT-I TO KACHUARKHASR PT—II | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM AND SIDE SLOPES DAMAGED AT 1ST KM IN STRETCHES ON DHUBRI BINNACHARA PWD ROAD TO CHAUDHURYPARA ROAD | BINNACHARA PWD ROAD TO CHAUDHURYPARA | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000), SIDE BERM AND SIDE SLOPES DAMAGED AT 1ST & 2ND KM IN STRETCHES ON KISMATHASDAHA PT-IV TO DB ROAD | KISMATHASDAHA | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM AND SIDE SLOPES DAMAGED AT 1ST KM IN STRETCHES ON TISTARPAR BOP ROAD TO TISTARPAR PT-I ROAD | TISTARPAR | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM AND SIDE SLOPES DAMAGED AT 1ST KM IN STRETCHES ON DHUBRI BINNACHARA ROAD TO ALIRGAON LP SCHOOL | DHUBRI BINNACHARA ROAD TO ALIRGAON | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000), ROAD FORMATION DMAGED AND SUBMERGED AT 1ST & 2ND KM ON VELAKOBA DURAHATI PWD ROAD TO SINGIMARI PART-II ROAD IN STRETCHES | VELAKOBA DURAHATI PWD ROAD TO SINGIMARI PART-II | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM AND SIDE SLOPE DAMAGED AT 1ST KM OF MOTIRCHAR DHARMASALA ROAD IN STRETCHES | MOTIRCHAR DHARMASALA | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM AND SIDE SLOPES DAMAGED AT 1ST KM IN STRETCHES OF I.G. ROAD | I.G. ROAD DHUBRI | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000), ROAD FORMATION DAMAGED AT 3RD TO 5TH & 7TH TO 8TH KM IN STRETCHES OF DHUBRI GAURIPUR ROAD | DHUBRI GAURIPUR ROAD | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

ROAD FORMATION SUBMERGED AND DAMAGED FROM CH. 400.00 M TO CH. 600.00 M IN STRETCHES OF GHEWMARI BSF CAMP TO IBB FENCHING ROAD | GHEWMARI BSF CAMP TO IBB FENCHING ROAD | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000).

SIDE SLOPE AND SIDE BERM DAMAGED AT 1ST KM IN STRETCHES OF GASPARA BAZAR TO PANCHAYAT OFFICE ROAD | GASPARA | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

SIDE BERM & SIDE SLOPES DAMAGD AT 1ST KM ON MOULANI BHASANI ROAD | BHASANI | DATED-18-06-2022 TO 23-06-2022 | (Long - 0.000000, Lat - 0.000000),

			SIDE BERM & SIDE SLOPES DAMAGED AT 1ST & 2ND KM ON KACHARIHATI DURAHATI PWD ROAD TO BHELAKOWA SC PARA ROAD KACHARIHATI DURAHATI PWD ROAD TO BHELAKOWA DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000, Lat - 0.000000), SIDE BERM & SIDE SLOPES DAMAGED AT 1ST KM ON CHAR DURAHATI MASZID ROAD DURAHATI DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000, Lat - 0.000000), SIDE BERM & CULVERT APPROCHES DAMAGED ON MOTIRCHAR DHARMASLA TO HAWRARPAR VILLAGE ROAD AT 1ST KM MOTIRCHAR DHARMASLA TO HAWRARPAR VILLAGE ROAD AT 1ST KM MOTIRCHAR DHARMASLA TO HAWRARPAR VILLAGE ROAD AT 1ST KM MOTIRCHAR DHARMASLA TO HAWRARPAR SIDE SLOPE & CULVERT APPROACH DAMAGED ON DHARMASLA BUS STAND TO DHARMASALA PT-V AT 1ST & 2ND KM DHARMASLA DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000), SIDE BERM SIDE SLOPE & CULVERT APPROACH DAMAGED ON DHARMASLA BUS STAND TO DHARMASALA PT-V AT 1ST & 2ND KM DHARMASLA DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000), SIDE BERM DAMAGED ON MOTIRCHAR DHARMASALA ROAD TO DHARMASALA MANDIR AT 1ST KM MOTIRCHAR DHARMASALA DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000), Lat - 0.000000), SIDE BERM & SIDE SLOPES DAMAGED ON GASPARA NEAR DHARMASALA OUT POST ROAD TO VELAKOBA ROAD AT 1ST KM VELAKOBA DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000, Lat - 0.000000), SIDE BERM & SIDE SLOPES DMAGED ON DHUBRI PATAMARI ROAD TO JUNGLIA VILLAGE ROAD AT 1ST & 2ND KM JUNGLIA DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000, Lat - 0.000000), AT - 0.000000), AT - 0.000000), ROAD HAS BEEN SUBMERGED AND BADLY DAMAGED KANAIMORE TO BEGUNTOLI AT 1ST AND 2ND KM BEGUNTOLI DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000), Lat - 0.000000), ADDAMAGED ON KGT TO JINKATA Dt. 04/06/2022-15/06/202 KGT TO JINKATA (Long - 0.000000), Lat - 0.000000), Lat - 0.000000), Lat - 0.000000, Lat - 0.000000, Lat - 0.000000, Lat - 0.000000), SIDE BERM DAMAGED ON KGT LINK ROAD TO SIMLABARI SATRA 1ST & 2ND KM (Long - 0.000000), Lat - 0.000000),
			SIDE BERM DAMAGED AT 1ST & 2ND KM ON KALDOBA SINDURAI ROAD Dt. 04/06/2022- 15/06/2022 1ST & 2ND KM ON KALDOBA SINDURAI ROAD (Long - 0.000000, Lat -
			0.000000)
C	Goalpara	1	Lakhipur - Nikaripara Road At Nikaripara As per report of PWD Roads Department, Nikaripara Road has been damaged due to strong current of flood water and the damage road is verified on 22.06.2022. (Long - 90.306457, Lat - 26.047190)
K	Kamrup	2	Rangia - Old N.T Road Vill- Rangia Town The Old N.T Road was damaged by the flood waters as per report of AEE, PWD, NKT, Roads, Rangia on 20.6.2022 (Long - 91.609246, Lat - 26.439255), Chamaria - Howli to Howlitary Howlitary Road submerged of the road namely Howli to Howlitary
			had taken place on dated 23.06.2022 and the same has been reported by AEE, PWD, Boko territorial road sub-division on dated 23.06.2022 (Long - 91.036878, Lat - 26.285753) Chandrapur - dhamkhunda Maloi basti dighalihati to dhipujijan pam road (PMGSY Pkg NO. AS 11
	Kamrup M)	1	663) Submerged from ch 1200.0 m to 2500.00 m, 2600.0 m to 3350. m, 3410.0 m 4200.0 m. avg. Deprth of submergence = .06m lat: 26.22935 long: 91.988395 dhamkhunda Maloi basti dighalihati to dhipujijan pam road (PMGSY Pkg NO. AS 11 663) Submerged from ch 1200.0 m to 2500.00 m, 2600.0 m to 3350. m, 3410.0 m 4200.0 m. avg. Deprth of submergence = .06m lat: 26.22935 long: 91.988395 Date-23/06/2022 (Long - 0.000000, Lat - 0.000000)
K	Karimganj	1	Patherkandi - Patharkandi-Mukamtilla Road to Kabaribond Pt-III Kabaribond As reported by AEE, PWD (T/R), Patharkandi, PMGSY Road's side beem eroded and ICBP surface damaged due to incessant rainfall on 19/06/2022. Approx length of damages is 20 meter. (Long - 92.304242, Lat - 24.605816)
K	Kokrajhar	34	Gossaigaon - SORAIBIL PWD ROAD TO BALAGAON SORAIBIL AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD GOSSAIGAON SORAIBIL PWD ROAD TO BALAGAON 1.5 KM (Long - 0.000000, Lat - 0.000000), SORAIBIL KATRIBARI ROAD SORAIBIL AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD CROSSLY BREACHED AT SORAIBIL KATRIBARI ROAD AND REPAIRING REQUIRED 2KM (Long - 0.000000, Lat - 0.000000),

GOSSAIGAON SORAIBIL | SORAIBIL | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF GOSSAIGAON SORAIBIL ROAD FROM 21 KM ZION ENGLISH MEDIUM SCHOOL ROAD SUBMERGED WITH HPC (S) CULVERT DAMAGED | (Long - 0.000000, Lat - 0.000000),

SSB CAMP ROAD | RAIMONA | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF SSB CAMP ROAD EROSION ON RAIMONA DUHIKOLA ROAD AT 2 KM | (Long - 0.000000), Lat - 0.000000),

SOUTH DUMBAZAR TO RANIPUR | RANIPUR | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON SOUTH DUMBAJHAR TO RANIPUR ROAD WOODEN BRIDGE DAMAGED AND ROAD FORMATION SUBMERGED AT 1 KM | (Long - 0.000000, Lat - 0.000000).

POKALAGI LP SCHOOL TO GAMBARIDHAM ROAD | POKALAGI | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON POKALAGI LP SCHOOL TO GAMBARIDHAM ROAD FORMATION FULLY DAMAGED | (Long - 0.000000), Lat - 0.000000),

JANALIGAON BAZAR TO KUSUMBIL LP SCHOOL | JANALIGAON | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN (PART-I) IMMEDIATE RESTORATION OF FLOOD DAMAGED AND EROSION ROAD FROM JANALIGAON BAZAR TO KUSUMBIL LP SCHOOL ROAD WITH BOULDER PROTECTION WORK. | (Long - 0.000000, Lat - 0.000000),

JANALIGAON BAZAR TO KUSUMBIL LP SCHOOL | JANALIGAON | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN (PART-II) IMMEDIATE RESTORATION OF FLOOD DAMAGED AND EROSION ROAD FROM JANALIGAON BAZAR TO KUSUMBIL LP SCHOOL ROAD WITH BOULDER PROTECTION WORK. | (Long - 0.000000, Lat - 0.000000),

JANALIGAON BAZAR TO KUSUMBIL LP SCHOOL | JANALIGAON | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN (PART-III) IMMEDIATE RESTORATION OF FLOOD DAMAGED AND EROSION ROAD FROM JANALIGAON BAZAR TO KUSUMBIL LP SCHOOL ROAD WITH BOULDER PROTECTION WORK. | (Long - 0.000000, Lat - 0.000000),

JANALIGAON BAZAR TO KUSUMBIL LP SCHOOL | JANALIGAON | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN (PART-IV) IMMEDIATE RESTORATION OF FLOOD DAMAGED AND EROSION ROAD FROM JANALIGAON BAZAR TO KUSUMBIL LP SCHOOL ROAD WITH BOULDER PROTECTION WORK. | (Long - 0.000000, Lat - 0.000000),

DALGAON TO RANIPUR | RANIPUR | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF DALGAON TO RANIPUR VILLAGE VIA BORDER ROAD 15 MTRS SUBMERGE. | (Long - 0.000000, Lat - 0.000000),

BOSHGAON TO RAIMONA | RAIMONA | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN PERMANENT RESTORATION OF BOSHGAON TO RANIPUR VIA HOSPITAL ROAD FORMATION DAMAGED AT 1.00 KM | (Long - 0.000000, Lat - 0.000000),

BOSHGAON TO RAIMONA TOWARDS MOTHAMBIL | RAIMONA | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN PERMANENT RESTORATION OF BOSHGAON TO RAIMONA VIA HOSPITAL TOWARDS MOTHAMBIL ROAD FORMATION DAMAGED AT 600.00 MTRS | (Long - 0.000000, Lat - 0.000000),

KURSHAKATI TO ANTGTHIHARA | KURSHAKATI | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 21.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KURSHAKATI TO ANGTHIHARA RCC BRIDGE VIA DOLABARI PWD ROAD FULLY SUBMERGED & ROAD FORMATION DAMAGED FROM 1 KM TO 5 KM | (Long - 0.000000, Lat - 0.000000),

GAIDANG BAZAR TO JIAGURI VILLAGE | JIAGURI | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN GAIDANG BAZAR TO JIAGURI VILLAGE ROAD 15.00M ROAD FORMATION HAS BEEN FOUND DAMAGE, REQUIRED 2 CELL 2X2 VOX CULVERT REQUIRED | (Long - 0.000000, Lat - 0.000000).

KACHUGAON SANKOSH ROAD TO BALLAMJHORA | BALLAMJHORA | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN SUBMERGED AND DAMAGED ROAD FORMATION FROM 1KM TO 3 KM OF KACHUGAON SANKOSH ROAD TO BALLAMJHORA | (Long - 0.000000, Lat - 0.000000), KACHUGAON SANKOSH ROAD TO KATRIBARI | KACHUGAON | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF SUBMERGED ROAD 1 KM FROM KACHUGAON SANKOSH TO KATRIBARI ANGANBARI LP SCHOOL PROVIDING SAND AND

GRAVELLING | (Long - 0.000000, Lat - 0.000000), POKALAGI BAZAR TO KACHUGAON SANKOSH | POKALAGI BAZAR | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF SUBMERGED PF 2800.00M FROM POKALAGI BAZAR TO KACHUGAON SANKOSH BY PROVIDING AND GRAVELLING ROAD | (Long -0.000000, Lat - 0.000000), KACHUGAON SANKOSH ROAD TO RAJENDRAPUR | KACHUGAON | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF SUBMERGED ROAD 1KM FROM KACHUGAON SANKOSH ROAD TO RAJENDRAPUR | (Long - 0.000000, Lat - 0.000000), PANBARI SIALMARI ROAD | PANBARI | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF PANBARI SIALMARI ROAD FORMATION WASHED OUT AT CH. 400.00M | (Long - 0.000000, Lat - 0.000000), SSB BAZAR TO BOLLAMJHORA | BOLLAMJHORA | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF SUBMERGED AT SSB BAZAR TO BALLAMJHORA ROAD | (Long -0.000000, Lat - 0.000000), BOLLAMJHORA TO BONGAON | BONGAON | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF BOLLAMJHORA TO BONGAON SSB CAMP | (Long - 0.000000, Lat -0.000000), Kokrajhar - HEKAIPRA NAMAPARA ROAD | HEKAIPARA | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 18.06.2022, HEKAIPARA TO NAMAPARA ROAD AT CHAINAGE 200.00M WAS DAMAGED | (Long -0.000000, Lat - 0.000000), DURAMARI MES TO SOUTH DURAMARI | DURAMARI | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 18.06.2022, DURAMARI MES TO SOUTH DURAMARI VILLAGE ROAD AT CHAINAGE 200.00M WAS DAMAGED | (Long - 0.000000, Lat - 0.000000), SESAPANI LPS TO MADHAY SESAPANI | SESAPANI | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 18.06.2022, SESAPANI LPS TO MADHAY SESAPANI VILLAGE ROAD CH 400.00M WAS DAMAGED | (Long - 0.000000, Lat - 0.000000), KUMGURI ROAD | KUMGURI | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, KUMGURI TO CHOUHAN BASTI VILLAGE ROAD AT CH 1500.00M WAS BREACHED | (Long - 0.000000, Lat - 0.000000), Dotma - Monakocha to Jodumani Road | Vill- Jodumani | As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of Monakocha to Jodumani road by Flood RCC box cell on 23-06-2022 | (Long - 0.000000, Lat - 0.000000), Angthihara to Umanagar road | Umanagar | As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of Angthihara to Umanagar road by Flood washed out at 1km by 25.00m length on 23-06-2022 | (Long - 0.000000, Lat - 0.000000), Surjayakata to Gwthaibari road | Gwthaibari | As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of Surjakata to Gwthaibari road by Flood on 23-06-2022 | (Long -0.000000, Lat - 0.000000), Anthaibari to Gomobil Road | Gomobil | As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of Anthaibari to Gomobil road by Flood on 23-06-2022 | (Long -0.000000, Lat - 0.000000), Kumguri Alongbar Club to Kunthaibari Road | Kunthaibari | As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of Kumguri Alongbar Club to Kunthaibari Road by Flood on 23-06-2022 | (Long - 0.000000, Lat - 0.000000), Boragari to Narenguri Road | Narenguri | As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of Boragari to Narenguri via Kolobari Road breached at 2nd km by 30.00m length and wodden bridge No. 2/1 damaged on 23-06-2022 | (Long - 0.000000, Lat -0.000000). NH31C to Kujrabguri Road | Kujrabguri | As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of NH 31C to Kujrabguri Road formation submerged by erosion at 2km on 23-06-2022 | (Long - 0.000000, Lat - 0.000000), East Ghilaguri to Bhalukmari village connecting road | Ghilaguri | As reported by Dotma Revenue Circle, Damage of village road and bridge of East Ghilaguri to Bhalukmari village connecting road on 23-06-2022 | (Long - 90.181625, Lat - 26.476254) Bhuragaon - Taptola to chenia Road | Taptola | Taptola to chenia Road submerged by flood water from chainage 2200.00m to 2500.00m, Ch 3700.00m to 3900.00m of Road part I & ch 450.00 to 650.00m and ch 720.00m to 900.00m of road part II on 21/06/2022. | (Long - 26.320578, Lat -4 92.181969), Morigaon Morigaon - Oujari to Bahakabari road (22-06-2022) | Oujari, Morigaon | As per PWD (Roads) Oujari to Bahakabari road under submergence for a length of 300m (ch.1000 to 1300m) Avg depth of submergence = 0.30m approx. | (Long - 92.279306, Lat - 26.237363),

Boghora Sitala Mandir road (23-06-2022) | Boghora, Morigaon | As per PWD (Roads) Boghora Sitala Mandir road is under submergence from ch.1030m to 1200m. Avg depth of submergence = 0.30m | (Long - 92.273965, Lat - 26.238950), Narayan Bazaar chariali to Basanaghat Bhuragaon road (23-06-2022) | Ahatguri Natuagaon, Narayan Bazar, Morigaon | As per PWD (Roads) Narayan Bazaar chariali to Basanaghat Bhuragaon road at Sidhabari is under submergence from Ch.1800m to 1980m. Avg depth of submergence= 0.20m. (Long - 92.310917, Lat - 26.251013) Nagaon - Solmari to Kakalichuk AS-19 595 | Solmari to Kakalichuk | Solmari to Kakalichuk AS-19 595, Submerged/damaged reported by PWD Barhampur Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), Nonoi jenganichuk to Japisojia | Nonoi jenganichuk to Japisojia | Nonoi jenganichuk to Japisojia, submerged/damaged, reported by PWD Barhampur Territorial Road Sub - Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), CN Road | CN Road | CN Road, submerged/damaged, Length-8th to 9th Km reported by PWD Barhampur Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), Ghugargaon to Kumargaon | Ghugargaon to Kumargaon | Ghugargaon to Kumargaon ,submerged/damaged,Length-1 to 2 Km reported by PWD Barhampur Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), NH-36 Badalgaon to Ghugargaon | NH-36 Badalgaon to Ghugargaon | NH-36 Badalgaon to Ghugargaon ,submerged/damaged,Length-1 Km reported by PWD Barhampur Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), NH-36 Kumargaon to Nibukali Road | NH-36 Kumargaon to Nibukali Road | NH-36 Kumargaon to Nibukali Road ,submerged/damaged,reported by PWD Barhampur Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), Sutargaon to Na-Kumargaon | Sutargaon to Na-Kumargaon | Sutargaon to Na-Kumargaon, submerged/damaged,reported by PWD Barhampur Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), NH-36 Badalgaon to Panikhaiti | NH-36 Badalgaon to Panikhaiti | NH-36 Badalgaon to Panikhaiti ,submerged/damaged,reported by PWD Barhampur Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), Haiborgaon Senchuwa Mowamari Kuh Bebejia Road | Haiborgaon Senchuwa Mowamari Kuh Bebejia Road | Haiborgaon Senchuwa Mowamari Kuh Bebejia Road, submerged/damaged, Length-4 to 7Km reported by PWD Nagaon Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat -0.000000),Nagaon Dakhinpat Road to Milanpur | Nagaon Dakhinpat Road to Milanpur near Khagarijan RCC Bridge | Nagaon Dakhinpat Road to Milanpur near Khagarijan RCC Bridge ,submerged/damaged,Length-15m reported by PWD Nagaon Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), 21 Nagaon Milanpur Bylane No.-2 | Milanpur | Milanpur Bylane No.-2, submerged/damaged, Length-120m, Depth -200-300mm reported by PWD Nagaon Territorial Road Sub -Division, dated-23/06/2022 (Long - 0.000000, Lat - 0.000000), Milanpur Bylane No.-3 | Milanpur Bylane No.-3 | Milanpur Bylane No.-3.submerged/damaged,Length-120m, Depth -200-300mm reported by PWD Nagaon Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000). Milonpur Bihutali Road | Milonpur Bihutali Road | Milonpur Bihutali Road .submerged/damaged,Length-70m, Depth -200-300mm reported by PWD Nagaon Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), Haiborgaon Girls College to ASTC Foot Bridge | Haiborgaon Girls College to ASTC Foot Bridge | Haiborgaon Girls College to ASTC Foot Bridge, submerged/damaged, Length-100m, Depth-200-250mm reported by PWD Nagaon Territorial Road Sub -Division, dated-23/06/2022 | (Long -0.000000, Lat - 0.000000), Greenland raod | Greenland raod | submerged/damaged, Length-150m, Depth-200-300mm reported by PWD Nagaon Territorial Road Sub -Division, dated-23/06/2022 | (Long - 0.000000, Lat - 0.000000), Raha - PMGSY road from Darangialgaon to Putakollong via Nakhanda | Darangialgaon | Date of Occurrence- 22/06/2022 Submerged- at several stretches Department- Morigaon Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Raha Barapujia Road to Matharbori via Saraligaon Khaplangkuchi | Matharbori | Date of Occurrence-21/06/2022 Submerged- at several stretches Department- Morigaon Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NH-37 to Mulankata Adarshagaon | Mulankata | Date of Occurrence- 21/06/2022 Submerged- at several stretches Department- Morigaon Territorial Road Sub-Division | (Long - 0.000000, Lat -0.000000), MRL04-Basanaghat Khandajan to Bordoloipathar via Ajarbari | Khandajan | Date of Occurrence-23/06/2022 Submerged-from 270m to 520 m Department- Morigaon Dist. Territorial Road Division (Long - 0.000000, Lat - 0.000000), Khandajan Bakorichapari road | Khandajan | Date of Occurrence- 23/06/2022 Submerged-from 750 m to 900 m & 1000 m to 1800 m Department- Morigaon Dist. Territorial Road Division | (Long -0.000000, Lat - 0.000000), NH-37 to Mulankata Adarshagaon | Mulankata | Date of Occurrence- 23/06/2022 Submerged-from

Hoo in to 400 m, 450 m in 525 m & 750 m to 1400 m Department. Morigon Dist. Territorial Road Devision (Long 0,000000, Lat - 0,000000).	 1	T	1
Pakowa (Submerged length 700 m. Information received from PWRD Department on 17:06:2022 via WT message. [1 Cung0.00000, Lat0.000000]. Barbheri Ranekuchi Danguapara Road [Danguapara (Submerged length 1.5 m. Information received from PWRD Department on 17:06:2022 via WT message. [1 Cung0.000000, Lat0.000000]. Blupen Hazarika path at Baikaria Khanjara [Khanjara [Submerged length 5:06 m. Information received from PWRD Department on 17:06:2022 via WT message. [1 Cung0.000000, Lat0.00000]. Kumikania to Niz Bahjani road [I Amarikania [Submerged length 5:06 m. Information received from PWRD Department on 17:06:2022 via WT message. [1 Cung0.000000, Lat0.00000]. Jaha to Charia Road [I Ada [Submerged length 1:5 m. Information received from PWRD Department on 17:06:2022 via WT message. [1 Cung0.000000]. Road from Debre Kalakuchi to Makaddabal Debrehalakuchi [Submerged length 5:2 m. Information received from DewRD Department on 18:06:2022 via WT message. [Long0.00000]. Road from Debre Kalakuchi to Makaddabal Debrehalakuchi [Submerged length 5:2 m. Information received from PWRD Department on 18:06:2022 via WT message. [Long0.00000]. Road from Debre Kalakuchi to Makaddabal Debrehalakuchi [Submerged length 5:2 m. Information received from PWRD Department on 18:06:2022 via WT message. [Long0.00000]. Lat0.000000]. This - THU III SI BACKSIDE ROAD [THU TOWN I LENGTH-SOMTS INSPORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED :17:06:2022 [Long0.00000]. Lat0.000000]. POWER HOUSE SIDE ROAD (BIDYANAGAR). [VARD-2,THU TOWN] LENGTH-SKNTIS.INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED :17:06:2022 [Long0.000000]. LENGTH-SKNTIS.INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED :17:06:2022 [Long0.00000]. THU GRIS SIG (SYALANE) [VARD-2,THU TOWN] LENGTH-SOMTS INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED :17:06:2022 [Long0.00000]. LAT0.000000]. BIDYANAGAR AND SIGNAL AND SIGNAL SIGNAR SIGNAR SIGNAR SIGNAR SIGNAR SIGNAR SIGNAR SIG			100 m to 400 m, 450 m to 525 m & 750 m to 1400 m Department- Morigaon Dist. Territorial Road Division (Long - 0.000000, Lat - 0.000000)
WT message. [Paschim Nalbari - Sandheli Pakowa road to Lt Braja Dutta house via Deka Supa at Niz Pakowa Niz
Barkheiri Banekuch Danguspana Road Danguapara Submerged length 1.5 m. Information received from PWRD Department on 1706/2022 via WT message. (Long 0.000000). Lat - 0.000000). Bilupen Hazarika path at Bailkaria Kharjari Kharjari Submerged length 200 m. Information received from PWRD Department on 1706/2022 via WT message. (Long 0.000000). Lat - 0.000000). Kamikata to Ntz- Baijairi road kumarikata Submerged length 5.64 m. Information received from PWRD Department on 1706/2022 via WT message. (Long 0.000000). Lat - 0.000000). Jaha to Charia Road Jaha Submerged length 1.5 m. Information received from PWRD Department on 1706/2022 via WT message. (Long 0.000000). Lat - 0.000000). Road from Debter Kalakucht to Makaddeal Debtedalakucht Submerged length 2.5 m. Information received from PWRD Department on 1716/2022 via WT message. (Long 0.000000). Lat - 0.000000). Kadaya Napitara Road Kaleya Submerged and Breach length 1.0 m. near No.2 Napitara. Information received from PWRD Department on 1806/2022 via WT message. (Long 0.000000). Tah 1100 ISB ADCKSIDE ROAD THEN TOWN LENGTHE-SORINS INFORMATION RECEIVED FROM CHAIRMAN, TMR, DATE OF SUBMERGED : 1706/2022 (Long 0.000000). Lat - 0.000000). POWER HOUSE SIDE ROAD (BIDYANAGAR) WARD-ZITHUT TOWN LENGTHE-SKRWINSINSORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED : 1706/2022 (Long 0.000000). Lat - 0.000000). POWER HOUSE FROM TSIDE ROAD WARD-ZITHUT TOWN LENGTHE-SKRWINSINSORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED : 1706/2022 (Long 0.000000). Lat - 0.000000). THU (GRI S HS, (BYARD-ZITHUT TOWN LENGTHE-SKRWINSINSORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED : 1706/2022 (Long 0.000000). Lat - 0.000000). MASCUR ROAD WARD-ZITHUT TOWN LENGTHE-SKWITSINFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED : 1706/2022 (Long 0.000000). Lat - 0.000000). Lat - 0.000000). Lat - 0.000000). NACHTA ROAD WARD-ZITHUT TOWN LENGTHE-SKWITSINFORMATION RECEIVED FROM CHAIR			Pakowa Submerged length 700 m. Information received from PWRD Department on 17/06/2022 via
from PWRD Department on 17/08/2022 via WT message; 1(Long 0.000000), Lat 0.000000), Knimikata to Nit. Balipain road at Knahraji Khaingai, Submerged elogib 200 m. Information received from PWRD Department on 17/08/2022 via WT message; 1(Long 0.000000), Lat 0.000000), Jaha to Charia Road Jaha i Submerged elogib 1.5 m. Information received from PWRD Department on 17/08/2022 via WT message; 1(Long 0.000000), Lat 0.000000), Brands to Charia Road Jaha i Submerged elogib 1.5 m. Information received from PWRD Department on 17/08/2022 via WT message; 1(Long 0.000000), Road from Deber Kalikachi in Okadadaha Debertakiachi Submerged length 2.5 m. Information received from PWRD Department on 17/08/2022 via WT message; 1(Long 0.000000), Kakaya Napipara Road Kakaya Nubmerged and Breach length 10 m. near No. 2 Napipara. Information received from PWRD Department on 17/08/2022 via WT message; 1(Long 0.000000), Lat 0.000000. Time THU HS BACKSIDE ROAD THU TOWN LENGTH-500MTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SIMMERGED: 17/06/2012 (Long 0.000000), Lat 0.000000. Lat 0.000000] Developed HOURS SIDE ROAD GROUND LENGTH-500MTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SIMMERGED: 17/06/2012 Long 0.000000, Lat 0.000000]. Developed HOURS H			
Bibupen Huaratika path at Bailkarian Kharjiral Kharjiran [Submerged length 200 an. Information received from PWRD Department on 17/06/2022 via WT message.] (Long. 9.0000000), Lat - 0.0000000), Kamilkant to Niz Bahjani rotal [sutmarkata] Submerged length 5.64 m. Information received from PWRD Department on 17/06/2022 via WT message. [Long. 9.0000000, Lat - 0.0000000), Jaha to Charia Road J Jaha [Submerged length 1.5 m. Information received from PWRD Department on 17/06/2022 via WT message. [Long. 9.0000000, Lat - 0.000000], Road from Debre Kalakuchi to Makadaba J Debrekalakuchi [Submerged length 2.5 m. Information received from PWRD Department on 17/06/2022 via WT message. [Long. 9.000000, Lat - 0.000000], Kakaya Najutpara Road [Kakaya] Submerged and Breach length 10 m. near No.2 Najutpara. Information received from PWRD Department on 18/06/2022 via WT message. [Long. 9.000000], Lat - 0.000000], Tahu THIRU HS BACKSIDE ROAD [THIRU TOWN] [LENGTH-500MTS.INFORMATION RECEIVED FROM CHAIRMAN, TAMB, DATE OF SUBMERGED 1.706/2022] (Long. 9.000000, Lat - 0.000000), POWER HOUSE SIDE ROAD [RIDYANAGAR], WARD 2.THIRU TOWN LENGTH-1.506/2022] (Long. 9.000000, Tahu 1.000000), POWER HOUSE FROM TSIDE ROAD [WARD 2.THIRU TOWN] LENGTH-1.506/2022] (Long. 9.000000, Lat - 0.000000), TOWER HOUSE FROM TSIDE ROAD [WARD 2.THIRU TOWN] LENGTH-1.506/2022] (Long. 9.000000, Lat - 0.000000), THIRU GIRLS IN SIGN MARKANI SIDENBRAGED 1.706/2022] (Long. 9.000000, Lat - 0.000000), THIRU GIRLS INS (MYALANI SIDENBRAGED 1.706/2022) (Long. 9.000000), Lat - 0.000000), MAS/JD ROAD(MYALANI SIDENBRAGED 1.706/2022) (Long. 9.000000), Lat - 0.000000), NAZIR PATHAK ROAD J WARD - 1.THIRU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 1.7706/2022 (Long. 9.000000), Lat - 0.000000), NAZI			
from PWRD Department on 17/06/2022 via WT message; [Long - 0.000000, Lat - 0.000000], Knnikata for NJ. Bahpia rico all Jumarikan [Submegel length 5.64 m. Information received from PWRD Department on 17/06/2022 via WT message. [Long - 0.000000, Lat - 0.000000], Lat - 0.000000], Road from Debte Kalakuchi to Makadaba Deberdakabachi [Submergel length 2.5 m. Information received from PWRD Department on 17/06/2022 via WT message. [Long - 0.000000], Lat - 0.000000], Road from Debte Kalakuchi to Makadaba Debterdakabachi [Submergel length 2.5 m. Information received from PWRD Department on 17/06/2022 via WT message. [Long - 0.000000], Lat - 0.000000], Rakaya Napipara Road [Kakaya [Submerged and Breath length 10 m. near No.2 Napipara. Information reviewed from PWRD Department on 18/06/2022 via WT message. [Long - 0.000000], Tat - 0.000000], Thub - THU HS BACKSIDE ROAD [THU TOWN] LENGTH-500MTS.INFORMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/16/2022 [Long - 0.000000], DEWER HOUSE SIDE ROAD [SUDMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/16/2022 [Long - 0.000000], POWER HOUSE FROM SIDE ROAD [SUBMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 [Long - 0.00000], POWER HOUSE FROM SIDE ROAD [SUBMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 [Long - 0.00000], POWER HOUSE FROM SIDE ROAD [SUBMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 [Long - 0.00000], POWER HOUSE FROM SIDE ROAD [SUBMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 [Long - 0.00000], POWER HOUSE FROM SIDE ROAD [SUBMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 [Long - 0.00000], POWER HOUSE FROM SIDE ROAD [SUBMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 [Long - 0.00000], POWER HOUSE FROM SIDE ROAD [SUBMATION RICCHIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 [Long - 0.00000], Lat - 0.000000], POWER HOUSE FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 [Long - 0.00000], Lat - 0.000000], POWER PROBE FROM CHAIRMAN,TMB, DATE OF			
Rumikata fo Niz - Bahjani road kunarikata Submerged length 5.64 m. Information received from PWRD Department on 1706-02202 via WT message; (Long - 0.000000), Lat - 0.000000), Jaha to Charia Road Jaha Submerged length 1.5 m. Information received from PWRD Department on 1706-0202 via WT message; (Long - 0.00000), Road from Deber Kalakuchi to Makaldaba Deherkalakuchi Submerged length 2.5 m. Information received from PWRD Department on 1706-0202 via WT message; (Long - 0.00000), Lat - 0.000000), Road from Deber Kalakuchi to Makaldaba Deherkalakuchi Submerged length 10 m. near No.2 Naptipara. Information received from PWRD Department on 1806-02022 via WT message; (Long - 0.000000), Lat - 0.000000], Tiha - THIU HS ROAKSIDE ROAD THIU TOWN LENGTH: SUBMERGED: 1706-02022 (Long - 0.000000), Lat - 0.000000], Thiu - THIU HS ROAKSIDE ROAD BIPLUT OWN LENGTH: SKMTS INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 1706-02022 (Long - 0.000000), POWER HOUSE SIDE ROAD (BIDYANAGAR), WARD-2,THIU TOWN LENGTH: SKMTS INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 1706-02022 (Long - 0.000000), Lat - 0.000000), POWER HOUSE FROM TSIDE ROAD WARD-2,THIU TOWN LENGTH: SKMTS INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 1706-02022 (Long - 0.0000000), Lat - 0.0000000), THIU GIRLS HS (BYLANEL LEAKHIM) PATHAR! WARD-2,THIU TOWN LENGTH: 2 KMTS. INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 1706-02022 (Long - 0.0000000), MASZID ROAD(WILANEL) WARD-3,THIU TOWN LENGTH: SWMTS. INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 1706-02022 (Long - 0.0000000), Lat - 0.0000000, Lat -			
FWRD Department on 17/06/2022 via WT message. 1 (Long 0.000000).			
on 1736/2922 via WT message. [cl. ang. 0.000000]. Lat. 0.000000]. Road from Deber Kalakuchi Di Makalada Di Deberkalakuchi Ji Submerged length 2.5 m. Information received from PWRD Department on 17:06/2022 via WT message. [cl. cng. e. 0.000000]. Co. 0.000000]. Rataya Napripara Road [Kakaya] Submerged and Breach length 10 m. near No. 2 Napripara. Information received from PWRD Department on 18:06/2022 via WT message. [cl. cng. e. 0.000000]. Lat. e. 0.000000]. Lat. e. 0.000000]. The Tith! HIS RACKSIDE ROAD [THAU TOWN] LENGTH-5:00MTS.INFORMATION RECEIVED PROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.000000]. POWER HOUSE SIDE ROAD (RIDVANAGAR).] WARD 2:THEU TOWN] LENGTH: 1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.00000]. POWER HOUSE FROM THE ROAD [WARD 2:THEU TOWN] LENGTH: 1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.00000]. Lat. 0.000000]. POWER HOUSE FROM THE ROAD [WARD 2:THEU TOWN] LENGTH: 2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.00000]. Lat. 0.000000]. THU GIRLS HIS GYLANG LAKIMIM PATIARI, WARD 2:THU TOWN LENGTH: 2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.00000]. MASZID ROAD BYLANE: 1) WARD 3:THU TOWN LENGTH: 2500/2022 [cl. cng. e. 0.00000]. MASZID ROAD BYLANE: 1) WARD 3:THU TOWN LENGTH: 15:KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.00000]. Lat. e. 0.000000]. CHOUDHURYPARA ROAD WARD-1.THU TOWN LENGTH: 15:KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.00000]. Lat. e. 0.000000]. CHOUDHURYPARA ROAD WARD-3.THU TOWN LENGTH: 2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.00000]. Lat. e. 0.000000]. Lat. e. 0.000000]. CHOUDHURYPARA ROAD WARD-4.THU TOWN LENGTH: 2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 [cl. cng. e. 0.000			
Road from Deher Kalkuchi to Makaldaba Deherkalakuchi Submerged lengh 2.5 m. Information received from PWRD Department on 17/06/2022 via WT message. Long = 0.000000, Lat = 0.0000000, Lat = 0.0000000, Lat Sakaya Submerged and Breach length 10 m. near No.2 Naptipara. Information received from PWRD Department on 18/06/2022 via WT message. Long = 0.000000, Lat = 0.0000000. Time - THIU HS BACKSIDE ROAD THIU TOWN LENGTH-15/00MTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). Lat = 0.0000000, POWER HOUSE SIDE ROAD BIDYANAGAR). WARD 2.THIU TOWN LENGTH-15/MTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). LENGTH-15/MTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). LENGTH-15/MTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). THU GIRLS HS (BYLANE LAKHMIN PATHAR) WARD 2.THIU TOWN LENGTH-12/KMTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). MASZID ROADGETANE-1) WARD-3.THIU TOWN LENGTH-15/MTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). Lat = 0.000000). BIDYANAGAR ROAD WARD -1.THIU TOWN LENGTH-15/KMTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). Lat = 0.000000). CHOLIDHIRYPARA ROAD WARD -2.THIU TOWN LENGTH-15/KMTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). Lat = 0.000000). THU TO KHAILHAGUR ROAD WARD -2.THIU TOWN LENGTH-15/KMTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). Lat = 0.000000). HIGH ROAD WARD -2.THIU TOWN LENGTH-15/KMTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long = 0.000000). Lat = 0.000000). HIGH ROAD WARD -2.THIU TOWN LENGTH-25/KMTS.NIFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBM			Jaha to Charia Road Jaha Submerged length 1.5 m. Information received from PWRD Department
received from PWRD Department on 17/06/2022 via WT message. (Long - 0.000000), Lat - 0.0000000, Kakaya Naptipara Road Kakaya Submerged and Breach length 10 m. near No. 2 Naptipara, Information received from PWRD Department on 18/06/2022 via WT message. (Long - 0.000000), Lat - 0.0000000. Tith - 110H US BACKSIDE ROAD TithUTOWN LENGTH-SOOMTS.INFORMATION RECEIVED FROM CHAIRMAN.TMB, DATE OF SUBMERGED : 17/06/2022 (Long - 0.000000), Lat - 0.0000000. POWER HOUSE SIDE ROAD MIDYANAGAR WARD-2.THU TOWN LENGTH-IS KMTS.INFORMATION RECEIVED FROM CHAIRMAN.TMB, DATE OF SUBMERGED : 17/06/2022 (Long - 0.000000), Lat - 0.0000000). POWER HOUSE FRONT SIDE ROAD WARD-2.THU TOWN LENGTH-IS KMTS.INFORMATION RECEIVED FROM CHAIRMAN.TMB, DATE OF SUBMERGED : 17/06/2022 (Long - 0.000000), Lat - 0.0000000). THU GIRIS IS (WIS WIS WIS WIS WIS WIS WIS WIS WIS WIS			
0.000000), Kakuya Napupara Road Kakaya Submerged and Breach length 10 m. near No.2 Napupara. Information received from PWRD Department on 18/06/2022 via WT message. (Long = 0.000000, Lat = 0.000000), Tibu - TIHU HS BACKSIDE ROAD TIHU TOWN LENGTH-S00MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), Lat = 0.000000), POWER HOUSE FISHE ROAD (RIDYANAGAR A), WARD-2.TIHU TOWN LENGTH-IXMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMIRGED : 17/06/2022 (Long = 0.000000), Lat = 0.000000), POWER HOUSE FROM TDIE ROAD WARD-2.TIHU TOWN LENGTH-IXMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMIRGED : 17/06/2022 (Long = 0.000000), Lat = 0.000000), THU GIRLS HS GYLANE LARHIM PATHAR) WARD-2.TIHU TOWN LENGTH-IXMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), Lat = 0.000000), MASZID BOAD(BYLANE I) WARD-3.TIHU TOWN LENGTH-ISMMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), MASZID BOAD(BYLANE I) WARD-3.TIHU TOWN LENGTH-ISMMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), Lat = 0.0000000), BIDYANAGAR ROAD WARD-3.TIHU TOWN LENGTH-ISMMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), Lat = 0.000000), THU BUNGLOW ROAD WARD-3.TIHU TOWN LENGTH-ISMMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), Lat = 0.000000), THU TO KITALHAGURI ROAD WARD-3.TIHU TOWN LENGTH-ISMMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), Lat = 0.000000), ROAD WARD-4.TIHU TOWN LENGTH-ISMMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), Lat = 0.000000), RADHAKRISHNA ROAD TO KHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), RADHAKRISHNA ROAD TO KHAIRMAN,TMB, DATE OF SUBMERGED : 17/06/2022 (Long = 0.000000), NASTE PATHAK ROA			
Kakuya Naptipura Road Kakaya Submerged and Breach length 10 m. neur No. 2 Naptipura. Information eceived from PWRD Department on 18:06/2022 via WT message. (Long 0.000000, Lat 0.000000). Tibs THU US BACKSIDE ROAD THIRU TOWN LENGTH-SOMTSINFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). POWER HOUSE SIDE ROAD (BIDYANAGAR). WARD-2.THU TOWN LENGTH-SKNTSINFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.00000). Lat 0.000000). POWER HOUSE FRONT SIDE ROAD WARD-2.THU TOWN LENGTH-SKMTSINFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). Lat 0.000000). THU GIRLS HS GWILAMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). Lat 0.000000). MASZID ROAD,RYLAME. 1) WARD-3.THU TOWN LENGTH-SCOWER 1:7:06/2022 (Long 0.000000). MASZID ROAD,RYLAME. 1) WARD-3.THU TOWN LENGTH-SCOWTS,NFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). MASZID ROAD,RYLAME. 1) WARD-3.THU TOWN LENGTH-SKMTS,NFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). Lat 0.000000). BIDYANAGAR ROAD WARD-3.THU TOWN LENGTH-SKMTS,INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). Lat 0.000000). THU BUNGLOW ROAD WARD-3.THU TOWN LENGTH-SKMTS,INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). Lat 0.000000). THU BUNGLOW ROAD WARD-3.THU TOWN LENGTH-SKMTS,INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). Lat 0.000000). NAZIR PATHAK ROAD WARD-4.THU TOWN LENGTH-SKMTS,INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). Lat 0.000000). NAZIR PATHAK ROAD WARD-4.THU TOWN LENGTH-SKMTS,INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17:06/2022 (Long 0.000000). NAZIR PATHAK ROAD TO KHARMAN,T			
Information received from PWRD Department on 18/06/2022 via WT message. (Long - 0.000000). Lat - 0.0000000. Tihu - THIU HS BACKSIDE ROAD THIRU TOWN LENGTH-SOMMTS.INFORMATION RECHVED FROM CHARMAN.TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). Lat - 0.000000. POWER FROM CHARMAN.TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). Lat - 0.000000. POWER FROM SUBMERGED :17/06/2022 (Long - 0.000000). Lat - 0.000000. POWER HOUSE FROM TDIR ROAD WARD-2.THIU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). Lat - 0.000000. Lat - 0.000000. THU GIRLS HS (BYLANE LAKHIMI PATHAR) WARD-2.THU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). THU GIRLS HS (BYLANE LAKHIMI PATHAR) WARD-2.THU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). MASZID BOAD(BYLANE-1) WARD-3.THU TOWN LENGTH-5.500MTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). Lat - 0.000000). BIDYANAGAR ROAD WARD-3.THU TOWN LENGTH-1.5KMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). Lat - 0.000000). THU BUNGLOW ROAD WARD-3.THU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). Lat - 0.000000). THU TO KITALIHAGURI ROAD WARD-4.THIU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). Lat - 0.000000). NAZIR PATHAK ROAD WARD-4.THIU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). RADHAKRISHNA ROAD TO KHALHAGURI ROAD WARD-4.THIU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000). RADHAKRISHNA ROAD TO KHALHAGURI ROAD WARD-4.THIU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHARM			
Lai - 0.000000, Tibu - Tibu HS BACKSIDE ROAD TIHU TOWN LENGTH-500MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000, Lai - 0.000000), POWER HOUSE SIDE ROAD, (BIDYANAGAR), WARD-2,THU TOWN LENGTH-1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000, Lai - 0.000000), POWER HOUSE FRONT SIDE ROAD WARD-2,THU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000, Lai - 0.000000), THU GIRLS HS (BYLANE LA RIMM PATHAB) WARD-2,THU TOWN LENGTH-2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000, Lai - 0.00000), MASZID ROAD(BYLANE-1) WARD-3.THU TOWN LENGTH-5.00MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000), MASZID ROAD(BYLANE-1) WARD-3.THU TOWN LENGTH-5.00MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000), Lai - 0.000000, BDDYANAGAR ROAD WARD-3.THU TOWN LENGTH-1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000), Lai - 0.000000, THU DOWN LAI - 0.000000, THU DOWN LAI - 0.000000, THU TOWN LAI - 0.000000, NAZIR PATHAK ROAD WARD-4, THU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000, Lai - 0.000000, NAZIR PATHAK ROAD WARD-4, THU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000, Lai - 0.000000, NAZIR PATHAK ROAD WARD-4, THU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17.06/2022 (Long - 0.000000, Lai - 0.000000, RABIATA ROAD WARD-4, THU TOW			
Tibe - THIU IIS BACKSIDE ROAD THIU TOWN LENGTH-SOOMTS.INFORMATION RCEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000), Lau - 0.000000, POWER HOUSE, SIDE ROAD (BIDYANAGAR.) WARD-2,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), POWER HOUSE FRONT SIDE ROAD WARD-2,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), THIU GIRLS HS (BYLANE LAKHIMI PATHAR) WARD-2,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), MASZID ROAD(BYLANE LAKHIMI PATHAR) WARD-2,THIU TOWN LENGTH-SOMMTS INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), BIDYARAGAR ROAD WARD-1,THIU TOWN LENGTH-SOMMTS INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), CHOUDHURYPARA ROAD WARD-3,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), THIU BUNGLOW ROAD WARD-3,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), THIU BUNGLOW ROAD WARD-3,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000), NAZIR PATHAK ROAD WARD-4,THIU TOWN LENGTH-SKMTS.INFORMATION RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.000000), NAZIR PATHALLY BREACHED.INFORMATION RECEIVED FROM GHARMAN,TMB, DATE OF SUBMERGED :17:06:2022 (Long - 0.00000			*
RECEIVED FROM CHARMAN,TMB, DATE OF SUBMERGED: 17.06/2022 [(Long - 0.000000),			
Lai - 0.000000), POWER HOUSE SIDE ROAD (BIDYANAGAR), WARD-2,TIHU TOWN LENGTH: SKMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000), POWER HOUSE FRONT SIDE ROAD WARD-2,TIHU TOWN LENGTH: ZKMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000), TIHU GIRLS HS (BYLANE LAKHIMI PATHAR) WARD-2,TIHU TOWN LENGTH: 2 KATS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 17/06/2022 (Long - 0.000000, Lai - 0.000000), MASZID ROAD(BYLANE)) WARD-3,TIHU TOWN LENGTH: 500MTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000), BIDYANAGAR ROAD WARD-1,TIHU TOWN LENGTH: 5KMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000), THHU BOURGLOW ROAD WARD-3,TIHU TOWN LENGTH: 1 KMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000), THHU TO KHALHAGURI ROAD WARD-4,TIHU TOWN LENGTH: 2KMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000), NAZIR PATHAK ROAD WARD-4, THU TOWN LENGTH: 2KMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000), NAZIR PATHAK ROAD WARD-4, THU TOWN LENGTH: 2KMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000), NAZIR PATHAK ROAD WARD-4, THU TOWN LENGTH: 2KMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lai - 0.000000, NAZIR PATHAK ROAD WARD-4, THU TOWN LENGTH: 2KMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), NAZIR PATHAK ROAD WARD-4, THU TOWN LENGTH: 2KMTS, INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), NAZIR PATHALE ROAD WARD-4, THU TO			
LENGTH-1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0,00000), DOWER HOUSE FRONT SIDE ROAD WARD-2.TIHU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHAIRMAN.TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), THU GIRLS IS (BYLANE LAKHIMI PATHAR) WARD-2.TIHU TOWN LENGTH-2.KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), MASZID ROAD(BYLANE-1) WARD-3.TIHU TOWN LENGTH-5:00MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), CASCID ROAD(BYLANE-1) WARD-3.TIHU TOWN LENGTH-5:00MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), CHOUDHURYDARA ROAD WARD-3.TIHU TOWN LENGTH-1: KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), CHOUDHURYDARA ROAD WARD-3.TIHU TOWN LENGTH-1: KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), THU TO KHALIHAGURI ROAD WARD-2.TIHU TOWN LENGTH-2: KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), THU TO KHALIHAGURI ROAD WARD-4.TIHU TOWN LENGTH-2: KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), NAZIR PATHAK ROAD WARD-4.TIHU TOWN LENGTH-2: KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), RADIRARISHNA ROAD TO KHALIHAGURI ROAD WARD-4.TIHU TOWN LENGTH-2: KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), RADIRARISHNA ROAD TO KHALIHAGURI ROAD WASD-4.TIHU TOWN LENGTH-2: KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), RADIRARISHNA ROAD TO KHALIHAGURI ROAD WASD-4.TIHU TOWN LENGTH-2: KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long -			
SUBMERGED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), POWER HOUSE FRONT SIDE ROAD WARD-2-TIHU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), THU GIRLS HS (BYLANE LAKHIMI PATHAR) WARD-2,TIHU TOWN LENGTH-2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), MASZID ROAD(BYLANE-1) WARD-3,TIHU TOWN LENGTH-500MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), BIDYANAGAR ROAD WARD-1,TIHU TOWN LENGTH-15.KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), CHOUDHURYPARA ROAD WARD-3,TIHU TOWN LENGTH-15.KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), THU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH-12.KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), Lat - 0.000000), MAZIR PORD CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), NAZIR PATHAR ROAD WARD-2,TIHU TOWN LENGTH-2:KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), NAZIR PATHAR ROAD WARD-4,TIHU TOWN LENGTH-2:KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), LAT - 0.000000), NAZIR PATHAR ROAD WARD-4,TIHU TOWN LENGTH-2:KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), RAID RATHAR ROAD WARD-4,TIHU TOWN LENGTH-2:KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED : 17:06-2022 (Long - 0.000000), RAID RATHAR ROAD WAS PATHALLY BURKERDED : 17:06-2022 (Long - 0.000000), RAID RATHAR ROAD WAS PATHALLY BURKERDED : 17:06-2022 (Long - 0.000000), RAID RATHAR ROAD WAS PATHALLY BURKERDED : 17:06-2022 (Long - 0.000000), Lat - 0.000000), NAID RECEIVED FROM CHAIRMA			POWER HOUSE SIDE ROAD (BIDYANAGAR). WARD-2,TIHU TOWN
POWER HOUSE FRONT SIDE ROAD WARD-2.THU TOWN LINGTH-2.ZMTS. INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000, Lat - 0.000000), TIHU GIRLS HS (BYLANE LAKHIMI PATHAR) WARD-2.THEU TOWN LENGTH:2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), MASZID ROAD BUXANE-1) WARD-3.THEU TOWN LENGTH:5.00MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), Lat - 0.000000), Lat - 0.000000, Lat - 0.00000			LENGTH:1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF
LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17706/2022 (Long - 0.000000), Lat - 0.000000), TIHU GIRLS HS (BYLANE LAKHIMI PATHAR) WARD-2,TIHU TOWN LENGTH-2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17706/2022 (Long - 0.000000), Lat - 0.000000), MASZID ROAD(BYLANE-1) WARD-3,TIHU TOWN LENGTH-500MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17706/2022 (Long - 0.000000), Lat - 0.000000), Lat - 0.000000, Lat - 0.000000, Lat - 0.000000, CHOUDHURYPARA ROAD WARD-1,TIHU TOWN LENGTH-1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17706/2022 (Long - 0.000000), CHOUDHURYPARA ROAD WARD-3,TIHU TOWN LENGTH-1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17706/2022 (Long - 0.000000), Lat - 0.000000), TIHU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH-12KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17706/2022 (Long - 0.000000), Lat - 0.000000), LAT - 0.000000), LAT - 0.000000, LAT - 0.000000), NAZIR PATHAK ROAD WARD-4,TIHU TOWN LENGTH-12KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17706/2022 (Long - 0.000000), LAT - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH-12KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 1706/2022 (Long - 0.000000), LAT - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH-12KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 1706/2022 (Long - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH-12KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 1706/2022 (Long - 0.000000), LaT - 0.000000), JAME MASIDI TO SURADI ROAD SURADI ROAD SURADI ROAD WARD-4,TIHU TOWN LENGTH-12KMTS.INFORMATION ROECIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 1706/2022 (Long - 0.000000, LaT - 0.000000), JAME MASIDI TO SURADI ROAD			
SUBMERGED :17/06/2022 (1.ong - 0.000000),			
THIU GIRLS HS (BYLANE LAKHIMI PATHAR) WARD-2.TIHU TOWN LENGTH: 2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000), Lat - 0.000000), MASZID ROAD(BYLANE: 1) WARD-3.TIHU TOWN LENGTH: 500MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), BIDYANAGAR ROAD WARD-1.TIHU TOWN LENGTH: 1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), CHOUDHURYPARA ROAD WARD-3.TIHU TOWN LENGTH: 1.KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), TIHU BUNGLOW ROAD WARD-2.TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), THIU TO KHALIHAGURI ROAD WARD-4.TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), NAZIR PATHAK ROAD WARD-4.TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), KALITA ROAD WARD-4.TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), RADHAKRISHNA ROAD WARD-4.TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4.TIHU TOWN LENGTH: 2kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), LATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), DATE OF SUBMERGED: 17/06/2022			
KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED 1:17:06/2022 (Long - 0.000000), Lat - 0.000000, Lat - 0.000000), MASZID ROAD(BYLANE-1) WARD-3,THU TOWN LENGTH:500MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), BIDYANAGAR ROAD WARD-1,THU TOWN LENGTH:1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), CHOUDHURYPARA ROAD WARD-3,THU TOWN LENGTH:1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), THU BUNGLOW ROAD WARD-2,THU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), THU TO KHALHAGURI ROAD WARD-4,THU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), NAZIR PATHAK ROAD WARD-4,THU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), Lat - 0.000000), KALITA ROAD WARD-4,THU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), RADIHAKRISHNA ROAD TO KHALHHAGURI ROAD WARD-4,THU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000), RADIHAKRISHNA ROAD TO KHALHHAGURI ROAD WARD-4,THU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHAUCH! LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17:06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length approx. 180m as reported by AEE PWRD Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 len			
17/06/2022 (Long - 0.000000), MASZID ROAD(BYLANE-1) WARD-3,TIHU TOWN LENGTH-500MTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), Lat - 0.000000, Lat - 0.0000000, CHOUDHURYPARA ROAD WARD-3,TIHU TOWN LENGTH-1. SKMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.0000000, TIHU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4,TIHU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADITA ROAD WARD-4,TIHU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), RADITA ROAD WARD-4,TIHU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, RADITA ROAD WARD-4,TIHU TOWN LENGTH-2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADITA ROAD WARD-4,TIHU TOWN LENGTH-2/MTS & 10 MTS. THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), MADITA TO WEAR AND TO SHALHAGURI ROAD WARD-4,TIHU TOWN LENGTH-2/MTS & 10 MTS. THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JEPWD(R),BARAMA . DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), MADITA TO SURADI ROAD SURADI LENGTH-1/MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JEPWD(R),BARAMA . DATE OF SUBM			
MASZID ROAD(BYLANE-1) WARD-3,TIHU TOWN LENGTH:500MTS INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.00000), BIDYANAGAR ROAD WARD-1,TIHU TOWN LENGTH:1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.00000), Lat - 0.000000, Lat - 0.000000, Lat - 0.000000, THOUDHURYPARA ROAD WARD-3,TIHU TOWN LENGTH:1 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), THU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), THU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NH3 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JLE-PWD(R),BARAMA . DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI ROAD BLPOTR),BARAMA . DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), Lat - 0.000000), Barkheti - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of reb. nos8/1 length apprx. 180m as reported by AEE PWRD Barkheti on 22/06/2022 (Long - 0.000000), Lat - 0.000000) Malkachar - 1. IBB link road to Puran sukchar 2. Hatsingimari to IBB Road. 1. Puran Sukchar 2. Hatsingimari on IBB Road. 1. Puran Sukchar 2. Sub-Division on 22/06/22 x 18:00PM: 1. IB			
Nalbari 23 Lat - 0.000000, BIDYANAGAR ROAD WARD-1,TIHU TOWN LENGTH:1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), Lat - 0.000000, CHOUDHURYPARA ROAD WARD-3,TIHU TOWN LENGTH:1 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), Lat - 0.000000, TIHU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), Lat - 0.000000, THU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), Lat - 0.000000, NAZIR PATHAK ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), NHS1 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:2MMTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rec br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000) Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.0000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2. Hatstingimari to IBB Road, 1.Puran Sukchar 2. Sishumara As per report receiv			MASZID ROAD(BYLANE-1) WARD-3,TIHU TOWN LENGTH:500MTS.INFORMATION
BIDYANAGAR ROAD WARD-1, TIHU TOWN LENGTH: 1.5KMTS.INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), CHOUDHURYPARA ROAD WARD-3, TIHU TOWN LENGTH: 1 KMTS.INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU BUNGLOW ROAD WARD-2, TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Lat - 0.000000), Lat - 0.000000), Lat - 0.000000, Lat - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4, TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Lat - 0.000000), KALITA ROAD WARD-4, TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4, TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN, TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NI31 TO MEGA FOOD PARK ROAD NATHRUCHI LENGTH: 20MTS & 10 MTS. THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM E.PWD(R), BARAMA DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), Barkbetti - hajo mukalmua daulsasi road Ladabati closed for all types of vehicle, damage of br. SUBMERGED: 117/06/2022 (Long - 0.000000, Lat - 0.000000), Nabari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000)			
RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000, CHOUDHURYPARA ROAD WARD-3,TIHU TOWN LENGTH: 1 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000, Lat - 0.000000, Lat - 0.000000, THU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH: 2 kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), THU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH: 2 kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4,TIHU TOWN LENGTH: 2 kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADTHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH: 2 kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), RADTHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH: 2 kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH: 2 kMTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM EPWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH: 10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JEPWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of roc br. no81 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000)	Nalbari	23	
Lat - 0.000000), CHOUDHURYPARA ROAD WARD-3,TIHU TOWN LENGTH:1 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH:2kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4,TIHU TOWN LENGTH:2kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road Jadabari closed for all types of vehicle, damage of br. approaches of rce br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000), Lat - 0.000000).			
CHOUDHURYPARA ROAD WARD-3,TIHU TOWN LENGTH:1 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH:2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4,TIHU TOWN LENGTH:2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2 KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2 kMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCH' LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkbetti - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rec br. no8/1 length appx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000)			
RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022 (Long - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000), Lat - 0.000000)			
Lat - 0.000000), TIHU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), TIHU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2. Hatsingimari to IBB Road. 1. Puran Sukchar 2. Sishumara As per report received from Assit. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PW: -1. IBB link road to puran sukchar via Manik Sarker high school			·
RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), THU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4, TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH: 2KMTS. INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH: 20MTS & 10 MTS. THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH: 10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000), Lat - 0.000000) Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000), Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2. Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
Lat - 0.000000), TIHU TO KHALIHAGURI ROAD WARD-4.TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCH! LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000), Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			TIHU BUNGLOW ROAD WARD-2,TIHU TOWN LENGTH:2KMTS.INFORMATION
TIHU TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) South Salmara As per report received from Asst. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:-1. IBB link road to puran sukchar via Manik Sarker high school			
RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NAZIR PATHAK ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2. Hatsingimari to IBB Road. 1. Puran Sukchar 2. Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
Lat - 0.000000), NAZIR PATHAK ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE, PWD(R), BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE, PWD(R), BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2. Hatsingimari to IBB Road. 1. Puran Sukchar 2. Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
NAZIR PATHAK ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), KALITA ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4, TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) South Salmara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Lat - 0.000000), Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH: 2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH: 20MTS & 10 MTS. THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE, PWD(R), BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH: 10MTS & 15 MTS. THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE, PWD(R), BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000). Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
Lat - 0.000000), KALITA ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH: 2KMTS. INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH: 20MTS & 10 MTS. THE ROAD WAS PARTIALLY BREACHED. INFORMATION RECEIVED FROM JE,PWD(R), BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH: 10MTS & 15 MTS. THE ROAD WAS BREACHED. INFORMATION RECEIVED FROM JE,PWD(R), BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
RADHAKRISHNA ROAD TO KHALIHAGURI ROAD WARD-4,TIHU TOWN LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
LENGTH:2KMTS.INFORMATION RECEIVED FROM CHAIRMAN,TMB, DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED:17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
SUBMERGED: 17/06/2022 (Long - 0.000000), Lat - 0.000000), NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH: 20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH: 10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
NH31 TO MEGA FOOD PARK ROAD NATHKUCHI LENGTH:20MTS & 10 MTS.THE ROAD WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
WAS PARTIALLY BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH:10MTS & 15 MTS.THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), JAME MASJID TO SURADI ROAD SURADI LENGTH: 10MTS & 15 MTS. THE ROAD WAS BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA. DATE OF SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
BREACHED.INFORMATION RECEIVED FROM JE,PWD(R),BARAMA . DATE OF SUBMERGED :17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
SUBMERGED: 17/06/2022 (Long - 0.000000, Lat - 0.000000), Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			· · · · · · · · · · · · · · · · · · ·
Barkhetri - hajo mukalmua daulasal road adabari closed for all types of vehicle, damage of br. approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
approaches of rcc br. no8/1 length apprx. 180m as reported by AEE PWRD Barkhetri on 22/06/2022. (Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
(Long - 0.000000, Lat - 0.000000), Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
Nalbari - Deharkalakuchi Road Deharkalakuchi As per report received from PWRD Department the Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000)			
Road Submerged due to Flood on 22.06.2022 (Long - 0.000000, Lat - 0.000000) Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
South Salmara Mankachar - 1. IBB link road to Puran sukchar 2.Hatsingimari to IBB Road. 1.Puran Sukchar 2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker high school			
South Salmara 2			
Salmara Sub-Division on 22/06/22 at 8:00PM:- 1. IBB link road to puran sukchar via Manik Sarker nigh school	South	2	2.Sishumara As per report received from Asstt. Ex. Engineer, PWRD, Mankachar Territorial road
has submerged by flood water and damaged the road surface, embankment in several locations. 50 M	Salmara		
		1	has submerged by flood water and damaged the road surface, embankment in several locations. 50 M

-		1	
			to 600 M 2.Road embankment, ICBP of Hatsingimari to IBB road at Sisumara Road has damaged by flood water and due to heavy rain. 1 KM to 5 KM (Long - 25.726054, Lat - 89.882864)
			Harisinga - Chenipara to Kaulibhanga road Chenipara The road from chenipara to Kaulibhanga damaged on 23/06/2022. (9.9m) (Long - 91.562900, Lat - 26.421000),
			Pachim Hahinagaon to Chenipara Hahinigaon Pachim Hahinagaon to Chenipara road breached at
			Hahinigaon on 23/06/2022. (10.1m) (Long - 0.000000, Lat - 0.000000), Andherighat toHarisinga road Hahini gaon Andherighat toHarisinga road damaged at Hahinigaon on
	Udalguri	5	23/06/2022. (5.6m) (Long - 91.568000, Lat - 26.404000),
			Khairabari - Barara to Bezbhagawati Road Barara HPC and road embankment was damaged on 21.06.2022 due to overflow of flood water at Barara. Length: 8M (approx.) (Long - 91.860605, Lat - 26.544274),
			Kalaigaon - Majarchuba Amguri Chowk to Amguri Shive Mandir No 2 Amguri The road surface has completely damaged on 23/06/2022 due to erosion caused by receding flood water covering a
	Total	173	length of around 300 meters and breadth of 7.5 meters (Long - 91.980753, Lat - 26.608291)
	District	Numbe	Details
	District	r	
	Bajali	2	Bajali - SPT Bridge No. 3/1 and 3/2 Saktipar Damaged Bridge. This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000),
	Бајап	2	SPT foot Bridge No. 1/1 Kaharpara Bridge Damaged, This Report is Received from AEE,PWD,Patacharkuchi TR Sub-Divission,Pathsala on 22/06/2022 (Long - 0.000000, Lat - 0.000000)
			Dhubri - BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 1/1, 1/2 & 1/3 ON
			DHARMASALA DURAHATI ROAD VIA SINGIMARI ROAD (.) DHARMASALA DURAHATI DATED-18-06-2022 TO 23-06-2022 (Long - 0.000000, Lat - 0.000000),
	Dhubri	3	BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 1/1 & 2/1 ON KISMAT HASDAHA SILGHAGRI ROAD TO ROAD TISTARPAR DATED-18-06-2022 TO 23-06-2022 (Long -
	Diluoii	3	0.000000, Lat - 0.000000),
			BRIDGE APPROACHS DMAGED OF RCC BR. 1/1 ON KALAHAT GHEWMARI ROAD TO DURAHATI VIA VELAKOBA ROAD VELAKOBA DATED-18-06-2022 TO 23-06-2022 (Long
			- 0.000000, Lat - 0.000000)
			Bagribari - Rupshi to Banyaguri Raod Rupshi As reported by AEE PWD Gauripur TRSD on 17/06/22, the road has been damaged (Long - 0.000000, Lat - 0.000000),
			Bashbari Bazar to Monglajhora Road Bashbari Bazar As reported by AEE PWD Gauripur TRSD on
			17/06/22, CD approaches damaged on (Long - 0.000000, Lat - 0.000000), Khutabagra Tiniani to Dampur Pt-II road Khutabagra Tiniani As reported by AEE PWD Gauripur
			TRSD on 17/06/22, side berm/hard crust has been damaged on (Long - 0.000000, Lat - 0.000000), Dotma - Salbari to Sinslitbari Road wodden bridge Sinslitbari As per reported by Asstt. Exe.
			Engineer PWRD RR Kachugaon Division, Damage of Salbari to Sinslitbari road wodden bridge by Flood on 23-06-2022 (Long - 0.000000, Lat - 0.000000),
Infrastructu re Damaged			Salbari to Tengaigaon Road wooden bridge Tengaigaon As per reported by Asstt. Exe. Engineer
- Bridge			PWRD RR Kachugaon Division, Damage of Salbari to Tengaigaon road wooden bridge by Flood on 23-06-2022 (Long - 0.000000, Lat - 0.000000),
			Gwthaibari to Samthaibari road wooden bridge Samthaibari As per reported by Asstt. Exe. Engineer
			PWRD RR Kachugaon Division, Damage of Gwthaibari to Samthaibari road wodden bridge by Flood. Br. No. 1/1 on 23-06-2022 (Long - 0.000000, Lat - 0.000000),
	Kokrajhar	12	Kujrabguri to Kumbhirguthu Road wooden bridge Kumbhirghutu As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of Kujrabguri to Kumbhirghutu wooden bridge by
	- Loningiiui		flood. Br. No. 1/1 on 23-06-2022 (Long - 0.000000, Lat - 0.000000),
			Oxiguri village wooden bridge Oxiguri As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of Oxiguri village wooden bridge by Flood on 23-06-2022 (Long -
			0.000000, Lat - 0.000000),
			North Singimari to Katribari road wooden bridge Katribari As per reported by Asstt. Exe. Engineer PWRD RR Kachugaon Division, Damage of North Singimari to Katribari road wooden bridge by
			Flood on 23-06-2022 (Long - 0.000000, Lat - 0.000000), Amlaiguri village wodden bridge Amlaiguri As per reported by Asstt. Exe. Engineer PWRD RR
			Kachugaon Division, Damage of Amlaiguri wooden bridge by Flood on 23-06-2022 (Long -
			0.000000, Lat - 0.000000), Borshijhora to Laodanga road wooden bridge Laodanga As per reported by Asstt. Exe. Engineer
			PWRD RR Kachugaon Division, Damage of Borshijhora and Laodanga road wooden bridge by Flood
			on 23-06-2022 (Long - 0.000000, Lat - 0.000000), Goybari to Bauti Road wooden bridge Bauti As per reported by Asstt. Exe. Engineer PWRD RR
			Kachugaon Division, Damage of Goybari to Bauti road wooden bridge by Flood on 23-06-2022 (Long - 0.000000, Lat - 0.000000)
			Paschim Nalbari - RCC BR No.1/1 on Batsor Kalimandir to Mohkholi Jaganath Mandir Road . B
	Nalbari	3	atsor Approach Damaged information Received from 23.06.22. (Long - 0.000000, Lat - 0.000000), HPC on Bagurihati to Mohkoli Road Bagurahati Approach Damaged information Received from
			23.06.22. (Long - 0.000000, Lat - 0.000000),

			RCC BR No.1/1 on Babila Road to Lokhopur Road Barbila Approach Damaged information Received from 23.06.22. (Long - 0.000000, Lat - 0.000000)	
	Total	20	· ·	
Infrastructu	District	Wildlife a	affected under protected areas description	
re Damaged - Wildlife	Morigaon	Mayong - Pobitora WLS 12nos of camps are inundated as reported by Range Officer PWLS on 23/06/22		
	District	Other Details		
	Bajali	Sarupeta - Anganwadi Centres Affected Anganwadi Center Affected at Tangla mullahpar(reported by CDPO Bhawanipur ICDS project), dated 23/06/22		
	Barpeta	Bhawanipur ICDS project), dated 23/06/22 Chenga - Anganwadi Centres Affected 179 No. Batgaon Nayapara, 177 No. Niz Ganakpara,65 No. Pub Andanga 67 No. Bhelenabh 69 No. Changbandha-1 70 No. Aduripara-1 71 No. Aduripara-2 72 No. Moiradia 73 No. Pub Moiradia 112 No. Dakhin Moiradia (33 nos. AWCs fully damaged) 30 No. Uttar Bampara, 154 No. A. Jayar Char 155 No. A.T. Dewani Supa 156 No. A. Kazir Char-2, 23 No. Gelabil 3 No. Saara, 2 No. Bldiapalipara Reserve 7 No. Subha 2 No. Dakhin Barchenga Mini 54 No. Subha Mannery Mini 3 No. Dakhin Bampara Mini 114 No. Hirapara 170 No. Malipara Puran Mothawuri Supahara 75 No. Mahchara 76 No. Pub Mahchara 77 No. Pub Mahchara 78 No. S 97 No. Simulbari-2 74 No. Mahcikaripara 79 No. Sikaripara 83 No. Pampara 92 No. Mahchara NC 133 No. Simulbari M. Para 136 No. Chaira Bil Para 137 No. Khalabandha Para 139 No. Pampara B. Char 141 No. M. Pampara Eidgah 142 No. Sikaripara Bhatipara 143 No. Sikaripara NHM House 21 No. Sikaripara Jatham Mini 22 No. Pub Mahchara Tini Ali Kalbagan Para Mini 64 No. Mara Kalahi Abed Bepari Supa Mini 65 No. Pampara Bil Para Mini 117 No. Damdama KC 185 No. Bardia 82 No. Kasimpur 110 No. Kasimpur 2 132 No. Kasimpur P. Para 61 No. Kasumara 62 No. Ramharipara 1 96 No. Chunerchali 148 No. Kasumara 151 No. P. Andabhanga 64 No. Kasumara NC 1 66 No. Kasumara NC 2 63 No. Pahar Para 68 No. Holongapara 157 No. Holongapara Char 25 No. H. Uttar Char Mini 161 No. Mairadia Markas Maszid 27 No. Paschim Mairadia Mini 20 No. Mahchara Bazar Para Mini 24 No. Kasumara Tiapara Mini 23 No. Sikaripara Dapara Mini , 38 No. Pub Balartari 186 No. Sarudia 59 No. Damdama 33 No. Roumari Pathar III ,108 No. Paspir Dargah 35 No. Chata , 53 No. Subha Hindu Supa Mini 50 No. Yasin President Supa ,(33 Nos. fully damaged,57 Nos. partialy damaged)Reported by CDPO Date-23-6-2022, Barnagar - Anganwadi Centres Affected As per report received fro CDPO Office on 23/06/2022, an AWC namely 35 No. Pachim Balabhita AWC is affected due to flood and heavy rain,		
	Bongaigao n	Anganwadi Centres Affected As per report received fro CDPO Office on 23/06/2022, an AWC namely 142 N Jashihati Pachim Suba AWC, Village- Kalahbhanga is affected due to flood and heavy rain Manikpur - Fisheries/Pond 1 No of Pond at Barbilla village, reported by Fishery Deptt., date- 23.06.2022, Srijangram - Fisheries/Pond Total 31 Nos of Pond. Villages -(1) Matraghola-3 nos, (2)Balarchar-13 Nos, (3)Ambari-3 Nos, (4)Banglapara-3 Nos, (5) Kalikura-2 Nos, (6) Kacharipety Pt. II- 1 No, (7) Kokila Pt.II-1 No. (8)Chakla Pt.I- 3 Nos, (9) Dhalagasa-1 Nos. Reported by Fishery Deptt. date-23.06.2022		
Infrastructu re Damaged - Others	Darrang	Mangaldoi - Fisheries/Pond as reported by Fishery department total fish farmer affected approx. 3395 and total water area affected approx. 284.9 hect. Dated 22-3-2022, Power Dept. Poles as reported by APDCL approx.15 nos. of poles are damaged under mangaldai sub division. Dated 21-6-2022, Sipajhar - Power Dept. Poles 4 No poles have been damaged as on 23-06-2022 as reported by APDCL, Power Dept. Conductors 4 Km. (Approx) have been damaged as on 23-06-2022 as reported by APDCL, Fisheries/Pond Total 2762 Nos (approx.) of Fish afrmers and total water area 284.27 Hectre. (approx.) affected as on 23-06-2022 as reported by Fishery Department, Dalgaon - Power Dept. Poles As per report received from SDE, Mangaldai, Kharupetia, Majbat, Kalaigaon Su-Division, APDCL Electric Pole have been damaged at various villages under Dalgaon Rev. Circle. Date of Occurrence 15-06-2022 to 19-06-2022, Patharighat - Power Dept. Poles poles damages as reported by SDE APDCL on 23.6.2022		
	Dhubri	Dhubri - KISMATI Agamoni HALAKU Bridge Ap CHAR RA Bridge Ap ON GANI Bridge Ap BAUSER Bridge Ap	Culvert Approach Road Damaged CULVERT APPROCH & SIDE BERM DAMAGE ON HASDAHA ROAD TO BANIARTARI VILL ROAD(DATED-18-06-2022 TO 23-06-2022)), - Bridge Approach Road Damaged BRIDGE APPROACHES OF RCC BR. NO. 1/1 & 2/1 ON JRA HE SCHOOL TO KATHALTOLI ROAD (PMGSY) Dt. 04/06/2022-15/06/2022, pproach Road Damaged BRIDGE APPROACHES OF SEMI RCC BR. NO. 1/1 ON RANPAGLI TO ANPAGLI DAMAGED Dt. 04/06/2022-15/06/2022, pproach Road Damaged RCC BOX CELL CULVERT APPROACH OF CUL NO. 1/1 DAMAGED ESHERDHAM TO POKALAGI PT-II ROAD Dt. 04/06/2022-15/06/2022, pproach Road Damaged BRIDGE APPROACHES OF RCC BR. NO. 5/1 ON KHERBARI KUTI ROAD DAMAGED (.) Dt. 04/06/2022-15/06/2022, pproach Road Damaged SIDE BERM & RCC BRIDGE NO 7/1 ON PRATAPGANJ KHERBARI AMAGE. Dt. 04/06/2022-15/06/2022	
	Dibrugarh	Chabua - Anganwadi Centres Affected DODHIA KULIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 23/6/2022 N27 35.845 E 95 13.22. Anganwadi Centres Affected DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27 36.652 E95 14.237, Anganwadi Centres Affected DODHIA AWC SUBMERGED AS PER INFORMATION RECEIVED FR SOCIAL WELFARE DEPT ON 23/6/2022 N27 36.390 E95 13.651, Anganwadi Centres Affected UPPER GEREKI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 23/6/2022 N27 33.942 E95 15.125, Anganwadi Centres Affected DODHIA CHALBIL AWC SUBMERGED AS PER INFORMATION		

RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27. 5714 E95. 2346, Anganwadi Centres Affected | RONGMOLA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27 33'33.40" E95 11'47.26", Anganwadi Centres Affected | UPPER GEREKI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 23/6/2022, Anganwadi Centres Affected | 2 NO. MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27 33' 50.38" E95 13' 16.90", Anganwadi Centres Affected | MULUKGHAT MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27 33'52.36" E95 13'15.74", Anganwadi Centres Affected | TENGABARI-MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27 33'52.88" E95 13' 14.42", Anganwadi Centres Affected | GEREKI NEPALI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27 33'50.76" E95 15'26.01", Anganwadi Centres Affected | KULIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/62/22 N27 35.860 E95 13.460, Anganwadi Centres Affected | DODHIA ROMAI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27 36.450 E95 13.782, Anganwadi Centres Affected | CHALBIL AISUNG CHAPORI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 23/6/2022 N27 34.890 E95 13.563 Matia - Fisheries/Pond | No. of fisheries/pond affected = 16 and water area affected by flood = 2.00 Ha as reported by Fishery Development Officer, Matia Block on 23/06/2022, Goalpara Balijana - Fisheries/Pond | As reported by Fishery Development Officer, Kharmuza Block approximately 1654 nos. of farmer having water area of 354 Ha pond/ tank/community tank have been affected due to flood. Information received on 22.06.2022 Bokakhat - Elementary Schools Damaged | Lohore Chapori LPS, Kemeri Majdolopa chalami LPS, Lohore Golaghat Chapori MES got partially damaged on 22.06.2022 Doboka - Handloom & Textile Deptt | Affected weavers 438 nos. of villages are 1) Patiapam, 2) Baliram Gaon, 3) Nagayapam, 4) Kathkatia Bhakat Gaon, 5) Kamargaon, 6) Changjurai Kohargaon, 7) Kohargaon, 8) Era Kapili, 9) Borjari,, 10) Jamunamukh, 11) Patidoya, 12) Kandulimari on dated w.e.f. 15/06/2022, Hojai Handloom & Textile Deptt | SHG/PWCS in Hiya SHG, Nagayapam, 2) Sadana BKSS Ltd. Jamunamukh, 3) Jamuna BKSS Ltd, Jamunamukh, 4) Surabhi BKSS Ltd, Jamunamukh, Looms & Accessories 44 nos. damaged on dated w.e.f. 15/06/2022 Kayan - Power Dept. Poles | 8 nos. Date: 22/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL, Rangia.. Power Dept. Conductors | 1.3 km. Date: 22/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL, Kamrup Rangia., Kamalpur - Fisheries/Pond | Due incessant rainfall 19.5 ha as per report of Fishery development Officer Kamalpur on 22-06-2022 Gossaigaon - Bridge Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF ROAD DAMAGED BRIDGE NO. 2/2 ROAD FROM JOYMAGAON (GOMNA), Culvert Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 17.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF ROAD DAMAGED JOYMAGAON KULI RCC BOX CULVERT 2X2 1 CELL, Culvert Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD RCC BOX CULVERT APPROACHES AND REQUIRED ROAD REPAIRING BALAGAON BALLAMJHORA ROAD TO SRIRAMPUR CULVERT NO. 1/2, Culvert Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD GHAKSA VILLAGE 2 CELL RCC BOX CULVERT 2X2=1, Bridge Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED Kokrajhar ROAD BRIDGE NO. 2/2 JOYMAGAON (GOMNA) REQUIRED REPAIRING, Bridge Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 18.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF SAPATGRAM GOSSAIGAON ROAD RCC BRIDGE NO. 20/1 BOTH SIDE APPROACHES EROSION & SUBMERGED, Culvert Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED RCC BOX CULVERT 3X3X2 CELL FROM SADHU BOSTI TO RAIMONA VIA BANGTHI LP SCHOOL ROAD AT CH. 800.00M., Culvert Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF FLOOD DAMAGED ROAD RCC CULVERT 2X2X1 CELL (3 NOS.) AT BALLAMJHORA HINDI MEDIUM LP SCHOOL ROAD, Bridge Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN BIJOYNAGAR TO DOHORDHORA VILLAGE ROAD AT RCC BRIDGE NO. 1/1 APPROACH ON BOTH SIDE DAMAGED, Bridge Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN GURUFELLA SARAIBIL ROAD AT GOMNA BAZAR

WOODEN BRIDGE NO. 1/1 DAMAGED,

Culvert Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN JIRAMPUR TO BALAGAON ROAD AT CULVERT APPROACH DAMAGED,

Bridge Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN ERODED IMMEDIATE RESTORATION APPROACH OF RCC BR. NO. 1/2 ON BALLAMJHORA TO BALAGAON,

Bridge Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION SUBMERGED AND DAMAGED ROAD FORMATION AND APPROACH OF RCC BRIDGE, CULVERT AT KACHUGAON SANKOSH ROAD TO SRIRAMPUR FROM 1 KM TO 4 KM,

Washed away Culverts | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF APPROACH WASHED OUT OF RCC SLAB CULVERT 1/3 ON BALAGAON SRIRAMPUR ROAD,

Culvert Approach Road Damaged | AS PER REPORT RECEIVED FROM PWD RR KACHUGAON SUB DIVISION ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF NH31 C TO KURSHAKATI ROAD HPC SINGLE CULVERT NO. 6/2 ONE SIDE ERODED,

Kokrajhar - Damaged SPT Bridge | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, SPT BRIDGE ON GWITHWIBARI VILLAGE ROAD WAS DAMAGED,

Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, APPROACHES OF RCC BOX CULVERT NO. 1/2 ON SIALMARI TO PADMABIL VILLAGE ROAD WAS ERRODED,

Bamboo Foot Bridge | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, BAMBOO FOOT BRIDGE NO. 1/3 ON HALTUGAON BISHMURI ROAD TO CHANDRAPUR WAS DAMAGED,

Bridge Approach Road Damaged | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, APPROACHES OF RCC BRIDGE NO. 3/1 ON NH 31C TO AMGURI WAS ERRODED,

Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, APPROACHES OF RCC BOX CULVERT NO. 2/1 ON NAYEKGAON KAMARPARA ROAD TO GALAJHORA VILLAGE ROAD WAS ERRODED, Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, APPROACHES OF HP CULVERT NO. 1/1, 1/3, 2/1, 2/2, 2/3 AND 3/1 ON NAYEKGAON KAMARPARA ROAD TO GALAJHORA VILLAGE ROAD WAS ERRODED,

Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, APPROACHES OF RCC BOX CULVERT NO. 1/1 ON TARAIGURI TO BANDUGURI VILLAGE ROAD WAS ERRODED,

Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, APPROACHES OF RCC BOX CULVERT NO. 2/1 ON KOKRAJHAR BAHALPUR ROAD TO GARLAJHORA SALJHAR ROAD WAS ERRODED, Culvert Approach Road Damaged | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 20.06.2022, APPROACHES OF RCC BOX CULVERT NO. 1/1 ON KAONIABHASA BHATIPARA ROAD TO KURSHAKATI VILLAGE ROAD WAS ERRODED, Damaged SPT Bridge | AS REPORTED BY ASSTT. EXECUTIVE ENGINEER PWD KOKRAJHAR RURAL ROADS DIVISION ON 18.06.2022, SPT BRIDGE NO. 2/1 ON MOLANDUBI TO KHUKSHI(SILIPATHA) ROAD WAS DAMAGED,

Bhawraguri - Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 17-06-2022 HP CULVERT NO. 1/1 & 1/2 HAVE BEEN DAMAGED ON THAISOGURI TO DHANGURI VILLAGE ROAD, Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 17-06-2022 HP CULVERT NO. 1/1 & 1/3 HAVE BEEN DAMAGED ON DHANGURI VILLAGE TO MAORIAGAON VILLAGE ROAD PART-I, Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 17-06-2022 HP CULVERT NO. 1/1 & 1/3 HAVE BEEN DAMAGED ON DHANGURI VILLAGE TO MAORIAGAON VILLAGE ROAD PART-II, Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 17-06-2022 HP CULVERT NO. 1/1 & 1/3 HAVE BEEN DAMAGED ON DHANGURI VILLAGE TO MAORIAGAON VILLAGE ROAD PART-III, Culvert Approach Road Damaged | AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 17-06-2022 SUBMERGED ROAD FROM 1ST KM TO 2ND KM, HP CULVERT NO. 2/1, 2/2, 2/3, 2/4 & 2/5 HAVE BEEN PARTIALLY DAMAGED AT LAKRIGURI VILLAGE ROAD.,

Power Dept. Poles | AS REPORTED BY SDE, GOSSAIGAON ELECTRICAL SUB-DIVISION, APDCL, LAR GOSSAIGAON ON 23-06-2022 TOTAL LT POLES -10, HT POLE-2 DAMAGED DURING FLOOD 2022 TILL NOW ,

Power Dept. Conductors | AS REPORTED BY SDE, GOSSAIGAON ELECTRICAL SUB-DIVISION, APDCL, LAR GOSSAIGAON ON 23-06-2022 TOTAL LT CONDUCTERS -1, HT CONDUCTERS-0 DAMAGED

DURNG FLOOD 2022 TIJL NOW. Power Dept. Transformers AS REPORTED BY SDE. GOSSAIGAON ELECTRICAL SUB-DIVISION. APDCT, JAR GOSSAIGAON ON 23-06-2022 TOTAL 16 KVA-1, 25 KVA-3, 63 KVA-2, 100 KVA-2 DAMAGED DURNG FLOOD 2022 TILL NOW. Bagribari - Culvert Approach Road Damaged As reported by AFE, PWD Gossaigaon on 2206/2022, Culver has been damaged at Ch. 500M on Tiplaci Monoglajion and Road via Harjbron. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2206/2022, LIPC culvert has been damaged on Marchightors PH-110 Roshbarn Bazar Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2206/2022, LIPC culvert has been damaged on Marchightors PH-10 Roshbarn Bazar Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2206/2022, LIPC culvert has been damaged on Marchightors PH-10 Bookalpain PWD Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2206/2022, Lipcert washon at 878 Bilari Public High School to Silbari Pragial Road, - Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2306/2022, Approaches of culvert Robot of Silbari Pragial Road, - Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2306/2022, Approaches of culvert Robot of Silbari Partic Bilary School to Silbari Pragial Road, - Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2306/2022, approaches of culvert Robot of Silbari School to Silbari Pragial Road, - Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2306/2022, approaches of culvert Robot Pragial Road As reported by AEE, Act Robot Pragial Road As reported by AEE, ACT Robot Robot Pragial Road As reported by AEE, ACT Robot		
APDCL_LAR GOSSAIGAON ON 23-06-2022 TOTIAL 16 KWA -1, 25 KVA-3, 63 KWA-2, 100 KVA-2 DAMAGED DURRNOR FLOOD 2022 "LILL NOW, Bagribari - Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 22/06/2022, Culvert has been damaged at 16.5000 m Tipkato Bata with Mangharian Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 22/06/2022, HIPC culvert has been damaged on Marshilphora Pt-10 Robinshin Bazar Road, Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 22/06/2022, HIPC culvert has been damaged on Marshilphora Pt-10 Robinshipton BWD Road, Washed away Culverts As reported by AEE, PWD Gossaigaon on 22/06/2022, HIPC culvert has been damaged on Marshilphora Pt-10 Robinshipton BWD Road, Washed away Culverts As reported by AEE, PWD Gossaigaon on 23/06/2022, Culvert washout at Silbari Public High Schoul to Silbara Pragalt Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 23/06/2022, Approaches of culvert No.11/1 has been damaged on Jalahila to Silbara Boad. Quiter Approach Road Damaged As reported by AEE, PWD Gossaigaon on 23/06/2022, Approaches of culvert No.11/1 has been damaged on Jalahila to 33/06/2022 Approaches Silbara Boad. Dotton - Irrigation Cunal/Scheme Damaged As per reported by Duma Revenue Circle, Damage of Subkatha Subcanal at village PMBath by Flood on 23/06/2023 Bilbpurta - Hisberies/Pond As reported by HDO, Kannuhari Block on 23/16/2022 the nos. and area of native and the substance of the proach of the substance of		
Bagrithari - Culvert Approach Road Damagued As reported by AEE, PWD Gossaigaum on 2206/2022, Culvert has been damaged at Ch.500M on Tipkai to Monejalinora Road via Harjhona. Culvert Approach Road Damagued As reported by AEE, PWD Gossaigaon on 2246/2022, HPC culvert has been damaged on Marshuljhora Pt-11 to Bashbari Bazar Road, Culvert Approach Road Damagued As reported by AEE, PWD Gossaigaon on 2246/2022, HPC culvert has been damaged on Marshuljhora Pt-11 to Nolpani Road, Culvert Approach Road Damagued As reported by AEE, PWD Gossaigaon on 2246/2022, HPC culvert has been damaged on Marshuljhora Pt-11 to Balahuljhora Pt-10		
Bagribari - Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 22/06/2022, Culvert has been damaged at 16.500M on Tiplator Bayar Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 22/06/2022, HPC culvert has been damaged on Marshiptom Pt-11 to Babbarh Bazar Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 22/06/2022, HPC culvert has been damaged on Marshiptom Pt-10 to Noblahipton Pt-10 to Noblah		
has been dumaged at Ch.500M on Tipkai to Monglajliora Road via Harjhora. Culvert Approach Road Damaged 18 reported by AEE, PWD Gossiagou on 2206/2022, HPC culvert has been dumaged on Marshuljhora P-t1 to Bashbari Bazar Road, Culvert Approach Road Damaged 18 reported by AEE, PWD Gossiagou on 2206/2022, HPC culvert has been dumaged on Marshuljhora P-t1 to Nolpani Road, Culvert Approach Road Damaged 18 reported by AEE, PWD Gossiagou on 2206/2022, HPC culvert has been dumaged on Marshuljhora P-t1 to Bhalukjhora PvD Road, Washed away Culverts A reported by AEE, PWD Gossiagou on 2206/2022, Culvert washout at Silhari Pathic High School to Silhari Pargahi Road, Culvert Approach Road Damaged 18 reported by AEE, PWD Gossiagou on 2306/2022, Approaches of culvert No.11 has been damaged on Jalabila to Silhari Road, Doma I-trigation Canal/Scheme Damaged As per reported by Doma Revenue Circle, Damage of Subkatha Sub-canal at village Nalbari hy Hood on 23-06-2022 Miprima - Highwaria - Hisheries Pond As reported by PDO, Karausabari Block on 23/06/2022 the nos. and area of punds/unks affected are - 152 nos. (22 8 ha) at Somapur Block, 130 nos. (26 hajuk Somapur guon, 165 nos. (29.7 hajuk) and No.1 Somapur 23 nos. (23.02 ha) at No.2 Somapur and 93 nos. (13.03 ha) at Rescene guant and No.1 Somapur 23 nos. (23.02 ha) at No.2 Somapur and 93 nos. (13.03 ha) at Rescene guant and No.1 Somapur 23 nos. (23.02 ha) at No.2 Somapur Block, 130 nos. (26 hajuk Somapur guon, 165 nos. (29.7 hajuk) and No.1 Somapur 23 nos. (23.02 hajuk) at No.2 Somapur Block, 130 nos. (26 hajuk) Somapur guon, 165 nos. (29.7 hajuk) and No.1 Somapur 23 nos. (23.05 hajuk) and No.2 Somapur Block, 130 nos. (26 hajuk) Somapur guon, 165 nos. (29.7 hajuk) and No.1 Somapur 23 nos. (23.05 hajuk) and No.2 Somapur guon, 165 nos. (29.7 hajuk		
Culvert Approach Road Damaged As reported by AEE, PWD Gossaigano on 22/06/2022, HPC culvert has been damaged on Marshilphiran Falt in Bashbari Bazar Road. Culvert Approach Road Damaged As reported by AHE, PWD Gossaigano on 22/06/2022, HPC culvert has been damaged on Marshilphiran Falt in Oxigani Road. Culvert Approach Road Damaged As reported by AHE, PWD Gossaigano on 22/06/2022, HPC culvert has been damaged on Marshilphora Pt-10 Ballakilphora PWD Gossaigano on 22/06/2022, Culvert washout at Silbari Public High School to Silbari Pangal. Culvert Approach Road Damaged As reported by AHE, PWD Gossaigano on 23/06/2022, Approaches of culvert No. 1/1 has been damaged on Marshilphora Pt-10 Ballakilphora PWD Book Silbari Public High School to Silbari Pangal. Dottom - Irrigation Canad/Scheme Damaged As per reported by Dotma Revenue Circle, Damage of Subkatha Sib-canal at village Nabhari by Hodo on 23/06/2022, Approaches of culvert No. 1/2 has been damaged on Association on 23/06/2022, Approaches of culvert No. 1/2 has been damaged on 1/2 nos. (22.8 ha) at Sonapur Block in 30 nos. (26 ha) at Sonapur gaon, 165 nos. (29.7 hashilphora Pt-10 Ballakilphora Pt-10 Ballak		
damaged on Marshuljhora Pe-II to Baishbari Bazar Road, Culvert Approach Road Damaged Jax reported by AEE, PWD Gossaigaon on 22:06:2022, HPC culvert has been damaged on Marshuljhora Pe-II to Nolpani Road. Culvert Approach Road Damaged Jax reported by AEE, PWD Gossaigaon on 22:06:2022, HPC culvert has been damaged on Marshuljhora Pe-I to Bhaluslyhora PWD Road, Washed away Culverts Jax reported by AEE, PWD Gossaigaon on 23:06:2022, Approaches of culvert Nos. 17 has been damaged on Jatibia to Silhar Road, No. 17 has been damaged on Jatibia to Silhar Road, No. 17 has been damaged on Jatibia to Silhar Road, No. 17 has been damaged on Jatibia to Silhar Road, Dotton - Irrigation Canal/Scheme Damaged Jax reported by Dotton Revenue Circle, Damage of Subkatha Sub-cumid at village Nalbari by Flood on 23:06:2022 Bilipuria - Fisheries/Pond J Ax reported by FDO, Karunabari Block on 23:06:2022 the nos. and area of habat No. 15 comput. 23:3 nos. (32:02 ha) at No. 25 conapur Block, 130 nos. (26 habat Sonapur gan, 165 nos. (29:7 habat No. 15 conapur, 23:3 nos. (32:02 ha) at No. 25 conapur and 93 nos. (13:95 ha) at Reserve gaon Burageon - Elementry Schools Damaged J Bokari MY School affected from the crosion by Brahmaputra river on 22:06:2022. Mikirgaon near Tihulia beel, Mikirgaon and Plane Pl		
Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2206/2022, HPC culvert has been damaged on Marshiphora PH-10 Robpail Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 2206/2022, HPC culvert has been damaged on Marshiphora PH-10 Bhallshipton PWD Road. Washed away Culverts As reported by AEE, PWD Gossaigaon on 23/06/2022, Approaches of culvert No.17 has been damaged on Jackhiphora PWD Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 23/06/2022, Approaches of culvert No.17 has been damaged on Jackhiphora PWD Road Road. Dorna - Irrigation Canal/Scheme Damaged As per reported by Dotma Revenue Circle, Damage of Subkatha Sub-canal at village Nalbari by Flood on 23-06-2022 Billiphipuria - Fisheries-Pond As reported by FDO, Kanrushari Block on 23/06/2022 the nos. and area of ponds-tanks affected are - 152 nos. (22.8 ha) at Sonapur Block, 130 nos. (26 ha)at Sonapur gaun, 165 nos. (29.7 ha) xt No.15 conapur, 233 nos. (32.60 ha) at No.2 Sonapur and 93 nos. (31.95 sh) at Reserve gaon Blurraguon - Elementary Schools Damaged Bokami MV School affected from the erosion by Brahmapurra river on 22-06-2022. Mikirbheta - Fisheries-Pond As reported by BDO, Kapili on 22-06-2022. 1Nos. of Fishery submerged in Niz-Mikirgoon near Tilmital beel. Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgoon near Tilmital beel. Agri Bundh Damaged Dakarghat (E) Lohatiparagoon, bamunggoon, Fetachak, Submerged / Damaged Pumphouse reported by Nagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Idahapthat (Lohatiparagoon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Idahapthat (Lohatiparagoon, bamunggoon, Fetachak, Submerged / Damaged Pumphouse reported by Nagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Hababaraha (Irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Hababaraha (Irrigation) Nag		
dumaged on Marshuljbron Pi-II to Nolpani Road. Culvert Approach Road Damaged J. As reported by AEE, PWD Gossáigaon on 22/06/2022, HIPC culvert has been damaged on Marshuljbron Pi-I to Bhalusljborn PWD Road, Washed away Culvert J. As reported by AEE, PWD Gossáigaon on 23/06/2022, Culvert washout at Silbari Public High Schoot to Silbari Pargath Road. Culvert Approach Road Damaged J. As reported by AEE, PWD Gossáigaon on 23/06/2022, Approaches of culvert No. 1/1 hav been damaged on Jalabila to Silbari Road. Dotta Irrigation Canal/Scheme Damaged J. As per reported by Dottan Revenue Circle, Damage of Subkatha Sub-canal at village Nalbari by Hod on 23/06/2022 Biliparia Fisheries/Pond J. As reported by PDO, Karumahari Block on 23/06/2022 the nos. and area of ponds/harbanks affected are 152 nos. (22.8 ha) at Sonapur Block, 130 nos. (28 ha)at Sonapur gum, 165 ms. (29.7 ha)at No.1 Sonapur, 233 nos. (23/26 la) at No.2 Sonapur and 93 nos. (13/95 ha) at Reserve gaon Buragaon - Elementary Schoots Damaged J Bokam W School affected from the croston by Brahmapatra river on 22-06-2022. Mikirgaon near Tihulia beel, Mikirgaon sub-Division (irrigation) Nagaon, dated-23/06/2022. Irrigation Canal/Scheme Damaged J Dakarghat (R), Alenisatra Kolongpar, Submeged/ Damaged Pumphouse reported by Nagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022. Irrigation Canal/Scheme Damaged J Dakarghat (R), Alenisatra Kolongpar, Submeged/ Damaged Pumphouse reported by Nagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022. Irrigation Canal/Scheme Damaged J Lalab DTWS. Alpha Bebjia is Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022. Irrigation Canal/Scheme Damaged J Lalab DTWS. Alpha Bebjia is Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022. Irrigation Canal/Sch		
Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 22/06/2022, HPC culvert has been damaged on Marshiphora Pt-10 Bhulshipon PWD Road, Washed away Calverts As reported by AEE, PWD Gossaigaon on 23/06/2022, Culvert washout at Silbari Public High Schoot to Silbari Pargaht Road. Culvert Approach Road Damaged As reported by AEE, PWD Gossaigaon on 23/06/2022. Approaches of culvert No. 1/1 has been damaged on Jatabita to Silbari Road. Dotton - Irrigation Canal/Scheme Damaged As per reported by Dotton Revenue Circle, Damage of Subkatha Sub-camal at willage Nalbari by Flood on 23/06/2022. Lakhimpu Park P		
Washed away Culverts JAs reported by AEE, PWD Gossaigaon on 23:06:2022, Culvert washout at Silbari Public High School to Silbari Pangalin Road. Culvert Approach Road Damaged JAs reported by AEE, PWD Gossaigaon on 23:06:2022, Approaches of culvert No.1/1 has been damaged on Jalabila to Silbari Road, Dotma - Irrigation Canal/Scheme Damaged JAs per reported by Dotma Revenue Circle, Damage of Subkatha Sub-canal at village Nalbari by Flood on 23:06-2022 Bibpuria - Fisheries/Pond JAs reported by FDO, Karunahari Block on 23:06:2022 the nos. and area of pods/stanks affected are - 152 nos. (22.8 ha) at Sonapur Block. 130 nos. (26 ha) at Sonapur and 93 nos. (139 sha) at Reserve gaon Bhurragon - Elementary Schools Damaged J Bokani MV School affected from the erosion by Brahmaputra river (oz. 22-06-2022. Mikirbeta - Fisheries/Pond JAs reported by BDO, Kapili on 22-06-2022. Nos. of Agri Bandh Damaged JAs reported by BDO, Kapili on 22-06-2022. Nos. of Agri Bandh damaged in Niz-Mikirgaon near Tihulia beel. Agri Bundh Damaged JAs reported by BDO, Kapili on 22-06-2022, Nos. of Agri Bandh damaged in Niz-Mikirgaon and Scheme Damaged J Dakarghat (Albahapargaon, Banamagaon, Fatechauk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23:06/2022, Irrigation Canal/Scheme Damaged J Dakarghat (Albahapargaon, Banamagaon, Fatechauk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23:06/2022, Irrigation Canal/Scheme Damaged J Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23:06/2022, Irrigation Canal/Scheme Damaged J Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23:06/2022, Irrigation Canal/Scheme Damaged J Pub-Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23:06/2022, Irrigation Canal/Scheme Damaged J Pub-Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagao		
High School to Silhari Pargain Road. Culvert Approach Road Damaged I As reported by AFE, PWD Gossaigaon on 23/06/2022, Approaches of culvert No. I/1 has been damaged on Jalabia to Silbari Road. Dotma - Irrigation Canal/Scheme Damaged As per reported by Dotma Revenue Circle, Damage of Subkatha Sub-canal at village Nalbari by Flood on 23-06-2022 Bilipuria - Fisheries/Pond As reported by FIDO, Karunubari Block on 23/06/2022 the nos. and area of ponds'ataks affected are - 152 nos. (22.8 ha) at Sonapur Block, 130 nos. (26 ha) at Sonapur gaon, 167 nos. (29.7 ha) at No.1 Sonapur, 233 nos. (23.62 ha) of No.2 Sonapur and 93 nos. (13.95 ha) at Reserve gaon Buragaon - Elementary Schools Damaged Bokani MV School affected from the resois on by Brahmapura river on 22-06-2022, Mikirjason near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirjason near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirjason near Tihulia beel, Agri Bundh Damaged Dakarghat ((Lihatiparagion, hamungaon, Fetichuk, Suhnerged/ Damaged Pumphouse reported byNagaon Sub-Division (trigation) Nagaon, adued-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, 10.6 & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (trigation) Nagaon, adued-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (trigation) Nagaon, adued-23/06/2022, Irrigation Canal/Scheme Damaged Dawland DTWS, Ranthali rijabheti; Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (trigation) Nagaon, adued-23/06/2022, Irrigation Canal/Scheme Damaged Dawland DTWS, 2 Ranthal rijabheti; Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (trigation) Nagaon, adued-23/06/2022, Irrigation Canal/Scheme Damaged Dawland DTWS, 2 Ranthal rijabheti; Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (trigation) Na		damaged on Marshuljhora Pt-I to Bhalukjhora PWD Road,
Culvert Approach Road Diamaged As reported by AFE, PWD Gossigaon on 23/06/2022, Approaches of culvert No.1/1 has been damaged on Jabiat to Silbari Road, Dotma - Irrigation Canal/Scheme Damaged As per reported by Dotma Revenue Circle, Damage of Subkatha Sub-canal at village Nalbari by Flood on 23-06-2022 Bilipuria - Fisheries/Pond As reported by FDO, Karunabari Block on 23/06/2022 the nos. and area of ponds/fanks affected are - 152 nos. (22.8 ha) at Sonapur Block, 130 nos. (26 ha) at Sonapur and 93 nos. (13.95 ha) at Reserve gaon and 31 No.1 Sonapur, 233 nos. (23.02 ha) at No.2 Sonapur and 93 nos. (13.95 ha) at Reserve gaon Bhuragaon - Elementary Schools Damaged Bokani MV School affected from the erosion by Brahmaputra river of 22-06-2022. (20.2)		
No.1/1 has been damaged on Jalabila to Silbari Road. Dotma - Frigation Canal/Scheme Damaged As per reported by Dotma Revenue Circle, Damage of Subkatha Sub-canal at village Nalbari by Flood on 23-06-2022 Bilipuria - Fisheries/Food As reported by FDO, Karunabari Block on 23:06-2022 the nos. and area of ponds/anks affected are - 152 nos. (22.8 ha) at Sonapur Block, 130 nos. (26 ha) at Sonapur gaon, 165 nos. (29.7 ha) at No.1 Sonapur, 233 nos. (32.62 ha) at No.2 Sonapur and 93 nos. (13:95 ha) at Reserve guon Bhuragon - Elementary Schools Damaged Bokani MV School affected from the erosion by Brahmaputra river (no. 22-06-2022) Mikirgaon near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022 1 Nos. of Fishery submerged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, Nos. of Agri Bandh damaged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Damaged Dakarghat (Ri), Alenisatra Kolongpar, Submeged/ Damaged Pumphouse reported byNagaon Sub-Division (ririgation) Nagaon, dated-23:06/2022. Irrigation Canal/Scheme Damaged Dakarghat (Li)hatiparagon, bamungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (ririgation) Nagaon, dated-23:06/2022. Irrigation Canal/Scheme Damaged Jahah DTWS, 1No. & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (ririgation) Nagaon, dated-23:06/2022. Irrigation Canal/Scheme Damaged Jahah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (ririgation) Nagaon, dated-23:06/2022. Irrigation Canal/Scheme Damaged Johah DTWS, Ranthali riajbheti, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (ririgation) Nagaon, dated-23:06/2022. Irrigation Canal/Scheme Damaged Bebeji at Nobmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (ririgation) Nagaon, dated-23:06/2022. Irrigation Canal/Scheme Damaged Bebeji at Nobmoria DTWS 2 Points, Submerged/ Damaged Pumphouse reported byNa		
Dotma - Irrigation Canal/Scheme Damaged As per reported by Dotma Revenue Circle, Damage of Subkatha Sub-canal at village Nalbari by Piodo on 23-06-2022		
Sub-canal at village Nalbari by Flood on 23-06-2022 Bihpuria - Fisheries/Pond As reported by FDO, Karunabari Block on 23/06/2022 the nos. and area of pondstanks affected are - 152 nos. (22.8 ha) at Sonapur Block, 130 nos. (26 ha)at Sonapur gaon, 165 nos. (29.7 ha)at No.1 Sonapur, 233 nos. (32.62 ha) at No.2 Sonapur and 93 nos. (13.95 ha) at Reserve gaon Buragad Bokani MV School affected from the crosion by Brathmaputra river on 22-06-2022. [Mikirpaon Lementary Schools Damaged Bokani MV School affected from the crosion by Brathmaputra river on 22-06-2022. [Nos. of Fishery submerged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon - Irrigation Canal/Scheme Damaged Dakarghat (It)hatiparagaon, barded-23/06/2022, Irrigation Canal/Scheme Damaged Dakarghat (It)hatiparagaon, bamungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, 1No. & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dawhar DTWS, Alopia Bebejia , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dawhar DTWS, Salah Gano, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gano, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gano, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gano, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gano, Sub		
Lakhimpu Bilipuria - Fisheries/Pond As reported by FIDO, Karunabari Block on 23/06/2022 the nos. and area of ponds/tanks affected are - 152 nos. (22.8 ha) at Ros. (29.7 ha)at No.1 Sonapur, 233 nos. (23.62 ha) at No.2 Sonapur and 93 nos. (13.95 ha) at Reserve gaon Bluragaon - Elementary Schools Damaged Bokani MV School affected from the erosion by Brahmaputra river on 2-2-06-2022. Mikirbheta - Fisheries/Pond As reported by BDO, Kapili on 22-06-2022 lNos. of Fishery submerged in Niz-Mikirgaon near Timulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon near Timulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon Nagaon - Irrigation Canal/Scheme Damaged Dakarghat (Rt), Alenisatra Kolongpar, Submeged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dakarghat (Li)hatiparagaon, hamaungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, I No. & No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dadhar DTWS, Ranhali rajabbeti , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bublar DTWS, Islah Managan, Jalah Caon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Submyosed MDTW Scheme a Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tushimukh DTWS, Tushimb		
Dandstanks affected are - 152 nos. (22.8 ha) at Sonapur Block, 130 nos. (26 ha)at Sonapur gaon, 165 nos. (29.7 ha)at No.1 Sonapur, 233 nos. (32.62 ha) at No.2 Sonapur, and 93 nos. (13.95 ha) at Reserve gaon Bhuragaon - Elementary Schools Damaged Bokami MV School affected from the crosion by Brahmaputra river on 22-06-2022, Mikiripaton - Elementary Schools Damaged Bokami MV School affected from the crosion by Brahmaputra river on 22-06-2022, 1 Nos. of Fishery submerged in Niz-Mikirgaon near Tihulia beel. Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon - Nagaon - Irrigation Canal/Scheme Damaged Dakarghat (Li)hatiparagaon, banungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dakarghat (Li)hatiparagaon, banungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwhar DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Brown Nagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported by		
Indigate No. 1 Sonapur, 233 nos. (32.62 ha.) at No. 2 Sonapur and 93 nos. (13.95 ha.) at Reserve gaon Bhurgaon - Elementary Schools Damaged Bokani MV School affected from the erosion by Brahmaputra river on 22-06-2022. Mikirbheta - Fisheries/Pond As reported by BDO, Kapili on 22-06-2022 Nos. of Fishery submerged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022 Nos. of Agri Bandh damaged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon Nigaon - Irrigation Canal/Scheme Damaged Dakarghat (Rt), Alenisatra Kolongpar, Submeged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dawkapta (Li)hatiparagaon, bamamgaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, I Ros. 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwdbra DTWS, Ranthali rajabheti , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gaon Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubhimuk DTWS, Tubhimuh Hujgaon, Matherged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubhimuk DTWS, Tubhimuh Hujgaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubhimuk DTWS, Tubhimuh Hujgaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubhimuk DTWS, Tubhimuh Hu	Lakhimpu	
Bhuragaon - Elementary Schools Damaged Bokani MV School affected from the erosion by Brahmaputra river on 22-06-2022. Mikirphota - Fisheries/Pond As reported by BDO, Kapili on 22-06-2022 1Nos. of Fishery submerged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon	r	
On 22-06-2022, Mikirbheta - Fisheries/Pond As reported by BDO, Kapili on 22-06-2022 1Nos. of Fishery submerged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Dumaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Dumaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon Nagaon - Irrigation Canal/Scheme Damaged Dakarghat (Rt), Alenisatra Kolongpar, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Dakirghata DTWS, 1Ro, & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, 1Ro, & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Data DTWS, Ranthali rajabheti, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Tuhlshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Tuhlshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Tuhlshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23-06/2022, Irrigation Canal/Scheme Damaged Tuhlshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNag		
Mikirbheta - Fisheries/Pond As reported by BDO, Kapili on 22-06-2022 Nos. of Fishery submerged in Niz-Mikirgaon near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon Nagaon - Irrigation Canal/Scheme Damaged Dakarghat (Rt), Alenisatra Kolongpar, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dakarghat (Lubhatiparagaon, bamungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, INo. & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jahah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwhalar DTWS, Ranthali rajabheti, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubhimukh DTWS, Tubhimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubhimukh DTWS, Tubhimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubhimukh DTWS, Tubhimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubhimukh DTWS, Tubhimuh Hu		
Mikirgaon near Tihulia beel, Agri Bundh Damaged As reported by BDO, Kapili on 22-06-2022, 2 Nos. of Agri Bandh damaged in Niz-Mikirgaon Nagaon - Irrigation Canal/Scheme Damaged Dakarghat (Rt), Alenisatra Kolongpar,Submeged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dakarghat (Lt)hatiparagaon, bamungaon, Fetachuk,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, 1No. & 2 No. Jalah Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Brownerd MDTWs, Tulshimukh Hujgaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimukh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimukh DTWS, Tulshimukh DTWS, Tulshimukh Pumphouserged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshim	м	,
Nagaon - Irrigation Canal/Scheme Damaged Dakarghat (Rt), Alenisatra Kolongpar, Submeged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dakarghat (L)hatiparagaon, bamungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, INo. & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwdhar DTWS, Ranthali rajabheti, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tw Points under PMKSY Hkkp-phase-1, Total - 1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tw Points under PMKSY Hkkp-phase-1, Total - 1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Trestile Depti Total - Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Total - Tulshimuh Hujgaon, Submerged/ Dam	Morigaon	
Nagaon - Irrigation Canal/Scheme Damaged Dakarghat (Rt), Alenisatra Kolongpar, Submeged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dakarghat (Lt)hatiparagaon, bamungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, 1No. & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwdhar DTWS, Ranthali rajahbeti, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022, Pondard Pondard Pondard Pondard Pakhimoria Dev. Block, dayted-23/06/2022, Pondard		
Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dakarghat (L.)hatiparagaon, bamungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, INo. & 2 No. Jalah , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Damaged Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub -Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points , Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Subprovered MDTWs Scheme at Dakhinpat, Dakhinpat, Bakhinpat, Bakhi		
Irrigation Canal/Scheme Damaged Dakarghat (Li)hatiparagaon, bamungaon, Fetachuk, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, 1No. & 2 No. Jalah, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwdhar DTWS, Ranthali rajabbeti, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected, Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23/06/2022, Tibu-Anganwadi Centres Affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, R		
Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Majulipathar DTWS, 1No. & 2 No. Jalah ,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Duwhar DTWS, Ranthali rajabheti , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub - Jalah DTWS, Jalah Gaon ,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points , Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tub Points under PMKSY Hkkp-phase-1, Total - 1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tub Points under PMKSY Hkkp-phase-1, Total - 1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tub Points under PMKSY Hkkp-phase-1, Total - 1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tub Points under PMKSY Hkkp-phase-1, Total - 1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tub Points under PMKSY Hkkp-phase-1, Total - 1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dat		
Irrigation Canal/Scheme Damaged Majulipathar DTWS, 1No. & 2 No. Jalah ,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Jalah DTWS, Alpoin Bebejia , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwdhar DTWS, Ranthali rajabheti , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub - Jalah DTWS, Jalah Gaon ,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub - Jalah DTWS, Tubinomia DTWS 2 Points , Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW Scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubinimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubinimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tubinimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinib		
reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged J Jalah DTWS, Alopia Bebejia, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwdhar DTWS, Ranthali rajabheti, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub-Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points, Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW Scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hikkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022. Timu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT. INFORMATION RECEIVED FROM CDPO,BARAMA,DATE OF SUBMERGED:17/06/2022 Tibla - Anganwadi Centres Affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road a		
Irrigation Canal/Scheme Damaged Jalah DTWS, Alopia Bebejia , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Pumbhar DTWS, Ranthali rajabheti , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub - Jalah DTWS, Jalah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points , Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Bothipatore (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc . Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Rohimibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged		
byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwdhar DTWS, Ranthali rajabheti , Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Pub -Jalah DTWS, Jalah Gaon ,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points , Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO, BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill. Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarch		
Nagaon Nagaon Nagaon Nagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Dwbhar DTWS, Palah Gaon, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points , Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tw Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tw Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc . Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Rubinibill., Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due		
Paschim Nalbari - Handloom & Textile Deptt 19 nos. of wavers Femalely affected , Damage of loom accessories, waven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tibu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA LCDS PROJECT. INFORMATION REfected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dbekiajuli Div, due to torrential rain surging water of Ghogra river have damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged de to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points , Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850, date 21.6.22 South Salmara - Anganwadi Centres		
byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Bebejia to Mohmoria DTWS 2 Points , Sukatiputa Lumati, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 Sou	Nagaan	Irrigation Canal/Scheme Damaged Pub - Jalah DTWS, Jalah Gaon ,Submerged/ Damaged Pumphouse reported
Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc . Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kach	Nagaon	byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022,
Irrigation Canal/Scheme Damaged Solarpowered MDTW scheme at Dakhinpat, Dakhinpat Kampur, Submerged/Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected, Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT. INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per i		
Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc . Information received from Handloom and textile Department on 23.06.2022, Tibu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water		
Irrigation Canal/Scheme Damaged Tulshimukh DTWS, Tulshimuh Hujgaon,Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon , dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected , Damage of loom accessories, weaven cloths etc . Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:11/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affe		
reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected, Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Irrigation Canal/Scheme Damaged TW Points under PMKSY Hkkp-phase-1,Total -1004Ponts-Submerged/ Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected, Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT.INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Damaged Pumphouse reported byNagaon Sub-Division (irrigation) Nagaon, dated-23/06/2022, Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected, Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT. INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Fisheries/Pond 100 Nos. of Pond affected under Pakhimoria Dev. Block, dayted-23/06/2022 reported by Fishery Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected, Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Dev. Officer, pakhimoria Dev. Block Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected, Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT.INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Paschim Nalbari - Handloom & Textile Deptt 19 nos. of weavers Femalely affected, Damage of loom accessories, weaven cloths etc. Information received from Handloom and textile Department on 23.06.2022, Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT. INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Tihu - Anganwadi Centres Affected TOTAL 11 NOS OF AWC DAMAGED UNDER BARAMA ICDS PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
PROJECT .INFORMATION RECEIVED FROM CDPO,BARAMA.DATE OF SUBMERGED:17/06/2022 Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara	Nalbari	·
Thelamara - Fisheries/Pond As reported by District Fishery Development Officer, Sonitpur on 23/06/2022, 24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara	1 1010011	
24.39 Ha. of pond area is affected of villages- Johamari, Hojaigaon, 2 No. Borpukhuri, 1 No. Borpukhuri, Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villlages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Thelamara, Punioni, Ruhinibill., Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villlages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Fisheries/Pond As reported by Fishery Development Officer, Dhekiajuli, Sonitpur on 23/06/2022, 16.49 Ha. of pond area is affected of villlages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
pond area is affected of villlages- Ruhinibill, Kamarchuburi, Bordubi, Kathonibari, Bhergaon, Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Sonitpur Dhekiajuli - Culvert Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
surging water of Belsiri river have damaged the side shoulder restrain wall and ICPB on 17 June along Batasipur to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara	Sonitour	1.
to Sudemjuli road at CH 850. date 21.6.22, Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara	Sompui	
Bridge Approach Road Damaged As reported by PWD Dhekiajuli Div, due to torrential rain surging water of Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Ghogra river have damaged the approach of RCC bridge no 7/2 on 17 June along Ghogra kachari to panchnoi nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
nepali road. date 21.6.22 South Salmara - Anganwadi Centres Affected As per information received from concerned CDPO 69 no Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
South Salmara Boidergaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L Lat - 25.854948' Long - 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Soluti Salmara 89.979449', Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
Salmara 89.979449°, Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara	South	
Anganwadi Centres Affected As per information received from concerned CDPO 70 no Boidergaon Nayapara		
AW WC has been damage due to flood water as on 22/0/22 area 0B-1K-5L Lat - 25.854948 Long - 89.9/9449,		
		Aw we has been damage due to hood water as on 22/6/22 area UB-1K-5L Lat - 25.854948' Long - 89.9/9449',

		Anganwadi Centres Affected As per information received from concerned CDPO 78 no Simlakandi AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L. Lat - 25.863503' Long - 90.003124' , Anganwadi Centres Affected As per information received from concerned CDPO 79 no Kalabari AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L. Lat - 25.855868' Long - 90.010631' , Anganwadi Centres Affected As per information received from concerned CDPO 53 no Teltary AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L. Lat - 25.886302' Long - 90.01358' , Anganwadi Centres Affected As per information received from concerned CDPO 55 no Barmanpara AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L. Lat - 25.884891' Long - 90.016469' , Anganwadi Centres Affected As per information received from concerned CDPO As per information received from concerned CDPO 57 no Salmara nayagaon pt-i AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L. Lat - 25.885832' Long - 90.013402', Anganwadi Centres Affected As per information received from concerned CDPO As per information received from concerned CDPO 52 no Baladoba kandargaon AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L. Lat - 25.895764' Long - 90.022412' , Anganwadi Centres Affected As per information received from concerned CDPO As per information received from concerned CDPO 51 no Baladoba daspara AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L. Lat - 25.896464' Long - 90.022911' ,
		Anganwadi Centres Affected As per information received from concerned CDPO As per information received from concerned CDPO 128 no Monirchar daspara AWWC has been damage due to flood water as on 22/6/22 area 0B-1K-5L. Lat - 25.851622' Long - 89.976943' Tamulpur - Power Dept. Poles 2 LT pole damaged on 15/6/22 at village Khairani information received from
		APDCL on 23/6/22, Power Dept. Poles 1 HT pole damaged on 15/6/22 at village Borbalishia information received from APDCL on 23/6/22, Power Dept. Poles 1 HT pole damaged on 15/6/22 at village Uttar Gandhibari information received from
	Tamulpur	APDCL on 23/6/22, Power Dept. Poles 1 HT pole damaged on 15/6/22 at village Dighalipar information received from APDCL on 23/6/22, Power Dept. Poles 1 LT pole damaged on 15/6/22 at village Bhrnagar information received from APDCL on
		23/6/22, Power Dept. Poles 1 HT pole damaged on 15/6/22 at village 2 no Dangargaon information received from APDCL on 23/6/22, Irrigation Canal/Scheme Damaged Breach Occored at R/B of Bengsimari Dong at the up stream at CH.960 M
		information received from irrigation department Harisinga - Power Dept. Poles LT and HT poles at Kulshi river, Dharamjuli Jungle, Atterikhat Bazar damaged on 22/06/2022. under Tangla electrical sub-division, Kalaigaon - Bamboo Foot Bridge The temporary bamboo foot bridge on Ramhari to Tangni-kalaigaon road has collapsed and washed away on 23/06/2022 due to erosion caused by overflowing of flood water from river Noa and Kawadanga at village Barjhar Bagisha. Length: 30 meters, Breadth: 3.5 meters. Longitude:92.035605, Latitude: 26.537627,
	Udalguri	Bamboo Foot Bridge The temporary bamboo foot bridge on Sujal to Sujal Chouhans road via Garubandha Gomtha PMGSY link road has collapsed and washed away on 23/06/2022 due to erosion caused by overflowing of flood water from river Kulshi at village Khas Bokrajhar. Length: 30 meters, Breadth: 3.5 meters. Longitude:92.951865, Latitude: 26.546752, Power Dept. Conductors Several HT conductors and LT conductors snapped at village Batiamari, Gerua(Beltoli), Habibhanga, Ranipukhuri, Tatelibhanguri, Ranthali, Uttar Barpukhuri, Niz kalaigaon, No 2 Singrimari, Bholabari, Niz Dala, Chengapather, No 1 Amguri, Majarchuba, Sagunbahi, Ojagaon and Jhargaon on 23/06/2022 due to erosion caused by receding flood water by river Noa, Kulshi and Kawadanga.
		erosion caused by receding flood water by river Noa, Kulshi and Kawadanga, Power Dept. Poles Several HT and LT poles damaged on 23/06/2022 at village Tamaru, Gerua, Bhehuguri, Chintagaon, No 2 Kalaigaon, Gerua (Beltoli) and Habibhanga due to erosion caused by receding flood water from river Noa, Kulshi and Nanoi, Agri Bundh Damaged Namjalah Erosion protection project under Udalguri District under RIDF-XXV at village Namjalah has damaged on 23/06/2022 due to heavy current at the junction of three rivers namely, Nanoi, Huduma and Naika. Type of damage: 6 numbers of boulder spurs. Length: 12 meters in each spurs and breadth 3 meters in each spurs. Longitude: 91.543906, Latitude: 26.380412
	District	Details
Erosion	Baksa	Baska - Dakhinsupa, Digaldhanga & Dhanbil, Gully erosion occurred at village Dakhinsupa, Digaldhanga &
	Barpeta	Dhanbil, on 18/06/2022 Dhanbil Coordinate: 26.641028, 91.33403 0 Kalgachia - 1. Kharballi vill, 2. Balaipather vill 1. As per LM report on 23/06/22 In kharballi vill land eroded-1B-1K-05L, coordinates- 26.36478, 90.92356. 2. As per LM report on 23/06/22 In Balaipather vill land eroded-1B-2K-15L, coordinates- 26.36588, 90.92584. 65
	Biswanath	Gohpur - No. 3 Upor Tinisukia Village Near about 3 Bighas of land has been eroded by River Brahmaputra due to which 2 Nos. families have shifted their house to a safer location.22-06-2022 10
		Manikpur - Bashbari no 2. Erosion Took Place in bashbari no 2 due to river Aie on Dated-23.06.2022 approx
	Bongaigao	60mtr erode away. 2200,
	Bongaigao n	=

	Dhubri	South Salmara Part - Chatla Bilpara, Matifata As per information received from CDPO 25 No chatlabilpara AWWC has been eroded due to erosion by river Brahmaputra at Bilpara. On 22/6/22 area 0B-1K-5L lat-90.04 long-25.93 As per information received from CDPO 44 No Matifata bilpara AWWC has been eroded due to erosion by river Brahmaputra at Matifata a. On 22/6/22 area 0B-1K-5L lat-25.93 long -90.04 As per information received from CDPO 36 No Matifata AWWC has been eroded due to erosion by river Brahmaputra at Bilpara. On 22/6/22 area 0B-1K-5L lat-90.04 long-25.93 As per information received from CDPO 24 No Chatlabilpara AWWC has been eroded due to erosion by river Brahmaputra at Matifata a. On 22/6/22 area 0B-1K-5L lat-25.93 long -90.04 0
	Kokrajhar	(Kokrajhar) At District - KOMOLACHORA AUZARGURI BECHIMARI UTTAR PATGAON MORNAI TEA GARDEN RAJADABRI SURJYAKHATA DOTMA SHANTI NAGAR AS REPORTED BY EXECUTIVE ENGINEER WR DIVISION, KOKRAJHAR ON 19-06-2022 1. BANK EROSION OBSERVED AT VILLAGES KOMOLACHORA (REACH LENGTH-300M) ON R/B, BARUAPARA (REACH LENGTH-220M) ON L/B, MOKRAPARA (REACH LENGTH-210M) ON L/B OF RIVER GAURANG. 2. BANK EROSION OBSERVED AT VILLAGES AUZARGURI (REACH LENGTH-230M) ON R/B, SAMSINGKELA (REACH LENGTH-250M) ON R/B OF RIVER CHAMPAMATI. 3. BANK EROSION OBSERVED AT VILLAGE BECHIMARI BANGLABASTI (REACH LENGTH-150M) ON L/B OF RIVER HEL. 4. BANK EROSION OBSERVED AT VILLAGE UTTAR PATGAON FROM CH.2200M TO 2600M ON L/B EMBANKMENT OF RIVER SARALBHANGA. 5. BANK EROSION OBSERVED AT MORNAI TEA GARDEN SECTOR 60, 62(REACH LENGTH-300M) ON R/B OF RIVER BORNAI. 6. BANK EROSION OBSERVED AT VILLAGE MALBHOG (REACH LENGTH-200M) ON R/B OF RIVER MALBHOG. 7. BANK EROSION OBSERVED AT VILLAGE MALBHOG (REACH LENGTH-200M) ON R/B OF RIVER MALBHOG. 7. BANK EROSION OBSERVED AT VILLAGES RAJABADRI BASHJHURI(REACH LENGTH-400M) ON R/B, SINGIMARI(REACH LENGTH-600M) ON B/B, WEST GARDENPUR(REACH LENGTH-300M) ON R/B, KURSHAMARI SANTALBASTI D/S OF EXISTING SCHEME, ALI NAGAR BORO BASTI(REACH LENGTH-400M) ON R/B, KAWAIMARI SANTALBASTI D/S OF EXISTING SCHEME, ALI NAGAR BORO BASTI(REACH LENGTH-300M) ON R/B, KAWAIMARI SANTALBASTI D/S OF EXISTING SCHEME, ALI NAGAR BORO BASTI(REACH LENGTH-400M) ON R/B, KURSHAKATI NO. 1 (PAMPARA REACH LENGTH-400M) ON R/B, GHONAPARA (REACH LENGTH-300M) ON R/B, KANUPARA NO. 2 (REACH LENGTH-300M) ON R/B, KANUPARA NO. 2 (REACH LENGTH-300M) ON R/B, BAMUNIJHORA (REACH LENGTH-300M) ON R/B, KANUPARA NO. 2 (REACH LENGTH-300M) ON R/B, THAKTHAKI PARA (REACH LENGTH-300M) ON R/B, HORINPUR (REACH LENGTH-300M) ON R/B, THAKTHAKI PARA (REACH LENGTH-300M) ON R/B, HORINPUR (REACH LENGTH-300M) ON R/B, DURABIL (REACH LENGTH-200) ON R/B OF RIVER GANGIA. 9. BANK EROSION OBSERVED AT VILLAGE DOTMA SHANTI NAGAR (REACH LENGTH-300M) ON R/B, DURABIL (REACH LENGTH-200) ON
	Lakhimpu r	Bihpuria - No. 1 Parbatipur near Dikrong river Active erosion observed near Dikrong river bank of No.1 Parbatipur since 22/06/2022. As reported by concerned LM, approximately 0.5 hectare of land has been eroded. 0
	Morigaon	Bhuragaon - Betani Erosion is going on at Betani village from 22-06-2022 0, Mayong - RajaMayong Hill Reserve Forest 0.04 Hectares of erosion as reported by Range Officer PWLS on 23/06/22 0, Laharighat - Leruamukh, Goroimari, Bhajaukhaiti and Borchapori As per report received from the Water resources dept on 23-06-2022, erosion is observed in areas like Leruamukh, Goroimari, Bhajaukhaiti and Borchapori with maximum erosion of 1 m in Leruamukh, 1 m in Goroimari, 2 m in Bhajaukhait gaon i and 2 m in Borchapori 0
	Nalbari	Banekuchi - Pub Bangnabari Erosion had occured in Lata Jan at Pub Bangnabari report from Gaon Pradhan on 18/6/2022 120
	Sonitpur	Thelamara - Village- Kahikuchi and Baligaon Bongali As reported by Tezpur Water Resource Division, Tezpur on 22/06/2022, bank erosion is observed at Kahikuchi area on R/B of River Gabharu of length 430m. Bank erosion is also observed at Baligaon Bongali on L/B of river Belsiri of length 700m. 0
	Tamulpur	Goreswar - 1. Village- No. 2 Suagpur and 2. Village Madaikata 1. Dated 22/06/2022, As informed by Water resource department erosion occurs on east bank of River Puthimari approximate damage 100 m. 2. Dated 22/06/2022 as reported by Lot Mandal a historical place the Arimatta Garh Village Madaikata got breached due to flood water approximately width of damage 80 m. 0
	Udalguri	Udalguri - 1. Tarajuli 2. Bajrajhar (Rowta Bagan) 3. No. 1 Sapkhaity 4. Kalajhar 1. Erosion Occured on R/B of Dhansiri river at Tarajuli village around 250m on 22.06.2022. GPS - Lat - 26.76347528 Long - 92.19341611 2. 1. Erosion Occured on both bank of Dhansiri river on at Bajrajhar (Rowta Bagan) around 300m on 22.06.2022. GPS - Lat - 26.72213 Long - 92.23409 3. Severe bank erosion near Kangkali chowk RTP at No 1 Sapkhaiti village by Sapkhaity river around 40m on 22.06.2022. GPS - Lat - 26.72213 Long - 92.23409. 4. Erosion Occured on the both bank of river Golandi at Kalajhar village around 300m on 22.06.2022. GPS - Lat - 26.84656 Long - 92.09942 0
	District	Details
Landslide	Cachar	Sonai - Rajgovindapur village, Bongram & Syamacharanpur House of Khokan Sarkar c/o Sachinanada Sarkar got damaged due to landside at Rajgovindapur village under Sonai Revenue Circle on 22.06.2022. 13
	Hailakand i	Hailakandi - Mohanpur RA under Hailakandi Revenue Circle dtd. 22.06.2022 Buffalo died due to landslide 0
	District	Details
Urban Flood	Cachar	Silchar - Linkroad, National Highway road point, Ambicapatty, Church Road, Chandicharan Road, Bilpar, Public School Road, Subhas Nagar, Sonai Road, N.S. Avenue, Premtala, Chengkuri Rood, Malugram, Kanakpur, Tarapur, Itkhola, Ghoniala, Meherpur, Public School Road, Due to incessant rainfall, the closure of sluice gates and over-topping of Embankments in many areas in and around Silchar Town dated 23.06.2022 21052

Karimganj	RK Nagar - Ward No. 1,2,3,4,6,7 Total 306 Nos families affected from date 18.06.2022 to 23.06.2022 1560
Morigaon	Morigaon - RAJAGAON (NABHETI, WARD NO 9) On dtd. 21-06-2022, as per Lot Mondol overflow of
	floodwater has reached Nabheti Ward no 9 of Morigaon Revenue Town. 1320