

FRIMS Assam



Flood Reporting And Information Management System

Assam Daily Flood Report as on 12-08-2022 at 4:00 PM									
Particulars	Situation as on	12-08-20	22 (in last 24	hours)					
Rivers flowing	Rivers flowing above danger level			Nil					
above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above highest flood level			Nil					
District Affected	No. of Districts Affected	Districts Name of Flood Affec Affected				Name of Urban Flood Districts			
	1 Tamulpur								
No. Of Revenue Circles Affected	1								
Name Of Revenue Circles Affected	District								
	Tamulpur	1 Goreswar							
	Total	1	_						
Villages Affected	District	Total Revenue Circle							
	Tamulpur		1 (Goreswar 1)						
	Total	1			Total	Population	Crop Area	Crop Area	
Population And	District	Male	Female	Children	Population Population	Details	(in Hect.)	Details	
Crop Area Affected	Tamulpur	204	160	61	425	(Goreswar 425)	0.00	(Goreswar 0.00)	
	Total	204	160	61	425	,,	0.00	,	
Relief Camps /	NT'I								
Centres Opened	Nil								
Inmates In Relief Camps	Nil								
Human Lives Lost - Confirmed	Nil								
Human Lives Lost Confirmed -	Nil								
Death Type	INII								
Human Lives Lost - Missing	Nil								
Human Lives Lost Missing - Type	Nil								
Animals Affected	Nil								
Animals Washed Away	Nil								
Houses Damaged	Nil								
Rescue Operation	Nil								
Relief Distributed	Nil								
Relief Distributed Others	Nil								
Infrastructure Damaged - Embankment Breached	Nil								
Infrastructure Damaged - Embankments Affected	Nil								
Infrastructure Damaged - Road	Nil								
Infrastructure Damaged - Bridge	Nil								
Infrastructure Damaged -	Nil								
Wildlife	Di citi	0.1							
Infrastructure	District	Other D	etails						

Damaged - Others	Udalguri	Harisinga - Power Dept. Poles L.T/H.T poles damaged at Village sastrapara, majgaon, hahini, tiklowchuba, liching, fulkuchi, khatowalpara, kawlibhanga, Atterikhat, Bhootiachang, Dulipasra, Tarabari, nonaikhuti, ghagra,murmela, Bamunjuli, Tenkibasti, Bholatar, Majuli T.E, Corramore T.E, Badlapara T.E, majuli basti, no. 2 Sonajuli, Corramore, Orangajuli on 08/08/2022, Power Dept. Conductors Conductors were snapped at village Jalah, Chenipara, Simaluguri, Chamuapara (Pukhuripar), Merbangchuba, Jangalpara, Niz Jhaparabari, Geruwa, Sastrapara, Mazgaon, hahini, Ticklowchuba, Lising, Fulkuchi, Khatowalpara, kaulibhanga, Attarikhat, Galachuba, Bhootiachang, Duliapara, Tarabari, Nonaikhuti, Ghagra, Murmela, Bamunjuli, Tenkibasti, Majuli T.E, Corramoe T.E, Badlapara T.E, Kathalguri, Majuli Basti, Corramore, Tangla Town, Pub Jangalpara, Chamuapara, Banseria, Pub Nalbari, Chenipara, Paneri T.E, Sikari Bangla, Nepali Khuti, Dimakuchi, No. 2 Ghagrapara Gaon, Tenkibasti, bamunjuli, Ratanpur, Khokhabasti, Nonaikhuti, Batakuchi, Bangaon, Alikash, Pachim Phutukibari, No. 2 Diamkuchi, No 4 Dimakuchi, Bhootiachang, Orangajuli T.E, Sagalijhar, Garuajhar, Kachubil, Amlaiguri, Bangurum, Santipur, Teliapara, Ghagrapara, Bamunjuli, NC Bhootiachang, No. 1, 2, 3 Diamkuchii on 08-08-2022
Erosion	District	Details
	Bongaigaon	Manikpur - Bashbari Part 2 Erosion of around 1300 mtr. had occurred w.ef 17/06/2022 to 30/06/2022.Two (2) Nos of Relief camp opened due to the said erosion (1) Tilpukhuri ME Madrasa "Male=179 Female=165 Child=124 Pregnant=1 Disability=1 Total=470(Latitude-26.39971 Longitude-90.753438) (2)3 no. Bashbari LP School, Male=86 Female=83 Child=77 Pregnant=2 Total=248(Latitude-26.426476 Longitude-90.759589) since 17.06.2022 to till date 01.07.2022/Bashbari no 2 Temp.Shelter, Male=55, Femele=45, Child=25,(Toatl=125,Latitude-26.4709483 Longitude-90.748884)Total Inmates 843. Medical Team- 2 Nos. date- 12.08.2022, Total Population-843. erosion continues to Bashbari par 2. on 12.08.2022 0
	Dhubri	South Salmara Part - Sundarpara pt As per information received from BEEO South Salmara 1/ Sundarpara ME Madrassa has been eroded due to erosion by river Brahmaputra at village Sundarpara on 3/8/22. Area 2B-2K-0L Lat-26.04 Long - 90.04 2/ Naimi Sundarbala LP School has been eroded due to erosion by river Brahmaputra on 5/8/22.area 2B-0K-0L. 0
	South Salmara	Mankachar - 1. Mankachar Pt-II 2. Fulerchar Pt-III As per report received from In-Charge control Room, Hatsingimari W.R Sub-Division, Hatsingimari, an Erosion causing damaged of land measuring of Mankachar Tinali length - 350 M & Breadth-5.00 M and Bangrichar, Newjespur and Barmanpara length-2500 M and Breadth-15 M. Occurred at Rev. village of Mankachar Pt-II and Fulerchar Pt-III on 12/08/2022. 0, South Salmara - Khopati Pt-II, Khopati Pt-III, Brahmaputra Berabhanga 1/ As per information received from EE PWD erosion occurred at village Khopati Pt-ii and Pt-III by the river Jinjiram on 11/8/22 area Approx. length - 1 km breath - 25 m Lat - 25.28 Long - 89.59 2/ as per information received from concerned Gaon Pradhan 3 nos family has been eroded due to erosion by river Brahmaputra at village Brahmaputra Berabhanga under South Salmara rev Circle on 11/8/22 area Approx. 5 B-2 K-10 L Lat 25.81 Long - 89.91 14 Udalguri - 1. Phulbari 2. Bhairabkunda 1. Erosion Occured on the R/B of Khawrang river at Phulbari
	Udalguri	village around 340m on 11.08.2022. GPS - Lat - 26.850884 Long - 92.086578 2. Erosion Occured on the R/B of Daifang river at Bhairabkunda (near Bus Stand & SSB Camp) village around 150m on 11.08.2022. GPS - Lat - 26.887095 Long - 92.114411 0
Landslide	Nil	
Urban Flood	Nil	