

FRIMS Assam



Flood Reporting And Information Management System

			Assan	n Daily Flood Report as on 30-06-2022 at 4:00 PM	1
Particulars	Situation as	on 30-06-2	2022 (in las	t 24 hours)	
Rivers					
flowing	Rivers flowi	ing above of	danger	Beki (Road Bridge), Kopili (Dharamtul), Burhid	lihing (Chenimari(Khowang)), Brahmaputra
above Danger	level			(Dhubri; Tezpur; Neamatighat)	
Level (as					
per CWC					
bulletin	Rivers flowi	ing above l	highest	Nil	
issued at 8	flood level				
AM)					
	No. of	NT	P T21 J A 66		Name of Halan Elect District
	Districts Affected	Name of	1 F1000 A11	ected Districts	Name of Urban Flood Districts
District	Affected	Baiali. B	Sarpeta, Bisy	vanath, Cachar, Chirang, Darrang, Dhemaji,	
Affected	25			asao, Goalpara, Golaghat, Hailakandi, Hojai,	
	25			1), Karimganj, Lakhimpur, Majuli, Morigaon,	Cachar, Dibrugarh, Tinsukia
		Nagaon,	Nalbari, Sc	nitpur, Tamulpur, Tinsukia, Udalguri	
No. Of					
Revenue Circles	75				
Affected					
Timeeted	District	Total	Revenue	Circle	
	Bajali	2	Sarupeta		
	Barpeta	5		ri, Barpeta, Baghbar, Chenga, Kalgachia	
	Biswanath	3	Biswanat	h, Gohpur, Halem	
	Cachar	5		nd, Silchar, Katigorah, Sonai, Lakhipur	
	Chirang	2	Bengtal,		
	Darrang	3		at, Mangaldoi, Sipajhar	
	Dhemaji	4		aon, Gogamukh, Dhemaji, Jonai	
	Dibrugarh Dima-	6	Chabua,	Moran, Tingkhong, Tengakhat, Dibrugarh East, N	aharkatia
	Hasao	1	Haflong		
	Goalpara	2	Lakhipur	, Balijana	
	Golaghat	2	Bokakha	, Khumtai	
Name Of	Hailakand ;	2	Algapur,	Hailakandi	
Revenue	Hojai	2	Hojai, La	nka	
Circles	Kamrup	5		forth Ghy, Nagarbera, Chamaria, Hajo	
Affected	Kamrup	1	Sonapur		
	(M)		•		
	Karimganj	4	Nilambaz	zar, Karimganj, RK Nagar, Badarpur	
	Lakhimpu r	7	Dhakuak	hana, Bihpuria, Subansiri, North Lakhimpur, Kada	am, Nowboicha, Narayanpur
	Majuli	2		^T jani Majuli	
	Morigaon	4		ta, Bhuragaon, Morigaon, Mayong	
	Nagaon	5		Kaliabor, Samaguri, Raha, Kampur	
	Nalbari	2		Nalbari, Barbhag	
	Sonitpur	1	Dhekiaju		
	Tamulpur Tinsukia	3	Goreswa	r Doomdooma, Tinsukia	
	Udalguri	1	Udalguri		
	Total	75	Cumguii		
	District	Total	Revenue	Circle	
	Bajali	18		a 16), (Bajali 2)	
Villages	Barpeta	461		ari 118), (Barpeta 145), (Baghbar 78), (Cho	enga 37), (Kalgachia 83)
Affected	Biswanath	108		ath 1), (Gohpur 31), (Halem 76)	
71110000	Cachar	610		ond 42), (Silchar 196), (Katigorah 153), (S	onai 161), (Lakhipur 58)
	Chirang	5		1), (Bijni 4)	
	Darrang	35	(Patharig	ghat 6), (Mangaldoi 13), (Sipajhar 16)	

	Dhemaji	166	(Sissibo	rggon 45) .	(Cogamukh	32), (Dhemaji 8), (Jonai	I Q1)	
						khong 4), (Tengakhat 4),		East 7). (Naharkatia 7
	Dibrugarh	36)	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	- /, (8-		(=8	
	Dima-	3	(Haflons	7 (3)				
	Hasao							
	Goalpara	5		ur 2), (Bali				
	Golaghat	31	(Bokakh	nat 27), (Kl	numtai 4)			
	Hailakand i	3	(Hailaka	ındi 3)				
	Hojai	7		5), (Lanka				
	Kamrup	70	(Kayan	9), (North	Ghy 8), (Na	agarbera 11), (Chamaria 2	23), (Hajo 1	9)
	Kamrup (M)	25			andrapur 7)			
	Karimganj	177				2), (RK Nagar 43), (Bada		
	Lakhimpu r	146	Nowboic	ha 4), (Na	rayanpur 58	(i), (Subansiri 19), (North i	Lakhimpur 8	3), (Kadam 7), (
	Majuli	20		16), (Ujani				
	Morigaon	300				6), (Morigaon 143), (May		
	Nagaon	327				amaguri 6), (Raha 121),	(Kampur 10	7)
	Nalbari Sonitpur	6	(Paschin), (Barbhag	1)		
	Tamulpur	2	(Goresw					
	Tinsukia	44			dooma 26).	(Tinsukia 17)		
	Udalguri	1	(Udalgu	. ,, ,		(
	Total	2608						
	54.4.			CT 41.1	Total		Crop	
	District	Male	Female	Children	Populatio	Population Details	Area (in Hect.)	Crop Area Details
	5 1 11	1505	1.1.10	2.505	n	(Sarupeta 33130), ((Sarupeta 671.00), (
	Bajali	17287	14648	2587	34522	Bajali 1392)	671.00	Bajali 0.00)
						(Sarthebari 200640), ((Sarthebari 614.00),
						Barpeta 32194), ((Barpeta 650.00), (
	Barpeta	167055	141666	91781	400502	Baghbar 98974), (16418.00	Baghbar 10183.00), (
						Chenga 49472), (Kalgachia 19222)		Chenga 3348.00), (Kalgachia 1623.00)
						(Gohpur 11134), ((Gohpur 712.00), (
	Biswanath	20134	19337	13057	52528	Halem 41310), (2030.00	Halem 1310.00), (
						Biswanath 84)		Biswanath 8.00)
						(Udharbond 57723), ((Udharbond 1049.26
	Cachar	558060	503664	369928	1431652	Silchar 725306), (Katigorah 230435), (9870.26), (Silchar 1922.00), (Katigorah 1959.00
	Cacilai	338000	303004	309928	1431032	Sonai 284513), (9670.20), (Sonai 2915.00), (
						Lakhipur 133675)		Lakhipur 2025.00)
	Chirang	302	346	215	863	(Bengtal 237), (Bijni	0.00	(Bengtal 0.00), (
Population	Cilitatig	302	340	213	803	626)	0.00	Bijni 0.00)
And Crop Area						(Dalgaon 0), ((Dalgaon 0.00), (Patharighat 1500.00
Affected	Darrang	23398	21447	9205	54050	Patharighat 4100), (6510.00), (Mangaldoi
						Mangaldoi 22577), (3418.00), (Sipajhar
						Sipajhar 27373)		1592.00)
						(Sissiborgaon 19178),		(Sissiborgaon
	Dhemaji	39170	33544	25019	97733	(Gogamukh 16713), (8053.80	1512.00), (Gogamukh 71.00), (
	Dhemaji	39170	33344	23019	91133	Jonai 58808), (8033.80	Jonai 6440.80), (
						Dhemaji 3034)		Dhemaji 30.00)
						(Chabua 8037), ((Chabua 7.60), (
						Tingkhong 270), (Tingkhong 4.20), (
	D:h 1	6555	5210	2260	15241	Moran 2047), (77 02	Moran 30.00), (
	Dibrugarh	6555	5318	3368	15241	Tengakhat 1919), (77.83	Tengakhat 22.00), (Dibrugarh East 0.00
						Dibrugarh East 2493), (), (Naharkatia 14.03
				<u>L</u>		Naharkatia 475)	<u> </u>)
	Goalpara	3107	2573	1616	7296	(Lakhipur 2413), (39.00	(Lakhipur 0.00), (
	Compara	2107	23,3	1010	, 0	Balijana 4883)	27.00	Balijana 39.00)
	Golaghat	0	0	0	0	(Bokakhat 0), (Khumtai 0)	75.70	(Bokakhat 62.70), (Khumtai 13.00)
	Hailakand	32	21	25	78	(Algapur 0), (Lala 0	0.00	(Algapur 0.00), (
					10	(Ingapar O), (Laia O	0.00	(1 115 up ut 0.00 /, (

i								Lala 0.00), (Katlicherra 0.00), (Hailakandi 0.00)
Hojai	601	331	190	1122	(Hojai 859) 263)), (Lanka	186.00	(Hojai 28.00), (Lanka 158.00)
Kamrup	20688	17071	4807	42566	Chamaria 0) 23196), (Kay), (Hajo yan 48), (649.20	(Nagarbera 183.00), (Chamaria 52.20), (Hajo 356.00), (Kayan 37.00), (North Ghy 21.00)
Kamrup (M)	560	489	0	1049			726.50	(Chandrapur 0.00), (Sonapur 726.50)
Karimganj	39113	23098	12232	74443	(Nilambazar RK Nagar 20 Badarpur 20	15933), (0458), (0150), (0.00	(Nilambazar 0.00), (RK Nagar 0.00), (Badarpur 0.00), (Karimganj 0.00)
Lakhimpu r	39018	34153	20925	94096	North Lakhim), (Nowboich Narayanpur Dhakuakhana Bihpuria 198 Kadam 0)	npur 10070 na 9231), (34522), (1 773), (828), (1948.10	(Subansiri 884.90), (North Lakhimpur 0.00), (Nowboicha 2.30), (Narayanpur 704.00), (Dhakuakhana 239.00), (Bihpuria 76.15), (Kadam 41.75)
Majuli	0	0	0	0		(Ujani	108.30	(Majuli 90.61), (Ujani Majuli 17.69)
Morigaon	49961	46097	27311	123369	(Mikirbheta Bhuragaon 0 Morigaon 10	03868),(9376.50	(Mikirbheta 826.50), (Bhuragaon 782.00), (Morigaon 3400.00), (Mayong 4368.00)
Nagaon	184921	173435	161107	519463	Kaliabor 89 Samaguri 0)), (), (Raha	18666.70	(Nagaon 404.00), (Kaliabor 9.00), (Samaguri 4.00), (Raha 9999.70), (Kampur 8250.00)
Nalbari	1044	957	379	2380	`	•	139.00	(Paschim Nalbari 0.00), (Barbhag 139.00)
Sonitpur	95	100	70	265	(Dhekiajuli	265)	221.00	(Dhekiajuli 221.00)
Tamulpur	956	890	354	2200	(Goreswar 2	2200)	0.00	(Goreswar 0.00)
Tinsukia	10097	8714	5993	24804	Doomdooma Tinsukia 352	14676), (23)	348.66	(Sadiya 16.00), (Doomdooma 269.16), (Tinsukia 63.50)
Udalguri	145	86	40	271	Harisinga 0), (0.00	(Udalguri 0.00), (Harisinga 0.00), (Kalaigaon 0.00)
Total	9	5	750209	2980493			76115.55	
District	Total							res
					1ga 15)			
Biswanath	21		•					
Cachar	354			igorah 94, S	onai 54,	79(Silchar 0)	0, Katıgorah	0, Sonai 79, Lakhipur
CI.	_	6(Rangte	112 Bijni 14	4)				
Chirang								
Darrang	17	3(Mangal	ldoi 2, Sipaj	ijhar 1)			loi 14, Sipajh	
		3(Mangal	ldoi 2, Sipaj aji 2, Sissibo		gamukh 0,			nar 0) aon 5, Gogamukh 7,
Darrang	17	3(Mangal 2(Dhemaj Jonai 0)	ldoi 2, Sipaj aji 2, Sissibo	njhar 1) orgaon 0, Gog	gamukh 0,	27(Dhemaji Jonai 12)		aon 5, Gogamukh 7,
Darrang Dhemaji Dibrugarh Dima-	17 29	3(Mangal 2(Dhemaj Jonai 0)	ldoi 2, Sipaj nji 2, Sissibo o a 0, Tengakh	njhar 1) orgaon 0, Gog	egamukh 0,	27(Dhemaji Jonai 12)	i 3, Sissiborga	aon 5, Gogamukh 7,
Darrang Dhemaji Dibrugarh Dima- Hasao Hailakand	17 29 3	3(Mangal 2(Dhemaj Jonai 0) 0(Chabua	ldoi 2, Sipaj nji 2, Sissibo na 0, Tengakh ng 23)	njhar 1) orgaon 0, Gog	gamukh 0,	27(Dhemaji Jonai 12) 3(Chabua	i 3, Sissiborga 1, Tengakhat 4)	aon 5, Gogamukh 7,
Darrang Dhemaji Dibrugarh Dima- Hasao Hailakand i	17 29 3 27	3(Mangal 2(Dhemaj Jonai 0) 0(Chabua 23(Haflor 1(Hailaka	ldoi 2, Sipaj nji 2, Sissibo a 0, Tengakh ng 23) andi 1)	njhar 1) orgaon 0, Gog	gamukh 0,	27(Dhemaji Jonai 12) 3(Chabua 4(Haflong 0(Hailakand	3, Sissiborga 1, Tengakhat 4) di 0)	aon 5, Gogamukh 7,
Darrang Dhemaji Dibrugarh Dima- Hasao Hailakand	17 29 3 27	3(Mangal 2(Dhemaj Jonai 0) 0(Chabua 23(Haflor 1(Hailaka 4(Hojai	ldoi 2, Sipaj nji 2, Sissibo a 0, Tengakl ng 23) andi 1)	njhar 1) orgaon 0, Gog		27(Dhemaji Jonai 12) 3(Chabua 4(Haflong 0(Hailakand 3(Hojai 3)	3, Sissiborga 1, Tengakhat 4) di 0)	aon 5, Gogamukh 7,
	Hojai Kamrup Kamrup (M) Karimganj Lakhimpu r Majuli Morigaon Nagaon Nalbari Sonitpur Tamulpur Tinsukia Udalguri Total District Bajali Barpeta Biswanath Cachar	Hojai 601 Kamrup 20688 Kamrup 560 Karimganj 39113 Lakhimpu 39018 Majuli 0 Morigaon 49961 Nagaon 184921 Nalbari 1044 Sonitpur 956 Tinsukia 10097 Udalguri 145 Total 118229 9 District Total Bajali 7 Barpeta 67 Biswanath 21 Cachar 354	Hojai 601 331	Hojai 601 331 190	Hojai 601 331 190 1122	Hailakandi 7	Hojai Gol	Hailakandi 78 Hailakandi

	Lakhimpu	29	3(Subans	siri 1, Naray	anpur 2, Dh	akuakhana 0,	26(Subans	iri 6, Narayan	pur 10, Dhak	tuakhana
	r		•	0, Nowboid	cha 0)			a 2, Nowboicl	na 6)	
	Majuli	10	0(Majuli				10(Majuli			
	Morigaon	27		aon 1, Mikir				on 11, Mikirt		
	Nagaon	176		•	ı 13, Kampur	•		on 14, Raha 0		")
	Nalbari	2			, Barbhag 1)			Nalbari 0, Ba	arbhag 0)	
	Sonitpur	1	0(Dhekia	•			1(Dhekiaju			
	Tamulpur	4	2(Goresv				2(Goreswa	• •		
	Tinsukia	26			nsukia 2, Sa	diya 0)		ooma 2, Tins	ukia 17, Sadi	ya 2)
	Udalguri	2	2(Udalgı	ıri 2)			0(Udalguri	(10)		
	Total	906	551				355			
	District	Total		e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y
	Bajali	1005		a 1005), (Ba	-	435	375	140	55	0
	Barpeta	7534	(Chenga (Sartheba		achia 0),	2051	2769	2676	34	4
	Biswanath	44	(Biswana (Halem	ath 0), (Goh 44)	pur 0),	14	21	9	0	0
	Cachar	257838	168398), (Sonai 4 2878)	ond 0), (Silc (Katigorah 42324), (Lak	44238), hipur	98307	95937	63394	200	0
	Chirang	863	(Bengtal	237), (Bijn	i 626)	302	342	215	4	0
	Darrang	787	(Mangalo 522)	n 0), (Pathar doi 265), (S	ipajhar	212	390	170	10	5
	Dhemaji	279		gaon 0), (G i 0), (Dhem	•	62	111	84	21	1
	Dima- Hasao	1432	(Haflong	1432)		502	557	319	53	1
Inmates In	Hailakand i	78		· 0), (Lala 0 erra 0), (Hai		32	21	25	0	0
Relief	Hojai	382		882), (Lanka		201	131	47	3	0
Camps	Kamrup	1785	(Hajo 1 (North G	era 0), (Chai 210), (Kayan shy 535)	1 40),	874	741	170	0	0
	Karimganj	11077	1013), (F Nagar 1		089), (RK	4632	3848	2582	12	3
	Lakhimpu r	501	(North L 0), (Now	khana 0), (E akhimpur 0 boicha 0), (ayanpur 40), (Kadam Subansiri	152	239	100	10	0
	Morigaon	175	(Morigae	eta 0), (Bhu on 175), (Ma	ayong 0)	67	73	33	2	0
	Nagaon	20987		r 0), (Samag 14416), (Ra r 4980)		8381	7027	5436	132	11
	Nalbari	64	(Paschim	n Nalbari 45), (Barbhag	29	25	9	1	0
	Tamulpur	102	(Goreswa			40	41	21	0	0
	Tinsukia	361	(Tinsukia			108	124	117	12	0
	Udalguri	271	(Harising (Udalgur	ga 0), (Kalai i 271)	igaon 0),	120	110	40	0	1
	Total	305565				116521	112882	75587	549	26
	District	Total	Male	Female	Children	Revenue Cir				
**	Barpeta	1	0	0	1	(Baghbar 0) (Sarthebari), (Chenga 0)	, (Kalgachia	0),
Human	Biswanath	1	1	0	0			0), (Halem 1)	
Lives Lost - Confirmed	Dhemaji	1	1	0	0	(Dhemaji 0)	, (Gogamukh	(Jonai 1), (Sissiborgae	
Commined	Lakhimpu r	2	1	0	1			ana 0), (Kada owboicha 0),		
	Morigaon	1	1	0	0			0), (Mikirbh		
	1 8	ı	l	1 -	<u> </u>		,, \j 	1 - / , (. , . /, (2.2021)	ν·· ι*/

	Nagaon	2	1	0	1		, (Kampur 0), (Nagaon 0)), (Raha 2), (S	Samaguri
				_		0)				
	Total District	8 Total	Flood Death	General Drownin g (Non Flood)	3 Landslide					
Human	Barpeta	1	1	0	0					
Lives Lost	Biswanath	1	1	0	0					
Confirmed -	Dhemaji	1	1	0	0					
Death Type	Lakhimpu r	2	2	0	0					
	Morigaon	1	1	0	0					
	Nagaon	2	2	0	0					
	Total	8 Total	8 Mala	0 Famala	0 Children	Dataila				
Human	District	Total	Male	Female	Children	Details (Katigorah C)) (Lakhinur l	(Silchar)	1), (Sonai 0),	
Lives Lost - Missing	Cachar	1	0	1	0	(Udharbond		O), (Shehar	1), (3011a1 0),	
Llumon	Total	Total	0 Elast	Non Floor	0					
Human Lives Lost	District Cachar	Total	Flood 1	Non Flood 0						
Missing - Type	Total	1	1	0						
Турс	District	Total	Big	Small	Poultry					
	Bajali	7840	4340	1110	2390					
	Barpeta	514935	189610	98059	227266					
	Biswanath	11487	8344	3143	0					
	Darrang	158739	79695	44528	34516					
	Dhemaji	28314	19458	8856	0					
	Dibrugarh	15285	7595	4713	2977					
	Kamrup	5670	4100	1570	0					
Animals Affected	Kamrup (M)	1369	861	323	185					
	Lakhimpu r	50758	25065	13569	12124					
	Majuli	20125	15988	4137	0					
	Morigaon	99837	37898	19060	42879					
	Nagaon	124464	57317	38102	29045					
	Sonitpur Total	470 103929	320 450591	150 237320	0 351382					
		3								
	District	Total	Big	Small	Poultry					
A : = 1 =	Barpeta	22	6	16	0					
Animals Washed	Darrang Dhemaji	1 12	0	12	0					
Away	Nagaon	5	2	3	0					
	Nalbari	11	4	7	0					
	Total	51	13	38	0					
	District	Fully Kucch	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
	Bajali	a 144	49	193	384	44	428	63	81	144
	Biswanath	144	1	15	0	0	0	0.5	0	0
	Bongaigao n	282	40	322	17	0	17	0	0	0
Houses	Kamrup	2	0	2	0	0	0	0	0	0
Damaged	Lakhimpu	0	0	0	2	0	2	0	0	0
	Sonitpur	0	0	0	0	0	0	6	0	6
	South Salmara	0	0	0	23	0	23	27	5	32
	Udalguri	25	0	25	132	0	132	0	0	0
	Total	467	90	557	558	44	602	96	86	182
Rescue Operation	District	Agency			Boats Deployed	Person Evacuated	Animal Evacuate	Helicopte rs	Person Evacuate	Medical Team Deploye
	District	Agency				Evacuated By Boats	d By	rs Deployed	d By	

							Boats		Helicopte	d
	Bajali				0	0	0	0	rs 0	32
	Barpeta		fice/Local		5	0	0	0	0	0
	Biswanath	Administ	ration		0	0	0	0	0	1
	Bongaigao				0	0	0	0	0	2
	Cachar	Administ Army/Par Defence/ Fire & Er	ramilitary f Trained Vo mergency S Local Peop		18	180	0	0	0	61
	Chirang	Tollee, B			0	0	0	0	0	5
	Darrang				0	0	0	0	0	24
	Dhemaji	SDRF			2	153	0	0	0	2
	Dibrugarh				0	0	0	0	0	6
	Dima- Hasao	Voluntee Police, W	ence/Train rs, Local Po ater Resou ent, PWRD	eople, irces	0	0	0	0	0	15
	Goalpara				0	0	0	0	0	3
	Kamrup				0	0	0	0	0	2
	Karimganj				8	0	0	0	0	11
	Lakhimpu r	SDRF			1	2	0	0	0	2
	Majuli				0	0	0	0	0	3
	Morigaon				0	0	0	0	0	19
	Nagaon		fice/Local ration, Loc	al People,	1	0	0	0	0	26
	Sonitpur				0	0	0	0	0	4
	Total District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)		- Rice Bran	(in Q)
	Biswanath	455.49	84.79	0.12	11.52	0.00	537.08	0.00		
	Cachar	1014.4 8	229.51	62.80	8140.19	0.00	0.00	0.00		
	Chirang	3.89	0.71	0.21	21.33	0.00	0.00	0.00		
	Darrang	263.00	57.60	19.00	1540.00	0.00	0.00	270.00		
	Dhemaji	1120.9 2	202.47	60.72	3018.37	0.00	0.00	145.59		
	Dibrugarh	90.78	16.71	5.01	1.54	0.00	0.00	0.00		
Relief	Dima- Hasao	49.77	4.74	1.71	237.00	0.00	0.00	0.00		
Distributed	Hailakand i	46.55	8.76	2.63	262.68	0.00	50.00	0.00		
	Hojai	0.00	0.00	0.00	0.00	0.00	0.00	50.00		
	Kamrup	8.25	62.65	0.50	2577.00	0.00	0.00	0.00		
	Karimganj	192.96	33.65	9.34	21.50	0.00	0.00	0.00		
	Lakhimpu r	403.79	73.11	21.95	2194.23	0.00	0.00	0.00		
	Majuli	0.00	0.00	0.00	0.00	0.00	100.00	0.00		
	Morigaon	129.33	23.45	7.03	703.35	0.00	148.00	440.00		
	Nagaon	3992.3 6	29.48	8.84	884.43	0.00	250.00	200.00		
	Sonitpur	2.90	0.53	0.16	0.16	0.00	0.00	0.00		
	Tamulpur	2.79	0.50	0.15	14.85	0.00	0.00	0.00		
	Tinsukia	160.62	32.35	9.71	716.57	0.00	0.00	0.00		
	Total	7937.8	861.01	209.88	20344.72	0.00	1085.08	1105.59		

		8			
	District	Baby Foo	od	Doby Food Colid	Othora
	District	Liquid		Baby Food Solid	Others
	Biswanath	0.00-Q		10.00-Pkt, 0.00-Q	Drinking water-120.00-L
					Candle-17500.00-Pkt; Mortien-11100.00-Pkt; Biscuit-578875.00-
	Cachar	0.00-Q		0.00-Q	Pkt; Amul Taza-72938.00-Pkt; Cake-1890.00-Pkt; Drinking
	CI :	0.00.0		0.00.0	Water-73218.00-Pkt; Sanitary Pad-40532.00-Pkt
	Chirang	0.00-Q		0.00-Q	1' 27/7' 00 P' 0 0 00 0
	Darrang	0.00-Q		0.00-Q	tarpaulin-2765.00-Pieces; 0-0.00-Q Tarpaulin-908.00-Pieces; Tarpulin-24.00-Pieces; soap-25.00-
					Pieces; Mosquito coil-10.00-Pieces; Candle-20.00-Pieces;
	Dhemaji	0.00-Q		0.00-Q	Detergent-10.00-Pkt; sanitary pad-20.00-Pkt; Match box-10.00-Pkt; Biscuit-20.00-Pkt; Phenyl-5.00-Pkt; Disposal Dishes-1000.00-Pieces; Potato-50.00-Kg; Soyabean-5.00-Kg; Mosquito net-100.00-Pieces
	Dibrugarh	0.00-Q		0.00-Q	Het-100.00-1 leces
	Diorugam	0.00-Q		0.00-Q	Milk-44.00-L; Potato-320.00-Kg; Onion-237.00-Kg; Biscuit-
	Dima- Hasao	0.00-Q		0.00-Q	1659.00-Pkt; Candle-633.00-Pkt; Match Box-237.00-Pkt; Mosquito Repellent-237.00-Q; Bathing Soap-237.00-Pieces
	Hailakand i	0.00-Q		0.00-Q	Water Purification Tablets-4200.00-Pieces; Water Packets-2600.00-Pkt
	Hojai	0.00-Q		0.00-Q	
	Kamrup	0.00-Q		0.00-Q, 100.00-Pkt	0-0.00-Q; Wheat Bran-74.55-Q; Tarpaulin-2000.00-Pieces
Relief Distributed Others	Karimganj	555.00-Pl Q	kt, 0.00-	135.00-Pkt, 0.00-Q	CANDLE-144.00-Pkt; MOSQUITO COIL-48.00-Pkt; BLEACHING POWDER-48.00-Pkt; SANITARY NAPKIN- 97.00-Pkt; MATCH BOX-135.00-Pkt; 0-0.00-Q; Candle-55.00- Pkt; Mosquito Coil-33.00-Pkt; Water Purification Tablet- 4625.00-Pkt; Chemical Packets-12235.00-Pkt; Water Pouch- 3700.00-Pkt; Lime & Alum Pouch-2050.00-Pkt; Hydrochloride Solution-110.00-L
	Lakhimpu r	0.00-Q, 1 Pkt	70.00-	69.00-Pkt, 2.04-Q, 90.00-Kg	Tarpaulin-1159.00-Pieces; Concentrate Feed (Cattle Feed)-19.00-Q; Sanitary Napkins-385.00-Pkt; Chira-2.04-Q; Jaggery(Gur)-51.00-Kg; TARPAULIN-107.00-Pieces; potato-30.00-Kg; Eggs-94.00-Pieces; Soyabean-5.00-Kg; Onion-10.00-Kg; candle-30.00-Pkt; maxo-15.00-Pkt; tea leaves-0.50-Kg; sugar-2.00-Kg; biscuit-30.00-Pkt; disposable glass and plate-600.00-Pieces; bucket with mug-20.00-Pieces; turmeric-1.00-Kg; dry chilli-0.50-Kg; bread-60.00-Pkt; bathing soaf-22.00-Pieces; detergent powder 10 Rs pouch -22.00-Pieces; vim Bar 10 Rs Pouch-5.00-Pieces; Match Box-4.00-Pkt; 0-0.00-Q
	Majuli	0.00-Q		0.00-Q	Helogen Tab-800.00-Pieces
	Morigaon	3155.00-Q, 2995.00-Pkt		3155.00-Q, 2995.00- Pieces	Tarpoulin-230.00-Pieces; Hand Tube Well-2.00-Pieces; Sanitary Napkin-239.00-Pkt; Tarpaulin-5000.00-Q; Temporary Toilet - 24.00-Q; Halogen tablets-13000.00-Q; Water pouch-22000.00-Q; Chemical Packets-2950.00-Q; HTW-20.00-Q; Sanitary Napkin-271.00-Q
	Nagaon	1894.00-l Q	Pkt, 0.00-	0.00-Q	Sanitary Napkin-180.00-Pkt; Tarpulin-1400.00-Pieces
	Sonitpur	0.00-Q		0.00-Q	Chira-2.90-Q; Gur-0.53-Q
	Tamulpur	0.00-Q		0.00-Q	Tarpaulin -320.00-Pieces
	Tinsukia	0.00-Q, 2	74.00-L	0.00-Q, 373.40-Kg	Sanitary Napkin-200.00-Pkt
	District	Numbe r	Details	D 1	
Infrastructu re Damaged	Biswanath	1	embanke approxim	nt is further eroded by fl nately 20 meters (Long	Hatibondhia The rising water of previously breached Brahmajan ood water of Brahmajan river on 29/06/2022 by a length - 93.539310, Lat - 26.825315)
Embankme nt Breached	Udalguri	1	which ha	s damaged in earlier floo	t village Gerua in the R/B of river Noa Gerua The embankment of has breached on 30/06/2022 due to erosion caused by overflowing the Noa covering a length of around 50 meters and breadth of 5 91.593532)
	Total	2			
Infrastructu	District	Numbe	Details		
re Damaged		r		-1 D 1 1 D 20 3	MILE THE LET TO SERVE
- Embankme	Cachar	1	Madhura		Madhura from Udharbond to Larsing approach Dyke along R/B of -450 M Report Received from Water Resource Department Silchar , Lat - 0.000000)
nt Affected	Dhemaji	1			n Nepalibasti to Gurathali Chapori In between Ch.17000.00 m to Ch.
	•			*	

Birgonom Severe boiling and damage of R/S slope on 30:06/22 (Long - 27.371021, Lat - 94.39312) Lakhimpu 1 Kadam - Bodhakara Subansiri Bodhakara village Raincut occurred due to heavy rain, informed by Gaon pradhaan, dated 29:6/2022 (Long - 0.000000, Lat - 0.000000) Majuli - Kolonijan Un-Embankment Kolonijan Bank erosion occurred at 29:06.2022, affected reach = 1.5 km (Long - 94.16650, Lat - 27.044180), Kamboon Borunchuk Bank erosion occurred at 29:06.2022, affected reach = 1.00 km (Long - 94.16720, Lat - 27.023990), Moroilamukh Un-Embankment Kolonijan Bank erosion occurred at 29:06.2022, affected reach = 800 mtr. (Long - 94.123430, Lat - 27.007610), Hostinapur Un-Embankment Hostinapur Bank erosion occurred at 29:06.2022, affected reach = 1.00 km (Long - 94.123470, Lat - 27.033160). Major Chapor Un-Embankment Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.80 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.80 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.80 km (Long - 94.124740, Lat - 27.033160). Major Chapor Bank erosion occurred at 29:06.2022, affected reach = 1.80 km (Long - 94.104140). Major Chapor Bank erosion occurred
Lakhimpu r 1 Kadam - Bodhakara Subansiri Bodhakara Vilage Raincut occurred due to heavy rain, informed by Gaon pradhaan, dated 29/6/2022 (Long - 0.000000). Lat - 0.0000000)
majuli Kolonijan Un-Embankment Kolonijan Bank erosion occurred at 29.06.2022, affected reach = 1.5 km (Long - 94.164650, Lat - 27.044180), Majuli S Majuli Long - 94.164650, Lat - 27.044180, Majuli S Majuli Un-Embankment Moroliamukh (U/S of Khabolo) Bank erosion occurred at 29.06.2022, affected reach = 1.00 km (Long - 94.165720, Lat - 27.023990), Moroliamukh Un-Embankment Moroliamukh (U/S of Khabolo) Bank erosion occurred at 29.06.2022, affected reach = 8.00 mt. (Long - 94.124340, Lat - 27.033160), Major Chapori Un-Embankment Hostinapur Bank erosion occurred at 29.06.2022, affected reach = 1.80 km (Long - 94.124740, Lat - 27.033160), Major Chapori Un-Embankment Hostinapur Bank erosion occurred at 29.06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160), Major Chapori Un-Embankment Major Chapori Bank erosion occurred at 29.06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160), Barbhag - RN 8 of river Pagladia from N.T road to Bijuliphat Sadhnapara As per report submitted by Asst. Executive Engineer on 29.06/2022 (Long - 91.470000, Lat - 26.350000), RB of river Pagladia from N.T road to Bijuliphat Ganagaukhuri As per report submitted by Asst. Executive Engineer on 29.06/2022 (Long - 91.45000, Lat - 26.350000), RB of river Pagladia from N.T road to Bijuliphat Ganagaukhuri As per report submitted by Asst. Executive Engineer on 29.06/2022 (Long - 91.45000, Lat - 26.350000), Road completely submerged. Road surface and formation damaged Sarthebari Reported by JE PWD ROAD on 28.06/2022 (Long - 91.21930), Lat - 26.350053), Baniakuchi to Amrikhowa Hariphata road via Hilayapara Road completely submerged. Road surface and formation damaged. Banyakuchi Reported by JE PWD ROAD on 28.06/2022 (Long - 91.21930), Lat - 26.350054), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. Banyakuchi Reported by JE PWD ROAD on 28.06/2022 (Long - 0.000000), Lat - 0.000000), Ba
Majuli - Kolonijan Un-Embankment Kolonijan II Bank erosion occurred at 29.06.2022, affected reach = 1.5 km (Long - 94.16460, Lat - 27.044180), Kambong Borunchuk Bank erosion occurred at 29.06.2022, affected reach = 1.00 km (Long - 94.165720, Lat - 27.023990), Morolamukh Un-Embankment Morialmawhk (Ur-Sor Khabolu) Bank erosion occurred at 29.06.2022, affected reach = 800 mtr. (Long - 94.123430, Lat - 27.007610), Hostinapur Un-Embankment Hostinapur Bank erosion occurred at 29.06.2022, affected reach = 1.80 km (Long - 94.124740, Lat - 27.033160). Major Chapori Un-Embankment Hostinapur Bank erosion occurred at 29.06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160). Major Chapori Un-Embankment Major Chapori Bank erosion occurred at 29.06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160). Barbhag - R/R of river Pagladia from N.T road to Bijulighat Sadhnapara As per report submitted by Asst. Executive Engineer on 29.062022 (Long - 91.470000, Lat - 26.350000). R/R of river Pagladia from N.T road to Bijulighat Gangapukhuri As per report submitted by Asst. Executive Engineer on 29.062022 (Long - 91.450000, Lat - 26.370000). Total
Majuli
Majuli
Majuli 5
Post
Policy P
km (1.0ng - 94.124740, Lat - 27.033160) Major Chapori Un-Embankment Major Chapori Bank erosion occurred at 29.06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160) Barbhag - R/B of river Pagladia from N.T road to Bijulighat Sadhnapara As per report submitted by Asst. Executive Engineer on 29/06/2022 (Long - 91.470000, Lat - 26.350000), R/B of river Pagladia from N.T road to Bijulighat Gangapukhuri As per report submitted by Asst. Executive Engineer on 29/06/2022 (Long - 91.450000, Lat - 26.370000) Total 10 District P Sarthebari - Nagson Sarthebari Road to Bagudi Hahchara Road (Starting at ch. 782 No LP School) Road completely submerged. Road surface and formation damaged Sarthebari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.168958, Lat - 26.336053), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Bagkaran Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation almaged Bipar to Kadamtol) Road completely submerged. Road surface and formation damaged Byaskuchi Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.30163), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir to
Major Chapori Un-Embankment Major Chapori Bank erosion occurred at 29.06.2022, affected reach = 1.00 km (Long - 94.124740, Lat - 27.033160) Nalbari 2 Barbhag - R/B of river Pagladia from N.T road to Bijulighat Sadhnapara As per report submitted by Asst. Executive Engineer on 29/06/2022 (Long - 91.470000, Lat - 26.350000), R/B of river Pagladia from N.T road to Bijulighat Gangapukhuri As per report submitted by Asst. Executive Engineer on 29/06/2022 (Long - 91.450000, Lat - 26.370000) Total 10 Numbe Pagladia
Barbhag - R/B of river Pagladia from N.T road to Bijulighat Sadhnapara As per report submitted by Asst. Executive Engineer on 29/06/2022 (Long - 91.470000, Lat - 26.350000), R/B of river Pagladia from N.T road to Bijulighat Gangapukhuri As per report submitted by Asst. Executive Engineer on 29/06/2022 (Long - 91.450000, Lat - 26.370000) Total 10
Nalbari 2 Barbhag - R/B of river Pagladia from N.T road to Bijulighat Sadhnapara As per report submitted by Asst. Executive Engineer on 29/06/2022 (Long - 91.47000), Lat - 26.350000)
R/B of river Pagladia from N.T road to Bijulighat Gangapukhuri As per report submitted by Asst. Executive Engineer on 29/06/2022 (Long - 91.450000, Lat - 26.370000)
Total 10 District Numbe r Sarthebari - Nagaon Sarthebari Road to Bagudi Hahchara Road (Starting at ch. 782 No LP School) Road completely submerged. Road surface and formation damaged Sarthebari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.188958, Lat - 26.336053), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniaha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation Bhogchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 9.1.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation Bepate Reported by JE PWD ROAD on 28/06/2027 (Long - 9.1.1851, Lat - 26.31639), Chenga Belbari Road to Rowly Barmara Road (Wathudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.1955140, Lat -
Total District Numbe r Details Sarthebari - Nagaon Sarthebari Road to Bagudi Hahchara Road (Starting at ch. 782 No LP School) Road completely submerged. Road surface and formation damaged Sarthebari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.168958, Lat - 26.336053). Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Urang - 0.000000), Bilpar Leported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.198561, Lat - 26.31639), Ch
District Numbe Cartebari Nagaon Sarthebari Road to Bagudi Hahchara Road (Starting at ch. 782 No LP School)
Barteta Postatis Proceedings of the Sarthebari - Nagaon Sarthebari Road to Bagudi Halchara Road (Starting at ch. 782 No LP School) Road completely submerged. Road surface and formation damaged Sarthebari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.168958, Lat - 26.336053), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000), Bagchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.18131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.18131, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged
Sarthebari - Nagaon Sarthebari Road to Bagudi Hahchara Road (Starting at ch. 782 No LP School) Road completely submerged. Road surface and formation damaged Sarthebari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.168958, Lat - 26.336053), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Road completely submerged. Road surface and formation damaged Sarthebari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.168958, Lat - 26.336053), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000), Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000), Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation and surface and formation hanged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.198561, Lat - 26.311639), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Rep
ROAD on 28/06/2022 (Long - 91.168958, Lat - 26.336053), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.19131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation Belbari Reported by JE PWD ROAD on 28/06/2021 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
and formation damaged. Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000), Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
91.219300, Lat - 26.350545), Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000), Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Baniakuchi to Amrikhowa Harighata road via Hilaypara Road completely submerged. Road surface and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation. Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
and formation damaged. Baniyakuchi Reported by JE PWD ROAD on 28/06/2022 (Long - 91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
91.219300, Lat - 26.350545), Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Baiha Tiniali to Agdia Bazar road Road completely submerged. Road surface and formation damaged. baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
baiha Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bagchara Bazar to Era Bamundi Road Road completely submerged. Road surface and formation Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation. Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Bhogchara Bazar Reported by JE PWD ROAD on 28/06/2022 (Long - 0.000000, Lat - 0.000000), Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Bilpar to Kadamtola Namasudrapara via Bhoukamari (Uttar Suba to Kadamtol) Road completely submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
submerged. Road surface and formation damaged Bilpar Reported by JE PWD ROAD on 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Barpeta 16 28/06/2022 (Long - 91.107275, Lat - 26.400109), Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Haladhibari to Kapla Bill (Baniakuchi to Haladhibari) Road completely submerged. Haladhibari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Reported by JE PWD ROAD on 28/06/2022 (Long - 91.218131, Lat - 26.350320), Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Barpeta Barpeta Byaskuchi Shiva Mandir to Rowly Barmara Road (Byaskuchi Shiva Mandir Chowk to Barmara Madrassa Chowk) Road completely submerged. Road surface and formation damaged Byaskuchi Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Reported by JE PWD ROAD on 28/06/2027 (Long - 91.198561, Lat - 26.311639), Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Infrastructu re Damaged - Road Barpeta Chenga Belbari Road to Rowly Barmara Road via Khudra Faladi (Byaskuchi to Bhogdia) Road completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
completely submerged. Road surface and formation . Belbari Reported by JE PWD ROAD on 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
- Road 28/06/2022 (Long - 91.192971, Lat - 26.306317), Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
Singra Bogchara Road (Singra to Tihu River Bank) Road completely submerged. Road surface and formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
formation Singra Reported by JE PWD ROAD on 28/06/2022 (Long - 91.165140, Lat -
1 26 335960)
Garettary Baisa Road (Garettari Chowk to Baisa) Road completely submerged. Road surface and
formation Garettary Reported by JE PWD ROAD on 28/06/2022 (Long - 91.157633, Lat - 26.333372),
Sarthebari Nasatra Bamundi Road (Sarthebari Puran Chowk to Bamundi) Road completely submerged.
Road surface and formation damaged. Sarthebari Reported by JE PWD ROAD on 28/06/2022
(Long - 91.206830, Lat - 26.371780),
Besimari Rangianadir Gaon road (Gahia to Rangianadir Pam) Road completely submerged. Road
surface and formation damaged. Besimari Reported by JE PWD ROAD on 28/06/2022 (Long - 01.143868 Let. 26.330722)
91.143868, Lat - 26.330722), Bharegaon to Amdah Road PMGSY Completed Road(Package No.AS-01-315) Road completely
submerged. Road surface and formation damaged. Bharegaon Reported by JE PWD ROAD on
28/06/2022 (Long - 91.124791, Lat - 26.457998),
Barpeta - Itarbhitha Dangarkuchi road Dangarkuchi Road submerged, Side berm damage 1000.00 m
PWRD Barpeta DOO 19.06.2022 (Long - 90.996558, Lat - 26.345296),
Keotkuchi Napara village road Keotkuchi Side berm damage 10.00 m PWRD Barpeta DOO
19.06.2022 (Long - 91.048118, Lat - 26.305691)
Gohpur - Overtopped by high flood water NH 15 to Chatiachuk Road NH 15 to Chatiachuk Roadon
Gohpur - Overtopped by high flood water NH 15 to Chatiachuk Road NH 15 to Chatiachuk Roadon 29-06-2022 ,1st KM from NH15 ; (Long - 0.000000, Lat - 0.000000),
Gohpur - Overtopped by high flood water NH 15 to Chatiachuk Road NH 15 to Chatiachuk Roadon 29-06-2022 ,1st KM from NH15 ; (Long - 0.000000, Lat - 0.000000),

Tinalibori on 29-06-2022. Ch.900.00m to 1500.00m | (Long - 0.000000, Lat - 0.000000), Overtopped by high flood water | Mornoiguri Kalmouguri PMGSY Road | Mornoiguri Kalmouguri PMGSY Road on 29-06-2022, Ch 500.00m to 3500.00m | (Long - 0.000000, Lat - 0.000000), Overtopped by high flood water | Mornoiguri PWD to Singarajan | Mornoiguri PWD to Singarajan on 29-06-2022. Ch 0.00 m to 1200.00 m | (Long - 0.000000, Lat - 0.000000), Overtopped by high flood water | NH52 to Thaisrnbari PMGSY Road | NH52 to Thaisrnbari PMGSY Road on 29-06-2022 | (Long - 0.000000, Lat - 0.000000), Overtopped by high flood water | Kukurachowa Kochgaon Road | Kukurachowa Kochgaon Road on 29-06-2022 | (Long - 0.000000, Lat - 0.000000), Overtopped by high flood water | Gopalpur Sonapur Road | Gopalpur Sonapur Road on 29-06-2022. Ch.900.00m to 2400.00m | (Long - 0.000000, Lat - 0.000000), Overtopped by high flood water | NH15 to Gohpur Rly Station Road | NH15 to Gohpur Rly Station Road on 29-06-2022. 1st KM from NH15 | (Long - 0.000000, Lat - 0.000000), Mornoiguri Kalmouguri Road | Kalmouguri | Kalmouguri on 29-06-2022. About 500.00 m stretch is eroded by flood water | (Long - 0.000000, Lat - 0.000000), Halem - Gohpur Bhogpur PMGSY Road | Bhogpur | Overtopping caused damage to Gohpur Bhogpur PMGSY Road.29.06.2022 | (Long - 93.609749, Lat - 26.870867), Magoni Paken PMGSY Road | Magoni | Flood water overtopped causing damage to side bums.29.06.2022 | (Long - 93.581963, Lat - 26.850590), Chandamari to Buroi TE Road | Nalanibari | Side berms partially damaged.29.06.2022 | (Long -93.445795, Lat - 26.928903), Paschim Tokowbari to Puroni Geraj Road | Puronigeraj | Flood water overtopped.29.06.2022 | (Long -93.475753, Lat - 26.872515), Jotte Balijan road | Amjaroni | Flood water overtopped.29.06.2022 | (Long - 93.497893, Lat -26.877764), Brahmajan Delhousi Kachari Road | Delhousi Kachari | Flood water overtopped.29.06.2022 | (Long -93.532097, Lat - 26.869602), Kekurijan to Halem Railway Colony Road | Kekurijan | Flood water overtopped.29.06.2022 | (Long -93.480535, Lat - 26.873354), Collegeguri Milan Nagar Road | Collegeguri | Hard crust damaged ch.500.00m to 510.00m 29.06.2022 | (Long - 93.601498, Lat - 26.878388), Sonapukhuri Sewa Ashram Road | Amjaroni | Sonapukhuri Sewa Ashram Road at ch 50.00m to 300.00 m on 29-06-2022. Hard crust damaged | (Long - 93.501061, Lat - 26.882991) Silchar - Public School road | Public School road, Silchar | Public School road, Silchar Length Affected 0.80, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat -0.000000), Old Lakhipur road | Old Lakhipur road | Old Lakhipur road, Silchar Length Affected 4.70, Depth of Submergence 2.00, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Jail road | Jail road | Jail Road, Silchar Length Affected 0.40, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000). Pachaia Mia road | Pachaia Mia road | Pachaia Mia road Silchar Length Affected 0.48, Depth of Submergence 1.00, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Shiv Colony road | Shiv Colony road | Shiv Colony road Silchar Length Affected 0.90, Depth of Submergence 0.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Silchar Kalain road | Silchar Kalain road | Silchar Kalain road Silchar Length Affected 1.00, Depth of Submergence 0.60, as per the report received from PWRD Silchar & Udharbond Territorial Road Cachar 92 Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Bilpar road | Bilpar road | Bilpar road, Length of Damage-900m, Length Affected 0.90, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Graveyard road | Graveyard road | Graveyard road Length Affected 0.30, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Water works road | Water works road | Water works road Length Affected 0.30, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), U K Sarani, Bilpar road | U K Sarani, Bilpar road | U K Sarani, Bilpar road Length Affected 0.40, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Sasan road | Sasan road | Sasan road Length Affected 0.40, Depth of Submergence 1.00, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Radhamadab road | Radhamadab road | Radhamadab road Length Affected 1.30, Depth of Submergence 1.00, as per the report received from PWRD Silchar & Udharbond Territorial Road

Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Ice-cream factory road | Ice-cream factory road | Ice-cream factory road Length Affected 0.15, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Bhuiya gaddi road | Bhuiya gaddi road | Bhuiya gaddi road length Affected 0.30, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Swamiji road | Swamiji road | Swamiji road length Affected 0.80, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Malugram road | Malugram road | Malugram road length Affected 2.00, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Mediland Hospital road | Mediland Hospital road | Mediland Hospital road length Affected 0.20, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Dacaipatty road | Dacaipatty road | Dacaipatty road length Affected Affected 0.20, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road

Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), Ganiala road | Ganiala road | Ganiala road length Affected Affected 1.25, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Church road | Church road | Church road length Affected Affected 0.70, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Shillongpatty road | Shillongpatty road | Shillongpatty road length Affected Affected 0.45, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Narsingtolla road | Narsingtolla road | Narsingtolla road length Affected Affected 0.15, Depth of Submergence 1.00, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

East Narsing, West Narsing road | East Narsing, West Narsing road | East Narsing, West Narsing road length Affected Affected 0.60, Depth of Submergence 1.00, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Tulapatty road | Tulapatty road | Tulapatty road length Affected Affected 0.15, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Janiganj road | Janiganj road | Janiganj road length Affected Affected 0.10, Depth of Submergence 0.60, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Subashnagar road | Subashnagar road length Affected 0.20, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Netaji road | Netaji road | Netaji road length Affected Affected 0.20, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Nutanpatty RR Shome road, Aryapatty road | Nutanpatty, RR Shome road, Aryapatty road | Nutanpatty, RR Shome road, Aryapatty road length Affected Affected 0.80, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Dewanjee Bazar road | Dewanjee Bazar road | Dewanjee Bazar road length Affected Affected 0.15, Depth of Submergence 0.80, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Goala patty road | Goala patty road | Goala patty road length Affected Affected 1.80, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Gopal Akhara road | Gopal Akhara road | Gopal Akhara road | (Long - 0.000000, Lat - 0.000000), Samananda Ashram road | Samananda Ashram road length Affected Affected 0.45, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Daspara Mazumder Bazar road | Daspara Mazumder Bazar road | Daspara Mazumder Bazar road length Affected Affected 0.60, Depth of Submergence 0.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Kalibari Chor road | Kalibari Chor road | Kalibari Chor road length Affected Affected 0.18, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Gatta Colony road | Gatta Colony road | Gatta Colony road length Affected 0.20, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Radhamadav College Approach road | Radhamadav College Approach road | Radhamadav College Approach road length Affected 0.30, Depth of Submergence 1.50, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Chincoorie Road Ist KM to 8th KM | Chincoorie Road Ist KM to 8th KM | Chincoorie Road Ist KM to 8th KM Approach road length Affected 8.00, Depth of Submergence 1.00, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

BANGLAGHAT TO ELGIN ROAD | BANGLAGHAT TO ELGIN ROAD | BANGLAGHAT TO ELGIN ROAD SUBMERGENCE FROM CH. 3100.00M TO CH. 4700.00 M IN STRETCHES 400 M as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

CHINCOORIE TO NAYAGRAM ROAD | CHINCOORIE TO NAYAGRAM ROAD | CHINCOORIE TO NAYAGRAM ROAD FROM CH.0.00 M TO CH.900.00 M (IN STRETCHES) as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

CHINCOORIE KALINJAR ROAD | CHINCOORIE KALINJAR ROAD | CHINCOORIE KALINJAR ROAD FROM CH.0.00 M TO CH.700.00 M (IN STRETCHES) as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

CHINCOORIE NUTAN KANCHANPUR ROAD | CHINCOORIE NUTAN KANCHANPUR ROAD | CHINCOORIE NUTAN KANCHANPUR ROAD CH.6000.00 M TO 6500.00 M (IN STRETCHES) AVERAGE DEPTH 20.00 CM. as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000), CHINCOORIE ROAD TO KATHAL TINALI | CHINCOORIE ROAD TO KATHAL TINALI | CHINCOORIE ROAD TO KATHAL TINALI CH.800.00M TO CH.2000.00M (IN STRETCHES) as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

BADSABARI TO ELGIN ROAD | BADSABARI TO ELGIN ROAD | BADSABARI TO ELGIN ROAD CH.0.00 M TO CH.1700.00 M & SARKAR PARA TO ELGIN ROAD CH.0.00M TO CH.2300.00M as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

DHARAMPAR ROAD | DHARAMPAR ROAD | DHARAMPAR ROAD FROM WEST KACHUDARAM PMGSY ROAD TO CHINCOORIE KANCHANPUR ROAD FROM.CH.100.00 M TO 400.00 (IN STRETCHES) as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Hatirpath Road | Hatirpath Road | Hatirpath Road length Affected 1.30, Depth of Submergence 1.00, as per the report received from PWRD Silchar & Udharbond Territorial Road Division, Silchar, as on dated 29.06.2022 | (Long - 0.000000, Lat - 0.000000),

Katigorah - Rajyeswarpur Bus stand to Saraspur via Sanyashikandi | Rajyeswarpur Bus stand to Saraspur via Sanyashikandi | Rajyeswarpur Bus stand to Saraspur via Sanyashikandi Length Affected (Km) 0.50 to 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Koroikandi To Jabda including RCC Bridge approaches | Koroikandi To Jabda including RCC Bridge approaches | Koroikandi To Jabda including RCC Bridge approaches Length Affected (Km) 1.00 to 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

ONGC road to TRK road | ONGC road to TRK road | ONGC road to TRK road Length Affected (Km) 0.20 to 0.50 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Katigorah Harinagar Road | Katigorah Harinagar Road | Katigorah Harinagar Road Length Affected (Km) 2.00 0.40 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Nischintapur to Niz Jalalpur Pt-I connecting PMGSY Pkg. No. AS-03-66 and Pkg. No. AS-03-13 | Nischintapur to Niz Jalalpur Pt-I connecting PMGSY Pkg. No. AS-03-66 and Pkg. No. AS-03-13 | Nischintapur to Niz Jalalpur Pt-I connecting PMGSY Pkg. No. AS-03-66 and Pkg. No. AS-03-13 Length Affected (Km) 0.50 0.20 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Gumrah Leverputa Road to LP School under Khelma Pt-II village | Gumrah Leverputa Road to LP School under Khelma Pt-II village | Gumrah Leverputa Road to LP School under Khelma Pt-II village Length Affected (Km) 1.00 0.65 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Gumrah Leverputa Road | Gumrah Leverputa Road | Gumrah Leverputa Road Length Affected (Km) 1.00 0.40 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Craigpark road to Hanumathal | Craigpark road to Hanumathal | Craigpark road to Hanumathal Length

Affected (Km) 0.10 0.70 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Moinagram to Jabda via Hiluatilla Mahadevbari. | Moinagram to Jabda via Hiluatilla Mahadevbari. | Moinagram to Jabda via Hiluatilla Mahadevbari Length Affected (Km) 2.50 0.40 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Leverputa Boterchak Road | Leverputa Boterchak Road | Leverputa Boterchak Road Length Affected (Km) 0.60 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Gumrah Natanpur to Jame Masjid of Tarapur 0.20 0.20 | Gumrah Natanpur to Jame Masjid of Tarapur 0.20 0.20 | Gumrah Natanpur to Jame Masjid of Tarapur 0.20 0.20 Length Affected (Km) As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Construction of Road from Khelma II To Khelma V | Construction of Road from Khelma II To Khelma V | Construction of Road from Khelma II To Khelma V Length Affected (Km) 1.20 0.45 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Katirail TE to Harinagar Pt-I road | Katirail TE to Harinagar Pt-I road | Katirail TE to Harinagar Pt-I road Length Affected (Km) 1.50 0.20 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Sadirkhal to Mohanpur | Sadirkhal to Mohanpur | Sadirkhal to Mohanpur Length Affected (Km) 0.30 0.70 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

NH 06 at Digarkhal to Natanpur via Rajeswarpur, Kushierkhal and Pirnagar | NH 06 at Digarkhal to Natanpur via Rajeswarpur, Kushierkhal and Pirnagar | NH 06 at Digarkhal to Natanpur via Rajeswarpur, Kushierkhal and Pirnagar Length Affected (Km) 0.70 0.60 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Sadirkhal to Rajatilla road | Sadirkhal to Rajatilla road | Sadirkhal to Rajatilla road Length Affected (Km) 3.00 0.60 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

TRK Road 20 th & 21st km | TRK Road 20 th & 21st km | TRK Road 20 th & 21st km Length Affected (Km) 1.50 0.40 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-91 G.N Road to Telkor grant via Saraspur | PMGSY Package No AS-03-91 G.N Road to Telkor grant via Saraspur | PMGSY Package No AS-03-91 G.N Road to Telkor grant via Saraspur Length Affected (Km) 2.50 0.40 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000), PMGSY Package No AS-03-91 Mahadevpur Bus stand at Mahadevpur Part-I to Part-II | PMGSY Package No AS-03-91 Mahadevpur Bus stand at Mahadevpur Part-I to Part-II | PMGSY Package No AS-03-91 Mahadevpur Bus stand at Mahadevpur Part-I to Part-II Length Affected (Km) 3.50 0.70 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-69 Telkor Grant to Natanpur | PMGSY Package No AS-03-69 Telkor Grant to Natanpur | PMGSY Package No AS-03-69 Telkor Grant to Natanpur Length Affected (Km) 2.00 0.50 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-68 NH-44 at Lakhipur-I to Boroitoli | PMGSY Package No AS-03-68 NH-44 at Lakhipur-I to Boroitoli | PMGSY Package No AS-03-68 NH-44 at Lakhipur-I to Boroitoli Length Affected (Km) 3.00 0.50 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-38 NH-44 at Lakhipur to Boroitoli via Itbhatta | PMGSY Package No AS-03-38 NH-44 at Lakhipur to Boroitoli via Itbhatta | PMGSY Package No AS-03-38 NH-44 at Lakhipur to Boroitoli via Itbhatta Length Affected (Km) 2.00 0.60 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-78 Chikorkandi to Khelma via Khelma III to Khelma IV | PMGSY Package No AS-03-78 Chikorkandi to Khelma via Khelma III to Khelma IV | PMGSY Package No AS-03-78 Chikorkandi to Khelma via Khelma III to Khelma IV Length Affected (Km) 0.50 0.25 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-78 Salimabad to Chikorkandi at Khelma V | PMGSY Package No AS-03-78 Salimabad to Chikorkandi at Khelma V | PMGSY Package No AS-03-78 Salimabad to Chikorkandi at Khelma V Length Affected (Km) 0.50 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000), PMGSY Package No AS-03-67 Bihara-V at NH-6 to S.K. Road | PMGSY Package No AS-03-67 Bihara-V at NH-6 to S.K. Road Length Affected (Km) 5.00 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-65 Haritikaor to Salimabad | PMGSY Package No AS-03-65 Haritikaor to Salimabad | PMGSY Package No AS-03-65 Haritikaor to Salimabad Length Affected (Km) 7.00 1.00 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Chikorkandi to Khelma, Package No AS-03-02 | Chikorkandi to Khelma, Package No AS-03-02 | Chikorkandi to Khelma, Package No AS-03-02 Length Affected (Km) 1.50 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-151 Haritikor-I to Salimabad Road | PMGSY Package No AS-03-151 Haritikor-I to Salimabad Road | PMGSY Package No AS-03-151 Haritikor-I to Salimabad Road Length Affected (Km) 1.50 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

NH-44 at Lakhipur-I to Boroitali,Package No AS-03-193 | NH-44 at Lakhipur-I to Boroitali,Package No AS-03-193 | NH-44 at Lakhipur-I to Boroitali,Package No AS-03-193 Length Affected (Km) 0.30 0.20 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-64 Telitikor to Jagadishpur | PMGSY Package No AS-03-64 Telitikor to Jagadishpur | PMGSY Package No AS-03-64 Telitikor to Jagadishpur Length Affected (Km) 0.20 0.20 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

NH 44 at Brahmangram to Konapara | NH 44 at Brahmangram to Konapara | NH 44 at Brahmangram to Konapara Length Affected (Km) 0.50 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-90 NH-44 at Katirail TE to Jagadishpur-IV via Netaji Road | PMGSY Package No AS-03-90 NH-44 at Katirail TE to Jagadishpur-IV via Netaji Road | PMGSY Package No AS-03-90 NH-44 at Katirail TE to Jagadishpur-IV via Netaji Road Length Affected (Km) 0.20 0.25 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

PMGSY Package No AS-03-256 Gonirgram to TRK Road via Dudhpur-I & Boalipar | PMGSY Package No AS-03-256 Gonirgram to TRK Road via Dudhpur-I & Boalipar | PMGSY Package No AS-03-256 Gonirgram to TRK Road via Dudhpur-I & Boalipar Length Affected (Km) 1.00 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

GN Road near Chandipur Ramkrishna Akhra to Digorkhal TE garden | GN Road near Chandipur Ramkrishna Akhra to Digorkhal TE garden | GN Road near Chandipur Ramkrishna Akhra to Digorkhal TE garden 0.20 0.30 Length Affected (Km) As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000), L037- Konapara TE to Sindura-IX. | L037- Konapara TE to Sindura-IX. | L037- Konapara TE to Sindura-IX. Length Affected (Km) 1.00 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Santipur Point of TRK Road to S.K. Road via Dhudpur Road | Santipur Point of TRK Road to S.K. Road via Dhudpur Road | Santipur Point of TRK Road to S.K. Road via Dhudpur Road Length Affected (Km) 0.40 0.30 As reported by PWRD, Borkhola & Katigorah Territorial Road Division, Katigorah on dated 29.06.2022. | (Long - 0.000000, Lat - 0.000000),

Lakhipur - NH53 to Palorbond Alipur Road | Palorbond Alipur | Package No. AS-03-57 Length 1.3 KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. | (Long - 0.000000, Lat - 0.000000),

Banskandi MV School to Scotpur | Scotpur | Package No. AS-03-57 Length 1.000 KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. | (Long - 0.000000, Lat - 0.000000),

L022-NH 53 to Alney TE via Chau bari | Chau bari | Package No. AS-03-165 Length 0.350 KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. | (Long - 0.000000, Lat - 0.000000),

NH 53 - Lambabasti via Niz Banskandi | Lambabasti | Package No. AS-03-94 Length 2.500 KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. | (Long - 0.000000, Lat - 0.000000),

Singirbond - 180 L.P School via Sibpur-I and II | Sibpur-I and II | Package No. AS-03-56 Length 2.800 KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. | (Long - 0.000000, Lat - 0.000000),

L034-NH 53 to Nagapunjee via Chaprow | Nagapunjee | Package No. AS-03-161 Length 0.500 KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. | (Long - 0.000000, Lat - 0.000000),

L027-NH 53 to Chisel punjee | Chisel punjee | Package No. AS-03-172 Length 0.600 KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. | (Long - 0.000000, Lat - 0.000000),

Scottpur - Bandu via Rail Basti TE | Narayan Basti to South Laduman | Package No. AS-03-95 Length 0.800 KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. | (Long - 0.000000, Lat - 0.000000),

NH 53 - Chisel Punjee | Chisel Punjee | Package No. AS-03-95 Length 1.500 KM Report Received

		From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue Circle. (Long -
		0.000000, Lat - 0.000000),
		Jirighat Bahadurpur Road Makhannagar Kajal Basti Digli Basti Package No. AS-03-93 Length 0.30
		KM Report Received From PWD Lakhipur T Road Division on 30.06.2022 Under Lakhipur Revenue
		Circle. (Long - 0.000000, Lat - 0.000000) Bengtal - Patalsana and Khungreb Dwisa village road Patalsana FV (Shantipur VCDC) As reported
		by BDO, Sidli, village road damage due to flood on 19-06-2022 L-100m B-5m D-2m. (Long -
		90.402403, Lat - 26.761901),
		Bordangi village road Bordangi FV (Shantipur VCDC) As reported by BDO, Sidli, village road
		damaged due to flood on 19-06-2022 L-10m B-6m D-0.8m. (Long - 90.712973, Lat - 26.712973),
		Salguri vilage road Salguri FV (Shantipur VCDC) As reported by BDO, Sidli, village road damaged due to flood on 19-06-2022 L-30m B-6m D-1.7m. (Long - 90.440067, Lat - 26.760936),
		Dantak Road to Nakedara Bazar Road Shantipur (Shantipur VCDC) As reported by BDO, Sidli,
Chirang	6	Dantak Road to Nakedara Bazar Road damaged due to flood on 19-06-2022 L-10m B-5m D-1.5m.
		(Long - 90.440965, Lat - 26.747377),
		No.1 Tukrajhar village road No.1 Tukrajhar (Tukrajhar VCDC) As reported by BDO, Sidli, No.1
		Tukrajhar village road damaged due to flood on 19-06-2022 L-4.5m B-6m D-3m. (Long - 90.457235, Lat - 26.685719),
		PWD road at village No.2 Balapara No.2 Balapara (Tukrajhar VCDC) As reported by BDO, Sidli,
		PWD road at village No.2 Balapara damaged due to flood on 19-06-2022 L-12m B-4m D-3.5m.
		(Long - 90.437472, Lat - 26.672636)
		Dalgaon - Dalgaon Town to Sialmari via Dhekerigaon road Dalgaon Town to Sialmari via
		Dhekerigaon road at CH-1550m Dalgaon Town to Sialmari via Dhekerigaon road pavement damaged
		and potholes observed at CH-1550m above 1Mx1M and 2Mx1.2M Date of occurrence - 29/06/2022 (Long - 0.000000, Lat - 0.000000),
		construction of pavers road from Natun Bazar rest house to abed ali house No.1 Magurmari as per
		report received from BDO, pub mangaldai Dev. block construction of pavers road from Natun Bazar
Darrang	4	rest house to abed ali house at No.1 Magurmari das been damaged partially. Date of occurrence -
		19/06/2022 (Long - 0.000000, Lat - 0.000000), construction of road from idris ali house to siddiq ali house via baigormari baigormari as per report
		received from BDO, pub mangaldai Dev. block construction of road from idris ali house to siddiq ali
		house via baigormari has been damaged partially. Date of occurrence - 19/06/2022 (Long - 0.000000,
		Lat - 0.000000),
		Sipajhar - Upper Kurua to Bhati Kurua road. Kurua area. Due to continuous rain and flood water
		road is partially breached at CH 1400.00 mtr. w.e.f. 16-06-2022. (Long - 0.000000, Lat - 0.000000) Sissiborgaon - PWD Bhairabpur Road Kulajan Pam to Bhairabpur Ashigarh (AS-04-233) At Ch
		1200.00 M. Water overtopped the road fully, damaged side shoulder, hard crust and road
		Embankment. (On 29/06/220) length-200 m (Long - 94.805113, Lat - 27.577488),
		PWD Road Embankment at Kadamtoala to No2. KarengBalipur (AS-04-255A) At Ch 1200.00M.
		Damaged the side shoulder, hard Crust and Road Embankment. (On 29/06/2022) length-500 m (Long
		- 94.805113, Lat - 27.577488), Gogamukh - PWD Road, Chowldhuwabali – Chutiakari. (PMGSY Package no. AS-04-42) Road
		overtopped at Ch.10000.00 m (at Rotuwa) Road Overtopped at Ch.10000.00 m for a length of 350.00
		m of Chowldhuwabali – Chutiakari road. Dated: 30/06/2022 (Long - 94.362454, Lat - 27.366244),
		PWD road, Old NT Road to Bhebeli At Ch.2100.00 m Road Overtopped at Ch.2100.00 of Old NT
		Road to Bhebeli. Dated: 30/06/2022 (Long - 94.372178, Lat - 27.432441), PWD Road, Kowpatani – Nalbari Road. At Ch.3330.00 m Road Overtopped at Ch.3330.00 m for a
		length of 200.00 m. Also damage of road surface occurred of Kowpatani – Nalbari Road on
		30/06/2022 (Long - 94.366058, Lat - 27.475835),
		Dhemaji - Lawmuri to No2 Gohain Gaon PWD road Lawmuri to No2 Gohain Gaon Today on
Dhemaji	9	30/06/2022, Erosion has made in hard crush and shoulder of PWD road at Ch.1600.00m ,Ch 1650.00m, Ch.1700.00m and ch.1800.00m.(Length-30.00m) (Long - 94.546539, Lat - 27.387300),
		Jonai - PWD territorial road embankment NH 52 to Ngabang Gali Ghat At Ch. 2300.m & Ch.
		3670.00m As per report received from PWRD, Territorial Road Sub- Division-II, Jonai a PWD
		territorial road embankment NH 52 to Ngabang Gali Ghat under PMGSY Package No. As-04-27, 20
		meter left road damaged on 28/06/2022 by Depi River. length 20 meters (Long - 95.120433, Lat -
		27.743644), PWD territorial road embankment NH 515 at Deka Mishing to Amlakhi Pait via Compani road From
		Ch.1100.00m to Ch.1170.00m As per report received from PWRD, Territorial Road Sub- Division-
		II,Jonai a PWD territorial road embankment NH 515 at Deka Mishing to Amlakhi Pait via Compani
		road under, 20.00 meter road breached on 29/06/2022 by Deka Nallah. (Long - 95.243369, Lat -
		27.761529),
		PWD territorial road Jonai Nepali Basti College Tiniali to Depi Bridge via Upendra Barmah High School, From Ch.4300.00m to Ch.4350.00M As per report received from PWRD, Territorial Road
		Sub- Division-II, Jonai a PWD territorial road Jonai Nepali Basti College Tiniali to Depi Bridge via
		Upendra Barmah High School, 50.00 meter road damaged on 29/06/2022 by Manjeck Nallah. (Long -
		95.195163, Lat - 27.828438)
Hailakand	20	Hailakandi - Bankim Chandra Lane under Hailakandi Rev. Circle on dtd. 24.06.2022 Hailakandi
i		Town, Ward No-4 Submerged, surface damaged (Long - 92.563435, Lat - 24.675669),

Mujibur Rahman Gally under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-4 | Submerged, surface damaged | (Long - 92.564562, Lat - 24.674385), `Isak Ali Barbhuiya Lane under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-2 | Submerged, surface damaged | (Long - 92.565613, Lat - 24.668956), Sunahar Ali Lane under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-1 | Submerged, surface damaged | (Long - 92.566195, Lat - 24.672439), S. Chanda Road under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-4 | Submerged, surface damaged | (Long - 92.563403, Lat - 24.670270), Hrishi Arabinda Lane under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-4 | Submerged, surface damaged | (Long - 92.563081, Lat - 24.675127), Watir Ali Lane under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-1 | Submerged, surface damaged | (Long - 92.566034, Lat - 24.671024), Al Karim Senior Secondary School Gully under Hailakandi Rev. Circle on dtd. 24.06.2022 Hailakandi Town, Ward No-2 | Submerged, surface damaged | (Long - 92.565446, Lat - 24.673567), Gauranga Pally under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-1 | Submerged, surface damaged | (Long - 92.566422, Lat - 24.674335), Yasin Ali Last Portion under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Towmn, Ward No-1 | Submerged, surface damaged | (Long - 92.566284, Lat - 24.673479), APJ Abdul Kalam Road Last Portion under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-1 | Submerged, surface damaged | (Long - 92.568823, Lat - 24.679610), Project E Road under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-12 | Submerged, surface damaged | (Long - 92.566961, Lat - 24.681542), New Town Road, Last Portion under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-3 | Submerged, surface damaged | (Long - 92.568018, Lat - 24.688633), Mission Road by the side of Ananta Vidya Niketan School under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-3 | Submerged, surface damaged | (Long - 92.562784, Lat -24.686557). Jugendra Road under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-3 | Submerged, surface damaged | (Long - 92.561450, Lat - 24.687212), Starting from Old Hospital Road via Ashram Road upto Gangpar Dhumkar PMGSY Road under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakand0i Town, Ward No-15 | Submerged, surface damaged | (Long - 92.562358, Lat - 24.690662), Shyama Prasad Lane Last Portion under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-13 | Submerged, surface damaged | (Long - 92.562773, Lat - 24.690821), Norshing Akhra Last Portion under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-13 | Submerged, surface damaged | (Long - 92.562650, Lat - 24.692076), Mrinal Paul Gally under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-13 | Submerged, surface damaged | (Long - 92.654188, Lat - 24.692444), Lokenath Lane under Hailakandi Rev. Circle on dtd. 24.06.2022 | Hailakandi Town, Ward No-13 | Submerged, surface damaged | (Long - 92.654198, Lat - 24.693193) Palashbari - NH-37 to Satpakhali PWD Road (Br No. 1/3) | Satpakhali | Affected on 14-06-2022 as reported by Executive Engineer, PWD South Kamrup Territorial Road Division | (Long - 0.000000, Lat - 0.000000). Kulshi Garubandha Bangelibila Baregaon Road | Kulshi | Affected on 14-06-2022 as reported by Executive Engineer, PWD South Kamrup Territorial Road Division | (Long - 0.000000, Lat -0.000000), Batarhat Jharobari Loharghat Road | Loharghat | Affected on 14-06-2022 as reported by Executive Engineer, PWD South Kamrup Territorial Road Division | (Long - 0.000000, Lat - 0.000000), Jioramukhuri to Khokhapara | Khokhapara | Affected on 14-06-2022 as reported by Executive Engineer, PWD South Kamrup Territorial Road Division | (Long - 0.000000, Lat - 0.000000), North Ghy - Bejubari Road RR | Bejubari | Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Dongamukh Road RR | Dongamukh | Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 | (Long - 0.000000, Lat - 0.000000), 29 Dolani Pathar Road RR | Dolani Pathar | Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Kamrup Hajo Teritorial Road Sub-Div. on dated 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Athiabai Molong Pahar Road RR | Athiabai Molong Pahar | Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 | (Long - 0.000000, Lat -Athiabai Kesasupa to Kusujan Road RR | Athiabai Kesasupa | Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 | (Long - 0.000000, Lat -0.000000), Kesasupa to Kusujan Part 2 RR | Kesasupa to Kusujan | Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Changsari Milanpur Supa Road RR | Changsari Milanpur Supa | Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 | (Long - 0.000000, Lat -0.000000), Silbharal Biscuit Factory Road RR | Silbharal Biscuit Factory | Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 | (Long - 0.000000, Lat -

1	T	
		0.000000), Silbharal Moktab School Road RR Silbharal Moktab School Road Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long -
		0.000000, Lat - 0.000000), Silbharal Madrassa School Road RR Silbharal Madrassa School Road Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long -
		0.000000, Lat - 0.000000), Changsari Lakhi Nagar Road Near Railway Line RR Changsari Lakhi Nagar Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022
		(Long - 0.000000, Lat - 0.000000), Silbharal Approach Road RR Silbharal Approach Road Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat -
		0.000000), Sesa Changsari Road RR Sesa Changsari Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat - 0.000000), Gaurangapur Pukhuripar Road RR Gaurangapur Pukhuripar Affected on 19/06/2022 As reported by
		Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat - 0.000000), Changsari Dharatil supa Road RR Changsari Dharatil supa Affected on 19/06/2022 As reported by
		Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat - 0.000000), Dhopatari Gossaibhog Road Rr Dhopatari Gossaibhog Affected on 19/06/2022 As reported by Asstt.
		EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat - 0.000000), Bonmaja Chakchaki Pam Road RR Bonmaja Chakchaki Pam Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat - 0.000000),
		Dhopatari Silbharal Samshan Road Rr Dhopatari Silbharal Samshan Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat - 0.000000),
		Dhopatari Molong to Dakhin Athiabai Road RR Dhopatari Molong to Dakhin Athiabai Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat - 0.000000),
		Bonmaja Borjoritol Road RR Bonmaja Borjoritol Affected on 19/06/2022 As reported by Asstt. EE, Jalukbari Hajo Teritorial Road Sub-Div. on dated 29/06/2022 (Long - 0.000000, Lat - 0.000000), Chamaria - Chamaria Old Bus stand to Solapathar Chamaria Chamaria old bus stand to solapathar road breach caused, side berm and side slope damaged ,on dated 29.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 29.06.2022 (Long - 0.000000, Lat -
		0.000000), Sontoli Lotorigaon Sontoli Sontoli Lotorigaon road side berm and surface damaged ,on dated 29.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 29.06.2022 (Long - 0.000000, Lat - 0.000000),
		Trilochan Solapathr Trilochan Trilochan solapathar road breach caused, side berm and side slope damaged ,on dated 29.06.2022 and the same has been reported by JE, PWD, Boko territorial road subdivision on dated 29.06.2022 (Long - 0.000000, Lat - 0.000000),
		Hajo - Bagta Malisupa Road Bagta Affected on 29/06/2022 as reported by PWD, Hajo (Long - 0.000000, Lat - 0.000000), Dihina Hainadi Namghar Dihina Affected on 29/06/2022 as reported by PWD, Hajo (Long -
		0.000000, Lat - 0.000000) Gossaigaon - No 3 Dawaguri Masjid Road No 3 Dawaguri As reported by Asstt. EE, PWD, Gossaigaon RR Sub-Division, No 3 Dawaguri Masjid Road has been erroded in some stretches on 28-
Kokrajhar	2	06-2022 (Long - 0.000000, Lat - 0.000000), Hasrawbari No 2 village road Hasrawbari No 2 As reported by Asstt. EE, PWD, Gossaigaon RR Sub-Division, Hasrawbari No 2 village road has been washout on 29-06-2022 (Long - 0.000000, Lat - 0.000000)
		Bihpuria - NH 15 at Laluk Kachajuli road Ch. 4500 m to Ch. 5590 m Road damaged due to spillway flood water of Gabharu river. Road embankment, shoulder, hard crust etc. damages occurred on 30/6/2022 as reported by AEE, PWRD, Bihpuria TRSD (Long - 93.901016, Lat - 27.178848), Garmur Block to Tunijan road Ch. 600m to Ch. 1500m to Ch. 1700m Road damaged due to spillway
Lakhimpu	8	flood water of Pava river. Road embankment, shoulder, hard crust etc. damages occurred on 30/6/2022 as reported by AEE, PWRD, Bihpuria TRSD (Long - 93.918392, Lat - 27.147398), Bongalmora to Salmora Road Ch. 0.00m to Ch. 300.00m Road damaged due to spillway flood water. Road embankment, shoulder, hard crust etc. damages occurred on 30/6/2022 as reported by
r		AEE, PWRD, Bihpuria TRSD (Long - 93.955928, Lat - 27.064215), Nowboicha - Lothow Jorhotia Road to GK Road Lothow Pathar Road embankment and shoulders and bamboo bridge damaged due to flood water spilover on 30.06.2022. Report received from PWRD
		Nowboicha Territorial Road Sub-Division (Long - 94.052557, Lat - 27.200594), Narayanpur - Ganakdoloni Nowghuli Road Nowghuli Ganakdoloni Nowghuli road submerged depth of 250 mm on 29/06/2022 as reported by PWRD, Bihpuria divn. (Long - 0.000000, Lat - 0.000000),
	I	0.000000/,

			Natun Dadhara road dadhara Natun dadhara road damaged about 200 mtr on 29/06/2022 as reported by Simoluguri GP. (Long - 0.000000, Lat - 0.000000), Christian gaon Rangoti road Rangati Christian gaon Rangoti road damaged about 300 mtr on 29/06/2022 as reported by Simoluguri GP. (Long - 0.000000, Lat - 0.000000),
			Serepai Chuburi road serepai chuburi Serepai Chuburi road damaged about 50 mtr on 29/06/2022 as reported by Simoluguri GP. (Long - 0.000000, Lat - 0.000000)
			Morigaon - Dharamtul Dandua Road (30-06-2022) Naramari As per PWD (Roads), Damage restoration caused by flood water on Dharamtul Dandua Road at 3rd KM (Long - 92.374402, Lat - 26.214022), Rupaibari to Thekeraguri road (30-06-2022) Rupaibari As per PWD (Roads), Rupaibari to Thekeraguri road affected at 2nd, 3rd KM due to flood. (Long - 92.422972, Lat - 26.205767),
			Satgaon Manipurtup road (27-06-2022) Satgaon As per PWD (Roads), Satgaon Manipurtup road Br no 1/1 approach (RR) affected length=0.11 m (Long - 0.000000, Lat - 0.000000), Pachim Meruagaon to Koroibari road (27-06-2022) Meruagaon As per PWD (Roads), Pachim
	Morigaon	6	Meruagaon to Koroibari length affected =0.23 m, Avg depth=0.45m (Long - 0.000000, Lat - 0.000000),
			Owabori tiniali to Padumpukhuri Ahatoli Tiniali vi aKoraiguri road (30-06-2022) Owabori As per PWD (Roads), Owabori tiniali to Padumpukhuri Ahatoli Tiniali vi aKoraiguri road Breach occurred at Ch.1400.00m to 1600.00m also road surface and shoulder got damaged at various stretches. (Long - 92.311338, Lat - 26.189310),
			Laharighat - Laharighat to Dakhin Bagalipara Road Laharighat to Daskin Bagalipara Road As per report received by WT message of 17/06/2022 and PWD roads divission Laharighat, thebridge approach of RCC BR NO 1/1 & RCC BOX Culvert no 3/1 on Laharighat to Dakhin Bagalipara has been damaged due to incressant rain. (Long - 92.308200, Lat - 26.417200)
			Dhing - MORIGAON BECHAMARI ROAD BECHAMARI DUE TO CONTINIOUS RAINFALL MORIAGON BECHARI ROAD AI 4TH 5TH 6TH & 7TH HAS BEEN SUBMERGED AS REPORTED BY ASSISTANT EXECUTIVE ENGINEER, PWD DHING TERRITORIAL ROAD
			SUB DIVISION ON 29.06.2022. THIS IS NOT AFFECTED DUE TO FLOOD. (Long - 92.451435, Lat - 26.408257), BECHAMARI GEREKONI ROAD BECHAMARI DUE TO CONTINIOUS RAINFALL BECHAMARI GEREKONI ROAD HAS BEEN SUBMERGED AS REPORTED BY ASSISTANT EXECUTIVE ENGINEER, PWD DHING TERRITORIAL ROAD SUB DIVISION ON 29.06.2022.
	Nagaon	7	THIS IS NOT AFFECTED DUE TO FLOOD. (Long - 92.457288, Lat - 26.404364), Raha - SH 15 to Nabanga road Nabhonga Date of occurrence -29/06/2022 Submerged- 0.40 m Department-PWD, Morigaon (Long - 0.000000, Lat - 0.000000), Dakhin Barapujia to Puta Kolong Puta Kolong Date of occurrence -29/06/2022 Submerged- 0.85 m
			Department-PWD, Morigaon (Long - 0.000000, Lat - 0.000000), Bakultol to Bahgaon via Patiagaon Bahgaon Date of occurrence -29/06/2022 Submerged- 0.35 m
			Department-PWD, Morigaon (Long - 0.000000, Lat - 0.000000), Jaluguti Torabaritup to Gandhibori Torabaritup Date of occurrence -29/06/2022 Submerged- 8th km Department-PWD, Morigaon (Long - 0.000000, Lat - 0.000000), Satabor Tiniali to Singimari Singimari Date of occurrence -29/06/2022 Submerged-Singimari
			Department-PWD, Morigaon (Long - 0.000000, Lat - 0.000000) Paschim Nalbari - Jowardi to Sonora road Jowardi Road wash away at 2 km and submerged in 3rd
	Nalbari	2	and 4th km. Information receivede from PWRD at 29/06/2022 (Long - 0.000000, Lat - 0.000000), Bangaon Bhagawati Supa to Simaliya road Bangaon Side berm eroded and edge restrain in damaged due to heavy rainfall at many stretches. Information received from PWRD on 29/06/2022. (Long - 0.000000, Lat - 0.000000)
	Udalguri	1	Khairabari - Khoirabari Goreswar Road Sukuliapara The road which was damaged during the 1st wave of flood is further deteriorate at various point by the 2nd Wave flood. Length: 2KM (approx.). Date: 29.06.2022 (Long - 91.786196, Lat - 26.569442)
	Total	221 Numbe	
	District	r	Details Colombia NECoto Marco Supreme PMCSV Pood Supreme CP provided to the pood of PCC Provided to the PCC Provided to the pood of PCC Provided to the PCC Provided to the PCC Provided to the P
Infrastructu re Damaged - Bridge	Biswanath	4	Gohpur - NEC to Uttar Sonapur PMGSY Road Sonapur GP approach at one end of RCC Br. No 2/1 over river Solengi is damaged badly on 29-06-2022 (Long - 0.000000, Lat - 0.000000), Solengi to Rrajgarh Road via Sonapur Sonapur GP road breached at the approach of 5 cell H.P culvert at Ch. 4700.00 m at Ch 4730.00 to 4790.00 m at Ch. 4680.00 m & at Ch. 5100.00 m to 5170.00 m road badly damaged at Ch. 2400.00 m HP Culvert Damaged Badly on 29-06-2022 (Long - 0.000000, Lat - 0.000000), Naya Ghagra Tea Garden Road Ghogra Slab Culvert damaged completely on 29-06-2022 (Long - 0.000000, Lat - 0.000000)
			0.000000, Lat - 0.000000), Sukurbori to Nigam Bishnu Road HP culvert partially damaged Sukurbori to Nigam Bishnu Road on 29-06-2022 (Long - 0.000000, Lat - 0.000000)
			Gossaigaon - Wooden Bridge No. 1/2 No. 1 Khokshaguri As reported by EE Gossaigaon PWD RR,
	Kokrajhar	1	Wooden Bridge No. 1/2 has been damaged on No. 1 Khokshaguri to No. 3 Khokshaguri road on 28-06-2022 (Long - 0.000000, Lat - 0.000000)

- Wildlife Dist	Sarupeta - PWSS Damaged Restoration of distribution pipe line including supplying, laying, fitting, and fixing of UPVC / G.I. pipes and providing RCC supporting pillar, FHTC etc. are damaged at .Purba Luasur Latitude - 26.45883, Longitude - 91.05726,Sukmanah Latitude - 26.43976, Longitude - 91.01626,Parabharal Latitude -
	Sarupeta - PWSS Damaged Restoration of distribution pipe line including supplying, laying, fitting, and fixing of UPVC / G.I. pipes and providing RCC supporting pillar, FHTC etc. are damaged at .Purba Luasur Latitude -
Infrastructu re Damaged - Others Baja	26.45931, Longitude - 91.01428, Purba Luwasur Latitude - 26.45883, Longitude - 91.05726, Galia Latitude - 26.44523, Longitude - 91.05128, Bhalaguri Latitude - 26.51083, Longitude - 91.03083, Hathinapur Latitude - 26.53089, Longitude - 91.13646, Hakartup Latitude - 26.51907, Longitude - 91.0810, Dakhinhati (Dangarpar) Latitude - 26.44551, Longitude - 91.09137, Chauliabori Latitude - 26.51907, Longitude - 91.08810, Dakhinhati (Dangarpar) Latitude - 26.44551, Longitude - 91.07014, Rajakhat Latitude - 26.50813, Longitude - 91.13856, Nakuchigaon Latitude - 26.44551, Longitude - 91.09193, Karagari Pathar Latitude - 26.43843, Longitude - 91.10966and Denartary Latitude - 26.49605, Longitude - 91.12197. This report is received from EE(PHE), Bajali Division, Pathsala on 29/6/2022, Anganwadi Centres Affected 322No. Karagari Pub Suba, Fully Damage, Lat: 26.432694, Long : 91.095164 as on 29/6/22, Anganwadi Centres Affected 43 no.Tangla-3, Fully Damage, Lat: 26.496074, long : 91.13814 as on 29/6/22, Anganwadi Centres Affected 37 no.Tangla Mullahpara-4, Fully Damage, Lat: 26.47865, Long : 91.125073 as on 29/6/22, Anganwadi Centres Affected 30 no.Rajakhat-1, Partially Damage, Lat: 26.482124, Long : 91.11673 as on 29/6/22, Anganwadi Centres Affected 147 no.Rajakhat Uttar-2, Partially Damage, Lat: 26.414713, Long : 90.973908 as on 29/6/22, Anganwadi Centres Affected 153 no.Rajakhat Walahata, Partially Damage, Lat: 26.480429, Long : 91.107576 as on 29/6/22, Anganwadi Centres Affected 326 no.Rajakhat Madhya, Partially Damage, Lat: 26.480429, Long : 91.110544 as on 29/6/22, Anganwadi Centres Affected 326 no.Rajakhat Nayapara-3, Partially Damage, Lat: 26.421697, Long : 91.101079 as on 29/6/22, Anganwadi Centres Affected 31 no.Karagarigaon-1, Partially Damage, Lat: 26.421697, Long : 91.101079 as on 29/6/22, Anganwadi Centres Affected 32 no.Karagarigaon-2, Partially Damage, Lat: 26.420064, Long : 91.106482 as on 29/6/22, Anganwadi Centres Affected 30 no.Karagarigaon-3, Partially Damage, Lat: 26.427766, Long : 91.

PWSS Damaged | Restoration of distribution pipe line including supplying, laying, fitting, and fixing of UPVC / G.I. pipes and providing RCC supporting pillar, FHTC etc. This report is received from Executive Enginner, PHE, Bajali Division. Pathsala on 29/06/2022, Anganwadi Centres Affected | 73 No. Barboiragi 74 No. Barsahan 167 No. Barsahan Barboiragi 110 No. Hajirapara(M) 114 No. Gosaipara Supa(M) 103 No. Bhagawatipara(M) 101 No. Bagether Supa(M) "93 Pipla 1 Vill- Pipla" "126 Nimua Baniagaon Vill- Nimua Baniagaon" "96 Maripur Anandapur Vill- Anandapur" "139 Maripur Anandapur Maripur" "95 Maripur Anandapur Vill- Nitya nanda" "180 Mandalpara Vill- UttarPhal (Mini) "131 No. Nadipar, Bichankuchi (M) 125 No. Balihajari, Vill-Balihajari (M) 68 No. Kanimara137 No. Maguri 47 No. Pub helona 1no. Rahadhar Birkala. 2no.Barbang (I). 3no. Barbang (II). 6no. Barbang (V). 7no. Barbang (VI). 181no. Majipara. 182no. Kacharivitha. 140no. Barbhala Machkhowapara. 15no. Choudhurypara "170 No. Bezkuchi Vill-Bezkuchi" 156 No. Kuwara Doloigaon, Vill-Kuwara63 No. Bongaon142 No. Sariha Satra 106 No. Dharamtola Bhoha47 No Doloigaon 25 No Bamakhata 26 No Bamakhata 257 No Sathisamuka 164 No Sathisamuka 173 No Boro supa Nimua 249 No Padupara 38 No Uparnoi 35 No Dubi 33 No Dubi 134 No Tepartary 30 No Kukuwabatabari 353 No Haripur (i) 354 No Baruapara (i) 39 No Dumuria 210 No Puran Dumuria 147 No Natun Belana 176 No Dumuria 175 No Nalipara 158 No Bhethua 240 No Belana 40 No Bhethua 246 No Nalipara 245 No Nadipar 152 No Muslim Supa 151 No Belana Bengjuli 46 No Belana 156 No Pakriguri 71 No Pachim Titka 31 No Titka Garia 32 No Titka Garia 13 No Bhotanta Mahitara 132 No Nityananda Panbari 149 No Bhati Uluwa 21 No Tuplai Panbari 44 No Charalpara 273 No Nalana 27 No Muguria 28 No Muguria 159 No Kumrekhowa. These all are partially damaged and this report is received from CDPO Bajali on 29/06/2022, Anganwadi Centres Affected | 70 No. Barbhaluki.144 No. Pub Suba, Bichankuchi (M)177 No. Bhati Gomura 53 No. Panara 64 No. Gouripur 97 No. Howly supa 152 No. Barbatabari 241 No Doloigaon Santipur 75 No. Barnalikuchi 136 No. Barnalikuchi 235 No. Balartary 91 No. Kaplasupa 237 No. Tangarkur. These all centres are full damaged and this report is received from CDPO Bajali on 29/06/2022 Baska - Fisheries/Pond | Total individual pond and fish firm affected: 554 Nos. Total Water area: 124.06 Ha. Date: 21/06/2022, Sarumanikpur 26.6174° N, 91.2530° E Naoshali 26.6100° N, 91.2590° E Ulubari 26.6351° N, 91.2578° E Saderisupa 26.6173° N, 91.2674° E Chutiapara 26.5927° N, 91.2846° E Pachim Athiabari 26.5014° N, 90.9987° E Katahbari 26.6170° N,91.2963°E Pub-Athiabari 26.6051° N, 91.3059° E Hatirtari 26.5934° E $^{\circ}$ N,91.3011°E 1 No Katligaon 26.6577° N,91.3590°E Cahnbarikhuti 26.6343° N,91.3445°E Allia 26.6499° N,91.4060°E Ahopa 26.6877° N,91.3060°E Sirisbari 26.3842° N,91.1954°E Garamdeu 26.6640° N,91.3156°E Bennabari 26.5929° N,91.3590°E Uzirbari 26.6405° N,91.3060°E Goldingpara 26.5874° N,91.3156°E Baksa Belguripatahar 26.6462° N,91.3349°E Rampur 26.7983° N,91.0220°E Thomna 26.6407° N,91.2867°E Thomna 26.6407°E T Jyotinagar Totlapara 26.6583° N,91.2915°E Lakshimpur A block Kalbari 26.6020° N,91.6105°E 2 No Katligaon Hazira Singrapara 26.6047° N,91.3542°E Adalbari 26.4446° N,91.4411°E Choudhurytup 26.6583° N,91.3417°E Karemura 26.5771° N,91.3144°E Uttar Goldingpara 26.5873° N,91.3155°E Natun Sripur 26.6226° N,91.3252°E Pamua Pathar 26.6079° N,91.3228°E Nalbari Sripurdeur 26.6195° N,91.3421°E Bunbari 26.7513° N,91.2807°E Panbari 26.6280° N,91.3831°E Chaibari 26.6580° N,91.3421°E Total villages: 39 Nos. As reported on 30-06-2022 by fishery department. Sarthebari - Anganwadi Centres Affected | 11 NO. Bar Amrikhowa, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 12 no. Barshala, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 100 no. Muslim para, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 7 no. Khudra Amrikhowa - I, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 8 no. Khudra Amrikhowa - II, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 9 no. Khudra Amrikhowa - III, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 10 no Khudra Amrikhowa - IV, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 99 NO. Khudra Amrikhowa - V, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 92 no. Na Kuchi, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 13 no. Chinadi – I, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 14 no. Chinadi - II, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 15 no. Barghopa, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 77 no. Bar Ghopa Boro Supa, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 16 no. Patlarkur, Reported by CDPO Sarukhetri on 30/06/2022, Barpeta Anganwadi Centres Affected | 17 no. Chatla- I, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 18 no. Chatla – II, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 21 Gariya Chatala - II, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 25 no. Gadeshali Pam - II, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 93 no. Gadeshali Pm -III, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 101 no. Khudra Bamunbari Paschim Supa, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 19 no. Khudra Bamunbari, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 22 no. Garemari – I, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 23 no. Garemari - II, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 78 no. Garemari – III, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 26 no. Majdia - I, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 27 no. Majdia - II, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 79 no. Majdia – III, Reported by CDPO Sarukhetri on 30/06/2022, Anganwadi Centres Affected | 128 No. Kawoimari 7 Nos A/7, Reported by CDPO Paka-Betbari on 28/06/2022, Anganwadi Centres Affected | 205 No. Kawoimari 7 B/8, Reported by CDPO Paka-Betbari on 28/06/2022,

	Anganwadi Centres Affected 201 No. Kawoimari Pashim/9, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 207 No. Kawoimari 8/ Pashim/10, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 86 No. Kurihar Pam, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 87 No. Bamundi No-1, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 88 No. Bamundi No-2, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 194 No. Bamundi Pashim supa -4, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 223 No. Bamundi Baithabhanga Nadipar-5, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 89 No. Uttar Nali Gaon-1, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 90 No. Madhya Nali Gaon-2, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 92 No. Dakshin Nali Goan -3, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 106 No. Nali Gaon Pub para -4, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 221 No. Nalir pam Madhya Supa -4, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 100 No. Nalir Pam No.1, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 101 No. Nalir Pam No.2, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 91 No. Nalir Pathar 1, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 96. No. Pithadi Pam No.1, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 97. No. Pithadi Pam No.2, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 147 No. Pithadi Pam No.3, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 95 No. Pithadi Gaon No-2, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 93 No. Helasar Pam Bhaktar Daba-1, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 98 No. Helasar Pam Bhaktar Supa-2, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 99 No. Helasar Pam 3, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 103 No. Karagari Block No.10(B)-5, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 105. No Karagari Block, Reported by CDPO Paka-Betbari on 28/06/2022,
	Anganwadi Centres Affected 70 No. Garetari, Reported by CDPO Sarukhetri on 30/06/2022,
	Baghbar - Irrigation Canal/Scheme Damaged Mandia LIS-(a) Bhatkuchi Point 1, (b) Bhatkuchi point 2, (c)
	Kopoha point. Canal System of all three points have submrged under water .DATE-30-6-2022,
	Chenga - Power Dept. Poles 18 nos. HT pole damaged, 4 nos. LP damaged, line length damaged 2.1 km
	reported by APDCL deptt. on 29/06/2022
	Gohpur - Anganwadi Centres Affected Kakilapather AWC. 29.06.2022,
	Anganwadi Centres Affected Sonajuli AWC. 29.06.2022,
	Fisheries/Pond 1006 Nos. of Fish Tanks are affected of area about 105 Hactre under Gohpur Circle. 30.06.2022, Halem - Anganwadi Centres Affected Bholaguri Mazdurline AWC. 29.06.2022,
	Anganwadi Centres Affected Bholaguri L.P AWC. 29.06.2022,
	Anganwadi Centres Affected Jogibari AWC. 29.06.2022,
	Anganwadi Centres Affected 2.No Jogibari AWC. 29.06.2022,
	Anganwadi Centres Affected Nalinibari AWC. 29.06.2022,
	Anganwadi Centres Affected Pachim Nalinibari AWC. 29.06.2022,
	Anganwadi Centres Affected Balijan Bonua AWC. 29.06.2022,
Biswanath	Anganwadi Centres Affected 2.No Kekurijan AWC. 29.06.2022,
	Anganwadi Centres Affected Buroi T.E 3No Line AWC. 29.06.2022,
	Anganwadi Centres Affected Hatimara AWC. 29.06.2022, Anganwadi Centres Affected Pachim Missamari AWC. 29.06.2022,
	Anganwadi Centres Affected Faciliti Missaniari AwC. 29.06.2022, Anganwadi Centres Affected Halem Railway Station AWC. 29.06.2022,
	Anganwadi Centres Affected Madhya Chatrang AWC. 29.06.2022,
	Anganwadi Centres Affected Purupbari Kachari AWC. 29.06.2022,
	Anganwadi Centres Affected Bhogpur AWC. 29.06.2022,
	Anganwadi Centres Affected Purupbari Dakhin Line AWC. 29.06.2022,
	Anganwadi Centres Affected Dubia Karbi AWC. 29.06.2022,
	Anganwadi Centres Affected Dubia Pathar AWC. 29.06.2022
	Boitamari - Gully Control Damaged Gully Control Project. Longtitude-90.507439, Lattitude-26.319323, as per
Donasia	report received from Soil Conservation, Bongaigaon date-29.06.2022, Pangtol - Gully Control Damaged Gully Control Project Long 90.233752, Lat-26.254787, as per report
Bongaigao n	Dangtol - Gully Control Damaged Gully Control Project, Long-90.233752, Lat-26.254787, as per report received from Soil Conservation, Bongaigaon date-29.06.2022,
11	Srijangram - Gully Control Damaged Gully Control Project Long-90.658481, Lat-26.326567, as per report
	received from Soil Conservation, Bongaigaon date-29.06.2022
	Sonai - Inland Water Transport Deptt. Damaged 10 nos of wooden landing stage are flashed away, 1 No. of
	Waiting shed of Sonabari ferry service was completely damaged, approach road of Neairgram, Sonabari &
l l	1
Cachar	Bagpur ferry service at both side completely damaged Report received from IWT Department on 30.06.2022,
Cachar	Bagpur ferry service at both side completely damaged Report received from IWT Department on 30.06.2022, Lakhipur - Inland Water Transport Deptt. Damaged Both Side of Fulertol ferry service Approach Damage due
Cachar	Lakhipur - Inland Water Transport Deptt. Damaged Both Side of Fulertol ferry service Approach Damage due to Flood report received from IWT Department on 30.06.2022
Cachar	Lakhipur - Inland Water Transport Deptt. Damaged Both Side of Fulertol ferry service Approach Damage due

30/06/2022, 78 numbers of agri bund damaged due to flood. date of occurrence - 14/06/2022 to 28/06/2022, Raised Plateform Damaged | as per report received from BDO, Pub Mangaldai Dev. Block, 8nos of raised plate form has been damaged partially under dalgaon rev. circle.date of occurrence-16/06/2022 to 26/06/2022, Anganwadi Centres Affected | as per report received from social welfare department total 31 nos of AWCs have been damaged under dalgaon revenue circle due to flood.date of occurrence-16/06/2022 to 26/06/2022, Mangaldoi - PWSS Damaged | As reported by PHE Department on 30-06-2022 all total 24 Nos. of PWSS are damaged/affected, Sipajhar - Handloom & Textile Deptt | Flood affected weavers under Lokrai GP are (1) Village Basachuba 70 nos. (2) Gopalpur 30 nos. Cumulative since 27-06-2022 is 327 nos. of Handloom weavers., PWSS Damaged | Minor damage occurred in the PVC pipeline which is now been accessed after receding the flood at Byaspara PWSS, Pakabangi Kabeichuba PWSS, Nayakpara PWSS, Patgirichuba PWSS, Dakhinchuburi PWSS, Devananda Satra MPWSS, Narikali PWSS as reported by PHE on 30-06-2022, Gogamukh - Bridge Approach Road Damaged | PWD Road, Kowpatani - Nalbari Road (Br. No.-8/1 at Ch.7370.00 m), Erosion of Bridge approach occurred at Ch.7370.00 m. Longitude: 94.379684°E, Longitude: 94.379684°E, Dated: 30/06/2022, Damaged RCC Bridge | PWD Road, Rupohi Garpara to Chutiapara Road, At Ch.370.00 m Longitude: $94.36195^{\circ}E,$ Latitude: $27.482474^{\circ}N$) Damage of culvert at Ch.370.00 m. on 30/06/22,Jonai - Culvert Approach Road Damaged | PWD territorial road Sirampuria to Bijoypur Deori under PMGSY Dhemaji Package No.As-04-156, 90.00meter culvert approach road damaged on 29/06/2022 by flood water of Rayang River.. Culvert Approach Road Damaged | PWD territorial road Akland Machua Camp to Majgaon Kachari Road under PMGSY Package No. AS-04-163, 70.00 meter culvert approach road damaged on 29/06/2022 by flooded water, Bridge Approach Road Damaged | PWD territorial road Bahir Jonai To Bera Chapori via Bolaipam road under PMGSY Package No.AS-04-12, 100.00 meter bridge approach road damaged by Boginadi River.on 29/06/2022 Chabua - Health Sub-Centre | DODHIA KULIGAON HEALTH SUB-CENTRE SUBMERGED AS PER INFORMATION RECEIVED FROM HEALTH DEPT. ON 30/6/2022 Coordinates-N27 35.835 E95 13.266, Elementary Schools Damaged | DODHIA KULIGAON LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 30/6/2022 N27 35.845 E95 13.227, Elementary Schools Damaged | DODHIA KARMI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 30/6/2022 N 27 36.032 E95 14.787, Elementary Schools Damaged | DODHIA TENGABARI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 30/6/2022 N27 36.652 E95 14.237, Elementary Schools Damaged | DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT ON 30/6/2022 N27 36.462 E95 14.673, Anganwadi Centres Affected | DODHIA KULIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 30/6/2022 N27 35.845 E 95 13.227, Anganwadi Centres Affected | DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 36.652 E95 14.237, Anganwadi Centres Affected | DODHIA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 36.390 E95 13.651, Anganwadi Centres Affected | UPPER GEREKI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 30/6/2022 N27 33.942 E95 15.125, Anganwadi Centres Affected | DODHIA CHALBIL AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27. 5714 E95. 2346, Anganwadi Centres Affected | RONGMOLA AWC SUBMERGED AS PER INFORMATION RECEIVED Dibrugarh FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 33'33.40" E95 11'47.26", Anganwadi Centres Affected | 1 NO. MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N2733'48. 87" E13'18. 49", Anganwadi Centres Affected | 2 NO. MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 33' 50.38" E95 13' 16.90", Anganwadi Centres Affected | MULUKGHAT MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 33'52.36" E95 13'15.74", Anganwadi Centres Affected | TENGABARI-MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 33'52.88" E95 13' 14.42", Anganwadi Centres Affected | GEREKI NEPALI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 33'50.76" E95 15'26.01", Anganwadi Centres Affected | KULIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/22 N27 35.860 E95 13.460, Anganwadi Centres Affected | DODHIA ROMAI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 36.450 E95 13.782, Anganwadi Centres Affected | CHALBIL AISUNG CHAPORI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022 N27 34.890 E95 13.563, Anganwadi Centres Affected | NEPHAPHU TE AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 30/6/2022, Elementary Schools Damaged | DODHIA ME SCHOOL SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 30/6/2022 N27 35'47.50" E95 13'23.69" Algapur - Elementary Schools Damaged | SINGARIARPAR LPS submerged Long- 92.617383 Lat- 24.7995 Hailakand under Algapur Revenue Circle dtd. 23.06.2022, Elementary Schools Damaged | KRISHNA RAM MES submerged Long- 92.62215 Lat- 24.834583 under

Algapur Revenue Circle dtd. 23.06.2022,

Elementary Schools Damaged | 42 NO BAKRIHAWAR LPS submerged Long- 92.62045 Lat- 24.833917 under Algapur Revenue Circle dtd. 23.06.2022,

Elementary Schools Damaged | ROYPARA LASKARPARA EGS submerged Long- 92.6167 Lat- 24.83235 under Algapur Revenue Circle dtd. 23.06.2022,

Elementary Schools Damaged | BAKRI HAWAR PART 6 LPS submerged Long- 92.620933 Lat- 24.824433 under Algapur Revenue Circle dtd. 23.06.2022,

Elementary Schools Damaged | KASHKURIRPAR EGS submerged Long- 92.619533 Lat- 24.817133 under Algapur Revenue Circle dtd. 23.06.2022,

Elementary Schools Damaged | 405 NO BAKRIKHALERPAR LPS submerged Long- 92.622483 Lat- 24.816917 under Algapur Revenue Circle dtd. 23.06.2022,

Elementary Schools Damaged | 26 NO BAKRI HAWAR LPS submerged Long- 92.609933 Lat- 24.839683 under Algapur Revenue Circle dtd. 23.06.2022,

Elementary Schools Damaged | 409 NO KALINAGAR PART 1 LPS submerged Long-92.625017 Lat-24.851183 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 289 NO POLARPAR LPS submerged Long-92.6191 Lat-24.85735 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 903 NO RAJANI KANTA LPS submerged Long-92.613833 Lat-24.85295 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 722 NO UTTAR KHIRA BARI LPS submerged Long-92.60605 Lat-24.846483 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 416 NO ANNUARPAR LPS submerged Long-92.60995 Lat-24.849667 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | TAIRPAR (CHANDPUR) EGS submerged Long-92.602783 Lat-24.849967 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | KABI NAZRUL ISLAM VLP submerged Long-92.615633 Lat-24.84225 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | SOUTH BURNIE BRAES GOVT J.B.S submerged Long-92.643917 Lat-24.765833 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 426 NO PURAN MOHANPUR LPS submerged Long-92.636317 Lat-24.754033 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | MOHANPUR POLLY UNANYAN LPS submerged Long-92.633933 Lat-24.749283 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | PREM LOCHAN H.S SCHOOL submerged Long-92.637033 Lat-24.7417 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | BAGAN LINE EGS submerged Long-92.641083 Lat-24.725417 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | BARNIR MUKH MES submerged Long-92.663 Lat-24.81215 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 908 NO RENU BALA LPS submerged Long-92.660667 Lat-24.800283 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | BHAGWAT PRASAD HIGH SCHOOL submerged Long-92.652372 Lat-24.787349 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | CHUNATIPAR VLP submerged Long-92.6443 Lat-24.771733 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 277 NO CHANDOLI PAR LPS submerged Long-92.62375 Lat-24.783383 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | NIZAMUDDIN ASSAMESE LPS submerged Long-92.649117 Lat-24.79725 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 414 NO NARAYANPUR GIRLS LPS submerged Long-92.65295 Lat-24.793933 Under Algapur Rev. Circle on dtd.23.06.2022,

Elementary Schools Damaged | 513 NO KOBIGURU LPS submerged Long-92.661717 Lat-24.813733 Under Algapur Rev. Circle on dtd.23.06.2022,

Lala - Elementary Schools Damaged | LALAMUKH ROBIDAS LPS submerged Long- 92.635033 Lat- 24.5484 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | 958 RAJATHAL LPS submerged Long- 92.636933 Lat- 24.541067 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | BHARATPUR MES submerged Long- 92.629933 Lat- 24.55145 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | SAKALAPAR LPS submerged Long- 92.59765 Lat- 24.523033 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | MOHAMMEDPUR MVS submerged Long- 92.600483 Lat- 24.5002 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | RAMPUJAN LPS submerged Long- 92.565367 Lat- 24.604217 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | 69 NORTH NITYANANDAAPUR LPS submerged Long- 92.597917 Lat-24.622567 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | KOIRANG MEMORIAL MANIPURI LPS submerged Long- 92.590167 Lat-24.60995 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | 427 WEST NITYANANDAPUR LPS submerged Long- 92.581833 Lat-24.615033 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | 3 NO NISCHINTAPUR LPS submerged Long- 92.536417 Lat- 24.636667 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | 310 SWARNAMOYEE LPS submerged Long- 92.542717 Lat- 24.6234 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | NISCHINTIPUR PART 2 LPS submerged Long- 92.545517 Lat- 24.617333 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | SRIDAMBASTI LPS submerged Long- 92.542083 Lat- 24.604067 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | 730 ISMAIL MEMORIAL LPS submerged Long- 92.579267 Lat- 24.615233 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | TILA GAON MVS submerged Long- 92.567583 Lat- 24.616033 under Lala Rev. Circle dtd. 23.06.2022,

Elementary Schools Damaged | 617 LANGALALA LPS submerged Long- 92.569717 Lat- 24.606517 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | RAMCHANDI QUARIPAR LPS submerged Long- 92.548633 Lat- 24.54085 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | 641 RAMCHANDI HINDI LPS submerged Long- 92.53335 Lat- 24.534883 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | RAMCHANDI TEA GARDEN LPS submerged Long- 92.529283 Lat-24.533567 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | 362 SUDARSHANPUR LPS submerged Long- 92.63055 Lat- 24.631717 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | SUDARSHANPUR S.S ALI MEM submerged Long- 92.628217 Lat- 24.6335 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | BISHNUPUR UMANANDA MES submerged Long- 92.634067 Lat- 24.626033 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | SUNAPUR RAJBAW MES submerged Long- 92.6271 Lat- 24.624617 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | GOBIL BITONLAL SAHU LPS submerged Long- 92.643983 Lat- 24.606517 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | 382 NO TANTOO ARMANIA LPS submerged Long- 92.5592 Lat- 24.532633 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | 296 TANTOO LPS submerged Long- 92.568267 Lat- 24.539167 under Lala Rev. Circle dtd. 24.06.2022,

Elementary Schools Damaged | 933 NO BILPAR LPS submerged Long- 92.564367 Lat- 24.55645 under Lala Rev. Circle dtd. 24.06.2022

Kayan - PWSS Damaged | Retrofitting of Souramuri PWSS. DTW, TP & Interconnection, FHTC and Distribution system damaged. Date: 17/06/2022. Reported by PHED, Rangia Division.

PWSS Damaged | Retrofitting of Baranghati PWSS. DTW, TP & Interconnection, FHTC and Distribution system damaged. Date: 17/06/2022. Reported by PHED, Rangia Division.,

PWSS Damaged | Retrofitting of Sukurbari PWSS. DTW, TP & Interconnection, FHTC and Distribution system damaged. Date: 17/06/2022. Reported by PHED, Rangia Division.,

PWSS Damaged | Retrofitting of Lachi Bishnupur PWSS. DTW, TP & Interconnection, FHTC and Distribution system damaged. Date: 17/06/2022. Reported by PHED, Rangia Division.,

PWSS Damaged | Retrofitting of Balisatra PWSS. DTW, TP & Interconnection, FHTC and Distribution system damaged. Date: 17/06/2022. Reported by PHED, Rangia Division.,

PWSS Damaged | Retrofitting of Simalua Borigog PWSS. DTW, TP & Interconnection, FHTC and Distribution system damaged. Date: 17/06/2022. Reported by PHED, Rangia Division.,

PWSS Damaged | Retrofitting of Bardanga Batakuchi PWSS. DTW, TP & Interconnection, FHTC and Distribution system damaged. Date: 16/06/2022. Reported by PHED, Rangia Division.,

Rangia - Elementary Schools Damaged | The floor of Athara Haradutta LPS in village Athara was damaged by flood waters on 20.06.2022 as per report of BEEO, Rangia,

North Ghy - Anganwadi Centres Affected | 24 Nos. Anganwadi Centers damaged under Chandrapur-Karara ICDS project as reported by CDPO, Chandrapur Karara on dated. 29/06/2022 namely Amingaon Murgipatty AWC, Bamunigaon AWC, Kalimandir Dayal Nagar AWC, Amingaon Madhyam, Amingaon Railway Quarter, Amingaon Bengali LP, Monikarneswar Mohila Samiti, Changsari Nimna Buniyadi, Changsari Balika AWC, Chngsari LP AWC, Chnagsrai Moktab AWC, Mandakata Balika L.P., South Mandakata L.P., Mandakata Bagan, 15 No. Bezera, Khairapara AWC, Agdola LP, 1no. Bhomolahati,

Anganwadi Centres Affected | 11 Nos. Anganwadi Centers damaged under Bezera ICDS Project as reported by CDPO, Bezera on dated 29/06/2022 namely Numalijalah Muslim Suba, Silagrant Kating Pahar, Athiabai Xat Suba, Tangani, Gardowa Kaxoriya Tangani, Banmaza, Saru Simelibari, Loynupam Borigaon Islampur, Borkonchpara, Gog, Saster Mahajonpara Nodipar,

Chamaria - PWSS Damaged | Dekachang and Dekachange bazar distribution pipeline and FHTC is damaged on dated 29.06.2022 and the same has ben reported by JE, PHE, Boko sub-division on dated 29.06.2022,

PWSS Damaged | Solapathar and Solaboralimara distribution pipeline and FHTC is damaged on dated 29.06.2022 and the same has ben reported by JE, PHE, Boko sub-division on dated 29.06.2022,

PWSS Damaged | Sontoli Satra distribution pipeline and FHTC is damaged on dated 29.06.2022 and the same has

Kamrup

ben reported by JE, PHE, Boko sub-division on dated 29.06.2022,

PWSS Damaged | Arikati and Goroimari Bilorjan distribution pipeline and FHTC is damaged on dated 29.06.2022 and the same has ben reported by JE, PHE, Boko sub-division on dated 29.06.2022,

PWSS Damaged | Kismat Kathmi distribution pipeline and FHTC is damaged on dated 29.06.2022 and the same has ben reported by JE, PHE, Boko sub-division on dated 29.06.2022,

PWSS Damaged | No-1 Rangapani and No-2 Rangapani distribution pipeline and FHTC is damaged on dated 29.06.2022 and the same has ben reported by JE, PHE, Boko sub-division on dated 29.06.2022,

Hajo - Elementary Schools Damaged | Khopnikuchi LP School, Flood and Room Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | 1259 Muwamari LP School, Floor Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Konadia LP School, Floor and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Kulhati MVS, Room Wall, Floor, Field, Water Motor, Almirah Damage on 22/06/2022 as reported by BEEO, Hajo,

Secondary Schools Damaged | Kulhati HS, Wall Damage on 22/06/2022 as reported by BEEO, Hajo, Elementary Schools Damaged | Tetelia LPS, Floor and Water Motor Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Talia LPS, Floor and Water Motor Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Baushi LPS, Floor Desk bench and Water Motor Damage on 22/06/2022 as reported by BEEO, Hajo,

Secondary Schools Damaged | Janajyoti HS, Floor and Desk bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Natur Sorabari LPS, Floor and Wall Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Paniapara LPS, Book Self Damage on 22/06/2022 as reported by BEEO, Hajo, Secondary Schools Damaged | BAS HS School, 25Kg of MDM Rice, Library & Practice Book, Almirah, Tubewell Damage on 22/06/2022 as reported by BEEO, Hajo,

Secondary Schools Damaged | AS Anchalik Girls High School, 6Qtls of MDM rice, Desk Bench, Floor Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Saniadi Sorabari LPS, Water Motor Damage on 22/06/2022 as reported by BEEO, Hajo,

 $Elementary\ Schools\ Damaged\ |\ Basudev\ LPS,\ Room,\ Floor\ and\ Desk\ Bench\ Damage\ on\ 22/06/2022\ as\ reported\ by\ BEEO,\ Hajo,$

 $Elementary\ Schools\ Damaged\ |\ Dhareswar\ LPS,\ Room,\ Floor\ and\ Desk\ Bench\ Damage\ on\ 22/06/2022\ as\ reported\ by\ BEEO,\ Hajo,$

Elementary Schools Damaged | 506 Sester LPS, Room, Floor and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Secondary Schools Damaged | Ramdia Girls HSS, Room, Floor and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Secondary Schools Damaged | Kaliram HS, Floor and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | 1261no Dhinger Barijan LPS, Floor and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo, Elementary Schools Damaged | Barijani LPS, Room and wall Damage on 22/06/2022 as reported by BEEO, Hajo,

Secondary Schools Damaged | Satdala HS, Computer Damage on 22/06/2022 as reported by BEEO, Hajo, Elementary Schools Damaged | Satdala MES, Desk bench and water Pumb Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | 1250 Satdala LPS, Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Pandit Nehru LPS, Kitchen Room Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Milapur LPS, Floor Damage on 22/06/2022 as reported by BEEO, Hajo, Elementary Schools Damaged | 3No. Kulhati LPS, Floor and Wall Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Bardadhi Sankardev LPS, Floor and Almirah Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Sankardev Balika Vidyapith MES, Floor and Wall Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Khudradadhi LPS, Floor and Wall Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | 2No. Akadi LPS, Floor ,Wall and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Akadi Milan LPS, Floor ,Wall and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo, Elementary Schools Damaged | Akadi Nadiapur LPS, Floor ,Wall and Desk Bench Damage on 22/06/2022 as

reported by BEEO, Hajo, Elementary Schools Damaged | Uttar Akadi LPS ,Floor ,Wall and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Akadi Kandarpar LPS, Floor ,Wall and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Akadi Katajan Balika LPS, Floor ,Wall and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Karibil LPS,Floor ,Wall and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Khopanikuchi Nizarapar LPS, Floor ,Wall and Desk Bench Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | 1No. Sialmari PP GP LPS, Kutcha Building and 20 Kg MDM rice Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Pandiartam LPS, Floor Damage on 22/06/2022 as reported by BEEO, Hajo, Elementary Schools Damaged | Gaon Burha Pam LPS, Floor Damage on 22/06/2022 as reported by BEEO, Hajo, Elementary Schools Damaged | Indira gandhi LPS, Kutcha Building Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | Gaonbura Pam Major Supa LPS, Floor Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | 119 No. Saniadi LPS, Building, Desk Bench, Urinal Damage on 22/06/2022 as reported by BEEO, Hajo,

Elementary Schools Damaged | 1232 Adhiapara LPS, Boundary wall, Kitchen Room, Toilet, Classroom Damage on 22/06/2022 as reported by BEEO, Hajo

Gossaigaon - Washed away Culverts | As reported by Asstt. EE, PWD, Gossaigaon RR Sub-Division, HPC Culvert No. 1/1 has been damaged on No. 1 Bajugaon village on 28-06-2022,

Washed away Culverts | As reported by Asstt. EE, PWD, Gossaigaon RR Sub-Division, Slab Culvert No. 1/1 has been damaged on No. 1 Maktaigaon village on 28-06-2022,

Washed away Culverts | As reported by Asstt. EE, PWD, Gossaigaon RR Sub-Division, HPC Culvert No. 1/1 has been damaged on No. 2 Khokshaguri village road on 28-06-2022,

Washed away Culverts | As reported by Asstt. EE, PWD, Gossaigaon RR Sub-Division, Box Culvert No. 1/1 has been damaged on No. 1 Jaraguri PGR on 28-06-2022,

(**Kokrajhar**) **At District** - Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. EAST DIVISION IRRIGATION KOKRAJHAR ON 27-06-2022, NEW BISHMURI FIS WAS DAMAGE AT D/S GUIDE BUND R/S WAS DAMAGED,

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. EAST DIVISION IRRIGATION KOKRAJHAR ON 27-06-2022, BIDESHIJHORA FIS WAS DAMAGED AT D/S GUIDE BUND R/S, Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. EAST DIVISION IRRIGATION KOKRAJHAR ON 27-06-2022, HALTUGAON SUBHAIJHAR FIS WAS DAMAGE AT D/S R/S ABHTMENT WALL.

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. EAST DIVISION IRRIGATION KOKRAJHAR ON 27-06-2022, GENDRABIL FIS WAS DAMAGE AT D/S L/S ABHTMENT WALL ABOUT, Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. EAST DIVISION IRRIGATION KOKRAJHAR ON 27-06-2022, KATHALGURI FIS WAS BREACH AT MAIN CANAL EMBANKMENT AT 40M TO 70M.

Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. EAST DIVISION IRRIGATION KOKRAJHAR ON 27-06-2022, HALOADAL FIS WAS DAMAGE AT D/S GUIDE BUND, Irrigation Canal/Scheme Damaged | AS REPORTED BY EXE. ENG. EAST DIVISION IRRIGATION KOKRAJHAR ON 27-06-2022, GHORAMARA FIS WAS DAMAGE AT D/S GUIDE BUND, Gully Control Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-2022, GULLY EROSION OCCURED AT AGRI FIELD JAMBUGURI UNDER KACHUGAON BLOCK,

Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-2022, AGRI BUND DAMAGED AT BOSHGAON AT BOSHGAON VILLAGE UNDER KACHUGAON BLOCK.

Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-2022, AGRI BUND DAMAGED AT NASRAIBIL BUND AT DALGAON VILLAGE UNDER KACHUGAON

Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-2022, AGRI BUND DAMAGED AT BALIMARI AT BOROBADHA VILLAGE UNDER KACHUGAON BLOCK

Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-2022, GOBDA AGRI BUND DAMAGED AT NO. 2SHIALMARI VILLAGE UNDER DOTMA BLOCK, Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-2022, MARUPARA AGRI BUND DAMAGED AT MARUPARA VILLAGE UNDER DOTMA BLOCK, Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-2022, LOHIT AGRI BUND DAMAGED AT SHIALMARI UNDER DOTMA BLOCK,

Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-2022, ELON AGRI BUND DAMAGED AT SHIALMARI VILLAGE UNDER DOTMA BLOCK, Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-

2022, ATATAKI CANAL BUND DAMAGED AT NEPALPARA UNDER DOTMA BLOCK, Agri Bundh Damaged | AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-

2022, AMRITPUR EARTHEN AGRI BUND DAMAGED AT AMRITPUR VILLAGE UNDER KACHUGAON

Kokrajhar

Ţ		·
		BLOCK,
		Agri Bundh Damaged AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06- 2022, HANGLA BUND DAMAGE AT GANDA BEEL AT GHOSKATA VILLAGE UNDER DOTMA
		BLOCK,
		Agri Bundh Damaged AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-
		2022, KACHUKATA AGRI CANAL DAMAGE AT KACHUKATA VILLAGE UNDER GOSSAIGAON
		BLOCK,
		Agri Bundh Damaged AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-
		2022, EROSION PROTECTION BUND DAMAGED AT TILAPARA UNDER DOTMA BLOCK, Agri Bundh Damaged AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-
		2022, KAORADUMUNI AGRI BUND DAMAGE AT KAORADUMUNI VILLAGE UNDER DOTMA,
		Agri Bundh Damaged AS REPORTED BY EXE. ENG. AGRICULTURE, BTC, KOKRAJHAR ON 29-06-
		2022, DADUABIL EARTHEN AGRI BUND DAMAGE AT DADUABIL UNDER DOTMA BLOCK
		Dhakuakhana - Bamboo Foot Bridge The bamboo bridge at 1st KM on Bakulguri to Banjipathar road is washed
		away on 29th June, 2022 due to incessant rain and rising of water level. Length: 70.00M. Report submitted by Dhakuakhana Territorial Road Division, Ghilamara.,
	Lakhimpu r	Narayanpur - Irrigation Canal/Scheme Damaged Pichala FIS upstream (Right Bank) about 400 m damaged
		from Head works on 29/06/2022 as reported by Irrigation Dept. Bihpuria.,
		Culvert Approach Road Damaged Culvert washed away on Kakchabori to Dolin Basumatary Chuburi Road on
		29/06/2022, as reported by PWRD, Bihpuria divn.,
		Agri Bundh Damaged On 29/06/2022 a 50m of graded bund from padmapur shiv mandir to pichala shiv mandir has been breached and another earthen graded bund breached from pujari chuburi to railway crossing approx 25
		metres at five points
		Majuli - Irrigation Canal/Scheme Damaged Pabhokhowa Sluice gate at Sumaimari area submerged on
		30/06/20222. Latitude: 26.934597 and Longgitude: 94.223952,
	3.6 * 1*	Anganwadi Centres Affected 3 nos of AWCs submerged on 29.06.2022. 1. Ujoni Jomudchuk Mini AWC, 2.
	Majuli	Uttar Birinabari AWC, 3. Kharkati Bonia AWC, Ujani Majuli - Anganwadi Centres Affected 6 nos of Anganwadi centers submerged on 29.06.2022. 1.
		Kinkorchuk AWC, 2. Kolonibari AWC, 3. Grazing Koibatra AWC, 4. Phuloni Chariali AWC, 5. Daboli Chapori
		AWC, 6. Mudoibil AWC,
		Mikirbheta - Anganwadi Centres Affected As per report by CDPO, Kapili ICDS Project on 28-06-2022,
		Chalakhabori AWC, Kachadhara AWC, Lungamukh-1 AWC, Lungamukh-2 AWC, Uttar Majgaon AWC,
		Majgaon Kantatabari AWC, Niz-Mikirgaon-1 AWC, Fisheries/Pond As per report by AFO ,Kapili Block on 30-06-2022, 7.90 Hectre of Fishery area affected,
		Morigaon - Agri Bundh Damaged As per P&RD, Mayong Dev. Block, dtd.29-06-2022, Agri bundh affected by
		flood at Ahatguri(9 nos.), Nellie(3 nos.), Silchang(6 nos.), Telahi(3 nos.), Uttardharamtul (2 nos.),
		Fisheries/Pond As per Fisheries Dev. Officer(Bhurbandha), dtd.30-06-2022, Water area affected= 6 Hect due to
		flood at Solmari area., Fisheries (Pand As per Fisheries Day, Officer (Mayone), dtd 20, 06, 2022, Weter area officeted = 4.2 Hectors, 7.
		Fisheries/Pond As per Fisheries Dev. Officer(Mayong), dtd.30-06-2022, Water area affected = 4.2 Hectare, 7 nos. of farmers affected at Uttar Dharamtul, Ahatguri and Telahi area due to flood.
		Mayong - Irrigation Canal/Scheme Damaged Nepali khuti PC main canal damaged 25.00m, D2 canal damaged
	Morigaon	45.00m, 2. Nepali Khandajan P.C Main Canal 17.00m D2 Canal 9.00m as reported by Irrigation department
		Morigaon on 30/06/22,
		Elementary Schools Damaged 49 nos of Elementary Schools damaged/affected as reported by BEEO,Mayong on 29/06/22 Suntola LP Madanbori LP NO.2 MURKATA LP HADUGPAR LP KALSHILAPAR LP BANMURI
		LP NO.1 MURKATA ME(MV) BARPAM LP (V) HATIBHANGI LP HATIBHANGI ME KATAHGURI LP
		No 10 Balimukh Lp(E) Balimukh Natungaon Lp Pabitara Lp Diprang LP Diprang LP (E) Nabahatia lp Nabahatia
		anchalik ME Khanajan lp(v) KACHARIGAON LP NO2 GAGALMARI L.P MERORHABI L.P (E)
		MERORHABI L.P (V) Kumarbori lp Bherbheri Kulibasti LP Lecharipar Pam Lp Ashigarh Lp (E) SANTIPUR ME LONMATI LP JHARGAONLP KUSUMPUR BINAPANI LP JAGI AUNI ATI LP JAGIBHAKATGAON
		LP Phaliamari LP Phaliamari Habi LP Phaliamari Habi LP EGS Sandahkhaity MEM Patekibori LP Morisuti Tup
		LP EGS Gagalmari Merbil LP Baramari LP No 2 Pavakati LP Garubandha LP No 2 Baramari LP Tepuri Sunaipar
		LP Garubandha Nadirpar LP BHOMORAGURI LP HATIUTHA ANCHALIK ME(R) BELGURI LP
	Nagaon	Nagaon - PWSS Damaged Kotani PWSS, Barhampur, Submerge/ Damaged-Distribution Pipe line, FHTC,
		Some unites inside the scheme campus, dated-30/06/2022, reported by PHE Nagaon Division, PWSS Damaged Badalgaon PWSS, Barhampur, Submerge/ Damaged-Distribution Pipe line, FHTC, Some
		unites inside the scheme campus, dated-30/06/2022, reported by PHE Nagaon Division,
		PWSS Damaged Nonoi PWSS, Barhampur, Submerge/ Damaged-Distribution Pipe line , FHTC, Some unites
	Nagaon	inside the scheme campus, dated-30/06/2022, reported by PHE Nagaon Division,
		PWSS Damaged Katoni Putani PWSS,Submerge/ Damaged-Distribution Pipe line, FHTC, Some unites inside
-		the scheme campus, dated-30/06/2022, reported by PHE Nagaon Division, PWSS Damaged Chengmora PWSS,Submerge/ Damaged-Distribution Pipe line, FHTC, Some unites inside the
		scheme campus, dated-30/06/2022, reported by PHE Nagaon Division
		Banekuchi - Fisheries/Pond On 19/6/2022 appro. 70 numbers of fisheries/Pond had affected in flood water
		report from Fisheries Department,
	Nalbari	Handloom & Textile Deptt On 19/6/2022 appr. 150 families had affected in flood water report from Handloom & Textile Department,
		Paschim Nalbari - Anganwadi Centres Affected Total 65 nos. AWC are affected by flood. Information received
		from CDPO on 29/06/2022,

PWSS Damaged | Total 15 nos. of PWSS are damaged due to flood. Information received from PHE Belsor Division on 29/06/2022., Ghograpar - Handloom & Textile Deptt | As per concerned department, on 29/06/2022, 31 (Thirty one) nos. of weavers has been affected., Nalbari - Handloom & Textile Deptt | As per the report received from Handloom & Textile Deptt, Nalbari on 30/06/2022, 255 nos. weavers are affected due to flood occurred on 15/06/2022 to 22/06/2022, Fisheries/Pond | As per the report received from Fisheries Deptt, Nalbari on 29/06/2022, 1270 nos. of farmers covering total 340.50 Hect. Fish Culture area affected due to flood occurred on 15/06/2022 to 22/06/2022 Thelamara - Elementary Schools Damaged | DATE-30/06/2022, As reported by DEEO, Sonitpur, Simaluguri Refugee LPS, Nalaniduba LPS, Rohinibill LPS, Bordubi LPS has been partially damaged., Sonitpur Dhekiajuli - Anganwadi Centres Affected | (Correction) As reported by CDPO Dhekiajuli, AWCs affected at monmohinipur TE (A), Tinkhuria Factory Line AWC, Tinkhuria 2 no Nadipar, Panbari TE(B), 1no Sesontola, Majbaligaon Pathar & Sopai TE AWCs. Date 28.6.22. Tamulpur - Elementary Schools Damaged | As report received on dated 30-06-2022, Kalbari LP School was Tamulpur found damaged.Long-91.602648,Lat-26.599367, Elementary Schools Damaged | As report received on dated 30-06-2022, barbilla LP School was found damaged. Udalguri - Power Dept. Poles | As reported by APDCL, Udalguri on 29.06.2022 a total of 48 Nos. of 11 KV Poles and 37 Nos. of LT Poles have been damaged in 46 nos of villages under Udalguri Revenue Circle in the recent flood on 18th, 19th, 20th, 21st and 22nd June, 2022., Power Dept. Conductors | As reported by APDCL, Udalguri on 29.06.2022 a total of 17.4 Kms of 11 KV Conductors and 24.95 Kms of LT Conductors have been damaged in 46 nos of villages under Udalguri Revenue Circle in the recent flood on 18th, 19th, 20th, 21st and 22nd June, 2022., Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Breach of Left canal embankment at Ch 18690 M of B1M Canal (approx. 10m) at Baslishiha Habi village on 11.06.2022. GPS - Lat -26.704826 Long - 92.202918, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Breach of canal embankment both side at Ch 1145 M of D1B1M Canal (approx. 20m) at Rowta Station village on 16.06.2022. GPS - Lat - 26.716173 Long - 92.206988, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Breach of Left canal embankment at Ch 3090M of D1B1M Canal (approx. 10m) at Baslishiha (near Rowta Sasan) village on 16.06.2022. GPS – Lat – 26.701534 Long – 92.213816, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Erosion of Canal embankment and embankment cum road of D2B1M Canal (approx. 20m) at Hazaragaon village on 16.06.2022. GPS - Lat - 26.674304 Long - 92.148102, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Erosion at Canal Embankment at Ch 15890 m of B1M canal (approx. 10m) at Bhelapara village on 16.06.2022. GPS - Lat -26.728725 Long - 92.198967, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Erosion at Canal Embankment and structure Damage of CC Fall at Ch 10800m of B1M canal (approx. 15m) at 1 No. Dhansirikhuti village on 16.06.2022. GPS – Lat – 26.755796 Long – 92.178288, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Erosion at Canal Embankment Ch 9500 m of BIM canal (approx. 15m) at No. 1 Dhansirikhuti village on 20.06.2022. GPS – Lat – Udalguri 26.763409 Long – 92.177446, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Erosion at Canal Embankment and CD Damages at Ch 12900m of BIM canal (approx. 10m) at 2 No. Dhansirikhuti village on 20.06.2022. GPS – Lat – 26.749117 Long – 92.185747, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Erosion of guide bundh and Toe wall construction at D/S in both side of Dhalapara Bhergaon FIS (approx. 10m) at Puroni Goroibari village on 16.06.2022. GPS – Lat – 26.746541 Long – 92.122778, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Breached of earthen canal at ch. 5600.00M to 5650m of D2B3M (approx. 50m) at Bhalukmari village on 20.06.2022. GPS - Lat -26.66691 Long – 92.066775, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Breached and CC Lining damaged at Ch. 1330.00M to Ch. 1380.00M of D2B1M canal (approx. 50m) at No. 1 Botabari village on 01.06.2022. GPS - Lat - 26.825382 Long - 92.121312, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Breached at Ch 1730M to Ch 1780M of K3M canal (approx. 50m) at Panimudi village on 21.05.2022. GPS - Lat - 26.788749 Long -92.992385, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Damage of RCC fall at Ch 1500.00M of K1M canal (approx. 10m) at No. 1 Botabari village on 08.06.2022. GPS - Lat - 26.794082 Long – 92.068847, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Breached of earthen canal at ch. 14050.00M to 14058.00M and silbng From Ch 14000 to 14400.00M of B2M canal (approx. 408m) at Mohanpur village on 08.06.2022. GPS – Lat – 26.707042 Long – 92.084477, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Breached of embankment at Ch 19340 OOM of main canal (approx. 30m) at No. 1 Amjuli village on 20.05.2022. GPS - Lat -26.80694444 Long - 92.00638889, Irrigation Canal/Scheme Damaged | As reported by Irrigation Department on 29.06.2022, Erosion at U/S and D/S of Aquaduct at ch. 1500.00m of B5M canal (approx. 30m) at No. 1 Amjuli village on 27.06.2022. GPS – Lat –

		26.762187 Long – 92.056166,
		Harisinga - Power Dept. Poles LT and HT poles at village Pub-Nalbari, Naobandha damaged on 28/06/2022.
		under Tangla electrical sub-division, Power Dept. Conductors Conductors were snapped at various places like Villages Pub-nalbari and Naobandha
	District	on 28/06/2022 under Tangla electrical sub-division
	District	Details Biswanath - Bharalijuli as per information received from concerned LM, erosion occurred by the banks of river
	Biswanath	Borgang at village Bharalijuliu.29.06.2022 0
	Bongaigao n	Manikpur - 2 no Bashbari & Salmara Erosion Took Place in Bashbari no 2 due to river Aie on date-30.06.2022 approx 10 mtr. erode away . Erosion Took place in Salmara Due to River Manas on Date-30.06.2022 approx 30 mtr. Population Affected=00(Latitude-26.485642 Longitude-90.773287)2 Nos of Relief camp(1) Tilpukhuri ME Madrasa,Male=179 Female=165 Child=124 Pregnant=1 Disability=1 Total=470(Latitude-26.39971 Longitude-90.753438) (2)3 Bashbari LP School, Male=86 Female=83 Child=77 Pregnant=2 Total=248(Latitude-26.426476 Longitude-90.759589) since 17.06.2022 to till date 30.06.2022/Total Inmates 710. Animals Affected- Big- 1412, Small-505, Poultry-2650, Wheat Bran-134.66 qtls. as per report received from DVO, Bongaigaon date-30.06.2022 777, Srijangram - Dubachuri Part I Kushbari Part II Baghekhaity Santoshpur part II, Kacharipety Part III and Behulapara. santoshpur Part II:camp is in operation.(inmates:198 nos.) Dubachuri Part I Embankment (inmates:205) Bhaduripara MV School Kacharipety Part III (inmate:140) . Kushbari Part II and Baghekhaity: No camp has openedfamily affected -12 nos. and Behulapara (90.697808 26.315085 kujia river) family affected -2 Nos. GR issued to Kushbari and Baghekhaity (Rice:1.29 Qt Dal: 0.225 Qt Salt:0.0675 Qt and M.oil : 6.75 Ltr), Medical Team Deployed- 6 Nos date-30.06.2022 620
	Chirang	Bengtal - Runikhata, Laokhriguri, Madarpur As reported by WRD, Erosion at Runikhata near cattle market on L/B of river Bhur L-350m B-5m D-3m on 29-06-2022 Lat-26.639118 Long-90.374498. As reported by WRD bank erosion at Laokhrikguri on R/B of river Nijla on 21-06-2022 L-1000m B-13m D-3m Lat-26.4338 Long-90.275. As reported by WRD bank erosion and inundation at Madarpur on L/B of river Aie on 21-06-2022 L-2000m B-12m D-2.8m Lat-26.355885 Long-90.31626 0
	Dhemaji	Jonai - At No.2 Milonpur on 29/06/2022 approx. 2 hectare of land got eroded by Sikari River. As per report received from Lot Mandal at No.2 Milonpur on 29/06/2022 approx. 2 hectare of land got eroded by Sikari River. 4
Erosion	Dhubri	South Salmara Part - Sundarpara pt - iv As per information received from concerned Lot Mondal 47 nos family has been eroded due to erosion by river Brahmaputra at village Sundarpara pt-iv on 27/06/22 to 29/06/22. Area Aprox 23B-2K-5L. Eroded families has been shifted to the safe place. 273
	Dibrugarh	Tengakhat - Tingrai Doomgaon Erosion damage to the playground of Tingrai High School at Tingrai Doomgaon near Tingrai Thakurbari Than for a length of 250m as reported by WRD. As on 30.06.2022 0
	Kamrup	Palashbari - Futuri On 17-06-2022 at around 10:30 PM the Bramhaputra eroded around 400m length and 10 m width of downstreme of Makadujh Land Spur including nose portion of Makaduj Spur. The report os submitted by Water Resources, PGP Sub division, Mirza 0
	Kokrajhar	Dotma - 1. Vill- Magurmari (Monakocha), 2. Amlaiguri 1. AS REPORTED BY CO DOTMA, Date: 30/06/2022 Erosion occurred at village Magurmari (Monakocha) by the river Hell and eroding agriculture Land. Length-Approx 100M 2. AS REPORTED BY CO DOTMA Date: 30/06/2022 Erosion occurred at village Amlaiguri by the river Buri and the village Fishery Tank is about to get affected. Length-Approx. 60M 0
	Lakhimpu	Kadam - Bodhakara Approximate 2km eroded away by the river Subansiri, moghuachuk to sonowalgaon,
	Morigaon	informed by BDO, Boginadi Dev. Block, dated 29/6/2022 0 Laharighat - Leruamukh, Goroimari PWD road, Bhajaikhati gaon & Barchapori As per report received from the Water Resources Dept on 30/06/2022, erosion is observed in areas like Leruamukh, Goroimari PWD road, Bhajaikhati gaon & Barchapori with maximum erosion of 0 m in Leruamukh, 0 m in Goroimari PWD road, 1 m in Bhajaikhati gaon & 1 m in Barchapori 0
	Sonitpur	Thelamara - Village- Dhekipelua, Pothalikhowa DATE-30/06/2022, As reported by Water Resources Deptt, Tezpur, Avulsion of river Belsiri is observed at Dhekipelua Pakoriguri RCC Bridge No.2/1 of length- 150m and at Pothalikhowa near PWD road of length 150m. 0, Tezpur - Arimora Dated 30/06/2022. As reported by WR Dept. erosion is observed on the right bank of the rive Dipota at villages Arimora . A stretch of 150 m of the crest of the embankment is washed away due to the erosion 0
	Tamulpur	Tamulpur - Vill- Dowamakha Severe erosion takes place at Dowamakha,L/B of river baralia. Dated - 30/06/2022 0
	Tinsukia	Tinsukia - 1. Khamtiguwali Koila Pather 1. Active river bank erosion is going on at Khamtiguwali Koila Pather area since 29/06/2022 till 30/06/2022. As per report by WR department, the stretch area is 100m. 90
Landslide	Nil	
	District	Details Silchar - National Highway road , Chandicharan Road, Bilpar, Public School Road, Subhas Nagar, N.S. Avenue,
Urban	Cachar	Kanakpur, Das Colony, Chengkoori Road, Tarapur, Vivekananda Road, Asham Road Due to incessant rainfall, the closure of sluice gates, and over-topping of Embankments in many areas in and around Silchar Town. From 18.06.2022 to Till today (Dated 30.06.2022) waterlogging still stays in the many places in Silchar City 225620
Flood	Dibrugarh	Dibrugarh East - 1. Chawlkhua Grant Gaon 2. Niz kodomoni gaon ward 3. Old Amolapatty ward 4. Jopora Gaon ward 5. Amolapatty Gaon Ward 6. Graham Bazar ward Flood due to water logging as on 30.06.2022 2443
	Tinsukia	Tinsukia - TINSUKIA TOWN SHEET NO 25, TINSUKIA TOWN SHEET NO 28 AND HIJUGURI DUE TO HEAVY RAINFALL ARTIFICIAL FLOOD OCCURS AT SOME POCKETS OF TINSUKIA TOWN SINCE

	YESTERDAY (29-06-2022) AND PRESENTLY WATER EXIST AT THE SAME PARTS AS WELL (30-06-
	2022) 945