

FRIMS Assam



Flood Reporting And Information Management System

		A	ssam Daily	Flood Report	as on 10-10-202	22 at 4:00 PM			
Particulars	Situation as o								
Rivers flowing above Danger	Rivers flowin	g above dan	iger level	Nil					
Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above highest flood level			Nil					
District Affected	No. of Districts Affected	Name of	Flood Affec	ted Districts		Name of Urban Flood Districts			
	3 Dhemaji, Dibrugarh, Lakhimpur								
No. Of Revenue	6					-			
Circles Affected	0								
Name Of Revenue Circles Affected	District	Total	Revenue	Circle					
	Dhemaji	2	Sissiborgaon, Jonai						
	Dibrugarh	1	Chabua						
	Lakhimpur	3	Nowboicha, North Lakhimpur, Bihpuria						
	Total	6							
	District	Total	Total Revenue Circle						
77'11	Dhemaji	10							
Villages	Dibrugarh	1	(Chabua 1)						
Affected	Lakhimpur	21	(Nowboicha 16), (North Lakhimpur 3), (Bihpuria 2)						
	Total	32							
	District	Male	Female	Children	Total Population	Population Details	Crop Area (in Hect.	Crop Area Details	
Population And Crop Area Affected	Dhemaji	2988	2435	1476	6899	(Sissiborgaon 4469), (Jonai 2430)	712.00	(Sissiborgaon 480.00), (Jonai 232.00)	
	Dibrugarh	1567	1240	1050	3857	(Chabua 3857)	0.00	(Chabua 0.00)	
	Lakhimpur	5407	4278	3152	12837	(Nowboicha 11563), (North Lakhimpur 1091), (Bihpuria 183)	0.00	(Nowboicha 0.00), (North Lakhimpur 0.00), (Bihpuria 0.00)	
	Total	9962	7953	5678	23593		712.00		
Relief Camps / Centres Opened	Nil		•						
Inmates In Relief Camps	Nil								
Human Lives Lost - Confirmed	Nil								
Human Lives Lost Confirmed - Death Type	Nil								
Human Lives Lost - Missing	Nil								
Human Lives Lost Missing - Type	Nil								
	District	Total	Big	Small	Poultry				
Animals	Dhemaji	2463	1888	575	0				
Affected	Lakhimpur	3125	2425	700	0				
	Total	5588	4313	1275	0				
Animals Washed Away	Nil								
Houses Damaged	Nil								
Rescue Operation	Nil								

Relief	Nil						
Distributed	1111						
Relief Distributed Others	Nil						
Others	District	Number	Details				
Infrastructure	2 1501 100	110222002	North Lakhimpur - NA ALI TELIAPATHAR GHANCHARAI RIGHT BANK NA ALI				
Damaged - Embankment Breached	Lakhimpur	TELIA PATHAR Embankment breached at NA ALI TELIAPATHAR GHANCHARAI RIGHT BANK about 20 MTR as reported by WR department, NLP on 10-10-2022. (Long - 0.000000, Lat - 0.000000)					
	Total	1					
Infrastructure Damaged - Embankment Affected	District	Number	Details				
	Lakhimpur	Nowboicha - Singra L/B embankment (U/S of NH-15) Bharaluwa Rain cuts has been observed at Singra LB embankment (U/S of NH-15)about 10 mtr during last night shower i.e. 09.10.2022. Report received from, AE, Water Resources Dept. Lakhimpur on 10.10.2022 (Long - 0.000000, Lat - 0.000000)					
	Total	1					
Infrastructure Damaged - Road	District	Number	Details				
	Dhemaji	1	Gogamukh - PWRD Road, Gogamukh Chariali to Borbam Abandant Erosion occurred at Ch.5500.00 m. Erosion occurred at Ch.5500.00 m of Gogamukh Chariali to Borbam Abandant road under PWRD, Dhemaji Territorial Road Division. Dated 10/10/2022. (Long - 94.302936, Lat - 27.390072)				
	Total	1					
Infrastructure Damaged - Bridge	Nil						
Infrastructure							
Damaged - Wildlife	Nil						
	District Other Details						
Infrastructure	District						
Infrastructure Damaged - Others	Karbi Anglong	Silonijan Kalioni(K	- Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am .				
Damaged -	Karbi	Silonijan Kalioni(K	- Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River				
Damaged -	Karbi Anglong	Silonijan Kalioni(Kalioni(Kalioni)) length of to Details Halem - Dalani Vil	- Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am . he breach = 40 m under PWD Barpather Road Division. latitude-26.474792,long-93.778562 Dipara Dalani Village Active erosion is observed at upstream of protection work at Dipara lage of river Brahmaputra reported by water resource department on 10/10/2022. 0				
Damaged -	Karbi Anglong District	Silonijan Kalioni(Kalioni(Kalioni(Kalioni)) Length of t Details Halem - D Dalani Vil Manikpun totally full Srijangra bank of M	- Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am . he breach = 40 m under PWD Barpather Road Division. latitude-26.474792,long-93.778562				
Damaged -	Karbi Anglong District Biswanath	Silonijan Kalioni(Kalioni(Kalioni(Kalioni)) Betails Halem - Dalani Vil Manikpun totally full Srijangra bank of Malismantled Agamoni Rev. Circle 10/10/202: • Househo themselve: Incident: 0 89.803718	- Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am . the breach = 40 m under PWD Barpather Road Division. latitude-26.474792,long-93.778562 Dipara Dalani Village Active erosion is observed at upstream of protection work at Dipara lage of river Brahmaputra reported by water resource department on 10/10/2022. 0 - Nachankuri no 3 Erosion of around 1000 mtr. at 3 no Nachankuri. 12 Nos. House Damage y kutcha dated 10.10.2022. Total population- 62 0, m - Tinkonia Part II Erosion has been reported at Tinkonia Part II since 08.10.2022 on river anas-Brahmaputra in a length of 100 m Approximately . As a result , 8 nos. of houses have been				
Damaged - Others	Karbi Anglong District Biswanath Bongaigaon	Silonijan Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kalioni(Kali	Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am . he breach = 40 m under PWD Barpather Road Division. latitude-26.474792,long-93.778562 Dipara Dalani Village Active erosion is observed at upstream of protection work at Dipara lage of river Brahmaputra reported by water resource department on 10/10/2022. 0 - Nachankuri no 3 Erosion of around 1000 mtr. at 3 no Nachankuri. 12 Nos. House Damage y kutcha dated 10.10.2022. Total population- 62 0, m - Tinkonia Part II Erosion has been reported at Tinkonia Part II since 08.10.2022 on river anas-Brahmaputra in a length of 100 m Approximately . As a result , 8 nos. of houses have been land shifted to safer place. erosion is still going on 10.10.2022. 0 - Village Kaimari Pt-I and Bholarkhas under Kaimari GP and Chotoguma GP under Agomani e Name of the village: Bholarkhas under Chotoguma GP. Date of Incident: 01/10/2022 to 2 · Time: 3.00PM. • GPS Co-ordinates: Lat: 26.3078053, Long: 89.8036509 • Land: 1B-2K-10L. Id damage: 7 Nos. • Population: 35 Nos. They have shifted their houses to another place by s. • Name of the village: Kaimari Pt-I under Kaimari GP. • Name of River: Gangadhar. • Date of 10/10/2022 to 10/10/2022. • Time: 3.00PM. • GPS Co-ordinates: Lat: 26.307824, Long: • Land: 1B-1K-10L. • Household damage: 14 Nos. • Population: 72 Nos. They have shifted their another place by themselves. 107 In East - 16/177 ORR Grant (Nagaghoolie Kachari Line) As per report received from Water division Dibrugarh, Bank erosion continuing from last 08/09/2022. 1200 m of land eroded till				
Damaged - Others	Karbi Anglong District Biswanath Bongaigaon Dhubri	Silonijan Kalioni(Kı length of t Details Halem - D Dalani Vil Manikpun totally full Srijangra bank of M dismantled Agamoni Rev. Circli 10/10/202 • Househo themselves Incident: 0 89.803718 houses to a Dibrugarl Resource of date (Appr Laharigha Leruamuk Bhuragao	Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am . he breach = 40 m under PWD Barpather Road Division. latitude-26.474792,long-93.778562 Dipara Dalani Village Active erosion is observed at upstream of protection work at Dipara lage of river Brahmaputra reported by water resource department on 10/10/2022. 0 The Nachankuri no 3 Erosion of around 1000 mtr. at 3 no Nachankuri. 12 Nos. House Damage y kutcha dated 10.10.2022. Total population-62 0, Thinkonia Part II Erosion has been reported at Tinkonia Part II since 08.10.2022 on river anas-Brahmaputra in a length of 100 m Approximately . As a result , 8 nos. of houses have been and shifted to safer place. erosion is still going on 10.10.2022. 0 Village Kaimari Pt-I and Bholarkhas under Kaimari GP and Chotoguma GP under Agomani e Name of the village: Bholarkhas under Chotoguma GP. Date of Incident: 01/10/2022 to 2. Time: 3.00PM. GPS Co-ordinates: Lat: 26.3078053, Long: 89.8036509 Land: 1B-2k-10L. Id damage: 7 Nos. Population: 35 Nos. They have shifted their houses to another place by the shifted their houses to another place by 11/10/2022 to 10/10/2022. Time: 3.00PM. GPS Co-ordinates: Lat: 26.307824, Long: Land: 1B-1K-10L. Household damage: 14 Nos. Population: 72 Nos. They have shifted their another place by themselves. 107 The East - 16/177 ORR Grant (Nagaghoolie Kachari Line) As per report received from Water division Dibrugarh, Bank erosion continuing from last 08/09/2022. 1200 m of land eroded till fox). GPS Co-ordinates are 27.31'32.63" N 95.0'41.76"E to 27.31'3.87" N 94.59'22.16" E 223 That - Leruamukh As per report of the Water Resources dept on 10-10-22, erosion is observed at the with max erosion of 3 m. 0, The Lengribori Bhrahmaputra river erosion eroded 3 meter from 07-10-2022 to 09-10-2022 0				
Damaged - Others	Karbi Anglong District Biswanath Bongaigaon Dhubri Dibrugarh	Silonijan Kalioni(Kalioni(Kalioni(Kalioni)) Retails Halem - Dalani Vil Manikpun totally full Srijangra bank of Malioni dismantled Agamoni Rev. Circle 10/10/202. • Househo themselves Incident: 0 89.803718 houses to a Dibrugarl Resource of date (Appri Laharigha Leruamuk Bhuragao Tezpur - 1	Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am . he breach = 40 m under PWD Barpather Road Division. latitude-26.474792,long-93.778562 bipara Dalani Village Active erosion is observed at upstream of protection work at Dipara lage of river Brahmaputra reported by water resource department on 10/10/2022. 0 - Nachankuri no 3 Erosion of around 1000 mtr. at 3 no Nachankuri. 12 Nos. House Damage y kutcha dated 10.10.2022. Total population- 62 0, m - Tinkonia Part II Erosion has been reported at Tinkonia Part II since 08.10.2022 on river anaas-Brahmaputra in a length of 100 m Approximately . As a result , 8 nos. of houses have been and shifted to safer place. erosion is still going on 10.10.2022. 0 - Village Kaimari Pt-I and Bholarkhas under Kaimari GP and Chotoguma GP under Agomani e Name of the village: Bholarkhas under Chotoguma GP. Date of Incident: 01/10/2022 to 2 · Time: 3.00PM. • GPS Co-ordinates: Lat: 26.3078053, Long: 89.8036509 • Land: 1B-2K-10L. ld damage: 7 Nos. • Population: 35 Nos. They have shifted their houses to another place by s. • Name of the village: Kaimari Pt-I under Kaimari GP. • Name of River: Gangadhar. • Date of 10/10/2022 to 10/10/2022. • Time: 3.00PM. • GPS Co-ordinates: Lat: 26.307824, Long: • Land: 1B-1K-10L. • Household damage: 14 Nos. • Population: 72 Nos. They have shifted their another place by themselves. 107 • East - 16/177 ORR Grant (Nagaghoolie Kachari Line) As per report received from Water division Dibrugarh, Bank erosion continuing from last 08/09/2022. 1200 m of land eroded till rox). GPS Co-ordinates are 27.31'32.63" N 95.0'41.76"E to 27.31'3.87" N 94.59'22.16" E 223 at - Leruamukh As per report of the Water Resources dept on 10-10-22, erosion is observed at h with max erosion of 3 m. 0, n - Lengribori Bhrahmaputra river erosion eroded 3 meter from 07-10-2022 to 09-10-2022 0 Koroiani Nepali 10/10/2022. As reported by Water				
Damaged - Others Erosion	Karbi Anglong District Biswanath Bongaigaon Dhubri Dibrugarh Morigaon	Silonijan Kalioni(Kalioni(Kalioni(Kalioni)) Retails Halem - Dalani Vil Manikpun totally full Srijangra bank of Malioni dismantled Agamoni Rev. Circle 10/10/202. • Househo themselves Incident: 0 89.803718 houses to a Dibrugarl Resource of date (Appri Laharigha Leruamuk Bhuragao Tezpur - 1	Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am . he breach = 40 m under PWD Barpather Road Division. latitude-26.474792,long-93.778562 Dipara Dalani Village Active erosion is observed at upstream of protection work at Dipara lage of river Brahmaputra reported by water resource department on 10/10/2022. 0 The Nachankuri no 3 Erosion of around 1000 mtr. at 3 no Nachankuri. 12 Nos. House Damage y kutcha dated 10.10.2022. Total population-62 0, Thinkonia Part II Erosion has been reported at Tinkonia Part II since 08.10.2022 on river anas-Brahmaputra in a length of 100 m Approximately . As a result , 8 nos. of houses have been and shifted to safer place. erosion is still going on 10.10.2022. 0 Village Kaimari Pt-I and Bholarkhas under Kaimari GP and Chotoguma GP under Agomani e Name of the village: Bholarkhas under Chotoguma GP. Date of Incident: 01/10/2022 to 2. Time: 3.00PM. GPS Co-ordinates: Lat: 26.3078053, Long: 89.8036509 Land: 1B-2k-10L. Id damage: 7 Nos. Population: 35 Nos. They have shifted their houses to another place by the shifted their houses to another place by 11/10/2022 to 10/10/2022. Time: 3.00PM. GPS Co-ordinates: Lat: 26.307824, Long: Land: 1B-1K-10L. Household damage: 14 Nos. Population: 72 Nos. They have shifted their another place by themselves. 107 The East - 16/177 ORR Grant (Nagaghoolie Kachari Line) As per report received from Water division Dibrugarh, Bank erosion continuing from last 08/09/2022. 1200 m of land eroded till fox). GPS Co-ordinates are 27.31'32.63" N 95.0'41.76"E to 27.31'3.87" N 94.59'22.16" E 223 That - Leruamukh As per report of the Water Resources dept on 10-10-22, erosion is observed at the with max erosion of 3 m. 0, The Lengribori Bhrahmaputra river erosion eroded 3 meter from 07-10-2022 to 09-10-2022 0				
Damaged - Others	Karbi Anglong District Biswanath Bongaigaon Dhubri Dibrugarh Morigaon Sonitpur	Silonijan Kalioni(Kalioni(Kalioni(Kalioni)) Retails Halem - Dalani Vil Manikpun totally full Srijangra bank of Malioni dismantled Agamoni Rev. Circle 10/10/202. • Househo themselves Incident: 0 89.803718 houses to a Dibrugarl Resource of date (Appri Laharigha Leruamuk Bhuragao Tezpur - 1	Bridge Approach Road Washed Away Approach Causeway of bridge 1/1 on River alioni Buddha Mandir road) was breached by flesh flood on 09/10/2022 at around 3.00 am . he breach = 40 m under PWD Barpather Road Division. latitude-26.474792,long-93.778562 bipara Dalani Village Active erosion is observed at upstream of protection work at Dipara lage of river Brahmaputra reported by water resource department on 10/10/2022. 0 - Nachankuri no 3 Erosion of around 1000 mtr. at 3 no Nachankuri. 12 Nos. House Damage y kutcha dated 10.10.2022. Total population- 62 0, m - Tinkonia Part II Erosion has been reported at Tinkonia Part II since 08.10.2022 on river anas-Brahmaputra in a length of 100 m Approximately . As a result , 8 nos. of houses have been and shifted to safer place. erosion is still going on 10.10.2022. 0 - Village Kaimari Pt-I and Bholarkhas under Kaimari GP and Chotoguma GP under Agomani e Name of the village: Bholarkhas under Chotoguma GP. Date of Incident: 01/10/2022 to 2 · Time: 3.00PM. • GPS Co-ordinates: Lat: 26.3078053, Long: 89.8036509 • Land: 1B-2K-10L. ld damage: 7 Nos. • Population: 35 Nos. They have shifted their houses to another place by s. • Name of the village: Kaimari Pt-I under Kaimari GP. • Name of River: Gangadhar. • Date of 10/10/2022 to 10/10/2022. • Time: 3.00PM. • GPS Co-ordinates: Lat: 26.307824, Long: • Land: 1B-1K-10L. • Household damage: 14 Nos. • Population: 72 Nos. They have shifted their another place by themselves. 107 • East - 16/177 ORR Grant (Nagaghoolie Kachari Line) As per report received from Water division Dibrugarh, Bank erosion continuing from last 08/09/2022. 1200 m of land eroded till rox). GPS Co-ordinates are 27.31'32.63" N 95.0'41.76"E to 27.31'3.87" N 94.59'22.16" E 223 at - Leruamukh As per report of the Water Resources dept on 10-10-22, erosion is observed at h with max erosion of 3 m. 0, n - Lengribori Bhrahmaputra river erosion eroded 3 meter from 07-10-2022 to 09-10-2022 0 Koroiani Nepali 10/10/2022. As reported by Water R				