

FRIMS Assam



Flood Reporting And Information Management System

	Assam Daily Flood Report as on 20-06-2022 at 4:00 PM ticulars Situation as on 20-06-2022 (in last 24 hours)										
Particulars	Situation as	s on 20-06	-2022 (in l	ast 24 hours)							
Rivers flowing above Danger Level (as	Rivers flow level	ving above	danger	Crossing), Kopili (Dha	Beki (Road Bridge), Pagladiya (Nt Road Crossing), Puthimari (Nh Road Crossing), Kopili (Dharamtul), Brahmaputra (Dhubri; Goalpara; Guwahati; Tezpur; Neamatighat)						
per CWC bulletin issued at 8 AM)	Rivers flow flood level	ving above	highest	Kopili (Kampur)							
	No. of Districts Affected			fected Districts	Name of Urban Flood Districts						
District Affected	32	Bongaiga Dhemaji Hasao, C Hojai, K Anglong Lakhimp Nalbari,	aon, Cacha , Dhubri, I Goalpara, C amrup, Ka West, Ka vur, Majuli Sivasagar,	peta, Biswanath, ar, Chirang, Darrang, Dibrugarh, Dima- Golaghat, Hailakandi, amrup (M), Karbi rimganj, Kokrajhar, , Morigaon, Nagaon, , Sonitpur, South r, Tinsukia, Udalguri	Barpeta, Cachar, Darrang, Goalpara, Kamrup (M), Karimganj						
No. Of Revenue Circles Affected	125	,		<u> </u>							
	District	Total	Revenu								
	Bajali	2	Sarupeta	. 0							
	Baksa	5		Baganpara, Barama, Bar	• 1						
	Barpeta	6	Baghbar	, Barpeta, Sarthebari, B	arnagar, Kalgachia, Chenga						
	Biswanat h	4	Gohpur,	Naduar RC part, Biswa	nath, Halem						
	Bongaiga on	3	Boitama	ri, Manikpur, Srijangraı	n						
	Cachar	5	Silchar,	Sonai, Udharbond, Kati	gorah, Lakhipur						
	Chirang	3		dli, Bengtal							
	Darrang	4	Mangalo	loi, Patharighat, Dalgao	n, Sipajhar						
	Dhemaji	4	Dhemaji	, Sissiborgaon, Jonai, G	ogamukh						
Name Of	Dhubri	8	Agamon	i, Chapar, South Salmar	ra Part, Athani, Dhubri, Gauripur, Golakganj, Bilasipara						
Revenue Circles	Dibrugar h	1	Chabua								
Affected	Dima- Hasao	1	Haflong								
	Goalpara	4	Balijana	, Matia, Rongjuli, Lakhi	pur						
	Golaghat	2	Khumta	i, Bokakhat							
	Hailakan di	4	Lala, Al	gapur, Hailakandi, Katli	cherra						
	Hojai	3	Lanka, I	Doboka, Hojai							
	Kamrup	9		Rangia, Kayan, Chamaria, Chaygaon, Kamalpur, Goroimari, Palashbari, Hajo, North Ghy							
	Kamrup (M) 5 Guwahati, Sonapur, Chandrapur, Azara, Dispur										
	Karbi Anglong West	1	Donkam	Donkamokam							

Solution Solution		Varimaan		
Lakkimp		Karimgan j	5	Karimganj, RK Nagar, Nilambazar, Badarpur, Patherkandi
Waishi Care Upais Majuik, Majuik Majuik Morigaon 4		_	2	Bhawraguri, Bagribari
Morigaon 4		_	6	Bihpuria, Dhakuakhana, Kadam, Nowboicha, Subansiri, North Lakhimpur
Nagaon 7 Nagaon, Raha, Samaguri, Kampur, Rupahi, Dhing, Kaliabor Nalibari 7 Ghograpar, Tibu, Paschim Nalibari, Barckuchi, Barckuchi		Majuli	2	Ujani Majuli, Majuli
Nailbari 7 Ghograpar Tibu, Paschim Nalbari, Banekuchi, Barkhetri, Barbhag, Nalbari Sivasagar 2 Sivsagar, Demow South Salmara 2 South Salmara, Naduar, Dhekinjuli, Tezpur South Salmara 2 South Salmara, Mankachar Tamulpur 2 Tamulpur, Goreswar Tinsukia 2 Doomdooma, Tinsukia Udalgari 5 Udalgari 5 Udalgari, Khairabari, Mazbat, Kalaigaon, Harisinga Total 125 Revenue Circle Bajali 173 (Sarupeta 78.), (Bajalil 95) (Baskal 96.) (Baskal 97.) (Bajalil 97.) (Bajalil 97.) (Bagibar 141.), (Barpeta 145.), (Sarthebari 135.), (Barmagar 21.), (Kalgachia 100.), (Chenga 69.) (Gobpur 4.), (Naduar RC part 3.), (Barmagar 8.), (Barmagar 21.), (Kalgachia 100.), (Chenga 69.) (Gobpur 4.), (Naduar RC part 3.), (Biswanath 7.), (Halem 28.) (Boitamari 22.), (Manikpur 2.), (Srijangram 91.) (Garmagar 49.), (Sidatari 16.), (Naduar RC part 3.), (Biswanath 7.), (Halem 28.) (Boitamari 22.), (Manikpur 2.), (Srijangram 91.) (Darangar 49.), (Magadol 165.), (Patharighat 79.), (Dalgaon 142.), (Sipajhar 73.) (Darangar 49.), (Magadol 165.), (Patharighat 79.), (Dalgaon 142.), (Sipajhar 73.) (Darangar 49.), (Gauripur 50.), (Gauripur 50.), (Gauripur 50.), (Gauripur 50.), (Gauripur 60.), (Golakgan 61.), (Alami 120.), (Dhubri 58.), (Gauripur 50.), (Gauripur 50.), (Galakgan 62.), (Bilasipara 201.) (Dimahasa 61.), (Lala 9.), (Algapur 22.), (Matia 76.), (Rongjuli 8.), (Lakhipur 137.) (Barangar 349.), (Barangar 28.), (Matia 76.), (Rongjuli 8.), (Lakhipur 137.) (Barangar 349.), (Barangar 3		Morigaon	4	Morigaon, Bhuragaon, Laharighat, Mayong
Sivasagar 2 Sivasagar 5 Chariduar, Thelamara, Naduar, Dhekiajuli, Tezpur 5 Chariduar, Thelamara, Naduar, Dhekiajuli, Tezpur 5 Chariduar, Thelamara, Naduar, Dhekiajuli, Tezpur 7 7 7 7 7 7 7 7 7		Nagaon	7	Nagaon, Raha, Samaguri, Kampur, Rupahi, Dhing, Kaliabor
South South South South South Salmara Analwar, Dhekiajuli, Tezpur		Nalbari	7	Ghograpar, Tihu, Paschim Nalbari, Banekuchi, Barkhetri, Barbhag, Nalbari
South Salmara 2 South Salmara, Mankachar Tamulpur 2 Tamulpur, Goreswar Tinsukia 2 Doomdooma, Tinsukia 2 Dosmdooma, Tinsukia		Sivasagar	2	Sivsagar, Demow
South Salmara 2 South Salmara, Mankachar Tamulpur 2 Tamulpur, Goreswar Timsukia 2 Doomdooma, Timsukia 2 Doomdoomdooma, Timsukia 2 Doomdooma, Timsukia 2 Doomdooma, Timsukia 2 Doomdooma, Timsuki		Sonitpur	5	Chariduar, Thelamara, Naduar, Dhekiajuli, Tezpur
Finsukia 2			2	South Salmara, Mankachar
Finsukia 2		Tamulpur	2	Tamulpur, Goreswar
Total 125			2	Doomdooma, Tinsukia
Total 125		Udalguri	5	Udalguri, Khairabari, Mazbat, Kalaigaon, Harisinga
Bajali			125	
Bajali		District	Total	Revenue Circle
Baksa 59				(Sarupeta 78), (Bajali 95)
Barpeta				
h 82 Gohpur 4), (Naduar RC part 3), (Biswanath 7), (Halem 28)				(Baghbar 141), (Barpeta 145), (Sarthebari 135), (Barnagar 21), (Kalgachia 100
On		h	42	(Gohpur 4), (Naduar RC part 3), (Biswanath 7), (Halem 28)
Chirang		on		
Darrang 459				
Dhemaji				
Dhubri 671		Darrang	459	
Dibrugar 1		Dhemaji	86	
Nagaon 1			671	
Hasao S Charlong S Goalpara 349 (Balijana 128), (Matia 76), (Rongjuli 8), (Lakhipur 137) Golaghat 38 (Khumtai 4), (Bokakhat 34) Hailakan di		h	1	(Chabua 1)
Villages Affected Golaghat 38 (Khumtai 4), (Bokakhat 34) Hailakan di		Hasao		
Affected Hailakan di (Lala 9), (Algapur 22), (Hailakandi 27), (Katlicherra 3) Hojai 92 (Lanka 16), (Doboka 35), (Hojai 41) Kamrup 361 (Rangia 86), (Kayan 28), (Chamaria 22), (Chaygaon 5), (Kamalpur 100), (Goroimari 37), (Palashbari 15), (Hajo 37), (North Ghy 31) Kamrup (M) 30 (Guwahati 6), (Sonapur 8), (Chandrapur 9), (Azara 2), (Dispur 5) Karbi Anglong West Karimgan j 305 (Karimganj 21), (RK Nagar 97), (Nilambazar 127), (Badarpur 24), (Patherkandi 36) Kokrajha r 106 (Bagribari 106) Lakhimp ur 126 (Bihpuria 18), (Dhakuakhana 7), (Kadam 12), (Narayanpur 12), (Nowboicha 34), (Subansiri 4), (North Lakhimpur 39) Majuli 47 (Ujani Majuli 17), (Majuli 30) Morigaon 230 (Morigaon 71), (Bhuragaon 27), (Laharighat 2), (Mayong 130) Nagaon 269 (Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15), (Kaliabor 2)				
Hojai 92	_		38	(Khumtai 4), (Bokakhat 34)
Kamrup 361 (Rangia 86), (Kayan 28), (Chamaria 22), (Chaygaon 5), (Kamalpur 100), (Goroimari 37), (Palashbari 15), (Hajo 37), (North Ghy 31) Kamrup (M) 30 (Guwahati 6), (Sonapur 8), (Chandrapur 9), (Azara 2), (Dispur 5) Karbi Anglong West (Donkamokam 5) Karimgan j (Karimganj 21), (RK Nagar 97), (Nilambazar 127), (Badarpur 24), (Patherkandi 36) Kokrajha r (Bagribari 106) Lakhimp ur (Bihpuria 18), (Dhakuakhana 7), (Kadam 12), (Narayanpur 12), (Nowboicha 34), (Subansiri 4), (North Lakhimpur 39) Majuli 47 (Ujani Majuli 17), (Majuli 30) Morigaon 230 (Morigaon 71), (Bhuragaon 27), (Laharighat 2), (Mayong 130) Nagaon 269 (Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15), (Kaliabor 2)	Affected	di		
Kamrup 361 Goroimari 37), (Palashbari 15), (Hajo 37), (North Ghy 31)		Hojai	92	-
(M) 30 (Guwanati 8), (Sonapur 8), (Chandrapur 9), (Azara 2), (Dispur 5) Karbi Anglong 5 (Donkamokam 5) West (Karimgan 305 36) (Karimganj 21), (RK Nagar 97), (Nilambazar 127), (Badarpur 24), (Patherkandi 36) Kokrajha r 106 (Bagribari 106) Lakhimp ur 126 (Bihpuria 18), (Dhakuakhana 7), (Kadam 12), (Narayanpur 12), (Nowboicha 34), (Subansiri 4), (North Lakhimpur 39) Majuli 47 (Ujani Majuli 17), (Majuli 30) Morigaon 230 (Morigaon 71), (Bhuragaon 27), (Laharighat 2), (Mayong 130) Nagaon 269 (Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15), (Kaliabor 2)			361	
Anglong West West Starting Starting West West West Starting West W		(M)	30	(Guwahati 6), (Sonapur 8), (Chandrapur 9), (Azara 2), (Dispur 5)
j 305 36) Kokrajha r 106 (Bagribari 106) Lakhimp ur 126 (Bihpuria 18), (Dhakuakhana 7), (Kadam 12), (Narayanpur 12), (Nowboicha 34), (Subansiri 4), (North Lakhimpur 39) Majuli 47 (Ujani Majuli 17), (Majuli 30) Morigaon 230 (Morigaon 71), (Bhuragaon 27), (Laharighat 2), (Mayong 130) Nagaon 269 (Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15), (Kaliabor 2)		Anglong	5	(Donkamokam 5)
Takhimp 126 (Bihpuria 18), (Dhakuakhana 7), (Kadam 12), (Narayanpur 12), (Nowboicha 34 126		Karimgan j	305	
ur 126), (Subansiri 4), (North Lakhimpur 39) Majuli 47 (Ujani Majuli 17), (Majuli 30) Morigaon 230 (Morigaon 71), (Bhuragaon 27), (Laharighat 2), (Mayong 130) Nagaon 269 (Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15), (Kaliabor 2)			106	
Morigaon 230 (Morigaon 71), (Bhuragaon 27), (Laharighat 2), (Mayong 130) Nagaon 269 (Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15), (Kaliabor 2)		-	126	
Nagaon 269 (Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15), (Kaliabor 2)		Majuli	47	(Ujani Majuli 17), (Majuli 30)
Nagaon 269 (Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15), (Kaliabor 2)			230	
				(Nagaon 44), (Raha 87), (Samaguri 7), (Kampur 109), (Rupahi 5), (Dhing 15
		Nalbari	288	(Ghograpar 39), (Tihu 27), (Paschim Nalbari 24), (Banekuchi 16), (Barkhetri 69

), (Barb	hag 37), (Nalbari 76)						
	Sivasagar	13		vsagar 9), (Demow 4) nariduar 32), (Thelamara 33), (Naduar 4), (Dhekiajuli 41), (Tezpur 57)								
	Sonitpur South	167	ì				iekiajuli 41), (1ezpur 5 /)				
	Salmara	75	(South	Salmara 37	7), (Mankac	har 38)						
	Tamulpur	37			Foreswar 28							
	Tinsukia	27 110	`), (Tinsukia		Jaionan I 22) (Harisings 5)				
	Udalguri Total	5424	(Odaigi	III 28), (F	Mairabari 1	3), (Mazbat 32), (Ka	iiaigaoii 32), (Harisiiga 3)				
	Total	0.2.	Б 1	CI 11	Total		Crop					
	District	Male	Femal e	Childre n	Populati on	Population Details	Area (in Hect.)	Crop Area Details				
	Bajali	172115	13510 0	31300	338515	(Sarupeta 178515), (Bajali 160000)	490.00	(Sarupeta 490.00), (Bajali 0.00)				
	Baksa	14650	12884	6216	33750	(Barnagar RC part 19682), (Baska 82), (Baganpara 1233), (Barama 252), (Jalah 12501)	668.33	(Barnagar RC part 410.00), (Baska 21.33), (Baganpara 12.00), (Barama 5.00), (Jalah 220.00)				
	Barpeta	499536	47004 9	261136	1230721	(Baghbar 370497), (Barpeta 158760), (Sarthebari 335837), (Barnagar 12452), (Kalgachia 198692), (Chenga 154483)	28102.50	(Baghbar 18983.00), (Barpeta 875.00), (Sarthebari 2289.00), (Barnagar 1439.00), (Kalgachia 1823.50), (Chenga 2693.00)				
	Biswanat h	6366	5370	4816	16552	(Gohpur 668), (Naduar RC part 0), (Biswanath 138), (Halem 15746)	775.50	(Gohpur 212.00), (Naduar RC part 22.50), (Biswanath 0.00), (Halem 541.00)				
Population And Crop Area Affected	Bongaiga on	50545	46076	49810	146431	(Boitamari 12843), (Srijangram 130808), (Manikpur 2780)	2671.00	(Boitamari 0.00), (Srijangram 2445.00), (Manikpur 226.00)				
	Cachar	80518	74620	52005	207143	(Silchar 42782), (Sonai 61300), (Udharbond 2724), (Katigorah 87119), (Lakhipur 13218)	15.00	(Silchar 0.00), (Sonai 15.00), (Udharbond 0.00), (Katigorah 0.00), (Lakhipur 0.00)				
	Chirang	3417	2697	2099	8213	(Bijni 6129), (Sidli 0), (Bengtal 2084)	2444.90	(Bijni 2444.90), (Sidli 0.00), (Bengtal 0.00)				
	Darrang	199377	16861 9	101245	469241	(Mangaldoi 125007), (Patharighat 77096), (Dalgaon 185900), (Sipajhar 81238)	9347.50	(Mangaldoi 2328.00), (Patharighat 2000.00), (Dalgaon 3795.50), (Sipajhar 1224.00)				
	Dhemaji	14100	12058	8478	34636	(Sissiborgaon 12196), (Jonai 18295), (Gogamukh 1358), (Dhemaji 2787)	9709.50	(Sissiborgaon 885.00), (Jonai 8794.50), (Gogamukh 0.00), (Dhemaji 30.00)				
	Dhubri	115788	93930	81481	291199	(Agamoni 430), (Chapar 690), (South Salmara Part 265395), (Athani	7617.33	(Agamoni 0.00), (Chapar 1018.20), (South Salmara Part 2394.00), (Athani				

					1758), (Dhubri 40		2289.03), (Dhubri
), (Gauripur 0), (Golakganj 1179), (660.50), (Gauripur 596.60), (
					Bilasipara 21707)		Golakganj 659.00), (Bilasipara 0.00)
Dibrugar h	1567	1240	1050	3857	(Chabua 3857)	2.50	(Chabua 2.50)
Goalpara	135673	10266 7	41808	280148	(Balijana 99311), (Matia 9408), (Lakhipur 171429), (Rongjuli 0)	1381.50	(Balijana 762.50), (Matia 614.00), (Lakhipur 0.00), (Rongjuli 5.00)
Golaghat	11878	10977	3677	26532	(Bokakhat 26532), (Khumtai 0)	106.00	(Bokakhat 80.00), (Khumtai 26.00)
Hailakan di	8477	6986	2560	18023	(Lala 5500), (Algapur 6510), (Hailakandi 5150), (Katlicherra 863)	76.00	(Lala 13.00), (Algapur 31.00), (Hailakandi 19.00), (Katlicherra 13.00
Нојаі	44689	34179	10930	89798	(Lanka 10757), (Doboka 27378), (Hojai 51663)	2349.00	(Lanka 815.00), (Doboka 436.00), (Hojai 1098.00)
Kamrup	146778	96911	38555	282244	(Rangia 82230), (Kayan 38122), (Chamaria 0), (Chaygaon 0), (Kamalpur 20972), (Goroimari 0), (Hajo 121438), (Palashbari 590), (North Ghy 18892)	3601.90	(Rangia 798.50), (Kayan 407.00), (Chamaria 95.50), (Chaygaon 144.00), (Kamalpur 468.90), (Goroimari 600.00), (Hajo 620.00), (Palashbari 208.50), (North Ghy 259.50)
Kamrup (M)	4718	3431	491	8640	(Guwahati 759), (Sonapur 5050), (Chandrapur 0), (Azara 981), (Dispur 1850)	436.50	(Guwahati 0.00), (Sonapur 109.50), (Chandrapur 0.00), (Azara 327.00), (Dispur 0.00)
Karbi Anglong West	3605	3605	4878	12088	(Donkamokam 12088)	2.40	(Donkamokam 2.40)
Karimgan j	71565	43721	18579	133865	(RK Nagar 38425), (Badarpur 26920), (Patherkandi 7751), (Karimganj 17569), (Nilambazar 43200)	290.00	(RK Nagar 290.00), (Badarpur 0.00), (Patherkandi 0.00), (Karimganj 0.00), (Nilambazar 0.00)
Kokrajha r	9164	8419	5301	22884	(Bhawraguri 0), (Gossaigaon 0), (Bagribari 22884)	284.49	(Bhawraguri 0.00), (Gossaigaon 0.00), (Bagribari 284.49)
Lakhimp	43743	30846	21629	96218	(Narayanpur 0), (Nowboicha 43094), (North Lakhimpur 28818), (Bihpuria 17756), (Dhakuakhana 1358), (Kadam 0), (Subansiri 5192)	1474.30	(Narayanpur 0.00), (Nowboicha 1040.30), (North Lakhimpur 165.00), (Bihpuria 0.00), (Dhakuakhana 50.00), (Kadam 51.00), (Subansiri 168.00)
Majuli	5765	5025	6607	17397	(Ujani Majuli 0), (Majuli 17397)	819.78	(Ujani Majuli 230.42), (Majuli

Morigaon 32798 30504 20036 83388 (Morigaon 56587), (Bhuragaon 26751), (Mayong 105920) (Ringaon 72100), (Bhuragaon 26751), (Mayong 105920) (Ringaon 72100), (Bhuragaon		Ī			I	I	1		I	500.263
Nagaon		Morigaon	32798	30504	20036	83338), (Bhurag 26751), (0), (Laha	gaon Mayong righat 0)	10592.00	(Morigaon 770.00), (Bhuragaon 721.00), (Mayong 9000.00), (Laharighat 101.00)
Nalburi 80711 70695 33032 184438 184438 18411 30369). (Paschim Nalbari 554.00). (Banckuchi 111.00) 56.400. (Banckuchi 111.00) 156.400. (Charidual 19814.) 1500. (Charidual 19804.) 1500. (Charid		Nagaon	153567		144774	440135	Raha 130 Samaguri Kampur 2 Rupahi 0	0046), (5844), (259500), (), (Dhing	15814.57	(Raha 7047.57), (Samaguri 252.00), (Kampur 7835.00), (Rupahi 160.00), (Dhing 328.00),
South South Salmara Salmara		Nalbari	80711	70695	33032	184438), (Tihu 1 Paschim N 48121), (27760), 11500), (12500), (30369), (Ialbari Banekuchi (Barbhag Nalbari	6176.10), (Tihu 367.00), (Paschim Nalbari 554.00), (Banekuchi 111.00), (Barbhag 83.50), (Nalbari 338.10), (Barkhetri
Sonitpur 27888 25581 27747 81216 (Naduar 0, 0), (Chariduar 59814), (Thelamara 4954), (Dhekiajuli 12228), (Tezpur 4220) 3802.30 (Outh Salmara 3560), (Dhekiajuli 12228), (Tezpur 4220) 2347.70), (Tezpur 732.60) (Outh Salmara 36500), (Outh Salmara 36500		Sivasagar	2846	2752	694	6292			56.00	
South Salmara S2511 47815 50827 151153 139183),		Sonitpur	27888	25581	27747	81216	(Naduar Chariduar (Thelama (Dhekiaju	(Naduar 0), (Chariduar 59814), (Thelamara 4954), (Dhekiajuli 12228		(Naduar 66.00), (Chariduar 0.00), (Thelamara 656.00), (Dhekiajuli 2347.70), (Tezpur
Tamulpur			52511	47815	50827	151153	139183),	(405.00	0.00), (Mankachar 405.00)
Tinsukia 4199 3675 3008 10882 1088		Tamulpur	9535	9029	2015	20579			1710.00), (Goreswar 1310.00)
Udalguri		Tinsukia	4199	3675	3008	10882), (Tinsuk	ia 4521)	1453.53	185.20), (Tinsukia 1268.33)
District Total Relief Camp Relief Distribution Centres		Udalguri	11193	8221	6598	26012	Khairabari Mazbat 3 Kalaigaon	(i 836), ((i 82), ((i 12606),	809.94	Khairabari 48.00), (Mazbat 475.44), (Kalaigaon 246.50),
Bajali 77 46(Sarupeta 9, Bajali 37) 31(Sarupeta 1, Bajali 30)		Total	2	76		4772140			7	
Baksa 13		District								
Relief Camps / Centres Opened Each arright Degrang 14 12(Bijni 10, Bengtal 2) 16(Mangaldoi 5, Patharighat 4, Dalgaon 16(Baghbar 0, Barpeta 0, Sarthebari 6, Chenga 3, Barnagar 7) 16(Baghbar 0, Barpeta 0, Sarthebari 6, Chenga 3, Barnagar 7) 16(Baghbar 0, Barpeta 0, Sarthebari 6, Chenga 3, Barnagar 7) 16(Baghbar 0, Barpeta 0, Sarthebari 6, Chenga 3, Barnagar 7) 16(Baghbar 0, Barpeta 0, Sarthebari 6, Chenga 3, Barnagar 7) 16(Baghbar 0, Barpeta 0, Sarthebari 6, Chenga 3, Barnagar 7) 16(Baghbar 0, Barnagar 1, Manikpur 1, Srijangram 0) 17(Baghbar 1, Manikpur 1, Srijangram 1, Manikpur		Bajali	77					_		
Relief Camps / Centres Deep colspan="4">Degrang 112 15, Chenga 37, Barnagar 0) Chenga 3, Barnagar 7) Relief Camps / Centres Opened Biswanat h 3 0(Biswanath 0) 3(Biswanath 3) Bongaiga on 32 30(Boitamari 2, Manikpur 2, Srijangram 2(Boitamari 1, Manikpur 1, Srijangram 0) Cachar 148 129(Silchar 58, Sonai 14, Udharbond 19(Silchar 0, Sonai 6, Udharbond 0, Katigorah 9, Lakhipur 4) Chirang 14 12(Bijni 10, Bengtal 2) 2(Bijni 0, Bengtal 2) Darrang 99 16(Mangaldoi 5, Patharighat 4, Dalgaon 83(Mangaldoi 55, Patharighat 8, Dalgaon 10, Patharighat 10, Pathar				Barnaga	r RC part (0)		Barnagar I	RC part 5)	
Camps / Centres Opened	Relief		112	_	_	_				
Opened Bongaiga on 32 30(Boitamari 2, Manikpur 2, Srijangram 2, Srijangram 2(Boitamari 1, Manikpur 1, Srijangram 0) Cachar 148 129(Silchar 58, Sonai 14, Udharbond 1, Katigorah 37, Lakhipur 19) 19(Silchar 0, Sonai 6, Udharbond 0, Katigorah 9, Lakhipur 4) Chirang 14 12(Bijni 10, Bengtal 2) 2(Bijni 0, Bengtal 2) Darrang 99 16(Mangaldoi 5, Patharighat 4, Dalgaon 83(Mangaldoi 55, Patharighat 8, Dalgaon 10, Patharighat 10, Patharigh	_		3	0(Biswa	0(Biswanath 0) 3(Biswana			th 3)		
Cachar 148			32	26)	- I // Boilamari I Wanikhiir					
Darrang 99 16(Mangaldoi 5, Patharighat 4, Dalgaon 83(Mangaldoi 55, Patharighat 8, Dalgaon		Cachar	148	,	29(Silchar 58, Sonai 14, Udharbond 19(Silchar 0, Sonai 6, Udharb					
		Chirang	14	12(Bijni	10, Bengt	al 2)		_		
			99	16(Mang	galdoi 5, P		4, Dalgaon	83(Manga	ldoi 55, Patl	

	Dhemaji	6	0(Jonai 0, Gogamukh 0)		6(Jonai 4	, Gogamukh	[2]		
	Dhubri	37	37(Chapar 2, Athani 4, Dhubr Golakganj 1, Bilasipara 29)	i 1,	0(Chapar	0, Athani	, Dhubri 0,		
	Dima- Hasao	30	25(Haflong 25)		5(Haflong	(5)			
	Goalpara	105	64(Balijana 28, Matia 6, Lakh	ipur 30)	41(Balijan	a 11, Matia	0, Lakhipuı	r 30)	
	Golaghat	9	0(Bokakhat 0)	9(Bokakha	at 9)				
	Hailakan di	30	5(Algapur 3, Katlicherra 2, La Hailakandi 0)		25(Algapur 1, Katlicherra 3, Lala 13, Hailakandi 8)				
	Hojai	78	48(Doboka 14, Hojai 34, Lanl		30(Doboka 19, Hojai 6, Lanka 5)				
	Kamrup	80	50(Rangia 18, Kayan 1, Kama Hajo 10, North Ghy 4)	alpur 17,	30(Rangia	1, Kayan 4 Ghy 4)	4, Kamalpur	15, Hajo	
	Kamrup (M)	5	2(Guwahati 2)		3(Guwaha	ti 3)			
	Karbi Anglong West	4	0(Donkamokam 0)		4(Donkam	nokam 4)			
	Karimgan j	98	40(Karimganj 19, Badarpur 19 Patherkandi 3, RK Nagar 0, N 0)	ilambazar	8, RK Na	ganj 0, Bada ngar 25, Nila	ambazar 13)		
	Lakhimp ur	27	0(Bihpuria 0, Dhakuakhana 0, Nowboicha 0, Subansiri 0, No Lakhimpur 0)		Nowboich Lakhimpu		iri 6, North		
	Morigaon	20	0(Morigaon 0, Bhuragaon 0)			on 5, Bhura			
	Nagaon	127	50(Nagaon 22, Raha 11, Kam Samaguri 0)	•	Samaguri		-		
	Nalbari	107	105(Tihu 20, Paschim Nalbari Banekuchi 14, Barkhetri 1, Ba 20, Nalbari 29, Ghograpar 0)	•	2(Tihu 0, Paschim Nalbari 0, Banekuchi 0, Barkhetri 0, Barbhag 0, Nalbari 1, Ghograpar 1)				
	Sonitpur	26	2(Chariduar 1, Dhekiajuli 1, T 0, Tezpur 0)		24(Charid 4, Tezpur	uar 6, Dheki 11)	iajuli 3, The	elamara	
	Tamulpur	52	22(Tamulpur 14, Goreswar 8)			pur 12, Gore			
	Tinsukia	20	1(Doomdooma 1, Tinsukia 0)		19(Doomdooma 1, Tinsukia 18)				
	Udalguri	66	25(Udalguri 10, Mazbat 7, Ka 3, Harisinga 5, Khairabari 0)	llaigaon	41(Udalguri 25, Mazbat 0, Kalaigaon 12, Harisinga 0, Khairabari 4)				
	Total	1425	810		615		D (ъ	
	District	Total	Revenue Circlewise	Male	Female	Children	Pregnant / Lactatin	Person with Disabili	
							g Mother	ty	
	Bajali	5718	(Sarupeta 1702), (Bajali 4016)	2417	2644	571	77	9	
	Baksa	277	(Barnagar RC part 0), (Jalah 0), (Baska 40), (Baganpara 148), (Barama 89)	98	133	44	2	0	
Inmates In Relief Camps	Barpeta	62477	(Barpeta 55933), (Sarthebari 2841), (Barnagar 0), (Kalgachia 0), (Chenga 1180), (Baghbar 2523)	15796	26614	19916	146	5	
Cumps	Bongaiga on	8430	(Boitamari 656), (Srijangram 7021), (Manikpur 753)	3889	3419	1033	89	0	
	Cachar	19433	(Silchar 10468), (Sonai 1823), (Udharbond 44), (Katigorah 4463), (Lakhipur 2635)	8364	7151	3915	1	2	
	Chirang	3831	(Sidli 0), (Bijni 3090), (Bengtal 741)	1693	1382	691	60	5	
	Darrang	5033	(Mangaldoi 1227), (Patharighat 572), (Dalgaon 1670), (Sipajhar 1564)	1870	1915	1214	29	5	

	Dhubri	6990	(Dhubri (Bilasipa	ni 0), (Atha 40), (Gaur ara 6171), olakganj 6	ripur 0), (Chapar	2168	2974	1828	20	0
	Dima- Hasao	1609	(Haflong	g 1609)		568	601	383	56	1
	Goalpara	19503	1673), (1	(Balijana 8622), (Matia 1673), (Rongjuli 0), (Lakhipur 9208)			6709	4084	175	26
	Hailakan di	674	(Lala 0), (Hailakandi 0), (Algapur 429), (Katlicherra 245)			330	175	153	16	0
	Hojai	35383	(Lanka (Doboka	0), (Hojai a 3419)	31964),	18894	15513	970	5	1
	Kamrup	8973	0), (Cha 2450), (Palashb	2419), (Ch ygaon 0), ((Goroimari pari 0), (Ha 163), (Nort	(Kamalpur 0), jo 3387),	3907	3216	1777	66	7
	Kamrup (M)	23		r 0), (Chan ra 0), (Disp ati 23)		9	11	3	0	0
	Karimgan j	10911	1523), (gar 0), (Bac Karimganj tandi 85)		4413	4361	2134	3	0
	Nagaon	12912	(Dhing (Nagaon	ıri 0), (Rup 0), (Kaliabo ı 7638), (R Kampur 41	or 0), aha	4820	4420	3550	110	12
	Nalbari	23200	(Paschin (Baneku	par 0), (Til n Nalbari 1 chi 1763), arbhag 174 5500)	0914), (Barkhetri	10422	9226	3245	284	23
	Sonitpur	287	,	ıar 117), (7 kiajuli 170	•	112	108	61	6	0
	Tamulpur	2923	(Tamulp	our 1512), ((Goreswar	927	923	1073	0	0
	Tinsukia	54	(Tinsuki 54)	a 0), (Doo	mdooma	25	12	15	2	0
	Udalguri	3178	280), (U	oari 0), (Ma dalguri 16 non 540), (l	15),	1245	1246	592	95	0
	Total	231819				90476	92753	47252	1242	96
	District	Total	Male	Female	Children		Circlewise	:mum (0) (0'1	aham I O) (C	mai 1)
	Cachar	1	1	0	0	(Udharboi	nd 0)		char 0), (So	
	Darrang	3	3	3 0 0		(Dalgaon 1)	1), (Manga	ldoi 1), (Pa	tharighat 0),	(Sipajhar
Human Lives Lost	Dibrugar h	1	0 1 0		(Chabua	1)				
- Confirmed	Hailakan di	1	0	0	1	(Algapur	0), (Hailak	andi 1), (Ka	tlicherra 0),	(Lala 0)
	Hojai	1	1	0	0			1), (Lanka 0		
	Kamrup	1	0	0	1	0), (Kama (Palashba	lpur 0), (K ri 0), (Rang	ayan 0), (No gia 1)	oroimari 0), orth Ghy 0),	
	Lakhimp	1	1	0	0	(Bihpuria	0), (Dhaku	akhana 0),	(Kadam 1),	

	ur					(Narayanpur 0), (North Lakhimpur 0), (Nowboicha 0), (Subansiri 0)
	Nagaon	2	2	0	0	(Dhing 0), (Kaliabor 0), (Kampur 2), (Nagaon 0), (Raha 0), (Rupahi 0), (Samaguri 0)
	Total	11	8	1	2	(
	District	Total	Flood Death	General Drowni ng (Non Flood)	Landslide	
	Cachar	1	1	0	0	
11	Darrang	3	3	0	0	
Human Lives Lost Confirmed	Dibrugar h	1	1	0	0	
- Death Type	Hailakan di	1	1	0	0	
	Hojai	1	1	0	0	
	Kamrup	1	1	0	0	
	Lakhimp ur	1	0	1	0	
	Nagaon	2	2	0	0	
	Total	11	10	1	0	D . 1
	District	Total	Male	Female	Children	Details (Charles of the control of t
	Cachar	1	1	0	0	(Katigorah 0), (Lakhipur 0), (Silchar 1), (Sonai 0), (Udharbond 0)
Human	Darrang	1	1	0	0	(Dalgaon 0), (Mangaldoi 1), (Patharighat 0), (Sipajhar 0)
Lives Lost - Missing	Kamrup	2	1	0	1	(Chamaria 0), (Chaygaon 0), (Goroimari 0), (Hajo 0), (Kamalpur 0), (Kayan 0), (North Ghy 1), (Palashbari 0), (Rangia 1)
	Tamulpur	1	1	0	0	(Goreswar 0), (Tamulpur 1)
	Udalguri	2	1	0	1	(Harisinga 0), (Kalaigaon 0), (Khairabari 1), (Mazbat 0), (Udalguri 1)
	Total	7	5	0	2	
	District	Total	Flood	Non Floo	d	
TT	Cachar	1	1	0		
Human Lives Lost	Darrang	1	1	0		
Missing -	Kamrup	2	2	0		
Type	Tamulpur	1	1	0		
Турс	Udalguri	2	2	0		
	Total	7	7	0		
	District	Total	Big	Small	Poultry	
	Bajali	96740	55863	28427	12450	
	Baksa	11278	5364	3762	2152	
	Barpeta	812849	35028 3	161571	300995	
	Biswanat h	34649	24689	9960	0	
	Bongaiga on	77126	49379	27747	0	
Animals	Cachar	112320	74152	15898	22270	
Affected	Chirang	7245	3590	2240	1415	
	Darrang	341023	16866	89549	82808	
	Dhemaji	30792	19193	11599	0	
	Dhubri	380926	23377 5	147151	0	
	Goalpara	68681	43525	12976	12180	
	Golaghat	420	350	70	0	
	Hailakan di	13564	4565	2359	6640	

	Hojai	91122	26200	20422	44500					
	Kamrup	265651	21279 3	35075	17783					
	Kamrup (M)	35857	15313	8044	12500					
	Karimgan j	1200	1200	0	0					
	Kokrajha r	36656	12967	5689	18000					
	Lakhimp ur	34670	20318	9480	4872					
	Morigaon	94299	26116	6681	61502					
	Nagaon	88059	48741	28462	10856					
	Nalbari	300130	12989 4	109135	61101					
	Sonitpur	11270	7596	3674	0					
	South Salmara	285895	11428 7	79087	92521					
	Tamulpur	142132	37614	26396	78122					
	Udalguri	9772	4972	3978	822			-		
	Total	338432 6	16914 05	849432	843489					
	District	Total	Big	Small	Poultry					
	Baksa	3	0	3	0					
Animals	Barpeta	1	0	1	0					
Washed	Nagaon	5200	0	0	5200					
Away	Nalbari	26	5	21	0					
	Udalguri	2	2	0	0					
	Total	5232	7	25	5200		1	1	1	
		Fully	Fully	Fully	Partially	Partially	Partially	Others	Others	Others
	District	Kucch	•	•	I di tidiij	I al clair	I di tidilij	Cincib	Cattle	
	District		Pukka	Total	Kuccha	Pukka	Total	Huts		Total
		a	Pukka	Total	Kuccha	Pukka	Total	Huts	Shed	Total
	Biswanat h	a 0	Pukka 0	0	2	0	2	0	Shed 0	0
	Biswanat h Chirang	a 0 2	0	0 3	2	0 2	2 2	0	Shed 0 0	0
	Biswanat h Chirang Darrang	a 0 2 35	0 1 0	0 3 35	2 0 0	0 2 0	2 2 0	0 0 0	0 0 0	0 0 0
Houses	Biswanat h Chirang Darrang Goalpara	a 0 2	0	0 3	2	0 2	2 2	0	Shed 0 0	0
Houses Damaged	Biswanat h Chirang Darrang	a 0 2 35	0 1 0	0 3 35	2 0 0	0 2 0	2 2 0	0 0 0	0 0 0	0 0 0
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur	a 0 2 35 0	0 1 0 0	0 3 35 0	2 0 0 19	0 2 0 0	2 2 0 19	0 0 0 0	Shed 0 0 0 0 0	0 0 0 0
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara	a 0 2 35 0 15 4	0 1 0 0 0 0	0 3 35 0 15 4	2 0 0 19 160 2 32	0 2 0 0 0 4 5	2 2 0 19 160 6 37	0 0 0 0 0 0 1 47	Shed 0 0 0 0 0 0 0 17	0 0 0 0 0 0 1 64
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara Tamulpur	a 0 2 35 0 15	0 1 0 0 0 0 0	0 3 35 0 15 4 0	2 0 0 19 160 2 32	0 2 0 0 0 4 5	2 0 19 160 6 37	0 0 0 0 0 0 1 47	Shed 0 0 0 0 0 0 17 0	0 0 0 0 0 0 1 64
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara Tamulpur Tinsukia	a 0 2 35 0 15 4 0 56 1	0 1 0 0 0 0 0 0	0 3 35 0 15 4 0 56	2 0 0 19 160 2 32 12 0	0 2 0 0 0 4 5	2 0 19 160 6 37 12 0	0 0 0 0 0 1 47 0	Shed 0 0 0 0 0 0 17 0 0	0 0 0 0 0 1 64 0
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara Tamulpur Tinsukia Udalguri	a 0 2 35 0 15 4 0 56 1 8	0 1 0 0 0 0 0 0 0	0 3 35 0 15 4 0 56 1 12	2 0 0 19 160 2 32 12 0	0 2 0 0 0 4 5 0 0	2 0 19 160 6 37 12 0	0 0 0 0 0 1 47 0 0	Shed 0 0 0 0 0 0 17 0 0 0 0	0 0 0 0 0 1 64 0 0
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara Tamulpur Tinsukia	a 0 2 35 0 15 4 0 56 1	0 1 0 0 0 0 0 0	0 3 35 0 15 4 0 56	2 0 0 19 160 2 32 12 0	0 2 0 0 0 4 5	2 0 19 160 6 37 12 0	0 0 0 0 0 1 47 0	Shed 0 0 0 0 0 0 17 0 0 0 17	0 0 0 0 0 1 64 0
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara Tamulpur Tinsukia Udalguri	a 0 2 35 0 15 4 0 56 1 8	0 1 0 0 0 0 0 0 0	0 3 35 0 15 4 0 56 1 12	2 0 0 19 160 2 32 12 0	0 2 0 0 0 4 5 0 0	2 0 19 160 6 37 12 0	0 0 0 0 0 1 47 0 0	Shed 0 0 0 0 0 0 17 0 0 0 0	0 0 0 0 0 1 64 0 0
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara Tamulpur Tinsukia Udalguri Total District	a 0 2 35 0 15 4 0 56 1 8 121	0 1 0 0 0 0 0 0 0	0 3 35 0 15 4 0 56 1 12	2 0 0 19 160 2 32 12 0 0 227 Boats Deploye d	0 2 0 0 0 0 4 5 0 0 0 0 11 Person Evacuat ed By Boats	2 2 0 19 160 6 37 12 0 0 238 Animal Evacuat ed By Boats	0 0 0 0 0 1 47 0 0 0 48 Helicopte rs Deployed	Shed	0 0 0 0 0 0 1 64 0 0 0 0 65 Medica l Team Deploy
	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara Tamulpur Tinsukia Udalguri Total	a 0 2 35 0 15 4 0 56 1 8 121 Agency	0 1 0 0 0 0 0 0 0 0 0 4 5	0 3 35 0 15 4 0 56 1 12 126	2 0 0 19 160 2 32 12 0 0 2 27 Boats Deploye	0 2 0 0 0 4 5 0 0 0 11 Person Evacuat ed By	2 0 19 160 6 37 12 0 0 238 Animal Evacuat ed By	0 0 0 0 0 1 47 0 0 0 48 Helicopte	Shed	0 0 0 0 0 0 1 64 0 0 0 0 65 Medica l Team Deploy ed
Damaged	Biswanat h Chirang Darrang Goalpara Lakhimp ur Sonitpur South Salmara Tamulpur Tinsukia Udalguri Total District	a 0 2 35 0 15 4 0 56 1 8 121 Agency NDRF Circle Of Administ Army/Pa NDRF, Steam dep conducte Sutirpath	0 1 0 0 0 0 0 0 0 4 5	0 3 35 0 15 4 0 56 1 12 126 1 force, erinary nos., camp ss(Amguri, alli,	2 0 0 19 160 2 32 12 0 0 227 Boats Deploye d	0 2 0 0 0 0 4 5 0 0 0 0 11 Person Evacuat ed By Boats	2 2 0 19 160 6 37 12 0 0 238 Animal Evacuat ed By Boats	0 0 0 0 0 1 47 0 0 0 48 Helicopte rs Deployed	Shed	0 0 0 0 0 0 1 64 0 0 0 0 65 Medica l Team Deploy ed

	G: 1 0 00	1		1			
Bongaiga on	Circle Office/Local Administration, Local People, Country Boat, Engine Boat	19	0	0	0	0	1
Cachar	Army/Paramilitary force, Circle Office/Local Administration, Civil Defence/Trained Volunteers, Fire & Emergency Services (F&ES), Local People, NDRF, Police, SDRF, Water Resources Department	14	654	6	0	0	19
Chirang		3	0	0	0	0	11
Darrang	Army/Paramilitary force, Local People, NDRF, SDRF, Civil Defence/Trained Volunteers, Police	21	500	0	0	0	12
Dhubri	Circle Office/Local Administration	31	172	182	0	0	8
Dima- Hasao	Civil Defence/Trained Volunteers, Fire & Emergency Services (F&ES), Police, SDRF, NHAI, PWRD	0	0	0	0	0	15
Goalpara		0	0	0	0	0	19
Hailakan di		0	0	0	0	0	8
Hojai	Army/Paramilitary force, Fire & Emergency Services (F&ES), Country Boats, Local People, NDRF, SDRF	51	2357	412	0	0	12
Kamrup	Circle Office/Local Administration, Fire & Emergency Services (F&ES), Local People, NDRF, SDRF, Army/Paramilitary force, Assam Mountain Association	28	448	60	0	0	28
Karimgan j	SDRF	15	325	4	0	0	5
Lakhimp ur		0	0	0	0	0	5
Morigaon	2 Machine boat deployed for relief material distribution	2	0	0	0	0	5
Nagaon	Fire & Emergency Services (F&ES), SDRF, Circle Office/Local Administration, Local People	24	2618	1164	0	0	9
Nalbari	NDRF, SDRF, Circle Office/Local Administration, Army/Paramilitary force	9	192	33	0	0	13
Sonitpur	-	0	0	0	0	0	3
South Salmara	Circle Office/Local Administration	8	127	84	0	0	0
Tamulpur	NDRF, SDRF, Rescue operation done by NDRF on 19/6/22 village Borbilla persons rescued 46	3	0	0	0	0	0
Udalguri	Fire & Emergency Services (F&ES), NDRF, Local	4	0	0	0	0	11

		People, S	DRF							
	Total				295	11292	27086	0	0	186
	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed	l - Rice Bra	n (in Q)
	Bajali	1105.9 8	466.95	117.21	6472.29	0.00	1279.30	0.00		
	Baksa	71.64	29.62	8.88	152.46	0.00	0.00	0.00		
	Barpeta	1281.8 9	232.34	69.70	0.00	0.00	841.00	0.00		
	Biswanat h	2.25	0.41	0.12	12.42	0.00	506.16	0.00		
	Bongaiga on	608.71	114.70	34.62	2966.26	0.00	890.40	0.00		
	Cachar	577.20	148.60	42.19	4504.12	0.00	0.00	0.00		
	Chirang	88.95	17.15	5.35	536.11	70.00	0.00	0.00		
	Darrang	2243.0	406.27	125.30	11949.00	0.00	0.00	1413.00		
	Dhemaji	0.00	0.00	0.00	0.00	0.00	889.24	0.00		
	Dhubri	136.73	25.20	7.58	757.65	0.00	8300.03	0.00		
	Dibrugar h Dima-	0.00	0.00	0.00	0.00	0.00	137.09	0.00		
	Hasao	23.12	2.20	0.79	110.00	0.00	0.00	0.00		
	Gologhat	117.65	21.63	6.49	649.00	0.00	130.00	0.00		
Relief	Golaghat Hailakan	65.74 154.10	12.10 30.34	3.63 8.63	363.24 863.11	0.00	0.00	0.00		
Distributed	di Hojai	180.00	31.50	6.49	420.00	0.00	23.50	15.00		
	Kamrup	1486.6	284.21	70.25	7724.83	0.00	5405.89	0.00		
	Kamrup	0.00	0.00	0.00	0.00	0.00	200.00	0.00		
	(M) Karbi Anglong West	94.16	18.13	5.44	543.96	0.00	0.00	0.00		
	Karimgan j	928.22	179.19	54.13	3668.73	0.00	0.00	0.00		
	Kokrajha r	0.00	0.00	0.00	0.00	0.00	120.00	0.00		
	Lakhimp ur	1492.5 7	276.33	82.29	8228.69	0.00	0.00	282.85		
	Morigaon	1142.1 0	206.45	61.93	0.00	0.00	400.00	0.00		
	Nagaon	1472.8 2	270.11	80.89	0.00	0.00	548.00	0.00		
	Nalbari	986.65	216.44	66.19	6619.00	0.00	0.00	0.00		
	Sonitpur South	151.85	27.81	8.36	0.00	0.00	64.40	0.00		
	Salmara	0.00	0.00	0.00	0.00	0.00	6318.00	0.00		
	Tamulpur Tinsukia	509.53 122.37	94.90 23.24	28.47 6.98	257.66 51.53	0.00	1488.39 0.00	0.00		
	Udalguri	240.50	44.93	13.59	908.61	0.00	18.00	476.50		
	Total	15284. 39	3180.7 5	915.50	57758.67	70.00	27559.4 0	2187.35		
Relief Distributed	District	Baby Fo		Baby Foo	d Solid	Others	U			
Others	Bajali	0.00-ml,	0.00-Q	50.00-Pkt		candle-20.	00-Pkt; M.C	Coil-20.00-Pk	t; Match Bo	x-2.00-

			Pkt; Tarpaulin-10140.00-Pieces
Baksa	0.00-Pkt, 0.00-Q	0.00-Pkt, 0.00-Q	Mother Horlicks -10.00-Pkt; Children Horlicks -40.00-Pkt; Sanitary Napkins-368.00-Pkt; Biscuit-1080.00-Q; Candel-1080.00-Q
Barpeta	0.00-Q	0.00-Q	wheat bran -1800.00-Q; Tarpauline sheets-20000.00-Pieces; Hnad Tube wells-168.00-Pieces; 0-0.00-Q; Drinking water-2250.00-L; Hand Tube well-12.00-Pieces
Biswanat h	0.00-Q	0.00-Q	
Bongaiga on	957.00-Pkt	1728.00-Pieces, 2133.00-Pkt	Tarpaulin-3100.00-Pieces; Sanitary Pad-348.00-Pkt; horlicks-186.00-Pkt
Cachar	0.00-Q	0.00-Q	Candle-484.00-Pkt; Match Box-484.00-Pkt; Mortien-484.00-Pkt; 0-0.00-Q; Cooked Food packet -44.00-Pkt
Chirang	0.00-Q	8.00-Pkt, 0.00-Q	Tarpaulin-662.00-Pieces; Mosquito Net-61.00-Pieces
Darrang	0.00-Q	460.00-Pkt, 0.00-Q	taurpaulin-500.00-Pieces; Tarpaulin-6000.00-Pieces; Candles-400.00-Pkt; Biscuit-50.00-Pkt; 0-0.00-Q
Dhemaji	0.00-Q	0.00-Q	Bleaching powder-450.00-Pkt; chemical Packet-250.00-Pkt; Halogen/ NaDDC Tablets-9000.00-Pieces; Tarpulin-124.00-Pieces
Dhubri	0.00-Q, 588.00- Pkt	0.00-Q	CHIRA-1.29-Q; GUR-1.29-Q; Temporary Toilet-6.00-Pieces; Temporary Bathroom-5.00-Pieces; Temporary HTW-3.00-Pieces; Water Bottle -500.00-Pieces; HTW-60.00-Pieces; Tarpaulin -80.00-Pieces; chira-19.04-Q; gur-10.50-Q; M.coil, Candle, M.box-1787.00-Q; Sanitary napkin-3336.00-Pieces; Tarpaulin/Polythine sheet-10196.00-Pieces; Temporary Toilet Constructed-4.00-Pieces; Temporary Bathroom Constructed-37.00-Pieces; Water Bottle(1lit) Distributed-3650.00-Pieces; Water Pouches Distributed-12500.00-Pieces; Bleaching Packet Distributed-4000.00-Pieces; Art paper, Pencil, Eraser Colour box -105.00-Pieces; Small Toys -35.00-Pieces
Dibrugar h	0.00-Q	0.00-Q	Tarpaulin sheets-45.00-Q
Dima- Hasao	0.00-Q	0.00-Q	Haldi-79.00-Pkt; Milk-79.00-L; Potato-9.48-Q; Onion-3.98-Q; Candle-228.00-Pkt; Match Box-292.00-Pkt; Mosquito Net-76.00-Pieces; Battery-152.00-Pieces; Torch-156.00-Pieces
Goalpara	0.00-Q	0.00-Q	Candle-2591.00-Pkt; Mosquito Coil-2414.00-Pkt; Match box-308.00-Pkt; Bleaching Powder-5.00-Kg
Golaghat	0.00-Q	0.00-Q	-
Hailakan di	1022.00-Pkt, 0.00-Q	0.00-Q, 20.00-Pkt	Sanitary Napken-130.00-Pkt; Sanitary Napkin-194.00-Pkt; Candle-230.00-Pkt; Match Box-300.00-Pieces
Hojai	0.00-Q	0.00-Q	Amual -420.00-L; Water -420.00-L; Sanitary Pads - 10.00-Pkt; Candle-175.00-Pkt; Bleching Powder-10.00- Pkt; Sanitary Pad-75.00-Pkt; Bleaching Powder (500 gm) Per pkt-75.00-Pkt; Tarpaulin-140.00-Pieces; Water Bottle-216.00-L; Sanitary Napkin-90.00-Pkt; Chira- 15.00-Q; Gur-2.20-Q; Biscuit-125.00-Pkt; Bleaching Powder (500Gm per Pkt)-90.00-Pkt
Kamrup	0.00-Q, 850.00- Pkt	0.00-Q, 850.00-Pkt	Tarpaulin-3050.00-Pieces; Mosquito Coil-100.00-Pkt; Plates & Glass-2000.00-Pieces; Sanitay Napkin-20.00- Pkt; 0-0.00-Q
Kamrup (M)	0.00-Q	0.00-Q	Tarpoulin-360.00-Pieces
Karbi Anglong West	0.00-Q	0.00-Q	
Karimgan j	295.00-Pkt, 0.00- Q	0.00-Q	CHIRA-4.00-Q; GUR-10.00-Q; Candle-15.00-Pkt; Mosquito Coil-20.00-Pkt; Napkin-30.00-Pkt
Kokrajha	441.00-Pkt, 0.00-	220.50-Kg, 0.00-Q	Sanitary Napkins-349.00-Pkt; Tarpaulin-2500.00-Pieces

1	r	Q					
	Lakhimp	0.00-Q		1745.00-Pkt, 61.00- Pieces, 0.00-Q	CONCENTRATED CATTLE FEED GODREJ SUPREME-53.50-Q; TARPAULIN-560.00-Pieces		
	Morigaon	0.00-Q		0.00-Q	Hand Tubewell-30.00-Pieces; Tarpuline-3000.00-Pieces		
	Nagaon	3412.00-Pkt, 0.00-Q		4792.00-Pkt, 0.00-Q	Tube Well-4.00-Pieces; Halogen tablets-3000.00-Q; Mosquito Coil-100.00-Pkt; Candle-100.00-Pkt; HTW- 2.00-Pieces; Drinking Water-11000.00-Pkt; Helogen Tablet-2000.00-Pieces		
	Nalbari	0.00-Q		157.00-Pkt, 0.00-Q	Tarpaulin-160.00-Pkt; sanitary paid-3500.00-Pkt; tarpulin-340.00-Pkt; tarpaulin -1155.00-Pkt; Terpolin - 1600.00-Pkt; Sanitary Paid -1000.00-Pkt; Coil-330.00-Pkt; Candle -330.00-Pkt; Match Box -400.00-Pkt; whaet bran-240.00-Q; tarpaulin-261.00-Pkt		
	Sonitpur	0.00-Q		0.00-Q, 40.00-Pkt	TARPAULIN-50.00-Pieces		
	South Salmara	0.00-Q		0.00-Q	0-0.00-Q		
	Tamulpur	0.00-L, 0	.00-Q	0.00-Kg, 0.00-Q	0-0.00-Kg		
	Tinsukia	0.00-Q		0.00-Q			
	Udalguri	0.00-Q, 1 Pkt	42.00-	1016.00-Pkt, 0.00-Q	Sanitary Pad-1992.00-Pkt; Tarpaulin-950.00-Pieces; Blanket-535.00-Pieces; Mosquito Net-350.00-Pieces; candle-230.00-Pkt; Match Box-40.00-Pkt; sanitary Pad- 140.00-Pkt; tarpauline-89.00-Pieces; Geobags-300.00- Pieces		
	District	Numb er	Details				
Infrastruct ure Damaged -	Darrang	1	breached	Patharighat - DUNI FIS under Irrigation Deptt Pandaghat Afflux bundh of Duni FIS breached at Ch 800 mt as reported by JE Irrigation on 20.6.22 (Long - 91.808914, Lat - 26.490462)			
Embankm ent Breached	Lakhimp ur	1	Romjan Mahghu	chuburi to subed chubu	o subed chuburi Singra River Side Bund Uttar Mahghuli ri Singra River Side Bund breached (approx 50Mtr) at Uttar t received from Nowboicha Block Development Office. 00)		
	Total	2					
	District	Numb er	Details				
	Bajali	1	Dalorpat	thar Reported by SDO	a R/B embankment,16 KM at Dalorpathar village :		
Infrastruct ure				300, Lat - 26.530000)	, Water Resource Department, Bajali on 20/6/2022. (Long		
ure	Bongaiga on	2	Dangtol Embank Bongaig Boitama at 2nd K	- Mulagaon Chengmari ment damaged at 4th, 5t aon date-20.06.2022 (I ari - Pachagaon to Dakh M. as per report receive	Road at Panchapur Bridge approach Chengmari th & 6th KM. as per report received from PWRD, Long - 90.497923, Lat - 26.417318), apara Road Pachagaon Embankment damaged partially d from PWRD, Bongaigaon date- 20.06.2022 (Long -		
		2	Dangtol Embank Bongaig Boitama at 2nd K 90.46912 Bokakh CH 1900	- Mulagaon Chengmari ment damaged at 4th, 5t aon date-20.06.2022 (I ari - Pachagaon to Dakh M. as per report receive 29, Lat - 26.334561) at - Brahmaputra Dyke 00 m Breach like dama	Road at Panchapur Bridge approach Chengmari th & 6th KM. as per report received from PWRD, Long - 90.497923, Lat - 26.417318), apara Road Pachagaon Embankment damaged partially		
ure Damaged - Embankm ent	on		Dangtol Embank Bongaig Boitama at 2nd K 90.46912 Bokakh CH 1900 overtopp Nilamba 20/06/20 the toe o	- Mulagaon Chengmari ment damaged at 4th, 5t aon date-20.06.2022 (I ari - Pachagaon to Dakh M. as per report receive 29, Lat - 26.334561) at - Brahmaputra Dyke 00 m Breach like dama bing for a length of 20.00 azar - Abdullapur left be 122 around 185 meter ref the embankment along	Road at Panchapur Bridge approach Chengmari th & 6th KM. as per report received from PWRD, Long - 90.497923, Lat - 26.417318), apara Road Pachagaon Embankment damaged partially of from PWRD, Bongaigaon date- 20.06.2022 (Long - from KRF boundary to Diffaloo Pathar Sukani Gaon at ge of embankment is occured at ch 19000 m due to		
ure Damaged - Embankm ent	on Golaghat Karimgan j Nalbari	1 1	Dangtol Embank Bongaig Boitama at 2nd K 90.46912 Bokakh CH 1900 overtopp Nilamba 20/06/20 the toe o at Abdul Barbha	- Mulagaon Chengmari ment damaged at 4th, 5t aon date-20.06.2022 (I ari - Pachagaon to Dakh M. as per report receive 29, Lat - 26.334561) at - Brahmaputra Dyke 00 m Breach like dama bing for a length of 20.00 azar - Abdullapur left be 022 around 185 meter re f the embankment along lapur area. (Long - 92.00 g - L/B of River Baralia partment breach length	Road at Panchapur Bridge approach Chengmari th & 6th KM. as per report received from PWRD, Long - 90.497923, Lat - 26.417318), apara Road Pachagaon Embankment damaged partially the from PWRD, Bongaigaon date- 20.06.2022 (Long - from KRF boundary to Diffaloo Pathar Sukani Gaon at ge of embankment is occured at ch 19000 m due to 0m on 20.06.2022 (Long - 93.517082, Lat - 26.657082) ank Abdullapur As reported by Water Resource dated on ach of bank damages (slump down) has been observed near geleft bank of river Longai from Patharkandi to Nilambazar		
ure Damaged - Embankm ent	on Golaghat Karimgan j	1 1 1 6	Dangtol Embank Bongaig Boitama at 2nd K 90.46912 Bokakh CH 1900 overtopp Nilamba 20/06/20 the toe o at Abdul Barbhas W. R de	- Mulagaon Chengmari ment damaged at 4th, 5t aon date-20.06.2022 (I ari - Pachagaon to Dakh M. as per report receive 29, Lat - 26.334561) at - Brahmaputra Dyke 00 m Breach like dama bing for a length of 20.00 azar - Abdullapur left be 022 around 185 meter re f the embankment along lapur area. (Long - 92.00 g - L/B of River Baralia partment breach length	Road at Panchapur Bridge approach Chengmari th & 6th KM. as per report received from PWRD, Long - 90.497923, Lat - 26.417318), apara Road Pachagaon Embankment damaged partially the drom PWRD, Bongaigaon date- 20.06.2022 (Long - from KRF boundary to Diffaloo Pathar Sukani Gaon at ge of embankment is occured at ch 19000 m due to 0m on 20.06.2022 (Long - 93.517082, Lat - 26.657082) ank Abdullapur As reported by Water Resource dated on ach of bank damages (slump down) has been observed near geleft bank of river Longai from Patharkandi to Nilambazar 344125, Lat - 24.741953) from Bhoiratola to Dusutimukh Dokoha As per report of		
ure Damaged - Embankm ent	on Golaghat Karimgan j Nalbari	1 1	Dangtol Embank Bongaig Boitama at 2nd K 90.46912 Bokakh CH 1900 overtopp Nilamba 20/06/20 the toe o at Abdul Barbhas W. R de	- Mulagaon Chengmari ment damaged at 4th, 5t aon date-20.06.2022 (I ari - Pachagaon to Dakh M. as per report receive 29, Lat - 26.334561) at - Brahmaputra Dyke 00 m Breach like dama bing for a length of 20.00 azar - Abdullapur left be 022 around 185 meter re f the embankment along lapur area. (Long - 92.00 g - L/B of River Baralia partment breach length	Road at Panchapur Bridge approach Chengmari th & 6th KM. as per report received from PWRD, Long - 90.497923, Lat - 26.417318), apara Road Pachagaon Embankment damaged partially the drom PWRD, Bongaigaon date- 20.06.2022 (Long - from KRF boundary to Diffaloo Pathar Sukani Gaon at ge of embankment is occured at ch 19000 m due to 0m on 20.06.2022 (Long - 93.517082, Lat - 26.657082) ank Abdullapur As reported by Water Resource dated on ach of bank damages (slump down) has been observed near geleft bank of river Longai from Patharkandi to Nilambazar 344125, Lat - 24.741953) from Bhoiratola to Dusutimukh Dokoha As per report of		
ure Damaged - Embankm ent Affected	on Golaghat Karimgan j Nalbari Total	1 1 1 1 Numb	Dangtol Embank Bongaig Boitama at 2nd K 90.46912 Bokakh CH 1900 overtopp Nilamba 20/06/20 the toe o at Abdul Barbhag W. R de 91.48972 Details Baghban Banglipa	- Mulagaon Chengmari ment damaged at 4th, 5t aon date-20.06.2022 (1 uri - Pachagaon to Dakh M. as per report receive 29, Lat - 26.334561) at - Brahmaputra Dyke 00 m Breach like dama bing for a length of 20.00 uzar - Abdullapur left b 022 around 185 meter re f the embankment along lapur area. (Long - 92.00 g - L/B of River Baralia partment breach length (36)	Road at Panchapur Bridge approach Chengmari th & 6th KM. as per report received from PWRD, Long - 90.497923, Lat - 26.417318), apara Road Pachagaon Embankment damaged partially the drom PWRD, Bongaigaon date- 20.06.2022 (Long - from KRF boundary to Diffaloo Pathar Sukani Gaon at ge of embankment is occured at ch 19000 m due to 0m on 20.06.2022 (Long - 93.517082, Lat - 26.657082) ank Abdullapur As reported by Water Resource dated on ach of bank damages (slump down) has been observed near geleft bank of river Longai from Patharkandi to Nilambazar 344125, Lat - 24.741953) from Bhoiratola to Dusutimukh Dokoha As per report of		

Gajia Kadong road flood Submarged at chainage 2nd ,3rd & 4th km. | Gajia, Medhirtary | Date of Damage- 19.06.2022 Type of Damage- Surface & Both side Shoulder damaged Damage Length- 1200 Reported by Pwd Deptt. | (Long - 90.979428, Lat - 26.311350), SPT Bridge no 1/1 at Kandapara of Gajia Kadong road flood damaged at chainage 7th & 8th km. | Kandapara | Date of Damage- 19.06.2022 Type of Damage- SPT Bridge damaged Damage Length- 140m Reported by Pwd Deptt. | (Long - 90.925842, Lat - 26.306809), Gajia Gobindapur road flood Submarged at chainage 2nd ,3rd & 4th km. | Patlikuchi, Gobindapur | Date of Damage- 19.06.2022 Type of Damage- Surface & Both side Shoulder damaged Damage Length- 240 Reported by Pwd Deptt. | (Long - 90.955902, Lat - 26.292408),

Sidhuni to Lurfuria road flood Submarged at chainage 1st, 2nd ,& 3rd km. | Sidhuni, Lurfuria | Date of Damage- 19.06.2022 Type of Damage- Surface & Both side Shoulder damaged Damage Length- 1200 Reported by Pwd Deptt. | (Long - 90.949622, Lat - 26.303072),

Jail road to Gajia Narayan Das Thakur Ata Satra via Korertol, road flood Submarged at chainage 1st, & 2nd km. | korertol | Date of Damage- 19.06.2022 Type of Damage-Surface, Hardcrust & Both side Shoulder damaged Damage Length- 900 Reported by Pwd Deptt. | (Long - 90.982900, Lat - 26.308560),

Manas Bridge approach to barpeta FAA Medical college(SH2) road flood Damaged at chainage 55km, 56km, 57km & 58km. | Jania, Chapra, Jahurpam | Date of Damage-19.06.2022 Type of Damage-Surface, Hardcrust & Both side Shoulder damaged Damage Length- 120 Reported by Pwd Deptt. | (Long - 90.973728, Lat - 26.328417),

Sarthebari - Kayakuchi Neularbhitha Debra Road | Kayakuchi | REPORTED by J.E. PWD Road on 20/06/2022 | (Long - 0.000000, Lat - 0.000000),

Barnagar - Jamadarbari to Jamadarbari Pathar Road | Jamadarbari | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged. | (Long - 90.905250, Lat - 26.504609),

Kamargaon Sisutol to Peragaon Parghat Road | Kamargaon | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged. | (Long - 90.879327, Lat - 26.534150),

Supariguri Adarsha School approach Road | Dotora | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 side berm damaged | (Long - 90.856528, Lat - 26.560162),

NH-31 to Tamulis House Road | Chantabari | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged. | (Long - 90.892803, Lat - 26.483553),

B.Ed College approach road | Chantabari | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged | (Long - 90.899794, Lat - 26.482768).

Sontorabari Shiv Mandir to Nadirpar | Ketekibari | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged | (Long - 90.403957, Lat - 26.482767),

Ketekibari Amguri Road | Ketekibari & Amguri | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 road is submerged | (Long - 90.902949, Lat - 26.470302),

Madulijhar Village Road | Madulijhar | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged | (Long - 90.886055, Lat - 26.455059),

Madulijhar Rupshi Road | Jakuapara | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged | (Long - 90.884780, Lat - 26.447502),

Rupshi Jakuapara near Banamali Mandir Road | Jakuapara | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged | (Long - 90.883625, Lat - 26.440250),

Meda to Bherbheri Dahaara Road | Meda | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged | (Long - 90.864500, Lat - 26.464229).

31 NH to Bhulukadoba Girls HS Road | Bhulukadoba | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface damaged | (Long - 90.846614, Lat - 26.481374),

Dakhin Ganakgari shiv Mandir to Baregaon paddy field Road | Baregaon and Dakhin Ganakgari | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on

20/06/2022 surface damaged | (Long - 90.880594, Lat - 26.478688),

Barnagar Circle Office t Rabin Sarma House Road | Baregaon | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 surface and culvert damaged. | (Long - 90.810595, Lat - 26.478098),

Amguri village Road | Amguri & Ketekibari | As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 the road is submerged. | (Long - 90.900354, Lat - 26.463449),

Kalgachia - various 09 nos of road(details in Remarks) | various location within the circle (details in Remarks) | As per report received from PWD dept and BDO office Rupshi on 20/06/22, total 09 nos of of PWD and village roads are damaged, they are-1. Due to continuous heavy rainfall road surface damaged with shoulder of SH2 (Manas Bridge Approach to Barpeta Medical College) At Ch. 35th Km (Affected Length = 200.00 m, Avg. Width = 2.50 m, Avg. Height = 1.80 m and location coordinate = 26.306572, 90.753843), At Ch. 36th Km (Affected Length = 220 m, Avg. Width = 2.50 m, Avg. Height = 1.80 m and location coordinate = 26.305601, 90.763339), At Ch. 37th Km (Affected Length = 180 m, Avg. Width = 2.40 m, Avg. Height = 1.80 m and location coordinate = 26.303089, 90.775647), At Ch. 40th Km (Affected Length = 230.00 m, Avg. Width = 2.50 m, Avg. Height = 1.70 m and location coordinate = 26.323389, 90.793646), At Ch. 41st Km (Affected Length = 280.00 m, Avg. Width = 2.50 m, Avg. Height = 2.00 m and location coordinate = 26.323213, 90.794404), At Ch. 42nd Km (Affected Length = 230.00 m, Avg. Width = 2.50 m, Avg. Height = 1.80 m and location coordinate = 26.321911, 90.808938), At Ch.43rd Km (Affected Length = 350.00 m, Avg. Width = 2.50 m, Avg. Height = 2.00 m and location coordinate = 26.329625, 90.812437), At Ch. 44th Km (Affected Length = 210.00 m, Avg. Width = 2.50 m, Avg. Height = 2.00 m and location coordinate = 26.328947, 90.834859), At Ch. 47th Km (Affected Length = 250.00 m, Avg. Width = 2.50 m, Avg. Height = 2.00 m and location coordinate = 26.327197, 90.813493), At Ch. 48th Km (Affected Length = 180.00 m, Avg. Width = 2.50 m, Avg. Height = 1.80 m and location coordinate = 26.330506, 90.862197). 2. Due to continuous heavy rainfall RCC box culvert (At Ch. 3900.00 m) approach damaged at Kalgachia to Kharbally road. (Length = 25.00 m, Avg width = 2.00 m, Height = 1.80 m and location Coordinate = 26.373390, 90.89024). 3. Const. of earthen field bundh st frm Rofsed ali house to Hasen Ali house, vill-Shawrachara (damaged details- length=70m, B=4m, H=1.2m) coordinates- 26.274686, 90.824785. 4. Const. of earthen filed bundh st frm Nurul Islam house to Abdul Goni house, vill-Shawrachara, damaged details- length= 50m, B-4m, H=1.50 m, coordinates-26.269853, 90.821648. 5. PMGSY road to chikni char, damaged details- L=90m, B=4m, H=1.2m, coordinates-26.268845, 90.836816 6. PMGSY road to chikni, damaged details-L=40m, B=4m, H=1.2m, coordinates- 26.267688, 90.805885. 7. Jawrimari Bazar rd, damaged details- L=50m, W=4m, H=1.2m, coordintes- 26.260858, 90.802475. 8.Earthen field bundh st frm MNP road to west side Shajahan Ali house at vill Kandulia under MGNREGA-2020-21, damaged details- L=25m, B=4m, coordinates- 26.296698, 90.778051. 9. Earthen field bundh st frm PWD rd to Kaser uddin house at Lachanga under MGNREGA- 2020-21, damaged details- L=40m, B=4m, coordinates- 26.39306, 90.888695 | (Long - 0.000000, Lat - 0.000000),

Chenga - Chenga Block Boundary to BD Road via Chenga Musalman gaon, PMGSY package No. AS/01-510 | Musalman Gaon | whole length submerged except bridge approach average depth 0.45 m. report by PWD, Roads date-20/06/2022 | (Long - 0.000000, Lat - 0.000000),

Padmapara to chenga basic road chowk | padmapara | Padmapara to chenga basic road chowk road submerged, average depth 0.35 m.report by PWD, Roads date-20/06/2022 | (Long - 0.000000, Lat - 0.000000),

Suva to Jatradia NC via Bandali Road | Suva | submerged, report by PWD, Roads date-20/06/2022 | (Long - 0.000000, Lat - 0.000000),

Khongra to Jatradia NC via Bandali Road | Khongra | submerged, report by PWD, Roads date-20/06/2022 | (Long - 0.000000, Lat - 0.000000),

Roumari Pathar to Nodirpar road | Roumari Pathar | submerged, average depth.0.6m, report by PWD, Roads date-20/06/2022 | (Long - 0.000000, Lat - 0.000000),

Khongra Roumari Pathar road to Chenimari road | khongra | submerged, average depth-0.45m, report by PWD, Roads date-20/06/2022 | (Long - 0.000000, Lat - 0.000000), Chenga Bahari road to Atia road | Bahari | submerged, average depth-0.40m, report by PWD, Roads date-20/06/2022 | (Long - 0.000000, Lat - 0.000000),

Chenga Bahari Road submerged at several stretches | Bahari | average depth-0.30m, report by PWD, Roads date-20/06/2022 | (Long - 0.000000, Lat - 0.000000),

•		
		Barpeta Doulasal road Batgaon submerged at several stretches, report by PWD, Roads date-20/06/2022 (Long - 0.000000, Lat - 0.000000),
		Roumari Pathar to Khongra 2 no. Pachim Supa via Sonartari, package no.As-01-511, road Khongara, Roumari Pathar, Sonartari submerged from 2.00 km to 3.40 km, report by PWD, Roads date-20/06/2022 (Long - 0.000000, Lat - 0.000000),
		Niz Chenga to bampara Road Niz Chenga submerged, report by PWD, Roads date-20/06/2022 (Long - 0.000000, Lat - 0.000000),
		Batgaon Haripur Road Batgaon submerged, report by PWD, Roads date-20/06/2022
		(Long - 0.000000, Lat - 0.000000), Batgaon Kadamtala road Batgaon submerged, report by PWD, Roads date-20/06/2022
		(Long - 0.000000, Lat - 0.000000),
		Balapara Ganakpara road Balapara submerged, report by PWD, Roads date-20/06/2022 (Long - 0.000000, Lat - 0.000000),
		Ganakpara Piralabhitha road Ganakpara submerged, report by PWD, Roads date-20/06/2022 (Long - 0.000000, Lat - 0.000000),
		Batgaon Sutiapara road Sutiapara submerged, report by PWD, Roads date-20/06/2022
		(Long - 0.000000, Lat - 0.000000)
Biswanat		Biswanath - BG road to 1 No. Japoriguri via Dakhin Moral gaon PMGSY PKG No.AS 22 635 for a length of about 300m (Ch 4900m to 5200m) was submerged by water of river
h	1	Brahmaputra Japoriguri Report received from PWD(roads) Biswanath via whatsapp on 20.06.2022 (Long - 93.195645, Lat - 26.720255)
		Bongaigaon - Dholagaon Dewangaon Road Dweangaon Breach occur Ch. 1500.00m. as
		per report received from PWRD, Bongaigaon date-20.06.2022 (Long - 90.526521, Lat - 26.405701),
		Salbari Bongaigaon Road Salbari Errosion and settlement of road embankment at 9th KM. as per report received from PWRD, Bongaigaon date-20.06.2022 (Long - 90.516932,
		Lat - 26.405897), Udmari Ravapara to Garopara Road Garopara Errosion of Road embankment at 3rd km.
		as per report received from PWRD, Bongaigaon date-20.06.2022 (Long - 90.609104, Lat - 26.465739),
Bongaiga	8	Boitamari - Jogighopa Chatpara Jogighopa Waterlogged at 1st KM. as per report
on	0	received from PWRD, Bongaigaon date- 20.06.2022 (Long - 90.573925, Lat - 26.223333), Srijangram - Haripur New Piradhara road Haripur New Piradhara road Submerged at 2nd km report PWRD Bongaigaon dated 19.06.2022 (Long - 90.679285, Lat - 26.314749),
		Borigaon Bamungaon road Borigaon Bamungaon road Road surface damaged at 1st km
		report PWRD Bongaigaon dated 19.06.2022 (Long - 90.678895, Lat - 26.338603), Abhayapuri PS to 8th APBN approach road. Abhayapuri PS to 8th APBN approach road.
		Damaged road embankment partially at Culvert no2/1 report PWRD Bongaigaon dated 19.06.2022 (Long - 90.658694, Lat - 26.350326),
		Gerukabari kirtanpara road Gerukabari Kirtanpara road Erosion of road threaten at 10th
		km report PWRD Bongaigaon dated 19.06.2022 (Long - 90.456000, Lat - 26.245200)
		Lakhipur - HAZARIGRAM TO KALAPANI HAZARIGRAM TO KALAPANI HAZARIGRAM TO KALAPANI IENGTH 25.0 M, AS REPORTED BY EE PWD
		RURAL ROADS, LAKHIPUR SUB-DIVISION ON DATED 20.06.2022. (Long -
Cachar	2	92936058.000000, Lat - 24803742.000000), NH-37 PALORBOND TO LAKHIPUR PALORBOND TO LAKHIPUR NH-37
		PALORBOND TO LAKHIPUR IENGTH 2451.0 M AS REPORTED BY EE PWD
		RURAL ROADS, LAKHIPUR SUB-DIVISION ON DATED 20.06.2022. (Long -
		92954963.000000, Lat - 24817264.000000) Bijni - Borobazar Bhabanipur Road at Nehru Bazar. at Subhaijhar As reported by PWD
		Chirang(R&B) Division, Borobazar bhabanipur Road at Nehru Bazar over topped & eroded
		at Subhaijhar. Length=200 mtr, Breadth=7.50, Depth=1.50 mtr. Date of Occurrence=18-06-2022 (Long - 90.603842, Lat - 26.595071),
		Khamarguri Amteka Road to Pub Baldi road Pub Baldi As reported by PWD
Chirang	3	Chirang(R&B) Division, kkhamarguri Amteka road to Pub Baldi road over topped &
		eroded. Length=100 mtr, Breadth=3.00 mtr, Depth=1.50 mtr. Date of Occurrence=18-06-
		2022. (Long - 90.601290, Lat - 26.599501), Bengtal - Koilamoila to Malivita Road Amteka As reported by PWD Road Embankment
		eroded on 19-06-2022, L-5000m B-7.50m D-0.50m (Long - 90.554244, Lat - 26.715406)
		Mangaldoi - Culvert Damage at MM Road under P.W.R.D under Mangaldai Revenue
Darrang	69	Circle as reported by P.W.R.D the Culvert Damage at MM Road due to flood under
		Mangaldai Revenue Circle . Dated 15-6-2022 (Long - 91.950000, Lat - 26.490000),

Ramhari to Mahaliajhar Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by P.W.R.D the Ramhari to Mahaliajhar Road submerged due to flood and the length of submergence is 100 mtr. approx under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.030000, Lat - 26.500000),

Culvert Damage at Mahaliajhar to Bhakatpara Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by P.W.R.D the Culvert Damage at Mahaliajhar to Bhakatpara due to flood under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.030000, Lat - 26.500000),

Mahaliajhar to Bhakatpara Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by P.W.R.D the Mahaliajhar to Bhakatpara Road submerged due to flood and the length of submergence is 1000 mtr. approx under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.030000, Lat - 26.530000),

Abhayapukhuri to Chapai Dalgaon under P.W.R.D | under Mangaldai Revenue Circle | as reported by P.W.R.D the Abhayapukhuri to Chapai Dalgaon submerged due to flood and the length of submergence is 200 mtr. approx under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.030000, Lat - 26.550000),

Borjhar Bagisa to Bhakatpara Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by P.W.R.D the Borjhar Bagisa to Bhakatpara Road submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.030000, Lat - 26.560000),

Culvert Damage at Borjhar Bagisa to Bhakatpara Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Culvert Damage at Borjhar Bagisa to Bhakatpara at MM Road due to flood under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.028000, Lat - 26.560000),

Bridge approach damageed at Bhagawat Mandir Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Bridge approach damageed at Bhagawat Mandir at MM Road due to flood under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 91.960000, Lat - 26.450000),

Ramhari To Mahaliajhar Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Ramhari To Mahaliajhar Road submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.030000, Lat - 26.519000),

NH-15 to DRDA Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH-15 to DRDA Road submerged due to flood and the length of submergence is 1500 mtr. approx under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.030000, Lat - 26.430000),

Mangaldai Stadium Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH-15 to DRDA Road submerged due to flood and the length of submergence is 100 mtr. approx under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.030000, Lat - 26.440000),

Lankapuri Bridge Approach damaged under P.W.R.D | under Mangaldai Revenue Circle | as reported by Lankapuri Bridge Approach Damage at MM Road due to flood under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 92.020000, Lat - 26.470000), M B Road at Adhamapara under P.W.R.D | under Mangaldai Revenue Circle | as reported by M B Road at Adhamapara submerged due to flood and the length of submergence is 200 mtr. approx under Mangaldai Revenue Circle . Dated 16-6-2022 | (Long - 91.120000, Lat - 26.260000),

Santipur to Market Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Santipur to Market Road submerged due to flood and the length of submergence is 1000 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.030000, Lat - 26.440000),

Lachit Nagar Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Lachit Nagar Road submerged due to flood and the length of submergence is 1200 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.025000, Lat - 26.450000),

M B Road at Telipara under P.W.R.D | under Mangaldai Revenue Circle | as reported by M B Road at Telipara submerged due to flood and the length of submergence is 3000 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.028000, Lat - 86.453000),

Telipara to Kerimeri Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Telipara to Kerimeri Road submerged due to flood and the length of submergence is 1000 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.028700,

Lat - 26.450000),

Santipur Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Santipur Road submerged due to flood and the length of submergence is 1500 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.020000, Lat - 26.460000), MPK Road at Karimchowk under P.W.R.D | under Mangaldai Revenue Circle | as reported by MPK Road at Karimchowk submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.028000, Lat - 26.440000),

MM Road at Hollow Chowka under P.W.R.D | under Mangaldai Revenue Circle | as reported by MM Road at Hollow Chowka submerged due to flood and the length of submergence is 1500 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 91.960000, Lat - 26.480000),

MM Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by MM Road submerged due to flood and the length of submergence is 3000 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 91.960000, Lat - 26.480000), Ramhari to Mahaliajhar Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Ramhari to Mahaliajhar submerged due to flood and the length of submergence is 1500 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.030000, Lat - 26.500000),

Gakhir Khuwa Para under P.W.R.D | under Mangaldai Revenue Circle | as reported by Gakhir Khuwa Para submerged due to flood and the length of submergence is 700 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.000000, Lat - 26.460000),

Dhula Tangni Bridge Approach Damaged under P.W.R.D | under Mangaldai Revenue Circle | as reported by Dhula Tangni Bridge Approach Damage at MM Road due to flood under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.110000, Lat - 26.490000), Bolopara to MB Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Bolopara to MB Road submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.020000, Lat - 26.519000),

Kachomari to MB Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Kachomari to MB Road submerged due to flood and the length of submergence is 700 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.010000, Lat - 26.520000),

Algachar to NH 15 under P.W.R.D | under Mangaldai Revenue Circle | as reported by Algachar to NH 15 Damage at MM Road due to flood under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 92.000000, Lat - 26.000000),

Paniakhat to NH 15 under P.W.R.D | under Mangaldai Revenue Circle | as reported by Paniakhat to NH 15 Road submerged due to flood and the length of submergence is 800 mtr. approx under Mangaldai Revenue Circle . Dated 17-6-2022 | (Long - 91.950000, Lat - 26.468000),

MPK Road at Janaram Chowk under P.W.R.D | under Mangaldai Revenue Circle | as reported by MPK Road at Janaram Chowk submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 18-6-2022 | (Long - 91.960000, Lat - 26.440000),

Atakata Chapori to NH-15 under P.W.R.D | under Mangaldai Revenue Circle | as reported by Atakata Chapori to NH-15 submerged due to flood and the length of submergence is $1000 \, \text{mtr.}$ approx under Mangaldai Revenue Circle . Dated 18-6-2022 | (Long - 92.110000, Lat - 26.480000),

Paniakhat to NH-15 under P.W.R.D | under Mangaldai Revenue Circle | as reported by Paniakhat to NH-15 Damage at MM Road due to flood under Mangaldai Revenue Circle . Dated 18-6-2022 | (Long - 92.101000, Lat - 26.470000),

Garapani Kharaji to NH-15 under P.W.R.D | under Mangaldai Revenue Circle | as reported by Garapani Kharaji to NH-15 submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 18-6-2022 | (Long - 92.099000, Lat - 26.450000),

Lankapuri Bridge Approach Damage under P.W.R.D | under Mangaldai Revenue Circle | as reported by Lankapuri Bridge Approach Damage at MM Road due to flood under Mangaldai Revenue Circle . Dated 18-6-2022 | (Long - 92.024890, Lat - 26.478000), Bolopara to MB road PMGSY under P.W.R.D | under Mangaldai Revenue Circle | as reported by Bolopara to MB road PMGSY submerged due to flood and the length of submergence is 700 mtr. approx under Mangaldai Revenue Circle . Dated 18-6-2022 |

(Long - 92.024700, Lat - 26.510000),

Kachomari to MB Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Kachomari to MB Road submerged due to flood and the length of submergence is 1000 mtr. approx under Mangaldai Revenue Circle . Dated 18-6-2022 | (Long - 92.010000, Lat - 26.510000),

Ramhari To Mahaliajhar Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Ramhari To Mahaliajhar Road submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 18-6-2022 | (Long - 92.030000, Lat - 26.519000),

Chapai Dalgaon to Mahaliajhar under P.W.R.D | under Mangaldai Revenue Circle | as reported by Chapai Dalgaon to Mahaliajhar submerged due to flood and the length of submergence is 300 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.000000, Lat - 26.000000),

Kerimeri to Telipara Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Kerimeri to Telipara Road submerged due to flood and the length of submergence is 700 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.037000, Lat - 26.450000),

Bega Police point to END office under P.W.R.D | under Mangaldai Revenue Circle | as reported by Bega Police point to END office submerged due to flood and the length of submergence is 1200 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.030000, Lat - 26.430000),

NH 15 to Manhumara Pukhuri via Upahupara under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH 15 to Manhumara Pukhuri via Upahupara submerged due to flood and the length of submergence is 700 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.010000, Lat - 26.430000),

NH 15 to 3rd colony boulder protection under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH 15 to 3rd colony boulder protection Damage at MM Road due to flood under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.000000, Lat - 26.420000), NH15 to Industry Estate under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH15 to Industry Estate submerged due to flood and the length of submergence is 700 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.000000, Lat - 26.420000),

NH 15 to 2 no. bezpara under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH 15 to 2 no. bezpara submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.005700, Lat - 26.420000),

NH 15to Konwar Para under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH 15to Konwar Para submerged due to flood and the length of submergence is 300 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.002000, Lat - 26.426600),

MPK road at Harinkhuja under P.W.R.D | under Mangaldai Revenue Circle | as reported by MPK road at Harinkhuja submerged due to flood and the length of submergence is 700 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 91.970000, Lat - 26.440000).

MPK Road to Harinkhuja PMGSY Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by MPK Road to Harinkhuja PMGSY submerged due to flood and the length of submergence is 800 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 91.970000, Lat - 26.450000),

M M Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by M M Road submerged due to flood and the length of submergence is 3000 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.000000, Lat - 26.460000), BJ Road at Barangabari under P.W.R.D | under Mangaldai Revenue Circle | as reported by BJ Road at Barangabari submerged due to flood and the length of submergence is 800 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.000000, Lat - 26.490000),

M B Road at Rubber Bugun under P.W.R.D | under Mangaldai Revenue Circle | as reported by M B Road at Rubber Bugun submerged due to flood and the length of submergence is 200 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.090000, Lat - 26.490000),

MB Road ta Telipara under P.W.R.D | under Mangaldai Revenue Circle | as reported by MB Road ta Telipara submerged due to flood and the length of submergence is 300 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.080000, Lat -

26.450000),

MB Road via Lankapuri PMGSY Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by MB Road via Lankapuri Damage at MM Road due to flood under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.024890, Lat - 26.478000),

M Ibrahim Ali Path under P.W.R.D | under Mangaldai Revenue Circle | as reported by M Ibrahim Ali Path submerged due to flood and the length of submergence is 600 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.030000, Lat - 26.430000), Salimuddin Ahmed Path under P.W.R.D | under Mangaldai Revenue Circle | as reported by Salimuddin Ahmed Path submerged due to flood and the length of submergence is 600 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.030000, Lat - 26.430000),

Denial Path under P.W.R.D | under Mangaldai Revenue Circle | as reported by Denial Path submerged due to flood and the length of submergence is 300 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.030000, Lat - 26.430000),

NH 15 to Mangaldai Stadium under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH 15 to Mangaldai Stadium submerged due to flood and the length of submergence is 1200 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.450000, Lat - 26.450000),

NH 15 to Don Bosco School under P.W.R.D | under Mangaldai Revenue Circle | as reported by NH 15 to Don Bosco School submerged due to flood and the length of submergence is 600 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.450000, Lat - 26.450000),

NH 15 to Megistrate Colony under P.W.R.D \mid under Mangaldai Revenue Circle \mid as reported by NH 15 to Megistrate Colony submerged due to flood and the length of submergence is 900 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 \mid (Long - 92.450000, Lat - 26.450000),

Barua Para Path under P.W.R.D | under Mangaldai Revenue Circle | as reported by Barua Para Path submerged due to flood and the length of submergence is 1200 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.020000, Lat - 26.460000), Medhipara Hatibakara Road under P.W.R.D | under Mangaldai Revenue Circle | as reported by Medhipara Hatibakara Road submerged due to flood and the length of submergence is 600 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.020000, Lat - 26.400000),

Bejpara to Mollapara under P.W.R.D | under Mangaldai Revenue Circle | as reported by Bejpara to Mollapara submerged due to flood and the length of submergence is 2000 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.000000, Lat - 26.490000),

M B Road near Chapai under P.W.R.D | under Mangaldai Revenue Circle | as reported by M B Road near Chapai submerged due to flood and the length of submergence is 500 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.090000, Lat - 26.030000),

Tamulipara to Magaldai Stadium under P.W.R.D | under Mangaldai Revenue Circle | as reported by Tamulipara to Magaldai Stadium submerged due to flood and the length of submergence is 1200 mtr. approx under Mangaldai Revenue Circle . Dated 19-6-2022 | (Long - 92.450000, Lat - 26.450000),

Patharighat - Ratnabali Satra road | Ratnawali satra | Demaged Ratnabali Satra road due to breach of Nonoi RB embankement as reported by PWD on 20.602022 | (Long - 91.869130, Lat - 26.454765),

road to Khtara Satra | Khtara Satra | Approch road to Khtara Satra via Ratnabali Satra Submerged L=200m ch 20m to 220m depth =0.60m as reported by PWD on 20.602022 | (Long - 91.869218, Lat - 26.454766),

Kotahi Dhoportal road | Kotahi Dhoportal | Kotahi Dhoportal road Submerged & Breach CD washway ch 2.60m as reported by PWD on 20.602022 | (Long - 91.840865, Lat - 26.501151),

MPK Road | MPK rd to MM rd | MPK rd to MM rd demaged & Breach at ch. 300 to 450m as reported by PWD on 20.602022 | (Long - 91.842974, Lat - 26.518997),

MM road | MM road near Sarabari HS | Erosion on MM road near Sarabari HS at ch 22.00km as reported by PWD on 20.602022 | (Long - 91.856264, Lat - 26.529115), MPK rd | MPK rd | Erosion on MPK rd at ch 23.0km as reported by PWD on 20.602022 | (Long - 91.835467, Lat - 26.497969),

MPK rd to Mahara | Sareng | MPK rd to Mahara connecting road Submerged & demaged THPC as reported by PWD on 20.602022 | (Long - 91.821455, Lat - 26.521834)

	1	T PRODUCT TO THE TOTAL TO THE TRANSPORT OF THE TRANSPORT
Dhemaji	1	Jonai - PWD territorial road embankment NH-52 to Ujani Missamara via Rongjuli under PMGSY package no. As-04-57, 10.00 meter breached on 20/06/2022 by Dikhari River. From Ch.7550.00m to 7560.00m As per report received from PWD,Jonai Territorial Road Sub- Division-II, Jonai a PWD territorial road embankment at NH-52 to Ujani Missamara via Rongjuli under PMGSY package no. As-04-57, 10.00 meter breached on 20/06/2022 by Dikhari River. (Long - 95.010624, Lat - 27.712816)
Dhubri	4	Chapar - NH-31 AT TARANGAPUR WATER SUPPLY TO TARANGAOUR PT-1 ROAD(,) SIDE BERM ERRODED AND ROAD SURFACE DAMAGED DUE TO HEAVY RAIN dated 14-06-22 to 18-06-22 (Latitude 26.25513, Longitude 90.422092)(.) Tarangapur (Long - 90.422092, Lat - 26.255130), SATYAPUR BHATIPARA LAKHIMANDIR TO SAGARKUTI ROAD (,) SIDE BERM ERODED DUE TO HEAVY RAIN AND FLOOD RIVER CHAMPABATI dated 14-06-22 to 18-06-22 (Latitude 26.276539, Longitude 90.43022) (.) Satyapur (Long - 90.430220, Lat - 26.276539), NH-31 AT AREARJHAR TO PUTHIMARI ROAD (,) SIDE BERM ERODED DUE TO HEAVY RAIN AND FLOOD RIVER BHRAMAPUTRA dated 14-06-22 to 18-06-22 (Latitude 26.248138, Longitude 90.408883)(.) Puthimari (Long - 90.408883, Lat - 26.248138), NH-31 AT SHIVA MANDIR TO DHRI BEEL VIA PAKHIPARA ROAD (,) SIDE BERM ERODED DUE TO HEAVY RAIN dated 14-06-22 to 18-06-22 (Latitude 26.262956, Longitude 90.398959)(.) Arearjhar Pt-I (Long - 90.398959, Lat - 26.262956)
Goalpara	26	Balijana - Kharmuja Taltola Road Kharmuja Date of occurrence- 16.06.2022 Length/dimension- 0.300 KM Average depth of submergence- 0.30 M Traffic disrupted from 16-06-2022 to Till Date (20/06/2022) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 (Long - 90.357113, Lat - 26.052853), Junkaipara batabari road Junkaipara batabari Date of occurrence- 16.06.2022 Length/dimension- 0.600 KM Average depth of submergence- 0.60 M Traffic disrupted from 16-06-2022 to Till Date (20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 (Long - 90.439477, Lat - 26.088189), Korichala Sopatola Dosera Ambari Road Ambari Date of occurrence- 16.06.2022 Length/dimension- 0.450 KM Average depth of submergence- 0.30 M 1 no. of culvert approach damaged Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 (Long - 90.440059, Lat - 26.097215), Ambari to Dosera Ambari Road Ambari to Dosera Ambari Date of occurrence- 16.06.2022 Length/dimension- 0.350 KM Average depth of submergence- 0.30 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 (Long - 90.904108, Lat - 26.090833), Kalyanpur to Polashkandi Road Kalyanpur to Polashkandi Road Date of occurrence- 16.06.2022 Length/dimension- 0.600 KM Average depth of submergence- 0.30 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 (Long - 90.408455, Lat - 26.088424), Deudhotoripara Road Deudhotoripara Date of occurrence- 16.06.2022 Length/dimension- 0.550 KM Average depth of submergence- 0.30 M Traffic disrupted from 16-06-2022 to Till Date (20-06-22) Report received from Dep

Length/dimension- 0.350 KM Average depth of submergence- 0.30 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.451092, Lat - 26.116426),

Pub – Ambari Kadotika to Konachipara Road | Ambari Kadotika to Konachipara | Date of occurrence- 16.06.2022 Length/dimension- 0.150 KM Average depth of submergence- 0.30 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.409853, Lat - 26.095334),

Kalyanpur (Batabari) to Markula (Kamal Bazar) Road | Kalyanpur (Batabari) to Markula (Kamal Bazar) | Date of occurrence- 16.06.2022 Length/dimension- 0.750 KM Average depth of submergence- 0.30 M Traffic disrupted from 16-06-2022 to Till Date (20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.408537, Lat - 26.088317), Garobhatkhowa Murlijhar Road | Murlijhar | Date of occurrence- 16.06.2022 Length/dimension- 0.450 KM Average depth of submergence- 0.50 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long -

Bashbari Banjalijhar Road | Banjalijhar | Date of occurrence- 16.06.2022 Length/dimension- 0.550 KM Average depth of submergence- 0.45 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.357491, Lat - 26.053070),

90.375865, Lat - 26.063990),

Latima Mathowari Road | Latima | Date of occurrence- 16.06.2022 Length/dimension- 0.450 KM Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.371107, Lat - 26.084587),

Maladhara Baguan Road | Chengpata | Date of occurrence- 16.06.2022 Length/dimension- 0.400 KM Average depth of submergence- 0.40 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.385577, Lat - 26.063965), Pub konkairpar to Poschim Konkairpar Road | Pub konkairpar to Poschim Konkairpar | Date of occurrence- 16.06.2022 Length/dimension- 0.400 KM Average depth of submergence- 0.30 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.410567, Lat - 26.086756),

Makri Kharmuja Road | Makri Kharmuja | Date of occurrence- 16.06.2022 Length/dimension- 0.050 KM Road Side Berm Eroded Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.515498, Lat - 26.155259),

Simlabari Markula to Dosera Ambari Road | Simlabari Markula to Dosera Ambari | Date of occurrence- 16.06.2022 Length/dimension- 0.100 KM Average depth of submergence- 0.45 M Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.417094, Lat - 26.090575),

Agia Lakhipur Road (Balijana Lakhipur) Road | Agia Lakhipur Road | Date of occurrence-16.06.2022 Length/dimension- 2.900 KM Road Side Berm Eroded Traffic disrupted from 16-06-2022 to Till Date(20-06-22) Report received from Department- PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur on 19.06.2022 | (Long - 90.374201, Lat - 26.011506),

Matia - Buduchar to Singramari Road (PMGSY PKG No-AS.07.288) | Buduchar | Affected length = 0.400 Km and average depth of submergence = 0.500 m (as on 18/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara | (Long - 90.766444, Lat - 26.109668),

Mamudpur to Bahati Bhatipara Road (PMGSY PKG No AS 07 365) | Bahati Bhatipara | Affected length = 0.620 Km and average depth of submergence = 0.700 m (as on 18/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara | (Long - 90.813287, Lat - 26.108333),

Buduchar to Basantapur Road | Buduchar | Affected length = 0.470 Km and average depth of submergence = 0.530 m (as on 18/06/2022) as reported by PWRD, Dudhnoi & Goalpara

			East Territorial Road Division, Goalpara (Long - 90.800062, Lat - 26.108433), Pokalagi Garoporatori Road Pokalagi Affected length = 0.540 Km and average depth of
			submergence = 0.900 m (as on 18/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.855073, Lat - 26.081730), Krishnai Karkashi to Simlapara Road (PMGSY PKG No AS-07-208) Karkashi Simlapara
			Affected length = 1.800 Km, road side berm and embankment damaged (as on
			18/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division,
			Goalpara (Long - 90.731197, Lat - 26.063970),
			Narapati PWD Road Narapati Affected length = 0.480 Km and average depth of
			submergence = 0.460 m (as on 18/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara (Long - 90.749953, Lat - 26.033660),
			Rongjuli - Matia- Simlitola Road Palpara, Domnapara near Nabagata Simlitola Partially
			submerged as on 20.06.2022 Information received from JE PWD(RR) on 20.06.2022.
			Submerged Length: 120m, water depth: 0.20m Latitude: 26.069864 Longitude: 90.892647 (Long - 90.892647, Lat - 26.069864)
			Lala - Monacherra Ishancherra Road Under Lala Revenue Circle on 20.06.2022 5th KM
			Submerged at 1.00 M hight. (Long - 92.533833, Lat - 24.600676),
			Algapur - Salchapra Bandukmara Road under Algapur Revenue Circle dtd. 20.06.2022 18th , 20th KM Damage due to over topping of runoff water a portion washed away at
			19th km. (Long - 92.642140, Lat - 24.677302),
			7th KM of Algapur Narainpur Road to Algapur Mohanpur Road under Algapur Revenue
	Hailakan		Circle dtd.20.06.2022. Ch. 12100.00 m to 12300.00m Washed away (Long - 92.632778,
	di	5	Lat - 24.753520), Heilehandi, Silahan Heilehandi Baad Undan Heilehandi Bayanya Cirola on 20.06.2022
			Hailakandi - Silchar Hailakandi Road Under Hailakandi Revenue Circle on 20.06.2022 Ch. 1100.00, Ch. 1330.00, Ch. 3900.00, Ch. 6300.00, Ch. 7000.00, Ch. 11600 m to
			12600.00m Landslide and overtopping and submerged and erosion of Matijuri bridge
			approach with damaged . (Long - 92.657993, Lat - 24.633723),
			Bazar to Tupkhana Road Under Hailakandi Revenue Circle on 20.06.2022 Ch. 850.00m,
			Ch. 900.00m, Ch. 950.00m, Ch. 1400.00m Erosion of shoulder and depression of the road due to rising of water level of river Dhaleswari. (Long - 92.560106, Lat - 24.675975)
			Lanka - Kharikhana to Maduli Road Kharikhana to Maduli Road Kharikhana to Maduli
			Road Submerged on 16/06/2022 (Long - 25.525400, Lat - 92.525000),
			Hojai - Hojai to Tumprang road Hojai to Tumprang Hojai to Tumprang road Submarged on 16-06-2022 (Long - 25.595400, Lat - 92.481900),
			NH54 To Sildubi road NH54 To Sildubi NH54 To Sildubi road Submarged on 16-06-
			2022 (Long - 25.525400, Lat - 92.525000),
			Hojai Tumprang to nawbhanga Kali mandir road Hojai Tumprang to nawbhanga Kali
			mandir Hojai Tumprang to nawbhanga Kali mandir road Submarged on 16-06-2022 (Long - 26.023000, Lat - 92.471500),
			Raikata Islam pur Submarged on 16-06-2022 Raikata Islam pur Raikata Islam pur
	Hojai	10	Submarged on 16-06-2022 (Long - 25.967100, Lat - 92.778600),
	Hojui	10	Uttar Bidyanagar to Kendurguri Road Uttar Bidyanagar to Kendurguri Uttar Bidyanagar
			to Kendurguri Road Submarged on 16-06-2022 (Long - 26.111000, Lat - 92.491000), Dakhin Laskar Pather to Udaypur Dakhin Laskar
			Pather to Udaypur Road Submarged on 16-06-2022 (Long - 25.912300, Lat - 92.891200),
			Barajapur to Fakuli Road Barajapur to Fakuli Road Barajapur to Fakuli Road Submarged
			on 16-06-2022 (Long - 92.776300, Lat - 26.068200), Barafuti to fakuli road Barafuti to fakuli Barafuti to fakuli Submarged on 16-06-2022
			(Long - 92.472400, Lat - 26.334000),
			Nawbhanga Kali Mandir Approach Road Nawbhanga Kali Mandir Approach Road
			Nawbhanga Kali Mandir Approach Road Submarged on 16-06-2022 (Long - 92.471600,
			Lat - 26.210000) Rangia - SPT Bridge 1/1 Kendukona to Balistra Road at Kanikuchi Vill- Kanikuchi The
			approach road to the SPT Bridge 1/1 Kendukona to Balistra Road at Vill Kanikuchi was
			damaged on 18.06.2022 as per report of AEE, PWD NKT Roads, Rangia (Long -
			0.000000, Lat - 0.000000), Chamaria - Jowkatadia to niburtari Jowkatadia Road submerged of the road namely
	Kamrup	9	jowkatadia to niburtari had taken place on dated 19.06.2022 and the same has been reported
			by JE, PWD, Boko territorial road sub-division on dated 19.066.2022 (Long - 91.112583,
			Lat - 26.110100), Kamalaur Petikushi ta simlihari raad Pelikushi Total Langht 6 Km Damaga of Roads
			Kamalpur - Batikuchi to simlibari road Balikuchi Total Lenght-6 Km, Damage of Roads by Pot Holes(ICBP Road) at Chainage=2.60KM on 19/06/2022 as per Report of the Asst.
L	l .	1	, , , , , , , , , , , , , , , , , , , ,

Fisceutive Fingg, PWD Kamalpur (Long - 2-0.468458, Lat - 91.7661116). Domakahora Railway Line Road (Domakahora Total Length- 90in kength of submergence-70m depth of submergence-0.45m, chainage at-300m on 1906/2022 as per report of Asst. Executive Fingg, PWD kamalpur (Long - 2-0.29244, Lat - 91.700638). decompara to paikana LP School via jugamanth mandir Paikam dura subal [Domapara] total length of road-500m, submerged clength-50m, depth of submergence-60m chainage on 1906/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 2-0.293963, Lat - 91.711102). Kamalpur Morrowa Road [Kamlpur Total Length of Road - 7 km, Submerged Length-200m, Depth of Submerged-0-6m, Chainage-450m on 1906/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 2-0.34670, Lat - 91.667415). Sutragono Dibulara Road [Sutragon Total Length of Road - 15 km. Submerged length - 500 M, Depth of Submergence - 60m Chainage - 450 m on 1946/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 26.34670), Lat - 9196/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 26.346905, Lat - 91.79042), kamalpur Borka Road [Kamalpur Total Length of Road - 8 km, Submerged length - 500 M, Depth of Submergence - 45m Chainage - 15 km, and Kh, 3 cm Kh, 4 kh M on 19-06/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 26.342817, Lat - 91.678704), Nagarberea - Hekra to magarbera road Indigateral Hekra to magarbera road abunerged on 19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 [Long - 20.347800, Lat - 91.82000) Gossalgoon - Gourda'to Singinnari Road [Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD Kachtodon NR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL ROAD NR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL ROAD NR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON SOSHABIL ROAD NR SUB DIVISION DUE TO HEAVY RAIN BENERGHAN SUB-RESTORATION ON ACHUGAON NR SUB DIVISION DUE TO HEAVY RAIN BENERGHAN SUB-RESTORATION ON	 		
Toun depth of submergence - 0.45m. chainage at 300m on 1906/2022 as per report of Asst. Executive Eng. PWD Lamapur [Long 26.29234, Lu 9.1,006318). docurpara to paikana I.P. School via jugamenth mondir Paikann dura suba [Documpara total length of road-50m, submergence - 60m chainage on 19/16/2022 as per report of Asst. Executive Engg. PWD kamalpur [Long - 26.293963, Lut - 9.1,7111/202]. Kamalpur Morowa Road [Kamlpur] [Total Length of Road-7 km. Submergeed Length-200m, Depth of Submergeed-10-6m., Chainage-450m on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur [Long - 26.494670, Lut - 91.667415). Surargano Dhaitar Road [Surargano Total Length of Road-1 5 km, Submerged Length-500 M. Depth of Submergeed-10-6m. Chainage-450m on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur [Long - 26.460905, Lut - 91.749042). kmmalpur Bota Road [Samapano Total Length of Road-1 5 km, Submerged length-500 M. Depth of Submergence - 4-5m Chainage-1st Km. 2nd KM. 3rd KM. 4th KM on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur [Long - 26.480905, Lut - 91.749042). kmmalpur Bota Road [Samapano Total Length of Road-1 5 km, Submerged length-500 M. Depth of Submergence - 4-5m Chainage-1st Km. 2nd KM. 3rd KM. 4th KM on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur [Long - 26.342817, Lut - 91.678704). Nagarbera - Hekra to nagarbera road submerged on 19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 [Clong - 26.347800, Lut - 91.38200)] Gossalgaon - Gurufela to Singimari Ruad [Curfela AS PER REPORT ON DATE 17.06-2022, AEB PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (-3.0000) [Jong - 0.00000, Lut - 0.00000, BADLY DAMAGED I KM (-3.0000) [Jong - 0.00000, Lut - 0.00000, BOKHABIL TO KUSHUMBIL [BOSHABIL LAS PER REPORT ON DATE 17.06-2022, AEB PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON KACHUGAON RASUB BUT TO HEAVY RAIN IMMEDIATE RESTORAT			Executive Engg, PWD Kamalpur (Long - 26.468458, Lat - 91.764116),
Executive Engg, PWD kamalpur (Long 26,292834, Lat91,799638), decumpant to pulsana IP. School via jagamanth marufer Palakama dara suba ID.compara (total length of road. 500m., submerged length 50m. depth of submergence. 60m chainage on 19/06/2022 is per report of Asst. Executive Engg. PWD kamalpur (Long 26,29363, Lat917,1102), Kamalpur Murowa Road Kamalpur (Total Length of Road. 7 km, Submerged Length 200m. Depth of Submerged -0.6m, Chainage -450m on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur (Long 26,346470, Lat91,667415), Sutargan Dibaliar Road Sturagan) Total Length of Road. 15 km, Submerged length 500 M, Depth of Submergence60m Chainage- 450 m on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur (Long26,346470, Lat91,678404), Road Length of Road. 15 km, Submerged length -500 M, Depth of Submergence450m Chainage- 15 km, 2nd km, 4m km on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur (Total Length of Road. 48 km, Submerged length -500 M, Depth of Submergence450m Chainage- 15 km, 2nd kM, 4m km on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur (Long26,342817, Lat91,678704), Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EF PWD Bokot territorial sub-division dated 20-6-2022 Long26,347800, Lat91,382000 Gossaigona - Gaurdelia to Singurar Road Guriela AS PIER REPORT ON DATE 7,06,3022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANIENT RESTORATION ON GURUFFELA TO SINGIMARI ROAD BADLY DAMAGED 1 km (L-3000M) Long0000000, Lat0000000), BOSHABIL TO KUSHIMBIL BOSHABIL (PMG8V) ROAD BADLY DAMAGED AT 2 km (L-20000M) Long0000000, Lat0000000), GOSSAIGAON SARABBIL ROAD TO BALAGAON SANKOSH ROAD TO DUMBAJHAR DAMBAGED APP W KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTO			
deoutpara to paikana LP School via jagannath mandir Paikana dura suba I Deoutpara (total length of road-500m, submerged length-50m, depth of submerged-co-60m changes on 19:06:0022 as per report of Asst. Executive Engg, PWD kamulpur (Leng - 26:293963, Lat - 01-171102), Kamulpur Morrova Road Kamulpur I Total Length of Road-7 km, Submerged Length-200m, Depth of Submerged-06m, Chainga-48th on 19:06:022 as per report of Asst. Executive Engg, PWD kamulpur (Long - 26:346470, Lat - 9):667415). Surrayaon Dibuliars Road Stutagaon Total Length of Road-1 km, Submerged length-500 M, Depth of Submergence - 40m Chainage-450 m on 19:06:2022 as per report of Asst. Executive Engg, PWD kamulpur (Long - 26:40905), Lat - 91:749427). kamulpur Borda Road Km, Submerged length-500 M, Depth of Submergence - 40m Chainage-1450 m on 19:06:2022 as per report of Asst. Executive Engg, PWD kamulpur I (Long - 26:40905), Lat - 91:749427). kamulpur Borda Road Kamulpur Cond - 26:74871, Lat - 91:75704). Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road Nagarbera Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19:6-2022 has been reported by EE PWD Boko territorial sub-division dated 20:6-2022 (Long - 26:34871, Lat - 33:3000) Gossalgaon - Gurufela to Singimuri Road Gurifela AS PER REPORT ON DATE 17:06:2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTOR ATTON ON GURUFFILA TO SINGIMARI ROAD BADI.Y DAMAGED 1 KM (1-3:00001), (Long - 00:00000, Lat - 00:00000), BOSHABIL. TO KUSHUMBI. BOSHABIL. AS PER REPORT ON DATE 17:06:2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL. RUSHMIR. PRINCAY RAIN PERMANENT RESTORATION ON BOSHABIL. RUSHMIR. PRINCAY RAIN PERMANENT RESTORATION ON SACHUGAON SANKOSH ROAD TO BALAGAON SANKOSH ROAD TO BALAGAON SANKOSH ROAD TO BALAGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17:06:2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON			
length of road-500m, submerged length-50m, depth of submergence-60m chainage on 19:06:02022 as per report of Asst. Executive Engg. PVD kamalpur [Long - 26.293963, Lat - 9].711102). Kamalpur Mornwa Road Kamalpur Total Length of Road-7 Am, Submerged Length-200m, Depth of Submerged-0.6m., Chainage-450m on 19:06:2022 as per report of Asst. Executive Engg. PVD kamalpur [Long] - 26.344670, Lat - 9].667415), Sutragano Dimitara Road Sutargano Total Length of Road-15 Km, Submerged length-500 M, Depth of Submergence60m Chainage-450 m on 19:06:2022 as per report of Asst. Executive Engg. PVD kamalpur [Long - 2.646905, Lat - 9].749042), kamalpur Borka Road Kamalpur Total Length of Road-8 Km, Submerged length-500 M, Depth of Submergence45m Chainage-1 Km, 204 KM, 40 KM on 19:06:2022 as per report of Asst. Executive Engg. PVD kamalpur [Long - 26.342817, Lat - 9].678704), Nagarbera - Hokra to nagarbera road Nagarbera Hekra to magarbera road Nagarbera Hekra to magarbera road 20.6-2022 (Long - 26.347800, Lat - 9].382000) Gossaigano - Giurifati no Singmari Road Gurifati AS PER REPORT ON DATE 17.06.2022, AEE PVD K ACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURLEFELA TO SINGMARIA ROAD BADLY DAMAGED KM (L-30.000h) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARABIL TO KUSHMBII, KUSUMBII, (PMGSY) ROAD BADLY DAMAGED AT2 KM (L-20.0000h) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARABIL ROAD TO BALAGAON I SARABIL ROAD TO BALAGAON SANCHIBL ROAD TO BALAGAON SANCHIBL ROAD TO BALAGAON RA SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABII. KUSUMBII, (PMGSY) ROAD BADLY DAMAGED AT2 KM (L-20.0000h) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARABIL ROAD TO BALAGAON RA SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON ROAD RAID AGAON RA SUB DIVISION DUE TO HEAVY RAIN REPROAD TO BALAGAON SANCOSH ROAD SUBMERGE AT 1 LOGGOODO, Lat - 0.000000), SANCOSH ROAD TO BALAGAON RA SUB DIVISION DUE TO HEAVY RAIN REPROAD RAIN RAIN RESTORATION ON KACHUGAON			
19-06/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 26.293963, Lat - 0-1.711102),			
- 91.711102). Karnalpur Morrowa Road Kamulpur Total Length of Road- 7 km, Submerged Length - 200m, Depth of Submerged-Lofm, Chainage-450m on 19/06/2022 as per report of Assi. Executive Engg. PWD kamalpur (Long - 26.344670, Lat - 91.667415). Suttragnon Dibuliara Road Sutragnon Total Length of Road-1.5 km, Submerged length - 500 M. Depth of Submergence - 450m Chainage-450 m on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur Clorg - 26.404905, Lat - 91/439942). kamalpur Borka Road Kamalpur Total Length of Road-1.5 km, Submerged length - 500 M, Depth of Submergence - 450m Chainage-1 St Km, 20 kM, 40 kM on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur (Long - 26.342817, Lat - 91.678704). Negarbera - Hekra to nagasbera road Nagasbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EP PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.347800, Lat - 91.882000) Gossaigaon - Gaurileta to Singimari Road Gurfela AS PER REPORT ON DATE 7.06.2022, AEP PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED I RM (1-39.0001) (Long - 0.00000), Lat - 0.0000000), BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEP PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSHMBIL PMGSV) ROAD BADLY DAMAGED AT 2 KM (1-200.000M) (Long - 0.00000), Lat - 0.000000), GOSSAIGAON SARAIBIL, ROAD TO BALAGAON SARABBIL AS PER REPORT ON DATE 17.06.2022, AEP PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARABIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD TO BALLAMHORA BALLAMHORA BALLAMHORA AS PER REPORT ON DATE 17.06.2022, AEP PWD KACHUGAON RANKOSH ROAD TO BALLAMHORA DAVASHI L'S CHE PWD KACHUGAON SANKOSH ROAD TO BALLAMHORA AS PER REPORT ON DATE 17.06.2022, AEP PWD KACHUGAON RANKOSH ROAD TO BALLAMHORA AS PER REPORT ON DATE 17.0			
Kamalpur Morowa Road Kamipur Total Length of Road-7 km, Submerged Length- 200m, Depth of Submerged-0 on, Chainage-450 mn on 1906/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 26.346470, Lat - 91.667415). Sutargaon Dinatiara Road Sutargaon Total Length of Road-1.5 Km, Submerged length- 500 M. Depth of Submergence60m Chainage- 450 m on 1906/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 20.466905, Lat - 91.749042), kamalpur Borka Road Kamalpur Total Length of Road-8 Km. Submerged length -500 M, Depth of Submergence45m Chainage- 1st Km. 2ad KM, 3rd KM, 4th KM on 19/06/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 26.342817, Lat - 91.678704), Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.34780), Lat - 91.382000) Gossaigaon - Grurella to Singimar Road Gurfela AS PER REPORT ON DATE 17.06.2022, ASE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFFLA TO SINGIMARI ROAD BADL'Y DAMAGED I KM (L-30.00M) (Long - 0.000000, Lat - 0.000000). BOSHABIL TO KUSHUMBIL BOSHABIL LAS PER REPORT ON DATE 17.06.2022, ASE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL LUS MIBIL PURGENY ROAD BADL Y DAMAGED AT 2 KM (L-200.00M) (Long - 0.000000). Lat - 0.000000). GOSSAIGAON SARABIL ROAD TO BALAGAON SARABIBL AS PER REPORT ON DATE 17.06.2022, ASE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PREMANENT RESTORATION ON GOSSAIGAON SARABIL ROAD TO BALAGAON SARABOSH ROAD TO BALAGAON SANKOSH ROAD TO DUMBAHHAR DUMBAHHAR AS PER REPORT ON DATE 17.06.2022, ASE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON RA SUB DIVI			
200m. Depth of Submerged-0.6m., Chainage-450m on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur (Long. 2-6.344670, Lat. 2-9.1667415). Suturgation Dhadiura Road Suturgation Total Length of Road-1.5 Km., Submerged length 500 M. Depth of Submergence 60m Chainage- 450 m on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur (Long. 2-26.46098), Lat 91-749942). karmalpur Borka Road Kamalpur Total Length of Road-8 Km., Submerged length - 500 M, Depth of Submergence 48m Chainage- 18 Km. Azad KM., at KM. and protected by 16-67202 as per report of Asst. Executive Engg. PWD kamalpur (Long 26.342817, Lat 91.678704). Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-62021 by English hene reported by FE PWD Roko territorial sub-division dated 20-6-2022 (Long 26.347800, Lat 91.382000) Gossalgano - Gurifela to Singimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURLIFELA TO SINGIMARI ROAD BADLY DAMAGED I KM. (L-30.0000) (Long00.00000). Lat 00.00000). BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN RESTORATION ON BOSHABIL ROAD TO BALAGAON SARABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN REMANNENT RESTORATION ON KACHUGAON SANKOSH ROAD DUSTON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long0.000000). Lat0.000000). SANKOSH ROAD TO DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD DUDIMBAHARA DAMAGED DHP CULL-VERF NO. 5/2 (Long0.000000). Lat0.0000			
Executive Engg, PWD kamalport [Long - 26.346470, Lat - 91.667415). Sunargaon Dimilara Road [Surargaon] Total Length of Road - 1.5 km, Submerged length - 500 M. Depth of Submergence60m Chainage- 450 m on 19/06/2022 as per report of Asst. Executive Engg, PWD kamalpur [Long - 26.46095, Lat - 91.749042), kumulpur Borka Road I (Kamalpur Total Length of Road-8 km. Submerged length - 500 M, Depth of Submergence45m Chainage- 1st km. 2nd KM, 3rd KM, 4th KM on 19/06/2022 as pre report of Asst. Executive Engg, PWD kamalpur [1 (Long - 26.34817), 4th KM on 19/06/2022 as pre report of Asst. Executive Engg, PWD kamalpur [1 (Long - 26.34817), 21.4 91.678704), Nagarbera - Hekra to nagarbera road [Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by FE PWD Roko territorial sub-division dated 20-6-2022 (Long - 26.347800, Lat - 91.382000) Gossaligaon - Gurufela to Singimari Road [Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GUNTEFLAT OS INGIMARI ROAD BADLY DAMAGED I KM (I=30.0001) [(Long - 0.000000, Lat - 0.000000), BOSIABIT TO KUSHUMBIL [BOSHABIL] AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGNY) ROAD BADLY DAMAGED AT 2 KM (I=200.000M) [(Long - 0.000000), Lat - 0.000000), GOSSAIGAON SARABIBI. ROAD TO BALAGAON [SARABIBL] ROAD TO BALAGAON SANKOSH ROAD SUBTOR HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARABIBL ROAD TO BALAGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM [(Long - 0.000000), Lat - 0.000000), KACHUGAON RAS UB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM [(Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA [JBALLAMJHORA] AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERTNO. 52] (Long - 0.000000), Lat - 0.000000), Sapatgram Tipkai Road			
Suargaon Diuliara Road Suargaon Total Length of Road-1.5 km, Submerged length - 500 M, Depth of Submergence60m Chainage-450 mon 1906/2022 as per report of Asst. Executive Engg. PWD Ramalpur Iclong - 26.460905, Lat. 91.749042), kamalpur Borka Road Kamalpur Total Length of Road-8 km, Submerged length -500 M, Depth of Submergence48m Chainage-18 km, 2nd km, 3rd kM, 4th km on 1906/2022 as per report of Asst. Executive Engg, PWD kamalpur Iclong - 26.342817, Lat 91.6578/04), Nagarrbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 Iclong - 26.347800, Lat 91.382000) Gossaigaon - Guriclia to Singimari Road Guricla AS PER REPORT On DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED I kM (1-30.0000) Icl ong - 0.000000, Lat0.000000). BOSHABIL TO KUSHUMBIL BOSHABIL SPER REPORT ON DATE I7.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSHUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (1-200.000M) [Iclong - 0.000000, Lat0.000000). GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARABIBL AS PER REPORT ON DATE 17.06.2022, AFE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BANDLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 Iclong - 0.000000, Lat0.000000, KACHUGAON SANKOSH ROAD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RISTORATION ON NA KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM Iclong - 0.000000, SANKOSH ROAD TO BALLAMHHORA BALLAMHHORA AS PER REPORT ON DATE 17.06.2022, AFE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAHAR DAMAGED HP CULVERT NO. 5/2 Iclong - 0.000000, Lat - 0.000000, SANKOSH ROAD TO DUMBAHAR DUMBAHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IM			
S00 M. Depth of Submergence60m Chainage - 450 m on 19/06/2022 as per report of Asst. Executive Eng. PWD kamalpur Clong - 26.460905. Lat - 9.17.4005. Lat - 9.17.4005. kamalpur Borka Road Kamalpur Total Length of Road-8 Km, Submerged length -500 M, Depth of Submergence45m Chainage - 1st Km, 2nd KM, 3rd KM, 4th KM on 19/06/2022 as per report of Asst. Executive Eng. PWD kamalpur Clong - 26.342817, Lat - 91.6787044), Nagarbera - Hickra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.347800, Lat - 91.382000) Gossaigaon - Gurufela to SIngimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L=30.004) (Long - 0.000000), Lat - 0.000000), BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL PMGSY) ROAD BADLY DAMAGED AT 2 KM (L=200.00M) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED AT 2 KM (L=200.00M) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED ADAMAGED AT 2 KM (L=200.00M) (Long - 0.000000, Lat - 0.000000), KACHUGAON SANKOSH ROAD TO BALAGAON BADLY DAMAGED APPROACHO F RCC BRIDGER OZ (Long - 0.000000), KACHUGAON SANKOSH ROAD TO BALAGAON BADLY DAMAGED APPROACHO F RCC BRIDGER OZ (Long - 0.000000), Lat - 0.000000), Lat - 0.0000000, Sankigaran Tipkait Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported			
Asst. Executive Engg. PWD kamalpur Clong - 26.460905, Lat. + 91.749042), kamalpur Borka Road Kamalpur Total Length of Road & Km. Submerged length - 500 M, Depth of Submergence - 45m Chainage- 1st Km, 2nd KM, 3rd KM, 4th KM on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur Clong - 26.342817, Lat. + 91.6787641), Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 Long - 26.347800, Lat 91.382000) Gossilgaon - Gurufela to Singimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L. =30.0000) Long - 0.000000, Lat 0.000000), BOSHABIL TO KUSHUMBIL BOSHABIL, AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L. = 200.0004) Long - 0.000000, GOSSAIGAON SARABIBL ROAD TO BALAGAON SARABIBL. AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON ROSSAIGAON SARABIBL. ROAD TO BALAGAON BADLY DAMAGED AT 2 KM (L. = 200.0004) Long - 0.000000, GOSSAIGAON SARABIBL. ROAD TO BALAGAON RAID SARABBL. ROAD TO BALAGAON SANABIB. ROAD TO BALAGAON SANABOSH ROAD TO BALAGAON SANABOSH ROAD TO BALAGAON SANABOSH ROAD TO BALAGAON SANKOSH ROAD TO BALAGAON SANKOSH ROAD TO BALAGAON SANKOSH ROAD SUBMERGE AT 22 KM MND 24 KM (Long - 0.000000, Lat - 0.000000). Lat - 0.000000, SANKOSH ROAD TO BALJ AMHHORA BALJ AMHORA BALJ BALJ BALJ BALJ BALJ BALJ BALJ BALJ			
kamalpur Borka Road [Kamalpur Total Length of Road-8 Km, Submerged length -500 M. Depth of Submergence45m Chainage- 1st Km, 2nd KM, 3rd KM, 4th on 19/06/2022 as per report of Asst. Executive Engg. PWD kamalpur [(Long - 26.342817, Lat - 91.678704). Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.347800, Lat - 91.382000) Gossaigaon - Gurufela to Singimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFEIA TO SINGIMARI ROAD BADLY DAMAGED 1 kM (L=30.00M) Long - 0.000000). Lat - 0.000000). BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFEIA TO SUB PROPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L=200.00M) Long - 0.000000). Lat - 0.0000000, GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RA SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 21 (Long - 0.000000). KACHUGAON SANKOSH ROAD KACHUGAON SANKOSH ROAD SUBMERGE AT 2 KM AND 24 KM (Long - 0.000000). KACHUGAON SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR DUMBAJHAR			
Depth of Submergence45m Chainage- 1st Km, 2nd KM, 3nd KM, 4th KM on 19/06/2022 as per report of Asst. Executive Engg, PWD kamalpur (Long - 26.342817, Lat - 91.678704), Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 (Long - 26.347800, Lat - 91.382000) Gossalgano - Gurifela to Singimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUIFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L30.0004) (Long - 0.000000, Lat - 0.000000), BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L200.0001) (Long - 0.000000), Lat - 0.000000), GOSSAIGAON SARABIBL ROAD TO BALAGAON SARABIBL ROAD TO BALAGAON SARABIBL ROAD TO BALAGAON SARABIBL ROAD TO BALAGAON RS SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARABIBL ROAD TO BALAGAON RA SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARABIBL ROAD TO BALAGAON RAIN SARABIBL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), Lat - 0.000000), KACHUGAON SANKOSH ROAD TO BALAGAON SANKOSH ROAD TO BALAGAON SANKOSH ROAD TO BALAGAON SANKOSH ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD TO BALLAMIHORA BAL			
as per report of Asst. Executive Engg., PWD kamalpur (Long - 26.342817, Lat - 91.678704), Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EF. PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.344800, Lat 91.382000) Gossaigaon - Gurufela to Singimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L=30.00M) (Long - 0.000000, Lat - 0.000000), BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL (MGSY) ROAD BADLY DAMAGED AT 2 KM (L= 200.00M) (Long - 0.000000), Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARABBIL. AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON SANKOSH ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, L			
91.678704), Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.347800, Lut - 91.382000) Gossaigaon - Guurdela to Singimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L=30.00M) (Long - 0.000000, Lut - 0.000000), BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT2 KM (L=200.00M) (Long - 0.000000, Lut - 0.000000), GOSSAIGAON SARABIL ROAD TO BALAGAON SARABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARABIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), Lat - 0.000000), Lat - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON RAS SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON S			
Nagarbera - Hekra to nagarbera road Nagarbera Hekra to nagarbera road submerged on 19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.347800, Lat - 91.382000) Gossaigaon - Gurufela to SIngimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L-30.00M1) (Long - 0.000000, Lat - 0.000000), BOSHABBIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL CAN SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARABIBI. ROAD TO BALAGAON SARABIBI. AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARABIBI. ROAD TO BALAGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON K ACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000), SANKOSH ROAD TO BALLAMIHORA BALCAMIHORA BALLAMIHORA BALLAMIHO			
19-6-2022 has been reported by EE PWD Boko territorial sub-division dated 20-6-2022			′′
Gossaigaon, Tourlela to Singimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L=30.00M) (Long - 0.000000), Lat - 0.000000), and - 0.000000, boSHABIL TO KUSHUMBIL, BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL, PMGSY) ROAD BADLY DAMAGED AT 2 KM (L=200.00M) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARABIL ROAD TO BALAGAON ISARABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL, PMGSY) ROAD PO 2/1 (Long - 0.000000, Lat - 0.000000, KACHUGAON SANKOSH ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000, Lat - 0.000000), KACHUGAON SANKOSH ROAD AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS REPORTED BY AEE, PWD RR GOSSAIGAON, croded in some stretches on 18.06.2022 (Long - 0.000000), Lat - 0.000000), SARROST ROAD TO SUBMARINA TO SUBM			
Gossaigaon - Gurufela to Singimari Road Gurfela AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L=30.00M) (Long - 0.000000), Lat - 0.000000), BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L=200.00M) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON RA SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GASAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguir PWD road. Goranimari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd K			i i
17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L=30.00M) [Long - 0.000000, Lat - 0.000000], BOSHABIL TO KUSHUMBIL [BOSHABIL JAS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L=200.00M) [Long - 0.000000, Lat - 0.000000], GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL JAS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 [Long - 0.000000, Lat - 0.000000], KACHUGAON SANKOSH ROAD I MACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM [Long - 0.000000], Lat - 0.000000], SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RA SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 [Long - 0.000000, Lat - 0.000000], Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been admaged on 18			
PERMANENT RESTORATION ON GURUFELA TO SINGIMARI ROAD BADLY DAMAGED 1 KM (L=30.00M) (Long - 0.000000, Lat - 0.000000), BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L= 200.00M) (Long - 0.000000), Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL RAS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON PRODOROU, Lat - 0.000000), KACHUGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road, Panbari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road Snanghat As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been submerged on 18.06.2022 (Long - 0.00000			
DAMAGED 1 KM (L=30.00M) [(Long - 0.000000, Lat - 0.000000), BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L=200.00M) [(Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000, Lat - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO BALLAMHORA BALLAMHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000), Lat - 0.000000), Bagribari - Gendabil market to Panbari road, Panbari Tas, teported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gao			·
BOSHABIL TO KUSHUMBIL BOSHABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L= 200.00M) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB BIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB BURGEG AT 1 KM (Long - 0.000000), Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR GOSSAIgaon, road surface has been damaged on 18.06.2022 (Long - 0.000000			
AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L= 200.000) (Long - 0.000000), Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000, Lat - 0.000000), Lat - 0.0000000, KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO BALLAMHHORA BALLAMHHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMHHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road IA 376 KM As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022 Report received from PWRD			
RESTORATION ON BOSHABIL KUSUMBIL (PMGSY) ROAD BADLY DAMAGED AT 2 KM (L= 200.00M) (Long - 0.000000), Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARABIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARABIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), Lat - 0.000000), KACHUGAON BANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON ROBUSISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS RUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000), Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, croded in some stretches on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Bashbari Mowamari PMGSY Road A1 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000)			·
AT 2 KM (L= 200.00M) (Long - 0.000000, Lat - 0.000000), GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000, Lat - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000), SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000), Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, road via Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road via Charle has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, croded in some stretches on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, croded in some stretches on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022 Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000			
GOSSAIGAON SARAIBIL ROAD TO BALAGAON SARAIBIL AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000, Lat - 0.000000), KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA BALLAMIHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMIHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR PESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000), Lat - 0.000000), Bagribari - Gendabii market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000). Nowboicha - Dalap			
ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000, Lat - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000)			
RAIN PERMANENT RESTORATION ON GOSSAIGAON SARAIBIL ROAD TO BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000), Lat - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS UB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RS UB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000, Lat - 0.000000), EANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PWGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PWGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PWGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000)			
BALAGAON BADLY DAMAGED APPROACH OF RCC BRIDGE NO 2/1 (Long - 0.000000, Lat - 0.000000), KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabii market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Lat - 0.000000), Condotto Nowboicha - Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Condotto Nowboicha - Dalapapathar HP Culvert no 2/1 and approaches are damaged			
Committee Comm			
KACHUGAON SANKOSH ROAD KACHUGAON AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road das been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), To and has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), To and has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), To and has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), To and has been submerged on 18.06.2022 (Long - 0.000000), Lat - 0.000			
Kokrajha r 11 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022, Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			′ ′′
Kokrajha T IIMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD SUBMERGE AT 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000)			· · ·
Kokrajha r 11 22 KM AND 24 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000), Lat - 0.000000),			·
Kokrajha r SANKOSH ROAD TO BALLAMJHORA BALLAMJHORA AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
TO DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000), Lat - 0.000000), Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			i i i i i i i i i i i i i i i i i i i
RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000), Lat - 0.000000),	Kokrajha	11	· · · · · · · · · · · · · · · · · · ·
BALLAMJHORA ADIVASHI LP SCHOOL SUBMERGE AT 1 KM (Long - 0.000000, Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),	r		·
Lat - 0.000000), SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE 17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
17.06.2022, AEE PWD KACHUGAON RR SUB DIVISION DUE TO HEAVY RAIN IMMEDIATE RESTORATION ON KACHUGAON SANKOSH ROAD TO DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			SANKOSH ROAD TO DUMBAJHAR DUMBAJHAR AS PER REPORT ON DATE
DUMBAJHAR DAMAGED HP CULVERT NO. 5/2 (Long - 0.000000, Lat - 0.000000), Bagribari - Gendabil market to Panbari road. Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			· · · · · · · · · · · · · · · · · · ·
Bagribari - Gendabil market to Panbari As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Sapatgram Tipkai Road Via Dudumari village Dudumari As reported by AEE, PWD RR Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Gossaigaon, road surface has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
0.000000), Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Mahamaya Mandir to Snanghat Road Snanghat As reported by AEE, PWD RR Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Gossaigaon, eroded in some stretches on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			· ·
Tipkai to Goroimari via Belguri PWD road. Goraimari As reported by AEE, PWD RR Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Gossaigaon,, road has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Bashbari Mowamari PMGSY Road At 3rd KM As reported by AEE, PWD RR Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Gossaigaon,, road has been submerged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			
Lakhimp ur Nowboicha - Dalapapathar Thengal Kachari Gaon Road Dalapapathar HP Culvert no 2/1 and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),			· · · · · · · · · · · · · · · · · · ·
Lakhimp ur and approaches are damaged on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),		-	
ur Territorial Road Sub-Division. (Long - 0.000000, Lat - 0.000000),	T a1-1-1		
	_	10	
NITES to Dorgoya Koad Borgoya Koad embankment and shoulder erosion, road hard	ur		
	<u> </u>	<u> </u>	191115 to Borgoya Koau Borgoya Koau embankment and shoulder erosion, road hard

crust damaged badly in The chainages CH: 2250.00m to CH:3200.00m due to spilway of flood water on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. | (Long - 0.000000, Lat - 0.000000), Pukhuria to Boloma Road | Boloma | Road embankment and shoulder erosion, road hard crust damaged in the chainages CH: 2200.00m to CH:3000.00m and CH:3950.00m to CH:4450.00m due to spilway of flood water on 18.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division. | (Long - 0.000000, Lat - 0.000000), Phulbari Naharani Road | Phulbari | 1. Slab Culvert no 9/1 at CH:8200.00m and approaches is badly damaged due to flood water spilway. 2. Hume Pipe culvert no.9/2 at CH: 8265.00m and approaches is being washed away due to flood water spilway. Report received from PWRD Nowboicha Territorial Road Sub-Division on 18.06.2022. | (Long - 0.000000, Lat -0.000000), Ahmedpur Kutubpur to Gorchiga PWD Road | Gorchiga | Road overtopped and submerged for a length of 300.00m with depth of 0.70m at CH: 9400.00m to CH: 9700.00m, damaged hard crust, shoulder and road embankment. And disrupting run of vehicular traffic. Report received from PWRD Nowboicha Territorial Road Sub-Division on 20.06.2022. | (Long-0.000000, Lat - 0.000000), Ahmedpur Kutubpur to Gorchiga PWD Road | Gorchiga | Road overtopped and submerged for about 0.30m depth, damaged hard crust, shoulder and road embankment at CH:10900.00m to CH:10950.00m. Embankment damaged for a length of 50.00m. Report received from PWRD Nowboicha Territorial Road Sub-Division on 20.06.2022 | (Long -0.000000, Lat - 0.000000), Ahmedpur Kutubpur to Gorchiga PWD Road | Gorchiga | Road overtopped and submerged about 0.30m depth at CH:7100.00m to CH:9400.00m in average at different stretches. Damaged hard crust, shoulder and road embankment at different stretches. Report received from PWRD Nowboicha Territorial Road Sub-Division on 20.06.2022. | (Long - 0.000000, Lat - 0.000000), NH15 at Dolohat to Pandhowa Road | Pandhowa | Road overtopped and submerged about 0.30m depth at CH:62000.00m to CH:9500.00m in average at different stretches. Damaged hard crust, shoulder and road embankment at different stretches. Report received from PWRD Nowboicha Territorial Road Sub-Division on 20.06.2022 | (Long - 0.000000, Lat -0.000000), Subansiri - Gogamukh Majuli E&D to Bamgaon Tinali Road | CH 400 MTR to 700 MTR | The road submerged at 1st KM (CH 400 MTR to 700 MTR) L-300 M reported by PWRD Territorial Rod Divn., Dhakuakhana, Ghilamara on 20/06/2022 | (Long - 0.000000, Lat -0.000000), Kekuri Madhupur to Balijan Kachari Road | Balijan Kachari Road | The road submerged L-60.00 M reported by PWRD Territorial Rod Divn., Dhakuakhana, Ghilamara on 20/06/2022 | (Long - 0.000000, Lat - 0.000000) Morigaon - NH-37 to Natun Makaria Road (19-06-2022) | Natun Makaria, Morigaon | As per PWD(Roads), NH-37 to Natun Makaria Road submerged at 1st KM & 2nd KM | (Long - 92.305575, Lat - 26.112203), Basanaghat Khandajan to Bordoipathar via Ajarbari Road (20-06-2022) | Basanaghat, Morigaon | As per PWD(Roads), Basanaghat Khandajan to Bordoipathar via Ajarbari Road (PMGSY PKG NO: AS-17-245) submerged at 1st and 2nd KM. | (Long - 92.305944, Lat -26.220270). Mayong - Diprang Buraburi | 1st,2nd,3rd, and 4th km | as reported by PWD Morigaon district territorial road division on 20/06/22 | (Long - 92.101000, Lat - 26.217000), Kopoujari to Japori | Submerged at 1st and 2nd km | As reported by PWD Morigaon district Morigaon territorial road division on 20/06/22 | (Long - 92.174000, Lat - 26.296000), Chotogorjan to Karchuwabori road | Submerged at 5th and 6th km | as reported by PWD Morigaon district territorial road division on 20/06/22 | (Long - 92.141000, Lat -26.267000). Chotogamariguri road | Submerged at 1st km | As reported by PWD Morigaon district territorial road division on 20/06/22 | (Long - 92.214000, Lat - 26.265000), DK Road | Submerged and damaged at stretches | As reported by PWD Morigaon district territorial road division on 19/06/22 | (Long - 92.135000, Lat - 26.174000), Garmari to Bargarmari road | Submerged at 2nd km | As reported by PWD Morigaon district territorial road division on 19/06/22 | (Long - 92.222000, Lat - 26.268000) Nagaon - Nagaon Dakhinpat kampur Road | Dakhinpat to Kampur, Nagaon | Nagaon Nagaon 51 Dakhinpat kampur Road, Damaged/ Submerged reported by Nagaon Territorial Road Division, Length- 13th to 18th km, dated-20/06/2022 | (Long - 0.000000, Lat - 0.000000),

Raha - Rahachaki Hariamukh Meteka road | Durgajan | Date of Occurrence-19/06/2022 Submerged-0.70 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Kampur Chaparmukh Raha SH-17 Road | Chaparmukh | Date of Occurrence-19/06/2022 Submerged-2 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Dakhinpat to Dighaldari via Baligaon | Dighaldari | Date of Occurrence-19/06/2022 Submerged-3.55 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Baligaon to Dakhinpat | Baligaon | Date of Occurrence-19/06/2022 Submerged-3 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Ma Basundhari Than to Pachimbulla via Sirmola | Ma Basundhari Than | Date of Occurrence-19/06/2022 Submerged-400 m Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Laopani to Morteng Pathar | Laopani | Date of Occurrence-19/06/2022 Submerged-2.05 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Laopani to Timunggaon | Laopani | Date of Occurrence-19/06/2022 Submerged-1 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Jukuta Khaigarh road to Midaimari | Khaigarh | Date of Occurrence-19/06/2022 Submerged-1.23 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Pahupurikhaiti to hugalitoli | Pahuparikhaiti | Date of Occurrence-19/06/2022 Submerged-0.72 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000).

Raha college approach road | Raha | Date of Occurrence-19/06/2022 Submerged-0.70 km Department- Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), **Kampur** - Road from Missamari to Sumeswari Colony | Kampur | Road from Missamari to Sumeswari Colony [PMGSY Pkg No. AS-19-452]: Affected length approx. L = 2.16 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Missamari 1 to Kalinagar | Kampur | Road from Missamari 1 to Kalinagar [PMGSY Pkg No. AS-19-432]: Affected length approx. L=2.40 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Missamari 1 to Rajabazarbasti [PMGSY Pkg No. AS-19-440]: Affected length approx. L = 2.05 Km. | Kampur | Road from Missamari 1 to Rajabazarbasti [PMGSY Pkg No. AS-19-440]: Affected length approx. L = 2.05 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Road from Phalihamari to Ram Nagar | Kampur | Road from Phalihamari to Ram Nagar [PMGSY Pkg No. AS-19-453]: Affected length approx. L = 1.02 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Sihupara to Tripurabasti | Kampur | Road from Sihupara to Tripurabasti [PMGSY Package no. AS-19-401]: Affected length approx. L=1.56 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from KSB Road to Panditghat | Kampur | Road from KSB Road to Panditghat [PMGSY Pkg .No. AS-19-241]: Affected length approx. L=2.50 Km. Breach occurred at 1st Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from KSB Road to Ujanmari via Ramanipathar | Kampur | Road from KSB Road to Ujanmari via Ramanipathar [Pkg No. AS-19-104]: Affected length approx. L=3.00 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from KSB Road to Fakali via Birinaati. | Kampur | Road from KSB Road to Fakali via Birinaati. Affected length approx. L = 5.00 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from KSB Road to Changkhula via Kachuabazar | Kampur | Road from KSB Road to Changkhula via Kachuabazar. Affected length approx. $L=8.00~\rm Km.~Dtd-19.06.2022$ reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Majgaon Chariali to Changkhula RCC Bridge. | Kampur | 15) Road from

Majgaon Chariali to Changkhula RCC Bridge. Affected length approx. L = 8.00 Km Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Kuhimari No. 1 to Shimlaipathar via ujagaon | Kampur | Road from Kuhimari No. 1 to Shimlaipathar via ujagaon [PMGSY Pkg No. AS-19-524]: Affected length approx. L = 4.00 Km. Breach occurred at 3rd & 4th Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

SH-18 Kampur-Singimari-Baithalangsu Segment | Kampur | SH-18 Kampur-Singimari-Baithalangsu Segment Affected from 26th Km to 36th Km. Approx. L=10.00 Km. Breach occurred at 28th and 29th Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Pramilaati to Baligaon | Kampur | Road from Pramilaati to Baligaon [PMGSY Pkg No. AS-19-553]: Affected length approx. $L=1.60~\rm Km.$ Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Road from Leprosy Coloney to Makhangaon | Kampur | Road from Leprosy Coloney to Makhangaon [PMGSY Pkg No. AS-19-104]: Affected length approx. $L=1.50~\rm Km.$ Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000), Lat - 0.000000),

Road from Borchali to Udmari | Kampur | Road from Borchali to Udmari. Affected length approx. L=3.00 Km. Breach occurred at 2nd Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Rajagaon to Chitalmari. | Kampur | Road from Rajagaon to Chitalmari. Affected length approx. L=1.00 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Singimari to Chitalmari. | Kampur | Road from Singimari to Chitalmari. Affected length approx. L = 1.00 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Kachua Tiniali to Alitangoni. | Kampur | Road from Kachua Tiniali to Alitangoni. Affected length approx. $L=1.00~\rm Km$. Eroded Bridges approached badly. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Ghilani to Madhabpara via Simaluguri, Pothimari. | Kampur | Road from Ghilani to Madhabpara via Simaluguri, Pothimari. Affected length approx. L=13.00~km. Braech occurred at different locations. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Puthimari to Puthimari 1 | Kampur | Road from Puthimari to Puthimari 1. Affected length approx. L = 3.00 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000),

Road from SH-17 to Niznarikali via Bareguga. | Kampur | Road from SH-17 to Niznarikali via Bareguga. Affected length approx. L = 1.50 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

Road from Kuwariati to Dhemajigaon | Kampur | Road from Kuwariati to Dhemajigaon. Affected length approx. L = 2.00 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000),

Road from Jukuta to Bamunithan | Kampur | Road from Jukuta to Bamunithan [PMGSY Pkg No. AS-19-455]: Affected length approx. L = 1.55 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Road from Jukuta to Jukuta Camp | Kampur | Road from Jukuta to Jukuta Camp [PMGSY Pkg No. AS-19-403]: Affected length approx. L = 1.02 km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Road from Madhabpara Simaluguri Raod to Jukuta. | Kampur | Road from Madhabpara Simaluguri Raod to Jukuta. Affected length approx. L = 1.90 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Road from Chnagkhula to Domaihagi | Kampur | Road from Chnagkhula to Domaihagi [PMGSY Pkg No. AS-19-147]: Affected length approx. L = 2.00 Km. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), Lat - 0.000000),

Road from Lutumari Chariali to Bakualaguri Tiniali. | Kampur | Road from Lutumari Chariali to Bakualaguri Tiniali. Affected length approx. $L=4.00~\rm Km$. Damaged one HP culvert. Dtd-19.06.2022 reported by PWRD, Raha Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000),

KATHIATOLI KAMPUR ROAD (SH-17) | Kampur | KATHIATOLI KAMPUR ROAD

(SH-17) AT 1ST, 2ND, 3rd,4th,5th, 6th,7th, 8th & 9th KM Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NAGAON-DAKHINPAT-KAMPUR-BAITHALANGSO ROAD (SH-18) | Kampur | NAGAON-DAKHINPAT-KAMPUR-BAITHALANGSO ROAD (SH-18) at 18th & 19th KM, Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), L046-TETELISORA TO PATIAPUM VIA MAJORATI RD, | Kampur | L046-TETELISORA TO PATIAPUM VIA MAJORATI RD, PMGSY, PACKAGE NO. AS-19-447. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), BHALBHALIAGAON TO BANPALIGAON | Kampur | BHALBHALIAGAON TO BANPALIGAON, PMGSY, AS-19-459. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), NH 36 TO PASCHIM KHALOI BHANGA VIA URIAGRANT TUBUKIGRANT | Kampur | NH 36 TO PASCHIM KHALOI BHANGA VIA URIAGRANT TUBUKIGRANT, PMGSY, AS-19-492. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), LUTUMARI LONGJUP RD TO JURIPARA, PMGSY, AS-19-527. | Kampur | LUTUMARI LONGJUP RD TO JURIPARA, PMGSY, AS-19-527. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long-0.000000, Lat - 0.000000), L043-KK RD AT TO TETELISORA GRANT | Kampur | L043-KK RD AT TO TETELISORA GRANT, PMGSY, AS-19-528. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat -0.000000), L065-CHARAIHAGI TO UTTAR CHANCHAKI GOHAINGAON | Kampur | L065-CHARAIHAGI TO UTTAR CHANCHAKI GOHAINGAON, PMGSY, PACKAGE NO. AS-19-554. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), L079-TETELICHARAGRANT TO TETELICHARA LALUNGAON | Kampur | L079-TETELICHARAGRANT TO TETELICHARA LALUNGAON, PMGSY, PACKAGE NO. AS-19-557. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), L-084 UJAGAON TO TINIGURIGAON, PMGSY, PACKAGE NO. AS-19-358. | Kampur L-084 UJAGAON TO TINIGURIGAON, PMGSY, PACKAGE NO. AS-19-358. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), L083-LUTUMARI LONGJUP RD TO LANKAGAON | Kampur | L083-LUTUMARI LONGJUP RD TO LANKAGAON, PMGSY, PACKAGE NO. AS-19-359. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000), L076-KSB ROAD TO ULUMGURI NC VILLAGE | Kampur | L076-KSB ROAD TO ULUMGURI NC VILLAGE, PMGSY, PACKAGE NO. AS-19-367. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long-0.000000, Lat - 0.000000), L040-KATHALGURI TO UPPER BORGAON LALUNGGAON RD | Kampur | L040-KATHALGURI TO UPPER BORGAON LALUNGGAON RD, PMGSY, PACKAGE NO. AS-19-370. Submerged/Damaged Dtd-20.06.2022, Reported by PWD(R)Barhampur Territorial Road Sub-Division | (Long - 0.000000, Lat - 0.000000) Paschim Nalbari - Solmara to Dakshin Bhojkuchi under PMGSY Package No. AS-20-171. Information received from PWRD deptt. on 17/06/2022. | Solmara | Submerged almost whole length of road ie 5.88 km | (Long - 0.000000, Lat - 0.000000), Nalbari Palla Road to Kaihati under PMGSY package No. AS-20-169 | Kaihati | Submerged from ch 10.00 to ch 1200.00 due to flood. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000), 69 Nalbari Amoni Bhakatpara to Chamata under PMGSY Package No. AS-20-106 | Amoni | Submerged from ch 600.00 m to Ch 1000.00 m. Side bern eroded. Road breached at ch 670.00 m on 17/06/2022 | (Long - 0.000000, Lat - 0.000000), Belsor to Sukekuchi via Gandhia Nabagrah Mandir under PMGSY Pkg No. AS-20-186 | Sukekuchi | Submerged from ch 100.00 to ch 3000.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000), Dahudi Ulubari to Bagurihati via Piplibari, Kaihati, Goalpara under PMGSY Pkg No. AS-

20-187 | Dahudi | Submerged at various stretches from ch 150.00-ch 2000.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000).

Solmara to Helacha Datepara Road under PMGSY Pkg No. AS-20-170. Information received from PWRD deptt. on 17/06/2022. | Solmara | Submerged due to flood ch 500.00 to Ch 4500.00. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Chamata Kaithalkuchi Road | Chamata | Road submerged in many stretches. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Kulbil Hirapara to Pahlangpara road | Hirapara | Submerged 500 m with depth 0.30 to 0.40 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Rupiabathan to SDC Office approach road | Rupiabathan | Submerged with depth of 0.40 to 0.70 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Kharsitha Madhupur Road. | Kharsitha | Road washed away at ch 1650.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Amoni to Bhakatpara Road | Amoni | Road overtopped in many stretches. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Gangapur Mohbiyani Road | Gangapur | Submerged. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Gadira SC Supa Road | Gadira | Submerged. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Sanimandal Road | Sanimandal | Submerged. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Ulubari to Solmara SC Supa Road | Solmara | Submerged length ch 100.00 to 800.00-700.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Khetri Dharmapur College to Tengabari | Tengabari | Submerged length ch.00 m to ch 500.00 m = 1500.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Chamata Rampur Road to Niz Tapa | Chamata | Submerged ch 500.00 m = 500.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Chamata Rampur road at Kasuapara to Banuarkur | Chamata | Submerged ch $0.00\ m$ to ch $1700.00=1200.00\ m.$ Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Natun Kheluwa to Solmara Satinpur Road | Natun Kheluwa | Submerged ch 0.00 m to 1900.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Dahudi High School to Solmara Helosa road via Sila Supa | Dahudi | Submerged ch 0.00 m to 1160.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Chamata Kaithalkuchi Road | Chamata | Breach occurred and wash away at Joward 10.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Pub Saniapar Namghar to Khetri Dharmapur College via Kakatipar | Saniapar | Submerged ch 0.00 m to 1500.00 m. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Kalopara Hari Mandir to THHS Road | Kalopara | Road submerged of total length 1700 m and depth 45 cm. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Road from Chariapar to Niz Tapa | Niz Tapa | Submerged for total length 550 m and depth 40 cm. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Helacha Kendubari Road to Dalepara Chupa | Helacha | Submerged for a total length 700 m and depth 35 cm on 17/06/2022 | (Long - 0.000000, Lat - 0.000000),

Chamata Rampur Road to Chamata Barnibari Road via F Ali Madrassa | Barnibari | Submerged for a length of 400 m and depth 15 cm. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Road from Chamata Rampur road to Dumurikhowa via Napara Supa | Chamata | Submerged for length of 400 m and depth 12 cm. Information received from PWRD deptt.

on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Helacha Kendubari road | Helacha | Submerged from ch 0.00 to 6000.00 cm. Information received from PWRD deptt. on 17/06/2022. | (Long - 0.000000, Lat - 0.000000),

Solmara Sorabari road | Solmara | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Solmara Pokhura Road | Solmara | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Ghilazari to Bhaira Solmari Road | Ghilazari | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Nalbari Palla road at Baruarpur to Pokhura road via Kathla | Pokhura | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000).

Amoni to Pokhura via Jokamari Road | Amoni | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000), Ulubari to Bori | Bori | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Dahudi High School to Solmara Helacha road via Sila Supa | Dahudi | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000).

Ulubari chowk to Solmara SC Supa via Dutta Supa | Solmara | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Solmara Pokhura road to Solmara Gopalthan | Solmara | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Solmara Pokhura road to Solmara SC Supa Namghar | Solmara | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Helacha Kendubari road to Kheluwa MV School via Baishya Supa | Helacha | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Natun Kheluwa to Solmara Satiripam road. | Kheluwa | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Amoni to Hatiputa Road | Hatiputa | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Chamata Rampur road at Kasuapar to Barurkur | Kasuapar | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000).

Chamata Rampur road to Niz Tapa via Bhadrakuchi | Niz Tapa | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Chamata Rampur road | Chamata | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Barbila chowk to Lakhopur via Sorabari | Barbila | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000),

Helacha Kendubari road to Barbila village road | Helacha | Submerged due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000).

Solmara to Dakhin Bhojkuchi | Solmara | Submerged PMGSY due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000), Solmara to Helacha Dalepara | Solmara | Submerged PMGSY due to flood. Information

received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000), Nalbari Palla road to Kaihati | Kaihati | Submerged PMGSY due to flood. Information

received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000), Chamata Rampur road to Niz Tapa | Niz Tapa | SubmergedPMGSY due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat -

Information received from PWRD deptt. on $18/06/2022.\ |\ (Long$ - 0.000000 , Lat - 0.000000 ,

Amoni Bhakatpara to Chamata | Amoni | Submerged PMGSY due to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat - 0.000000), Belsor to Sukekuchi via Gandhia Nabagraha mandir | Sukekuchi | Submerged PMGSY due

to flood. Information received from PWRD deptt. on 18/06/2022. | (Long - 0.000000, Lat -

0.000000), Dahudi ulubari to Bagurihati via Piplibari Dahudi Submerged PMGSY due to flood. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Jagara Goalpara road to Jagara Mukalmua Road via Bharali supa Jagara Submerged due to heavy rainwater for a length of 600 m. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Belsor Nalicha road Belsor Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Kakaya Barnibari road Kakaya Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	
Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Jagara Goalpara road to Jagara Mukalmua Road via Bharali supa Jagara Submerged due to heavy rainwater for a length of 600 m. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Belsor Nalicha road Belsor Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Kakaya Barnibari road Kakaya Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	
0.000000), Jagara Goalpara road to Jagara Mukalmua Road via Bharali supa Jagara Submerged due to heavy rainwater for a length of 600 m. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Belsor Nalicha road Belsor Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Kakaya Barnibari road Kakaya Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	
Jagara Goalpara road to Jagara Mukalmua Road via Bharali supa Jagara Submerged due to heavy rainwater for a length of 600 m. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Belsor Nalicha road Belsor Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Kakaya Barnibari road Kakaya Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	
to heavy rainwater for a length of 600 m. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Belsor Nalicha road Belsor Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Kakaya Barnibari road Kakaya Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	3
18/06/2022. (Long - 0.000000, Lat - 0.000000), Belsor Nalicha road Belsor Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Kakaya Barnibari road Kakaya Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	-
from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000), Kakaya Barnibari road Kakaya Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	
Kakaya Barnibari road Kakaya Side berm eroded due to heavy rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	d
received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	
Billeswar Moktab to B.B.B road Billeswar Submerged side of Belsor PS. Information	
received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat - 0.000000),	
Chamata Barnibari Road Barnibari Side beam of culvert & surface damage due to heavy	y
rainfall. Information received from PWRD deptt. on 18/06/2022. (Long - 0.000000, Lat -	-
0.000000),	
Banekuchi - Kashimpur to Burinagr Road kashimpur as per report submitted by PWD	
Department as on 18.06.2022 Kashimpur to Burinagr Road Submerged (Long - 0.000000)),
Lat - 0.000000), Pub Kendukuchi to haripur Road Kendukuchi as per report submitted by PWD	
Department as on 18.06.2022 Kendukuchi to Haripur Road Submerged . (Long -	
0.000000, Lat - 0.000000),	
Koithalkuchi to Sahpur Road Koithalkuchi as per report from Goan Pradhan on	
18.06.2022 Koithalkuchi to Sahpur Road Submerged . (Long - 0.000000, Lat - 0.000000)	-
Kashimpur to GoKharghat Road Kashimpur as per report submitted by PWD Department	nt
as on 18.06.2022 Kashimpur to GoKharghat Road Submerged . (Long - 0.000000, Lat - 0.000000),	
Barbhag - Ukhura koithalkuchi Road 2.10 KM 0.60 mtr ukhura as per report from	
PWRD department on 17.06.2022 (Long - 0.000000, Lat - 0.000000),	
Nakkheti Arrongmow Village Road 13.00 KM 0.70 Mtr Nakheti as per report from	
PWRD department on 17.06.2022 (Long - 0.000000, Lat - 0.000000),	
G,.D.B to Arrongmow Village Road 1.50 KM 0.60 Mtr Arrongmow as per report from	
PWRD department on 17.06.2022 (Long - 0.000000, Lat - 0.000000),	
Nalbari - Gousala to Bhebheri road Gousala As per the report received from PWRD on 19.06.2022 above mention road is damaged due to flood (Long - 0.000000, Lat -	
0.000000),	
NH 31 to Charminar Chowk road Charminar Chowk As per the report received from	
PWRD on 19.06.2022 above mention road is submerged due to flood (Long - 0.000000,	
Lat - 0.000000),	
Budrukuchi to Chandakuchi road budrukuchi As per the report received from PWRD on	1
19.06.2022 above mention road is submerged due to flood (Long - 0.000000, Lat - 0.000000),	
Nalbari to Bahjani road bahjani As per the report received from PWRD on 19.06.2022	
above mention road is submerged due to flood (Long - 0.000000, Lat - 0.000000)	
Dhekiajuli - Batasipur PWD road side damage due to rising rain water near Monmohinipu	ur
TE. Dated 19.6.22 Monmohinipur (Long - 92.455086, Lat - 26.803459),	
Tezpur - Dolabari to Bhumoraguri High Madrassa Road Bhomoraguri Village Dated:	
20/06/2022. As reported by PWD (Roads) Erosion occured at shoulder at right side at ch. 3065.00m over HP Culvert. (Approximate length:15.00m) (Long - 92.842804, Lat -	
26.617696),	
Milonpur Mental Hospital Road Bebejia Dated: 20/06/2022. As reported by PWD	
(Roads) Setteled down HP Culvert. at Ch.500.00mErroded shoulder at Right Side about	
Sonitpur 5 7.00 m length. (Long - 92.746105, Lat - 0.000000),	
Dipota Bimalajan road Khulaguti Kachari (Dipota Bimalajan) Dated: 20/06/2022. As	
reported by PWD (Roads)heavy erosion occured at the downstream side of road at ch	. ,
1370.00m at the Bimaljan side approach of ongoing RCC Br No.2/1 due to overtopping by fresh flood water from the river Dipota and as a result of that one new river channel has	1
been found created. (Long - 92.731360, Lat - 26.687911),	
Niz Bihaguri to Jharani Road Borakota Pathar Dated: 20/06/2022. As reported by PWD	
(Roads) Niz Bihaguri to Jharani Road damage Ch.2000.00m to 2050.00 m (Long -	
92.690830, Lat - 26.657432)	
Tamulpur 4 Tamulpur - dolongpar to Sapkhata road Dolongpar village eroision damage 20 m. Date	:d

2006/5/2021 (Long. 9-13,70000), Lat - 26,40000), Gandhibati or Kourbaha road (Obrace chowk) Dakhin gandhibati eroision damage 800 m. Dated 2006/2022 (Long. 9-16,40000, Lat - 26,548000), Eckerikuchi Goppul pur to Nix Karuthalar road (Ultur Goulbera eroision damage 800 m. Dated 2006/2022 (Long. 9-16,40000, Lat - 26,548000), Goreswar - Grosswar Barkachulan purd road. Barkachula Duc to overtopping of flood water road got breached at Village Barkachula (paproximately damage 10 m. Dated 19/06/2022). (Long. 0.000000, Lat - 0.000000) Total		1	<u> </u>	20/06/2022 L(Long. 01 570000 Let. 26 640000)
m. Dated 2006/2021 (Long = 91,640000, Lat = 26,548000), Coressur = Crosswar Farchauth part and [Hardauthal Due to overtopping of flood water road got breached at Village Barkachula port coul. [Brakenhla] Total 349 District Village Barkachula port coul. [Brakenhla] Due to overtopping of flood water road got breached at Village Barkachula approximately damage 10 m. Dated 19:06-2022. [Long = 0.000000, Lat = 0.000000) Brakenhlage Barkachula approximately damage 10 m. Dated 19:06-2022. [Long = 0.000000, Lat = 0.000000), Barkachula [Due to overtopping of flood water road got breached at Village Barkachula approximately damage 10 m. Dated 19:06-2022. [Long = 0.000000, Lat = 0.000000), Barkachula [Due to overtopping of flood over the county of the count				
Rekenkuchi Gopal pur to Niz Kaurbaha road Uttar Goalbera eroision damage 800 m. Dated 2006/2022 (Jong = 1,64000), Lat = 2,654000).				
Dated 2006/2022 (Long. + 91,640000, Lat 26,540000)				
Barpeta Goreswar - Goreswar Barkachula pndr road. Barkachula Due to overtopping of flood water road go breached at Village Barkachula approximately damage 10 m. Dated 19/06/2022 (Long - 0.000000, Lat - 0.000000)				
District Total 349 Details				
District cr PWD Details PWD Details Cr PWD Details PWD PWD Details PWD				water road got breached at Village Barkachula approximately damage 10 m. Dated
District Numb Petalis Sarthebari - SPT Bridge no 1/1 over River Pahumara Colony Bazar Reported By JE PWD on 20/6/2022 (Long - 0.000000), Lat - 0.000000), BR Colony Bazar Reported By JE PWD on 20/6/2022 (Long - 0.000000), Lat - 0.000000), RC Colony Bazar Reported By JE PWD on 20/6/2022 (Long - 0.000000), Lat - 0.000000), Radgachia - RCC Br.35r.4 49/1. State High way2 As per report received from PWD dcpt on 20/6/2022 (Long - 0.000000), Lat - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report received from PWD dcpt on 20/6/2022 (Long - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report received from PWD dcpt on 20/6/2022 (Long - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report received from PWD dcpt on 20/6/2022 (Long - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report received from PWD dcpt on 20/6/2022 (Long - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report received from PWD dcpt on 20/6/2022 (Long - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report received from PWD dcpt on 20/6/2022 (Long - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report received from PWD dcpt on 20/6/2022 (Long - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report and product on 20/6/2022 (Long - 0.000000), Chenga - RCC Br.35r.4 49/1. State High way2 As per report was received from PWD dcash, Biswanath - One HP culvert no. 1/1 (3 Row 1000 margor at Rowmari No.3 Batimari road The report was received from PWD dcash, Biswanath via whaspap and the above is a culvert on 20/6/2022 (Long - 0.000000), As a state - No. 1/1 Sapatara No.				19/06/2022. (Long - 0.000000, Lat - 0.000000)
Barpeta Bar		Total		
Barpeta Bar		District		Details
Barpeta Bar			CI	Sarthebari - SPT Bridge no 1/1 over River Pahumara Colony Bazar Reported By JE
Barpeta Coologoon, Lar -0.0000000, Bardega Barpeta Bar				
Barpeta Bar				
Barpeta Barpeta Barpeta G Gept on 20/06/22, Due to continuous heavy rainfall RCC bridge No. 35/1 approach and RCC bridge No. 49/1 approach damaged at SH2 (Manas Bridge approach to Barpeta Medical College) (Damaged length = 350.00m, Avg. width = 2.50 m, Height = 4.00 m and location coordinate = 26.306503, 90.754164/26.33531, 90.869207). [Clong - 0.000000, Lat - 0.000000]. Chenga - RCC bridge appraoch croded on Batgaon Doulsaal Road Batgaon croded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000). RCC bridge appraoch on khongra Roumari Pathar road to Balatrair road Khongra eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000). RCC bridge appraoch on khongra Roumari Pathar road to Balatrair road Khongra eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000). RCC bridge appraoch on khongra Roumari Pathar road to Balatrair road Khongra eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000). RCC bridge appraoch on Abroads Roumari No.3 Batiamari road The report was received from PWD/roads), Biswanath via whasapp and the above is a culvert on 20.06.2022 (Long - 9.34.11132, Lat - 26.806882) Chamaria - Kismat kathmi to Morakolohi Morakolohi Kismat kathmi to Morakolohi approache road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 19.06.2022 (Long - 0.609030, Lat - 9.133480), Nagarbera - Doukuchi upharpara wooden bridge Doukuchi Doukuchi pahapara wooden bridge was affected due to erosion on 19-6-2022 (Long - 20.115100, Lat - 9.1056000)				
Barpeta Barpeta 6 RCC bridge No. 49/1 approach damaged at SH2 (Manas Bridge approach to Barpeta Medical College) (Damaged length = 350.00m, Avg. width = 2.50 m, Height = 4.00 m and location coordinate = 26.306503, 90.754164/26.33531, 90.869207). [Clong - 0.000000, Lat - 0.000000]. Chenga - RCC bridge approach or khongra Roumari Pathar road to Balgaton eroded, report by PWD, ROADs deptt, on 20/06/2022 [Clong - 0.000000, Lat - 0.000000]. RCC bridge approach on khongra Roumari Pathar road to Balgatrari road Khongra eroded, report by PWD, ROADs deptt, on 20/06/2022 [Clong - 0.000000, Lat - 0.000000]. Biswanath h Siswanath in the property PWD, ROADs deptt, on 20/06/2022 [Clong - 0.000000, Lat - 0.000000]. Biswanath in whasapp and the above is a culvert on 20/06.2022 [Clong - 93.411132, Lat - 26.806882] Chamaria - Kismat kathmi to Morakolohi Morakolohi Kismat kathmi to Morakolohi approach road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 19.06.2022 and the same has been bridge was affected due to erosion on 19-6-2022 and same the has been reported by JE. PWD Boko territorial sub-division dated 20-6-2022 [Clong - 26.115100, Lat - 91.056000] Baggribari - Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village As reported by A. EE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 [Clong - 0.000000, Lat - 0.000000] Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village As reported by A. EE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 [Clong - 0.000000, Lat - 0.000000] Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village As reported by A. EE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 [Clong - 0.000000, Lat - 0.000000] Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, bas been damaged on 18.06.2022 [Clong - 0.000000, Lat - 0.000000] Bridge No.1/1 Sapatgram to Tipkai Via K				Kalgachia - RCC Br.35/1 & 49/1. State High way2 As per report received from PWD
Medical College) (Damaged length = 350.00m, Avg. width = 2.50 m, Height = 4.00 m and location coordinate = 26.306503, 90.754164/26.33351, 90.869207). [Long = 0.000000, Lat - 0.000000]. Chenga - RCC bridge appraoch eroded on Batgaon Doulsaal Road Batgaon eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000), RCC bridge appraoch on khongra Roumarl Pathar road to Balartari road [Khongra eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000), RCC bridge appraoch on khongra Roumarl Pathar road to Balartari road [Khongra eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000), RCC bridge appraoch on khongra Roumarl Pathar road to Balartari road [Khongra eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000), RCC bridge appraoch on the was affected Rowmari to No.3 Batiamari road The report was received from PWD(troads), Biswamath via whasapp and the above is a culvert on 20.06.2022 (Long - 9.34.11132, Lat - 28.60882) Chamaria - Kismat kathmi to Morakolohi Morakolohi Kismat kathmi to Morakolohi approach road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 19.06.2022 (Long - 0.00000), Nagarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to crosion on 19-6-2022 and same the has been reported by AEE, PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 9.005000) Bagribar - Bridge No.6/1 Gossaigaon Tipkai road to Gendabii connecting road As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai via Khangkharaibari PWD road				dept on 20/06/22, Due to continuous heavy rainfall RCC bridge No. 35/1 approach and
Medical College) (Damaged length = 350,00m, Avg. width = 2.50 m, Height = 4.00 m and location coordinate = 26,036653, 90.754164/26,33351, 90.869207). Cong 0.000000, Lat - 0.000000, Chenga - RCC bridge appracoh or obsolute and property by PWD, ROADs deptt., on 2006/2022 (Long - 0.000000, Lat - 0.000000). RCC bridge appracoh on khongra Roumari Pathar road to Balartari road Khongra roded, report by PWD, ROADs deptt., on 2006/2022 (Long - 0.000000). Lat - 0.000000, Lat - 0.000000). RCC bridge appracoh on khongra Roumari Pathar road to Balartari road Khongra roded, report by PWD, ROADs deptt., on 2006/2022 (Long - 0.000000). Lat - 0.000000). RCC bridge appracoh on khongra Roumari Pathar road to Balartari road Khongra roded, report by PWD, ROADs deptt., on 2006/2022 (Long - 0.000000). Lat - 0.000000). RCC bridge appracoh on khongra Roumari Pathar road to Balartari road Khongra road was affected du knomari to No.3 Batiamari road The report was received from PWD(roads), Biswanath via whasapp and the above is a culver on 20.06.2022 (Long - 92.6090930), Lat - 91.13480). Nagarbera - Doukuchi paharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 20.115100, Lat - 91.056000) Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by AEE, PWD Gossaigaon, both is de approaches has been damaged on 18.06.2022 (Long - 0.00000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by AEE, PWD Gossaigaon, both is de approaches has been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, bas deen damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, bas been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD		Domesto	6	RCC bridge No. 49/1 approach damaged at SH2 (Manas Bridge approach to Barpeta
Chenga - RCC bridge appraoch eroded on Batgaon Doulasal Road Batgaon eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000), RCC bridge appraoch on khongra Roumari Pathar road to Balartari road Khongra eroded, report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000) Biswanath - One HP culvert no. 1/1 (3 Row 1000 mm)row at Rowmari - No 3 Batiamari road was affected Rowmari to No.3 Batiamari road The report was received from PWDroads), Biswanath via whasapp and the above is a culvert on 20.06.2022 (Long - 93.411132, Lat - 26.806882) Chamaria - Kismat kathmi to Morakolohi Morakolohi Kismat kathmi to Morakolohi approach road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 19.06.2022 (Long - 26.090930, Lat - 91.133480), Nagarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to crosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000)		Багрета	0	Medical College) (Damaged length = 350.00m, Avg. width = 2.50 m, Height = 4.00 m and
Chenga - RCC bridge appraoch eroded on Batgaon Doulasal Road Batgaon eroded, report by PWD, ROADs deptt, on 20006/2022 (Long - 0.000000), Lat - 0.000000, RCC bridge appraoch on khongra Roumari Pathar road to Balartari road Khongra eroded, report by PWD, ROADs deptt, on 2006/2022 (Long - 0.000000, Lat - 0.000000). Bridge No. 1/1 Spatian				location coordinate = 26.306503, 90.754164/26.33351, 90.869207). (Long - 0.000000, Lat
Report by PWD, RoADs deptt, on 20/06/2022 (Long - 0.000000), Lat - 0.000000), RCC bridge appracoh on khongra Roumari Pathar road to Balartari road Khongra eroded, report by PWD, RoADs deptt, on 20/06/2022 (Long - 0.000000), Lat - 0.000000) Biswanath				
RCC bridge appraoch on khongra Roumari Pathar road to Balantari road Khongra eroded, report by PWD, RoADs deptt, on 20/06/2022 (Long - 0.000000, 1 act - 0.000000) Biswanath - One HP culvert no. 1/1 (3 Row 1000 mm)row at Rowmari - No 3 Batiamari road was affected Rowmari to No.3 Batiamari road The report was received from PWD(roads), Biswanath via whasapp and the above is a culvert on 20.06.2022 (Long - 93.411132, Lat - 26.806882) Chamaria - Kismat kathmi to Morakolohi Morakolohi Kismat kathmi to Morakolohi approach road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE. PWD, Boko territorial road sub-division on dated 19.06.2022 [(Long - 26.090930, Lat - 91.133480), Nagarbera - Doukuchi phaharpara wooden bridge Doukuchi Doukuchi phaharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000) Bagribari - Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by, AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by, AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by AEE, PWD Gossaigaon, bahari - SPT Bridge Sariyahata As per the report received from PWRD on 19.06.2				
Report by PWD, ROADs deptt, on 20/06/2022 (Long - 0.000000, Lat - 0.000000)				
Biswanath 1				
Biswanat h PWD(roads), Biswanath via whasapp and the above is a culvert on 20.06.2022 (Long - 93.411132, Lat - 26.806882) Chamaria - Kismat kathmi to Morakolohi Morakolohi Kismat kathmi to Morakolohi approach road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 19.06.2022 (Long - 26.090930, Lat - 91.133480), Nagarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000) Bagribari - Bridge No.6/1 Gossaigaon Tipkai road to Gendabil connecting road As reported by , AEE, PWD Gossaigaon the bridge has been washout on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road As reported by, AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Chart - Condono -				
h PWD(roads), Biswanath via whasapp and the above is a culvert on 20.06.2022 (Long - 93.411132, Lat - 26.806882) Chamaria - Kismat kathmit to Morakolohi Morakolohi Kismat kathmit to Morakolohi approach road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 19.06.2022 (Long - 26.090930, Lat - 91.133480), Nagarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000) Bagribari - Bridge No.6/1 Gossaigaon Tipkai road to Gendabil connecting road As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai to Goroimari via Belguri PWD road. As reported by AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai to Goroimari via Belguri PWD road As reported by AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai to Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, pas been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) District Wildlife affected under protected areas description (Golaghat)		D.		
93.411132, Lat - 26.806882 Chamaria - Kismat kathmi to Morakolohi Kismat kathmi to Morakolohi approach road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 19.06.2022 (Long - 26.909030, Lat - 91.133480), Nagarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000)			1	· · · · · · · · · · · · · · · · · · ·
Infrastruct ure Damaged - Bridge Kamrup Examrup Sample Examrup Chamaria - Kismat kathmi to Morakolohi Morakolohi Morakolohi Abita Morakolohi Approach road, bridge severely damaged on dated 19.06.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 19.06.2022 (Long - 26.090930, Lat - 91.133480), Nagarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000)		h	_	
Infrastruct ure Damaged - Bridge Kamrup Agarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division on dated 19.06.2022 (Long - 26.090930, Lat - 91.133480), Nagarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000) Bagribari - Bridge No.6/1 Gossaigaon Tipkai road to Gendabil connecting road As reported by, AEE, PWD Gossaigaon the bridge has been washout on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Hipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, barially damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road. As reported by AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, barb been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, barb been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, barb been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, barb been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khang				· · · · · · · · · · · · · · · · · · ·
ure Damaged - Bridge Kamrup Ze	T. C			
Damaged - Bridge Rimrup Bridge Rimrup Bridge Bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000) Bagribari - Bridge No.6/1 Gossaigaon Tipkai road to Gendabil connecting road As reported by, AEE, PWD Gossaigaon the bridge has been washout on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000), Bridge No.3/1 Balapara pt-II Dudumari village As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by, AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.0		Kamrup		
Bridge Nagarbera - Doukuchi paharpara wooden bridge Doukuchi Doukuchi paharpara wooden bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000) Bagribari - Bridge No.6/1 Gossaigaon Tipkai road to Gendabil connecting road As reported by, AEE, PWD Gossaigaon the bridge has been washout on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.3/1 Balapara pt-II Dudumari village As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Malbari			2	
bridge was affected due to erosion on 19-6-2022 and same the has been reported by EE PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000) Bagribari - Bridge No.6/1 Gossaigaon Tipkai road to Gendabil connecting road As reported by, AEE, PWD Gossaigaon the bridge has been washout on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000, 1 Bridge No.3/1 Balapara pt-II Dudumari village As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000), 1 Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by, AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, 1 Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16	-		2	
PWD Boko territorial sub-division dated 20-6-2022 (Long - 26.115100, Lat - 91.056000)	Dilage			
Bagribari - Bridge No.6/1 Gossaigaon Tipkai road to Gendabil connecting road As reported by, AEE, PWD Gossaigaon the bridge has been washout on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Bridge No.1/1 Sapatgram Tipkai road Via Dudumari village. As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000), Bridge No.3/1 Balapara pt-II Dudumari village As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by, AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Lat - 0.000000, Lat -				
Rokrajha r Rok				1,7 6
Nalbari Total To				
Kokrajha r Some provided p			5	
Kokrajha r Kokorajha koskata r Kok				
Kokrajha r				
Bridge No.3/1 Bahapara pt-II Dudumari Village As reported by, AEE, PWD Gossaigaon, both side approaches has been damaged on 18.06.2022 (Long - 0.000000), Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by, AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Morigaon Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16 District Wildlife affected under protected areas description (Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.		17 . 1 1		
both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1,1/2 Tipkai to Goroimari via Belguri PWD road. As reported by, AEE, PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Morigaon Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16				Bridge No.3/1 Balapara pt-II Dudumari village As reported by, AEE, PWD Gossaigaon,
PWD Gossaigaon, partially damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000), Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Morigaon Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16 District Wildlife affected under protected areas description [Golaghat] At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.		1		both side approaches has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000),
Bridge No.1/1 Sapatgram to Tipkai Via Khangkharaibari PWD road As reported by AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Morigaon Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16 District Wildlife affected under protected areas description (Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated) . As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.				
AEE, PWD Gossaigaon, has been damaged on 18.06.2022 (Long - 0.000000, Lat - 0.000000) Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari 1 Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16 District Wildlife affected under protected areas description (Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated) . As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.				
Morigaon Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari				
Morigaon 1 Mayong - Approaches of RCC bridge no 2/1 04M14 to 2no Dungabori Road Damaged and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari 1 Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16 District Wildlife affected under protected areas description (Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.				
Morigaon 1 and eroded as reported by PWD Morigaon district territorial road division on 19/06/22 (Long - 92.194000, Lat - 26.155000) Nalbari 1 Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16 District Wildlife affected under protected areas description (Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.				
Nalbari Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16				
Nalbari 1 Nalbari - SPT Bridge sariyahtali As per the report received from PWRD on 19.06.2022 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000) Total 16 District Wildlife affected under protected areas description Infrastruct ure U		Morigaon	1	
Nalbari 1 above mention bridge damaged due to flood (Long - 0.000000, Lat - 0.000000)				
Total 16 District Wildlife affected under protected areas description Infrastruct ure Damaged - Wildlife Golaghat Damaged - Wildlife Golaghat At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated) . As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.		Nalbari	1	
Infrastruct ure Damaged - Wildlife affected under protected areas description Golaghat Golaghat Golaghat Golaghat Middife Wildlife Wildlife affected under protected areas description (Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.		Total	16	above mention bridge damaged due to nood (Long - 0.000000, Lat - 0.000000)
Infrastruct ure Damaged - Wildlife (Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06- 2022.				affected under protected areas description
ure Damaged - Wildlife Golaghat Golaghat inundated), Kaziranga Range (out of 49 camps 9 are inundated), Bokakhat Range (Out of 7 camps 3 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.	Infrastruct			
Damaged - Wildlife are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 20-06-2022.		Coloration		
Wildlife 2022.	Damaged -	Golaghat		
Morigaon Mayong - Pobitora WLS. out of a total of 25numbers of Camps 17nos of camps ate affected and 14	Wildlife			
		Morigaon	Mayong	- Pobitora WLS. out of a total of 25numbers of Camps 17nos of camps ate affected and 14

		nos of camps are inundated as reported by Range Officer PWLS on 20/06/22
		Kaliabor - In Bagori Range out of total 38 nos. of camp 10 nos. of camp and in Burhapahar Range
	Nagaon	out of total 25 nos. of camp 6 nos. of camp innundated due to flood water Dtd-20.06.2022 as reported
		by DFO, EAWD
	District	Other Details
	Baksa	Baska - Culvert Approach Road Damaged Garamdew to Ban Ahopa road Culvert with approach damaged on 19/06/2022, Co-ordinate - 26.6638, 91.310326
	Barpeta	Baghbar - Anganwadi Centres Affected 272 nos of AWC are affected Date:- 19-06-2022, Barpeta - Bridge Approach Road Damaged dabaliapara, damage land 10 ft. Date-19-6-2022., Sarthebari - Anganwadi Centres Affected 7,Date-20-6-2022, Fisheries/Pond 3371, date-20-6-2022, Barnagar - Culvert Approach Road Damaged As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 culvert approach damage of Culvert Np. 2/1 damaged on Sorbhog Jamadarbari Road. Lat-26.504609, Long- 90.90525, Culvert Approach Road Damaged As per report received from Asst. Ex Engineer PWD,SBG Terri Road Divn on 20/06/2022 culvert approach damage of Culvert N0. 1/1 and 1/2 damaged on Barnagar College approach road Road. Lat-26.504609, Long- 90.90525, Kalgachia - Protection Bundh Damaged As per report received fr BDO Rupshi on 19/06/22, due to heavy rainfall, 2 nos of flood protection bundh damaged. details- 1. Flood protection bundh st frm Somesh Uddin house to Aynal Hoque house at vill Shawrachara, damaged details- L= 30m, W=4m, H=3m, coordinates- 26.271968, 90.834597, 2. Flood protection bundh st frm Fazar Ali house to Suruz Khan house at vill Shawrachara Gaon, damaged details- L= 20m, W=4m, H=2.4m, coordinates- 26.272749, 90.836816,, Fisheries/Pond As per report received from Fishery dept on 19/06/22, total 929 nos of Ponds are submerged as on today within the jurisdiction of Kalgachia rev circle, total water area- 204.26 Ha., Chenga - Fisheries/Pond approx.98 hec. water affected and approx. 429 fish pond submerged date- 20-6-2022
Infrastruct ure Damaged - Others	Biswanat h	Biswanath - Bridge Approach Road Damaged Bridge approach road damaged at Nabapur-Japoriguri to Silamari Road for a length of approx 2 * 50 m (coordinates:26.720292,93.195665) as per report from PWD(roads) Biswanath via whatsapp on 20-06-2022., Halem - Anganwadi Centres Affected Pachim Gopaljarini AWC on 20.06.2022, Anganwadi Centres Affected Gopal Jharini AWC on 20.06.2022, Anganwadi Centres Affected 1 NO Bortamuli AWC on 20.06.2022, Anganwadi Centres Affected 2 No Bortamuli on 20.06.2022, Anganwadi Centres Affected Bhulaguri Mazdoor line on 20.06.2022, Anganwadi Centres Affected Bholaguri AWC on 20.06.2022, Anganwadi Centres Affected Golsepa AWC on 20.06.2022
	Bongaiga on	Bongaigaon - Secondary Schools Damaged Purani Bongaigaon High School, as per report received from Ins. of School, Bongaigaon date- 20.06.2022, Secondary Schools Damaged Chokapara High School, as per report received from Ins. of School, Bongaigaon date- 20.06.2022, Boitamari - Secondary Schools Damaged Ponchagaon High School. as per report Ins. Of School, Bongaigaon, date- 20.06.2022, Secondary Schools Damaged J.N.M. Girls High School, Boitamari, as per report Ins. Of School, Bongaigaon, date- 20.06.2022, Secondary Schools Damaged J.N.M. Girls High School, Boitamari, as per report Dist.Fishery Dev. Bongaigaon, date- 20.06.2022, Fisheries/Pond Total 2 nos pond(1) Nayagaon, (2) Kabaitary Pt. VI. as per report Dist.Fishery Dev. Bongaigaon, date- 20.06.2022, Manikpur - Secondary Schools Damaged Bhatipara High School, as per report received from Ins. of School, Bongaigaon date 20.06.2022, Secondary Schools Damaged Sonaikola High School, as per report received from Ins. of School, Bongaigaon date 20.06.2022, Fisheries/Pond 13 No of Pond (1)Chalabila No.1- 8, (2) Kushmari - 3, (3) Nowagaon-1, (4)Borbila-1, Srijangram - Secondary Schools Damaged Golapara High School, Longitude-90°47'41.3448", Latitude-26°23'29.16348" as per report Ins. Of School, Bongaigaon, date- 20.06.2022, Secondary Schools Damaged P.M.H.S. School, Longitude-90.845167, Latitude-26.4086, as per report Ins. Of School, Bongaigaon, date- 20.06.2022, Secondary Schools Damaged D.P.M High School, Longitude-90.845167, Latitude-26.3937, as per report Ins. Of School, Bongaigaon, date- 20.06.2022, Secondary Schools Damaged Namberpara High School, Longitude-90.81769562, Latitude-26.40013041, as per report Ins. Of School, Bongaigaon, date- 20.06.2022, Secondary Schools Damaged Namberpara High School, Longitude-90.694348, Latitude-26.307358, as Secondary Schools Damaged Piradhara High School, Longitude-90.694348, Latitude-26.307358, as

per report Ins. Of School, Bongaigaon, date-20.06.2022, Secondary Schools Damaged | Chukani High School, Longitude-90.751667, Latitude-26.392317, as per report Ins. Of School, Bongaigaon, date-20.06.2022, Secondary Schools Damaged | Amguri Latibari High School, Longitude-90.611555, Latitude-26.3536617, as per report Ins. Of School, Bongaigaon, date-20.06.2022, Secondary Schools Damaged | Kacharipeti High School, Longitude-90.727467 Latitude-26.350383, as per report Ins. Of School, Bongaigaon, date-20.06.2022, Secondary Schools Damaged | Balarchar High School, Longitude-90.78095 Latitude-26.364467, as per report Ins. Of School, Bongaigaon, date-20.06.2022, Secondary Schools Damaged | Kokila Pubpara High School, Longitude-90.835517 Latitude-26.389867, as per report Ins. Of School, Bongaigaon, date-20.06.2022, Secondary Schools Damaged | Kirtanpara High School, Longitude-90.757733 Latitude-26.57285, as per report Ins. Of School, Bongaigaon, date-20.06.2022, Fisheries/Pond | 21 No of Pond (i)Kushbari Pt-I- 2nos Pond (ii) Dubasuri Pt-I- 1nos Pond (iii) Sontoshpur Pt-III -1 nos Pond (iv) Tupkarchar-1 no Pond (v) Nararvita Pt-IV -2 nos Pond (VI) Rangapani -2nos Pond, (vii) Topgaon Pt-I-1no Pond, (viii) Kirtanpara-4no Pond, (ix) Chailabari Pt-I 1no Pond, (x) Dhalagasa-1no Pond,(xi)Balarchar-5nos Pond, Cachar Sonai - Power Dept. Poles | 04 Nos. of POLES Damage Under Sonai ESD on 20.06.2022 Bijni - Power Dept. Poles | As reported by SDE Bijni Electrical Sub Division, on 17-06-2022, Total poles Damaged=10 Nos., Power Dept. Conductors | As reported by SDE Bijni Electrical Sub Division, on 17-06-2022, Total conductor damaged=1.5 Km(approx) on 18-06-2022., Bridge Approach Road Damaged | As reported by PWD Chirang(R&B) Division, RCC Br. Approach eroded at Bhawraguri of Ballamguri to Amguri Bazar road via Khungkrajhora. Length=30 mtr, Breadth=8.00 mtr, Depth=5.00 mtr. Longitude=90.605166 Latitude=26.59492. Date of Occurrence=16-06-2022, Fisheries/Pond | As reported by District Fishery Dev Officer, Chirang, total of 12 Ponds affected and damaged of embankment desalting of submerged due to heavy rainfall on 15-06-2022 to 18-06-2022. Chirang Sidli - Irrigation Canal/Scheme Damaged | As reported by Sidli Division(Irrigation), Downstream guide bund L/S and R/S of Juilaga FIS damage on 16-06-2022 at Lauripara (long-90.385987, Lat-26.559971), damage details - length- 30m, Width-4m, height-4m, Irrigation Canal/Scheme Damaged | As reported by Sidli Division(Irrigation), Irrigation canal breached due to heavy flood (Canal arise from Daobobil FIS) on 16-06-2022 at Tirimari village (Long-90.409586, Lat-26.512862) damage details- Length- 20m, width-3m, height-1.5 m, Fisheries/Pond | As reported by District fishery Dev. Officer, 8 Nos. of Pond are Breakage of embankment, Siltation and submersion due to heavy rainfall on 17-06-2022., Bengtal - Fisheries/Pond | As reported by DFDO, 5 nos. of pond from village Aminpara FV, 2 nos. of ponds from village Khorpaguri, 2 nos. of ponds from village Bhur Khojobari, and 1 each from village Gwthwibari and Dwigudung were affected/submerged/damaged on17-6-2022 to 19-6-2022 Mangaldoi - Fisheries/Pond | as reported by fisheries department approx.2596 nos. of farmers and total water area apprpx. 196 Hct. are affected as of now. Dated 20-6-2022, PWSS Damaged | as reported by PHE department approx.5 Nos. of PWSS are damaged till now. Dated 20-6-2022, Patharighat - Power Dept. Conductors | conductor snapped approx. 20 km at various places under the circle as reported by SDE APDCL on 20.6.2022, Darrang Power Dept. Poles | 27 poles damaged at various places under the circle as reported by SDE APDCL on 20.6.2022, Fisheries/Pond | 358 ha. of area of pond and fisheries submerged as reported by Fishery Deptt, Sipajhar - Fisheries/Pond | Total nos. of fish farmers affected appx. 570 nos. & Total water area affected appx. 43 hect.-dated 20/6/2022, Fisheries/Pond | Fish Farmer affected : 2291 nos. Area : 123.4 Hectre Dibrugarh West - Protection Bundh Damaged | As per report received from Executive Engineer, WR Division on 20.06.2022 that Infrastructure Damage has been observed at Chaulkhowa Area near Chaulkhowa Ring Bund. Flood Restoration works completed under SDRF 2016-17 has been completed washed Reach length-200 m at Left bank of River Brahmaputra GPS Co-ordinates = Lat Dibrugar 27°21'27.86"N to Long 94°46'4.67"E, Chabua - Elementary Schools Damaged | DODHIA ME SCHOOL SUBMERGED AS PER h RECEIVED FROM EDUCATION DEPT. ON 20/6/2022 N27 36.390 E95 13.651, Elementary Schools Damaged | DODHIA KULIGAON LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 20/6/2022 N27 35.845 E95 13.227, Elementary Schools Damaged | DODHIA KARMI LPS SUBMERGED AS PER INFORMATION

	RECEIVED FROM EDUCATION DEPT. ON 20/6/2022 N 27 36.032 E95 14.787,
	Elementary Schools Damaged DODHIA TENGABARI LPS SUBMERGED AS PER
	INFORMATION RECEIVED FROM EDUCATION DEPT. ON 20/6/2022 N27 36.652 E95 14.237,
	Elementary Schools Damaged DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION
	RECEIVED FROM EDUCATION DEPT ON 20/6/2022 N27 36.462 E95 14.673,
	Anganwadi Centres Affected DODHIA KULIGAON AWC SUBMERGED AS PER
	INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 20/6/2022 N27 35.845 E 95
	13.227,
	Anganwadi Centres Affected DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022 N27 36.652 E95
	14.237,
	Anganwadi Centres Affected DODHIA AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022 N27 36.390 E95 13.651,
	Anganwadi Centres Affected UPPER GEREKI AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT. ON 20/6/2022,
	Anganwadi Centres Affected DODHIA CHALBIL AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022,
	Anganwadi Centres Affected RONGMOLA AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT. ON 20/6/2022 N27 33'33.40" E95 11'47.26".,
	Anganwadi Centres Affected 1 no. Mirigaon AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022,
	Anganwadi Centres Affected 2 No. MIRIGAON AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022,
	Anganwadi Centres Affected MULUKGHAT MIRIGAON AWC SUBMERGED AS PER
	INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022,
	Anganwadi Centres Affected TENGABARI-MIRIGAON AWC SUBMERGED AS PER
	INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022,
	Anganwadi Centres Affected GEREKI NEPALI AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022,
	Anganwadi Centres Affected KULIGAON AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022,
	Anganwadi Centres Affected DODHIA ROMAI AWC SUBMERGED AS PER INFORMATION
	RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022, Anganwadi Centres Affected CHALBIL AISUNG CHAPORI AWC SUBMERGED AS PER
	INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 20/6/2022
	Haflong - Road Breaches Damage of Culvert at Ch.2350m (Haflong - Jatinga) Road as per info
	received from PWRD dated 20/06/2022,
Dima-	Road Breaches Due to landslide, road leading to Saitop village is blocked as per info received from
Hasao	local dated 20/06/2022,
	Road Breaches Damage of Khejurbond - Kauladisa (KK Road) due to landslide as per info received
	from PWRD dated 20/06/2022
	Bokakhat - Fisheries/Pond Approx. 01 Hect. of water area affected on 19.06.2022,
	Dergaon - Elementary Schools Damaged Schools inundated- 1) Milan Pur Missing LPS 2) Christika
Golaghat	Koibartta LPS on 19.06.2022 as per report received from BEEO,North Block,Dergaon,
	(Golaghat) At District - Fisheries/Pond Approx. 01 Hect. of water area affected on 19-06-2022
	under Bokakhat Revenue Circle
	Doboka - PWSS Damaged 1) Beduwati Sarlok, Latitude 26.091172° & Longitude 92.823978°, 2)
	Jugijan Baliramgaon, Latitude 26.094704°, Longitude 92.778664°, 3) Kapili Kathkatia, Latitude
	26.109718°, Longitude 92.733099°, 4) Patiapam, Latitude 26.0852°, Longitude 92.4209°, 5) Jungle
По::	Block, Latitude 26.084506° & Longitude 92.806311°, 6) Changmaji Gaon, Latitude 26.111073° &
Hojai	Longitude 92.81124°, 7) Borjari Majgaon, Latitude 26.0720° & Logitude 92.4359°, 8) Patia Pathar, Latitude 26.0917° & Longitude 92.4159°, 9) Nagayapam, Latitude 26.0812° & Longitude 92.4350°,
	10) Changjurai, Latitude 26.109788° & Longitude 92.4330 , latitude 26.0812 & Longitude 92.4330 ,
	26.0824° & Longitude 92.4627°, 12) Oksek Pathar (Barge Submerged), Latitude 26.11953° &
	Longitude 93.033455° on dated 17/06/2022 under Binnakandi Block
	Kayan - Damaged SPT Bridge One steel bridge (4x3.5) m Garamsung Gorput Road. Date:
	19/06/2022. Reported by PWRD, Hajo Division.,
	Culvert Approach Road Damaged One culvert damaged, kamalpur morowa road near barpulla
Kamrup	chowk. Date: 19/06/2022. Reported by PWRD, Hajo Division.,
	Kamalpur - Fisheries/Pond Due to incessant rainfall 26 ha as per report of Bihdia Fishery
	Development Officer as on 19/6/2022,
 	Power Dept. Poles Due to incessant rainfall 6 pole and line - 14.06 KM as per APDCL report under

	Kamalpur Revenue Circle as on 19/6/2022
Kamrup (M)	Dispur - Protection Bundh Damaged At Anil Nagar the Bharalu guard wall minor breach occured with leakage and the wall is vulmerable condition if water level rises. Date- 20/06/2022, Protection Bundh Damaged At Junali opposite of FINER OFFICE THE Bharalu guard wall 20m approx breached. Date- 20/06/2022
Kokrajha r	Bhawraguri - Culvert Approach Road Damaged AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 20-06-2022 IMMEDIATE RESTORATION OF PATIALPARA TO KUSUMBIL ROAD RCC BOX CULVERT NO.2/3 BOTH SIDE APPROACHES EROSION., Culvert Approach Road Damaged AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 20-06-2022 IMMEDIATE RESTORATION OF KUNJODOBA TO JAMUNATARY ROAD RCC BOX CULVERT NO.2/1 APPROACH & ROAD WASHED OUT, Culvert Approach Road Damaged AS REPORTED BY AEE PWD RR, KACHUGAON DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE TO TILL 20-06-2022 IMMEDIATE RESTORATION OF BADLA TO BAMUNIGAON ROAD RCC BOX CELL NO.1/1 DAMAGED AND EROSION., Bagribari - Washed away Culverts As reported by AEE, PWD RR Gossaigaon, Culvert No 1/1 has been washout on Gendabil Notunbosti to Gossaigaon Tipkai connecting road on 18.06.2022, Culvert Approach Road Damaged As reported by AEE, PWD RR Gossaigaon, Culvert No.1/1,2/1 has been damaged and eroded in some stretches on Khangkharaibari to Daimaguri connecting road., Culvert Approach Road Damaged As reported by AEE, PWD RR Gossaigaon, Culvert no.1/1 and road surface has been damaged on Sapatgram to Tipkai road via Khangkharaibari on 18.06.2022, Culvert Approach Road Damaged As reported by AEE, PWD RR Gossaigaon, Culvert no.1/1 and road surface has been damaged on Balapara Pt-1 to Boraibari Village road on 18.06.2022, Culvert Approach Road Damaged As reported by AEE, PWD RR Gossaigaon, Culvert No 1/1 with road surface has been damaged on Balapara Pt-1 to Boraibari Village road on 18.06.2022, Culvert Approach Road Damaged As reported by AEE, PWD RR Gossaigaon, Culvert No 1/1 with road surface has been damaged on Balapara Pt-1 to Boraibari Village road on 18.06.2022, Culvert Approach Road Damaged As reported by AEE, PWD RR Gossaigaon, Culvert No 1/1 and road surface has been damaged on Cilkikhaata to Pastibari PWD road on 18.06.2022, Culvert Approach Road Damaged As
Lakhimp ur	Bihpuria - Fisheries/Pond As reported by FDO, Karunabari Block on 20th June 2022-15 nos. of ponds affected at No. 1 Pachim Laluk (2.5 hectare), 25 nos. ponds affected at Garmur (3.8 hectare) and 35 nos. ponds affected at Torajuli (5 hectare), Power Dept. Poles As reported by SDE, Nowboicha ESD -01 no. of PSC Pole 7.5 mtrs., 03 nos. of PSC 8.5 mtrs. and 1.80 KM Conductors damaged at No. 3 Islampur on 19th June 2022, Power Dept. Poles As reported by SDE, Nowboicha ESD -01 no. of PSC Pole 7.5 mtrs., 02 nos. of PSC 8.5 mtrs. and 2.50 KM Conductors damaged at Laluk Garmur on 19th June 2022, Power Dept. Poles As reported by SDE, Nowboicha ESD -02 no. of PSC Pole 7.5 mtrs. and 1.40 KM Conductors damaged at Ampara Milanpur on 19th June 2022, Power Dept. Poles As reported by SDE, Nowboicha ESD -02 nos. of PSC 8.5 mtrs. and 1.60 KM Conductors damaged at Jubanagar on 19th June 2022, Power Dept. Poles As reported by SDE, Nowboicha ESD -02 no. of PSC Pole 7.5 mtrs., 02 nos. of PSC 8.5 mtrs. and 3.20 KM Conductors damaged at Pava on 19th June 2022, Power Dept. Poles As reported by SDE, Nowboicha ESD -02 no. of PSC Pole 7.5 mtrs., 01 nos. of PSC 8.5 mtrs. and 1.70 KM Conductors damaged at Gobinpur on 19th June 2022, Power Dept. Poles As reported by SDE, Nowboicha ESD -02 no. of PSC Pole 7.5 mtrs., 01 no. of PSC 8.5 mtrs. and 1.60 KM Conductors damaged at Bishrampur on 19th June 2022, Power Dept. Poles As reported by SDE, Nowboicha ESD -01 no. of PSC Pole 7.5 mtrs., 02 nos. of PSC 8.5 mtrs. and 3.00 KM Conductors damaged at Bishrampur on 19th June 2022, Narayanpur - Bridge Approach Road Damaged Rangati majgaon to dhemagarh road rcc bridge no 4/1 embankment of the approach road of both side are eroded heavily due to rising of river dihiri can as reported by PWD Territorial Road Divn. Bihpuria on 20/06/2022, Narayanpur - Bridge Approach Road Divn. Bihpuria on 20/06/2022, Nowboicha - Anganwadi Centres Affected 15 nos. of AWC affected under Nowboicha Revenue Circle. Damage in physical terms likely Floor, door
Majuli	Ujani Majuli - Health Sub-Centre Salmora HWC submerged due to flood on 19.06.2022, Anganwadi Centres Affected 3 nos. of AWCs partially submerged on 19.06.2022. 1. Grazing Koibarta AWC 2. Kolonibari AWC 3. Dakhinpat gaon Digholi Pat AWC,

Majuli - Anganwadi Centres Affected | 36 nos of Anganwadi centers partially submerged on 19.06.2022. 1. Upper Sonowal AWC 2. Kongkurmukh AWC 3. Ukhalchuk AWC 4. Gopalchuk Birson Chuburi AWC 5. Balijan AWC 6. Charighoria AWC 7. Madhupur AWC 8. Ulupam AWC 9. Gopalchuk AWC 10. Luhit Chapori AWC 11. Madhupur Chapori AWC 12. Purona Misamora AWC 13. Modarguri AWC 14. Kankan Chapori AWC 15. Major Chapori AWC 16. Borjan AWC 17. Jugal Chuburi AWC 18. Borduar AWC 19. Misamora AWC 20. Bhangunmari AWC 21. New Misamora AWC 22. Jaboni Chuburi AWC 23. Chengelisuti AWC 24. Namsing Mini AWC 25. Cherepaikhowa AWC 26. Notun Chapori AWC 27. 2 no. Bhekeli AWC 28. Madhupur AWC 29. Gopalchuk Birson Chuburi AWC 30. Kartik Chapori AWC 31. Koroiguri AWC 32. Bhekeli Modarguri AWC 33. Buha Chapori AWC 34. Tenga Chapori AWC 35. Chaidhyaghoria AWC 36. Bhimpara AWC

Morigaon - Health Sub-Centre | (20-06-2022) As per Jt. Director of Health Services, Dharamtul SHC submerged.,

Bhuragaon - Anganwadi Centres Affected | UTTAR PACHIM BARUNGURI, HAIBORGAON PATHAR, GORIAGAON - A, PUB GORIAGAON, HINDU JAPARI, RUPOHIBILL KADAMTOLA,KHERKATA PATHAR,KUBETORY,SANDHOKHAITY,71 no Bor Hollowkunda,72 no Hollowkunda,249 no Hollowkunda sapari-A4,47 no Hollowkunda sapari-B,69 no Tengaguri kosarigaon-A,448 UttarTengaguri kosarigaon sapari,222 no Tengaguri kosarigaon-B,43 no Mohmari pather-B,223 no Mohmari pather-c,42 no Mohmari pather-A,60 no Balidunga pam-,161 no Balidunga Pam-,2351 no Pub Balidunga fakirgaon ,64 NO 2 no Borkur470, no 2 no borkur uttar pachim suburi,246 no 2no Borkur sapari,65 no seujia pather,469 no Dakhin pachim colony,63 no 2 no Borkur ,50 No. Barukata Chaharia,44 No. Niz-Chaharia,45 No. Boramari Kacharigaon,477 No. Niz-Chaharia Luit Paria (Mini),46 No. Bihubori Kacharigaon A,269 No. Jengpori Laokhowa Suburi,47 No. Durabandhi, 267 No. Buwalguri Tribel Suburi, 347 No. Bihubari Beel Sapori, 32 No. Bhakuamari Pam submerged on 19-06-2022,

Elementary Schools Damaged | BARALIMARI HS, NO.2 DURABANDHI LP, NO1 BARUNGURI A. SARKAR LP, PUB BARALIMARI LP, BARDUBA TOP LP, BHURAGAON H.SARKAR H.S.SCHOOL, UTTAR BARDUBA LP (E), UTTAR CHENIMARI LP, TENGAGURI GAON LP, DHEKERAMARI LP, CHENIA ME, PACHIM JAPORI BALIKA LP, PACHIM RUPAHI BILL KISAMKURI LP (E), TENGAGURI GAON CHAPORI LP, HAMUR CHAR LP (E), NO.1

Morigaon

CHAR LP (E), RUPAHI GAON LP, HINDU JAPARI CHAR LP (E), HINDU JAPARI LP, JAPORI HS, GARALU SAROJINI LP, HABIR CHAR LP (E), PACHIM BAGAKURI CHAR LP (E), NO.1 KAURIHAGI LP (E), AIRMARI CHAR LP (E), NO.2 TENGAGURI CHAR LP (E), NO.2 KAURIHAGI LP (E), JAOGAON CHAR LP (E), SIALMARI KACHARIGAON LP, LENGRIBORI LP, DUNGARPAR ME, BOKANI ME, JENGPORI LP (E), LENGERI LP (E), BOWALGURI LP, DUNGAR PAR LP (E), BARUKATA CHAHARIA LP, LENGERI LP, PUB DUNGARPAR FULESWARI LP, TOLOGAON LP, JURBIL LP, DAKHIN JURBIL COLONY LP, KATHPORI GHANA SIMALU LP, SISHUMARI CHAR LP (E), KATHPORI GHANASIMALU CHAR LP (E), DAKHIN JURBIL COLONY LP (E), BARALIMARI MEM, NO.1 BARPATHAR LP (E), KHERKATABORI CHAR LP (E), KHERKATA BORI AJGAR ALI L.P., TENGATOLI LP, KHERKATA PATHAR LP, KHANDAHKHAITY KACHARIGAON LP (E), KHERKATA LP, HAIBARGAON PB ME, KASEM CHAR LP (E), NO.3 NABUR CHAR LP (E), GORIBOR CHAR LP (E), NITMARI CHAR LP (E), KASHIPURI COLONY LP (E), NO.2 KISAMKURI LP (E), NO.2 NABUR CHAR LP (E), NO.3 KISAMKURI LP (E), SIALMARI KACHARIGAON CHAR LP (E), JATIABORI CHAR LP (E), NO.2 HAMUR CHAR LP (E), BAGAKURI CHAR LP (E), BORHOLOWKANDA CHAPORI L.P., SEUJIA PATHAR LP, NO. 2 BARKUR P.S. MADRASSA, SEUJIA PATHAR CHAPORI LP (E), NO.2 BORKUR GIRLS LP, AZARGURI LP, BARUATING LP, MERHABI PITHAKHAITY LP (E), PUB BARUATING LP, BARUATING MEM, KHARIKATA CHAR LP (E), PUB KALAIR CHAR LP (E), NIZ CHAHARIA LP, MERBILL LP (E), BARUATING CHAR LP (E), PUB BALIDUNGA MEM, DAKHIN TENGAGURI KACHARIGAON ME, PACHIM MAHMARI L.P., Bhuragaon Haricharan Sarkar HS School submerged on 19-06-2022

Raha - Secondary Schools Damaged | Chaparmukh BBH Higher Secondary School has been submerged on 20/06/2022,

Samaguri - Anganwadi Centres Affected | 1)57 No Bhurbandha 3, 2) 121 No Bogamukh 1, 3)139 No N C Bhurbandha, 4)157 No Bhurbandha Nadiper, 5)164 No Bhurbandha Dubiper No 1, 6)179 No Bhurbandha No 2, 7)203 No Arob Ali Bosti Bhurbandha Bg, 8)202 No Bhurbandha 4no, 9) 205 No Bhurbandha Nadiper 4no, 10)206 No Bogamukh Hatipara 6n, 11)208 No Bhurbandha Yakubpara 1no, 12)209 No Adhikaribosti 1no Bhurbandha, 13)212 No Bagariti Chowhanbasti 4no, 14)213 No Bogamukh Dakhinpara 5no Dtd-19.06.2022,

Elementary Schools Damaged | 1)3 No Durgabasti LPS, 2) Bhurbandha Chouhan Basti LPS, 3)Bhurbandha Bazargaon LPS, 4)Uttar Lawkhowa Bapuji LPS, 5) 2 No Bhurbandha Binapani LPS, 6. Bhagamukh MES, 7. Bir Chilarai MKB Dtd-19.06.2022,

Nagaon

		Kampur - Anganwadi Centres Affected Total-190nos. AWC affected under kampur Rev. Circle
		reported by ICDS Kathitoli Dtd-20.06.2022
	Nalbari	Paschim Nalbari - Irrigation Canal/Scheme Damaged Burhadia ELIS Point No- 4 & 5, Amoni ELIS, Ghilazari DTWIS Point No. 1, Solmara DTWIS Point No. 1, all Schemes are submerged due to floodwater of Burhadia River. Information received from Irrigation Department on 17/06/2022., Handloom & Textile Deptt 52 nos. weavers family affected. Damage of loom accessories, woven cloths etc. Information received from handloom and textile dept. on 19/06/2022, Banekuchi - Culvert Approach Road Damaged Kashimpur to Merkuchi Road and Culvert Damaged Report From PWD Department on 18.06.2022., Barkhetri - Handloom & Textile Deptt 31 Nos weavingshawn partially damaged of looms and accessories ,looms post ,woven cloth and running warp ect as reported by demonstrator,handloom and textle Nalbarii on 20.06.2022 , Fisheries/Pond Appro 2800 Fishery farmer ,covering aprox 720 HCt. fishery area affected by Flood /Rain as reported by Fishery demonstrator Barkhetri on 20.06.2022
		Sivsagar - Elementary Schools Damaged 264 Nos Rupahimukh LPS, Anirudhdav LPS, Soraguri MES, Rupahimukh Janajati HS,265 Nos Borgaon Miri LPS,, New Gotonga LPS, 499 Nos Garbhonga LPS,Namoni Mamol Garbhonga LPS,Rowmari Phukan Phodia LPS,899 Gupalpur LPS and 263 Nos Guskota LPS are submerged on 19-05-2022,
	Sivasagar	Demow - Anganwadi Centres Affected Jikakota Anganwadi centre was submerged from 18/6/2022 to 20/6/2022, Anganwadi Centres Affected 2 No Borpathar Anganwadi centre was submerged from 18/6/2022 to 20/6/2022,
		Anganwadi Centres Affected Ranuwabali Anganwadi centre was submerged from 18/6/2022 to 20/6/2022, Anganwadi Centres Affected Dehingkalghar Anganwadi Centre was submerged from 18/6/2022 to 20/6/2022
	Sonitpur	Dhekiajuli - Road Breaches Panchnoi to Bhutpara connecting village katcha road damaged due to rising agricultural water at Panchnoi Nepali village. Dated 19.6.22, Road Breaches As per PWD Dhekiajuli div. report, Pmgsy road from Keherukhanda to Nagapathar severely damaged due to flood water at Ch 5719m to 5919m. dated 19.6.22, Washed away Culverts As per PWD Dhekiajuli div. report, slab culvert approach no 2/3 & 3/2 washed away at Gangapur FV due to rising water of Sopai river. package no AS22-181 dated 18.6.22. (reported before), Bridge Approach Road Washed Away As per PWD Dhekiajuli div. report, bridge approach washed away at RCC bridge no1/3 at Monabag TE. dated 17.6.22 (reported before), Fisheries/Pond Fishery damage bhairaguri 29.33ha, Bhergaon 17.33ha, No3 Rongagora 22.27ha, Morabelsiri 14.77ha, Power Dept. Conductors As reported by APDCL, DKJ ESD-I, 1.2KM Conductors damaged under Dhekiajuli Block. Dated 17, 18 & 19.6.22, Power Dept. Poles As reported by APDCL, DKJ ESD-I,11 nos Poles damaged under Dhekiajuli Block. Dated 17, 18 & 19.6.22, Power Dept. Transformers As reported by APDCL, DKJ ESD-I, 3 nos Transformers damaged under Dhekiajuli Block. Dated 17, 18 & 19.6.22,
	Udalguri	Bridge Approach Road Washed Away As per PWD Dhekiajuli div. report, bridge approach washed away at RCC bridge no 4/2 at Santipur to Gangapur via Thakurbasti road dated 18.6.22 Khairabari - Irrigation Canal/Scheme Damaged Udmari FIS U/S canal embankment breached at several chainage. Length: 10 M (approx.) at 6nos. of spot. GPS Coordinates: Lat 26.64388 Long91.8577. Date of Occurrence: 18.06.2022, Irrigation Canal/Scheme Damaged Mahaliapara FIS erosion at D/S of headwork. Length: 50 M (approx.) GPS Coordinates: Lat26.62406 Long 91.8484 . Date of Occurrence: 18.06.2022, Irrigation Canal/Scheme Damaged Harharia FIS at Dongpara main canal embankment at Ch. 172m breached at both side for Length: 10 M (approx.) GPS Coordinates: Lat26.6624366 Long91.785243. Date of Occurrence: 18.06.2022
	District	Details
	Baksa	Baska - Lokpala Erosion at the left bank of River Mora Pagladia at village Lokpala (3 No Lokpala) on 19/06/2022. Erosion length around 30 meters. co-ordinate 1 : - 26.621780, 91.408879, Co-ordinate 2 :- 26.622260, 91.409520. 0
Erosion	Biswanat h	Biswanath - 1 No Dhuli Dilichang, Rowmari Erosion was reported by Lot Mondal near Balichang weekly market by the banks of river Dhuli and at the bridge approach over river Dhuli on 20.06.2022, and severe bank erosion at rowmari area on the R/Bank of river Buroi. Length=1000, Lat:26.8137 N, Long:93.420132 E 0, Halem - Dariakhat As reported by Water Resources, Gohpur on 20/06/2022, bank erosion is

	observed at Dariakhat area on R/B of river Brahmajan. Overtopping is also observed. Length 27m 0
	Manikpur - Erosion to place in Bashbari no 2 approach road 100 mtr. & Agril bundh 50 mtr .erosion
Bongaiga	continues. date-20.06.2022 Erosion Took Place due to River Aie 37 ft.date-20.06.2022/ Erosion due
on	to Aie river 200 mtr. Date:20.06.2022 2200
	Bijni - No-2 Khujurapguri, East Bhabanipur, Balagari, Alengmari, Kashibari, Joypur Bhabanipur,
	Simlaguri, As reported by Chirang W.R. Division, Kajalgaon, Erosion going on at No 2
	Khujurapguri due to Aie river. Length=24.3 mtr(Approx), Breadth= 10 mtr (Approx), Depth= 2.25
	mtr(Approx). Longitude=90.60381 Latitude= 26.550975. Date of Occurrence=20-06-2022. As
	reported by Chirang W.R. Division, Kajalgaon, Erosion going on at East Bhabanipur due to
	Kanamakra river. Length=700 mtr, Breadth=18 mtr, Depth=3 mtr. Longitude=90.572328
	Latitude=26.606104. Date of Occurrence= 17-06-2022. As reported by Chirang W.R. Division,
	Kajalgaon, Erosion going on at Balagari d/s area due to Nangalbhanga river. Length=500 mtr,
	Breadth=25 mtr, Depth=3 mtr. longitude=90.550310 Latitude=26.659241. Date of Occurrence=16-
	06-2022. As reported by Chirang W.R. Division, Kajalgaon, Active river bank erosion at Alengmari
	d/s area due to Nangalbhanga river. Length=300 mtr, Breadth=20 mtr, Depth=3.20 mtr.
Chirang	Longitude=90.552835 Latitude=26.649364. Date of Occurrence=16-06-2022. As reported by Chirang
	W.R. Division, Kajalgaon, River bank erosion going on at Kashibari(west amguri) due to river
	Nangalbhang. Length=150 mtr, Breadth=10 mtr, Depth=2.70 mtr. Longitude=90.554907
	Latitude=26.633030. Date of occurrence=17-06-2022. As reported by Chirang W.R. Division,
	Kajalgaon, River bank erosion going on at Joypur-Bhabanipur due to river Nangalbhanga.
	Length=280 mtr, Breadth=12 mtr, Depth=2.50 mtr. Longitude=90.558121 Latitude=26.602764. Date
	of occurrence=17-06-2022. As reported by Chirang W.R. Division, Kajalgaon, River bank erosion
	going on at simlaguri d/s area due to river Nangalbhanga. Length=300 mtr, Breadth=10 mtr,
	Depth=2.50 mtr. Longitude=90.555291 Latitude=26.638705. Date of occurrence=17-06-2022. 0,
	Bengtal - Durgapur Approximately L-200m B-10m D-5m of R/B eroded by Aie River on 19-06-
	2022 at village Durgapur 0
	Agamoni - Vill: KAIMMATI under CHOTOGUMA GP RIVER EMBANKMENT OF RIVER
	GANGADHAR AT VILL KAIMMATI UNDER CHOTOGUMA GP IS GETTING ERODED AT
	SEVERAL POINTS. AS PER THE FIELD VERIFICATION, THERE ARE HEAVY RAIN CUTS
	AT SEVERAL POINTS. • VILLAGE : KAIMMATI • RIVER: GANGADHAR • GP :
	CHOTOGUMA • INCIDENT DATE : 17/06/2022 TO 20/06/2022 • TIME : 1.00 PM • LAND : 0
	BIGHA 1 KHATA 10 LESSA • HOUSEHOLD AFFECTED : 0 • POPULATION AFFECTED : 0 •
	GPS COORDINATE : LAT. 26.328972. LONG. 89.787409 0,
	South Salmara Part - Matifata As per field verification by the concern lat mondol 4 nos family has
D1 1 :	been eroded due to erosion by river Brahmaputra at village Matifata. On 19/6/22 area Aprox 5B-2K-
Dhubri	10L. 21,
	Athani - Sadhubhasa Pt-I, Sadhubhasa Pt-II, Salmara Pt-Vii, Salmara Pt-iii, Boyzeralga Pt-X,
	Boyzeralga River Block N.C, Katlamari Pt-III, Katlamari Pt-iv, River Block 5 N.C, Podmeralga Pt-II, Bhelengamari, River Block 3 N.C, Salmara Pt-ii, Salmara Pt-V Erosion occurred at Village
	Sadhubhasa Pt-I, Sadhubhasa Pt-II, Salmara Pt-Vii, Salmara Pt-iii, Boyzeralga Pt-X, Boyzeralga
	River Block N.C, Katlamari Pt-III, Katlamari Pt-iv, River Block 5 N.C, Podmeralga Pt-II,
	Bhelengamari, River Block 3 N.C, Salmara Pt-ii and Salmara Pt-V due to flood. 189 Nos. of dwelling
	houses were eroded and they have shifted to their another places. No people become landless due to
	the erosion. Total eroded land measuring 170B-0K-10L. out of which 75B-3K-0L are Residential land
	and 94B-2K-10L are agricultural land. dated 16-06-22 to 19-06-22 1162
	Lala - Sudarsanpur pt-2 unde Lala Rev CircleDate- 19/06/2022 Due to active erosion occurred at
Hailakan	sudarshanpur pt Ill (Goalipar) on R/B of River Katakhal the pacca house of Abir Singha has been
di	collapsed under Lala revenue circle. 1000
	(Kokrajhar) At District - BESARGAON, KAONIABHASA, GARUMARACHAR, BOP PEPSU,
	FHALUGURI AS PER REPORTED BY EXE. ENG WR KOKRAJHAR DIVISION ON 17.06.2022
	1. BANK EROSION OBSERVED AT VILLAGE BEASRGAON(REACH LENGTH 250M) AND
	AT VILLAGE USHAMATI(REACH LENGTH 210M) ON L/B OF RIVER GAURANG. 2. BANK
	EROSION OBSERVED AT VILLAGE KAONIABHASA(ERRODED LENGTH 230M) ON R/B OF
Kokrajha	RIVER CHAMPAMATI 3. BANK EROSION OBSERVED AT VILLAGE
r	GARUMARACHAR(REACH LENGTH 500M) AND AT VILLAGE BAGDOGRA(REACH
	LENGTH 500M) ON L/B OF RIVER SONKOSH 4. BANK EROSION OBSERVED AT VILLAGE
	BOP PEPSU ERRODED LENGTH 350M ON R/B OF RIVER BALATUNG. 5. BANK EROSION
	OBSERVED AT VILLAGE FHALUGURI(REACH LENGTH 450M) AND AT VILLAGE
	CHITHILARGHOP(REACH LENGTH 300M) ON R/B OF RIVER GONGIA 0
Lakhimp	Kadam - Puthimari village Around 0.5 Hact. of land eroded by the River kakoi at Puthimari village,
ur	date: 20/06/2022 informed by WRD, Lakhimpur 0
Morigaon	Morigaon - Saruati, Patrabori, Morigaon (17-06-2022) As per WR Dept, Widening of embankment
11101154011	

	1	
		at erosion affected reach of Saruati on right bank of river Kollong. 0,
		Laharighat - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori As per report of Water
		Resources dept on 20/06/2022, erosion in observed in areas like Leruamukh, Goroimari , Bhajaikhati
		gaon & Barchapori with maximum erosion of 1 m in Leruamukh, 2 m in Goroimari, 5 m in
		Bhajaikhati gaon & 12 m Barchapori 0
	Nalbari	Ghograpar - Katuria As per report received from WRD, on 19/06/2022, Active sloughening continue at Katuria area (Ch-8th Km near railway line on R/B of river noona, Length - 300 M 0
		Chariduar - CHARIDUAR 220 FT LENGHT LAND ERODED AT BAMGAON REVENUE
		VILLAGE RIVER JARASHAR DTD 19/06/2022 EROSION AT SILGHAT RAILWAY LINE
	Sonitpur	UNDER CHARIDUAR REVENUE CIRCLE DTD 20/06/2022 0,
	T	Thelamara - ACTIVE BANK EROSION IS OBSERVED AT KHAGORIJAN AREA ON THE L/B
		OF RIVER BELSIRI DTD 20/06/22 REPORTESD BY WATER RESOURCE DEPT 0
	South Salmara	South Salmara - Katdanga Satdubi pt-i As per information received BEEO South salmara 501 No
		Satimari LP School has been eroded at village Kathdanga Satdubi Pt-I due to erosion by river
		Brahmaputra as on 19/2/22 area Aprox 1 B-2k-10L 0
		Tamulpur - Village Baraliapar, Village Dakhin Gandhibari 1.Eroision 150 m left bank of river
	Tamulpur	Baralia, lat-26.65 long 91.57 village barialiapr 2.Severe Eroision 20 ha right bank of river puthimari,
		lat 26.34 long 91.402 0
		Sadiya - 8th mile, Kailabasti, Lakhimpuria 1. Erosion at 8th mile by Kundil river under the bridge
	Tinsukia	since 16/06/2022 to 20/06/2022 as per report received from the concerned Gaon Pradhan. Stretch area
		is 04 m. Location (27°52'02"N, 95°45'36"E). 2. Active erosion is reported from Koilabasti area by
		Kundil river since 16/06/2022 to 20/06/2022 by concerned Gaon Pradhan. Stretch area is 10 m.
		Location (27°50'48.8"N, 95°42'45.2"E). 3. Active erosion is reported from Lakhimpuria area by
		Kundil river since 16/06/2022 to 20/06/2022 by concerned Gaon Pradhan. Stretch area is 5 m. 0
		Khairabari - 1. JALUKBARI 2. CHABUKDHARA 1. Overflow of Khutinodi at Jalukbari caused
	Udalguri	erosion near Mahendra Boro's house. Length & Breadth: 150 M & 3M (approx.). GPS Coordinates:
		Lat-26.3410 Long: 91.4735. Date of Occurrence: 18.06.2022. Total population affected: 100 (approx.)
		2. Severe Gully erosion at Chabukdhara Village near Amar Boro's house. Length & Breadth: 9 M & 3
		M (approx.). GPS Coordinates: Lat-26.3410 Long: 91.4735. Date of Occurrence: 18.06.2022. Total
		population affected: 80 (approx.) 0
	District	Details
Landslide	Kamrup	Palashbari - Dakhala A minor landslide on 19/06/2022. No loss of life or property took place. Report submitted after field verification of Gaon Pradhan. 0
	Karimgan	Patherkandi - Mendibari, Kalkalighat, Puran Chandpur, Lakhipur, Duhalia Pt-3, Duhalia Pt-4,
		Duhalia pt-2, Eral Pt-4 landslides occured at various parts of the above mentioned villages on
	j	19/06/2022 152
Urban Flood	District	Details
		Barnagar - Barpeta Road Due to heavy rainfall ward no 1, 2, 5 & 9 of Barpeta Road Town is partly
	Barpeta	affected from 15/06/2022 to till date 5800
		Silchar - Linkroad, National Highway road point, Ambicapatty, Church Road, Chandicharan Road,
	Cachar	Bilpar, Public School Road, Subhas Nagar, Sonai Road, N.S. Avenue Due to incessant rainfall,
		closure of sluice gates and over-tapping of Embankments in many areas in and around Silchar Town
		on dated 20.06.2022 11251
	Darrana	Mangaldoi - Ward No. 2,4,5,10 The water logging due to rising of river bega is receding. Dated -20-
	Darrang	6-2022 12000
	Goalpara	Lakhipur - Lakhipur Town Ward No. 1,2,3,4,5,6,8,9&10 Due to Urban Flood in Lakhipur Town
		Ward No. 1,2,3,4,5,6,8,9&10 got affected. The Date of occurrence of Urban Flood on 16.06.2022 to
	Compara	i
		till date i.e 20.06.2022 7512
		Guwahati - B.Baruah Road, Jalukbari, BG Colony Partial watter logging on 20-06-2022 0,
	Kamrup	Guwahati - B.Baruah Road, Jalukbari, BG Colony Partial watter logging on 20-06-2022 0, Dispur - Rukminigaon, Hatigaon, Sarumotoria, Sawkuchi, Hengrabari, Baghorbari, Jatia Birina Path
	Kamrup (M)	Guwahati - B.Baruah Road, Jalukbari, BG Colony Partial watter logging on 20-06-2022 0,
	Kamrup	Guwahati - B.Baruah Road, Jalukbari, BG Colony Partial watter logging on 20-06-2022 0, Dispur - Rukminigaon, Hatigaon, Sarumotoria, Sawkuchi, Hengrabari, Baghorbari, Jatia Birina Path