

FRIMS Assam



Flood Reporting And Information Management System

	Assam Daily Flood Report as on 02-07-2022 at 4:00 PM								
Particulars	Situation as	on 02-07-2	2022 (in last 24 hours)						
Rivers flowing above Danger Level (as	Rivers flowi	ng above d	Kopili (Dharamtul), Disang (Nanglam (Chenimari(Khowang)), Brahmaputra						
per CWC bulletin issued at 8 AM)	Rivers flowi	ng above h	nighest flood Nil						
	No. of Districts Affected	Name of	Flood Affected Districts	Name of Urban Flood Districts					
District Affected	27	Dhemaji, Hailakan Majuli, N	arpeta, Biswanath, Cachar, Charaideo, Chirang, Darrang, Dibrugarh, Dima-Hasao, Goalpara, Golaghat, di, Hojai, Kamrup, Kamrup (M), Karimganj, Lakhimpur, Morigaon, Nagaon, Nalbari, Sivasagar, Sonitpur, r, Tinsukia, Udalguri	Dibrugarh					
No. Of Revenue Circles Affected	77	-							
	District	Total	Revenue Circle						
	Bajali	2	Bajali, Sarupeta						
	Barpeta	5	Barpeta, Baghbar, Kalgachia, Chenga, Sarthebari						
-	Biswanath	3	Biswanath, Gohpur, Halem						
	Cachar	5	Udharbond, Silchar, Sonai, Lakhipur, Katigorah						
	Charaideo	1	Sonari						
	Chirang	1	Bijni						
	Darrang	3	Mangaldoi, Patharighat, Sipajhar						
	Dhemaji	2	Sissiborgaon, Jonai						
	Dibrugarh	7	Chabua, Moran, Dibrugarh West, Naharkatia, Tengakhat, Tingkhong, Dibrugarh East						
	Dima- Hasao	1	Haflong						
	Goalpara	2	Lakhipur, Balijana						
	Golaghat	2	Bokakhat, Khumtai	umtai					
Name Of	Hailakandi	1	Algapur						
Revenue	Hojai	2	anka, Hojai						
Circles	Kamrup	4	Chamaria, North Ghy, Kayan, Hajo	North Ghy, Kayan, Hajo					
Affected	Kamrup (M)	2	Chandrapur, Sonapur						
	Karimganj	5	Nilambazar, Karimganj, RK Nagar, Badarpur, Patherkan	di					
	Lakhimpu r	6	Subansiri, Bihpuria, North Lakhimpur, Narayanpur, Now	boicha, Dhakuakhana					
	Majuli	2	Majuli, Ujani Majuli						
	Morigaon	5	Mikirbheta, Morigaon, Bhuragaon, Mayong, Laharighat						
	Nagaon	6	Kaliabor, Nagaon, Kampur, Raha, Samaguri, Rupahi						
	Nalbari	1	Paschim Nalbari						
	Sivasagar	1	Demow						
	Sonitpur	4	Thelamara, Dhekiajuli, Chariduar, Tezpur						
	Tamulpur	1	Goreswar						
	Tinsukia	2	Tinsukia , Doomdooma						
	Udalguri	1	Udalguri						
	Total	77							
	District	Total	Revenue Circle						
Villages	Bajali	3	(Bajali 1), (Sarupeta 2)	140.) (8					
Affected	I Domoto	317	(Barpeta 145), (Baghbar 42), (Kalgachia 77), (Chenga 19), (Sarthebari 34)						
	Barpeta			lenga 19), (Sarthebarr 34)					
	Biswanath Cachar	11 574	(Biswanath 1), (Gohpur 2), (Raigachia 77), (Ci (Udharbond 34), (Silchar 156), (Sonai 154), (Lak	<u> </u>					

	1	1	1					
	Charaideo	1	(Sonari					
	Chirang	4	(Bijni					
	Darrang	25), (Sipajhar 6)		
	Dhemaji	36		orgaon 10),				
	Dibrugarh	94			ın 16), (Dib ibrugarh East	rugarh West 17), (Naharka 5)	tia 29), (Te	ngakhat 12), (
	Dima- Hasao	1	(Haflon	ng 1)				
	Goalpara	5	(Lakhir	our 2), (Bal	iiana 3)			
	Golaghat	37		hat 30), (K				
	Hailakandi	23	(Algapı	. // \				
	Hojai	5		2), (Hojai	13)			
	Kamrup	22				(Kayan 9), (Hajo 6)		
	Kamrup (M)	28	1		Sonapur 20)	(,		
	Karimganj	76	(Nilaml	bazar 28), (Karimganj 1	2), (RK Nagar 20), (Bada	arpur 16)	
	Lakhimpu					North Lakhimpur 7), (Nar		(Nowboicha 2), (
	r	57		khana 15)	1 , ,,,	1 1 // (J 1 . /	1 // (
	Majuli	14	(Majuli	10), (Ujan	i Majuli 4)			
	Morigaon	310	(Mikirb	heta 25), (Morigaon 14	6), (Bhuragaon 27), (May	ong 103), (Laharighat 9)
	Nagaon	238	(Kaliab	or 2), (Nag	gaon 23), (K	Campur 81), (Raha 116),	Samaguri 1	1), (Rupahi 5)
	Nalbari	1	(Paschi	m Nalbari 1)	_	-	
	Sivasagar	6	(Demov	w 6)				
	Sonitpur	32	(Thelan	nara 4), (D	hekiajuli 9),	(Chariduar 15), (Tezpur	4)	
	Tamulpur	3	(Goresv		•			
	Tinsukia	10	(Margh	erita 1), (T	insukia 4), (Doomdooma 5)		
	Udalguri	1	(Udalgı	ıri 1)	*			
	Total	1934						
	District	Male	Femal e	Children	Total Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details
	Bajali	668	774	291	1733	(Bajali 453), (Sarupeta 1280)	0.00	(Bajali 0.00), (Sarupeta 0.00)
	Barpeta	83166	72929	64720	220815	(Barpeta 37120), (Baghbar 98000), (Kalgachia 19222), (Chenga 21588), (Sarthebari 44885)	14172.00	(Barpeta 8825.50), (Baghbar 2712.00), (Kalgachia 1301.50), (Chenga 1319.00), (Sarthebari 14.00)
	Biswanath	1709	1413	801	3923	(Gohpur 580), (Halem 3343), (Biswanath 0)	207.00	(Gohpur 109.00), (Halem 95.00), (Biswanath 3.00)
Danielation	Cachar	482088	42123 8	328612	1231938	(Udharbond 50723), (Silchar 598925), (Sonai 265513), (Lakhipur 92771), (Katigorah 224006)	0.00	(Udharbond 0.00), (Silchar 0.00), (Sonai 0.00), (Lakhipur 0.00), (Katigorah 0.00)
Population And Crop	Charaideo	26	14	10	50	(Sonari 50)	0.00	(Sonari 0.00)
Area	Chirang	230	260	158	648	(Bijni 648)	0.00	(Bijni 0.00)
Affected	Darrang	17315	15928	5146	38389	(Dalgaon 0), (Mangaldoi 22577), (Patharighat 3320), (Sipajhar 12492)	6501.00	(Dalgaon 0.00), (Mangaldoi 3418.00), (Patharighat 1500.00), (Sipajhar 1583.00)
	Dhemaji	8412	6976	6563	21951	(Sissiborgaon 5701), (Jonai 16250)	375.90	(Sissiborgaon 65.00), (Jonai 310.90)
	Dibrugarh	6703	5264	3506	15473	(Chabua 2822), (Moran 4434), (Dibrugarh West 3217), (Tingkhong 312), (Dibrugarh East 1119), (Naharkatia 534), (Tengakhat 3035)	607.24	(Chabua 12.00), (Moran 127.59), (Dibrugarh West 189.00), (Tingkhong 28.13), (Dibrugarh East 39.50), (Naharkatia 154.02), (Tengakhat 57.00)
	Goalpara	3107	2573	1616	7296	(Lakhipur 2413), (Balijana 4883)	39.00	(Lakhipur 0.00), (Balijana 39.00)
	Goalpara Golaghat	3107	2573	1616	7296 0		39.00 92.00	(Lakhipur 0.00), (

						0), (Hailakar Algapur 424			Lala 0.00), (Hailakandi 0.00), (Algapur 0.00)
	Hojai	367	189	149	705	(Lanka 263 442)), (Hojai	173.00	(Lanka 158.00), (Hojai 15.00)
	Kamrup	1168	763	451	2382	(Chamaria (1427), (Nort), (Kayan 46	th Ghy 909 5)	169.20	(Chamaria 20.70), (Hajo 100.00), (North Ghy 18.50), (Kayan 30.00)
	Kamrup (M)	2266	1796	451	4513	(Chandrapur Sonapur 102	4)	812.50	(Chandrapur 0.00), (Sonapur 812.50)
	Karimganj	14465	9463	4429	28357	(Nilambazar Karimganj 6 Badarpur 98 Patherkandi Nagar 6067	097), (60), (0), (RK	894.00	(Nilambazar 0.00), (Karimganj 894.00), (Badarpur 0.00), (Patherkandi 0.00), (RK Nagar 0.00)
	Lakhimpu r	10198	9868	5833	25899	(Subansiri 0 Lakhimpur 4 Narayanpur Nowboicha 0 Dhakuakhana Bihpuria 218	4068),(0),(0),(. 0),(599.00	(Subansiri 60.00), (North Lakhimpur 0.00), (Narayanpur 0.00), (Nowboicha 0.00), (Dhakuakhana 539.00), (Bihpuria 0.00)
	Majuli	0	0	0	0	(Majuli 0), Majuli 0)	(Ujani	51.26	(Majuli 31.50), (Ujani Majuli 19.76)
	Morigaon	69704	66116	38029	173849	(Mikirbheta Morigaon 12 Bhuragaon 2 Mayong 794 Laharighat 0	27957), (26751), (+), (8007.65	(Mikirbheta 1356.50), (Morigaon 3318.00), (Bhuragaon 925.00), (Mayong 2362.00), (Laharighat 46.15)
	Nagaon	137780	12821 4	112946	378940	(Kaliabor 78 Nagaon 525 Kampur 171 Raha 15517 Samaguri 0)	05), (183), (4), (), (Rupahi	17587.20	(Kaliabor 5.00), (Nagaon 404.00), (Kampur 7191.00), (Raha 9900.20), (Samaguri 4.00), (Rupahi 83.00)
	Nalbari	836	765	237	1838	(Paschim Na	lbari 1838	0.00	(Paschim Nalbari 0.00)
	Sivasagar	2602	2257	1604	6463	(Demow 64		24.40	(Demow 24.40)
	Sonitpur	1999	2351	1855	6205	(Thelamara Dhekiajuli 5 Chariduar 35 Tezpur 724)	127), (54), (357.63	(Thelamara 54.00), (Dhekiajuli 260.00), (Chariduar 31.63), (Tezpur 12.00)
	Tamulpur	998	865	412	2275	(Goreswar 2		0.00	(Goreswar 0.00)
	Tinsukia	547	507	323	1377	(Margherita Tinsukia 702 Doomdooma	2), (675)	44.20	(Margherita 0.00), (Tinsukia 18.00), (Doomdooma 26.20)
	Udalguri	153	91	65	309	(Khairabari Harisinga 0 Kalaigaon 0 Udalguri 30), (), (0.00	(Khairabari 0.00), (Harisinga 0.00), (Kalaigaon 0.00), (Udalguri 0.00)
	Total	863957	76661 4	587207	2217778			50714.18	
	District	Total	Relief C					ribution Cent	res
	Bajali	6	6(Sarupe		1.0		0(Sarupeta		
	Barpeta	41		eta 35, Che				0, Chenga 0)	
	Biswanath	5		1 1, Gohpur		115	4(Halem 2	, Gohpur 2)	
Relief	Cachar	201	Katigora	ıh 95)	ai 37, Lakhi	pur 15,			khipur 0, Katigorah 0)
Camps /	Charaideo	1	0(Sonari				1(Sonari 1)	
Centres	Chirang	4	4(Bijni		" 10)		0(Bijni 0)	L:112 C: "	
Opened	Darrang	18		aldoi 0, Sipa	•			loi 12, Sipajh	
	Dhemaji Dibrugarh	9 24	3(Dibrug		onai 0) Chabua 0, N	Moran 0,	21(Dibrugar		6) abua 2, Moran 6,
	Dima-	24	Dibruga:	rh West 0) ong 22)			Dibrugarh V		
	Hasao		-(-2021)	φ i ==/			(8	,	

	Hailakandi	5	5(Algapi	ur 5)			0(Algapur	0)		
	Hojai	10	3(Hojai	(3)			7(Hojai 7)		
	Kamrup	15	15(North	Ghy 2, Ka	yan 2, Hajo	11)	0(North Gl	ny 0, Kayan	0, Hajo 0)	
	Varimaani	47	34(Nilar	nbazar 6, Ka	arimganj 15,	RK Nagar	13(Nilamb	azar 1, Karin	nganj 0, RK N	lagar 0,
	Karimganj	47		pur 8, Pathe				0, Patherkandi		
	Lakhimpu r	16	0(Subansiri 0, Bihpuria 0, Narayanpur 0, Nowboicha 0)				16(Subansiri 5, Bihpuria 6, Narayanpur 4, Nowboicha 1)			
	Morigaon	40	12(Miki	rbheta 3, Mo	origaon 3, Bl	nuragaon 6)	28(Mikirbl	neta 0, Morig	aon 13, Bhura	agaon 15)
	Nagaon	47	47(Naga	on 17, Kam	pur 17, Raha	ı 13)	0(Nagaon	0, Kampur 0	, Raha 0)	
	Nalbari	1	1(Paschi	m Nalbari 1)		0(Paschim	Nalbari 0)		
	Sivasagar	6	0(Demo	w 0)			6(Demow	6)		
	Sonitpur	4	0(Dhekia	ajuli 0, Char	riduar 0, Tez	pur 0)	4(Dhekiaju	ıli 1, Charidu	ar 2, Tezpur	1)
	Tamulpur	5	2(Goresv	war 2)			3(Goreswa	r 3)		
	Tinsukia	11		tia 2, Doom	dooma 3)			2, Doomdoo	ma 4)	
	Udalguri	2	2(Udalgi	uri 2)			0(Udalguri	(0)		
	Total	542	404				138			
	District	Total		e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y
	Bajali	1280		0), (Sarupeta		455	515	255	55	0
	Barpeta	3407		3249), (Baş nia 0), (Cher ari 0)		822	1190	1393	2	0
	Biswanath	44	(Gohpur	0), (Halem	44)	14	21	9	0	0
	Cachar	242157	(Udharbond 0), (Silchar 143368), (Sonai 20450), (Lakhipur 2075), (Katigorah 76264)			107755	74206	60096	100	0
	Chirang	648	(Bijni 6	548)		230	258	158	2	0
	Dibrugarh	203	(Chabua 0), (Moran 0), (Dibrugarh West 0), (Naharkatia 0), (Tengakhat 0), (Tingkhong 0), (Dibrugarh East 203)			101	80	22	0	0
Inmates In	Dima- Hasao	1421	(Haflong 1421)			509	546	314	51	1
Relief Camps	Hailakandi	2136	_	erra 0), (Lala ndi 0), (Alg		1135	674	320	7	0
	Hojai	408	(Lanka	0), (Hojai 4	08)	225	131	49	3	0
	Kamrup	965	(North C	ia 0), (Hajo Shy 175), (K	ayan 38)	467	328	170	0	0
	Karimganj	5842	824), (Pa	azar 368), (I atherkandi 0 anj 3770), (I),	2645	1617	1580	0	0
	Morigaon	5107	(Mikirbheta 928), (Morigaon 482), (Mayong 0), (Laharighat 0), (Bhuragaon 3697)			1867	1808	1381	51	0
	Nagaon	12922	(Rupahi	or 0), (Samaş 0), (Nagaon r 4980), (Ra	(6351),	4828	4436	3515	132	11
	Nalbari	26	(Paschin	n Nalbari 26)	12	9	5	0	0
	Tamulpur	102	(Goresw			40	41	21	0	0
	Tinsukia	358	(Doomd	rita 0), (Tin ooma 155)		121	120	104	12	1
	Udalguri	309		oari 0), (Hari on 0), (Udal	•	128	115	65	0	1
	Total	277335	34.1	Т	CLUI	121354	86095	69457	415	14
Human	District	Total	Male	Female	Children	Revenue Cir		(C:1.1	0) (011)	
Lives Lost - Confirmed	Cachar	1	1	0	0	(Katigorah Cudharbond		U), (Silchar 	0), (Sonai 1),	
	Total	1	1	0	0					
Human Lives Lost Confirmed - Death Type	District	Total	Flood Death	General Drownin g (Non Flood)	Landslide					

	Cachar	1	1	0	0					
	Total	1	1	0	0					
Human	Total	1	1	U	U					
Lives Lost -	Nil									
Missing	1111									
Human										
Lives Lost										
Missing -	Nil									
Type										
71	District	Total	Big	Small	Poultry					
	Bajali	2183	431	422	1330					
		41.6605	15763	66001	100100					
	Barpeta	416685	6	66921	192128					
	Biswanath	12183	8006	4177	0					
	Darrang	120	120	0	0					
	Dhemaji	21003	19292	1711	0					
	Dibrugarh	21857	8795	6444	6618					
	Golaghat	350	265	85	0					
Animals	Hailakandi	47629	16191	10156	21282					
Affected	Kamrup	2500	2000	500	0					
Affected	Kamrup	1019	729	215	75					-
1	(M)	1019	147	213	13					
	Lakhimpu	16997	8113	3448	5436					
1	r									
1	Morigaon	135949	43332	22211	70406					
	Nagaon	98053	45348	29760	22945					
	Sivasagar	4085	2789	1296	0					
	Sonitpur	1167	805	362	0					
	Total	781780	31385	147708	320220					
			2							
	District	Total	Big	Small	Poultry					
	Barpeta	32661	0	1	32660					
			_	_						
	Darrang	1000	0	0	1000					
Animals	Golaghat	1	0	1	1000					
Washed	Golaghat Karimganj	1 1	0	1 0	1000 0 0					
	Golaghat Karimganj Morigaon	1 1 147	0 1 0	1 0 0	1000 0 0 147					
Washed	Golaghat Karimganj Morigaon Nagaon	1 1 147 285	0 1 0 20	1 0 0 65	1000 0 0 147 200					
Washed	Golaghat Karimganj Morigaon Nagaon Nalbari	1 1 147 285 147	0 1 0 20 4	1 0 0 65 43	1000 0 0 147 200 100					
Washed	Golaghat Karimganj Morigaon Nagaon	1 147 285 147 34242	0 1 0 20	1 0 0 65	1000 0 0 147 200					
Washed	Golaghat Karimganj Morigaon Nagaon Nalbari Total	1 1 147 285 147 34242 Fully	0 1 0 20 4 25	1 0 0 65 43 110	1000 0 0 147 200 100 34107	Partially	Partially	Others	Others	Others
Washed	Golaghat Karimganj Morigaon Nagaon Nalbari	1 147 285 147 34242 Fully Kucch	0 1 0 20 4	1 0 0 65 43	1000 0 0 147 200 100	Partially Pukka	Partially Total	Others Huts	Cattle	Others Total
Washed	Golaghat Karimganj Morigaon Nagaon Nalbari Total District	1 147 285 147 34242 Fully Kucch	0 1 0 20 4 25 Fully Pukka	1 0 0 65 43 110 Fully Total	1000 0 147 200 100 34107 Partially Kuccha	Pukka	Total	Huts	Cattle Shed	Total
Washed	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji	1 147 285 147 34242 Fully Kucch a	0 1 0 20 4 25 Fully Pukka	1 0 0 65 43 110 Fully Total	1000 0 147 200 100 34107 Partially Kuccha	Pukka 0	Total	Huts 10	Cattle Shed	Total 10
Washed	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat	1 147 285 147 34242 Fully Kucch	0 1 0 20 4 25 Fully Pukka	1 0 0 65 43 110 Fully Total	1000 0 147 200 100 34107 Partially Kuccha	Pukka	Total	Huts	Cattle Shed	Total
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu	1 147 285 147 34242 Fully Kucch a	0 1 0 20 4 25 Fully Pukka	1 0 0 65 43 110 Fully Total	1000 0 147 200 100 34107 Partially Kuccha	Pukka 0	Total	Huts 10	Cattle Shed	Total 10
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r	1 1 147 285 147 34242 Fully Kucch a 2 0	0 1 0 20 4 25 Fully Pukka 0 0	1 0 0 65 43 110 Fully Total 2 0	1000 0 147 200 100 34107 Partially Kuccha 10 0	Pukka 0 0 0 0	Total 10 0 1	Huts 10 7 0	Cattle Shed 0 0 0	Total 10 7 0
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon	1 147 285 147 34242 Fully Kucch a 2 0	0 1 0 20 4 25 Fully Pukka 0 0	1 0 0 65 43 110 Fully Total 2 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1	Pukka 0 0 0 0 0	Total 10 0 1 175	Huts 10 7 0 0	Cattle Shed 0 0 0 0	Total 10 7 0 0
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia	1 1 147 285 147 34242 Fully Kucch a 2 0 0	0 1 0 20 4 25 Fully Pukka 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2	Pukka 0 0 0 0 0 0 0	Total 10 0 1 175 2	Huts 10 7 0 0 0	Cattle Shed 0 0 0 0 0 0	Total 10 7 0 0 0
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1	0 1 0 20 4 25 Fully Pukka 0 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47	Pukka 0 0 0 0 0 0 0 0 0	Total 10 0 1 175 2 47	Huts 10 7 0 0 0 2	Cattle Shed 0 0 0 0 2	Total 10 7 0 0 0 4
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia	1 1 147 285 147 34242 Fully Kucch a 2 0 0	0 1 0 20 4 25 Fully Pukka 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2	Pukka 0 0 0 0 0 0 0	Total 10 0 1 175 2 47 235	Huts 10 7 0 0 0	Cattle Shed 0 0 0 0 2 2	Total 10 7 0 0 0 4 21
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1	0 1 0 20 4 25 Fully Pukka 0 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235	Pukka 0 0 0 0 0 0 0 0 0 0 0	Total 10 0 1 175 2 47 235 Animal	Huts 10 7 0 0 0 2 19	Cattle Shed 0 0 0 0 2 2 Person	Total 10 7 0 0 0 4 21 Medical
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 1 0 4	0 1 0 20 4 25 Fully Pukka 0 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235	Pukka 0 0 0 0 0 0 0 0 Person	10 0 1 175 2 47 235 Animal Evacuate	Huts 10 7 0 0 2 19 Helicopte	Cattle Shed 0 0 0 0 2 Person Evacuate	Total 10 7 0 0 0 4 21 Medical Team
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1	0 1 0 20 4 25 Fully Pukka 0 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235	Pukka 0 0 0 0 0 0 0 0 0 0 0	10 0 1 175 2 47 235 Animal Evacuate d By	Huts 10 7 0 0 0 2 19	Cattle Shed 0 0 0 0 2 2 Person	10 7 0 0 0 4 21 Medical Team Deploye
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 1 0 4	0 1 0 20 4 25 Fully Pukka 0 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235	Pukka 0 0 0 0 0 0 0 Person Evacuated	10 0 1 175 2 47 235 Animal Evacuate	Huts 10 7 0 0 0 2 19 Helicopte rs	Cattle Shed 0 0 0 0 2 Person Evacuate d By	Total 10 7 0 0 0 4 21 Medical Team
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 1 0 4	0 1 0 20 4 25 Fully Pukka 0 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235	Pukka 0 0 0 0 0 0 0 Person Evacuated	10 0 1 175 2 47 235 Animal Evacuate d By	Huts 10 7 0 0 0 2 19 Helicopte rs	Cattle Shed 0 0 0 0 2 2 Person Evacuate d By Helicopte	10 7 0 0 0 4 21 Medical Team Deploye
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District	1 1 147 285 147 34242 Fully Kucch a 2 0 1 1 0 4 Agency	0 1 0 20 4 25 Fully Pukka 0 0 0 0	1 0 0 65 43 110 Fully Total 2 0 0 1 1 1 0 4	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed	Pukka 0 0 0 0 0 0 Person Evacuated By Boats	10 0 1 175 2 47 235 Animal Evacuate d By Boats	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed	Cattle Shed 0 0 0 0 2 2 Person Evacuate d By Helicopte rs	Total 10 7 0 0 0 4 21 Medical Team Deploye d
Washed Away Houses Damaged Rescue	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District District	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 0 4 Agency Veterinar treatment	0 1 0 20 4 25 Fully Pukka 0 0 0 0 0 0 vy dept- 4 is camp org	1 0 0 0 65 43 110 Fully Total 2 0 0 1 1 0 4	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed 0	Pukka 0 0 0 0 0 0 Person Evacuated By Boats	10 0 1 175 2 47 235 Animal Evacuate d By Boats 0	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed 0	Cattle Shed 0 0 0 0 2 2 Person Evacuate d By Helicopte rs 0	Total 10 7 0 0 0 4 21 Medical Team Deploye d 13
Washed Away	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 0 4 Agency Veterinar treatment Guileza,E	0 1 0 20 4 25 Fully Pukka 0 0 0 0 0 0 0 0 3ry dept- 4 is camp org	1 0 0 0 65 43 110 Fully Total 2 0 0 1 1 0 4	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed	Pukka 0 0 0 0 0 0 Person Evacuated By Boats	10 0 1 175 2 47 235 Animal Evacuate d By Boats	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed	Cattle Shed 0 0 0 0 2 2 Person Evacuate d By Helicopte rs	Total 10 7 0 0 0 4 21 Medical Team Deploye d
Washed Away Houses Damaged Rescue	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District Bajali Barpeta	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 0 4 Agency Veterinar treatment	0 1 0 20 4 25 Fully Pukka 0 0 0 0 0 0 0 0 3ry dept- 4 is camp org	1 0 0 0 65 43 110 Fully Total 2 0 0 1 1 0 4	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed 0	Pukka 0 0 0 0 0 0 0 0 Person Evacuated By Boats 0	10 0 1 175 2 47 235 Animal Evacuate d By Boats 0	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed 0	Cattle Shed 0 0 0 0 2 2 Person Evacuate d By Helicopte rs 0	Total 10 7 0 0 0 4 21 Medical Team Deploye d 13
Washed Away Houses Damaged Rescue	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District Bajali Barpeta	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 0 4 Agency Veterinar treatment Guileza,E	0 1 0 20 4 25 Fully Pukka 0 0 0 0 0 0 0 0 3ry dept- 4 is camp org	1 0 0 0 65 43 110 Fully Total 2 0 0 1 1 0 4	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed 0	Pukka 0 0 0 0 0 0 Person Evacuated By Boats	10 0 1 175 2 47 235 Animal Evacuate d By Boats 0	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed 0	Cattle Shed 0 0 0 0 2 2 Person Evacuate d By Helicopte rs 0	Total 10 7 0 0 0 4 21 Medical Team Deploye d 13
Washed Away Houses Damaged Rescue	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District Bajali Barpeta	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 0 4 Agency Veterinar treatment Guileza,E	0 1 0 20 4 25 Fully Pukka 0 0 0 0 0 0 0 0 3ry dept- 4 is camp org	1 0 0 0 65 43 110 Fully Total 2 0 0 1 1 0 4	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed 0	Pukka 0 0 0 0 0 0 0 0 0 Person Evacuated By Boats 0 0	Total 10 0 1 175 2 47 235 Animal Evacuate d By Boats 0 0	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed 0	Cattle Shed 0 0 0 0 0 2 2 Person Evacuate d By Helicopte rs 0 0	Total 10 7 0 0 0 4 21 Medical Team Deploye d 13
Washed Away Houses Damaged Rescue	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District Bajali Barpeta	1 1 147 285 147 34242 Fully Kucch a 2 0 1 1 0 4 Agency Veterinar treatment Guileza,E Gaon,Bal	0 1 0 20 4 25 Fully Pukka 0 0 0 0 0 0 0 sydept-4 c camp org	1 0 0 65 43 110 Fully Total 2 0 0 1 1 1 0 4 4 mos of anised at Haldhia	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed 0	Pukka 0 0 0 0 0 0 0 0 Person Evacuated By Boats 0	10 0 1 175 2 47 235 Animal Evacuate d By Boats 0	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed 0	Cattle Shed 0 0 0 0 2 2 Person Evacuate d By Helicopte rs 0	Total 10 7 0 0 0 4 21 Medical Team Deploye d 13
Washed Away Houses Damaged Rescue	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District Bajali Barpeta Biswanath Bongaigao n	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 0 4 Agency Veterinar treatment Guileza,E Gaon,Bal	0 1 0 20 4 25 Fully Pukka 0 0 0 0 0 0 0 sydept-4 c camp org Bardanga, Faipather	1 0 0 65 43 110 Fully Total 2 0 0 1 1 1 0 4 4 mos of anised at Haldhia	1000 0 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed 0 0 0	Pukka 0 0 0 0 0 0 0 0 0 Person Evacuated By Boats 0 0 0	Total 10 0 1 175 2 47 235 Animal Evacuate d By Boats 0 0 0	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed 0 0 0	Cattle Shed 0 0 0 0 0 2 2 Person Evacuate d By Helicopte rs 0 0 0	Total 10 7 0 0 0 4 21 Medical Team Deploye d 13 0
Washed Away Houses Damaged Rescue	Golaghat Karimganj Morigaon Nagaon Nalbari Total District Dhemaji Golaghat Lakhimpu r Morigaon Tinsukia Udalguri Total District Bajali Barpeta Biswanath Bongaigao	1 1 147 285 147 34242 Fully Kucch a 2 0 0 1 1 0 4 Agency Veterinar treatment Guileza,E Gaon,Bal	0 1 0 20 4 25 Fully Pukka 0 0 0 0 0 0 0 sydept-4 c camp org	1 0 0 0 65 43 110 Fully Total 2 0 0 1 1 1 0 4 4 vil	1000 0 147 200 100 34107 Partially Kuccha 10 0 1 175 2 47 235 Boats Deployed 0	Pukka 0 0 0 0 0 0 0 0 0 Person Evacuated By Boats 0 0	Total 10 0 1 175 2 47 235 Animal Evacuate d By Boats 0 0	Huts 10 7 0 0 0 2 19 Helicopte rs Deployed 0	Cattle Shed 0 0 0 0 0 2 2 Person Evacuate d By Helicopte rs 0 0	Total 10 7 0 0 0 4 21 Medical Team Deploye d 13

		Fire & E	nergency	Services						
			NDRF, ŠI							
	Chirang				0	0	0	0	0	4
	Darrang				1	0	0	0	0	21
	Dhemaji				0	0	0	0	0	2
	Dibrugarh				0	0	0	0	0	8
	Dima- Hasao		ence/Trainers, Police,		0	0	0	0	0	15
	Goalpara	MIIAI, A	IDCL		0	0	0	0	0	2
	Golaghat				0	0	0	0	0	1
	Hailakandi				0	0	0	0	0	24
	Hojai				0	0	0	0	0	3
	Kamrup				0	0	0	0	0	2
	Majuli				0	0	0	0	0	6
	Morigaon	material o	leployed fo distribtutio	n.	10	0	0	0	0	15
	Nagaon		fice/Local ration, Lo	cal People,	1	0	0	0	0	24
	Sonitpur				0	0	0	0	0	4
	Total District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in	0 Cattle Feed	- Rice Bran	(in Q)
	Di i	52 .00	10.21	0.00	0.00		Q)	0.00		
	Biswanath	53.89	10.21	0.00	0.00	0.00	295.00	0.00		
	Cachar	145.37	27.17	7.32	732.00	0.00	0.00	0.00		
	Charaideo	0.84	0.15 2.99	0.50 1.55	0.50	0.00	0.00 40.00	0.00		
	Chirang	17.46 111.48	110.85	8.73	133.03 2122.00	0.00	0.00	0.00		
	Darrang Dhemaji	0.00	0.00	0.00	0.00	0.00	1911.22	0.00		
	Dibrugarh	125.95	23.07	6.20	188.01	0.00	227.50	0.00		
Relief Distributed	Dima- Hasao	1.95	0.16	0.00	5.00	0.00	0.00	0.00		
	Hailakandi	0.00	0.00	0.00	0.00	0.00	25.00	0.00		
	Karimganj	61.00	11.16	3.31	312.30	0.00	320.00	354.00		
	Lakhimpu r	354.04	64.15	19.24	1924.00	20.00	0.00	721.46		
	Morigaon	609.49	111.00	33.30	946.49	0.00	660.00	0.00		
	Sivasagar	106.71	19.39	5.82	0.00	0.00	0.00	0.00	· · · · · · · · · · · · · · · · · · ·	
	Sonitpur	37.44	6.92	2.08	142.50	0.00	8.50	0.00		
	Tamulpur	31.59	6.03	1.81	180.00	0.00	0.00	0.00		
	Tinsukia	26.35	4.80	1.45	145.75	0.00	0.00	0.00		
	Total	1683.5	398.05	91.31	6831.58	20.00	3487.22	1075.46		
	District	Baby Fo	od	Baby Food	l Solid	Others				
	Biswanath Cachar	0.00-Q 0.00-Q		0.00-Q 0.00-Q		Mortien -13.0	n Dlett Camall	12 00 Dl-+		
	Charaideo	0.00-Q 0.00-Pkt		0.00-Q 0.00-Pkt		Mortien -13.0	o-i ki, Calidi	-13.00-PKl		
	Chirang	0.00-I Kt		103.00-Pkt		Candle-383.00-Pkt; Potato-2.37-Q; Onion-79.00-Kg; Chilli-20.00-Kg; Soyabean-39.50-Kg; Soap-40.00-Pieces; Tarpaulin-				
Relief	Darran ~	0.00-Q		0.00-Q, 75	6 00 Dlst	18.00-Pieces				
Distributed	Darrang Dhemaji	0.00-Q 0.00-Q		0.00-Q, 750 0.00-Q	0.00-FKI	0-0.00-Q Tarpaulin-210) (()_Pieces			
Others	Dibrugarh	0.00-Q, 1 Pkt	151.00-	0.00-Q, 74	4.50-Kg	Bleaching Powder-59.00-Kg; Halogen Tablet-2400.00-Pieces; Water Pouches-2500.00-Pkt; NADCC Tablet-9000.00-Pieces; Water Pouch-1500.00-Pkt; Water Pouch-4000.00-Pieces; Halogen Tablets-500.00-Pieces; Soyabean-12.00-Pkt; Potato-52.00-Kg; Green veg-14.00-Kg; Bread-50.00-Pkt; Turmeric powder -2.10-Kg; Horlicks-41.00-Pkt; Lemon-12.00-Pieces; Onion-40.00-Kg; Mosquito coil-10.00-Pieces; Mineral water-70.00-L				
	Dima- Hasao	1.00-Pkt		0.00-Q		Onion-8.00-Kg; Milk-1.50-L; Match Box-10.00-Pkt; M. Repellent-13.00-Pkt; Soap-16.00-Pieces; Phenyl-2.00-L				

1	Hailakandi	0.00-Q		0.00-Q	
	Karimganj	0.00-Q		0.00-Q	Wheat Bran-150.00-Q; HALOGEN TABLET-2500.00-Pieces; CHEMICAL PACKETS (50 GRAMS)-1200.00-Pkt; WATER POUCH (300 ML)-5000.00-Pkt; HYPOCHLORITE SOLUTION-10.00-Pieces; LIME BLEACHING MIXTURE (500GRAM POUCH)-40.00-Pkt; Water Purification Tablet-3825.00-Pkt; Chemical Packets-6950.00-Pkt; Water Pouch-300.00-Pkt; Lime & Bleaching Powder Pouch-1550.00-Pkt; Hydrochloride Solution-25.00-L
	Lakhimpu r	0.00-Q, 1 Pkt	819.00-	21.83-Q	Concentrated Cettle Feed Godrej Supreme-105.00-Q; Halogen Tablet (PHE)-8000.00-Pkt; Water Pouch (PHE)-11000.00-Pkt; Jaggery (Gur)-5.46-Q; Chira-16.24-Q; tarpaulin-1000.00-Pieces
	Morigaon	0.00-Q		0.00-Q	Chemical Packets-500.00-Q; Halogen Tablets-4000.00-Q; Water Pouch -4000.00-Q
	Nagaon	0.00-Q		0.00-Q	HTW-1.00-Pieces; Tube Well-15.00-Pieces
	Sivasagar	234.50-L		234.50-Kg	Sugar (against baby food)-118.00-Kg; Sanitary Napkin-1330.00-Pkt; Phenyl-1980.00-Pieces
	Sonitpur	0.00-Q		0.00-Q	Chira-25.26-Q; Gur-4.75-Q
	Tamulpur Tinsukia	0.00-Q 0.00-Q		0.00-Q 0.00-Q	0-0.00-Q
		Numbe		0.00-Q	U-0.00-Q
	District	r	Details		
Infrastructu re Damaged - Embankme nt Breached	Darrang	2	Chenglia depressi Nonoi R Nagaon	ajhar Ch 16800 m from Mi on as reported by W/R dep /B embankment from MM Vill at Ch 7700 m from M	ment Chengliajhar Breach at Nonoi R/B embankment at PK to NH-15 at 12.40 A.M on 17/6/2022 due to slump down and att (Long - 91.853361, Lat - 26.417306), to MPK Road Nagaon Breach at Nonoi R/B embankment at PK to NH-15 at 11.15 A.M on 17/6/2022 due to slump down and att (Long - 91.853020, Lat - 26.500905)
	Total	2			
	District	Numbe r	Details		
			infront o	of Dipu Sarma house throug EGA 2019-20.AFFECTED	iver at Barmanikpur Barmanikpur Embankment at Kaldiya River gh Narayan Nath house to Hitesh Das Vill- Barmanikpur LENGTH 30M BREADTH 4M DEPTH 2M.This report is received
Infrastructu re Damaged - Embankme nt Affected	Bajali	7	Mathaur from Ch NREGA BDO,Ba Embank M BREA (Long - Embank Side of Ferosion M BREA (Long - Embank Via Bela 1M.This 0.000000 Embank to Bakap 1.4mtr.T 0.000000	ri from Chaibari Uttar suba aibari Uttar suba pub Muri AFFECTED LENGTH 20 ajali Dev. Block on 02/07/2 ment of Kaldiya river from ADTH 4M DEPTH 2M.Th 0.000000, Lat - 0.000000), ment of Kaldiya river Da Rehabari H S school to Bar DO,Bajali Dev. Block on 02 of Embankment at kaldiya ADTH 4M DEPTH 2M.Th 0.000000, Lat - 0.000000), ment of Kaldiya river ger ana suba Under MGNREG a report is received from Bl 00, ment on Kaldia River Bar para LP School under MGN This report is received from 00)	2/07/2022 (Long - 0.000000, Lat - 0.000000), pub Muriya Gohain ghar CHAIBARI amaged Dong Mathauri ya Gohain ghar to Ramakanta Das house at Vill -Chaibari under O M BREADTH 4M DEPTH 2M.This report is received from 2022 (Long - 0.000000, Lat - 0.000000), n the back side Rihabari HS Rihabari AFFECTED LENGTH 20 is report is received from BDO,Bajali Dev. Block on 02/07/2022 khin Rehabari Embankment of Kaldiya river starting from the back adhasidhani Under MGNREGA 2020-21.This report is received 2/07/2022 (Long - 0.000000, Lat - 0.000000), river old majid to charapar Gergeria AFFECTED LENGTH 30 is report is received from BDO,Bajali Dev. Block on 02/07/2022 geria Embankment of Kaldiya river Habil Ali house to Deben Das A 2020-21 .AFFECTED LENGTH 30 M BREADTH 4M DEPTH DO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - malikuchi Embankment on Kaldia River from Bijay Kalita house NREGA 2020-21. LENGTH 100mtr BREADTH 4mtr DEPTH 10 BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat -
re Damaged - Embankme	Barpeta	7	Mathaur from Ch NREGA BDO, Ba Embank M BREA (Long - Embank Side of From BE Erosion M BREA (Long - Embank Via Bela 1M. This 0.000000 Embank to Bakap 1.4mtr. To 0.000000 Chenga Brahmap divi. on	ri from Chaibari Uttar suba aibari Uttar suba pub Muri AFFECTED LENGTH 20 ajali Dev. Block on 02/07/2 ment of Kaldiya river from ADTH 4M DEPTH 2M.Th 0.000000, Lat - 0.000000), ment of Kaldiya river Da Rehabari H S school to Bar DO,Bajali Dev. Block on 02 of Embankment at kaldiya ADTH 4M DEPTH 2M.Th 0.000000, Lat - 0.000000), ment of Kaldiya river ger ana suba Under MGNREG report is received from Bl 00, ment on Kaldia River Bar ara LP School under MGNREG report is received from 00 on 1000000 ment of Kaldiya river Bar ara LP School under MGN bris report is received from 00 on 1000000 ment of Kaldiya River Bar ara LP School under MGN bris report is received from 00 on 1000000 ment of Kaldiya River Bar ara LP School under MGN bris report is received from 00 on 1000000 ment of Kaldia River Bar ara LP School under MGN bris report is received from 00 on 1000000 ment of Kaldia River Bar ara LP School under MGN bris report is received from 00 on 10000000 ment of Kaldia River Bar ara LP School under MGN bris report is received from 00 on 10000000 ment of Kaldia River Bar ara LP School under MGN bris report is received from 00 on 10000000 ment of Kaldia River Bar ara LP School under MGN bris report is received from 00 on 10000000 ment of Kaldia River Bar ara LP School under MGN bris report is received from 00 on 10000000 ment of Kaldia River Bar ara LP School under MGN bris report is received from 00 on 100000000000000000000000000000000	2/07/2022 (Long - 0.000000, Lat - 0.000000), pub Muriya Gohain ghar CHAIBARI amaged Dong Mathauri ya Gohain ghar to Ramakanta Das house at Vill -Chaibari under O M BREADTH 4M DEPTH 2M.This report is received from 2022 (Long - 0.000000, Lat - 0.000000), n the back side Rihabari HS Rihabari AFFECTED LENGTH 20 is report is received from BDO,Bajali Dev. Block on 02/07/2022 khin Rehabari Embankment of Kaldiya river starting from the back idhasidhani Under MGNREGA 2020-21.This report is received 2/07/2022 (Long - 0.000000, Lat - 0.000000), river old majid to charapar Gergeria AFFECTED LENGTH 30 is report is received from BDO,Bajali Dev. Block on 02/07/2022 geria Embankment of Kaldiya river Habil Ali house to Deben Das A 2020-21 .AFFECTED LENGTH 30 M BREADTH 4M DEPTH DO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - rmalikuchi Embankment on Kaldia River from Bijay Kalita house NREGA 2020-21. LENGTH 100mtr BREADTH 4mtr DEPTH 1 BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - Brahmaputra river Rumari village B/Dyke on R/B of river arjan from ch. 5.80 km to 33.232 km reported by W.R Mukalmua
re Damaged - Embankme			Mathaur from Ch NREGA BDO, Ba Embank M BREA (Long - LEMBANK Side of Farmank Via Bela 1M. This 0.00000 Embank to Bakap 1.4mtr. To.000000 Chenga Brahmap divi. on Srijang Mulbari Bongaig	ri from Chaibari Uttar suba aibari Uttar suba pub Muria AFFECTED LENGTH 20 ajali Dev. Block on 02/07/2 ment of Kaldiya river from ADTH 4M DEPTH 2M.Th 0.000000, Lat - 0.000000), ment of Kaldiya river Da Rehabari H S school to Bar DO,Bajali Dev. Block on 02 of Embankment at kaldiya ADTH 4M DEPTH 2M.Th 0.000000, Lat - 0.000000), ment of Kaldiya river ger ana suba Under MGNREG or report is received from Bl DO, ment on Kaldia River Bar DO, ment on Kaldia River Bar Doy, ment on Ment on Doy, ment on Doy, ment on Doy, ment on Doy, ment	2/07/2022 (Long - 0.000000, Lat - 0.000000), pub Muriya Gohain ghar CHAIBARI amaged Dong Mathauri ya Gohain ghar to Ramakanta Das house at Vill -Chaibari under D M BREADTH 4M DEPTH 2M.This report is received from 2022 (Long - 0.000000, Lat - 0.000000), In the back side Rihabari HS Rihabari AFFECTED LENGTH 20 is report is received from BDO,Bajali Dev. Block on 02/07/2022 khin Rehabari Embankment of Kaldiya river starting from the back Idhasidhani Under MGNREGA 2020-21.This report is received 2/07/2022 (Long - 0.000000, Lat - 0.000000), river old majid to charapar Gergeria AFFECTED LENGTH 30 is report is received from BDO,Bajali Dev. Block on 02/07/2022 Ingeria Embankment of Kaldiya river Habil Ali house to Deben Das A 2020-21 .AFFECTED LENGTH 30 M BREADTH 4M DEPTH DO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - Imalikuchi Embankment on Kaldia River from Bijay Kalita house INREGA 2020-21. LENGTH 100mtr BREADTH 4mtr DEPTH INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - Imalikuchi Embankment on Kaldia River from Bijay Kalita house INREGA 2020-21. LENGTH 100mtr BREADTH 4mtr DEPTH INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - INBDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat -
re Damaged - Embankme	Barpeta Bongaigao	1	Mathaur from Ch NREGA BDO,Ba Embank M BREA (Long - Embank side of F from BE Erosion M BREA (Long - Embank Via Bela 1M.This 0.000000 Embank to Bakar 1.4mtr.T 0.000000 Chenga Brahmar divi. on Srijangr Mulbari Bongaig Mahmo Pachim affected the crest	ri from Chaibari Uttar suba aibari Uttar suba pub Muri AFFECTED LENGTH 20 ajali Dev. Block on 02/07/2 ment of Kaldiya river from ADTH 4M DEPTH 2M.Th 0.000000, Lat - 0.000000), ment of Kaldiya river Da Rehabari H S school to Bar DO,Bajali Dev. Block on 02 of Embankment at kaldiya ADTH 4M DEPTH 2M.Th 0.000000, Lat - 0.000000), ment of Kaldiya river ger ana suba Under MGNREG a report is received from Bl 00), ment on Kaldia River Bar ara LP School under MGN ara LP School under MG	2/07/2022 (Long - 0.000000, Lat - 0.000000), pub Muriya Gohain ghar CHAIBARI amaged Dong Mathauri ya Gohain ghar to Ramakanta Das house at Vill -Chaibari under O M BREADTH 4M DEPTH 2M.This report is received from 2022 (Long - 0.000000, Lat - 0.000000), on the back side Rihabari HS Rihabari AFFECTED LENGTH 20 on is report is received from BDO,Bajali Dev. Block on 02/07/2022 on the back side Rihabari Embankment of Kaldiya river starting from the back of the data of th

		1	WDD
			WRD, crest slump down at CH.4000m at 1No. Dehinghulla Extension of Tengakhat Bund uo to Jokai R.F, Temporary restoration work carried out by WRD. (Long - 95.350000, Lat - 27.350000) Katlicherra - Dyke along L/B of katakhal from Katlicherra to Sahabad Katlicherra Bagan Farryghat
			under Katlicherra Revenue Circle on 23/06/2022 Sloughening, erosion & vertical settlement (Long - 92.556099, Lat - 24.456342),
			Dyke alongR/B ofKatakhal(Mohadevtila-Rupacherra bunglowtila) Down steam of Sluice gate over Ranganala under Katlicherra Revenue Circle on 23/06/2022 Sloughening, erosion & vertical
			settlement (Long - 92.598464, Lat - 24.483253), Algapur - Dyke along L/B of Katakhal from Mohanpur to Confluence Mohanpur Pt-IV Ch. 3500m to 3560m under Algapur Rev. Circle dtd. 27.06.2022 Breach like damage (Long - 92.634065, Lat - 24.749261),
	Hailakandi	8	Dyke along L/B of Katakhal from Mohanpur to Confluence Mohanpur Pt-III Ch. 3670m to 3720m under Algapur Rev. Circle dtd. 27.06.2022 Breach like damage (Long - 92.634267, Lat - 24.751793),
			Dyke along L/B of Katakhal from Mohanpur to Confluence Mohanpur Pt-III Ch. 4480m to 4495m under Algapur Rev. Circle dtd. 27.06.2022 Breach like damage (Long - 92.637694, Lat - 24.744808),
			Dyke along L/B of Katakhal from Mohanpur to Confluence Mohanpur Pt-III Ch. 4600m to 4700m under Algapur Rev. Circle dtd. 27.06.2022 overtopping (Long - 92.643278, Lat - 24.761394), Dyke along L/B of Katakhal from Mohanpur to Confluence Narainpur Pt-II Ch. 7000m to 7125m under Algapur Rev. Circle dtd. 27.06.2022 overtopping (Long - 92.649624, Lat - 24.789390),
			Flood protection & drainage of Bakrihaware area Dholeswar Point, Panchgram Ch. 4480m to 5200m under Algapur Rev. Circle dtd. 27.06.2022 overtopping (Long - 92.605427, Lat - 24.857653)
	Majuli	3	Ujani Majuli - B/Dyke Jaborchuk Kathani Bank erosion at Jaborchuk Kathani on 02-07-2022 (Long - 94.492791, Lat - 27.135847), B/Dyke Maj Gejera Bank erosion at Maj Gejera on 02-07-2022 (Long - 94.455810, Lat - 27.123845), B/Dyke Namoni Gejera Bank erosion at Namoni Gejera on 02-07-2022 (Long - 94.442865, Lat -
			27.118456)
	Nagaon	2	Kampur - South Ghilani Embankment South Ghilani Bank Erosion and sloughening is in progress at South Ghilani area (In between Ch. 7000 to 8000m) on dated 01.07.2022 reported by Water Resources Department. (Long - 0.000000, Lat - 0.000000),
	ivagaon	2	Raha - Abargaon Manipurtup area Manipurtup Date of occurrence from-22/06/2022 Eroded and breach like situatioon at embankment. Department-Morigaon WR Division (Long - 0.000000, Lat - 0.000000)
	Sonitpur	1	Thelamara - R/B Embankment of Meghaijaroni of river Gabharu Meghaijaroni As reported by Tezpur Water Resources Department, Tezpur on 02/07/2022, one third of the crest of the R/B Embankment of river Gabharu at Meghaijaroni has washed away. (Long - 0.000000, Lat - 0.000000)
	Total	25	Emodification of five Gaonard at Meghanjaroni has washed away. [(Long = 0.000000, Eat = 0.000000)
	District	Numbe r	Details
			Bajali - Road from Nalana Belana PWD road to Ramen kakati land at Belana (14th Finance) BELONA AFFECTED LENGTH 100M BREADTH 5M DEPTH 0.3M.This report is received from
			BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000), Road from Natun Belana paver block road to Idgah Maidan at vill Belana(14th Finance) Belona AFFECTED LENGTH 200M BREADTH 5M DEPTH 1M.This report is received from BDO,Bajali
			Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000), Road from Chakla suba namghar to Upen Roy house .(14th Finance) Belona AFFECTED LENGTH 100M BREADTH 5M DEPTH 1M.This report is received from BDO,Bajali Dev. Block on
			02/07/2022 (Long - 0.000000, Lat - 0.000000), Block paver road from Madan Ray house to Diganta Kalita hous at vill Dumuria Dumuria AFFECTED LENGTH 50M BREADTH 4M DEPTH 0.3M.This report is received from BDO,Bajali
Infrastructu re Damaged - Road	Bajali	40	Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000), Village link road at mushlim suba at Dumuria Dumuria AFFECTED LENGTH 100M BREADTH 5M DEPTH 1M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000),
			Road from Nalana Belona PWD(Sariha suba)to pipe line with S/G at vill Dumuria Dumuria AFFECTED LENGTH 100M BREADTH 5M DEPTH 0.5M. This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000),
			village link road from Rafique Ali house to rahim ali house at vill Pathsala gaon Pathsala Gaon AFFECTED LENGTH 30M BREADTH 4M DEPTH 1M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000),
			Road from Sitpur LP School to Naba Das house at village Jalikhata Jalikhata AFFECTED LENGTH 20M BREADTH 5M DEPTH 1.8 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000),
			Road from Kochdiga block paver road to Priyanath Kalita house Kochdiga AFFECTED LENGTH 200M BREADTH 4M DEPTH 0.60M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000),
ĺ			Road from Lt Dhaniram Kalita House to Culvert at Kochdiga Kochdiga AFFECTED LENGTH

20M BREADTH 4M DEPTH 0.60M. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Road from Rupdiga Tihu river bridge to Chandra Kalita house | Rupdiga | AFFECTED LENGTH 300M BREADTH 4M DEPTH 0.45M. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Road from Jaganath Mandir to Irrigational Canal at vill- Barmanikpur | Barmanikpur | AFFECTED LENGTH 40M BREADTH 4M DEPTH 1M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Road from Hiren Das house to Hitesh Das house at Vill- Chaibari under 14th FC | Chaibari | AFFECTED LENGTH 40M BREADTH 4M DEPTH 1M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Roads from Dinesh Kalita house to Irrigation Canal at vill- pub Rihabari | Pub Rihabari | AFFECTED LENGTH 30M BREADTH 4M DEPTH 1M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Roads from Lakhimi Chowk to near Bisheswar Shiva Mandir Via Irrigation office in Vill- Dakhin Rihabari | Dakhin Rehabari | AFFECTED LENGTH 30M BREADTH 4M DEPTH 1M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Roads from Hudukhata PWD rd to Gergeria Charapar Suba in vill- Gergeria Under MGNREGA 2020-21 | Gergeria | AFFECTED LENGTH 30M BREADTH 4M DEPTH 3M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Improvement of road from with sand gravelling Pokha Ketekibari Wooden Bridge to Dhaneswari PWD road and one set H/P under 14th FC , 2019-20 (1st Installment) | pokha ketekibari | AFFECTED LENGTH 40M BREADTH 3.5M DEPTH 0.6M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Improvement of road from with sand gravelling from PWD (mune Kalita) to Chematiya Jan Ward No 2 under 14th FC 2019-20 (1st Installment) | pipla | AFFECTED LENGTH 40M BREADTH 3.5M DEPTH 0.6M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

hokartap Tinili to tangertaol L.P. School | bhotanta mohitara | length 1.00K.m breadth 18ft depth 1ft.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Kurabaha Amartal to bandha Sidhani G.P. area | kurowaha | 0.50km 14ft 5ft. This report is received from BDO, Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Barsuba Dong to kameleswar Basumatary house | bhotanta mohitara | length 1.50km breadth 18ft depth 1 ft.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

N.H. High Way to jamartal road at vill Bhotanta mohitara | Bhotanta Mohitara | length 1.25km breadth 16ft depth 1.5ft.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Bhotanta mahitara tiniali chowk to irrigation cannel | bhotanta mohitara | length 1.5km breadth 16ft depth 2ft. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000).

Phingua garh high school road | bhotanta mohitara | length 2km breadth 18ft depth 1.5ft.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Badankuchi road to Panbari P.W.D | bar saderi | length 1.25km breadth 16ft depth 2ft. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Const of road & culvert from Barsahan to Smachan | barsahan | length 400M breadth 3M depth 0.45. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000).

Imp of road from GP Office Chowk to Khudra Bhaluki PWD road with culvert | khudra bhaluki | length 600M breadth 3M depth0.45. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Const of Road Jayanta Sarma land to Jaganath Mandir vill Dharamtala under 14th FC | dharamtala | length 10 m. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Const of Road from lakhi mandir to Mohan Das house under 14th FC | Raipur | length50mtr breadth 14mtr Depth 25mtr. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Rep of road from Bharat Nath house to Dimbeswar Nath House | Kharadhara | Length 120 Mtr Breadth4M Depth1M.This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Rep of agribandh cum road Nimua Kalita Suba Road with Cultvert | Nimua | Length 150 Mtr Breadth 4M Depth 1M. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000).

Rep of agriband cum road from Garemari Sathisamuka village to Public Smachan | sathisamukha | length 120 Mtr breadth5M depth1M. This report is received from BDO,Bajali Dev. Block on 02/07/2022 | (Long - 0.000000, Lat - 0.000000),

Rep of agribandh cum road from Majarkhat to Garemari Sathisamuka PWD Connected Road | garemari sathisamukha | length 100 Mtr Breadth 4M Depth 1.5M. This report is received from

Г			
			BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000), Upgradation of road from Kanu Sarma Land to West Direction Bargunari Length4.00 M Breadth5.50 M Depth 2.00 M. This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000),
			Upgradation of road from Binay Das house to Manasha Mandir at Vill. dubi Length 5.50 M Breadth 6.00 M 1.50 M. This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long -
			0.000000, Lat - 0.000000), Upgradation of road from Goharkhat LP School to Hume Pipe Culvert at Vill. Dubi length 4.50 M Breadth5.50 M Depth1.80 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022
			(Long - 0.000000, Lat - 0.000000), Upgradation of road from Dubi GP border to Dubi Bhethuwa PWD connection road at vill. Titka Taje Length5.00 M Breadth6.00 M Depth1.50 M.This report is received from BDO,Bajali Dev.
			Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000), Block Paver road from Kaldiya RCC bridge to Na Satra Kirtan ghar under WPTBC at Chaibari
			chaibari affected length26.00 m breadth4.2 m depth2.5 Mtr.This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000), Bamunkuchi Dekapara Path From 29 no railgate to Jalipara road in front of Dhiraj deka House
			Dekapara length 10.00 m breadth3.8 m Depth1.5 m.This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000)
			Barpeta - Basudev devalaya road Barpeta Submerge 200.00 PWRD Barpeta DOO 19.06.2022 (Long - 91.018231, Lat - 26.305875), Dabaliapara Baniapara road Dabaliapara Submerge 250.00 m PWRD Barpeta DOO 19.06.2022
			(Long - 0.000000, Lat - 0.000000), Dangarkuchi Kaljar road Dangarkuchi Submerge 250.00 m PWRD Barpeta DOO 19.06.2022
			(Long - 0.000000, Lat - 0.000000), Howly Joypur Road Howly Submerge 240.00 m PWRD Barpeta DOO 19.06.2022 (Long - 0.000000, Lat - 0.000000),
			Metwakuchi Village road Metwakuchi Submerge 430.00 PWRD Barpeta DOO 19.06.2022 (Long - 0.000000, Lat - 0.000000), Sarbananda das road Barpeta Submerge 250.00 m PWRD Barpeta DOO 19.06.2022 (Long -
			0.000000, Lat - 0.000000), Gandhinagar village road Gandhinagar Submerge 150.00 m PWRD Barpeta DOO 19.06.2022
Ba	nrpeta	71	(Long - 0.000000, Lat - 0.000000), Dakkhni hati Smakhanghat road Dakkhni hati Submerge 150.00 m PWRD Barpeta DOO 19.06.2022 (Long - 91.018433, Lat - 26.316766),
			Kalayahati app.road Kalayahati Submerge 200.00 m PWRD Barpeta DOO 19.06.2022 (Long - 0.000000, Lat - 0.000000),
			Nakhanda E&D embankment Road Barpeta Submerge 170.00 m PWRD Barpeta DOO 19.06.2022 (Long - 91.012376, Lat - 26.299265), Pohumara Temura Road Pahumara Submerge & SPT Br. App. Damage and breach occurred in 2
			stretches 1500.00 m PWRD Barpeta DOO 19.06.2022 (Long - 91.007782, Lat - 26.271483), Patbaushi Nangalkur Road Patbaushi Submerge & SPT Br. App. Damage 2200.00 m PWRD
			Barpeta DOO 19.06.2022 (Long - 91.007247, Lat - 26.276173), Basudev devalaya road Barpeta Submerge 200.00 PWRD Barpeta DOO 21.06.2022 (Long - 0.000000, Lat - 0.000000),
			Ganakkuchi Handloom to Barpeta Polytechnic Road Ganakkuchi Submerge 250.00 m PWRD Barpeta DOO 21.06.2022 (Long - 0.000000, Lat - 0.000000) Gohpur - NH-52 to Rly. Line NH-52 to Rly. Line PMGSY Road NH-52 to Rly. Line PMGSY Road
Bis	swanath	2	Ch 0.00m to Ch. 750.00m. As per Gohpur Territorial Road Division on 29-06-2022. (Long - 0.000000, Lat - 0.000000),
			Halem - Tinikunia to Buroi TE Road Buroi TE Tinikunia to Buroi TE road breached by 100m on 01.07.2022 (Long - 93.483641, Lat - 26.917457) Boitamari - C.C. BLOCK ROAD FROM TILAPARA MOSJID TO AMJAD ALI HOUSE
			TILAPARA MOSJID TO AMJAD ALI HOUSE C.C Block Road Damaged at Tilapara Mosjid Road 150 mtrs. Reported by Zila Parishad Bongaigaon, Dated- 01.07.2022 (Long - 90.471170, Lat - 26.356670),
			ROAD FROM REKIBUDDIN HOUSE TO NITYABAZAR PAHAR REKIBUDDIN HOUSE TO NITYABAZAR PAHAR Road damaged from REKIBUDDIN HOUSE TO NITYABAZAR PAHAR
	ongaigao	6	UNDER MGNREGA 8 Mtrs, Reported by Zila Parishad, Bongaigaon. Dated- 01.07.2022 (Long - 90.454512, Lat - 26.322198), Bongaigaon - Kashidoba Kakoijana to Betbari road Kashidoba kakoijana to betbari road Approach
n			of RCC Br.No 1/1 damaged reported by PWRD Bongaigaon District territorial road Division Bongaigaon dated 02-07-2022 (Long - 90.594147, Lat - 26.425273), Kashidoba Kakoijana to Betbari road Kashidoba Kakoijana to Betbari road Aproach of RCC Br No
			2/1 damaged reported by PWRD Bongaigaon District territorial road Division Bongaigaon dated 02-07-2022 (Long - 26.431694, Lat - 90.588082),
			Dangtol - Bogulamari borchora link road Bogulamari borchora link road Damaged Bogulamari borchora link road 0.026 k.m. Reported by Zila Parishad, Bongaigaon. Dated - 01.07.2022 (Long - 90.416385, Lat - 26.426036),

			CC Block Rd. from Noldoba Chariali to Phukan das House Ph ii Noldoba Chariali to Phukan das
			House Ph ii CC Block Rd. from Noldoba Chariali to Phukan das House Ph ii, 0.01 k.m. Reported
			by Zila Parishad, Bongaigaon. Dated- 01.07.2022 (Long - 90.450287, Lat - 26.392770) Udharbond - Const. of Flood Protection Bund Birju Tilla at Dayapur TE Const. of Flood protection
			bund from Roghu Mura House to Birju Tilla at Dayapur TE Status -On Going % of Damage 100% as
			reported by DRDA Cachar on dated 01.07.2022, (Long - 0.000000, Lat - 0.000000),
			Const. of Flood Protection bund Dayapur -II Const. of Flood protection bund from Jubel laskar
			agriculture land to Jamir Uddin Kazi land at Dayapur -II Status on Going % of Damage 80 % as
			reported by DRDA Cachar on dated 01.07.2022, (Long - 0.000000, Lat - 0.000000),
			Const. of Road cum Bund Durganagar -IV Const. of Road cum bund from VIP Road to Kabarasthan via Boraithali status on going % of Damage 70% as reported by DRDA Cachar on dated
			01.07.2022, (Long - 0.000000, Lat - 0.000000),
			Cost. of Road starting from VIP Road Durganagar Const. Road starting from VIP road to PHE
			Status on going % of Damage % 20 as reported by DRDA Cachar on dated 01.07.2022, (Long -
			0.000000, Lat - 0.000000),
			Const of road starting from VIP road Durganagar Pt-IV Const of Road starting from VIP road solu choudhury house Status on Going % of Damage 40 % as reported by DRDA Cachar on dated
			01.07.2022, (Long - 0.000000, Lat - 0.000000),
			Const. of Road cum Bund Const. of Road cum Bund Const. of road cum Bund from Deshmukhya
			lane status on going % of Damage 60% as reported by DRDA Cachar on dated 01.07.2022, (Long -
			0.000000, Lat - 0.000000),
			Const. of MI bund cum RD Gossiapur -I Const of MI Bund cum Rd. Jalal Uddin house at
			Chailtakandi from MNP Status on Going % of Damage 25 % as reported by DRDA Cachar on dated 01.07.2022, (Long - 0.000000, Lat - 0.000000),
			Const of MI Bund cum Road Durganagar -III Const of MI bund cum road staring from Gias Uddin
			Choudhury house to New Masjid at Durganagar -III Status on Going % of Damage 10 % as reported
			by DRDA Cachar on dated 01.07.2022, (Long - 0.000000, Lat - 0.000000),
			Silchar - Paloi Derbi Borjelenga Road (PDB) Borjelenga Paloi Derbi Borjelenga Road (PDB) at 5th & 8th km, Ch-4700.00 to 5000.00 & ch. 8070 m to 8570 m Length Affected 0.80km, Average depth of
			Submergence 0.75, as per the report received from PWD Dholai Sonai (T) Road Division, as on dated
			30.06.2022 (Long - 0.000000, Lat - 0.000000),
			PMGSY PKG No. AS-03-260, Rd. Sarbantilla PMGSY PKG No. AS-03-260, Rd. from 18t Km of
			PDB Road to Sarbantila, ch. 0.00m to 1300 m & Ch-2500.00m to 2700.00m Length Affected 1.50km,
			Average depth of Submergence 0.70, as per the report received from PWD Dholai Sonai (T) Road Division, as on dated 30.06.2022 (Long - 0.000000, Lat - 0.000000),
			Silcoorie PMGSY road Irongmara Silcoorie PMGSY road to Irongmara Bapuji LP School of
	Cachar	42	Irongmara Grant Village under APART(Pkg No. APART/NOCP/ROADS/C-06), ch. 100m t0 900m,
			Length Affected 0.80 km, Average depth of Submergence 0.80, as per the report received from PWD
			Dholai Sonai (T) Road Division, as on dated 30.06.2022 (Long - 0.000000, Lat - 0.000000),
			Bag Bahar G.P. Office to New Bagbahar Arali Bag Bahar Bag Bahar G.P. Office to New Bagbahar Arali, Ch. 20m to 250m & 1400 m 1700m Length Affected 0.50 km, Average depth of Submergence
			0.20, as per the report received from PWD Dholai Sonai (T) Road Division, as on dated 30.06.2022
			(Long - 0.000000, Lat - 0.000000),
			PDB Road to NH-54 Paloi Point PDB Road to NH-54 at Paloi Point, Ch.0m to 800m Length
			Affected 0.80 km, Average depth of Submergence 0.50, as per the report received from PWD Dholai
			Sonai (T) Road Division, as on dated 30.06.2022 (Long - 0.000000, Lat - 0.000000), Road from Paloi T.E to Borjalenga TV Paloi TE Road from Paloi T.E to Borjalenga TV , PMGSY
			Package No AS-03-191 Length Affected 0.50 km, Average depth of Submergence 0.45, as per the
			report received from PWD Dholai Sonai (T) Road Division, as on dated 30.06.2022 (Long -
			0.000000, Lat - 0.000000),
			Saidpur Roypara Road Saidpur Roypara Road Saidpur Roypara Road, ch.0m to 1000m Length Affected 1.00 km, Average depth of Submergence 0.50, as per the report received from PWD Dholai
			Sonai (T) Road Division, as on dated 30.06.2022 (Long - 0.000000, Lat - 0.000000),
			SH39 to Tarurajbari Tarurajbari SH39 to Tarurajbari AS-03-181, ch.0m to 1200m Length Affected
			1.20 km, Average depth of Submergence 0.80, as per the report received from PWD Dholai Sonai (T)
			Road Division, as on dated 30.06.2022 (Long - 0.000000, Lat - 0.000000), Silcoorie Grant -I to Tarutajbari, Silcoorie Grant -I to Tarutajbari, AS-03-154,
			Ch700m 1150m & 2600m 4000m Length Affected 1.85 km, Average depth of Submergence 0.85, as
			per the report received from PWD Dholai Sonai (T) Road Division, as on dated 30.06.2022 (Long -
			0.000000, Lat - 0.000000),
			Silcoorie Sildubi Road, Ch. 750m to 1500m Silcoorie Sildubi Road Silcoorie Sildubi Road, Ch.
			750m to 1500m 4000m Length Affected 0.75 km, Average depth of Submergence 0.80, as per the report received from PWD Dholai Sonai (T) Road Division, as on dated 30.06.2022 (Long -
			0.000000, Lat - 0.000000),
			NH-54 at Sonabarighat to Sayedpur Sonabarighat NH-54 at Sonabarighat to Sayedpur Ch 1500m to
			3200m Length Affected 1.70 km, Average depth of Submergence 0.60, as per the report received from
			PWD Dholai Sonai (T) Road Division, as on dated 30.06.2022 (Long - 0.000000, Lat - 0.000000),
			Sonai - Silchar Hailakandi Road Silchar Hailakandi Road to Sarbantilla CH 0 M to 1000 M Report Received from EE PWD Dholai & Sonai (T) Road Division Under Sonai Revenue Circle on
L	L	1	

24.06.2022 | (Long - 0.000000, Lat - 0.000000), 21 KM of Silchar Hailakandi Road | Roskandy Gate Bazar to Ratanpur 0 M to 1000 M | Report Received from EE PWD Dholai & Sonai (T) Road Division Under Sonai Revenue Circle on 24.06.2022 | (Long - 0.000000, Lat - 0.000000), Silchar Hailakandi Road | CH. 27500.00M to CH. 31000.00M | Report Received from EE PWD Dholai & Sonai (T) Road Division Under Sonai Revenue Circle on 24.06.2022 | (Long - 0.000000, Lat -0.000000), Lakhipur - NH 37 to Machpara Badribasti Road | Badribasti | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat -0.000000), NH 37 to Uttar Lalpani road | Uttar Lalpani | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), Road from Nagabazar at Kaptanpur-I to Rupailbali | Kaptanpur-I | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat -0.0000000). Chotomamda at LRA to Sonai RCC bridge | Chotomamda at LRA | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat -0.000000), Putikhal to Tilka Bridge | Putikhal | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), Binnakandi Grant to Didarkush grant | Motinagar via Boali grant (Binakandi grant Moti Nagar grant) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), Motinagar Binnakandi Road | (Binnakandi to Motinagar via Boali) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat -0.000000), Kaptanpur XIII to LRA | Binnakandi (Rokarpar Gaon to Binnakandi) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat -0.000000), Silchar Pailapool Road to Udharbond Banskandi Road | (Labac Garden to Shibtilla) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long -0.000000, Lat - 0.000000), NH 53 to Digor Fulertal | (Hemarkulin to Digor Fulerta) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), Banskandi Puran Bazar Road | (Banskandi to Cheri Bazar) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), NH 53 Sribar Lakhipur Road | (Nandanchand Road) (Sibpur to Lakhipur Bazar) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long -0.000000, Lat - 0.000000), Lakhipur Banskandi Road | (Lakhipur to Chandrapur IV) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), T03 to Howkip Punjee | (Howkip Punjee to U.S Uttar Lalpani IV) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat -0.000000). Labac Salamatpur Road Part 2 | (Labac Premtola to Salamatpur) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat -T05 to Barthol TE | (Dewan T.E to Thaliu Colony) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), NH 53 to U S Lobonkhal | (Labankhal to Labankhal) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), NH 53 at Ujan Tarapur to Manipur II | (Ujantarapur to Manipur 2) | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat -0.000000), Tilka grant to L.R.A road at(Putikhal to Tilka Grant) | Kaptanpur V to 632 No Putikhal L.P School | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000), At the Vivekananda Statue of the junction point of LRA Road | LRA Road | Report Received from EE PWD (T) Road Division Lakhipur under Lakhipur Revenue Circle on 30.06.2022 | (Long - 0.000000, Lat - 0.000000) Dalgaon - kuwaripukhuri panbari via dunibasti road | kuwaripukhuri panbari via dunibasti road at CH-65M to 106M | kuwaripukhuri panbari via dunibasti road side berm eroded date of occurrence -16/06/2022 | (Long - 0.000000, Lat - 0.000000), Mangaldoi - Landing Slope Near Entrance of Bipin Medhi Road, ward no 6 under MMB | ward no. 6 | 71 Darrang as reported by Mangaldai Municipal Board, the Landing Slope Near Entrance of Bipin Medhi Road is damaged/submerged during flood 2nd wave and the affected length is 2.50 mtr. Date 16-6-2022 (Long - 92.010000, Lat - 26.260000), Culvert near Mangaldai Commerce College Entrance, ward no 6 under MMB | ward no. 6 | as reported by Mangaldai Municipal Board, Culvert near Mangaldai Commerce College Entrance, is

damaged/submerged during flood 2nd wave and the affected length is 3.00~mtr. Date 16-6-2022 | (Long - 92.010000, Lat - 26.260000),

Embankment of Bega river at ward no 7 under MMB | ward no. 7 | as reported by Mangaldai Municipal Board, Embankment of Bega river is damaged/submerged during flood 2nd wave and the affected length is 15.00 mtr . Date 16-6-2022 | (Long - 92.010000, Lat - 26.270000),

Culvert blockedge due to accumulation of mud, ward no 10 under MMB | ward no. 10 | as reported by Mangaldai Municipal Board, Culvert blockedge due to accumulation of mud is damaged/submerged during flood 2nd wave and the affected length is 4.50 mtr . Date 16-6-2022 | (Long - 92.010000, Lat - 26.250000),

Road and Drain collapse at ward no 2, M. Ibrahim Ali Road MMB | ward no. 2 | as reported by Mangaldai Municipal Board, Road and Drain collapse at ward no 2, M. Ibrahim Ali Road is damaged/submerged during flood 2nd wave and the affected length is $10.00 \, \text{mtr}$. Date 17-6- $2022 \, \text{l}$ (Long - 92.020000, Lat - 26.260000),

Drain Damaged near NH 15 Road, Ward No 1, Mangaldai MMB | Ward No 1 | as reported by Mangaldai Municipal Board, Road and Drain Damaged near NH 15 Road is damaged/submerged during flood 2nd wave and the affected length is $2.50 \, \text{mtr}$. Date $17-6-2022 \mid (Long - 92.010000, Lat - 26.260000)$,

Culvert drainage at entrance part of near sakti sangha at ward no $5\,\text{MMB}$ | ward no $5\,\text{l}$ as reported by Mangaldai Municipal Board, Culvert drainage at entrance part of near sakti sangha is damaged/submerged during flood 2nd wave and the affected length is $3.50\,\text{mtr}$. Date $17\text{-}6\text{-}2022\,\text{l}$ (Long - 92.010000, Lat - 26.260000),

Surrounding of Road Crossing Culvert near Meet House, ward no 9, Mangaldai MMB | ward no 9 | as reported by Mangaldai Municipal Board, Surrounding of Road Crossing Culvert near Meet House is damaged/submerged during flood 2nd wave and the affected length is $5.50 \, \text{mtr}$. Date 17-6-2022 | (Long - 92.010000, Lat - 26.260000),

Soil errosion near the East side of Sankar nagar road, ward no 9 MMB | ward no 9 | as reported by Mangaldai Municipal Board, Soil errosion near the East side of Sankar nagar road is damaged/submerged during flood 2nd wave and the affected length is 10.00 mtr . Date 20-6-2022 | (Long - 92.010000, Lat - 26.260000),

Culvert Damaged at infront of Lt Nareswar Medhi house, ward no 10, Mangaldai MMB | ward no 10, | as reported by Mangaldai Municipal Board, Culvert Damaged at infront of Lt Nareswar Medhi house is damaged/submerged during flood 2nd wave and the affected length is 5.60 mtr. Date 20-6-2022 | (Long - 92.010000, Lat - 26.250000),

Road is damaged due to flood at Foroz naga, ward no 7, Mangaldai MMB | ward no 7 | as reported by Mangaldai Municipal Board, Road is damaged due to flood at Foroz naga, is damaged/submerged during flood 2nd wave and the affected length is 20.00 mtr. Date $20-6-2022 \mid (\text{Long} - 92.010000, \text{Lat} - 26.270000)$,

Road is damaged at the backside of Sainik Bhawan, Ward no 1, Mangaldai MMB | Ward no 1, | as reported by Mangaldai Municipal Board, Road is Road is damaged at the backside of Sainik Bhawan is damaged/submerged during flood 2nd wave and the affected length is 15.00 mtr. Date 20-6-2022 | (Long - 92.010000, Lat - 26.260000),

Road at the Entrance part of Dr. Kamakhya pd. Mishra's house is damaged at ward no 5, Mangaldai MMB | ward no 5, | as reported by Mangaldai Municipal Board, Road is at the Entrance part of Dr. Kamakhya pd. Mishra's house is damaged/submerged during flood 2nd wave and the affected length is 13.00 mtr. Date 20-6-2022 | (Long - 92.010000, Lat - 26.260000),

Road is completely damaged towards Dr. Kamakhya pd. Mishra's house, Ward no 5, Mangaldai MMB | Ward no 5, | as reported by Mangaldai Municipal Board, Road is completely damaged towards Dr. Kamakhya pd. Mishra's house is damaged/submerged during flood 2nd wave and the affected length is 20.00 mtr. Date 20-6-2022 | (Long - 92.020000, Lat - 26.260000),

Drain near Mangaldai Stadium at ward no 2, Mangaldai is partly damaged MMB | ward no 2, | as reported by Mangaldai Municipal Board, Road is Drain near Mangaldai Stadium at ward no 2, Mangaldai is partly is damaged/submerged during flood 2nd wave and the affected length is 25.00 mtr . Date 20-6-2022 | (Long - 92.020000, Lat - 26.260000),

Road and boundary wall near Mangaldai Stadium Bylane no 2, at ward no 2, Mangaldai is partly damaged MMB | ward no 2 | as reported by Mangaldai Municipal Board, Road Road and boundary wall near Mangaldai Stadium Bylane no 2, Mangaldai is partly is damaged/submerged during flood 2nd wave and the affected length is 18.00 mtr . Date 20-6-2022 | (Long - 92.020000, Lat - 26.260000), **Patharighat** - MPK Namkhola to Bhergaon KK connecting Road | Athiabari | Msg recieved from EE PWD Roads Kalaigaon :on 02/07/2022 at 3.45 p.m Scheme : MPK Namkhola to Bhergaon KK connecting Road via Athiabari Breach at Ch 700 mt for a length of G= 15.00 m due to complete damage of HP culvert. | (Long - 26.556490, Lat - 91.838733),

Sipajhar - PROFORMA 'B' Details of damages to roads, bridges and culverts under PWRD, Sipajhar & Kalaigaon Territorial Road Division, Sl. No. Name of District Name of Division Name of Circle Name of Roads (Specify RR/MDR/SR) Length Affected (Km) Average depth of Submergence (in M) No. Of SPT/RCC No of Culvert Damaged No of Culvert App. damaged No of SPT/RCC Br./Cul washed away Length/ Span of Bridge (M) Breaches Cost for Temporary restoration to open Traffic (Rs. In Lac) Cost for Permanent restoration (Rs. In Lac) Total restoration cost(Rs.in Lac) Restoration of work already started by Traffic disruptted Form- to Bridge damaged App. Damaged No. Length (M) Remarks 1 2 3 4 5 6 8 9 10 11 12 13 14 15 16 17 18 1 Darrang Sipajhar Tinisuti Malibari Road 0.600

0.50 to 1.00 (from 15/05/2022 to 27/06/2022 1 2 0.40 0.40 2 Darrang Sipajhar Bachachuba to N H 52 (Bhuktabari Sonapur)Road 5.000 0.60 to 1.5 (from 15/05/2022 to 27/06/2022 2 3 60.00 6.00 6.00 3 Darrang Sipajhar Haldha Maijeli Road 0.400 0.800 (from 15/05/2022 to 27/06/2022 1 0.40 0.40 4 Darrang Sipajhar Patharighat Assom Mala Group -I 6.000 1.20 (from 15/05/2022 to 27/06/2022 2 20 8.00 8.00 yes 5 Darrang Sipajhar Majorchuba Byaspara Road 1.500 0.9 (from 15/05/2022 to 27/06/2022 1 20 0.50 2.00 2.50 yes shoulder damaged 6 Darrang Sipajhar Dhanai Bora Path 1.000 0.45 (from 15/05/2022 to 27/06/2022 6.00 6.00 7 Darrang Sipajhar Biratchuba to NH-52 1.000 0.75 (from15/05/2022 to 27/06/2022 1 6 0.35 2.00 2.35 yes 8 Darrang Sipajhar Bhuktabari Sonapur Road 5.000 2.00 (from 15/05/2022 to 27/06/2022 3 2 3 70 3.00 250.00 253.00 yes 9 Darrang Sipajhar Patharighat Andherighat Jayantipur Road 4.000 0.60 (from 15/05/2022 to 27/06/2022 1 10 Darrang Sipajhar Bordaulguri Borachuba Road PMGSY Package No AS-16-195 1.000 0.90 (from15/05/2022 to 27/06/2022 1 yes 11 Darrang Sipajhar Sigimari Dampur Road PMGSY Pkg No-184 1.000 0.90 (from15/05/2022 to 27/06/2022 2 still under water 12 Darrang Sipajhar Ganeshqurry Kalitapara Road (from15/05/2022 to 27/06/2022 3 20 still under water 13 Darrang Sipajhar Lenga Kurua Road 2.000 5.00 (from 15/05/2022 to 27/06/2022 4 25 5.00 still under water 14 Darrang Sipajhar Bhatikurua Upper Kurua Rd 1.000 1 1 1 2 Yes 15 Darrang Sipajhar Garukhuti to Kalitapara Road PMGSY Pkg No AS16-192 3.000 1.00 (from15/05/2022 to 27/06/2022 2 20 still under water 16 Darrang Sipajhar NH- $15 \ to \ Borachuba \ Part \ 2 \ PMGSY \ Pkg \ No-182 \ 4.000 \ 1.00 \ (from 15/05/2022 \ to \ 27/06/2022 \ 1 \ 3 \ 20 \ still \ 20 \ from 15/05/2022 \ to \ 20 \ from 1$ under water 17 Darrang Sipajhar Dumunichowki Kurua Road 2.000 0.60 (from15/05/2022 to 27/06/2022 1 18 Darrang Sipajhar/Patharighat Dumunichowki Khtara Road 5.000 0.80 (from 15/05/2022 to 27/06/2022 1 1 20 4.00 40.00 44.00 yes 19 Darrang Sipajhar Nagapra to Bordaulguri Borachuba Rd 3.000 0.8 (from 15/05/2022 to 27/06/2022 1 10 20 Darrang Sipajhar Botabari to NH-52 (PMGSY PkgAS16-87) 1.000 1.00 (from 15/05/2022 to 27/06/2022 1 30 0.60 3.00 3.60 yes 21 Darrang Sipajhar Ghorabandha Garukhuti Road 3.000 1.000 (from 15/05/2022 to 27/06/2022 22 Darrang Sipajhar NH-15 to Barkalijhar South PMGSY Pkg No-182 2.000 0.6 (from15/05/2022 to 27/06/2022 1 23 Darrang Sipajhar Manoighat Maroi Road 2.000 0.7 (from 15/05/2022 to 27/06/2022 1 30 0.900 24 Darrang Sipajhar Narikali Punia Road 1.000 0.7 (from15/05/2022 to 27/06/2022 25 Darrang Sipajhar/Pataarighat Chakarmukh Bishnupur Rd 2.000 1 (from 15/05/2022 to 27/06/2022 1 10 still under water 26 Darrang Sipajhar Narikali Road from Bhuktabari Road to Janasewa Kathamar Road 1.000 1 (from 15/05/2022 to 27/06/2022 27 Darrang Sipajhar Bihubhanga Futukitoli Road 1.000 0.7 (from 15/05/2022 to 27/06/2022 28 Darrang Sipajhar Janasewa Kathamar Road 3.000 0.7 (from 15/05/2022 to 27/06/2022 1 ? 0.800 yes 29 Darrang Sipajhar Uttar Kabeichuba Road 1.000 0.600 (from 15/05/2022 to 27/06/2022 30 Darrang Sipajhar Bordoulguri to Borochuba Road (RL) 3.000 1.000 (from 15/05/2022 to 27/06/2022 1 30.00 31 Darrang Sipajhar 050-Choto Athiabari to Bordoulguri Borachuba (AS-16-148) 3.000 2.000 (from 15/05/2022 to 27/06/2022 2 1 100.00 still under water 32 Darrang Sipajhar Bagachala to Andherighat jayantipur Road (AS-16-135) 4.000 1.500 (from15/05/2022 to 27/06/2022 1 1 1 2 150.00 33 Darrang Sipajhar NH 15 to SP Road (AS-16-185) 4.000 1.000 (from15/05/2022 to 27/06/2022 1 34 Darrang Sipajhar Solardal to Ghorabandha Garukhuti Road (AS-16-77) (from15/05/2022 to 27/06/2022 still under water 35 Darrang Sipajhar Anandipara to Sipajhar patharighat Road (AS-16-87) 1.000 0.450 (from 15/05/2022 to 27/06/2022 1 36 Darrang Sipajhar Kanarchuba to Bordoulguri Borachuba Road (AS 16 111) (from15/05/2022 to 27/06/2022 still under water 37 Darrang Sipajhar Baniapara to Ghorabandha Garukhuti Road (AS-16-129) 2.000 0.700 (from 15/05/2022 to 27/06/2022 38 Darrang Sipajhar Tilachuba to GG Road (AS-16-128) 2.000 0.900 (from 15/05/2022 to 27/06/2022 39 Darrang Patharighat Baghmari to Dipila Borigaon Road (AS-16-131) 3.000 1.000 (from 15/05/2022 to 27/06/2022 3 50.00 ? 4.000 ? 16.000 ? 20.00 YES 40 Darrang Sipajhar/Patharighat Naopota to Dumunichowki Khatara Road (AS-16-141) 2.000 1.000 (from 15/05/2022 to 27/06/2022 41 Darrang Sipajhar Solpam to Dumunichowki Khatara Road (AS-16-142) 2.000 1.000 (from15/05/2022 to 27/06/2022 1 1 4 60.00 ? 3.000 ? 75.000 42 Darrang Sipajhar Kuwarijan to DK Road (AS-16-140) $(from 15/05/2022\ to\ 27/06/2022\ STILL\ UNDER\ WATER\ 43\ Darrang\ Sipajhar\ Kalitapara\ to\ DK\ Road$ (AS-16-127) 2.000 1.000 (from 15/05/2022 to 27/06/2022 44 Darrang Sipajhar NH-15 to Borachuba part 2 (PMGSY II) (AS-16-141) 4.000 1.000 (from 15/05/2022 to 27/06/2022 2 3 90.00 STILL UNDER WATER 45 Darrang Sipajhar NH-15 to Barkaliajhar south (PMGSY II) (AS-16-182) 2.000 1.000 (from 15/05/2022 to 27/06/2022 1 46 Darrang Sipajhar Solpam to Bhuktabari Sonapur Road(Soalpa fishery) road 2.000 1.800 (from 15/05/2022 to 27/06/2022 1 1 10.00 ? 1.200 ? 8.000 ? 9.20 47 Darrang Sipajhar Maroi Pakadali Bengnoi 2.000 1.000 (from 15/05/2022 to 27/06/2022 2? 0.500? 8.000 ? 8.50 48 Darrang Sipajhar Patgirichuba LP School to Bochachuba 2.000 1.000 (from 15/05/2022 to 27/06/2022 3 20 49 Darrang Sipajhar Bochachuba Solpam Road 2.000 1.000 (from 15/05/2022 to 27/06/2022 1 ? 1.000 ? 25.000 ? 26.00 50 Darrang Sipajhar Solpam Bodiasisa 2.000 1.200 (from15/05/2022 to 27/06/2022 2 12 ? 3.000 ? 25.000 ? 28.00 yes 51 Darrang Sipajhar BB OL to Saktola Embankment 2.000 0.900 (from 15/05/2022 to 27/06/2022 1 10.00 52 Darrang Sipajhar Bhati Kurua to Upper Kurua 1.000 0.700 (from 15/05/2022 to 27/06/2023 1 2 1 20.00 ? 1.500 53 Darrang Patharighat/Sipajhar Bordoulguri Deomornoi Road 0.300 0.900 (from 15/05/2022 to 27/06/2022 110.800 7 20 12 52 915 | Sipajhar | As reported by PWRD | (Long - 0.000000, Lat -

Dhubri

Bilasipara - Improvement of existing Kutcha road with Interlocking Cement concrete Block at Ward No. 1, from Abdul Goni house towards back side of Beparipara. Under 15th Finance Commission for the year 2020-21 (1st. instt. 25% of UBG) Ch. 0.00m to 134m | from Abdul Goni house towards back side of Beparipara | AFFECTED BY THE FLOOD WATER W.E.F. 14/06/2022 TO 18/06/2022 |

(Long - 90.225564, Lat - 26.223004), Construction of Block Road at Ward No 2 start from Monoranjan Barman's house to Purno Chakroborty's house under 14th Finance Commission for the year 2017-18 (2nd instt. of GBG) during 2019-20. | Monoranjan Barman's house to Purno Chakroborty's house | AFFECTED BY THE FLOOD WATER W.E.F. 14/06/2022 TO 18/06/2022 | (Long - 90.224027, Lat - 26.235271), Improvement of existing Kutcha Road with interlocking Cement concrete Block at Ward No. 3, from Anil Mandal house towards Tipin Biswas house under 15th Finance Commission for the year 2020-21 (1st instt. of UBG). | Anil Mandal house towards Tipin Biswas house | AFFECTED BY THE FLOOD WATER W.E.F. 14/06/2022 TO 18/06/2022 | (Long - 90.227672, Lat - 26.226158), Construction of Road from Bilasipara Old NH way near Ashok Bastralaya to Manik Sutradhar at ward no. 7 under SOPD-ODS under Bilasipara Municipal Board for the year 2019-20, Chainage: 0.00m to 000.00m | near Ashok Bastralaya to Manik Sutradhar at ward no. 7 | AFFECTED BY THE FLOOD WATER W.E.F. 14/06/2022 TO 18/06/2022 | (Long - 90.235753, Lat - 26.231930), Improvement of existing Kutcha road with Interlocking Cement concrete Block & one side drain at Ward No. 14, from College Road beside Town Girls' High School towards Manik Poddar house. Ch. 0.00m to 109m | at Ward No. 14, from College Road beside Town Girls' High School towards Manik Poddar house. | AFFECTED BY THE FLOOD WATER W.E.F. 14/06/2022 TO 18/06/2022 | (Long -90.231648, Lat - 26.223078), Construction of Road at Ward No.14 start from Hon'ble MLA, 27-BLp. East LAC's house towards Bilasipara Maha Smasan Main Road under SOPD-ODS under Bilasipara Municipal Board for the year 2019-20 | at Ward No.14 start from Hon'ble MLA, 27-BLp. East LAC's house towards Bilasipara Maha Smasan Main Road | AFFECTED BY THE FLOOD WATER W.E.F. 14/06/2022 TO 18/06/2022 | (Long - 90.229596, Lat - 26.225296), Construction of Road at Ward No.11 Start from Haren Paul House towards E & D Bund near House of Bhajan Hawldar under SOPD-ODS for the year 2019-20 & 2020-21 | at Ward No.11 Start from Haren Paul House towards E & D Bund near House of Bhajan Hawldar | AFFECTED BY THE FLOOD WATER W.E.F. 14/06/2022 TO 18/06/2022 | (Long - 90.244844, Lat - 26.231915), Construction of CC Block Road at w/no.8, start from PWD Road at Rokakhata HS School to Mizanur Rahman house for the year 2019-20 | at w/no.8, start from PWD Road at Rokakhata HS School to Mizanur Rahman house | AFFECTED BY THE FLOOD WATER W.E.F. 14/06/2022 TO 18/06/2022 | (Long - 90.238979, Lat - 26.238200) Naharkatia - Hapmari to Tiniali TE road. | As on 1-07-2022 report received from Gaon Pradhan and Dibrugarh 1 JE,PWD a Hume pipe culvert is damaged due to flood at Hapmari to Tiniali TE road. Now it is temporarily Barricated by bamboo for safety of the people. | | (Long - 95.103200, Lat - 27.172700) Lanka - Kharikhana to Dakhin Laskar Pather | Kharikhana to Dakhin Laskar Pather | Culvert approach , Base course, Surface course and shoulder damaged on Dated 15 June 22 to 20 June 2022 | (Long -92.567000. Lat - 26.056000). Doboka - Doboka Jamunamukh Road | Doboka Jamunamukh Road | Culvert approach, Base course, Surface course and shoulder damaged on Dated 16 June 2022 | (Long - 92.824350, Lat - 26.081288), Doboka Jamunamukh Road to Patidayagaon | Doboka Jamunamukh Road to Patidayagaon | Culvert approach, Base course, Surface course and shoulder damaged On dated 16/06/22 | (Long-92.176330, Lat - 26.110862), Sarupather Jamunamukh Road | Sarupather Jamunamukh Road | Base course, Surface course and shoulder damaged On dated 16/06/22 | (Long - 92.751972, Lat - 26.128514), Sarlok to Niharimukh Road | Sarlok to Niharimukh Road | Road embankment including road surface is damaged. On dated 16/06/22 | (Long - 92.812575, Lat - 26.089725), Pata Pather to Kathkatia Bhakat Gaon. | Pata Pather to Kathkatia Bhakat Gaon. | Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.715505, Lat - 25.128163), Borjari Majgaon to Baliramgaon | Borjari Majgaon to Baliramgaon | Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.745000, Lat - 26.108366), Sarlok to Binakandi via Jugijan | Sarlok to Binakandi via Jugijan | Base course, Surface course and shoulder damaged on Dated 16/06/22 | (Long - 92.817936, Lat - 26.091367), Hojai 33 Kampur Jamunamukh Road | Kampur Jamunamukh Road | Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.741088, Lat - 26.105838), Nagaya Pam to Sarupathar | Nagaya Pam to Sarupathar | Culvert approach , Base course , Surface course and shoulder damaged On dated 16/06/22 | (Long - 92.740540, Lat - 26.124650), Nilbagan Murajhar Howraghat | Nilbagan Murajhar Howraghat | Bridge approach, base course, surface course damaged On dated 16/06/22 | (Long - 92.900924, Lat - 26.065933), Hojai - Amtola To Dighalbali road | Amtola To Dighalbali road | Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.816000, Lat - 25.972000), Solmarijan To Ashinagar Road | Solmarijan To Ashinagar Road | Road embankment including road surface is damaged. on dated 16/06/22 | (Long - 92.800870, Lat - 25.975000), Uttar Bidyanagar To Rajbari Road | Uttar Bidyanagar To Rajbari Road | Base course, Surface course and shoulder damaged on 16/06/22 | (Long - 92.816000, Lat - 26.019000), Rajbari To Kenduguri Road | Rajbari To Kenduguri Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.785900, Lat - 26.028400), Kenduguri To Hayang Gaon Road | Kenduguri To Hayang Gaon Road | Base course , Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.785600, Lat - 26.027300), Radhanagar To Kumurakata Road | Radhanagar To Kumurakata Road | Culvert approach, Base course

, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.480900, Lat - 26.000000), Hojai Tumpreng Road To Dighalbali Road | Hojai Tumpreng Road To Dighalbali Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.802500, Lat - 25.992400), Borhola To Nahargaon Road | Borhola To Nahargaon Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.778000, Lat - 26.058000), Hojai Tumpreng Road To Kumurakata No 1 Road | Hojai Tumpreng Road To Kumurakata No 1 Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/2022 | (Long-92.801000, Lat - 25.998000), Rajbari To Sankha Devi Road | Rajbari To Sankha Devi Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/2022 | (Long - 92.785600, Lat - 26.027300), Lanka Dhalapukhuri Road To Nandapur Tongia Forset Village Road | Lanka Dhalapukhuri Road To Nandapur Tongia Forset Village Road | Culvert approach , Base course , Surface course and shoulder damaged on dated16/06/2022 | (Long - 92.836603, Lat - 25.945852), Hojai Tumpreng Road to Dakhin Kumurakata Forest village Road | Hojai Tumpreng Road to Dakhin Kumurakata Forest village Road | Culvert approach , Base course , Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.047330, Lat - 26.000330), Mathura Bazar To Kenduguri Road | Mathura Bazar To Kenduguri Road | Culvert approach , Base course , Surface course and shoulder damaged on dated $16/06/2022 \mid$ (Long - 92.301000, Lat -25.130000), Pub Bagori To Pachim Bagori Road | Pub Bagori To Pachim Bagori Road | Bridge approach, base course, surface course damaged on dated 16.06.22 | (Long - 92.821243, Lat - 26.062889), Hojai Mubarak Basti to Pachim Nilbagan Rd | Hojai Mubarak Basti to Pachim Nilbagan Rd | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.014000, Lat - 26.120000), Singimari to Bishnupur Road | Singimari to Bishnupur Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.800900, Lat - 25.975000), Jugijan Bazar to Barafuti Barjapur Road | Jugijan Bazar to Barafuti Barjapur Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.813600, Lat -26.022000), Hojai Tumpreng Road Ch. at 7th Km | Hojai Tumpreng Road Ch. at 7th Km | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/06/22 | (Long - 92.785900, Lat -26.028000), Rajabari to Nabhanga Road | Rajabari to Nabhanga Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/6/22 | (Long - 92.787340, Lat - 26.006070), Bishnupur to Dighalbali Road | Bishnupur to Dighalbali Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/6/22 | (Long - 92.803770, Lat - 25.976000), Hojai Tumpreng Road To Dakhin Kumurakata No 2 Road | Hojai Tumpreng Road To Dakhin Kumurakata No 2 Road | Culvert approach, Base course, Surface course and shoulder damaged on dated 16/6/22 | (Long - 92.805000, Lat - 25.998000), Hojai Tumpreng Road to kenduguri | Hojai Tumpreng Road to kenduguri | Base course, surface cource and shoulder damage on 16/6/22 | (Long - 92.787000, Lat - 26.005900) Chamaria - Howlitary Chamaria Satra | Howlitary | Howlitary Chamaria Satra bridge approach, Embankment and surface damaged on dated 2.07.2022 and the same has been reported by JE, Pwd. Boko territorial road sub-division on dated 2.07.2022 | (Long - 0.000000, Lat - 0.000000), Chamaria Satra Kahibari | Chamaria | Chamaria Satra Kahibari bridge approach, embankment and surface damaged on dated 2.07.2022 and the same has been reported by JE, PWD, Boko territorial road sub-division on dated 2.07.2022 | (Long - 0.000000, Lat - 0.000000), Neuldoba Pathalipara | Neuldoba | Neuldoba Pathalipara side berm, side slope and surface damaged on dated 2.07.2022 and the same has been reported by JE, PWD Boko territorial road sub-division on dated 2.07.2022 | (Long - 0.000000, Lat - 0.000000), Sontoli to Badlapathar | Sontoli | Sontoli to Badlapathar bridge approach, side berm and surface damaged on dated 2.07.2022 and the same has been reported by JE, PWD Boko territorial road subdivision on dated 2.07.2022 | (Long - 0.000000, Lat - 0.000000), Sontoli to Bardia Nowapara | Sontoli | Sontoli to Bardia Nowapara bridge approach, side berm and Kamrup 30 surface damaged on dated 2.07.2022 and the same has been reported by JE, PWD Boko territorial road sub-division on dated 2.07.2022 | (Long - 0.000000, Lat - 0.000000), Sontoli Lutirtari | Sontoli | Sontoli Lutirtari bridge approach, side berm and surface damaged on dated 2.07.2022 and the same has been reported by JE, PWD Boko territorial road sub-division on dated 2.07.2022 | (Long - 0.000000, Lat - 0.000000), Mahtoli Rangapani | Mahtoli | Mahtoli Rangapani Beach caused at 3rd km, side berm and surface damaged on dated 2.07.2022 and the same has been reported by JE, PWD Boko territorial road subdivision on dated 2.07.2022 | (Long - 0.000000, Lat - 0.000000), North Ghy - NG Mandakata to Kumnagar | NG Mandakata to Kumnagar | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), NH 15 to Mandakata Road | NH 15 to Mandakata | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Bamunsupa Barpalaha to Thakurpara to Madan Kamdev VIA Thakurpara & Islampur | Bamunsupa

Barpalaha to Thakurpara | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Madan Kamdev Bhirtorkhola Road | Madan Kamdev Bhirtorkhola | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -0.0000000). Madankamdev to Iskampur Road | Madankamdev to Iskampur | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -0.000000), Borpolaha Marosali Road | Borpolaha | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Dakhin Agdola to Jonaru Road | Dakhin Agdola to Jonaru | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -0.0000000). Agdola DEka Supa Road | Agdola DEka Supa | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Baihata Medical Road | Baihata Medical | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), NH 31 to Borbilla Pahar Road RR | NH 31 to Borbilla Pahar | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -0.0000000). Gog LP School to Janarpar Road RR | Gog LP School to Janarpar | Affected on 19/6/2022 as reported by Asstt. EE, PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -Bagulababa Majar Road at Khairapara RR | Bagulababa Majar Road at Khairapara | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Gog LP School to idgaha Maidan Road RR | Gog LP School to idgaha Maidan | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), NH 15 to Ballampar Road at Gog Rr | NH 15 to Ballampar | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -0.000000), Changsari Rangmahal Road RR | Changsari Rangmahal | Affected on 19/6/2022 as reported by Asstt. EE, PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Changsari Boloibill Road Leg2 (Erosion) RR | Changsari Boloibill | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), Satgaon Howrapar Road RR (Erosion) | Satgaon Howrapar | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -Satgaon Anil House Road RR (Erosion) | Satgaon Anil House Road | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000). NG Mandakata Road MDR | NG Mandakata | Affected on 19/6/2022 as reported by Asstt. EE, PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000), NG Mandakat to Simelibari Road Rr | NG Mandakat to Simelibari | Affected on 19/6/2022 as reported by Asstt. EE, PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -0.000000), GNRC Road at Cutting Pahar RR | GNRC Road at Cutting Pahar | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -Rahdhola Rudreswar Road Rr | Rahdhola Rudreswar Road | Affected on 19/6/2022 as reported by Asstt. EE, PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat -0.0000000). Kotabazra Road RR | Kotabazra Road | Affected on 19/6/2022 as reported by Asstt. EE,PWD, Jalukbari Hajo Territorial Road Div. on 29/06/2022 | (Long - 0.000000, Lat - 0.000000) Nilambazar - BINODINI BAZAR TO FAKUA | BINODINI | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, BINODINI BAZAR TO FAKUA Road got damaged due to flood water. Affected length is 1000M. | (Long - 92.408955, Lat - 24.660667), MOINA (NH-8) TO ERALIGOOL | MOINA | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, MOINA (NH-8) TO ERALIGOOL Road got damaged due to flood water. Affected length is 1500M. | (Long - 92.355336, Lat - 24.660290), 19 Karimganj KANAIBAZAR TO SUNATULA ROAD | KANAIBAZAR | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, KANAIBAZAR TO SUNATULA ROAD got damaged due to flood water. Affected length is 2000M. | (Long - 92.315996, Lat - 24.665564), DUFAGHAT TO ROGURTOOK ROAD | ROGURTOOK | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, DUFAGHAT TO ROGURTOOK ROAD got damaged due to flood water. Affected length is 500M. | (Long - 92.328409, Lat - 24.675677), RCC BRIDGE APPROACH OVER NEFATULA RIVER NEAR AMC SENIOR MADRASSA ON

BILBARI SCHOOL TO NAYAGRAM | BILBARI | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that,RCC BRIDGE APPROACH OVER NEFATULA RIVER NEAR AMC SENIOR MADRASSA ON BILBARI SCHOOL TO NAYAGRAM ROAD got damaged due to flood water. Affected length is 150M. | (Long - 92.312273, Lat - 24.701073), KAYASTHAGRAM TO SINGARIA | KAYASTHAGRAM | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, KAYASTHAGRAM TO SINGARIA ROAD got damaged due to flood water. Affected length is 600M. | (Long - 92.366897, Lat - 24.710875), NH-8 TO BARAIGRAM BARAITOOK (PMGSY AS-13-298) | BARAIGRAM BARAITOOK | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, NH-8 TO BARAIGRAM BARAITOOK (PMGSY AS-13-298)ROAD got damaged due to flood water. Affected length is 300M. | (Long - 92.322991, Lat - 24.703374), BATAIYA TO SINGARIA ROAD | BATAIYA | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, BATAIYA TO SINGARIA ROAD got damaged due to flood water. Affected length is 700M. | (Long - 92.349627, Lat - 24.703192), NH 44 TO LASKARBARI | NH 44 | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, NH 44 TO LASKARBARI ROAD got damaged due to flood water. Affected length is 600M. (Long - 92.355005, Lat - 24.700585), BARAIGRAM PECHARPAR ROAD TO NABIPUR | BARAIGRAM PECHARPAR | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, BARAIGRAM PECHARPAR ROAD TO NABIPUR ROAD got damaged due to flood water. Affected length is 500M. | (Long - 92.336081, Lat NH 44 TO UTTAR BANDARKUNA | UTTAR BANDARKUNA | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, NH 44 TO UTTAR BANDARKUNA ROAD got damaged due to flood water. Affected length is 1500M. | (Long - 92.378815, Lat - 24.681895), ERALIGOOL TO SINGARIA | ERALIGOOL | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, ERALIGOOL TO SINGARIA ROAD got damaged due to flood water. Affected length is 700M. | (Long - 92.376665, Lat - 24.684103), E&D BAND FROM ISAGANJ TO DARARPAR | ISAGANJ | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, E&D BAND FROM ISAGANJ TO DARARPAR ROAD got damaged due to flood water. Affected length is 900M. | (Long - 92.316769, Lat - 24.692142), NH-44 TO JUNAIPATTY ROAD | JUNAIPATTY | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, NH-44 TO JUNAIPATTY ROAD got damaged due to flood water. Affected length is 500M. | (Long - 92.362956, Lat - 24.691965), NILAMBAZAR TO FARAMPASHA | NILAMBAZAR | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, NILAMBAZAR TO FARAMPASHA ROAD got damaged due to flood water. Affected length is 500M. | (Long - 92.364052, Lat - 24.734470), BINODINI PWD ROAD TO JOKIALA | BINODINI PWD ROAD | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, BINODINI PWD ROAD TO JOKIALA ROAD ALONG WITH ONE BRIDGE CULVERT got damaged due to flood water. Affected length is 750M. | (Long -92.386049, Lat - 24.654570), BINODINI PWD ROAD TO SHIVBARI | BINODINI | As reported by AEE, PWRD, Nilambazar, dated on 01/07/2022 that, BINODINI PWD ROAD TO SHIVBARI ROAD got damaged due to flood water. Affected length is 1500M. | (Long - 92.379860, Lat - 24.645264), ERALIGOOL PWD ROAD TO BARCHARRA (PMGSY PACKAGE NO.AS-13-194) | ERALIGOOL | As reported by AEE, PWRD, Nilambazar, dated on 21/06/2022 that, ERALIGOOL PWD ROAD TO BARCHARRA (PMGSY PACKAGE NO.AS-13-194) ROAD got damaged due to flood water. Affected length is 3800M. | (Long - 92.378178, Lat - 24.664222), KATIALA BODOLBHANGA ROAD | KATIALA BODOLBHANGA | As reported by AEE, PWRD, Nilambazar, dated on 22/06/2022 that, KATIALA BODOLBHANGA ROAD got damaged due to flood water. Affected length is 100M. | (Long - 92.425740, Lat - 24.762911) Gossaigaon - UPENDRAPUR VILLAGE ROAD | UPENDRAPUR | AS PER REPORT RECEIVED FROM AEE, PWD RR KACHUGAON SUBDIVISION ON 30.06.2022 DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE 2022 TO TILL TODAY RESTORATION OF FOREST VILLAGE ROAD AT UPENDRAPUR VILLAGE ROAD ERODED DUE TO FLOOD. | (Long - 0.000000, Lat - 0.000000), GHAKSA VILLAGE ROAD | GHAKSA | AS PER REPORT RECEIVED FROM AEE, PWD RR KACHUGAON SUBDIVISION ON 30.06.2022 DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE 2022 TO TILL TODAY RESTORATION OF ROAD AT GHAKSA VILLAGE ROAD | (Long - 0.000000, Lat - 0.000000), Kokrajhar 17 Kokrajhar - CHAKRASHILA ALURBHUI ROAD | CHAKRASHILA | AS REPORTED BY CO, KOKRAJHAR ON 02.07.2022 CHAKRASHILA ALURBHUI ROAD WAS DAMAGED | (Long -0.000000, Lat - 0.000000), (Kokrajhar) At District - BARZABIL ROAD | BARZABIL | AS REPORTED BY AEE, PWD GOSSIOGAON RR SUB-DIVISION RECEIVED ON 30-06-2022, VILLAGE ROAD HAS BEEN DAMAGED AT BARZABIL VILLAGE NEAR BILU NARZARY HOUSE | (Long - 0.000000, Lat -0.000000), NORTH GANGIA ADIVASHI ROAD | NORTH GANGIA | AS REPORTED BY AEE, PWD KACHUGAON RR SUB-DIVISION RECEIVED ON 30-06-2022, SUBMERGED ROAD FORMATION & DAMAGED THE ROAD FORMATION FROM CH0.00 TO 3000M &

			DAMAGED CULVERTS NO. 1/1, 1/2, 2/1 & 3/1 ON NORTH GANGIA ADIVASHI VILLAGE TO SOUTH GANGIA LINK ROAD (Long - 0.000000, Lat - 0.000000), NORTH GANGIA LINK ROAD NORTH GONDIA AS REPORTED BY AEE, PWD KACHUGAON RR SUB-DIVISION RECEIVED ON 30-06-2022, SUBMERGED ROAD FORMATION & DAMAGED THE ROAD FORMATION FROM CH0.00 TO 3000M &
			DAMAGED CULVERTS NO. 1/2 ON NORTH GANGIA TO BODOPUR LINK ROAD (Long - 0.000000, Lat - 0.000000), DHONGURI ROAD DHONGURI AS REPORTED BY AEE, PWD KACHUGAON RR SUBDIVISION RECEIVED ON 30-06-2022, SUBMERGED ROAD FORMATION & DAMAGED THE ROAD FORMATION FROM CH0.00 TO 3000M & DAMAGED CULVERTS NO. 3/1 & 3/2 ON
			DHONGURI TO MAORIAGAON PT-III ROAD (Long - 0.0000000, Lat - 0.0000000), NEW ISLAMPUR ROAD NEW ISLAMPUR AS REPORTED BY AEE, PWD KACHUGAON RR SUB-DIVISION RECEIVED ON 30-06-2022, SUBMERGED ROAD FORMATION & DAMAGED THE ROAD FORMATION FROM CH0.00 TO 2000M & DAMAGED CULVERTS NO. 1/1, 1/2,
			1/3, 1/4, 1/5, 2/1, 2/2, 2/3, 2/4, 2/5 2/6 ON NEW ISLAMPUR VILLAGE ROAD (Long - 0.000000, Lat - 0.000000), CHAKMA TAJPUR ROAD CHAKMA AS REPORTED BY AEE, PWD GOSSAIGAON RR SUB-DIVISION RECEIVED ON 30-06-2022, CHAKMA TAJPUR ROAD HAS BEEN ERRODED
			IN SOME STRETCHES (Long - 0.000000, Lat - 0.000000), FAKIRAGRAM BANARGAON ROAD FAKIRAGRAM AS REPORTED BY AEE, PWD KOKRAJHAR RR SUB-DIVISION RECEIVED ON 01/07/2022, FAKIRAGRAM BANARGAON ROAD TO EAST BECHIMARI VILLAGE ROAD CH400.00M WAS DAMAGED (Long - 0.000000, Lat - 0.000000),
			UTTAR DOBRAGAON ROAD UTTAR DOBRAGAON AS REPORTED BY AEE, PWD KOKRAJHAR RR SUB-DIVISION RECEIVED ON 01/07/2022, ROAD DAMAGED ON UTTAR DOBRAGAON VILLAGE ROAD. (Long - 0.000000, Lat - 0.000000), TILAPARA ROAD TILAPARA AS REPORTED BY AEE, PWD KOKRAJHAR RR SUB-
			DIVISION RECEIVED ON 01/07/2022, TILAPARA TO MAHAJANPARA VILLAGE ROAD WAS DAMAGED (Long - 0.000000, Lat - 0.000000), SWAHIDBEDI TO TILAPARA ROAD TILAPARA AS REPORTED BY AEE, PWD KOKRAJHAR RR SUB-DIVISION RECEIVED ON 01/07/2022, SWAHIDBEDI TO TILAPARA
			VILLAGE ROAD AT CH 250M WAS DAMAGED (Long - 0.000000, Lat - 0.000000), KOKRAJHAR MONAKOCHA ROAD KOKRAJHAR AS REPORTED BY AEE, PWD KOKRAJHAR RR SUB-DIVISION RECEIVED ON 01/07/2022, KOKRAJHAR MONAKOCHA ROAD CT CH 2300M WAS ERRODED (Long - 0.000000, Lat - 0.000000),
			HATIMATHA ROAD KOKRAJHAR AS REPORTED BY AEE, PWD KOKRAJHAR RR SUB- DIVISION RECEIVED ON 01/07/2022, HATIMATHA VILLAGE ROAD AT CH 50M TO 80M WAS DAMAGED (Long - 0.000000, Lat - 0.000000), RAMFALBIL ROAD KOKRAJHAR AS REPORTED BY AEE, PWD KOKRAJHAR RR SUB-
			DIVISION RECEIVED ON 01/07/2022, KOKRAJHAR RAMFALBIL ROAD AT CH 18KM WAS ERRODED (Long - 0.000000), Lat - 0.000000), PATGAON BILASHPUR ROAD PATGAON AS REPORTED BY AEE PWD KOKRAJHAR RR SUB-DIVISION ON 01-07-2022, PATGAON BILASHPUR ROAD AT CH2300M WAS ERRODED
			(Long - 0.000000, Lat - 0.000000) Narayanpur - Const. of Agri bundh at Raut chuburi to Khatiara chuburi 100 Meter road Damaged
			Rajgarh As per report from Rajgarh Panchayat on 02/07/2022 (Long - 0.000000, Lat - 0.000000), Gravel road at Geleki Chuk 100M Damaged Ganakdalani Panchayat As per report from Ganakdalani Panchayat on 02/07/2022. (Long - 0.000000, Lat - 0.000000),
	Lakhimpu r	5	Gravel road at Chutiagaon 100M Damaged Chutiagaon As per report from Ganakdalani Panchayat on 02/07/2022. (Long - 0.000000, Lat - 0.000000), Gravel road at Bhitordoloni 100M damaged Bhitordoloni As per report from Ganakdalani Panchayat on 02/07/2022. (Long - 0.000000, Lat - 0.000000),
	Moriggon	1	Gravel road at Ganakdoloni Umesh Phukan Chuburi 100M damaged Ganakdoloni As per report from Ganakdalani Panchayat on 02/07/2022. (Long - 0.000000, Lat - 0.000000) Morigaon - Lothabori Gaginibori Road (01-06-2022) Lothabori As per PWD(Roads), Lothabori Gaginibori Road under submergence and shoulder eroded at different stretches of 1st, 2nd nd 3rd KM.
	Morigaon	1	Avg depth of submergence is 0.2m (Long - 92.338473, Lat - 26.271240) Chariduar - GHOGORA TE TO TUMUKI ROAD FROM CH 550.00M TO 620.00 M CH 700.00M
	Sonitpur	1	TO 850.00 M CH 4650.00M TO 4800.00M DEPTH OF SUBMERGENCE 30 CM TO 50CM. DTD 02/07/2022 CHARIDUAR REVENUE CIRCLE (Long - 0.000000, Lat - 0.000000) Margherita - MRL02-NH 153 (KORIAPANI VIA UDOIPUR 3 MILE) LAKHMI MANDIR,
	Tinsukia	1	UDAIPUR 3 MILE (FROM CH 1500.00M TO CH 1600.00M) AROUND 5M OF STRETCH DUE TO INCESSANT HEAVY RAINFALL THE ROAD WAS FOUND UNDER SUBMERGENCE ON 02-07-2022 RESULTING IN DAMAGE OF HARD CRUST AND EROSION OF SOIL AT SHOULDERS ARE TAKING PLACE. PERMANENT RESTORATION WILL BE REQUIRED DURING AND AFTER FLOOD PERIOD PERMANENT RESTORATION WILL BE REQUIRED
	TD - 1	210	DURING AND AFTER FLOOD PERIOD (Long - 95.843067, Lat - 27.386563)
Infrastructu	Total District	348 Numbe	Details Details
mirastructu	DISTRICT	Numbe	Details

re Damaged		r						
- Bridge		Bajali - Rep of Kalkhoa Bridge at vill Nimua nimua Rep of Kalkhoa Bridge damaged at vill Nimua.						
Driage	Bajali	length 15Mtr Breadth 2M Depth 0.8 M. This report is received from BDO,Bajali Dev. Block on 02/07/2022 (Long - 0.000000, Lat - 0.000000)						
	Total	1						
	District	Wildlife affected under protected areas description						
Infrastructu re Damaged - Wildlife	Golaghat	(Golaghat) At District - Inundated Camps as on date: Agoratoli Range (out of 34 camps 16 are inundated), Kaziranga Range (out of 49 camps 14 are inundated), Bokakhat Range (Out of 7 camps 2 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 02-07-2022.						
	Morigaon	•						
		· · · · · · · · · · · · · · · · · · ·						
Infrastructure Damaged - Others	Morigaon District Bajali	Nayong - Pobitora WLS [Onumbers of camp inundated as reported by Range Officer PWLS on 02/07/22 Other Details Bajidi - Power Dept. Transformers one transforfer of 250kva damaged at Haripur chowk:this report is received from SDE, APDCL, Pathsala on 02/07/2022, Power Dept. Poles 14 Nos. HT Poles damaged. total length 21.2 KM.this report is received from SDE, APDCL, Pathsala on 02/07/2022, Agri Bundh Damaged Agribundh from Pub Majjupara Sangha to Gopesh Deka land. LENGTH 160M BREADTH 20 MDEPH 1.5M. This report is received from BDO, Bajali Dev. Block on 02/07/2022, Agri Bundh Damaged Agril-Bandh Starting from south side of Bhogeshwari Mandir to Madapara at Bhati Uluwa, LENGTH 25M, BREADTH 3M AND DEPTH 1 M. This report is received from BDO, Bajali Dev. Block on 02/07/2022, Agri Bundh Damaged Agril Bundh from Nagen Kalira land to Suren Kakati Land under MGNREGA/20-21. LENGTH 150M BREADTH 1.5M DEPTH 0.45MThis report is received from BDO, Bajali Dev. Block on 02/07/2022, Agri Bundh Damaged Agril bundh from Tarani Roy Land to Dinesh Talukdar Land. Under MGNREGA/19-20.1ENGTH 110M BREADTH 1M AND DEPTH .6MThis report is received from BDO, Bajali Dev. Block on 02/07/2022, Bamboo Foot Bridge Wooden foot bridge Halgrin Ghat-Kalita Supa , under 14th FC/2017-18.LENGTH 32 M AND BREADTH .9MThis report is received from BDO, Bajali Dev. Block on 02/07/2022, Bamboo Foot Bridge Wooden foot bridge Halgrin Ghat-Kalita Supa , under 14th FC/2017-18.LENGTH 32 M AND BREADTH .9MThis report is received from BDO, Bajali Dev. Block on 02/07/2022, Agri Bundh Damaged Earthfilling at both side approaches of wooden foot bridge at Halgrin Ghat, under 14th FC/2017-18.LENGTH 32 M AND BREADTH .9M BREADTH 4M DEPTH 1 M This report is received from BDO, Bajali Dev. Block on 02/07/2022, Agri Bundh Damaged Agribundh from Pathsala Golibandha PWD road to Pakrital at vill Belana(MGNEREGA), Length 50m Breadth 4m depth 0.5mThis report is received from BDO, Bajali Dev. Block on 02/07/2022, Agri Bundh Damaged Agribundh from Romaged Romaged						

Agri Bundh Damaged | Agribundh from PWD Rd to Paddy field via Gagan Das house at Vill- Chaibari.affected length 10 m breadth 4m depth 1m. This report is received from BDO, Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Agribundh from Irrigation Canal to Sanjay Kalita Paddy field at Pub Rihabari. Length 20m Breadth4 Depth2m. This report is received from BDO, Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Agribundh Miraj Boro house to othrasangha Pond via Prahlad Boro house at Pub Rihabari MGNREGA 2020-21 Length30m Breath 4m Depth 1m. This report is received from BDO, Bajali Dev. Block on 02/07/2022.

Irrigation Canal/Scheme Damaged | Damaged Irriagtion Bundh near Kailash Nath shop to Gangadhar Koibartya at vill- Barmanikpur. length30m breadth4m depth3mThis report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Agribandh from Tihu-Bangaon PWD road to Go reserve & Smachan.length 200M breadth 2.5M Depth 0.45M.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Agribandh from Tihu-Bangaon PWD road to Bhadravitha Sani Mandir.length 200M breadth 2.5M depth0.45MThis report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Agribandh from Barbhaluki Dekapara (kaldia river) embankment to Khalihamari Suba.length 10M breadth 2.5M depth 1M.This report is received from BDO,Bajali Dev. Block on 02/07/2022, Agri Bundh Damaged | Agribundh from Gopal Gohai Namghar to Manik Chandra Deka house at vill Barnalikuchi under MGNREGA 2020-21. Length 100mtr Breadth 3.8mtr Depth 1.2mtr.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Agribundh cum Road form Saiten Sarma house to Amar Sarma house at vill Barbatabari under MGNREGA .Length 10mtr Breadth4.5mtr Depth 0.4mtr.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Agribandh cum road from shyama Puja to Narayan Nath house at vill Sathisamuka .length 100 Mtr breadth 5M depth 1.5M.This report is received from BDO,Bajali Dev. Block on 02/07/2022, Agri Bundh Damaged | 705-Agribandh- deojarapar from infront of Achyut Roy house to Pabitra Roy house with hume pipe/19-20 LD/9010247276).length0.70 breadth 10 Mtr depth2.8 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | 719-Agribandh from Karuna Barman house to Lakhsi Hola pathar east side Kaldia river/2019-20 /LD/9010247277)length 0.60 breadth20 M depth1.8 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022.

Agri Bundh Damaged | 727-Impvnt.of Agribandh from Suliyapara Bhabananda Sarma house to Sikhroita paddy field/2019-20 LD/9010247279).length0.80 breadth50 M depth2.1 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | 770-Agribandh from choudhury para ghat via bokulthan to Saktijan at village Bichankuchi/2019-20 LD/9010247283.length0.60 breadth200 M depth1.9 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Agri bundh from Modan Rauta road to Mahabhairav Smokhan length.0.80 breadth250 M depth1.6 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Improvement of agreebandh from L.P School to Tengera Jaan at Village Titkataje .length7.00 M breadth7.50 M depth1.80 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Improvement of agreebandh from Rajen Saloi land to Kanoibari Suba agreefield at vill. Titka Taje. length 5.00 M breadth 6.00 M depth 1.50 M. This report is received from BDO, Bajali Dev. Block on 02/07/2022.

Agri Bundh Damaged | Const. of agreebandh from Tiniali chowk to Sadagar Road at vill Borgunari.length5.50 M breadth6.00 M Depth2.30 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Improvement of agreebandh from Dina nath Das house tpo Ailajaan Shiv Mandir to Kanoibari Suba agreefield. Length 5.00 M Breadth 6.00 M Depth 2.10 M. This report is received from BDO, Bajali Dev. Block on 02/07/2022,

Agri Bundh Damaged | Const. of Agril Bandh Cum RD.from HN. PWD Rd to Munin Talukdar house at pachim Kathalmuri .Length5.00 M Breadth6.00 M Depth1 M.This report is received from BDO,Bajali Dev. Block on 02/07/2022

Barpeta - Bridge Approach Road Damaged | (Date of occurence 19.06.2022)Dakkhin hati Approach road Br. Approach damage 25.00 "Latitude - 26.317475 Longitude - 91.011905",

Bridge Approach Road Damaged | (Date of occurence 19.06.2022)Dakkhin hati Approac road Br. Approach damage 25.00 m,

Elementary Schools Damaged | (Date of occurence 22.06.2022)(Floor ,Roofs ,Wall, and Door with Windows) Name of schools : 1/ 116 No.Moiramara-1 2/ 186 No.Azad Path 3/ 195 No.Ahila Balika School 4/ 206 No.Ambari Uttar 5/ 100 no.Noonmati-1 6/ 280 no.Noonmati Pub-2 7/ 289 no.Noonmati Madhya-3. 8/ 292 no.Noonmati Ghilajhari-4 9/ 291 No.Joypur-4 10/ 101 no.Ghilajhari-1 11/ 102 no.Ghilajhari-2 12/ 282 no.Ghilajhari Paschim Char-3 13/ 286 no.Ghilajhari Madhya- 14/ 106 no.Katlijhar-1 15/ 126No.Katlijhar 16/ 283 no.KatlijharPub Dakshin-4 17/ 285 no.Katlijhar Dakshin Pub-5 18/ 108 No.Hajipara-1 19/ 109 no.Hajipara-2 20/ 110 no.Hajipara-3 21/ 279 no.Hajipara Dakshin Paschim-5 22/ 288No. Hajipara 23/ 371 no.Hajipara Pachim Dakshin Char (M) 24/ 287 no.Deulipara Pub-2 25/ 372 no.Deulipara Madhya (M) 26/ 61 no.Khandakarpara-1 28/ 63 no.Khandakarpara-3 29/ 375 no.Khandakarpara H.K. Collage (M) 30/ 115 no.Fulkipara-1 31/ 163 no.Fulkipara-2 32/ 276 no.Fulkipara Paschim dakshin-4 33/ 373 no.Fulkipara Uttar (M) 34/ 113 no.Itervitha-2 35/ 114 no.Itervitha-3 36/ 131No. Itervitha-3 37/ 169 no.Itervitha-5 38/ 267 no.Itervitha Pub Madhya-6 39/ 270 no.Itervitha Pub-7 40/ 275 no.Itervitha-8 41/ 117 no.Moiramara-2 42/ 260 no.Moiramara Dakshin-3 43/ 261 no.Moiramara 4th APTF-4 44/ 262 no.Moiramara Uttar Ambari-5 45/ 132

Barpeta

no.DollagaonMoiramara-8 46/ 199 no.Moiramara Natun Basti. 47/ 116 No Moiramara-1 48/ 70 no.Danakuchi-1 49/ 166 no.Danakuchi Pub Dakshin-2 50/ 212 no.Danakuchi Pub -3 51/ 224 no.Danakuchi Pub-4 52/ 73 no.Sonkuchi-1 53/161 no.Sonkuchi-2 54/363 no.Sonkuchi Pachim River (M) 55/70No. Donakuchi-1 56/ 166No. Donakuchi-2 57/212No. Donakuchi-3 58/76 no. Dangarkuchi-1 59/224No. Donakuchi-4 60/73No. Sonkuchi-1 61/161No. Sonkuchi-2 62/137 no.Dangarkuchi Uttar-3 63/160 no.Dangarkuchi Pub-4 64/232 no.Baniarapara Paschim Madhya-6 65/ 235 no.Baniaraparam dakshin Madhya-7 66/ 240 no.Baniarapara dakshin Madhya-8 67/ 93 no.Dhakaliapra-1 68/ 127 no.Dhakaliapra-2 69/ 138 no.Dhakaliapra-3 70/ 78 no.Kumullipara-1 71/79 no.Kumullipara-2 72/80 no.Kumullipara-3 73/81 no.Kumullipara-4 74/82 no.Kumullipara-5 75/130 no.Kumullipara-6 76/ 185 no.Kumullipara Pub-7 77/ 233 no.Kumullipara Paschim Madhya -9 78/ 236 no.Kumullipara Uttar Pub-10 79/239 no.Kumullipara Uttar Paschim-11 80/83 no.Baniarapara-1 81/84 no.Baniarapara-2 82/ 85 no.Baniarapara-3 83/ 129 no.Baniarapara-4 84/ 86 no.Garemarigaon-1 85/ 87 no.Garemarigaon-2 86/ 229 no.Garemaripathar Madhya-3 87/ 230 no.Garemaripathar uttar-4 88/ 365 no.Garemari Pathar Pub Dakshin (M) 89/66 no.Bahmura -1 90/135 no.Bahmura-2 91/165 no.Bahmura-3 92/210 no.Bahmura Dakshin-4 93/ 215 no.Bahmura Madhya-6 94/ 67 no.Jahorpam-1 95/ 68 no.Jahorpam-2 96/ 69 no. Jahorpam-3
 97/220 no. Jahurpam Madhya 98/223 no. Jahorpam-6
 99/75 no. Dhanbandha-2
 100/ 162no.Dhanbandha West-3 101/219 no.Dhanbandha Dakshin-6 102/221 no.Dhanbandha Madhya-7 103/71 No. Deurikuchi 104/72 no.Deurikuchi-2 105/136 no.Deurikuchi Dakshin-3 106/216 no.Deurikuchi-4 107/118 no.Bogaijanpara -1 108/277 no.Bogaijanpara Uttar Chowk -6 109/119 no.Hatijana-1 110/121 no.Joshihatipara-1 111/263 no.Joshihatipara Uttar-3 112/264No. Joshihatipara Dakshin 113/167 no.Joshihatipara-2 114/105 no.Nagarjhar-1 115/ 140 no.Nagarjhar Dakshin-2 116/ 171 no.Nagarjhar-3 117/ 125No.Ambari 118/ 170 no. Ambari Uttar - 2 119/90 no. Dabaliapara-1 120/91 no. Dabaliapara-2 121/92 no. Dabaliapara-3 122/254No. Dabaliapar Uttar Madhya-5 123/257 no.Dakshin Dabaliapara Madhya-6 124/366 no.Dabaliapara Near High School (M) 125/94 no.Kadamguri -1 126/95 no.Kadamguri -2 127/139 no.Kadamguri Uttar-3 128/243 no.Kadamguri Pub Dakshin-4 129/ 247 no.Kadamguri -5 130/ 96 no.Duttakuchi -1 131/ 128 no.Duttakuchi -2 132/180 no.Duttakuchi Pachim -3 133/242 no.Duttakuchi Dakshin-4 134/246 no.Duttakuchi Uttar-5 135/368 no.Duttakuchi (M) 136/97 no.Jogirpam-1 137/98 no.Jogirpam-2 138/99 no.Joghrpam-3 139/248 no.DakshinJoghirpam Dewanpara-5 140/255 no.Jogirpam Khandakarapara-6,

Barnagar - PWSS Damaged | As per report received from Asst. Ex. Engineer (PHE), Barpeta Sub- Division , Barpeta on 02/07/2022 the PWSS viz. Satbainer Tup PWSS in the village Satbainir Tup is damaged due to flood. The pipeline, cleaning & washing of UGR and development of Deep tubewell, FHTC is damaged.,

Baghbar - Elementary Schools Damaged | Garala Suti LPS is wasted away (Date - 22-6-2022),

Kalgachia - Elementary Schools Damaged | As reported by Education dept (BEEO Rupshi) on 02/07/22, total 12 nos of schools are partially damaged, details as- 1. Bonghugi Uttarpara LPS, 2. Pub charcharia LPS, 3. PGP Mowamari DS Rampur LPS, 4. 863 Khudrakhuwa LPS, 5. 1673 Paschim Srirampur LPS, 6. Pub Langla LPS, 7. Kaurjahi LPS, 8. Char Langla LPS, 9. Char Langla LPS, 10. Barbitha Pre Senior Madrassa, 11. Dakshin Minisimla LPS, 12. 1787 No Kasukati Charcharia LPS,

Sarthebari - PWSS Damaged | Kaharpara PWSS, Reported by JE, PHE, Paka-Betbari Division on 2/7/2022, PWSS Damaged | Kawaimari PWSS, Reported by JE, PHE, Paka-Betbari Division on 2/7/2022,

PWSS Damaged | Bheragaon PWSS, Reported by JE, PHE, Paka-Betbari Division on 2/7/2022,

PWSS Damaged | RETROFITTING OF BAR AMRIKHOWA PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022.

PWSS Damaged | RETROFITTING OF BARGHOPA PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022

PWSS Damaged | RETROFITTING OF BARMARA PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022.

PWSS Damaged | RETROFITTING OF BAYASHA PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,

PWSS Damaged | Retrofitting of Belbari PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022, PWSS Damaged | RETROFITTING OF BHAKUATEPA ROWLY PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,

PWSS Damaged | RETROFITTING OF BHOGDIA PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,

PWSS Damaged | RETROFITTING OF BYASKUCHI PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,

PWSS Damaged | RETROFITTING OF CHINADI PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,

PWSS Damaged | RETROFITTING OF GADESHALI PAM PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,

PWSS Damaged | Retrofitting of Garia Chatala, Reported by JE, PHE, Sarukhetri Division on 2/7/2022, PWSS Damaged | Retrofitting of JOSODAR PAM PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022.

PWSS Damaged | Retrofitting of KALJAHI PATHAR PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022.

PWSS Damaged | RETROFITTING OF KARAKUCHI PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022.

PWSS Damaged | Retrofitting of KUKAR PAR PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022, PWSS Damaged | RETROFITTING OF LACHIMA PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,

PWSS Damaged | Retrofitting of NAMSHALA PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,

PWSS Damaged | Retrofitting of RANGIA NADIR PAM PWSS, Reported by JE, PHE, Sarukhetri Division on 2/7/2022,
Fisheries/Pond | Namshala, Barsala bilar pathar, 12 Bigha Water area, Reported by owner on 2/7/2022

 $\textbf{Gohpur} \text{ - Power Dept. Poles} \mid \text{APDCL Gohpur has reported 8 Nos of LT Pole} \text{ , 6 Nos HT in Solengi and 9 Nos of LT Pole, 6 Nos of HT in Gohpur Area damaged on } 29/06/22,$

Power Dept. Conductors | APDCL Gohpur has reported 2.6 KM Conductor in Solengi and 3.8 KM Conductor in Gohpur Area damaged on 29/06/22,

Anganwadi Centres Affected | Rup Nagar AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Gohaichuk AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Raipuria Line AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Chatiachuk AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Bilotia AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Pub Bilotia AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | No 1 Borpholong AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Sonalibori is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Panigaon(Mini) AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Kakila Pather AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Badalpather AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Sessa Axomiya AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Bosistapur AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Sutardoloni AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Chingarajan AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Kolmouguri Kaibatra AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Nabapur Mini AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Nabapur Harimondir AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | 1 No Bosisthapur AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

 $Anganwadi\ Centres\ Affected\ |\ 2\ No\ Nabapur\ AWC\ is\ affected\ by\ Flood\ water\ and\ Partial\ damage\ is\ reported\ by\ CDPO\ ,\ Pub\ Chiduar\ ICDS\ project\ reported\ on\ 01/07/22,$

Anganwadi Centres Affected | Gospuria AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Kollapani AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Karisubba AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Dohgharia AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Karisubba AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Uppor Swaguri AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Leluagaon AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Purona Baligaon AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Sonajuli AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Gopserguri AWC is affected by Flood water and Partial damage is reported by

CDPO , Pub Chiduar ICDS project reported on 01/07/22, Anganwadi Centres Affected | Na Bil AWC is affected by Flood water and Partial damage is reported by CDPO ,

Pub Chiduar ICDS project reported on 01/07/22,

Biswanath

Anganwadi Centres Affected | Rajabari Pather-1 AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Ozabara AWC is affected by Flood water and Partial damage is reported by CDPO , Pub Chiduar ICDS project reported on 01/07/22,

Anganwadi Centres Affected | Nabil Bherbheri AWC is affected by Flood water and Partial damage is reported by CDPO, Pub Chiduar ICDS project reported on 01/07/22,

Power Dept. Poles | Power Sector under the CGM (O&M), UAR, AEGCL. Submerged in flood water in recent flood at Gohpur area on 28-06-2022.

Boitamari - Fisheries/Pond | Fishery Farm pond in the land of Jahanara Khatun under NREGA 20-21. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Fisheries/Pond | Fishery Pond in the land of Sahera Khatun under NREGA 20-21. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Fisheries/Pond | Fishery Farm pond in the land of Rupbhanu Begum under NREGA 20-21. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Fisheries/Pond | Fishery Farm Pond in the land of Sabiya Khatun under NREGA 20-21. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Fisheries/Pond | Fishery Farm Pond in the land of Hanufa Khatun under NREGA 20-21. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Fisheries/Pond | Excavation & Development of Community farm Pond in the Land of Hasdoba Bapuji Samuhik Kendra Ph-I. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Fisheries/Pond | Excavation & Development of Community farm Pond in the Land of Hasdoba Bapuji Samuhik Kendra Ph-II. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Culvert Approach Road Damaged | CC culvert near Yusuf Ali house at Kheluapara at 5 m. Lat-26.25, Long-90.44. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Culvert Approach Road Damaged | CC culvert near Sorhab Ali at Kheluapara at 5 m. Lat-26.25, Long-90.43. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Culvert Approach Road Damaged | CC culvert at Jhaukura Pt 2 Dumduma Char near Jara Khandakar at 5 m. Lat-26.26, Long-90.45. Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Manikpur - Agri Bundh Damaged | Anti erosion bundh from No. 2 Bhandara Tiniali to No. 2 Bhandara kabarsthan at No. 2 bhandara 0.13 km, Lat-26.442349 Long-90.759459 reported by Zila Parishad Bongaigaon Dated 01-07-2022 ,

Agri Bundh Damaged | Agril bundh from 4 No. Jandoha to 6 No. Jamdoha 0.08km,Lati -26.431861 Long-90.711968 reported by Zila Parishad Bongaigaon Dated 01-07-2022 ,

Agri Bundh Damaged | Agril bundh from 3 No. Jamdoha PMGSY rd to Prafulla Ray house at 3 No. Jamdoha 0.1 Km Lati-26.451624 Long-90.702017 Reported by Zila Parishad Bongaigaon Dated 01-07.2022,

Agri Bundh Damaged | Agril bundh from 1 No. Bhandara to Srijangram GP border Ph-III 0.1 km Lati-26.423436 Long-90.738776 reported by Zila Parishad Bongaigaon Dated 01-07-2022,

Agri Bundh Damaged | Agril bundh from 2 No. Garugaon to No. 3 Jaraguri via Nachanguri No. 3 Ph- I, II, III, 0.6 km Lati-26.47365 Long-90.650655, reported by Zila Parishad Bongaigaon Dated 01-07-2022,

Agri Bundh Damaged | Agril bundh from Manas Bridge to Sasan Ghat at Nagarjhar 0.1 km Lati-26.468553 Long-90.747326, reported by Zila Parishad Bongaigaon Dated 01-07-2022,

Agri Bundh Damaged | Agril bundh from Moksed Ali house to Sahar Ali house at Supariguri vill 0.09 km Lati-26.482805 Long-90.741427 reported by Zila Parishad Bongaigaon Dated 01-07-2022,

Dangtol - Culvert Approach Road Damaged | Box culvert near Aditya barman house at 0.015 k.m Lat-26.430615, Long-90.409764. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | Box culvert near Alom pukhuri at borchora pt -6 at 0.017 k.m Lat-26.424685, Long-90.408354. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | Rcc box culvert on Morachhampa bridge near dhaneswar mandal house at naytapara pt 1 at 0.008 k.m Lat-26.447383, Long-90.412898. Reported by Zila Parishad, Bongaigaon Dated-01.07.2022,

Agri Bundh Damaged | Agril Bundh Cum Road From Umaraddin house to dilbar sk at 0.1 k.m. Lat-26.359944, Long-90.431757. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Agri Bundh Damaged | Agril Bundh Cum Road from pawamusa house to Shoharuddin at lingdoba at 0.1 k.m. Lat-26.359169, Long-90.447732. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Agri Bundh Damaged | Agril Bundh Amir fokir house to mohiruddin house ph-iii at 0.1 k.m. Lat-26.361177, Long-90.456693. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | HP culvert on the road from nur mohammad house to lingdoba L P school at Lingfdoba at 0.1 k.m. Lat-26.355662, Long-90.446493. Reported by Zila Parishad, Bongaigaon Dated-01.07.2022,

Culvert Approach Road Damaged | Box Culvert at South Ghagpara near Sahid Mondal House at 0.15 k.m. Lat-26.360545, Long-90.462474. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | 90 mm dia HP Culvert near Siddique Alli House at Bandarani at 0.1 k.m. Lat-26.364186, Long-90.429603. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | Box culvert near Arman Ali house at Nangkargaon at 0.05 k.m. Lat-26.361177, Long-90.456693. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | Box Culvert near Abbas Ali House at Nangkargaon at 0.02 k.m. Lat-26.361171, Long-90.456687. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | Box Culvert near Bhuban sarkar House on the Road from Bamunitila GP Office to Bhuban Sarkar House at Bamunitila at 0.05 k.m. Lat-26.369325, Long-90.457092. Reported by Zila

Bongaigao n Parishad, Bongaigaon Dated-01.07.2022,

Agri Bundh Damaged | Agril bundh cum Rd. frm Sajahan Ali house to Pawmusa house at Lingdoba at 0.1 k.m. Lat-26.355662, Long-90.446493. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Agri Bundh Damaged | Agril Bundh Cum Rd Mathauri Bundh beel suti near bakkar mandal house at 0.05 k.m. Lat-26.352852, Long-90.448758. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | RCC box Culvert at Shingimari Mukh at Durgamari at 0.1 k.m. Lat-26.380976, Long-90.459252. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Culvert Approach Road Damaged | H P Culvert Near Oser Ali House At Bhitor Chengmari at 0.02 k.m. Lat-26.380816, Long-90.468372. Reported by Zila Parishad, Bongaigaon Dated- 01.07.2022,

Gully Control Damaged | Gully control 15 m. river Kujiia at Simlaguri. Lat- 26.480238, Long-90.691094, Reported by Soil Conservation Bongaigaon. Dated- 02.07.2022,

Srijangram - Agri Bundh Damaged | Agril. Road from Numberpara Pt I,South Chariali Bazar to Bdidge Bazar,30m Name of GP Numberpara Chakla Latitude-26.379032 Longitude-90.817951, Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Agri Bundh Damaged | Agril Bundh from Mozid Ali house to Balarchar GP boundary, 150m Name of GP Golapara Banglapara, Latitude-26.381807 Longitude-90.797653,Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Agri Bundh Damaged | Agril Bundh from Banglapara paar ghat to Kadamtali paar ghat west, 50m Name of GP - Golapara Banglapara, Latitude-26.397785, Longitude-90.79276 Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Agri Bundh Damaged | Agril Bundh (AA) Raha rd to Numberpara GP boundary,30m, Name of GP- Golapara Banglapara Latitude-26.398128, Longitude- 90.802756 Reported by Zila Parishad Bongaigaon Dated 01.07.2022, Agri Bundh Damaged | Agril Bundh from RCC Bridge to Golapara Pt I road,200m Name of GP- Golapara Banglapara Latitude-26.385654 Longitude-90.805443, Reported by Zila Parishad Bongaigaon Dated 01.07.2022, Agri Bundh Damaged | Agril Bundh from Jangsher Ali house to Bill Bazar at Golapara Pt IV East 100m Name of GP- Golapara Banglapara Latitude-26.40765 Longitude-90.804145, Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Agri Bundh Damaged | Agril Bundh from at Numberpara Pt III Paddy Field Phase I, 150m Name of GP Numberpara Chakla, Latitude-26.406205, Longitude-90.804194, Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Agri Bundh Damaged | Agril Bundh from Boroichala Play ground to Boroichala North LPS via Water supply, 150m Name of GP. Jopea Latitude-26.353471 Longitude-90.766399, Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Fisheries/Pond | Farm Pond (IBS) Name of GP Jopea Latitude-26.36981 Longitude-90.76781, Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Bamboo Foot Bridge | Guide Bundh from Rohan Ali house to Numberpara GP Border, 20m Name of GP Golapara Banglapara Latitude- 26.399058 Longitude- 90.804943, Reported by Zila Parishad Bongaigaon Dated 01.07.2022,

Bamboo Foot Bridge | Guide bundh with Protection Measures at Balarpet in the LB river Aie under MGNREG, 0.7 mtr Name of GP Srijangram Latitude-26.417579 Longitude-90.75159, Reported by Zila Parishad Bongaigaon Dated 01.07.2022

Udharbond - Fisheries/Pond | Total 189 Water Area affected (HA) & Total 430 No of Fish Farmer affected as per the report received from Fishary Deptt Cachar as on dated 01.07.2022,

Silchar - PWSS Damaged | BOROHAL W/S/S MASIMPUR BAGICHA W/S/S MASIMPUR GRANT W/S/S MASIMPUR PT-I W/S/S MASIMPUR PT-II W/S/S KUKILPUR W/S/S SOUTH MASIMPUR W/S/S 12 NO. BASTI W/S/S ARDAVALLIC W/S/S BADARPUR BORKHOLA W/S/S HARINCHERRA W/S/S/ NARAINCHERRA GRANT W/S/S NARAINCHERRA (ARICOL) W/S/S BORKHOLA BAZAR W/S/S BORKHOLA W/S/S UJAN NAGAR W/S/S ANOWARPAR W/S/S BALACHERRA GRANT W/S/S BORORAMPUR GARDEN W/S/S BORORAMPUR W/S/S DALUGHAT W/S/S DALUGRAM W/S/S MAINACHERRA W/S/S RAMPUR T.E W/S/S SCHEME RAMPUR W/S/S CHANDRANATHPUR W/S/S KATACHERRA W/S/S BORKHOLA PT-II W/S/S NOGOD W/S/S PURANDARPUR W/S/S SCHEME SONAPUR(PATAKHAIPAR) W/S/S CHESRI W/S/S CHRISTIAN LANE W/S/S KALINAGAR W/S/S SILDAR W/S/S KALINAGAR GARDEN W/S/S RAMAN BASTI W/S/S WEST JARAILTALA W/S/S VITOR GANGAPUR W/S/S ABONGCHERRA W/S/SCHEME BORBOND W/S/S LALBAG W/S/S MAINAGARH W/S/S ABONG W/S/S CHEMTI BEEL W/S/S RANINAGAR W/S/SCHEME CHANDPUR PT-IV & V W/S/S BHANGARPAR W/S/S BHANGARPAR PT-V W/S/S BURIBAIL PT-III W/S/S ROUARPAR W/S/S KRISHNAPUR W/S/S PELADAHAR W/S/S ROYPUR W/S/S SCHEME SARAIL W/S/S SCHEME MANIPURI BASTI W/S/S DUBAG W/S/S JATINGAMUKH W/S/S KHANPARA W/S/S KUMARPARA W/S/S NIZ JOYNAGAR W/S/S ALGAPUR W/S/SCHEME MANIKPUR NORTH W/S/S MANIKPUR W/S/S

Cachar

NISCHINTAPUR W/S/S RAKHALKHALERPAR PT-I WSS RAKHALKHALERPAR W/S/S
CHENGUARPAR W/S/S GAGRAPAR W/S/S NANDIGRAM W/S/S SALCHAPRA PT-II W/S/S
SALCHAPRA PT-III W/S/S SALCHAPRA W/S/S SANJURAI WSS SRIDHARPUR W/S/S SRIKONA W/S/S
GOURBASTI W/S/S HATIRHAR PT- I&II SALCHAPRA GRANT W/S/S CHIRUKANDI W/S/S
ATHALKANDI W/S/S RAMNAGAR W/S/SCHEME BERAKHAL W/S/S BISINGA W/S/S PECHADAHAR
W/S/S SIBBARI WSS TARAPUR PT IV TARAPUR PT-V W/S/S KASHIPUR W/S/S NETAJI NAGAR W/S/S
TARAPUR PT VI (PH II) W/S/S TARAPUR PT-VI W/S/S TUKERGRAM W/S/S DURGANAGAR
(SILCHAR) W/S/S TARAPUR PT-VII W/S/S TARAPUR PT-VIII TARAPUR PT I W/S/S MALINIBEEL

W/S/S DIGOR SRIKONA W/S/S KAMALA BAGAN W/S/S SRIKONA GRANT W/S/S LALMATI W/S/S

OWAL TILLAH W/S/S GREATER TAPANG W/S/SCHEME CHIBITABICHIA PT-I W/S/S CHIBITABICHIA PT-III & IV W/S/S CHIBITABICHIA PT-IX W/S/S CHIBITABICHIA PT-V & VI W/S/S KUARPAR W/S/S CHIBITABICHIA PT-II W/S/S, submerged as per the report received from PHE Silchar Division, as on dated 01.07.2022,

Inland Water Transport Deptt. Damaged | Annapurna Ferry Service, Chotodudpatil Ferry Service, Borodudpatil Ferry Service, Berenga Ferry Service, Badri Ferry Service, Gandhighat Ferry Service, Jatinga Ferry Srvice, approch road of Ferry Services both side fully damaged & wodden landing stage washed out, as per the report recived from IWT, Cachar as on dated 30.06.2022,

Fisheries/Pond | Total 998 Water Area affected (HA) & Total 3135 No of Fish Farmer affected as per the report received from Fishary Deptt Cachar as on dated 01.07.2022,

Sonai - Fisheries/Pond | Total 1095 Nos of Fish Farmers Affected & 196 Hector Fishery Area affected due to Recent Flood Report Received from Dist. Fishery Department on 02.07.2022. Under Sonai Revenue Circle. , Lakhipur - Inland Water Transport Deptt. Damaged | 01 No of Frey Service at Fulertal Approach Damage due to Flood Report received from IWT Department on 01.07.2022 Under Lakhipur Revenue Circle,

Fisheries/Pond | Total 148 Water Area affected (HA) & Total 470 No of Fish Farmer affected as per the report received from Fishary Deptt Cachar as on dated 01.07.2022,

Katigorah - PWSS Damaged | SARISHAKURI W/S/S SCHEME TINTIKREE W/S/S CHOUDHURY GRAMW/S/S ISHANABAD W/S/S BEHARA PT-V W/S/S BHAIRABPUR PT-I W/S/S BHAIRABPUR PT-III W/S/S BHAIRABPUR W/S/S PASCHIM NATANPUR W/S/S TIKAR BURUNGA W/S/S. LAL TILLAH W/S/S DINANATHPUR GRANT W/S/S LAMBATILLAH W/S/S UPPER TELICHERRA W/S/S BEHARA PT-I & II W/S/S BEHARA W/S/S GORERVITOR W/S/S GUMRAH WSS PUBERGRAM W/S/S LAMARGRAM MANIKPUR W/S/S MADURKHAL W/S/S NATANPUR W/S/S RONGPUR W/S/S SCHEME NATANPUR GRANT W/S/S NIZ JALALPUR W/S/S PIRNAGAR W/S/S TARAPUR (KALAIN) W/S/S MAJENTA T.E. W/S/S SINDURA CHA BAGICHA W/S/S KHELMA PT V W/S/S KHELMA PT-VII W/S/S KHELMA W/S/S BAISHNABPARA W/S/S BURARAIYARPAR W/S/S KALINAGAR (KHELMA) W/S/S KARACHURA W/S/S BICHITRAPUR W/S/S KURKURI PT-III W/S/S KURKURI PT-IV W/S/S BATULMARA W/S/SCHEME JALALPUR W/S/SCHEME BISWAMBARPUR W/S/S KUSHIARKUL W/S/S BOROITOLI W/S/S LAKHIPUR W/S/S BOROITOLI PT-II W/S/S DASPARA W/S/S DURGANAGAR W/S/S MAHADEVPUR PT- II W/S/S SRINAGAR W/S/S SARASPUR W/S/S 4 NO. RAJPUR W/S/S NILAM BASTI W/S/S DIGORKHAL W/S/S GOBINDAKUPA W/S/S PAIKAN W/S/S SEUTI PT-IV W/S/S LAMAR DUDPUR W/S/S ANANDAPUR W/S/SCHEME PASCHIM KADAMTOLA W/S/SCHEME NIZ-FULBARI W/S/S SRIPUR W/S/S GOBINDAPUR W/S/S KALACHANDBARI W/S/S LATHGRAM W/S/S PURBA GOBINDAPUR W/S/S SCHEME SIBNARAYANPUR W/S/S HARINAGAR W/S/S HARINAGAR PT-II W/S/S CHANDINAGAR PT-III W/S/S CHANDINAGAR PT-IV W/S/S CHANDINAGAR PT-VI W/S/S HARINAGAR PT-IV W/S/S NIZ-HARITIKAR W/S/S TUKERGRAM (KATIGORAH) W/S/S ANDHARIRPAR W/S/S JAGADISHPUR PT-V W/S/S JAGADISHPUR W/S/S LATHIMARA W/S/S NIZ KATIGORAH W/S/S JAGADISHPUR PT-II W/S/S MOHANPUR W/S/SCHEME GANGAPUR W/S/S MAZIRBEEL W/S/S GOALNAGAR (KHELMA) W/S/S KANDIGRAM W/S/S CHANDINAGAR PT I & V SAIDPUR PT-III W/S/S SALIMABAD W/S/S VOTERCHAK W/S/SCHEME KOROIKANDI W/S/S MADURPAR W/S/S NAZATPUR W/S/S RAJATILLAH W/S/S TELITIKAR W/S/S NIZ-KATIGORAH PT-II W/S/S JAGADISHPUR PT-IV BOALIKHALERPAR W/S/S submerged as per report received from PHE Silchar Division, as on dated 02.07.2022,

Inland Water Transport Deptt. Damaged | Sidheswari Ferry Service, Lathimara Ferry Service, Buribail Ferry service, Rajnagar Ferry Service, Rajatilla Ferry Service, Gangapur Ferry Service, Silghat Ferry Srvice, approch road of Ferry Services both side fully damaged & wooden landing stage washed out, as per the report received from IWT, Cachar as on dated 30.06.2022,

Fisheries/Pond | Total 254 Water Area affected (HA) & Total 1140 No of Fish Farmer affected as per the report received from Fishary Deptt Cachar as on dated 01.07.2022

Chirang

Bijni - Irrigation Canal/Scheme Damaged | As reported by Bijni Sub Division,Irrigation department, embankment of the upstream right side about 8 mtr of Dimajhora FIS breached by flood water on 23-06-2022 at Dimajhora. Length=8 mtr Breadth=3 mtr Depth=3.20 mtr Longitude=90.637183 Latitude=26.621827 Latitude=, Irrigation Canal/Scheme Damaged | As reported by Bijni Sub Division,Irrigation department, portion of the main earthern canal of Gelajhora boulder Weir FIS damaged on 23-06-2022 at Dutangpara. Length=20 mtr Breadth=3

Bengtal - Elementary Schools Damaged | 682 No. Sishubari LP School severely damaged due to erosion activity of Nangal river on 28-06-2022 Lat-26.623823 Long-90.548693

mtr Depth=3.10 mtr Longitude=90.602803 Latitude=26.59676,

Dalgaon - Bridge Approach Road Damaged | as per report received from dalgaon territorial road sub division rain cut and damaged has been occurred at approach of RCC Br No. 3/1 at simaluguri mazgaon to daipam road about (1.5mx1.3m). Date of occurrence - 16/06/2022,

 $Handloom \& Textile \ Deptt \ | \ as \ per \ report \ received \ from \ Handloom \& \ Textile \ department, \ total \ 20 \ nos \ of \ weaver \ affected \ under \ dalgaon \ revenue \ circle \ as \ on \ 27/06/2022,$

Anganwadi Centres Affected | another 10nos of AWCs damaged has been reported by CDPO, pub mangaldai ICDS on 02/06/2022,

Bridge Approach Road Damaged | as per report received from PWRD Br No. 1/1 both approaches eroded(578m to 580m east approach) and (598m to 608m west approach) date of occurrence - 16/06/2022,

Power Dept. Poles | as per report received from SDE, APDCL, Kalaigaon, Kharupetia, Mangaldai and Mazbat sub division total mazbat-33nos, kharupetia - 19nos, kalaigaon - 13 nos and mangaldai - 18 nos of pole damaged due to flood on 16-06-2022 to 29-06-2022,

Power Dept. Conductors | as per report received from SDE, APDCL, Kalaigaon, Kharupetia, Mangaldai and

Darrang

Mazbat sub division total mazbat-13.2km, kharupetia - 6.9km, kalaigaon - 12.8km and mangaldai - 5.3km conductor damaged due to floodon 16-06-2022 to 29-06-2022, Power Dept. Transformers | as per report received from SDE, APDCL, mazbat sub division 1 no of transformar damaged due to floodon 16-06-2022 to 29-06-2022, Mangaldoi - Anganwadi Centres Affected | as reported by district social welfare office on 02-7-2022, Total 99 anganwadi centres were affected /damaged during flood 2022., Sericulture Deptt. Damaged | A total 174 nos farmers were affected .occurrence date 30/06/2022, Patharighat - PWSS Damaged | 10 nos of PWSS scheme damaged/affected by flood as reported by JE PHE on 02/07/2022 namely 1. Niz Sarabari PWSS 2. Katahi PWSS 3. Santipukhri PWSS 4. Athiabari PWSS 5. Namkhola PWSS 6. Deomornoi PWSS 7. kaikara PWSS 8. Potapukhri PWSS 9. Athkuria PWSS 10. saloipara PWSS (pipeline damaged), Anganwadi Centres Affected | in total overall 16 nos. of AWC affected as reported by CDPO, Patharighat on 02/07/2022, Fisheries/Pond | In total 4700 nos. of pond measuring 380 Ha of water area affected as reported by Fishery Dev. Officer on 02/07/2022, Sericulture Deptt. Damaged | A total 68 nos farmers were affected .occurrence date 30/06/2022, Sipajhar - Fisheries/Pond | 2610 nos. of Fish farmers abd 265 Hectre of watre area affected as reported by Nodal Officer, Fishery Department. occurrence date 26/06/2022, Handloom & Textile Deptt | A total 26 nos. weavers were affected. occurrence date 26/06/2022, Sericulture Deptt. Damaged | A total 622 nos farmers were affected .occurrence date 30/06/2022 Bilasipara - Power Dept. Conductors | L.T:- 2.1 and HT:- 13 DATE- 14/06/2022 TO 18/06/2022, Power Dept. Transformers | 12 no's DATE- 14/06/2022 TO 18/06/2022, Power Dept. Poles | L.T:- 8 and HT:-6 DATE- 14/06/2022 TO 18/06/2022, Dhubri Athani - Power Dept. Poles | 8.5 M PSC POLES-24, 7.5 M PSC POLES-6 DATE-16/06/2022 TO 25/06/2022, Power Dept. Conductors | CONDUCTOR 2.6 KM DATE-16/06/2022 TO 25/06/2022, Power Dept. Transformers | TRANSFORMER-4, DISC AND PIN-45+40, CHANNEL-16, T CROSS ARM-19 DATE-16/06/2022 TO 25/06/2022 Golaghat **Bokakhat** - Fisheries/Pond | 0.4 hect of water area got affected on 01.07.2022 Algapur - Irrigation Canal/Scheme Damaged | Scheme Name- PMKSY STW- HKKP-PH-II, Solar Panel damaged at vill- Uttar Kanchanpur Pt-II Long- 92.601746 Lat- 24.837596 under Algapur Rev. Circle dtd. Hailakandi Irrigation Canal/Scheme Damaged | Scheme Name- PMKSY STW- HKKP-PH-II, Solar Panel damaged at vill-Bakrihaware Pt-II Long- 92.607928 Lat- 24.826666 under Algapur Rev. Circle dtd. 29.06.2022 Lanka - Elementary Schools Damaged | Siv Mandir New LP School, Lat 25.883883, Long 92.877833, Sri Kapileswar Nath LP School, Lat 25.881583 Long 92.8668 Damaged On 16/05/2022, **Doboka** - Power Dept. Poles | Total 70 nos. of electrical ploes damage on 19/6/22 under village of Pub Bagari, Baliram Pathar, Borjari Gaon, Jamunamukh, Nam Doboka ,Pub Jugijan, Hojai - Road Breaches | Radhanagar GP-Construction of CC block road from PMGSY road to Nilratan Mazumder house 26.06441864 92.79984295 "Construction of road cum bundh from Nimai house to Mangalem house via. Tumpreng road Work code; - 0413008/FP/9010266547" "25.998568 92.805133" damage as on dated Agri Bundh Damaged | Hayang GP-"Const. of Agril bundh from Kalimohan Bhowmick House to Nepalikhuti PMGSY road Work Code: -0413008/FP/9010268300" "Const. of Agril Bundh From Sanit Biswas house to Kalimohan house Work Code :-0413008007/FP/GIS/91292" "Const. of Agril Bundh From Mubarak Ali house to Mainul Haque Borbhuyan house at Solmari Work Code :-0413008007/FP/GIS/90680" "Bundh at Solmaritop parghat near Sikandar and Amir Uddin house. Work Code :-"damage as on dated 16/6/22, Agri Bundh Damaged | Borpukhuri -Construction of cum bund from 4m Rajapukhuri main road to Gopalnagar GP border. (0413008003/FP/9010248105) Construction of cum bund from Mithun biswas house to Prakash Biswas house.(0413008/FP/9010267092) Construction of cum bund from Abdul kalam house to Kandulimari GP border Phase-2 (0413008003/FP/GIS/88495) Construction of cum bund from Gaon bura house to Abdul Latiff house.(Fp/9010269704)damage as on dated 16/6/22, Hojai Agri Bundh Damaged | Pub Dhaniram Pathar-"Const. of Agril bundh from Sri Hari Krishna house to Yusub Ali house Work Code :-0413011/FP/9010268299"damage as on dated 16/6/22, Agri Bundh Damaged | Barafuti GP-Const of Agril bundh from Islam Uddin house to Abdul Sattar house (0413008009/FP/9010266824) AP Const of Agril bundh from Abdul Jalil house to Abdul Jabbar house(0413008009/FP/GIS/91256 Construction of bundh from Abdul Matlib house to Jamir Hussain house (0413008/FP/9010250606) Construction of agril bundh from Rafiqul Islam house to Ramjan Ali house (0413008009/IC/9010241621) " 0413008/FP/9010266959 Const of Agril bundh from Amsar Uddin house to Prasanna Biswas house via Adhar Mallick land" "0413008009/FP/GIS/91251 GP Const of Agril bundh from Bajal Uddin house to Taher Ali house" "0413008009/FP/GIS/91249 GP Const of Agril bundh from Pub Jugijan CC block road to Sadikul Islam house"damage as on dated 16/6/22, Agri Bundh Damaged | Kandulimari-"0413008008/FP/GIS/90979 GP Const of Agril bundh from Jamal Uddin house to Allauddin house w 2" "0413008008/FP/9010267415 GP Const of Agril bundh from Fakar Uddin to Babul Biswas house at Jugirper" "0413008008/FP/GIS/88378 GP Const of Agril bundh starts from Fuja Mulla house to manuwara Begum house via. Mikir Bari" damage as on dated 16/6/22, Agri Bundh Damaged | Radhanagar- 0413008006/FP/GIS/89874 Const of Agril bundh from PMGSY house to Nadu Chauhan house " 0413008008/FP/901266962 GP Const of Agril bundh from Dharmendra Chauhan house to Jimma nalla"damage as on dated 16/6/22, Agri Bundh Damaged | Rajbari-0413008005/FP/9010266942 Const of Agril bundh from Sujal Sorang land to

Nibaran Raijung Tinali " 0413008005/FP/GIS/91230 Const of Agril bundh from Krishna mandal house to PWD Tinali" 0413008005/FP/GIS/91362 Const of Agril bundh from PMGSY road to Bolaram Das house Const of Agril bundh from Mathura Bazar Tinali to Kenduguri Sivpur Tinali "Const of Agril bundh from Parghat to Hariyali ID no 0413008005/FP/90102527" (Const of Agril bundh from Bhuban Das house to PMGSY road) ID No. 0413008005/FP/GIS/91633 Const of Agril bundh from Nanan Hasnu house to Dutilal land ID no 0413008005/FP/GIS/91629damage as on dated 16/6/22, Protection Bundh Damaged | Hayang GP & Rajbari GP-"Flood protection bundh from Hayong GP office to Warigedeng Choigari Community Hall Work ID :- 0413008007/FP/9010267413" 0413008005/FP/9010266909 Const of Flood Protection bundh from PMGSY road to Amtola damage as on dated 16/6/22, Fisheries/Pond | Hayang GP & Barafuti GP Const of Community Fishary at Hayang Basti Smashan, Const of Community Fishary at Hayang Basti Smashan damage as on dated 16/6/22, Power Dept. Poles | Total 81 nos of electrical poles damaged as on 16/06/22 under village of Komorakata, Bishnupur, Raikata Kachari Gaon, Kenduguri, Dakhin Laskar Pathar Jorhat West - Protection Bundh Damaged | due to last few days rise in the water level of River Brahmaputra, the Upstream of Bull Head-I of hatisal-Neamati Protection Works was eroded at a strip of 15 m width for a length of 450 m. Reported by: UAI (WR) Division, Jorhat. Date: 01/07/2022. Lat: 26.862309 Long: 94.237855, Jorhat Protection Bundh Damaged | due to last few days rise in the water level of River Brahmaputra ,the downstream of Spur No-VIII was eroded at a strip of 5 m width for a length of 250 m. Reported by: UAI (WR) Division, Jorhat. Date: 01/07/2022. Lat: 26.827164 Long: 94.164523 Chamaria - PWSS Damaged | Kahibari source development, site development, approach road damaged on dated 2.07.2022 and the same has been reported by JE, PHE, Boko Sub-Division on dated 2.07.2022, PWSS Damaged | Choudharypam distribution pipeline, internal foothpath, DTW development damaged on dated 2.07.2022 and the same has been reported by JE, PHE, Boko Sub-Division on dated 2.07.2022, PWSS Damaged | Dekachang and Dekachang Bazar source development and site development damaged on dated 2.07.2022 and the same has been reported by JE, PHE Boko Sub-Division on dated 2.07.2022, PWSS Damaged | Sontoli Satra site development damaged on dated 2.07.2022 and the same has been reported by JE, PHE Boko Sub-Division on dated 2.07.2022, PWSS Damaged | Goroumari Bilorjan source development, site development, distribution pipeline, FHTC damaged on dated 2.07.2022 and the same has been reported by JE, PHE Boko Sub-Division on dated 2.07.2022, PWSS Damaged | Arikati source development, site development damaged on dated 2.07.2022 and the same has been reported by JE, PHE Boko Sub-Division on dated 2.07.2022, PWSS Damaged | Kismat kathmi source development, site development damaged on dated 2.07.2022 and the same has been reported by JE, PHE Boko Sub-Division on dated 2.07.2022, Rangia - Health Sub-Centre | Udiana Sub Centre in vill- Udiana was partially damaged on 17.6.2022 as per report submitted by SDM&HO, Rangia., Health Sub-Centre | Kekohati Sub Centre in vill- Kekohati was partially damaged on 17.6.2022 as per report submitted by SDM&HO, Rangia., Health Sub-Centre | Paschim Sitara Sub Centre in vill-Paschim Sitara was partially damaged on 17.6.2022 as per report submitted by SDM&HO, Rangia., Health Sub-Centre | Titkuri Sub Centre in vill- Titkuri was partially damaged on 17.6.2022 as per report submitted by SDM&HO, Rangia., North Ghy - Public Health Centre (PHC) | 44 Nos. of Piped Water Supply Scheme affected on 17/06/2022 as reported by Asstt. Executive Engineer (PHE), Hajo PHE Sub-Division on dated 02/07/2022., Hajo - PWSS Damaged | Kailashpur PWSS, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, Kamrup PWSS Damaged | 2No. Bamundi PWSS, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Panditor Pam,FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | No.1 Ganakpara PWSS, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Bhelkar, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | No. 2 Solmari, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Topabari, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Banglapara, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | 2No. Barni, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Hablakha, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Dongarpar, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Khalihamari, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Dampur, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Bala Suba, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Kumarpara, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Niz Hajo, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Saktibari, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Fakirtola, Transformer damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Hajo Madhab, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Panipara, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Barchapari, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Barahtola, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Dakhin Singra, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Kumarpur, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Kowarpur, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Patani, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1,

PWSS Damaged | Sarabori, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Kalitakuchi, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Khupnikuchi, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Rajabajar, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Mokhania, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Ketekibari, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Ukhura, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Helesa, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Niz Ukhura, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Tetelia No. 1, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Muslim Suba, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Sanpara Grant, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Tukradia, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Khetri Hardia No. 1, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Subanshah, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Tanganmari, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Sanpara Grant No. 1, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Abhoypur, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Baragaon, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Gerua No. 1, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Bardadhi, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1, PWSS Damaged | Damdama, FHTC damaged on 18-06-2022 as reported by PHE, Ghy Div-1 Nilambazar - Power Dept. Poles | As reported by SDE, APDCL, Nilambazar dated on 01/07/2022 that due to flood 42 Nos. of LT Poles and 30 Nos. HT Poles at 62 affected location got damaged., Karimganj - Bridge Approach Road Damaged | KATAKHAL ON LC ROAD BRIDGE NO.2/1, BOTH SIDE OF BRIDGE APPROACH IS DAMAGED. LAT 24.844423 LONG 92.343526. WT MESSEGE WAS SENT BY ASST.EXECUTIVE NGINEER/PWRD, KARIMGANJ ON 30/06/2022, Secondary Schools Damaged | DUE TO RECENT FLOO MMMC GIRLS HS SCHOOL WAS PARTIALLY DAMAGED FLOOR, WALL, TOILET. THE REPORT WAS SUBMITTED BY PRINCIPAL OF MMMC GIRLS HS SCHOOL ON 02/07/2022., Badarpur - Power Dept. Poles | As per report submitted SDE, APDCL Badarpur, dated. - 01/07/2022, 21 Karimganj (Twenty one) nos. of LT Poles, 20 (Twenty) nos. of HT poles, have been damaged due to flood w.e.f 16/06/2022 to 19/06/2022. Also report of 08 (eight) nos. of Tilted L.T poles and 11 (eleven) nos of H.T poles has also been reported., PWSS Damaged | As per report submitted by AEE, PHE Badarpur Sub-Division, dated. - 01/07/2022, the boundary wall of Sheralipur PWSS has been damaged also damage of Raw Water DISS and UPVC pipe line of about 900 mtr. With PSC Electric pole of 7 nos have been damaged at Madanmohan PWSS and Sheralipur PWSS. Total 02 nos. of PWSS damage has been reported., Secondary Schools Damaged | As per report submitted by Headmaster, Ghoramara High School, dated. 01/07/2022 the damage of floor of rooms, partial sliding of soil from Vit of School building and partial damage of School path as been reported due to flood. The Latitude of the school is -24.814769 and Longitude is 92.443178 Gossaigaon - Damaged SPT Bridge | AS PER REPORT RECEIVED FROM GOSSAIGAON MUNICIPAL BOARD, GOSSAIGAON ON 01.07.2022 REPAIRING OF SAMSAN KHOLA WOODEN FOOT BRIDGE ON MODATI RIVER CONNECTING TO WARD NO.2 & 4 (NEAR GIRIDHARI ASHRAM) AT GOSSAIGAON TOWN, Damaged SPT Bridge | AS PER REPORT RECIVED FROM GOSSAIGAON MUNICIPAL BOARD, Kokrajhar GOSSAIGAON ON 01.07.2022 REPAIRING OF WOODEN FOOT BRIDGE ON MODATI RIVER CONNECTING TO WARD NO.2 & 3 (NEAR ANANTA KUTIR L.P. SCHOOL) AT GOSSAIGAON TOWN, Damaged SPT Bridge | AS PER REPORT RECIEVED FROM AEE, PWD KACHUGAON RURAL ROAD SUBDIVISION ON 30.06.2022 DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 14TH JUNE 2022 TO TILL TODAY RESTORATION OF THAIGIRGURI WOODEN BRIDGE Bihpuria - Handloom & Textile Deptt | Weaving equipment of 2 nos. of weaver have been affected on 02/07/2022 at village Rangajanas reported by Demonstrator, Handloom & Textile, Bihpuria circle, North Lakhimpur - Anganwadi Centres Affected | Naharani Nepali Khuti AWC, Ghancharai AWC, 1 No. Ghancharai Mini, Magurmari Mising, Kandalipur AWC, Telia Pathar, AWC, Barengolia Gohain Chuk, Falakhuwa AWC, Balipathar Chapori Santipur AWC, Pub Bocha AWC, 2 No Haldhiati AWC all are Partially Affected as per report received from CDPO Telahi on 01-07-2022., Anganwadi Centres Affected | Angerkhowa AWC, Maluwal Santipur AWC, Pachim Nepali Karatipar AWC, Maluwal Kathapukhuri AWC, Maluwal Missing AWC, Bamungaya, AWC, Uttar Bamungaya AWC, Amtola Bongaon AWC, Pokadol AWC, Duargaon, Balijan Chambari AWC all are Partially Affected as per report Lakhimpu received from CDPO Telahi on 01-07-2022., Anganwadi Centres Affected | Pakania Bahguri AWC, Gorchiga Bahguri AWC, Bordubi Moluwal AWC, Mohorichuk all are Partially Affected as per report received from CDPO TelahiAWC, Chengmari Chapori AWC, Dharmapur AWC, Mudoibil Bakalchuk AWC, Alichiga AWC, Bordubi Channong AWC as per report received from CDPO Telahi on 01-07-2022., Anganwadi Centres Affected | Gutung Na-Ali AWC, Angonibari AWC, Tekeliphuta AWC, Manku Chapori AWC, Ghagarmukh Baligaon AWC, Bazar Patty Baligaon Mini AWC, Morton Chapori AWC, all are Partially Affected as per report received from CDPO Telahi on 01-07-2022., Anganwadi Centres Affected | Ujani Mortonchapori AWC, Namoni Rajabura AWC, Rajabura AWC, Rajbura

Kangkan Chapori AWC, Mukpichuk AWC, 9 No. Guli Achen AWC, Purani Dhala/Dhala Miri AWC, Purani Dhala Paken AWC, all are Partially Affected as per report received from CDPO Telahi on 01-07-2022.,

Anganwadi Centres Affected | Tamargaon AWC, Tamar Chapori AWC, Dafalakata Simaluguri AWC, Dafalakata Silikhaguri AWC, Ghuli Gaon AWC, Munindra Chuk Ghuligaon, Namoni Asserakata Mohorichuk AWC, Joyram Chuburi Mini, AWC, Ujani Asserakata AWC, all are Partially Affected as per report received from CDPO Telahi on 01-07-2022.,

Anganwadi Centres Affected | Kurimari AWC, Gamchuk Simaluguri AWC, Simaluguri Purnima AWC, Gamchuk Ujani AWC, Jengrai Singimari A AWC, Jengrai Singimari (B) AWC all are Partially Affected as per report received from CDPO Telahi on 01-07-2022.,

Anganwadi Centres Affected | Ujani Balijan AWC, Asserakata Madhya Balijan (M) AWC, Santipur AWC, Gowalbari Sialchapori AWC, Ujani Gowalbari AWC, Majarchapori AWC, Ujani Majarchapori AWC all are Partially Affected as per report received from CDPO Telahi. on 01-07-2022,

Power Dept. Poles | 8.5 meter 10 Nos as per report received from APDCL, North Lakhimpur Divn. on 01-07-2022,

Power Dept. Poles | 7.5 meter 21 nos as per report received from APDCL, North Lakhimpur Divn. on 01-07-2022.

Power Dept. Conductors \mid 3.9 Conductor as per report received from APDCL, North Lakhimpur Divn. on 01-07-2022 ,

Anganwadi Centres Affected | Balibheta AWC, Gudabori Tup AWC, Uriamtola AWC, Modhupur Borchapori AWC, Borchapori AWC, Simaluguri AWC, No 1 Naharani Missing, AWC, Nachil Chuk AWC, Naharani AWC, Ghunasuti Jamuguri AWC, Namoni Karhachapori AWC, Bandarkata, 9/6 Koilamari AWC, Ampara AWC, Borbil Narayan Puria AWC, Borbil Majorchaporoi AWC, 9/6 Koilamari Balichapori MINI AWC all are Partially Affected as per report received from CDPO Lakhimpur on 01-07-2022,

Narayanpur - Culvert Approach Road Damaged | on 28/06/2022 Construction of Earthen Pheripherial Bundh from Ananda Borah chuburi to Lakhipur pather.1 Nos RCC Culvert fully Damage and 100 mter Road as per report from panchayat,

Washed away Culverts | on 28/06/2022 Const. of Egri bundh at Aniruddha chuburi to Sarbeswar Thakuria chuburi.on 26/06/2022 1 Nos RCC Culvert fully Damage .as per report of panchayat,

 $Agri\ Bundh\ Damaged\ |\ on\ 28/06/2022\ Const.\ of\ Flood\ control\ bundh\ Karbi\ chuburi\ to\ Dihiri\ .\ Earth\ filling\ fully\ Damaged,$

Washed away Culverts | on 28/06/2022 H P Culvert at Das chuburi Fully Damaged Const. of RCC Culvert at Moni gogoi chuburi to Deka gaon. RCC Culvert Fully Damaged Const. of RCC Culvert at Dhemagarh to Balipather link Road. RCC Culvert Fully Damaged Const. of RCC Culvert at Gohain Chuburi RCC Culvert Fully Damaged,

Agri Bundh Damaged | on 28/06/2022 Const of Agri bundh at Bhuyan Tiniali to Ramaji Const. of Road at Dharamgarh Sewashram to Gopalpur Hari mandir. Earth feeling fully Damaged . Const. of Earth feeling at Atul Phukan Chuburi to Joishing Pather. Earth Feeling Dammaged 500 meter. Tiniali Earth feeling fully Damaged ., Agri Bundh Damaged | on 28/06/2022 Const. of Agri bundh at Gohain chuburi to Haren Chuburi. RCC Culvert and Earth feeling Fully Damaged Const. of Earth feeling from Simaluguri to Rampur Bhyaya Dolopabari. 2 Meter Damaged,

Agri Bundh Damaged | On 28/06/2022 Const. of Feriferial bundh from Bishnupur to Gaon burha Chuburi . Fully Damaged Const. of Agri bundh from Padmeswar Lahan chuburi to Padma Hazarika chuburi . Fully Damaged Const. of gali control bundh at Jadab Gogoi Chuburi. Dammaged,

Washed away Culverts | On 28/06/2022 Const. of RCC Culvert at Kamalpur RCC Culvert Fully Damaged Const. of RCC Culvert at No 2 Rampur to Jalukata Road. RCC Culvert Fully Damaged Const. of RCC Culvert at No 2 Rampur to Pahukata. RCC Culvert Fully Damaged,

Bridge Approach Road Damaged \mid on 28/06/2022 Const. of Road from Sunajuli centre to Rampur link road. Bridge side Damaged 100 meter,

Agri Bundh Damaged | on 28/06/2022 Const. of earthen Peripheral Bundh from Geleki Harimandir to Nitananda Chuburi 100 M Const. of earthen Peripheral Bundh from Dibrual/Chutia to Raja Chuburi 100 M Const. of earthen Peripheral Bundh from Rangapani to Jorhatia Pichala river of Diburual Gaon side Raja 100 M Const. of earthen Peripheral Bundh from Dibrual Pathar to Kamal Gogoi via ananda Ligira Chuburi 150M Const. of earthen Peripheral Bundh for Budhindra Gogoi Chuburi 100M Earthen Check Dam at Sessa river Major doloni 300M Const. of earthen Peripheral Bundh at Santipur near pichala river 200M Const. of earthen Peripheral Bundh from Dhalpur Majgaon tiniali to Satya Bora Chuburi 100M Const. of earthen Peripheral Bundh from Rangati Arimora PWD to Phutabhog Rangajan via Rajabari L/R 200M Const. of earthen Peripheral Bundh from Chutia Gaon Bridge to Raja Chuburi 100M,

Culvert Approach Road Damaged | on 28/06/2022 Const. Culvert at Pachim Nidanchuwa Under 15th FFC Wing wall 2 Nos Const. Culvert at Nidanchua under 14th FFC Wing wall 2 Nos Const. Culvert at Bhitordoloni under 14th FFC 2 Nos wing wall with approch road Const. Culvert at Bhitordoloni under 15th FFC Narayanpur Anchalik Panchyat 2 Nos wing wall with approch road Const. Culvert at Phutabhog under 15th FFC 2 Nos wing wall with approch road

Majuli

Majuli - Washed away Culverts | Culvert on Bhugpur Pomua road expired on 02-07-2022 (constructed in 2010-2011). Lat - 26.966006, Long- 94.211036,

PWSS Damaged | Bebejia new PWSS submerged on 01-07-2022 (distribution pipelines are under water in Sarighoria, Ukholchuk, Kulichapori)

Morigaon

Mikirbheta - Fisheries/Pond | As per report by DFDO, Morigaon on 02/07/2022, 392 ponds, 65.97 water area affected due to flood under Bhakatgaon, Barbhagia, Charaibahi and Jaluguti GP., Sericulture Deptt. Damaged | As per report by Asst. Director of Sericulture, Morigaon on 02/07/2022, Charaibahi

Circle, 1.3 hec effected area (Castor 2500, akesseru 500), Jaluguti Circle, 2.5 Hec effected area (Castor 320, Kesseru 700), Morigaon - Fisheries/Pond | As per Fishery Dev. Block (Mayong), dtd.02-07-2022, Total farmer affected=1 nos, Total pond affected= 1nos., Water area affected= 4bigha at Village= Dekagaon, Fisheries/Pond | As per Fishery Dev. Block (Bhurbandha), dtd.01-07-2022, Water area affected= 4Hectare, Total pond affected= 30 nos., at Jurgaon (Azarbari GP), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture (Morigaon), dtd. 02-07-2022, Name of the Farm/Centre= ESG, OUJARI, Affected area=0.5, No. of plants= Castor(400nos.), Kesseru(150nos.), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture (Morigaon), dtd. 02-07-2022, Name of the Farm/Centre= ECC, NELLIE, Affected area=1.5, No. of plants= Castor(2000nos.), Kesseru(450nos.), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture(Morigaon), dtd. 02-07-2022, Name of the Farm/Centre= MFPC,LUKAKUCHI, Affected area=1.0, No. of plants= Castor(1300nos.), Kesseru(400nos.), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture(Morigaon), dtd. 02-07-2022, Name of the Seri Circle= Morigaon, Affected area=2.5, No. of plants= Castor(3000nos.), Kesseru(500nos.), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture(Morigaon), dtd. 02-07-2022, Name of the Seri Circle= Oujari, Affected area=2.3, No. of plants= Castor(2800nos.), Kesseru(600nos.), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture(Morigaon), dtd. 02-07-2022, Name of the Seri Circle= Lukakuchi, Affected area=5.0, No. of plants= Castor(8000nos.), Kesseru(1200nos.), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture(Morigaon), dtd. 02-07-2022, Name of the Seri Circle= Silsang, Affected area=3.0, No. of plants= Castor(3500nos.), Kesseru(700nos.), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture(Morigaon), dtd. 02-07-2022, Name of the Seri Circle= Nellie, Affected area=3.5, No. of plants= Castor(4000nos.), Kesseru(800nos.), Sericulture Deptt. Damaged | As per Asstt. Director of Sericulture(Morigaon), dtd. 02-07-2022, Name of the Seri Circle= Ahotguri, Affected area=1.6, No. of plants= Castor(2000nos.), Kesseru(450nos.), Bhuragaon - PWSS Damaged | Bordooba tup PWSS Distribution System, Deep Tube Well on 19-06-2022, Public Health Centre (PHC) | Running water system along with pumping motor on 30-06-2022 Nagaon - Handloom & Textile Deptt | Looms & accessories, Total-17 Nos. Submerged/damaged reported by Handloom & Textiles, Department, Nagaon, Dated-02/7/2022, Handloom & Textile Deptt | Warp & Yarn ,Total-44 Nos. Submerged/damaged reported by Handloom & Textiles, Department, Nagaon, Dated-02/7/2022, Kampur - Irrigation Canal/Scheme Damaged | Submerge Transformer Sub Station along with pump motor, Control Room & damaged Brick lined main and Branch Canal. Deurigaon-Kathiatoli Lift Irrigation Scheme, Hose Pipe: 2 Right Sub Canal= 5m, Left Sub Canal=10m Control Room repair= 1 Job, Wire Rope= 2 Nos on dated 01.07.2022 reported by Irrigation Department Raha Sub Division, Raha Nagaon., Irrigation Canal/Scheme Damaged | Submerge Transformer Sub Station along with pump motor, Control Room & damaged Brick lined main and Branch Canal. Saraihagi Pt. No. 3 Lift Irrigation Scheme, Hose pipe= 2 No, Sub Canals= 50m, Armoured Cable=150m, wire Rope=2Nos, Cut out 200 Amps=2 Nos, on dated 01.07.2022 reported by Irrigation Department Raha Sub Division, Raha Nagaon., Irrigation Canal/Scheme Damaged | Submerge Transformer Sub Station along with pump motor, Control Room Nagaon & damaged Brick lined main and Branch Canal. Saraihagi Pt No. 4 Lift Irrigation Scheme, Hose Pipe=1 No. Main Canal=10m, Canal Bed=20m, Wire Rope=2 Nos, Armoured Cable=55m, Cut Out 200Amps=3 nos, Barge Roof=1 Job on dated 01.07.2022 reported by Irrigation Department Raha Sub Division, Raha Nagaon., Irrigation Canal/Scheme Damaged | Submerge Transformer Sub Station along with pump motor, Control Room & damaged Brick lined main and Branch Canal. Dakhin Changchaki Lift Irrigation Scheme, Hose pipe=1 No, Main Canal bed=30m, Sub Canal wall=40m, Wire Rope=2 Nos, Anchor=1 No, Cut Out 200 amps=3 Nos, armoured Cable=50mtr, on dated 01.07.2022 reported by Irrigation Department Raha Sub Division, Raha Forest Deptt, Damaged | Sahitya Mohishi Udyan (Borpani Forest Area) 3 hectre 5% damage, Aromatic Medicine Plantation: 3 h 5% damage, Changkhola Plantation: 40h 10% damage as reported by Environment & Forest Dept. Kampur on dated 01.07.2022, Raha - Anganwadi Centres Affected | 30 nos. of Anganwadi Centres were submerged on 30/06/2022 reported by Social Welfare Nagaon Paschim Nalbari - Culvert Approach Road Damaged | Damage of slab culvert at Panigaon. Information received Nalbari from PWRD Department 0n 02/07/2022 Thelamara - Power Dept. Conductors | As reported by Sub divisional Engineer, Dhekiajuli Electrical Sub division II, Dhekiajuli on 01/07/2022, 0.82km of conductors along with 33KV Pin-27, channel cross arm-4, stay set -4, 33KV "V" cross arm 9, top cleat 9 of village Gabharupar has been damaged., Power Dept. Conductors | As reported by Sub divisional Engineer, Dhekiajuli Electrical Sub division II, Dhekiajuli on 01/07/2022, 1.5 km of conductors along with 33KV Pin-52,33KV "V" cross arm 14, Top cleat 14, channel cross arm-2, stay set -2 of village Baligaon has been damaged., Power Dept. Poles | As reported by Sub divisional Engineer, Dhekiajuli Electrical Sub division II, Dhekiajuli on Sonitpur 01/07/2022, 9 poles of village Gabharupar, 14 poles of Baligaon and 2 poles of Borbil Gaon has been damaged., Power Dept. Conductors | As reported by Sub divisional Engineer, Dhekiajuli Electrical Sub division II, Dhekiajuli on 01/07/2022, 0.1 km of conductors along with 11 KV Pin-6, channel cross arm 1, stay set 2 of village Borbil gaon has been damaged., Chariduar - Culvert Approach Road Damaged | BOX CELL CULVERT APPROACH ON GHOGORA TE TO TUMUKI ROAD CULVERT NO 1/3 DTD 02/07/2022, Culvert Approach Road Damaged | GHOGORA TE TO TUMUKI ROAD SLAB CULVERT APPROACHES OF CULVERT NO 1/1 AT CH 70.00 M & BOX CELL CULVERT APPROACH OF CULVERT NO 1/3 AT CH

		750 00M DTD 00 07 000
		550.00M DTD 02/07/2022, Protection Bundh Damaged DIPOTA RIVER, PAHIJULI RIVER, BISHNURABHA ROAD BALIKA VIDYALAYA, HINDUGAON ROAD, SAMSHANGHAT ROAD, UNDER REVENUE CIRCLE PROTECTION WORK OF RIVER BANK DTD 02/07/2022,
		Anganwadi Centres Affected BAURI BASTI AWC UNDER BORJULI GP AND RANGAPARA ICDS PROJECT DTD 02/07/2022
		Tamulpur - Elementary Schools Damaged As report received on dated 02-07-2022, Charanjangal Bathou LP School was partially damaged,
	Tamulpur	Elementary Schools Damaged As report received on dated 02-07-2022, Adarsha Milan ME School was found partially damaged.
		Elementary Schools Damaged As report received on dated 02-07-2022, Gowalbil LP School was found partially
	Udolovei	damaged. Udalguri - Irrigation Canal/Scheme Damaged As reported by Irrigation Department on 02.07.2022, Breach of canal embankment at Ch. 1980 M of K3D1B1M Canal around 10m at Mahaliapara village on 20.06.2022. GPS - Lat - 26.652917 Long - 92.2254055, Walkinger PWSS Democrat 6 pumplers of PWSS democrat at village Come Polyraiber Phahaguri Niz Dela
	Udalguri	Kalaigaon - PWSS Damaged 6 numbers of PWSS damaged at village Gerua, Bokrajhar, Bhehuguri, Niz Dala, Balipara, and Khas Ranthali as reported on 02/07/2022. Longitude and Latitude are respectively, 91.985647, 26.546238, 92.025412, 26.658721, 91.998587, 26.672458, 91.889752, 26.666541, 91.789542, 26.354852, 92.0007451, 26.579862
	District	Details
	Bajali	Bajali - Erosion at the Kaldiya river near Bhupen Das house to Rajhuwa smachan at Chaibari Adhikari ghat Erosion at the Kaldiya river near Bhupen Das house to Rajhuwa smachan at Chaibari Adhikari ghat .affected length 200 m breadth 10m depth 10m on 02/07/2022 0
	Barpeta	Barnagar - Gamariguri As per received from Water Resources Dept, Sorbhog on 30/06/2022 At Gamariguri village L/B of river beki is under erosion. Reach Length= 400 M 0, Kalgachia - 1. Charchapari VGR, 2. Showpur, 3. Kismat Moinbari, 4. Dhakaliapara As per report of concerned LMs on 02/07/22 various erosion incidents occurred, the details as- 1. in charchapari VGR total 6 nos of Kutcha houses are fully eroded, land eroded- 3B-1K-12L, location coordinates- 26.226185, 90.675276. 2. In showpur vill total 2 nos of Kutcha houses are fully eroded, location coordinates- 26.333018, 90.884137. 3. In Kismat Moinbari vill total 3 nos of Kutcha houses are fully eroded, land eroded- 1B-3K-08L. 4. In Dhakaliapara vill total 14 nos of Kutcha houses are fully eroded, land eroded- 7B-4K-12L, location coordinates- 26.333018, 90.884137. 139, Chenga - Balidhari K, CHenimari K, Domdoma K, Kachumara NC 55 nos. families affected due to erosion on the site of river Brahmaputra reported by Gaon Pradhan and concerned lot mandal on 1/07/2022 275
	Biswanath	Biswanath - Rowmari Severe bank erosion is observed at Rowmari area on the R/ Bank of the river Buroi. Length 1000.00m on 01-07-2022. 0
Erosion	Bongaigao n	Manikpur - Bashbari Part 2 Erosion of around 1300 mtr. had occurred w.ef 17/06/2022 to 30/06/2022.Two (2) Nos of Relief camp opened due to the said erosion (1) Tilpukhuri ME Madrasa,Male=179 Female=165 Child=124 Pregnant=1 Disability=1 Total=470(Latitude-26.39971 Longitude-90.753438) (2)3 no. Bashbari LP School, Male=86 Female=83 Child=77 Pregnant=2 Total=248(Latitude-26.426476 Longitude-90.759589) since 17.06.2022 to till date 01.07.2022/Total Inmates 718. 718, Dangtol - Jelkajhar Erosion caused by River Tunia of around 10 m. Reported by Soil Conservation, Bongaigaon. Dated- 02.07.2022 0, Srijangram - Dubachuri part II ,Santoshpur part II , Jopea Boroichala and Kacharipety Part III Relief camps are in operation :4 nos. 1. Dubachuri Part I Embankment (205)2.Santoshpur Part II MVS (198)3. Jopea Boroichala Anchalik Club(110) and Bhaduripara LPS (103). GR issued . Rice : 3.6 Q Dal :0.66 Qt Salt :0.198 Qt M.Oil : 19.8 Ltr dated 02-07-2022, Medical Team-6 616
	Charaideo	Mahmora - 1. At Dhemaji Beel Gaon (Desang River) 2. At Santipur, Dhemaji Beel Gaon (Desang River) 3. At Koroiguridubi , Doomordolong Habi Gaon (Deroi River) 1. Sever erosion occurred at Dhemaji Beel Gaon (130 meter) at right bank of Desang river on 01/07/2022 reported by WR Dept. Demow WR Subdivision, Mouza Mahmora , under Mahmora RC. Lat- 27.04861111 , Long- 94.92194444 2. Sever erosion occurred at Santipur area of Dhemaji Beel Gaon (150 meter) at right bank of Desang river on 01/07/2022 reported by WR Dept. Demow WR Subdivision, Mouza Mahmora , under Mahmora RC. Lat- 27.04847778 , Long- 94.93472222 3. Sever erosion occurred at Koroiguri Dubi of Doomordolong Habi Gaon , (80 meter) at right bank of Deroi river on 01/07/2022 reported by WR Dept. Demow WR Subdivision, Mouza- Khaloighugura , under Mahmora RC. Lat- 27.09500000 , Long- 94.85000278 0
	Chirang	Bijni - Bijni As reported by Bijni Municipal Board,Bijni,ongoing erosion occured at Dulani River Ghat at Sibsankar Colony since 25-06-2022 due to Dulani river. Length=10 mtr(Approx) Breadth=7 mtr(approx) Depth=3 mtr(Approx). Longitude=90.694878 Latitude=26.497738 0
	Darrang	Dalgaon - Thalthali, Rangagarapathar, Rahmanpur and Bhabapur as per report received from WR department river bank erosion occurred at village Talathali -1000m length, Date of occurrence - 18/05/2022, Rangagarapathar - 800m, date of occurrence - 14/05/2022, Rahmanpur - 380m, date of occurrence - 19/05/2022 and Bhabapur - 470, Date of occurrence - 16/05/2022 0, Mangaldoi - Mangaldai River, Saktola River as per report received from WR department river bank erosion occurred at village Adhomapara-800m length, Date of occurrence - 18/05/2022, Bollopara - 800m, date of occurrence - 14/05/2022, Sonalipam Stadium - 1500m, date of occurrence - 03/06/2022, New Colony - 800m, Date of occurrence - 10/06/2022, Kawaripathar -1000m, Date of occurrence 13/06/2022, Denagaon - 500m, Date of occurrence - 31/05/2022, Chereng - 1000m, date of occurrence - 15/05/2022, Shaheed - 300m, date of occurrence - 08/06/2022 and as per report received from WR department river bank erosion occurred at village Kabikara (Ch

	3600m R/B- 200m Occurrence date 18/05/22, Ch 3800m R/B-100m Occurrence date 14/05/2022, Ch 4000m R/B 100m Occurrence date 08/06/2022, Ch 200m R/B-100m Occurrence Date 03/06/2022), Bor Athiabari (Ch 800m L/B-100m Occurrence Date 14/05/2022, Ch 1000m L/B-100m Occurrence Date 18/05/2022, Ch 1400m L/B-150m Occurrence Date 10/06/2022), Athiabari (Ch 1400m R/B-200m Occurrence Date 03/06/2022, Ch3000m R/B-150m Occurrence Date 15/05/2022), Patalsingapara (Ch 2400m L/B-100m Occurrence Date 08/06/2022, Ch3000m R/B-150m Occurrence Date 08/06/2022), Ch3000m Date 08/06/2022, Ch3000m Date 08/06/2022), Patalsingapara (Ch 2400m L/B-100m Occurrence Date 08/06/2022, Ch3000m Date 08/06/2022), Patalsingapara (Ch 2400m L/B-100m Occurrence Date 08/06/2022), Ch3000m Date 08/06/2022), Patalsingapara (Ch 2400m L/B-100m Occurrence Date 08/06/2022), Ch3000m Date 08/06/2022), Patalsingapara (Ch 2400m L/B-100m Occurrence Date 08/06/2022), Ch3000m Date 08/06/2022), Patalsingapara (Ch 2400m L/B-100m Occurrence Date 08/06/2022), Ch3000m Date 08/06/2022), Ch30000m Date 08/06/2022), Ch30000 Date 08/06/2022)		
	2000m L/B -120m Occurrence Date 31/05/2022),Dogdhapara (Athiabari)-Ch-5800m R/B-130m Occurrence Date 13/06/2022, Bor Thekerabari (Ch 8100m L/B-150m Occurrence Date 13/06/2022), 0,		
	Sipajhar - Saktola River as per report received from WR department river bank erosion occurred at village Hazarikapara (Ch 7500m L/B- 150m- Occurrence Date 10/06/2022), Debananda (Ch 8150m R/B-150m Occurrence Date 31/05/2022 0		
Dibrugarh	Tengakhat - Holokoni Majuli As reported by WRD on 02/07/2022 Holokoni Majuli bank sloughening from ir between Ch.7300m to 8000m for length about 600m 0		
Golaghat	Khumtai - Un Embankment portion of river Gelabeel at Badulipar area At upstream of Gelabeel RCC bridge of both bank at Badulipar area. River bank damage due to high flood for a length of 300m at right bank in between Kanfola and Bhakat Chapori area and at left bank for a length 200m in Badulipar area on 02-07-2022 0		
Hailakandi	Lala - (1) Vernerpur Basti (30m) (2) Lalacherra Ferryghat (50m) (3) Lalacherra T.E. (100m) (4) Lalaghat (40m (5) Rajyeswarpur Pt-V (40m) (6)Nalukbak(Rajyeswarpur Pt-I (50m)) (7) Nalukbak(Rajyeswarpur Pt-I (30m)) (8) Godamghat (60m) (9) Borbond Pt-I (80m) 1. Long- 92.617858 Lat- 24.524647, vertical settlement, erosion sloughening, under Lala Rev. Circle dtd. 18.06.2022 2. Long- 92.618794 Lat- 24.529361, vertical settlement, erosion sloughening, under Lala Rev. Circle dtd. 18.06.2022 3. Long- 92.6207 Lat- 24.5282, vertical settlement erosion sloughening, under Lala Rev. Circle dtd. 17.06.2022 4. Long- 92.627241 Lat- 24.613096, vertical settlement, erosion sloughening, under Lala Rev. Circle dtd. 17.06.2022 5. Long- 92.616896 Lat- 24.604169, vertical settlement, erosion sloughening, under Lala Rev. Circle dtd. 20.06.2022 6. Long- 92.576614 Lat- 24.609774, erosion, vertical settlement under Lala Rev. Circle dtd. 20.06.2022 7. Long- 92.579156 Lat- 24.614134, overtopping, population affected-8000 under Lala Rev. Circle dtd. 20.06.2022 8. Long- 92.580271 Lat- 24.561401, sloughening, erosion of vertical settlement, under Lala Rev. Circle dtd. 19.06.2022 9. Long- 92.581534 Lat- 24.617387, sloughening, erosion of vertical settlement, population affected- 5000, under Lala Rev. Circle dtd. 20.06.2022 0		
Kokrajhar	(Kokrajhar) At District - KHUTAMARI WEST GARDENPUR BOSHGAON JOYBHUM MAGURMA AS REPORTED BY EE WR KOKRAJHAR DIVISION ON 29-06-2022 1. RIVER BANK EROSION OBSERVED AT VILLAGE KHUTAMRI, NAMAPARA REACH LENGT 300M ON L/B OF RIVER GAURANG. 2. RIVER BANK EROSION OBSERVED AT VILLAGE WEST GARDENPUR REACH LENGTH 500M, WEST GARDENPUR SC BASTI REACH LENGTH 400M ON R/B AND OLD KHAGRABARI REACH LENGTH 300M ON L/B OF RIVER GARUPHELLA 3. RIVER BANK EROSION OBSERVED AT VILLAGE BOSHGAON REACH LENGTH 300M ON L/B OF RIVER JANALI 4. RIVER BANK EROSION OBSERVED AT VILLAGE JOYBHUM OF RIVER TARRANG 5. RIVER BANK EROSION OBSERVED AT VILLAGE MAGURMARI ON L/B OF RIVER HEL 0		
Lakhimpu r	Kadam - Kakoi Rajgarh Approximately 0.267 Hect. of land eroded by the River Kakoi at Kakoi Rajgarh Jaluabasti, informed by the concerned LM, dated 02/07/2022 0, Dhakuakhana - Gudan-Takarchuk area Severe bank erosion observed at Gudan Takarchuk area by River Brahmaputra since 30th June, 2022. (Length: 200 M). Report submitted by Dhakuakhana Water Resource		
Majuli	Division. 0 Majuli - 1. Kulamora village, 2. Jamudchuk, 3. Namoni Balijokaibowa Bank erosion place at 3 Nos. of Un-Embankment on dtd.02-07-2022 1. Kulamora Lat=27.044917, Lon=94.205948, Affected Reach Length- 1.7 Kr 2. Jamudchuk Lat=27.047536, Lon=94.229445, Affected Reach Length- 1.9 Km 3. Namoni Balijokaibowa Lat=27.031121 Lon=94.187696, Affected Reach Length- 1.8 Km 0, Ujani Majuli - 1. Jengerai Balichapori, 2. Ratanpur Miri Kuli gaon, 3. Kumarbari Bank erosion took places at Nos of Un-Embankment on dtd. 02-07-2022 1. Jengerai Balichapori Lat=27.070668, Long=94.225533; Affecte Reach Length- 1.9 Km 2. Ratanpur Miri Kuli gaon Lat=27.100054 Long=94.39476; Affected Reach Length- 2. Km 3. Kumarbari Lat=27.084195 Lon=94.293242; Affected Reach Length- 1.8 Km 0		
Morigaon	Laharighat - Leruamukh, Goroimari PWD road , Bhajaikhati gaon & Barchapori As per report received from the Water Resources dept on 02-06-2022, erosion is observed in areas like Leruamukh, Goroimari PWD road , Bhajaikhati gaon & Barchapori with maximum erosion of 0 m in Leruamukh, 0 m in Goroimari PWD road , 2 m in Bhajaikhati gaon & 2 m in Barchapori 0		
Nagaon	Dhing - BIRINGABARI RETIREMENT EMBANKMENT AT GATIKORA AREA AS REPORTED BY SECTION OFFICER, DHING - II SECTION, NAGAON W.R. DIVISION ON 01.02.2022, THE BIRINGABARI EMBANKMENT HAS ALREADY BEEN ERODED FOR A REACH OF 150M DUE TO ACTIVE EROSION. RESTORATION WORK STATRED TO PROTECT THE EMBANKMENT. 0		
Nalbari	Paschim Nalbari - Nadla Erosion at left L/B of River Burhadia. Information received from Water Resource Department on 01/07/2022 0		
Sivasagar	Sivsagar - Rupahimukh Erosion of Telidunga to Rupahimukh MGNREGA Road near 528 Nos. Baligaon LP School, Rupahimukh of Jokaichuk Mouza under Sivasagar Revenue Circle on 02-07-2022 as report received fr Zilla Parishad, Sivasagar. 0, Amguri - Dum Gaon of Dupdor Mouza, Baruah Ali GP A portion of appx. 20 feets of Borshilla Noi (Jaan) rig		
	Bank has been washed away due to heavy rain at Dum gaon under Baruah Ali GP of Amguri Development bloc Erosion occurred form 25.06.22 0		

		dated 02-07-2022, erosion takes places on No 2 Dongargaon. Affected length 80m.(Long-91.696801 Lat-
		26.770812),L/B of River Barnadi,. 0
	Tinsukia	Sadiya - koilabasti 2. Active erosion is reported from Koilabasti area by Kundil river. Reported by concern
	Tilisukia	Gaonpradhan. 27°50'48.8"N, 95°42'45.2"E. Stretch area 10m. From date 30/7/2022 to 02/07/2022. 0
		Khairabari - 1. Rupakhat, 2. Udmari, 3. Bogpuri, 4. Kacharipara 1. Erosion occured on the R/B of Nonai River
		at Rupakhat for length of 450M. Date: 01.05.2022. GPS: Lat-26.383634 Long- 91.541760. Population affected:
		100 (approx.) 2. Severe erosion is found at Udmari village by Kalpani River near Upen Boro's paddy field. Date:
		01.07.2022. Length: 100M (approx.). GPS: Lat- 26.644265 Long- 91.848288 Population affected: 60 (approx.) 3.
		Severe gully erosion occured at Bogpuri Village by Kalpani River near Rupa Boro's paddy fiels. Date: 01.06.2022
	7711	GPS: Lat- 26.638054 Long- 91.847126. Population affected: 50 (approx.) 4. Severe gully erosion is continuing at
	Udalguri	Kacharipara village near Bireswaer Deka's Paddy field. Date: 01.06.2022. GPS: Lat- 28.655065 Long: 91.773968.
		Length: 100 M (approx.). Population affected: 200 (Approx.) 0,
		Harisinga - Amlaiguri Ghagra Erosion continuing at Amlaiguri, Ghagra R/B 600m of Bhorla river . From 17th
		June to 01 July 2022 0,
		Kalaigaon - Uttar Bokrajhar Severe erosion on L/B of river Kulshi due to heavy current of the river as reported
		on 02/07/2022 covering a length of 310 meters 40
Landslide	District	Details
	Hailakandi	Hailakandi - Bondukmara Landslide happened backyard of Bondukmara Outpost No casualites. under
		Hailakandi Rev. Circle dtd. 29.06.2022 0
Urban	District	Details
Flood	Dibrugarh	Dibrugarh East - Ward no 3 (Khlihamari), ward no 21 (Gangapara), ward no 21 (Gabharuathar), ward no -
		01(Dhobiatty and kumarpatty Urban flood due to water logging areas as on 02.07.2022 2111