

## **FRIMS Assam**



## Flood Reporting And Information Management System

			-		as on 12-06-2022	2 at 4:00 PM				
Particulars	Situation as o	on 12-06-20	22 (in last 24	4 hours)						
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Nil									
District Affected	No. of Districts Affected	Name of Flood Affected Districts  Name of Urban Flood Districts								
	3 Dhemaji, Lakhimpur, South Salmara									
No. Of Revenue Circles Affected	4									
Name Of	District	Total	Revenue							
	Dhemaji	2	Dhemaji, Sissiborgaon							
Revenue Circles	Lakhimpur	1	Subansiri							
Affected	South Salmara	1	Mankachar							
	Total	4 T-4-1	Decree Chal							
	District Dhemaji	2	Total Revenue Circle							
Villages	Lakhimpur	6	(Dhemaji   1), (Sissiborgaon   1)							
Affected	South	_	( Subansiri   6 )							
Antected	Salmara	12	( Mankachar   12 )							
	Total	20	0							
Population And Crop Area Affected	District	Male	Female	Children	Total Population	Population Details	Crop Area ( in Hect. )	Crop Area Details		
	Dhemaji	457	419	160	1036	( Dhemaji   616 ), ( Sissiborgaon   420 )	64.00	( Dhemaji   4.00 ), ( Sissiborgaon   60.00 )		
	Lakhimpur	137	120	56	313	(Subansiri   313)	231.00	( Subansiri   231.00 )		
	South Salmara	0	0	0	0	( Mankachar   0 )	87.00	( Mankachar   87.00 )		
	Total	594	539	216	1349		382.00			
Relief Camps / Centres Opened	Nil									
Inmates In Relief Camps	Nil	Nil								
Human Lives Lost - Confirmed	Nil									
Human Lives Lost Confirmed - Death Type	Nil									
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
Animals Affected	District	Total	Big	Small	Poultry					
	Lakhimpur	9006	2490	1145	5371					
	Total	9006	2490	1145	5371					
Animals Washed Away	Nil									
Houses Damaged Rescue	Nil									
Operation Relief	Nil									
Distributed	Nil									

Relief									
Distributed Others	Nil								
	District	Number	Details						
Infrastructure Damaged - Embankment Breached	Tamulpur	Goreswar - Bangalipara Ring Bandh   Village Bangalipara   Dated 12/06/2022 The repaired portion of the east bank Ring Bandh of sub tributary River Deosunga has been damaged due to overtopping of water. Approximate damage 10 metres.Flash flood condition occurred in the morning and gradually receded, now the situation is normal.							
	Total	1							
Infrastructure Damaged - Embankments Affected	Nil								
	District	Number	Details						
Infrastructure Damaged - Road	Karimganj	RK Nagar - Chandkgani to Padarpar Road   Chandkgani to Padarpar Road   Due to heavy on date 06-06-2022 bridge approch damaged lenght upto 60 m,  Bhairabnagar to Tatirgool   Bhairabnagar to Tatirgool   due to heavy rain road surface dang upto length 150 m on date 06-06-2022							
	Lakhimpur	5	Subansiri - Bangkeleng to Konwarbari road   Konwarbari   Bangkeleng to Konwarbari road eroded at 1st km opprx 200 mtrs as reported by Dhakuakhana Territorial Road divn. on 11-06-2022,  Bilmukh to Mohbal road   Mohbal   Bilmukh to Mohbal road is submerged opprx 1000 mtrs as reported by Dhakuakhana Territorial Road divn. on 11-06-2022,  Champora to Keseruguri road   Champora   Left bank Champora to Keseruguri road eroded at 1st km opprx 250 mtrs as reported by Dhakuakhana Territorial Road divn. on 11-06-2022,  Gadangarchuk to Konwarbari road   Gadangarchuk   Gadangarchuk to Konwarbari road eroded at 1st km opprx 250 mtrs as reported by Dhakuakhana Territorial Road divn. on 11-06-2022,  Konwarbari to No 2 Gadangarchuk road   No 2 Ga dangarchuk   Konwarbari to No 2  Gadangarchuk road is submerged at 1st km opprx 800 mtrs as reported by Dhakuakhana Territorial Road divn. on 11-06-2022						
	Total	7							
- 0	District	Number	Details The state of the state						
Infrastructure Damaged - Bridge	Tamulpur	1	Goreswar - Tengajhar wooden Bridge   Village Tengajhar   The wooden Bridge at Village Tengajhar over River Suklai which was reported as west part was washed away today morning 12/06/2022.the reparing portion (west part) again was washed away. Approx 3metres.						
Infrastructure Damaged - Wildlife	Total Nil	1							
· · · · · · · · · · · · · · · · · · ·	District	Other Det							
Infrastructure Damaged - Others	Lakhimpur	Subansiri - Bamboo Foot Bridge   Bamboo bridge damaged on Napam to Guwarthali Milanpur Gaon road appx 70 mtrs as reported by Dhakuakhana Territorial Road divn. on 11-06-2022, Culvert Approach Road Damaged   The Approach of Culvert at 1st Km apprx 5 mtr at Gadangorchuk to Bangkeleng road is damaged as reported by Dhakuakhana Territorial road divn on 11-06-2022., Culvert Approach Road Damaged   Box culvert at Maj Pathorichuk to Borkolia road apprx 12 mtr is damaged as reported by Dhakuakhana Territorial road divn. on 11-06-2022., Bamboo Foot Bridge   Bamboo bridge damaged on Kekuri Madhupur to Chelajan Kachari road appx 110 mtrs as reported by Dhakuakhana Territorial Road divn. on 11-06-2022.							
	South Salmara	Mankachar - Fisheries/Pond   As per report submitted Fishery Department, Mankachar, total 134 Nos. fishery/ pond damaged due to heavy rainfall on 12-06-2022 under Mankachar Rev. Circle.							
	Tamulpur	<b>Goreswar</b> - Bamboo Foot Bridge   The bamboo footbridge (that was temporarily constructed after the west part of the wooden Bridge over River Suklai at Village Tengajhar was washed away)The bamboo footbridge has been washed away today morning 12/06/2022. Coordinates 26.606594, 91.691076.							
Erosion	District	Details							
	Biswanath	Halem - Paken   As reported by Water Resources Gohpur, mild erosion observed at Paken area on R/B of river Brahmaputra on 12/06/2022. Length 1400m   0							
	Kokrajhar	<b>Bagribari</b> - Village Jongirkilla Pt-I & Jongirkilla Pt-II   as per report collected from Bagribari Rev. Circle Due to heavy rainfall a JFMC embankment of Community Tank at village Jongirkill Pt-II has been breached and the water merged to a steam and suddenly a speed flow of water come towards the village and erosion has been occurred. As a result, Population affected= 105 Nos. House- 2nos. partially affected with household properties, Pond- 10 nos. eroded, Life Stock washed away Small (Goat)-01 no. Poultry= 40 nos., Crop (Summer Paddy) affected = Area: 3.5 Hector, families displaced 02 and 01 shifted to shelter camp on- 12.06.2022   105							
	Morigaon	Laharighat - Leruamukh ,Goroimari , Borchapori & Bhajakhaiti   As per report received from Water Resources Dept on 12-6-22, erosion is observed in places like Leruamukh ,Goroimari , Borchapori & Bhajakhaiti with maximum erosion of 1 m at Leruamukh ,0m at Goroimari, 3 m at Borchapori & 4m at Bhajakhaiti respectively.   0							
	Tinsukia	Doomdooma - 1. Village: No. 1 Kordoiguri(Darjijan), 2. Village : No. 2 Kordoiguri ( Simoluguri Satra ).							

		1. River Bank erosion is being observed at No. 1 Kordoiguri (Darjijan)on the left Bank of River
		Brahmaputra (Ananta Nallah) since 19/05/2022 till 12/06/2022. As per information received from
		concerned Lot Mandal and WR department officials the affected stretch is about 400 m in length.( Long:
		95.450531, Lati: 27.651217), population affected 37. 2. River Bank erosion is being observed at No.2
		Kordoiguri (Simoluguri Satra)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till
		12/06/2022. As per information received from concerned Lot Mandal and WR department officials, the
		affected stretch is about 460 m in length.( Long: 954505, Lati: 27.65196)   0
		<b>Udalguri</b> - Dhibisora   Erosion Occured on the L/B of Moradhansiri river at Dhibisora village around 150m
	Udalguri	on 11.6.2022   0,
		Khairabari - Rupakhat   Due to heavy rainfall, the flow of water over Nonai river raised, resulting erosion
		on its R/B at Rupakhat on 12.6.2022. Length 200 m. (approx.)   150
Landslide	Nil	
Urban Flood	Nil	