

## **FRIMS Assam**



## Flood Reporting And Information Management System

	Assam Daily Flood Report as on 17-06-2023 at 4:00 PM									
Particulars	Situation as on	tion as on 17-06-2023 (in last 24 hours)								
Rivers flowing above Danger Level (as	Rivers flowing	g above dan	ger level			Puthimari (Nh Road Crossing), Kopili (Kampur), Brahmaputra (Neamatighat)				
per CWC bulletin issued at 8 AM)	Rivers flowing	g above higl	nest flood	level		Nil				
District/Sub -division	No. of Districts/Su b-divisions* Affected	Name of divisions		ected Distr	icts/Sub-	Name of Urban Flood Districts/Sub-divisions*				
Affected	13	Hojai, La		g, Dhemaji, 1 Nagaon, Sor		Cachar, Kamrup (M), Nalbari				
No. Of Revenue Circles Affected	23		•							
	District/Sub -division*	Total	Revenue	e Circle						
	Biswanath	2	Gohpur,	Halem						
	Cachar	1	Silchar							
	Darrang	2	Mangaldoi, Dalgaon							
	Dhemaji	1	Dhemaji							
Name Of	Dibrugarh	2	Chabua, Dibrugarh West							
Revenue	Hojai	3	Doboka, Lanka, Hojai							
Circles	Kamrup (M)	2	Azara, Dispur							
Affected	Lakhimpur	2	Nowboicha, Narayanpur							
	Nagaon	1	Raha Nollegii							
	Nalbari	1	Nalbari  Dhakigirli Taraya Chasidyas							
	Sonitpur Tinsukia	3	Dhekiajuli, Tezpur, Chariduar							
	Udalguri	2	Tinsukia Harisinga Kalaigaon							
	Total	23	Harising	Harisinga, Kalaigaon						
	District/Sub	Total	Revenue Circle							
	-division*									
	Biswanath	28	( Gohpur   5 ), ( Halem   23 )							
	Darrang	19	(Mangaldoi   2), (Dalgaon   17)							
	Dhemaji	4	(Dhemaji   4)							
Villages	Dibrugarh	7		( Chabua   1 ), ( Dibrugarh West   6 ) ( Doboka   3 ), ( Lanka   3 ), ( Hojai   11 )						
Affected	Hojai	17 24	1							
	Lakhimpur Nagaon	9	( Raha		( Narayanpur	11 )				
	Sonitpur	24		,	Teznur l 14 ) 7	Chariduar   9 )				
	Tinsukia	3	`	<b>J</b> • // ·	. czpui   14 ), (	Charlana [7]				
	Udalguri	11	(Tinsukia   3) (Harisinga   3), (Kalaigaon   8)							
	Total	146	(11411511	5 1 0 /9 ( IX						
<b>D</b>	District/Sub -division*	Male	Femal e	Childre n	Total Populatio n	Population Details	Crop Area ( in Hect. )	Crop Area Details		
Population And Crop	Biswanath	1652	1366	613	3631	( Gohpur   1400 ), ( Halem   2231 )	40.00	( Gohpur   23.50 ), ( Halem   16.50 )		
Area Affected	Darrang	432	362	277	1071	( Mangaldoi   178 ), ( Dalgaon   893 )	70.00	( Mangaldoi   0.00 ), ( Dalgaon   70.00 )		
	Dhemaji	156	152	52	360	( Dhemaji   360 )	15.00	( Dhemaji   15.00 )		
	Dibrugarh	1567	1240 1050 3857 (Chabua   3857), ( 170.50 (Chabua   116.50), (							

						Dibrugarh V	West   0)		Dibrugarh W	est   54.00		
									)			
	Hojai	0	0	0	0	( Doboka   ( 0 ), ( Lanka		322.75	( Doboka   3' Hojai   260.1 Lanka   25.5	9),(		
	Lakhimpur	12221	12094	960	25275	( Nowboicha   25097 ), ( Narayanpur   178 )		29.63	( Nowboicha   0.00 ), ( Narayanpur   29.63 )			
	Nagaon	0	0	0	0	(Raha   0)		490.87	( Raha   490.			
	Sonitpur	29	23	0	52	( Dhekiajuli   52 ), ( Chariduar   0 ), ( Tezpur   0 )			( Dhekiajuli   0.00 ), ( Chariduar   15.00 ), ( Tezpur   9.90 )			
	Tinsukia	985	848	833	2666	( Tinsukia		238.00	(Tinsukia   2			
	Udalguri	312	228	83	623	( Harisinga   365 ), ( Kalaigaon   258 )			( Harisinga   Kalaigaon   8			
	Total	17354	16313	3868	37535			1409.65				
	District/Sub -division*	Total	Relief C	Camp			<b>Relief Distribution Centres</b>					
Relief	Biswanath	4		ır   0, Halen	n   0)		4(Gohpur   2, Halem   2)					
Camps /	Dibrugarh	1	0(Chabu				1(Chabua   1)					
Centres Opened	Lakhimpur Tinsukia	10	0(Nowb 0(Tinsul	oicha   0)			10(Nowboicha   10)					
Opened	Udalguri	3	2(Kalaig				1(Tinsukia   1) 1(Kalaigaon   1)					
	Total	19	2(Kararg	5uO11   2)			1(Kalaigaoi	·   ·   /				
Inmates In Relief	District/Sub -division*	Total	Revenue Circlewise			Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y		
Camps	Udalguri	9	(Harisin	ga   0), (Kal	aigaon   9)	4	4	0	1	0		
Human	Total	9				4	4	0	1	0		
Confirmed Human Lives Lost Confirmed - Death Type Human Lives Lost - Missing Human Lives Lost Missing - Type	Nil Nil Nil											
	District/Sub -division*	Total	Big	Small	Poultry							
	Biswanath	35390	25500		·							
Animals	Dibrugarh	5368		9890	0							
Affected			4418	950	0							
	Lakhimpur	4305	3301	950 1004	0 0 0							
	Sonitpur	4305 180	3301 125	950 1004 55	0 0 0 0							
	Sonitpur Udalguri	4305 180 249	3301 125 56	950 1004 55 81	0 0 0 0 0 112							
Animals Washed Away	Sonitpur	4305 180	3301 125	950 1004 55	0 0 0 0							
Washed	Sonitpur Udalguri Total	4305 180 249	3301 125 56	950 1004 55 81	0 0 0 0 0 112							
Washed Away Houses	Sonitpur Udalguri Total	4305 180 249	3301 125 56	950 1004 55 81	0 0 0 0 0 112	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter	Medical Team Deploye d		
Washed Away Houses Damaged	Sonitpur Udalguri Total Nil Nil District/Sub	4305 180 249 <b>45492</b>	3301 125 56	950 1004 55 81	0 0 0 0 112 112	Evacuate d By	Evacuate d By	s	Evacuated By Helicopter	Team Deploye		
Washed Away Houses Damaged	Sonitpur Udalguri Total Nil Nil District/Sub -division*	4305 180 249 <b>45492</b>	3301 125 56	950 1004 55 81	0 0 0 0 112 112 112 Boats Deployed	Evacuate d By Boats	Evacuate d By Boats	s Deployed	Evacuated By Helicopter s	Team Deploye d 3 0		
Washed Away Houses Damaged	Sonitpur Udalguri Total Nil Nil District/Sub -division*	4305 180 249 45492 Agency	3301 125 56	950 1004 55 81	0 0 0 0 112 112 112 Boats Deployed	Evacuate d By Boats	Evacuate d By Boats	s Deployed	Evacuated By Helicopter s	Team Deploye d		

						Fooder	Bran (in					
	7.	10.10	0.11	0.00	0.00	(in Q)	Q)	0.00				
	Biswanath	49.10	8.66	0.00	0.00	0.00	222.00	0.00				
	Dibrugarh	63.13 363.63	11.57	3.47 20.22	186.00 2022.00	0.00	0.00	0.00 303.00				
	Lakhimpur Sonitpur	0.77	67.41 0.16	0.05	0.00	0.00	0.00	0.00				
	Tinsukia	42.99	7.99	2.39	239.94	0.00	0.00	0.00				
	Udalguri	4.55	0.81	0.24	24.20	0.00	0.00	0.00				
	Total	524.17	96.60	26.37	2472.14	0.00	222,00	303.00				
	District/Sub	Baby Foo					222.00	202.00				
	-division*	Liquid		Baby Foo	od Solid	Others						
Relief	Biswanath	0.00-Q		0.00-Q								
Distributed	Dibrugarh	0.00-Q		0.00-Q		0-0.00-Q						
Others	Lakhimpur	0.00-Q		680.00-Pl	ct	Tarpaulin -	2414.00-Piece	es				
	Sonitpur	0.00-Q		0.00-Q								
	Tinsukia	0.00-Q		0.00-Q		0-0.00-Q						
	Udalguri <b>District/Sub</b>	0.00-Pkt Numbe		0.00-Q		0-0.00-Q						
	-division*	r	Details									
Infrastructur e Damaged	Darrang	2	Mangaldoi - Approach Road in Noanadi Kachia Bund FIS   At village Choto Athiabari   Due to rise of water level breach occurred at approach Road in Noanadi Kachia Bund FIS and approx. length of breach is 15 mt. as reported by the irrigation department. Dated 17/06/2023.   (Long - 91.995900, Lat - 26.443300, Dept - Irrigation),  Kamarpara Embankment.   At village Kamarpara   Due to rise of water level breach occurred at PNRD Embankment at Kamarpara Village and approx. length of breach is 11 mt Dated 17/06/2023.   (Long - 91.992800, Lat - 26.419400, Dept - P&RD)									
- Embankme nt Breached	Nagaon	1	<b>Kampur</b> - Premajaan Embankment at Saibuk Gaon   Saibuk Gaon   The premajaan Embankmen P&RD Department breached 5 metres at Saibuk Gaon on dated 17.06.2023 at 7.30 am under Kampur Revenue Circle.   (Long - 26.106437, Lat - 92.717367, Dept - P&RD)									
	Sonitpur	1	<b>Chariduar</b> - 1 no embankment breached on DTD 17/06/2023 at Bahbari Deka chuburi(Dekar village which was constructed under MGNREGA scheme   Dekargaon     (Long - 92.710210, 26.717130, Dept - P&RD)									
	Udalguri	1	17/06/20	<b>Kalaigaon</b> - Embankment at Majarchuba in the L/B of river Noa   Majarchuba   Breached on 17/06/2023. Length 20 meters Breadth 4 meters. Due to overtopping of river Noa   (Long - 91.998531, Lat - 26.598621, Dept - P&RD)								
	Total	5										
	District/Sub -division*	Numbe r	Details									
			Gohpur - Mild Erosion observed at R/Bank embankment of river Sessa   at Auguri area of length 30 mtr on 17/06/23     (Long - 93.737047, Lat - 26.952548, DeptSelect Department), Mild bank Erosion is observed on R/Bank of river Sessa   At Baligaon Marginal Embankment in Gosarguri area of length 100 mtr on 17/06/23     (Long - 93.712256, Lat - 26.989844, Dept - Water Resource Deptt.), Mild bank erosion is observed on R/Bank of river Sessa   at Gopsarguri marginal embankment Of length 120 mtr on 17/06/23     (Long - 93.716944, Lat - 26.979766, Dept - Water Resource Deptt.), Erosion is observed on R/Bank embankment of river Solengi   at Dakhin Deonabari of length 20 mtr on 17/06/23     (Long - 93.643767, Lat - 26.913720, Dept - Water Resource Deptt.)									
	Biswanath	4	Mild bar Gosargu Resourc Mild bar length 1 Erosion	ri area of le e Deptt.), nk erosion is 20 mtr on 1 is observed	ngth 100 mtr s observed on 7/06/23    (Lo on R/Bank er	R/Bank of riv on 17/06/23   R/Bank of riv ong - 93.7169 onbankment of	(Long - 93.7 ver Sessa   at 0 44, Lat - 26.97 f river Solengi	12256, Lat - 26.989844, Dept - Water Gopsarguri marginal embankment Of 19766, Dept - Water Resource Deptt.),   at Dakhin Deonabari of length 20 mtr				
Infrastructur e Damaged	Biswanath  Darrang	1	Mild bar Gosargu Resourc Mild bar length 1 Erosion on 17/06 <b>Mangal</b> overtopp the ember	ri area of le e Deptt.), nk erosion is 20 mtr on 1' is observed 5/23    (Lon doi - Left B bing at some ankment thu	s observed on 7/06/23    (Lo on R/Bank er g - 93.643767 ank Embankn er portions of Pas eroding awa	R/Bank of riving - 93.7169 hent At Bishn NRD Bund a ay a portion o	ver Sessa   at 0 44, Lat - 26.9 f river Solengi 3720, Dept - W upur   At Vill t Bishnupur V f land of the b	12256, Lat - 26.989844, Dept - Water Gopsarguri marginal embankment Of 19766, Dept - Water Resource Deptt.),   at Dakhin Deonabari of length 20 mtr				
			Mild bar Gosargu Resourc Mild bar length 1 Erosion on 17/06 Mangal overtopp the ember Departm Jonai - Borong side Duc	ri area of le e Deptt.), nk erosion is 20 mtr on 1' is observed 5/23     (Lon doi - Left B bing at some ankment thu hent. Dated Water Reso   Due to ince el bund in be	s observed on 7/06/23    (Lo on R/Bank er g - 93.643767) ank Embankne portions of P us eroding awa 16/06/2023   (urce Deptt. rivessant rain and etween Sadhu	R/Bank of rivers on 17/06/23    R/Bank of rivers - 93.7169    nbankment of particular and the control of the co	ver Sessa   at 0 44, Lat - 26.97 f river Solengi 8720, Dept - W aupur   At Vill t Bishnupur V f land of the b 6900, Lat - 26 Country side D er level of rive ag got 75.00 m	Gopsarguri marginal embankment Of 79766, Dept - Water Resource Deptt.),   at Dakhin Deonabari of length 20 mtr Vater Resource Deptt.)  age Bishnupur   Due to flood water Gillage, breach like situation occurred in bund as reported by water Resource				
e Damaged - Embankme	Darrang	1	Mild bar Gosargu Resourc Mild bar length 1 Erosion on 17/06 Mangal overtopp the embe Departm Jonai - Borong side Due 16/06/20 Lakhipu to heavy Nichinp 90.1902   (Long	ri area of le e Deptt.), nk erosion is 20 mtr on 1' is observed 5/23     (Lon doi - Left B bing at some ankment thu nent. Dated Water Reso   Due to ince el bund in be 123.   (Long 11 - Kharmu r ainfall Ne ur) within C 83 to ended - 0.000000,	s observed on 7/06/23    (Lo on R/Bank er g - 93.643767 ank Embankn er portions of Pas eroding awa 16/06/2023   (Lurce Deptt. rivessant rain and etween Sadhur - 95.090000, iza to Niching why 21 nos land the 34.00KM to point lat - 26.0 Lat - 0.00000	R/Bank of rivers of the control of t	ver Sessa   at 0 44, Lat - 26.9 f river Solengi 720, Dept - W 10 10 10 11 11 12 13 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16	Gopsarguri marginal embankment Of 79766, Dept - Water Resource Deptt.),   at Dakhin Deonabari of length 20 mtr Vater Resource Deptt.)  age Bishnupur   Due to flood water Gillage, breach like situation occurred in bund as reported by water Resource543900, Dept - Irrigation)  ual bund   Between Shadhughat to be Brahmaputra, River side and Country letter slumped down and eroded on later Resource Deptt.)  are report of WR Division Goalpara, Due in occurred at B/dyke (Kharmuza to bint from lat-26.045284, long-14.06.2023 to till date on 17.06.2023. Deptt.)				
e Damaged - Embankme	Darrang  Dhemaji  Goalpara  Karimganj	1 1 1	Mild bar Gosargu Resourc Mild bar length 1 Erosion on 17/06 Mangal overtopp the ember Departm Jonai - Borong side Due 16/06/20 Lakhipu to heavy Nichinp 90.1902   (Long -	ri area of le e Deptt.), nk erosion is 20 mtr on 1' is observed 5/23     (Lon doi - Left B bing at some ankment thu nent. Dated Water Reson   Due to ince el bund in be 123.   (Long nr - Kharmu r ainfall Ne ur) within C 83 to ended - 0.000000, andi - Righ ngth occurre	s observed on 7/06/23    (Lo on R/Bank et g - 93.643767 ank Embankn et portions of Pas eroding awa 16/06/2023   (arce Deptt. rivessant rain and etween Sadhu - 95.090000, aza to Niching wly 21 nos lau ch. 34.00KM t point lat - 26.0 Lat - 0.00000 at bank of rive et don right bar	R/Bank of river to n 17/06/23    R/Bank of river grade and control of the control	ver Sessa   at 0 44, Lat - 26.9 f river Solengi 8720, Dept - W 10 10 10 11 11 12 13 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16	Gopsarguri marginal embankment Of 79766, Dept - Water Resource Deptt.),   at Dakhin Deonabari of length 20 mtr Vater Resource Deptt.)  age Bishnupur   Due to flood water Gillage, breach like situation occurred in bund as reported by water Resource .543900, Dept - Irrigation)  ual bund   Between Shadhughat to be Brahmaputra, River side and Country leter slumped down and eroded on later Resource Deptt.)  er report of WR Division Goalpara, Due in occurred at B/dyke (Kharmuza to bint from lat-26.045284, long-14.06.2023 to till date on 17.06.2023.				
e Damaged - Embankme nt Affected	Darrang  Dhemaji  Goalpara  Karimganj  Total	1 1 1 8	Mild bar Gosargu Resourc Mild bar length 1 Erosion on 17/06 Mangal overtopp the ember Departm Jonai - Borong side Due 16/06/20 Lakhipu to heavy Nichinp 90.1902   (Long -	ri area of le e Deptt.), nk erosion is 20 mtr on 1' is observed 5/23     (Lon doi - Left B bing at some ankment thu nent. Dated Water Reson   Due to ince el bund in be 123.   (Long nr - Kharmu r ainfall Ne ur) within C 83 to ended - 0.000000, andi - Righ ngth occurre	s observed on 7/06/23    (Lo on R/Bank et g - 93.643767 ank Embankn et portions of Pas eroding awa 16/06/2023   (arce Deptt. rivessant rain and etween Sadhu - 95.090000, aza to Niching wly 21 nos lau ch. 34.00KM t point lat - 26.0 Lat - 0.00000 at bank of rive et don right bar	R/Bank of river to n 17/06/23    R/Bank of river graph of the part	ver Sessa   at 0 44, Lat - 26.9 f river Solengi 8720, Dept - W 10 10 10 11 11 12 13 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16	Gopsarguri marginal embankment Of 79766, Dept - Water Resource Deptt.),   at Dakhin Deonabari of length 20 mtr Vater Resource Deptt.)  age Bishnupur   Due to flood water fillage, breach like situation occurred in bund as reported by water Resource .543900, Dept - Irrigation)  ual bund   Between Shadhughat to be Brahmaputra, River side and Country leter slumped down and eroded on later Resource Deptt.)  ber report of WR Division Goalpara, Due in occurred at B/dyke (Kharmuza to be point from lat-26.045284, long-14.06.2023 to till date on 17.06.2023. Deptt.)  Tapadarpara   A slump down around larpa on 17/06/2023 due to heavy				
e Damaged - Embankme nt Affected	Darrang  Dhemaji  Goalpara  Karimganj  Total  District/Sub	1 1 1 8 Numbe	Mild bar Gosargu Resourc Mild bar length 1 Erosion on 17/06 Mangal overtopp the ember Departm Jonai - Borong side Due 16/06/20 Lakhipu to heavy Nichinp 90.1902   (Long -	ri area of le e Deptt.), nk erosion is 20 mtr on 1' is observed 5/23     (Lon doi - Left B bing at some ankment thu nent. Dated Water Reson   Due to ince el bund in be 123.   (Long nr - Kharmu r ainfall Ne ur) within C 83 to ended - 0.000000, andi - Righ ngth occurre	s observed on 7/06/23    (Lo on R/Bank et g - 93.643767 ank Embankn et portions of Pas eroding awa 16/06/2023   (arce Deptt. rivessant rain and etween Sadhu - 95.090000, aza to Niching wly 21 nos lau ch. 34.00KM t point lat - 26.0 Lat - 0.00000 at bank of rive et don right bar	R/Bank of river to n 17/06/23    R/Bank of river graph of the part	ver Sessa   at 0 44, Lat - 26.9 f river Solengi 8720, Dept - W 10 10 10 11 11 12 13 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16	Gopsarguri marginal embankment Of 79766, Dept - Water Resource Deptt.),   at Dakhin Deonabari of length 20 mtr Vater Resource Deptt.)  age Bishnupur   Due to flood water fillage, breach like situation occurred in bund as reported by water Resource .543900, Dept - Irrigation)  ual bund   Between Shadhughat to be Brahmaputra, River side and Country leter slumped down and eroded on later Resource Deptt.)  ber report of WR Division Goalpara, Due in occurred at B/dyke (Kharmuza to be point from lat-26.045284, long-14.06.2023 to till date on 17.06.2023. Deptt.)  Tapadarpara   A slump down around larpa on 17/06/2023 due to heavy				
e Damaged - Embankme nt Affected	Darrang  Dhemaji  Goalpara  Karimganj  Total	1 1 1 8	Mild bar Gosargu Resourc Mild bar length 1 Erosion on 17/06 Mangal overtopp the emb Departm Jonai - Borong side Due 16/06/20 Lakhipi to heavy Nichinp 90.1902   (Long - Patherk 10M Lei rainfall.	ri area of le e Deptt.), nk erosion is 20 mtr on 1' is observed 5/23    (Lon doi - Left B bing at some ankment thu nent. Dated Water Reson   Due to ince el bund in be 1/23.   (Long 1/23 - Kharmu r ainfall Ne ur) within C 83 to ended - 0.000000, andi - Righ ngth occurre   (Long - 24	s observed on 7/06/23    (Lo on R/Bank er g - 93.643767 ank Embankne portions of Pas eroding awa 16/06/2023   (Lurce Deptt. rivessant rain and etween Sadhu - 95.090000, Iza to Niching wly 21 nos lauch 34.00KM to point lat - 26.0 Lat - 0.00000 at bank of rive ed on right bank 1.614148, Lat	R/Bank of river to 17/06/23    R/Bank of river 193.71694  Inhankment of 194.71694  Inhankment of	(Long - 93.7) ver Sessa   at 0 44, Lat - 26.97 f river Solengi 8720, Dept - W tupur   At Vill t Bishnupur V f land of the b 6900, Lat - 26 Country side D er level of rive tag got 75.00 m 000, Dept - W thinpur   As pec cuts have been KM damage po 190.174836 on ter Resource E apadarpara.   7 tongai at Tapad Dept - Water	Gopsarguri marginal embankment Of 79766, Dept - Water Resource Deptt.),   at Dakhin Deonabari of length 20 mtr Vater Resource Deptt.)  age Bishnupur   Due to flood water fillage, breach like situation occurred in bund as reported by water Resource .543900, Dept - Irrigation)  ual bund   Between Shadhughat to be Brahmaputra, River side and Country leter slumped down and eroded on later Resource Deptt.)  ber report of WR Division Goalpara, Due in occurred at B/dyke (Kharmuza to be point from lat-26.045284, long-14.06.2023 to till date on 17.06.2023. Deptt.)  Tapadarpara   A slump down around larpa on 17/06/2023 due to heavy				

	Goalpara	3	pathar to Ghiladhari Road   As per report received from PWD(R) due to flood & incessant rainfall the single HP Culvert washed away at Ch.6100m (approx length-15m) and surface of the road damaged due to raincut at Ch.4100m and 4700m on rangagara pathar to ghiladhari road(PMGSY Pkg No.As-16-149). dated 16.06.2023 Immediate restoration is required.   (Long - 26.598606, Lat - 92.315520, Dept - P&RD)  Balijana - PANCHARATNA TO KHARMUJA ROAD   PANCHARATNA - KHARMUJA   DAMAGED REPORTED BY PWRD, GOALPARA WEST & JALESWAR TERRITORIAL ROAD DIVISION, LAKHIPUR ON 16/06/2023 VIA WHATSAPP TEXT. The Length is 100 Metre   (Long - 90.482242, Lat - 26.146440, Dept - PWD (Roads)), KUMRI BAZAR TO DARI DURI BAZAR ROAD   DAMAGED REPORTED BY PWRD, GOALPARA WEST & JALESWAR TERRITORIAL ROAD DIVISION, LAKHIPUR ON 16/06/2023 VIA WHATSAPP TEXT. The Length is 15 Metre.   (Long - 90.539875, Lat - 26.178553, Dept - PWD (Roads)),  Lakhipur - Kharubhaj to Fetengapara via Takimari Tiniali Bazar PMGSY Road.   Near Takimari Bazar   As per report of PWD Road Department, Due to incessant rainfall for last 7 days, Kharubhaj				
			to Fetengapara via Takimari Tiniali Bazar PMGSY Road Package No. AS-07-259 from CH.2350 M to CH. 2360M & from CH. 2420 to CH. 2425 M affected length 15 meter from 15.06.2023 to till date on 17.06.2023.   (Long - 90.299667, Lat - 26.047658, Dept - PWD (Roads))  Palashbari - 1. Jaramukhuria to Khokhapara Road under Palashbari Territorial Road Div. Mirza				
	Kamrup	3	1. Jaramukhuria to Khokhapara   About 30-50 mtrs. Dated. 16/06/2023   (Long - 25.891405, Lat - 91.428910, Dept - PWD (Roads)),  2. Palashbari-mirza to Chandubi Road under Palashbari Territorial Road Div. Mirza   Palashbari-Mirza-Chandubi   About 30-50 mtrs. Dated. 16/06/2023   (Long - 25.913121, Lat - 91.469841, Dept - PWD (Roads)),  Rangia - Chepti-Bihdia Road   Moranjana, Rangia, Assam   Due to heavy rain showers from 13/06/2023 to 16/06/2023 the both side approaches to RCC Bridge no 2/1 on Chepti- Bihdia road has been eroded. (Approximately 200 m)   (Long - 91.652126, Lat - 26.415723, Dept - PWD (Roads))				
	Tamulpur	1	<b>Tamulpur</b> - Due to heavy rain & flash flood Ananda Bazar to Jamuguri via Borkajuli, Package no : AS -24- 247 have been damaged on 16 June 2023.   Ananda Bazar to Jamuguri via Borkajuli(GARUGHUTU)     (Long - 91.544316, Lat - 26.664059, Dept - PWD (Roads))				
	Total	8					
	District/Sub	Numbe	Details				
Infrastructur e Damaged - Bridge	-division*  Sonitpur	<b>r</b>	Chariduar - New Ghogra T.E playground to Ganesh Mandir Road   New Ghogra T.E road, Dated - 17/06/2023   Hume pipe culvert at ch.500 m.   (Long - 92.729307, Lat - 26.743575, Dept - PWD (Roads))				
	Total	1					
Infrastructur e Damaged - Wildlife	Nil						
	District/Sub -division*	Other De	etails				
	Biswanath	Gohpur - Elementary Schools Damaged   SESSA ANIRUDHA LPS Submerged Fully on 17/06/23, Elementary Schools Damaged   PUB BILOTIA LPS submerged partially on 17/06/23, Elementary Schools Damaged   NOBIL LPS submerged Partially on 17/06/23, Elementary Schools Damaged   NO. 2 BORFOLONG LPS Submerged Fully on 17/06/23, Elementary Schools Damaged   KHAGESWAR TALUKDAR LPS submerged Partially on 17/06/23, Elementary Schools Damaged   KAKILA GURI LPS Submerged Fully on 17/06/23, Elementary Schools Damaged   SONAJULI LPSSubmerged Fully on 17/06/23					
Infrastructur		Mangaldoi - Power Dept. Conductors   As reported by APDCL Kalaigaon HT & LT Conductors snapped at Samala, Bhuragarh, Balipota, Garubandha, Balipota, Kaithpara. dated 17.06.2023, Power Dept. Poles   As reported by APDCL Kalaigaon HT poles were damaged at Balipota, Bhuragarh and Samala. Approx. 4 poles damaged. dated 17.06.2023					
	Darrang	Samala, E Power De	ept. Poles   As reported by APDCL Kalaigaon HT poles were damaged at Balipota , Bhuragarh and				
Infrastructur e Damaged - Others	Darrang  Dibrugarh	Samala, F Power De Samala. A Chabua - Welfare d Anganwa departmen Anganwa	ept. Poles   As reported by APDCL Kalaigaon HT poles were damaged at Balipota, Bhuragarh and Approx. 4 poles damaged. dated 17.06.2023  Anganwadi Centres Affected   Kottock line AWC affected as per information received from Social lepartment on 17-06-2023 coordinates Lat 27.531478 Long 95.21476, di Centres Affected   Tengabari AWC affected as per information received from Social Welfare int on 17-06-2023 coordinates Lat 27.611502 Long 95.239086, di Centres Affected   Dadhia AWC affected as per information received from Social Welfare				
e Damaged		Samala, F Power De Samala. A Chabua - Welfare d Anganwa departme: Anganwa departme: Dudhnoi	cpt. Poles   As reported by APDCL Kalaigaon HT poles were damaged at Balipota, Bhuragarh and Approx. 4 poles damaged. dated 17.06.2023  Anganwadi Centres Affected   Kottock line AWC affected as per information received from Social lepartment on 17-06-2023 coordinates Lat 27.531478 Long 95.21476, di Centres Affected   Tengabari AWC affected as per information received from Social Welfare int on 17-06-2023 coordinates Lat 27.611502 Long 95.239086, di Centres Affected   Dadhia AWC affected as per information received from Social Welfare int on 17-06-2023 coordinates Lat 27.559956 Long 95.255222  - Irrigation Canal/Scheme Damaged   Earthen canal is broken upto 3.00m (approx) length at Aithan				
e Damaged	Dibrugarh	Samala, F Power De Samala. A Chabua - Welfare d Anganwa departmen Anganwa departmen FIS on 17 Diphu - C DLHS ros 06-2023 d 93.40889	Approx. 4 poles damaged. dated 17.06.2023  Anganwadi Centres Affected   Kottock line AWC affected as per information received from Social department on 17-06-2023 coordinates Lat 27.531478 Long 95.21476, di Centres Affected   Tengabari AWC affected as per information received from Social Welfare int on 17-06-2023 coordinates Lat 27.611502 Long 95.239086, di Centres Affected   Dadhia AWC affected as per information received from Social Welfare int on 17-06-2023 coordinates Lat 27.611502 Long 95.239086, di Centres Affected   Dadhia AWC affected as per information received from Social Welfare int on 17-06-2023 coordinates Lat 27.559956 Long 95.255222  - Irrigation Canal/Scheme Damaged   Earthen canal is broken upto 3.00m (approx) length at Aithan 1/06/2023 under Borpathar revenue village. Latitude: 25.948491, Longitude: 90.724175  Culvert Approach Road Damaged   Damage occurred to the Culvert no.1/2 on the road 51st km of ad to Bagmari via On Bey gaon (Diphu Revenue Circle) under PMGSY package no.AS12281 on 15-due to incessant heavy rainfall. Under Diphu PWD(R) Div. Coordinates Lat 25.820617 Long				

		Nadika Mofiz Police Tiniali to Ahom gaon via Basar gaon under Yubanagar GP as reported by officials of Karunabari Development Block on 17/06/2023. (MGNREGA 21-22 ongoing scheme) ,
		PWSS Damaged   A pipeline damaged under Menehapar Chuburi PWSS (Nadika) as reported by AEE, PHED, Bihpuria Sub Division on 17/06/2023,  Narayanpur - PWSS Damaged   Pipeline damaged at joyram chubri at village no.2 rangati as reported by PHED dept. on 17/06/2023,
		<b>Kadam</b> - Bamboo Foot Bridge   3 Nos. of Temprorary bamboo foot bridge has been damaged due to increasing water level of the River Kakoi at Gujihola on 16/06/2023, reported by the P&RD Dept. Boginadi
	Sonitpur	Dhekiajuli - Culvert Approach Road Damaged   As per information received from Executive Engineer, PWD, Barchalla & Dhekiajuli Territorial Road Division on 16-06-2023 that Due to torrential rain in Arunachal Pradesh and Assam for last several days surging water of Mora Suti has damaged the Culvert NO. 3/1 on 15th June, 2023 on NH-15 to LAHABARI road Near at AMTOL Bhreragaon., Culvert Approach Road Damaged   As per information received from Assistant Executive Engineer on 16-06-2023, PWD Barchalla Territorial Road that due to incessant rain since last few days flood water damaged "BARCHALLA TO TURIPAM ROAD(HUME PIPE CULVERT AT CH 1600.00 MTR) and "NEW GHOGRA T.E PLAYGROUND TO GANESH MANDIR ROAD (HUME PIPE CULVERT AT CH 500.00 MTR)
	Tamulpur	<b>Goreswar</b> - Irrigation Canal/Scheme Damaged   As per information received from AEE Irrigation Protection work (boulder sausage) L/B of river Suklai about 350 m guide band got damaged at village Jabrangpar Mouza Defeli. Date 15/06/23. Lat:26. 65992 Lon: 91.717442
	Udalguri	Khairabari - Irrigation Canal/Scheme Damaged   As reported by the department, due to continuous downpour of rainfall occurred since the 2nd week of June 2023, the canal embankment of BUDURA FIS was beached for length of 30M and 25M and breadth 4.5M at two numbers of chainages on 17.06.2023. Lat- 26.649960 Long-91.787055 and Lat-26.6489833 Long-91.786935, Irrigation Canal/Scheme Damaged   As reported by the department, due to continuous downpour of rainfall occurred since the 2nd week of June 2023, the canal embankment of MAYAKHAT FIS was beached for length of 110M and breadth of 35M on 17.06.2023. Lat- 26.626434 Long-91.816857
	District/Sub -division*	Details
	Biswanath	Gohpur - At L/Bank of Chatrang river.   Mild Erosion is observed at downstream of NH-15 of length 30 mtr on 17/06/2023   0   (Long - 93.616940, Lat - 26.602700),  Halem - Paken, Jogibari   1.Brahmaputra river- Mild bank erosion continues at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length =30m. (avg.width=0.10m).17/06/2023 2 BRAHMAJAN river- lat-26.86688 long- 93.505862 Due to sharp current of flood, the side slope on L/Bank embankment of river Brahmajan eroded upto crest level for a reach length. of 30m at Ch 7200m near Jogi Bari area. Length=30m( Avg. width=2.15m). on 16/06/2023 report by W.R.divi. Gohpur . Date-17/06/2023 report by W.R.divi. Gohpur River Brahmajan: 3) Due to Sharp current of flood, the side slope on L/Bank embankment of river Brahmajan eaten upto two third of crest width for a reach length of 30m at Ch 7200m near Jogibari area. Palliative measures are taken in the form of launching of tree branches with 8G wire. Length 30m, Latitude: 26.86688, Longitude: 93.505862. 17/06/2023 4)Due to Sharp current of flood, the side slope on R/Bank embankment of river Brahmajan washed away upto crest level for a reach length of 50m at Ch 8130m near Goroimari area. Palliative measures are taken in the form of launching of tree branches with 8G wire. Length = 50m, Latitude: 26.858833, Longitude: 93.508615 River Brahmaputra: 17/06/2023 5)Mild bank erosion continues at Paken area of B/Dyke from Jamuguri to Kharoi outfall. Length 30.00m, Latitude: 26.800677, Longitude: 93.626984. 17/06/2023   0   (Long - 93.627646, Lat - 26.800760)
Erosion	Dibrugarh	Moran - Bhoralibari Kalita Gaon   Bank damage occurred at 2 No Bhoralibari kalita gaon for a length 900m as per report received from WRD on 17.06.2023   0   (Long - 95.002266, Lat - 27.372369),  Naharkatia - Amguri Gaon   As per report received from JE,WR department, Dibrugarh West as on 17-06-2023 Bank erosion observed at Amguri gaon for a length of 300m   0   (Long - 95.233370, Lat - 27.335340)
	Golaghat	Sarupathar - Koirigaon   Erosion at koirigaon gaon date 16/06/2023 Reach length 380m   0   (Long - 93.828145, Lat - 26.126046)
	Morigaon	Laharighat - Kathani   As per Water Resource Department, Morigaon River Brahmaputra erosion eroded 2 meter at a length of 500 meter at Kathani revenue village under Laharighat Revenue Circle from 16-06-2023 to 17-06-2023.   0   (Long - 92.312168, Lat - 26.434602),  Bhuragaon - Balidunga Pam, Kupatimari   As per Water Resource department, Morigaon, Bhrahmaputra river erosion eroded 10 meter at a length of 700 meter at Kupatimari and Balidunga Pam revenue village under
	Nalbari	Bhuragaon Rev. Circle from 16-06-2023 to 17-06-2023   0   (Long - 26.411003, Lat - 92.251558)  Barkhetri - Kaplabori, Hanapa, Pubhanapara   B/dyke on R/B of river Brahmaputra from Adabari to Kukarjan at Kaplabori. Length 400m. B/dyke on R/B of river Pahaldia from bijulighat to adabari at Hanapa, length 300m and at Pub Hanapara-length 500m as reported by AEE, WRD, Mukalmua. Dated 17/06/2023   0   (Long - 0.000000, Lat - 0.000000)
	Sivasagar	Amguri - Miri Chutia Gaon   Slumped down on 15-06-2023 at Left Bank of Jhanji river near Miri Chutia gaon of Amguri Revenue Circle   0   (Long - 26.762973, Lat - 94.412092),  Sivsagar - Lepai and Akhoiphutia   Slum down on 16-06-2023 at left bank of river Desang at Akhoiphutia and Lepai under Sivasagar Revenue Circle. Report Received from Water Resources on 17-06-2023   0   (Long - 94.580413, Lat - 27.068842)
	South Salmara	Mankachar - Fattapara   AS per report received from I/C Control Room, Hatsingimari W.R Sub-Division, Hatsingimari, an erosion causing damaged of Agriculture land measuring length-150 M & Breadth-2 M, occurred at Revenue village Fattapara on 17-06-2023. AS per report received from Gaon Pradhan has been 2

	1	(T)
		(Two) nos house hold shifted to other place on 17-06-2023.   8   (Long - 25.757626, Lat - 89.890822)
		Udalguri - 1.Dhansiri Irrigation Project 2. Mora Chandana   1. Dhansiri Irrigation Project- a. Breached of
		earthen canal at ch. 2500.0M to ch. 2510.0M(10M) of D2B2M canal of Dhansiri Irrigation Project.( Lat-
		26.710689, Long- 92.104027) b. Breached of Earthen Canal at ch. 2550.0M to ch. 2560M (10M) of D2B2M
		canal of Dhansiri Irrigation Project. (Lat- 26.711307 Long-92.103721 2. Mora Chandana a. CC lining damaged
	Udolovni	at B2M Canal from ch 10870 to 10920 (50m) of Dhansiri Irrigation Project. (Lat- 26.702584, Long-
	Udalguri	92.012847)   0   (Long - 0.000000, Lat - 0.000000),
		Harisinga - 1. No.2 Sagunbahi Village 2. Naobandhagao   1. Erosion continuing at No.2 Sagunbahi village by
		Kalanadi river due to heavy rainfall on 17th June 2023. Approximate damage 10 meters. Long 91.8468 Long-
		26.8532. 2. Erosion continuing at Naobandhagao village by Suklai river due to heavy rainfall on 17th June
		2023. Approximate damage 100meters. Lat 26.7043 Long. 91.7570   215   (Long - 0.000000, Lat - 0.000000)
	District/Sub	2025. Tapproximate damage 100meters. Eat 20170 to Eong. 9117070   215   (Eong. 0.000000)
	-division*	Details
		Haflong - Damadi Hawar, Dihur Phonglo   1. Residence of Veronica Khersa of Damadi Hawar Village Lat:-
	Dima-Hasao	25.302221, Long:- 93.133824 dtd. 17-06-2023 2 Residence of Pramila Daulagupu of Dihur Phonglo Village
		dtd- 17-06-2023. 3. Lower Halflong Road damage. Dated:16-06-2023. 4. Samparidisa to Nobdi
Landslide		Daulagupu.Dated:16-06-2023. Latt:25.258679,Long:93.002024. 5. Dima-Hasao Angling Rood damage on 17-
		06-2023. Latt:25.428867,Long:92.998313. 6. Stone Stepping Stair Damage near Dibarai Lake on 174-06-2023.
		Latt:25.173527,Long:93.007339.   0   (Long - 0.000000, Lat - 0.000000)
		Guwahati - Dhirenpara , Sonali path   One person namely Muktar Ali, age-35, s/o-Lt. Tabizuddin Ali, c/o-
	Kamrup (M)	sunil dad of 2 no.bordoloni, ps- baghbar, Dist: Barpeta was expired due to landslide on 17/06/2023 at around
		7.45 AM.   1   (Long - 26.150124, Lat - 91.727915)
	District/Sub	D. C. II
	-division*	Details
		Silchar - National Highway, Link Road, Ambicapatty, N.S. AVENUE, Sonai Road, Malinibeel, Bilpar,
	Cachar	Nagatilla, Church Road,   Flash Flood due to heavy rain on dated 17.06.2023.   20000   (Long - 0.000000, Lat -
		0.000000)
		Azara - Dharapur   Flash flood and water logged in Dharapur Chariali on 17/06/2023   0   (Long - 26.081400,
Urban		Lat - 91.373900),
Flood	Kamrup (M)	<b>Dispur</b> - Hatigaon, Wireless, Rukminigaon, Baghorbori, No.2 Japorigog   Waterlogging at Sijubari, Wireless
	1	BSNL office's back side, Rukminigaon, Rukminagar side, Baghorbori, Kalitakuchi, Anil Nagar and
		Sorumotoria. 17/06/2023   0   (Long - 0.000000, Lat - 0.000000)
		Nalbari - commerce collage road, veterinary road, collage road, Nalbari-Hajo road, malikuchi road, debiram
	Nalbari	hs road, bhakatpara road, circuit house road, forest office road, debiram road, as per reported by LM under
		Nalbari Rev Circle., these are submerged due to rain water on 17.06.2023   1500   (Long - 0.000000, Lat -
		0.000000)
	1	*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)
		.J.,, .J