

## **FRIMS Assam**



## Flood Reporting And Information Management System

	Assam Daily Flood Report as on 21-06-2023 at 4:00 PM								
Particulars	Situation as on	21-06-202	3 (in last 2	24 hours)					
Rivers flowing above Danger Level (as	Rivers flowing	above dan	ger level	Beki (Road Bridge), Pagladiya (Nt Road Crossing), Puthimari (Nh Road Crossing)					
per CWC bulletin issued at 8 AM)	Rivers flowing flood level	above high	nest	Nil					
District/Sub	No. of Districts/Su b-divisions* Affected	Name of divisions		ected Districts/Sub-	Name of Urban Flood Districts/Sub-divisions*				
-division Affected	20	Chirang, Dibrugar Kokrajha	Darrang, I h, Golagha r, Lakhim	eta, Biswanath, Dhemaji, Dhubri, at, Hojai, Kamrup, pur, Nagaon, Nalbari, r, Udalguri	Bajali, Darrang, Kamrup (M), Kokrajhar, Nalbari				
No. Of Revenue Circles Affected	45			-					
	District/Sub -division*	Total	Revenue	e Circle					
	Bajali	2	Sarupeta	. Bajali					
	Baksa	4		Barama, Baganpara, Jalah					
	Barpeta	1	Barpeta						
	Biswanath	2	Halem, Gohpur						
	Chirang	1	Bijni						
	Darrang	4	Sipajhar, Patharighat, Mangaldoi, Dalgaon						
	Dhemaji	2	Sipajnar, Patnangnat, Mangaidoi, Daigaon  Dhemaji, Sissiborgaon						
	Dhubri	2	Chapar, Agamoni						
Name Of	Dibrugarh	3	Moran, Dibrugarh West, Chabua						
Revenue	Golaghat	1	Moran, Dibrugarh West, Chabua Bokakhat						
Circles	Hojai	2		Bokakhat Doboka, Hojai					
Affected	Kamrup	1	·						
	Kamrup (M)	2	_	Hajo Dispur, Guwahati					
	Kokrajhar	4	Gossaigaon, Bhawraguri, Dotma, Kokrajhar						
	Lakhimpur	2		Bihpuria, Nowboicha					
	Nagaon	2	Kampur						
	Nalbari	6			pari, Tihu, Ghograpar, Barbhag				
	Sonitpur	1	Dhekiaji		. , , , , , , , , , , , , , , , , , , ,				
	Tamulpur	2	, , ,	ar, Tamulpur					
	Udalguri	1	Mazbat	<u> </u>					
	Total	45							
	District/Sub	Total	Revenue	e Circle					
	-division*								
	Bajali Baksa	42 63		ta   32 ), ( Bajali   10 )	aganpara   17 ), ( Jalah   18 )				
		2	( Baska		aganpara   1 / ), ( Jaran   10 )				
	Barpeta Biswanath	37		a   2 )   18 ), ( Gohpur   19 )					
Villages	Chirang	31	( Bijni						
Affected		187	-		), ( Mangaldoi   75 ), ( Dalgaon   16 )				
	Darrang			<u> </u>					
	Dhuhri	3		iji   2 ), ( Sissiborgaon   1	)				
	Dhubri	17		(13), (Agamoni   14)	( ) ( Chehye   1 )				
	Dibrugarh	8		1 ), ( Dibrugarh West   6	) ), ( Cnadua   1 )				
	Golaghat	17	( Bokakl						
	Hojai	11	( Doboka   6 ), ( Hojai   5 )						

	Kamrup	24	( Hajo	24.)								
	Kamup Kokrajhar	145		( Gossaigaon   29 ), ( Bhawraguri   25 ), ( Dotma   90 ), ( Kokrajhar   1 )								
	Lakhimpur	143	1		owboicha   13		a   90 ), ( <b>K</b> 0	Krajiiai   1 )				
	Nagaon	27	· •	ır   10 ), ( No		,						
	Nagaon	21				hil 2 ) ( Noll	ori   11 ) (T	ibu   16 ) (Cl	hograpar   40 ), ( Barbhag			
	Nalbari	108	33)	•	J), ( Danekuc	[ 3 ), ( Naic	Jaii   11 ), ( 1	mu   10 ), ( Gi	nograpai   40 ), ( Baronag			
	Sonitpur	1		ajuli   1 )								
	Tamulpur	42		Goreswar   17 ), ( Tamulpur   25 )								
	Udalguri	1	( Mazba	Mazbat   1 )								
	Total	780							T			
	District/Sub -division*	Male	Femal e	Childre n	Total Populatio n	Population		Crop Area ( in Hect. )	Crop Area Details			
	Bajali	401	306	32	739	( Sarupeta     739 )	0), (Bajali	226.30	( Sarupeta   191.30 ), ( Bajali   35.00 )			
	Baksa	11738	10647	4186	26571	( Baska   38 Barama   13 Baganpara   Jalah   7309	370), ( 14017), (	3873.60	(Baska   43.60), (Barama   37.00), (Baganpara   159.00), (Jalah   3634.00)			
	Barpeta	1701	1383	756	3840	(Barpeta   3		0.00	( Barpeta   0.00 )			
	Biswanath	0	0	0	0	( Halem   0   0 )	), ( Gohpur	429.50	( Halem   30.50 ), ( Gohpur   399.00 )			
	Chirang	0	0	0	0	(Bijni   0)		61.79	(Bijni   61.79)			
	Darrang	536	549	827	1912	( Sipajhar   Patharighat Mangaldoi   Dalgaon   0	316), (   1596), (	3333.34	( Sipajhar   1486.50 ), ( Patharighat   761.94 ), ( Mangaldoi   878.90 ), ( Dalgaon   206.00 )			
	Dhemaji	136	145	85	366	(Dhemaji   0), ( Sissiborgaon   366)		14.00	( Dhemaji   5.00 ), ( Sissiborgaon   9.00 )			
	Dhubri	245	161	170	576	( Agamoni   576 ), ( Chapar   0 )		62.05	( Agamoni   60.00 ), ( Chapar   2.05 )			
Population And Crop Area	Dibrugarh	0	0	0	0	( Moran   0 ), ( Chabua   0 ), ( Dibrugarh West   0 )		181.76	(Moran   0.50), ( Chabua   127.26), ( Dibrugarh West   54.00			
Affected	Golaghat	0	0	0	0	( Bokakhat   0 )		200.00	( Bokakhat   200.00 )			
	Hojai	0	0	0	0	( Hojai   0 ), ( Doboka   0 )		131.83	( Hojai   67.83 ), ( Doboka   64.00 )			
	Kamrup	0	0	0	0	( Hajo   0 )		146.00	( Hajo   146.00 )			
	Kokrajhar	125	111	80	316	( Kokrajhar   260 ), ( Gossaigaon   0 ), ( Bhawraguri   0 ), ( Dotma   56 )		359.10	( Kokrajhar   172.12 ), ( Gossaigaon   29.02 ), ( Bhawraguri   47.76 ), ( Dotma   110.20 )			
	Lakhimpur	12142	12024	930	25096	( Bihpuria   Nowboicha		2.00	(Bihpuria   2.00), ( Nowboicha   0.00)			
	Nagaon	0	0	0	0	(Kampur   0	0), (Raha	1263.58	( Kampur   106.00 ), ( Raha   1157.58 )			
	Nalbari	20018	18113	6576	44707	(Nalbari   330), ( Barbhag   7), ( Paschim Nalbari   455), (Banekuchi   589), ( Tihu   12924), ( Ghograpar   30402)		306.00	( Nalbari   20.00 ), ( Barbhag   38.00 ), ( Paschim Nalbari   22.50 ), ( Banekuchi   47.50 ), ( Tihu   109.00 ), ( Ghograpar   69.00 )			
1	Sonitpur	29	23	13	65	( Dhekiajuli	• •	0.00	( Dhekiajuli   0.00 )			
	Tamulpur	6125	5496	3989	15610	( Goreswar Tamulpur		1.00	( Goreswar   0.00 ), ( Tamulpur   1.00 )			
	Udalguri	15	9	8	32	(Mazbat   3		0.00	( Mazbat   0.00 )			
	Total	53211	48967	17652	119830			10591.85	. ,			
	District/Sub -division*	Total	Relief C				Relief Dist	ribution Cent	tres			
	Baksa	9	5(Baska	3, Barama	ı   1, Baganpaı	ra   1)	4(Baska   1	Barama   3. F	Baganpara   0)			
Relief	Biswanath	4		n   0, Gohpu		·· 1 =/		Gohpur   1)				
Camps /	Dhubri	1	1(Agam	•	1 "/		0(Agamoni					
Centres	Kokrajhar	1	1(Dotma				0(Dotma   0					
Opened	Nalbari	5		2, Ghograp	ar   3)			Ghograpar   0)	)			
	Sonitpur	1			1 ~ /							
			0(Dhekiajuli   0)				( uju	1(Dhekiajuli   1)				
	Tamulpur	9	2(Goras	war   1, Tan	nulmur   1)		7(Coreanie	7, Tamulpui	r   (i)			

	Udalguri	1	0(Mazba	at   0)			1(Mazbat	1)		
	Total	31	14	1 - 7			17	,		
	District/Sub -division*	Total	Revenue	e Circlewis		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y
	Baksa	1157	(Baska   660), (Barama   139), (Baganpara   358), (Jalah   0)			423	420	278	16	20
Inmates In	Dhubri	193		(Chapar   0), (Agamoni   193)			54	61	0	0
Relief	Kokrajhar	56	` .		hawraguri   (Dotma   56)	15	21	20	0	0
Camps	Nalbari	614	(Paschin (Baneku (Tihu   6 (Ghogra	n Nalbari   ( chi   0), (Na 59), (Barbha par   545)	0), albari   0), g   0),	295	237	57	24	1
	Tamulpur	71	(Goresw 16)	rar   55), (Ta	amulpur	34	25	12	0	0
	Total	2091				845	757	428	40	21
Human Lives Lost - Confirmed Human Lives Lost	Nil									
Confirmed - Death Type	Nil									
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
	District/Sub	Total	Big	Small	Poultry					
	-division*				•					
	Bajali	1210	720	490	0					
	Baksa Biswanath	25042 5044	9521 3115	5596 1929	9925					
Animals		9313	5548	3765	0					
Affected	Darrang Dibrugarh	5256	4197	1059	0					
Affected	Lakhimpur	7079	5492	1587	0					
	Nalbari	52840	19329	17651	15860					
	Tamulpur	1690	1010	680	0					
	Udalguri	5	3							
	Total	107479	48935	32759	25785					
Animals Washed	District/Sub -division*	Total	Big	Small	Poultry					
Away	Baksa	1	1	0	0					
Houses	Total  District/Sub -division*	Fully Kucch	Fully Pukka	Fully Total	0 Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
Damaged	Baksa	0	0	0	2	0	2	0	0	0
	Kokrajhar	1	0	1	1	0	1	0	0	0
	Total	1	0	1	3	0	3	0	0	0
	District/Sub -division*	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d
Rescue	Bajali	SDRF		a .	0	0	0	0	0	2
Operation	Baksa	Fire & Ei (F&ES),	mergency SDRF	Services	6	390	0	0	0	2
	Biswanath				0	0	0	0	0	4
	Dhubri				0	0	0	0	0	1
	Lakhimpur	CDDE			0	0	0	0	0	3
	Nalbari	SDRF			2	325	0	0	0	0

	Tamulpur	Circle Office/Local Administration, Green 'Adventure, Sikhar Adventure, Sikhar Adventure, Sikhar Adventure, Fire & Emergency Services (F&ES), NDR SDRF, GREEN TREK		een Trek Adventure litary gency IDRF,	10	565	0	0	0	2
	Total				18	1280	0	0	0	14
	District/Sub -division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed	- Rice Bran (	in Q)
Relief	Baksa	10.88	1.99	0.60	0.60	0.00	0.00	0.00		
Distributed	Biswanath	0.00	0.00	0.00	0.00	0.00	110.00	93.90		
	Sonitpur	0.77	0.16	0.05	0.00	0.00	0.00	0.00		
	Tamulpur	33.99	6.12	1.84	183.50	0.00	108.60	0.00		
	Udalguri	0.53	0.10	0.03	2.88	0.00	0.00	0.00		
	Total	46.17	8.37	2.52	186.98	0.00	218.60	93.90		
	District/Sub	Baby Foo	od	Baby Foo	d Solid	Others				
	-division*	Liquid		-	u bonu					
Relief	Baksa	0.00-Q		0.00-Q		Candle-78.0	00-Pieces; So	aps-78.00-Pied	es; Maxo Coi	l-60.00-Pkt
Distributed	Biswanath	0.00-Q		0.00-Q		0.0				
Others	Sonitpur	0.00-Q		0.00-Q		0-0.00-Q				
	Tamulpur	0.00-Q		0.00-Q						
	Udalguri	0.00-Q		0.00-Q						
	District/Sub -division*	Numbe r	Details							
Infrastructur e Damaged - Embankme nt Breached	Baksa Nalbari Total	Barama - Breach occurred on L/B of Mora Pagladia   Alagjar   Breach occurred Pagladia river at village Alagjar near Charanpara supa at a stretch of 200 m da (Long - 91.357248, Lat - 26.540695, Dept - Water Resource Deptt.),  Breach occurred on R/B embankment of Kaljhar Village   Kaljhar Village Near Breach occurred on R/B embankment of Kaljhar Village Near Breach College at approx. dated-21/06/2023   (Long - 91.362613, Lat - 26.531607, Dept - Water Breach occurred on L/B of Mora Pagladia   Alagjar   Breach occurred on L/B of river at village Alagjar near Madhya Alagjar supa of stretch of 25 m approx.dt (Long - 91.362613, Lat - 26.531608, Dept - Water Resource Deptt.)  Tihu - ROAD CUM EMBANMENT,R/B MORA PAGOLDIA RIVER   GOB LENGTH IS APPROX : 40 MTS, REPORTED BY DEPARTMENTAL OFFI 21/06/2021   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.)				Near B.ed Collector at a stretch of the American Parameter Resource I (B) of Mora Para.dtaed-21/06/EOBARADAL FFICIALS Da	2023   lege.   f 10 m Deptt.), gladia 2023			
	District/Sub	Numbe	Details							
	-division*	r								
Infrastructur e Damaged - Embankme	Bajali	3	Sarupeta - Ringbundh of Pahumara River   Village: Nakuchi Pather   Report received from concerned LM on 21th June,2023 at 9 am   (Long - 91.086815, Lat - 26.437753, Dept - P&RD),  Bajali - Embankment of Kaldia at Sariha Chakla   Sariha Chakla   Report received from Chairman Patacharkuchi MB dated 21/06/2023 at 10AM   (Long - 91.238575, Lat - 26.529092, Dept - Municipal Road),  Embankment of Kaldia at Golibandha   Golibandha near GP office   Report received from concerned LM dated 21/06/2023 at 8AM   (Long - 91.160469, Lat - 26.443195, Dept - P&RD)							&RD), Chairman ot - 1 &RD)
nt Affected	Biswanath	1	Gohpur - R/Bank embankment of Sessa   at Auguri area mild Bank Erosion observed of length 50							length 50
	Nalbari	2	Nalbari 7300 Da Pagaldia	mtr on 21/06/23   (Long - 93.737047, Lat - 26.952548, Dept - Water Resource Deptt.)  Nalbari - Nalbari Sonkuriha embankment at Pagaldia river   Sondha   Side Berm damaged at Ch 7300 Dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.),  Pagaldia embankment at Doulgobindapur ward no-4, Bolakuchi   ward no-4, Bolakuchi   Dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.)						
	Total	6								
	District/Sub -division*	Numbe r	Details							
Infrastructur e Damaged - Road	Bajali	3	Bajali - Patacharkuchi to Nityananda   Kuwara   Report received from AEE, PWD Roads dated 21/06/2023 at 10AM   (Long - 91.227660, Lat - 26.525417, Dept - PWD (NH Roads)), Nityananda to Pipla   Pipla   Report received from AEE, PWD Roads dated 21/06/2023 at 10.30 AM   (Long - 91.256251, Lat - 26.527099, Dept - PWD (NH Roads)), Nityananda to Akaya   Kaharpara   Report received from AEE, PWD Roads dated 21/06/2023 at 10.30 AM   (Long - 91.207493, Lat - 26.599310, Dept - PWD (NH Roads))							t 10.30 2023 at
	Baksa	1			dham to Baga - 0.000000, L				21/06/2023 app	orox 40 mtr

Barpeta	1	<b>Barpeta</b> - Kadamguri Charichain Road   Kadamguri   As per report received from PWD Dept. a portion of Kadamguri Charichain Road washed away by Flood sater. Date:21/06/2023   (Long -
Бшреш	1	90.994956, Lat - 26.389730, Dept - PWD (Roads))
Bongaigao	n 17	Manikpur - Dangaigaon kirtanpara Road   Dangaigaon   Water logging from Ch.1000.00m to Ch.1200.00m and Road surface damaged. as per report received from PWRD, Bongaigaon dated-21.06.2023   (Long - 90.736267, Lat - 26.441949, Dept - PWD (Roads)), Bhandara pt.1 to Bhandara pt.V PMGSY Road   Bhandara   Submerged from Ch.2750.00m to Ch.2950.00m, submereged depth is 45cm.as per report received from PWRD, Bongaigaon dated-21.06.2023   (Long - 90.748306, Lat - 26.424079, Dept - PWD (Roads)), Bongaigaon - Kharija Dolaigaon pt.11 to SSB camp Road   Kharija   Shoulder and ICBP hard crust damaged at Ch.2nd Kmas per report received from PWRD, Bongaigaon dated-21.06.2023   (Long - 90.580864, Lat - 26.487310, Dept - PWD (Roads)), SH2 to Kukurmari Sutarpara Road via PWRD Office   Sutarpara Road   Erossion and depression occurred at hard crust portion near FCI road at 1st Km.as per report received from PWRD, Bongaigaon dated-21.06.2023   (Long - 90.544766, Lat - 26.490591, Dept - PWD (Roads)), Bongaigaon dated-21.06.2023   (Long - 90.544766, Lat - 26.490591, Dept - PWD (Roads)), Bongaigaon Bakrivita road   Bhakrivita   Hard crust damaged and pot hole occurred at Ch. 2nd Km. as per report received from PWRD, Bongaigaon adated-21.06.2023   (Long - 90.546857, Lat - 26.498114, Dept - PWD (Roads)), Bongaigaon college to Dolaigaon road   Dolaigaon   Road surface damaged and water stagnant at various surfaces at Ch.000 to Ch.200.00m.as per report received from PWRD, Bongaigaon dated-21.06.2023   (Long - 90.538297, Lat - 26.484983, Dept - PWD (Roads)), Bougingaon college to Dolaigaon road   Dolaigaon   Road surface damaged and water stagnant at Ch.0.00 to Ch.180.00m.as per report received from PWRD, Bongaigaon dated-21.06.2023   (Long - 90.563631, Lat - 26.408217, Dept - PWD (Roads)), B.Ed College approach Road   B.Ed College   Hard crust and shoulder damaged and water stagnant at Ch.000 to Ch.180.00m.as per report received from PWRD, Bongaigaon dated-21.06.2023   (Long - 90.679589, Lat - 26.38964, Dept - PWD (Roads)),  B.Ed College a
Chirang	2	Bijni - Bijni Subhaijhar Road to No 1 Sisubari   No 1 Sisubari   As reported by PWD Bijni (R&B) Sub Division, Bijni Subhaijhar Road to No 1 Sisubari damaged at No 1 Sisubari. Length=3.50 mtr, Breadth= 2.50 mtr, Depth=2.00 mtr. Date of Occurrence=21-06-2023   (Long - 90.638557, Lat - 26.523069, Dept - PWD (Roads)), Borobazar Bhabanipur Road to No 2 Dogorpara   No 2 Dogorpara   As reported by PWD Bijni (R&B) Sub Division, Borobazar Bhabanipur Road to No 2 Dogorpara road damaged at No 2 Dogorpara. Length=20.00 mtr, Breadth= 2.00 mtr, Depth=3.50 mtr. Date of Occurrence=21-06-2023   (Long - 90.619491, Lat - 26.596530, Dept - PWD (Roads))
Darrang	4	Patharighat - Turai to Taragaon Road   Taragaon   As reported by JE, PWD Road submerged at length 1 km dated.21/06/2023   (Long - 26.424246, Lat - 91.821298, Dept - PWD (Roads)), MPK to Hussainchubri Road   Hussainchubri   Road submerged at length CH. 1 km Length L= 600 mt Depth 0.40 mt.dated.21/06/2023   (Long - 91.816143, Lat - 26.500555, Dept - PWD (Roads)), MPK road at 21st km   MPK Road   As reported ,Submerged length=300m, depth = 0.35m.dated.21/06/2023   (Long - 91.845116, Lat - 26.483933, Dept - PWD (Roads)), Dalgaon - Barhabi to Mazgaon road   Barhabi to Mazgaon road   As per report received from

ı	1	
		PWD(R) barhabi to mazgaon PMGSY road shoulder has been damaged at Ch-1650m. immediate restoration is required. Date of occurrence- 20/06/2023   (Long - 92.126601, Lat - 26.637039, Dept - P&RD)
Dhubri	2	Chapar - NH 31 at Chirakuta to Tokrabandha quarry road surface damaged on Dated 20-06-2023   Chirakuta   Road damaged due to over flow of water by the river Gaurang   (Long - 90.242500, Lat - 26.220760, Dept - PWD (Roads)),  Road from Chirakuta to Jamduar pt -I submerged due to water on Dated 20-06-2023   Jamduar Pt-I   Road damaged due to over flow of water by the river Gaurang   (Long - 90.242700, Lat - 26.220600, Dept - PWD (Roads))
Goalpara	1	Matia - Garomari to Nabagata Simlitola   Nabagata Simlitola   Road submerged from Ch. 2600 M to 2800 M and from 2900 M to 3100 M and the approach of Bridge No 3/1 has been eroded and subsided, Date - 20/06/2023, reported by AEE, PWRD, Goalpara East Territorial Road Sub-Division, Goalpara   (Long - 90.884238, Lat - 26.078810, Dept - PWD (Roads))
Kamrup	2	Goroimari - Road Submerged length 150 m breadth 6m Tukrapara to Dakhin Choudharypam as reported by AEE, PWRD, Chhaygaon, dtd- 20.06.2023   Goroimari     (Long - 91.196227, Lat - 26.090307, Dept - PWD (Roads)),  Road Submerged length 100 m breadth 6m Bowrabhitha to Monjuribilor Dhundhuntari as reported by AEE, PWRD, Chhaygaon, dtd- 20.06.2023   Goroimari     (Long - 91.210927, Lat - 26.083880, Dept - PWD (Roads))
Kokrajhar	9	Bagribari - BASHBARI MOWAMARI ROAD   Mowamari   As reported by Executive Engineer, PWRD, Dhubri Civil Sub-Division, Territorial Road Division side berm, hard crust have been badly damaged and eroded due to heavy rainfall in last few days. Date-21.06.2023   (Long - 89.997472, Lat - 26.086477, Dept - PWD (Roads)),  Gossaigaon - Panbari to Sialmari Road   Panbari & Sialmari   As reported by AEE PWD RR Kachugaon Sub division Dated 21.06.2023 due to continous rainfall right side of road formation is badly erosion (L-120.00M) by the Sialmari River   (Long - 90.053435, Lat - 26.511800, Dept - PWD (Roads)),  Bhawraguri - Rupshi Pt II to Rupshi Railway Gate (Kumguri beel to near choutara Railway line PWD Road to Rupshigaon Pt II)   Eroded at Ch 300.00 m   As reported by AEE PWD RR Kachugaon & BDO, Gossaigaon due to incessant heavy rainfall from 16th June, 2023 to 21.06.2023 at Rupshigaon pt ii village rupshi pt ii to rupshi railway gate Road formation eroded at ch 300.00m   (Long - 26.405640, Lat - 90.075860, Dept - P&RD),  Dotma - Serfanguri Gossainichina Road   Serfanguri   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Serfanguri Gossainichina Road Br. No.1/1 approaches eroded   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Serfanguri to Kumguri via Laokriguri   Kumguri   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Serfanguri to Kumguri via Laokriguri Br. No.1/1 approach road eroded.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Jogdoi Fakiragram road   Jogdoi   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Gomobil Angthihara road   Gomobil   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Gomobil Angthihara road bridge approach eroded at Br. No.3/1, 6/1, 6/2.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Gomobil Angthihara road   Gomobil   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Gomobil Angthihara road bridge approacheroded at Br. No.3/1, 6/1, 6/2.   (Long - 0.000000, Lat - 0.000000, Lat - 0.000000, Lat - 0.0
Lakhimpur	2	Nowboicha - NH-15 at Rajali to Haripur Balitika Road   Balitika   NH-15 at Rajali to Haripur Balitika, overtopped and erosion, breaches at CH:3000M to CH:6500 M, breached at CH:3500 M on 21.06.2023. Report received from PWD (Roads)   (Long - 27.133053, Lat - 94.001978, Dept - PWD (Roads)),  NH-15 to Mahghuli Borchala Road   Solmoria   NH-15 to Mahghuli Borchala Road, overtopped from CH:1600 M to CH:4500 M on 21.06.2023. Report received from PWD(Roads)   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
Nagaon	2	Kampur - Road from Chankchaki to Bakulaguri   Chankchaki to Bakulaguri   Road from Chankchaki to Bakulaguri (PMGSY-11, Pkg No. AS-19-715): Embankment erosion took place at Premajaan. Affected length approx. L= 100.00 m. date- 19/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Road from Kumbhirdubi to Chiropathar   Kumbhirdubi to Chiropathar   Road from Kumbhirdubi to Chiropathar (PMGSY-1, Pkg No. AS-19-462): Erosion took place at different stretches. Affected length pprox. L= 400.00m date- 19/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
Nalbari	15	Paschim Nalbari - Tihu Lachima Road to Lakhopur via Kendubari   Kendubari   Submerged due to flood water. Information received from PWD (R) Department on 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Chamaa Kaithalkuchi Road   Chamata   Submerged due to rain water. Information received from

		1	DVID (D) D
			PWD (R) Department on 20/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), <b>Banekuchi</b> - On 20/06/2023 at 7.00 PM Mohan Bazar Chowk to Banekuchi Chowk PWD road
			submerged appr.200 mtr. report from Gaon Pradhan   Rajakhat Banekuchi     (Long - 91.395332,
			Lat - 26.459034, Dept - PWD (Roads)), <b>Barkhetri</b> - Loharkatha-Bezkuchi Road   HAMLAKUR   Due to incessant heavy rain for last few
			days, road side berm eroded and damaged by creating hole at 3rd Km on Loharkatha Bezkuchi
			Road as reportyed by AEE, PWRD, Barkhetri Teritorial Sub Div. on 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
			Ghograpar - Nalbari - Dhamdhama Road   Balitara   Submerged at Nalbari dhamdhama road to
			Pub Balitara on 21-06-2023   (Long - 91.470000, Lat - 26.510000, Dept - PWD (Roads)),
			Ghograpar tamulpur Road Nalbari   Arara   Submerged at Ghograpar Tamulpur Road Nalbari on 21-06-2023   (Long - 91.570000, Lat - 26.480000, Dept - PWD (Roads)),
			Rangia Dhamdhama Road   Dhamdhama   Submerged at Rangia Dhamdhama Road on 21-06-2023
			(Long - 91.480000, Lat - 26.550000, Dept - PWD (Roads)), Gohain Kamal Ali Road   Chataibari-Dhamdhama   Gohain Kamal Ali Road submerged due to
			flood on 21-06-2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
			PWD IB Dhamdhama   Dhamdhama   PWD IB Dhamdhama submerged due to flood water on 21-
			06-2023   (Long - 91.470000, Lat - 26.550000, Dept - PWD (Roads)),  Barbhag - PMGSY Road Dokoha to Mathura road   Dokoha   Length: 8 km submerged dated:
			21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
			PMGSY Mathura sala road   Khudra Tingtingi   Length: 6 km submerged dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
			Athgharia Barbukia road under signature project   Athgharia   Length : 7.50km submerged dated:
			21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),   Sanekuchi-Bargasha road   Sanekuchi   Length : 3 km. submerged dated: 21/06/2023   (Long -
			0.000000, Lat - 0.000000, Dept - PWD (Roads)),
			Barsimalia Village road   Barsimalia   Length: 2.10km submerged dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
			GBD to Barbukia road   Barbukia   Length : 2.10km submerged dated: 21/06/2023   (Long -
			0.000000, Lat - 0.000000, Dept - PWD (Roads))
			<b>Tamulpur</b> - Due to heavy rainfall and flash flood Patkijuli Hatiduba Firing Range culvert and approach road got damaged on 21 June 2023   Hatiduba     (Long - 91.491448, Lat - 26.781797,
			Dept - PWD (Roads)),
			Due to heavy rainfall and flash flood Dowamakha village road damaged on dated 21 june 2023   Dowamakha     (Long - 91.655155, Lat - 26.660245, Dept - PWD (Roads)),
	Tamulpur	5	Due to heavy rainfall and flash flood Hahkata Balabari road Sub-Marge (Ananda Bazar Hahkata
	Tunnunp un		Balabari road) damaged on 21/06/2023   Hahkata     (Long - 91.516315, Lat - 26.637378, Dept - PWD (Roads)),
			Boraliapar Iron Bridge damaged on 21 June 2023   Boraliapar     (Long - 91.655076, Lat -
			26.657136, Dept - PWD (Roads)), Daranga Bridge in kumarikata got affacted 21 June 2023   Kumarikata     (Long - 91.514079, Lat -
			26.729985, Dept - PWD (Roads))
			<b>Mazbat</b> - Erosion occurred at left side of the Mazbat-Deochani road from Ch- 12500 M to 12850 M due to heavy rainfall on 20/6/2023   Mazbat-Deochani road     (Long - 92.332017, Lat - 26.857267,
			Dept - PWD (Roads)),
			Erosion occurred at Ch- 3000 M, approx length 50m, width 4.50m, depth 3m of the Manuhmari to
			Gariapthar road due to heavy rainfall on 20/6/2023   Manuhmari to Gariapthar road     (Long - 92.369075, Lat - 26.709564, Dept - PWD (Roads)),
			Damages of both side approaches of RCC slab culvert 4.00m span on Alisinga to Rowmari road due
	Udalguri	6	to heavy rainfall on 20/6/2023   Alisinga to Rowmari road     (Long - 92.317950, Lat - 26.675120, Dept - PWD (Roads)),
			Earthen shoulder eroded at approximately length 100.00m, depth 2.00m on Mazbat-Gelabil road
			due to heavy rainfall on 20/6/2023   Mazbat-Gelabil road     (Long - 92.282567, Lat - 26.774485, Dept - PWD (Roads)),
			Damage of both side approches of RCC slab culvert on NH-15 to Simaluguri road near Bathow
			Mandir due to heavy rainfall on 20/6/2023   NH-15 to Simaluguri road near Bathow Mandir     (Long - 92.258600, Lat - 26.680759, Dept - PWD (Roads)),
			Damages of HPC culvert on MRL05-Orang Dalgaon road under PMGSY-III due to heavy rainfall
	Total	72	on 20/6/2023   Orang Dalgaon road     (Long - 92.182400, Lat - 26.381700, Dept - PWD (Roads))
	District/Sub	Numbe	Details
	-division*	r	Baganpara - Thakursupa to Jartaluk connecting rcc bridge damaged on dated 21/06/2023
Infrastructur	Baksa	1	Thakursupa   Road is completely disconnected   (Long - 91.484416, Lat - 26.576328, Dept - PWD
e Damaged - Bridge			(Roads))  Barpeta - Kujarpith Bonbaha Raod to DK Road   Betbari   As per report received from PWD Dept
Dilugo	Barpeta	1	a Bamboo foot bridge is partially affected on 21/06/23   (Long - 91.017104, Lat - 26.406384, Dept -
	Down	1	PWD (Roads))  Polygon, BCC Pr No 14/1 on Polygon to Dhyrgoni via downyllhyni godd BCC Pr No 14/1 on
	Darrang	1	<b>Dalgaon</b> - RCC Br No.14/1 on Dalgaon to Dhupguri via devpukhuri road   RCC Br No.14/1 on

	Kokrajhar	3	Dalgaon to Dhupguri via devpukhuri road   As per report received from PWD(R), due to heavy rain & incessant rainfall the approach of RCC br no.14/1 on Dalgaon to Dhupguri via devpukhuri road under Asom Mala project (package no.CE/AM/SOPD(L1)/35/2020-21/5) has been badly damaged. Immediate restoration is required. Date of occurrence - 20/06/2023   (Long - 92.316065, Lat - 26.613227, Dept - PWD (Roads))  Bagribari - Bridge No.4/1   Bongshijhora to Monglajhora Road   As reported by Asstt. Exec. Engineer, PWD (RR) Sub-Division Gossaigaon, Damaged due to the incessant heavy rainfall. Date: 20-06-2023   (Long - 89.973048, Lat - 26.247123, Dept - PWD (Roads)),  Bridge No.4/1   Bongshijhora to Monglajhora Road   As reported by Asstt. Exec. Engineer, PWD (RR) Sub-Division Gossaigaon, Damaged due to the incessant heavy rainfall. Date: 20-06-2023   (Long - 89.971291, Lat - 26.247542, Dept - PWD (Roads)),  Bridge No.4/3   Bongshijhora to Monglajhora Road   As reported by Asstt. Exec. Engineer, PWD (RR) Sub-Division Gossaigaon, Damaged due to the incessant heavy rainfall. Date: 20-06-2023   (Long - 89.972507, Lat - 26.247179, Dept - PWD (Roads))				
	Nalbari	1	Paschim Nalbari - RCC Bridge No.1/1 on Barbila Chowk to Lakhopur via Sarabari   Lakhopur   Approaches badly damaged due to flood water. Information received from PWD (R) Department on 21/06/2023.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))				
	Total	7					
Infrastructur e Damaged - Wildlife	Nil						
	District/Sub	Other D	etails				
	-division*						
	Baksa	91.34704 Power Do 21/06/20 Culvert A 26.63336	Road Breaches   Road breached at Tekelibhanga to Doomni village Doomni Coordinate: 26.644772, date: 21/06/2023., ept. Poles   1 no. HT pole uprooted at village Narayanpur Coordinate: 26.709654, 91.347878 date: 23., approach Road Damaged   Chaibari to Panbari connecting road Slab culvert damaged. Cordinate: 4, 91386898, Date: 21/06/2023., eaches   Dhanbil to Chaibari Connecting CC Block Road damaged. Cordinate: 26.640733, 91.390791				
Infrastructur e Damaged - Others	Chirang	Bijni - Road Breaches   As reported by concerned LM, due to incessant rain village road of village Batabari is reported to be damaged. Length=3.04 mtr, Breadth=3.6mtr, Dept=1.21 mtr. Latitude=26.512399 Longitude=90.69214 Date of Occurrence=21-06-2023., Sidli - Bamboo Foot Bridge   As reported by AE, PWD Chirang (R&B) Division, Kajalgaon, NH-31(C) Athiabari to Dhupguri road , Bamboo foot bridge at Ch.787.00m over river Suthi washed out at Athiabari Location- Latitude-26.556649, Longitude-90.423385, Damage details- Length -30.00m , Breadth-3.50m , Depth-4.50m date of occurrence -21-06-2023, Culvert Approach Road Damaged   As reported by AE, PWD Chirang (R&B) Division, Kajalgaon, Dangshibari village road , Culvert approach road damaged at Dangshibari Location- Latitude-26.593069, Longitude-90.45741, Damage details- Length -5.00m , Breadth-4.00m , Depth-3.00m date of occurrence -21-06-2023, Irrigation Canal/Scheme Damaged   As reported by JE, Sidli Sub-Division (Irrigation), Irrigation Canal Embankment damage from Ch.6829.50m to Ch. 6834.50 at Taktara village of LBC-6 Location- Latitude-26.529336, Longitude-90.430933 , damage details-Length -15.00m , Breadth-3.50m , Depth-2.80m date of occurrence- 21-06-2023, Bengtal - Culvert Approach Road Damaged   As reported by AEE, PWD Chirang (R&B) Division, Kajalgaon, Bamungaon Aujhar road Culvert approach damaged at Garlabari FV Location- Latitude-26.59522, Longitude-90.43821, Damage details- Length -4.50m , Breadth-2.50m , Depth-3.00m and Latitude-26.59532 Longitude-90.43821, Damage details- Length -4.50m , Breadth-2.50m , Depth-3.00m and Latitude-26.59532 Longitude-					
	Darrang	Patharighat - Fisheries/Pond   As reported by Fishery Deptt. 67.47 Hectare area of pond submerged dated.21/06/2023,  Mangaldoi - Power Dept. Poles   As per report received from APDCL Mangaldai approx.5 poles are dama Dated 21/06/2023,  Power Dept. Conductors   As per report received from APDCL Mangaldai approx. 1.5 km conductor are damaged. Dated 21/06/2023,  Road Breaches   Baigormari to Magurmari No.1 road breached, breach length 7 M approx. Lat-26.480247, Long-92.145739 under Pub Mangaldai Rev. Circle,dated.21/06/2023,  Dalgaon - Fisheries/Pond   as per report received from fishery department, 10 nos of beneficiary,10 nos ta water area 3.95 Ha at village No.2 Sialmari has been affected under Dalgaon Revenue Circle.Date of occurrence - 20/06/2023,  Power Dept. Conductors   As per report received from SDE,APDCL, kharupetia, 33kv conductor snap due uprooting of a huge tree.Date of occurrence - 21/06/2023,  Power Dept. Poles   As per report received from SDE,APDCL, kharupetia, 1 no of pole due to uprooting o huge tree has been damaged.Date of occurrence - 21/06/2023					
	Dhemaji	to Ch.230 m, Dated	kh - Bridge Approach Road Damaged   Old NT Road at Padumoni to Deogorhbari; At Ch. 200.00m   0.00m; Longitude:94°24'59'', Latitude:27°25'15''N; Dhemaji Territorial Road Division, Length-30 : 21/06/2023,   pproach Road Damaged   Bordoloni Chariali to Nagaon Road; At Ch. 150.00m to Ch.200.00m;				

		Longitude:94°25'19'', Latitude:27°24'53''N; Dhemaji Territorial Road Division, length- 50 m, Dated: 21/06/2023
	Kokrajhar	Gossaigaon - Damaged SPT Bridge   As reported by BDO, Kachugaon Dev Block, Dated 21.06.2023 due to heavy rainfall No.2 Bhomrabil wooden bridge damaged near SSB camp, Damaged SPT Bridge   As reported by BDO, Kachugaon Dev Block, Dated 21.06.2023 due to heavy rainfall Ballamguri to Polashguri Wooden Bridge damaged, Damaged SPT Bridge   As reported by Gossaigaon Municipal Board Dated 20.06.2023 due to heavy rainfall Wooden Bridge damaged near Giridhari Ashram connecting Gossaigaon Ward No.1 and Ward No.4, Damaged SPT Bridge   As reported by Municipal Board Dated 20.06.2023 due to heavy rainfall Wooden Bridge damaged at Samshamkola connecWard No.1 and Ward No.4, Damaged SPT Bridge   As reported by Gossaigaon Municipal Board Dated 20.06.2023 due to heavy rainfall Wooden Bridge damaged near Ananta Kutir L.P. School connecting Gossaigaon Ward No.2 and Ward No.3, Bamboo Foot Bridge   As reported from AEE PWD RR Gossaigaon Sub Division, Dated 21.06.2023 due to Heavy rainfall Bamboo Foot Bridge No. 1/1 has been washout at Dingdinga Mandarkuti Road, Damaged SPT Bridge   As reported from AEE PWD RR Gossaigaon Sub Division, Dated 21.06.2023 due to Heavy rainfall Harafuta to Simultapu Road via Nayagaon Road, Washout Bridge No.2/1, Bhawraguri - Agri Bundh Damaged   As reported by BDO Kachugaon development block due to incessant heavy rain from 14th June, 2023 to 21.06.2023 dhodhora bund at Dakhin Mukuldang village near Raju's paddy field is badly damaged (Lat: 26.480671, long:90.093411), Agri Bundh Damaged   As reported by BDO Kachugaon development block due to incessant heavy rain from 14th June, 2023 to 21.06.2023 North Chekadani bund at Dakhin Mukuldang village near Pradip's paddy field is badly damaged (Lat: 26.485303, long:90.086181)), Bridge Approach Road Damaged   As reported by AEE PWD RR Kachugaon due to incessant heavy rainfall from 16th June, 2023 to 21.06.2023 at Asharikandi Kartimari village Bhawraguri Sapatgram Road Bridge
	Lakhimpur	approach eroded at Br. No. 20/1(Lat: 26.346232, long:90.108015) <b>Subansiri</b> - Bamboo Foot Bridge   As reported by Dhakuakhana Territorial Road Division, Ghilamara the Bamboo Foot Bridge on Kekuri Madhupur to Chelajan Kachari road is damaged (L= 110M) on 21/06/2023, Bamboo Foot Bridge   As reported by Dhakuakhana Territorial Road Division, Ghilamara the Bamboo Foot Bridge on Kekuri Madhupur to Balijan Kachari road is damaged (L= 150M) on 21/06/2023, Bamboo Foot Bridge   As reported by Dhakuakhana Territorial Road Division, Ghilamara the Bamboo Foot Bridge on Relidence of the Managed of the 125M) on 21/06/2023
	Majuli	Bridge on Balideori to Manordeori road is damaged (L= 125M) on 21/06/2023  Ujani Majuli - Bamboo Foot Bridge   Due to rise of Flood water of a tributary of River Brahmaputra communication of the following villages have been cut off 1) Lachon Chapori - Lachon Dhunaguri from 20/6/2023. Reconstruction of the Bamboo Bridge is going on.,,  Bamboo Foot Bridge   Due to rise of Flood water of a tributary of River Brahmaputra communication of the following villages have been cut off between Ratanpur Gayan and Bonoriya Chapori from 20/6/2023. Reconstruction of the Bamboo Bridge is going on.
	Nalbari	Barkhetri - Damaged RCC Bridge   Due to incessant heavy rain for last few days both the approaches of RCC Br1/1 on Mukalmua Bhangnamri Ferry Ghat road badly eroded and damaged on North side 60m and on Soth side 50m as reportyed by AEE, PWRD, Barkhetri Teritorial Sub Div. on 21/06/2023,  Tihu - Agri Bundh Damaged   BREACHED NEAR TIHU AKHARA PWD ROAD RCC BRIDGE ,MORAPAGOLDIA (L/B),BOPROSUPA ,SIALMARI,BALI , LENGTH IS APPROX 40FTS ,DAMAGED ON 20/06/2023 AS PER REPORT GP , Agri Bundh Damaged   BEREACHED NEAR KAIHATIPARA SUPA,BALI OF MORA PAGOLDIA (L/B),LENGTH APPROX 60 FTS ,DAMAGED ON 20/06/2023 REPORTED BY GP ), Agri Bundh Damaged   BREACHED NEAR CREMATION GROUND ,MAHAJANPARA SUPA, BALI ,(R/B)MORA PAGOLDIA RIVER , LENGTH IS APPOX 30 FTS ,DAMAGED ON 20/06/2023 REPORTED BY GP , Ghograpar - Culvert Approach Road Damaged   On 21-06-2023 Culverthas been damaged on ghograpar Tamulpur Road, Lat - 26.48, Long -91.57
	Udalguri	Khairabari - Washed away Culverts   Due to overflow of downpour, the HPC measuring 10 × 5 M approx. on the Bhergaon - Tangla road has been eroded at Bar Tangla, disrupting the overall communication on 19.06.2023. Lat: 26.652593 Long: 91.878958,  Harisinga - Washed away Culverts   Purani Bhergaon to Borhola village road. One HPC wash out at village Jabangahabi due to heavy rainfall on 20th June 2023. LAT 26.6692 LONG 91.8040.,  Irrigation Canal/Scheme Damaged   Socha FIS right canal embankment breach for length approximate 100m at different changes and breadth 2.5m at village no.2 bamunjuli due to heavy rainfall on 18th June 2023. LAT 26.8089 LON 92.8322.,  Irrigation Canal/Scheme Damaged   Geruapara FIS canal embankment breached for length 100m at different changes and breadth 2.5m along with canal outlets damaged. At village Patala due to heavy rainfall on 18th June 2023 LAT 26.6990 LON 91.8364
	District/Sub -division*	Details
Erosion	Baksa	<b>Baganpara</b> - Borikadonga Barman supa   As per SDO WR on dated 20/06/2023 at Borikadonga approx 300 meter has been eroded on R/B of river Pagladia.   300   (Long - 91.472415, Lat - 26.699782)
	Barpeta	<b>Kalgachia</b> - Showpur   Showpur , Kurakur, nera Beki bridge, SH-2, reported by LM on 20.06.2023   0   (Long - 90.887857, Lat - 26.339905),
	1	Chenga - Roumari Pathar Bazar (700 m), Balartari (600 m)   B/dyke on R/B of river Brahmaputra from

		Adabari to Kukarjan from ch 5.80 km to 33.232 km Information received from Water Resource department on 21.06.2023   0   (Long - 0.000000, Lat - 0.000000)
		Biswanath - 4 No. Kumalia (Forciati)   continuous active ban erosion is observed at Forciati area in between Ch.3rd to 4th Km of Biswanath-Panpur and 6th to 7th Km of Solmari Kalakati area of Biswanath-Panpur Dyke of river Brahmaputra as per report from water resources. 21/06/2023   0   (Long - 93.126548, Lat - 26.685488), Halem - Paken   River Brahmaputra -Mild bank erosion is observed at Paken area of B/Dyke from Jamuguri to
	Biswanath	Kharoi outfall. 21/06/2023 Length = 10.00m, Latitude:, Longitude:   0   (Long - 93.625317, Lat - 26.799672), <b>Gohpur</b> - At Gopsarguri   Mild bank erosion is observed on marginal embankment on R/Bank of river Sessa of length 50 mtr on 21/06/23   0   (Long - 93.716944, Lat - 26.979166),
		Naduar RC part - No-2 Bhojmari & Kalakati   Dated 21/06/2023, As reported by Biswanath WR Subdivision, (1) active bank erosion is observed at No-2 Bhojmari area on the R/Bank of river Brahmaputra of Biswanath-Panpur Dyke. Length= 20.00 m, Lat 26.670388 Long 93.089423 (2) Continuous active bank erosion is observed at Kalakati area in between 6th to 7th km of Biswanath-Panpur Dyke of river Brahmaputra. 21/06/2023 Lat 26.67441008 Long 93.09784163 Lat 26.67468932 Long 93.09795485   0   (Long - 0.000000,
		Lat - 0.000000) <b>Dhubri</b> - kuntirchar Pt-I, kuntirchar Pt-II, Majerchar   Erosion is going on (by the river Brahmaputra) at village Kuntirchar Pt-I, Kuntirchar Pt-II & Majerchar As per the field verification w.e.f 17/06/23 to 21/06/23 it is seen that till now 47 nos of family has been affected (total area = 64Bigha-1Katha-5Lessa)and they have shifted
	Dhubri	their houses to another place. No situation has arisen for opening of any relief Camp. (Kinirchar Pt-I Lat-26.04912778, Long-89.99160278) (Kuntirchar PtII-Lat-26.03223611 Long-89.98838611) (Majerchar-Lat-26.05064722, Long- 90.13675833)   325   (Long - 26.049128, Lat - 89.991603)
	Kamrup	Chaygaon - No 2 Ratanpur village to Jogibari Road.   PWD(R) chhaygaon Sub-Division reported about erosion of about 90 mtr of a PWD road because of the rising water level of Kulsi River. Date: 20/06/2023.   0   (Long - 91.382541, Lat - 26.004431)
	Kokrajhar	<b>Dotma</b> - Vill- Nowebhita   Dated: 21/06/2023 Erosion occured at village Nowerbhita by the river Longa. Around 200metres (Approx.) eroded.   0   (Long - 0.000000, Lat - 0.000000)
	Lakhimpur	<b>Bihpuria</b> - Dikrong Ghat area near 80 No. Solmari Grant   Active erosion observed at Dikrong ghat area on R/B of Dikrong river at 80 No. Solmari Grant village due to which one family has been shifted to safe location Approximately 200 meters of land has been eroded as reported by WRD, Bihpuria Sub-Division on 21/06/2023. 02 nos. Of tarpaulins provided to the erosion affected family.   7   (Long - 93.878200, Lat - 27.081900)
	Majuli	<b>Majuli</b> - Kartik Chapori NC   Erosion occured on 20th June, 2023 and one family have been shifted to a nearby safe place. Approximately 3 katha of land area has been eroded   5   (Long - 94.164901, Lat - 26.841096)
	Morigaon	<b>Bhuragaon</b> - Balidunga Pam, Kupatimari   As per Water Resource department, Morigaon, Bhrahmaputra river erosion eroded 1 meter at a length of 700 meter at Kupatimari and Balidunga Pam revenue village under Bhuragaon Rev. Circle from 20-06-2023 to 21-06-2023."   0   (Long - 26.411003, Lat - 92.251558)
	Nagaon	<b>Kaliabor</b> - Hatimura Area   Severe bank erosion of river Brahmaputra due to sudden slump down at Hatimura area length about 100 meters and breadth about 22 metres on 20.06.23 reported by Water Resources Department.   0   (Long - 92.995224, Lat - 26.612052)
	Sonitpur	<b>Thelamara</b> - Village- Baligaon Bongaligaon and Garuduba   Date-21/06/2023, As reported by Tezpur Water Resource Tezpur Division on 21/06/2023- 1) Active bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri, Length = 200.00m, Latitude : 26.736022, Longitude: 92.558699 2) Bank erosion is observed at Garuduba area of river Belsiri Length = 150.00m, Latitude : 26.642391, Longitude:
	Sompar	92.530572   0   (Long - 92.530572, Lat - 26.642391), <b>Tezpur</b> - Burha chapori (Dhania Sisuati)   Dated: 21/06/2023. As reported by Tezpur Water Resources  Division, Tezpur bank erosion of river Brahmaputra is observed at Burha Chapori (Dhania Sisuati). Length:  350.00m   0   (Long - 92.628394, Lat - 26.526149)
	South Salmara	Mankachar - Berabhanga Pt-I, II and Jordanga Pt-I.   AS per report received from I/C Control Room Hatsingimari W.R Sub-Division, Hatsingimari, an erosion due to Brahmaputra river at Berabhanga Pt-I, land measuring length-40 M, Breadth- 3 M, Berabhanga Pt-II- length-120 M, Breadth-1 M and Jordanga Pt-I length- Breadth- on 21-06-2023 As per report received from Gaon Pradhan 8 (Eight) nos. house hold shifted to other place due to erosion at Berabhanga Pt-I on 21-06-2023.   43   (Long - 25.773519, Lat - 89.902791)
	Tamulpur	<b>Tamulpur</b> - Vill- Kalbari   Severe bank erosion and gully erosion occurred at Gerua and its adjacent paddy area in Kalbari village on 21 June 2023   0   (Long - 91.602460, Lat - 26.590520)
	Udalguri	Mazbat - 1/ Swrangjuli 2/ Raidanglow   1/ Erosion occurred on L/B of river Mainajuli for a length of 300m on 20/6/2023 due to heavy rainfall. (Lat: 26.857074 long: 92.344789 2/ erosion occurred on R/B of river Mainajuli for a length of 200m on 20/6/2023 due to heavy rainfall (Lat: 26.84345, Long: 92.3359)   0   (Long 0.000000, Lat - 0.000000),  Kalaigaon - Pachim Jangalpara   Erosion continues at village Pachim Jangalpara in the R/B of river Nanoi nea Pachim Jangalpara LP School covering a length of around 120 meters and depth of 5 meters on 21/06/2023 due
	District/Sub	to heavy current of the river.   30   (Long - 91.998994, Lat - 26.566631)
	-division*	Details  W.G. W. M. J. W. J. D. G. W. J. W. W. J. W. W
Landslide	Dima-Hasao	Haflong - Mahur, Kalachand, Between Dimruchora and Jolaidisa   1. Landslide at Mahurpura village approach road on 21-06-2023 Lat :- 25.160488, Long :- 93.067072. 2. Landslide near Kalachand electric post on 20-06-2023 Lat :- 25.341306, Long:- 93.133135. 3. Road block in between Dimruchora and Jolaidisa at nH54 due to break down of culvert 21-06-2023.   0   (Long - 0.000000, Lat - 0.000000)

	Kamrup (M)	<b>Guwahati</b> - Devagiri path Kharghuli   A landslide incident occurred at Devagiri path Kharghuli on 21/06/2023, no casualty   0   (Long - 91.766362, Lat - 26.194403)
	District/Sub -division*	Details
	Bajali	<b>Bajali</b> - Pathsala and Patacharkuchi Town   ward No 10 of Pathsala Town and 2,3,4,5,6,8,10 of Patacharkuchi Town dated 21/06/2023 reported by Chairman of Pathsala and Patacharkuchi MB   653   (Long - 0.000000, Lat - 0.000000)
	Darrang	<b>Dalgaon</b> - Kharupetia Town (ward no.1 and 8)   as per report received from lm, waterlogging at kharupetia town (ward no 1 and 8) under dalgaon revenue circle as on 20/06/2023   100   (Long - 92.149805, Lat - 26.519547)
Urban Flood	Kamrup (M)	Dispur - Rukminigaon, Hatigaon, Baghorbori Revenue Village   Waterlogging at Rukminigaon, Hatigaon-Sijubari, Wireless and Baghorbori. Roads are inundated no houses affected on 21/06/2023   0   (Long - 0.000000, Lat - 0.000000),  Guwahati - Chandmari, B.Baruah Road, Satipur masjid goli, Boragaon, Maligaon   Partially water logging at Chandmari, B.Baruah Road, Satipur masjid goli, Boragaon, Maligaon on 21/06/2023   0   (Long - 0.000000, Lat - 0.000000)
	Kokrajhar	Dotma - Fakiragram MB   Due to incessanr rainfall from 12-06-2023 to till date waterlogging at various wards under Fakiragram MB, Date: 21-06-2023 1. WARD NO.1 2. WARD NO.2   520   (Long - 0.000000, Lat - 0.000000),  Kokrajhar - Ward no.1 to 10   DUE TO INCESSANT RAINFALL FROM 12.06.2023, WATER LOGGED AT KOKRAJHAR URBAN AREA VIDE WARD NO. 1 TO 10, dated-21/06/2023   12769   (Long - 0.000000, Lat - 0.000000)
	Nalbari	Nalbari - collage road, forest office road, gopal bazar road, hajo nalbari road   as per the report received from LM, these roads are submerged due to rain water Dated: 21/06/2023   600   (Long - 0.000000, Lat - 0.000000)
		*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)