

FRIMS Assam



Flood Reporting And Information Management System

D (1	Assam Daily Flood Report as on 01-07-2023 at 4:00 PM ars Situation as on 01-07-2023 (in last 24 hours)										
Particulars	Situation as on	101-07-202	3 (111 last 2	24 hours)							
Rivers flowing above Danger	Rivers flowing	g above dan	ger level	vel Nil							
Level (as per CWC bulletin issued at 8 AM)	Rivers flowing flood level	g above higl	nest	Nil							
District/Sub- division Affected	No. of Districts/Su b-divisions* Affected	Name of divisions		ffected Districts/Sub-		Name of Urban Flood Districts/Sub-divisions*					
	5	Bajali, D	hemaji, Go	olaghat, Jorl	nat, Kamrup						
No. Of Revenue Circles Affected	8										
	District/Sub -division*	Total		Revenue Circle							
Name Of Revenue Circles Affected	Bajali	2	_	Bajali, Sarupeta							
	Dhemaji	1	Sissibor	-							
	Golaghat Jorhat	1	Dergaor								
	Kamrup	3		Jorhat West Kamalpur, North Ghy, Hajo							
	Total	8	Kamaip	ui, ivoitii Gi	1y, 11aj0						
	District/Sub -division*	Total	Revenue Circle								
	Bajali	10	(Bajali 9), (Sarupeta 1)								
Villages	Dhemaji	1	(Sissiborgaon 1)								
Affected	Golaghat	6	(Dergaon 6)								
	Jorhat	1	(Jorhat West 1)								
	Kamrup	104	(Kamal	(Kamalpur 21), (North Ghy 6), (Hajo 77)							
	Total	122	Total					Cwan			
	District/Sub -division*	Male	Femal e	Childre n	Populatio n	Population Details		Crop Area (in Hect.)	Crop Area Details		
Population	Bajali	944	895	202	2041	(Bajali 1983), (Sarupeta 58)		15.00	(Bajali 7.00), (Sarupeta 8.00)		
And Crop	Dhemaji	136	145	85	366	(Sissiborgaon 366)		15.00	(Sissiborgaon 15.00)		
Area Affected	Golaghat Jorhat	0	0	0	0	(Dergaon 0)		12.10 6.60	(Dergaon 12.10) (Jorhat West 6.60)		
	Kamrup	2	2	4	8	(Jorhat West 0) (Kamalpur 0), (North Ghy 8), (Hajo 0)		1031.53	(Kamalpur 33.03), (North Ghy 10.50), (Hajo 988.00)		
	Total	1082	1042	291	2415	1 ~ /		1080.23			
Relief Camps / Centres Opened	District/Sub -division*	Total	Relief C	Camp			Relief Distribution Centres				
	Bajali	2	0(Bajali	•		2(Bajali 2)					
	Kamrup	7		Ghy 1, Ha	jo 0)	6(North Ghy 1, Hajo 5)					
Inmates In Relief Camps	Total District/Sub -division*	9 Total	Revenue Circlewise			Male	8 Female	Children	Pregnant / Lactating Mother	Person with Disabilit y	
	Kamrup	8	(Kamalpur 0), (Hajo 0), (North Ghy 8)			2	2	4	0	0	
	Total	8				2	2	4	0	0	

Human Lives Lost - Confirmed	Nil											
Human Lives Lost Confirmed - Death Type	Nil											
Human Lives Lost - Missing	Nil											
Human Lives Lost Missing - Type	Nil											
Type	District/Sub division* Total Big Small Poultry											
Animals	Bajali	1632	725	687	220							
Affected	Dhemaji	55	35	20	0							
	Kamrup	22185	18518	3667	0							
	Total	23872	19278	4374	220							
Animals Washed Away	Nil											
Houses Damaged	Nil											
Rescue Operation	District/Sub -division*	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopte rs Deployed	Person Evacuate d By Helicopte rs	Medical Team Deploye d		
	Kamrup				0	0	0	0	0	1		
	Total				0	0	0	0	0	1		
Relief Distributed	District/Sub -division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)				
	Bajali	0.00	0.00	0.00	0.00	0.00	195.60	0.00				
	Kamrup	0.10	0.02	0.01	0.60	0.00	734.00	0.00				
	Total	0.10	0.02	0.01	0.60	0.00	929.60	0.00				
Relief Distributed	District/Sub -division*	Baby Foo Liquid	od	Baby Foo	od Solid	Others						
Others	Bajali	0.00-ml		0.00-Pkt		G II 200 PL						
I f t t	Kamrup	0.00-Q	0.00-Q Candle-2.00-Pkt									
Infrastructur e Damaged - Embankmen t Breached	Nil											
Infrastructur e Damaged - Embankmen ts Affected	Nil											
	District/Sub -division*	Numbe r	Details									
Infrastructur e Damaged - Road	Bajali	49	Bajali - Chakla Village, Patacharkuchi- Anchali Road. Chakla Road damaged. length- 20.00m, Breadth - 1.50m, Height- 1.18m This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 (Long - 91.236621, Lat - 26.506438, Dept - PWD (Roads)), Bongaon - Kashkuri Road. Bongaon Road damaged. length- 2000.00m., Breadth - 1.50m, Height-1.10m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 (Long - 91.209845, Lat - 26.432779, Dept - PWD (Roads)), Ghelengpara- Bagapara Road Bagapara Road damaged. length-600.00m, Breadth -6.00m, Height-1.00 This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 (Long - 91.237448, Lat - 26.467396, Dept - PWD (Roads)), Ulua Bhogeswari Road at 3rd km Bhoges Road damaged. length-2000.00m, Breadth -6.00m,									

Height-1.00m This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.222945, Lat - 26.578796, Dept - PWD (Roads)).

Dr. Bhupen Hazarika Path, Pathsala | Pathsala | Road damaged. length-1000.00m ,Breadth -3.00m , Height-0.90m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.757888, Lat - 26.503825, Dept

- PWD (Roads)),

Ext. of Bamakhata Kardeguri Road (Pahla to Kuwara Chowk) at 1st & 2nd Km | Bamakhata | Road damaged. length-2500.00m ,Breadth -6.00m , Height-0.60m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.249806, Lat - 26.529770, Dept - PWD (Roads)),

Anandapur to Bagapara via Baniapara at 1st to 7th km | Bagapara | Road damaged. length- 2000.00m ,Breadth -6.00m , Height-1.00m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.237458, Lat - 26.562925, Dept - PWD (Roads)),

Santi Chowk to Lakhimi Chowk at 3rd, 4th & 5th Km | lakhimi Chowk | Road damaged. length-2500.00m,Breadth -6.00m, Height-1.00m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.207186, Lat - 26.600321, Dept - PWD (Roads)),

Saibari village Approach Road | Saibari | Road damaged. length-600.00m ,Breadth - 6.00m, Height-0.80m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.211770, Lat - 26.600889, Dept - PWD (Roads)),

Anandapur Pipla Road at 1st,2nd, 3rd & 4th Km | Anandapur | Road damaged. length-4000.00m,Breadth - 6.00m, Height-0.9m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.218591, Lat - 26.566676, Dept - PWD (Roads)).

NH127 (A) to the village Ghatbar Saderi (Martyr Pranay Kalita's House)(1st & 2nd Km) | NH127 | Road damaged. length-1200.00m, Breadth -2.00m, Height-0.35m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.233069, Lat - 26.497417, Dept - PWD (NH Roads)),

Road from 7th Km of Tihu Doomni Road to Natun Bagapara village from Ch. 0.00 m to 2.58 Km | Tihu, Doomni | Road damaged. length-1000.00m, Breadth - 6.00m, Height-0.90m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.248787, Lat - 26.581140, Dept - PWD (Roads)),

Original Bamakhata Kardeguri Road (AS-01-65) (From Ch.0.00 to $5.92~\mathrm{Km}$) | Bamakhata | Road damaged. length-2000.00m,Breadth - 3.00m, Height-0.85m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.217081, Lat - 26.522325, Dept - PWD (Roads)),

Lachit Nagar Path, Pathsala (1st Km) | Pathsala town | Road damaged. length-1000.00m, Breadth - 2.35m, Height-1.1m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.182026, Lat - 26.507985, Dept - PWD (Roads)).

Tihu Dumni Road (From Ch.0.00 to 6.50 Km) | Tihu | Road damaged. length-1800.00m ,Breadth - 2.50m , Height-1.00m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.252778, Lat - 26.540000, Dept - PWD (Roads)),

Kharadhara Chowk to Barhamchari (From Ch.0.00 to 7.00 Km) | Kharadhara | Road damaged. length-500.00m, Breadth -3.00m, Height-0.60m This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.259167, Lat - 26.545556, Dept - PWD (Roads)),

Tihu Dumni Road to Garemari Village (From Ch.0.00 M to 2.00 Km) | Garemari Village | Road damaged. length-500.00m, Breadth -2.00m , Height-0.35m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.260833, Lat - 26.578889, Dept - PWD (Roads)),

Seuni Chariali to Naosali (1/1 Culvert Damaged) | Seuni | Road damaged. length-1200.00m,Breadth -6.00m, Height-1.10m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long -91.212885, Lat - 26.617292, Dept - PWD (Roads)),

Patacharkuchi Girls' High School to Swahid Madan Rauta Road (1st Km) | Patacharkuchi | Road damaged. length-200.00m ,Breadth -6m , Height-0.6m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.230772, Lat - 26.505917, Dept - PWD (Roads)),

Nityananda Panbari Road to Kaljirapara New field to NH-31 to Kuruwa (AS-01-480) (1st to 5th Km) | Panbari | Road damaged. length- 1290.00m,Breadth -6m , Height-0.6m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.192559, Lat - 26.505534, Dept - PWD (Roads)),

NH-31 at Birkola Chowk to Niz Sariah (NH-31 at Birkola Chowk to Niz Sariah (AS-01-486)(2nd, 3rd, 4th Km). | Bikiola chowk | Road damaged. length-2400.00m,Breadth -5.10m, Height-0.60m.

This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.236883, Lat - 26.497192, Dept - PWD (Roads)), Nityananda Pathsala road including Link No1 No2 No3 to Old NT road to Railway line (AS01-485)(1st, 2nd, 3rd &4th Km) | Nityananda | Road damaged. length-2300.00m, Breadth -5m, Height-0.9m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.185052, Lat - 26.500303, Dept - PWD (Roads)).

Patacharkuchi Anchali Road (NH-31 at Patacharkuchi to Nityananda) (1st to 6th Km) | Nityananda | Road damaged. length- 5000.00m,Breadth - 7.5m, Height-2m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.226258, Lat - 26.526672, Dept - PWD (Roads)),

Damage of Uparnoi Ulua Road and Approaches of Bridge No 4/1. | Uparanoi | Road damaged. length-600.00m ,Breadth -6.5m , Height-6m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.207980, Lat - 26.474652, Dept - PWD (Roads)),

Dubi Helana Road (1st and 2nd Km) | Dubi | Road damaged. length-1100.00m, Breadth -6m, Height-0.6m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.196180, Lat - 26.474652, Dept - PWD (Roads)),

Dekapara to Pakrirtol (1st and 2nd Km) | Dekapara | Road damaged. length-200.0m ,Breadth -6 m , Height-0.9m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.211793, Lat - 26.484922, Dept - PWD (Roads)),

Malipara Chowk to Railway Gate (1st Km) | Malipara | Road damaged, length- 1000.00m ,Breadth -3m , Height-0.65m This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.202519, Lat - 26.482558, Dept - PWD (Roads)),

Rupdiga Approach Road (1st & 2nd Km) | Rupdiga | Road damaged. length-2500.00m ,Breadth - 5.0m , Height-0.60m This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 90.446472, Lat - 26.448172, Dept - PWD (Roads)),

Nalena Belana Road(3rd km to 6th Km) | Belona | Road damaged. length- 2000.00m, Breadth-7.00m and height- 1.00m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023. | (Long - 91.146801, Lat - 26.483517, Dept - PWD (Roads)),

Pokha Odalguri Road (1st to 3rd Km) | Odalguri | Road damaged. Length- 2000.00m, Breadth-6.00m, Height- 0.35m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.234276, Lat - 26.561264, Dept - PWD (Roads))

Patacharkuchi Barbatabari Road(1st & 2nd Km) | Barbatabari | Road damaged. length-1500.00m, Breadth- 6.00m, height- 0.35m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.234725, Lat - 26.497603, Dept - PWD (Roads)),

Golaghat Dhaneswari Road(1st km & 2nd Km) | Dhaneswari | Road damaged. length- 3000.00m, breadth- 5.00m, height- 0.60m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.224167, Lat - 26.572778, Dept - PWD (Roads)),

Patacharkuchi link Road (3.00 Km) | Patacharkuchi | Road damaged. length- 1300.00m, breadth-6.00m, height-0.90m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 26.496764, Lat - 91.238200, Dept - PWD (Roads)).

Tihu Bangaon road to Melkipara (1.00 Km) | Melkipara | Road damaged. length- 1000.00m, breadth- 4.00m, height- 0.70m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.225736, Lat - 26.459069, Dept - PWD (Roads)),

Tihu Bangaon Road to Agdala road (1.00 Km) | Bangaon | Road damaged. length- 1000.00m, breadth- 3.00m, height- 0.60m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023. | (Long - 91.234636, Lat - 26.454075, Dept - PWD (Roads)),

Tihu Bangaon Road Balipara L.P School to Bhadrabhitha road (1.50 Km) | Balipara | Road damaged. length- 1000.00m, breadth- 6.00m, height- 1.20m. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023. | (Long - 91.235606, Lat - 26.463631, Dept - PWD (Roads)),

Ulua- dhaneswari Road breached at Napara (20.00 m). | Napara | Road damaged. length-2500.00m ,Breadth -6.50m, Height-0.75. This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023. | (Long - 91.224682, Lat - 26.576270, Dept - PWD (Roads)),

Anandapur Ghelengpara Road (Damaged SPT Bridge No.-1/1) | Ghelengpara | Road damaged. length-900.00m ,Breadth -4.00m , Height-2.20m. This report is received from Executive

Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long-91.239256, Lat - 26.585505, Dept - PWD (Roads)), Haripur Gobindapur ICBP Road(1st to 3rd Km) | Gobindapur | Road damaged. length-3000.00m, Breadth -6.00m, Height-0.60m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023. | (Long - 91.202225, Lat -26.506891, Dept - PWD (Roads)), Haripur Jogyadham road to Melkipara Road (1st Km) | Melkipara | Road damaged. length-1000.00m, Breadth -6.00m, Height-0.65m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023. | (Long-91.202455, Lat - 26.506290, Dept - PWD (Roads)), Bajali circle office approach Road (0.20 Km) | Patacharkuchi | Road damaged. length-200.00m, Breadth -6.00m, Height-0.60m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.233003, Lat -26.506004, Dept - PWD (Roads)), SNAS Road (1st to 3rd Km) | Patacharkuchi | Road damaged. length-3000.00m, Breadth -6.00m, Height-0.60m. This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.249426, Lat - 26.547200, Dept - PWD (Roads)), Pathsala Golibandha Road (1st to 7th Km) | Golibandha | Road damaged. length-2300.00m ,Breadth - 6.00m, Height-0.60m This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.158944, Lat -26.492310, Dept - PWD (Roads)), Pathsala Cremation ground (1st and 2nd Km) | Pathsala | Road damaged. length-300.00m, Breadth -6.00m, Height-2.50m This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.158611, Lat - 26.500278, Dept - PWD (Roads)), Pathsala C.H.C to Kenduguri via Muguria Gaon (1.50 K.M) | Kenduguri | Road damaged. length-1000.00m, Breadth -4.05m, Height-0.60m This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long-91.167727, Lat - 26.507624, Dept - PWD (Roads)), Road from NH127A to Laugaon Gate (3.75 Km) | Laugaon. | Road damaged. length-1000.00m ,Breadth -2.00m, Height-1.20m This report is received from Executive Engineer,PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023. | (Long - 91.172409, Lat -26.606606, Dept - PWD (Roads)), Hudukhata Naosali Road (6.00 km) | Naosali | Road damaged. length-3000.00m, Breadth -1.00m, Height-1.00m This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.149958, Lat - 26.622185, Dept - PWD (Roads)). Birbira to Santipur (Doloigaon) (including 2 nos Breaches). | Doloigaon | Road damaged. length-600.00m, Breadth - 2.50m, Height-1.80m This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.160264, Lat -26.536133, Dept - PWD (Roads)), Natun Belana Road. | Belona | Road damaged. length-2000.00m, Breadth - 1m, Height-1.5m This report is received from Executive Engineer, PWRD, Bhawanipur, Patacharkuchi & Sarukhetri TR Division on 01/07/2023 | (Long - 91.138751, Lat - 26.487284, Dept - PWD (Roads)) Sarthebari - Mohan Bazar to Galibandha Road (PMGSY Completed road- Pkg No-AS-01-185) RCC Bridge No. 1/1 approaches damaged due to heavy rainfall at 1st KM. Side berms damaged at 2nd KM due to heavy rainfall. (Lat- 26.41611, Long – 91.12155) Under Sarthebari Rev Circle. Mohan Bazar to Galibandha Road | As per report received from PWD Dept on 01/07/2023 | (Long -91.121550, Lat - 26.416110, Dept - PWD (Roads)), Baithabhanga Pithadi Road SPT Br No. 2/1 waterway blocked due to deposition of Water hyacinth.(Lat- 26.37858, Long- 91.129657, Under Sarthebari Rev Circle). | Baithabhanga Pithadi Road | As per report received from PWD Dept on 01/07/2023 | (Long - 91.129657, Lat -26.378580, Dept - PWD (Roads)), Kashkuri Pam to Kashkuri Pathar PMGSY Completed road submerged at 2nd Km. Slab Culvert damaged and side berms damaged due to heavy rainfall (Lat- 26.415798, Long- 91.2318, Under Sarthebari Rev. Circle) | Kashkuri Pam to Kashkuri Pathar | As per report received from PWD Dept Barpeta 25 on 01/07/2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Neularbhitha Satrapaka via Jabrikuchi PMGSY Completed road RCC Br. Approach 1/1 damaged due to heavy rainfall. Road hard crust with side berms damaged at 1st KM to 3rd KM. (Lat-26.383247 ,Long-91.182528 , Under Sarthebari Rev Circle) | Neularbhitha Satrapaka via Jabrikuchi As per report received from PWD Dept on 01/07/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), Hathinapur to Rajakhat Barsimla via Kawaimari Reserve (PMGSY Completed road- AS-01-459) side berms damaged due to heavy rainfall from 2nd to 6th KM. Slab culvert approaches damaged on South side at 3rd Km. (Lat- 26.441262 Long-91.18089, Under Sarthebari Rev Circle). Hathinapur to Rajakhat Barsimla via Kawaimari Reserve | As per report received from PWD Dept on 01/07/2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Rowli Bhokutepa Chenga road side berms damaged due to heavy rainfall under Sarthebari Rev

Circle. | Rowli Bhokutepa Chenga road | As per report received from PWD Dept on 01/07/2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Chenga Belbari road (PMGSY completed- Pkg No-AS-01-528) side berms damaged sue to heavy rainfall. | Chenga Belbari road | As per report received from PWD Dept on 01/07/2023 | (Long -0.000000, Lat - 0.000000, Dept - PWD (Roads)), NAGAON SARTHEBARI ROAD RCC BRIDGE APPROACH DAMAGE AT SINGRA | NAGAON SARTHEBARI ROAD | As per report received from PWD Dept on 01/07/2023 | (Long - 91.169794, Lat - 26.335984, Dept - PWD (Roads)), SINGRA BOGCHARA ROAD DAMAGE BADLY DAMAGEDUE TO OVER TOP MANT STRETCHES | SINGRA BOGCHARA ROAD | As per report received from PWD Dept on 01/07/2023 | (Long - 91.164661, Lat - 26.342020, Dept - PWD (Roads)), TIHU SARTHEBARI ROAD RCC BRIDGE APPROACH DAMAGE AT KALATALI | TIHU SARTHEBARI ROAD | As per report received from PWD Dept on 01/07/2023 | (Long -91.230488, Lat - 26.392789, Dept - PWD (Roads)), NASATRA BAMUNDI ERA CHOWK ROAD DAMAGE BADLY AT MANY STRETCHES | NASATRA BAMUNDI ERA CHOWK ROAD | As per report received from PWD Dept on 01/07/2023 | (Long - 91.187247, Lat - 26.369164, Dept - PWD (Roads)), SARTHEBARI NASATRA ROAD SUBMARGED AT MANY STRETCHES AND DAMAGED SIDE BERM AND HARD CRUST ALSO | SARTHEBARI NASATRA ROAD | As per report received from PWD Dept on 01/07/2023 | (Long - 91.208590, Lat - 91.208590, Dept - PWD RANGIA NADIR PAM TO BHOGHCHARA BAZAR ROAD SUBMERGED AND DAMAGED THE ROAD BADLY | RANGIA NADIR PAM | As per report received from PWD Dept on 01/07/2023 | (Long - 91.146732, Lat - 26.356145, Dept - PWD (Roads)), GOHIYA TO BURIKHAMAR ROAD DAMAGE DUE TO FLOOD | GOHIYA TO BURIKHAMAR ROAD | As per report received from PWD Dept on 01/07/2023 | (Long -91.147747, Lat - 26.331996, Dept - PWD (Roads)), KALATALI VILLAGE ROAD SUBMERGED AND DAMAGED ROAD SURFACE | KALATALI VILLAGE ROAD | As per report received from PWD Dept on 01/07/2023 | (Long -91.226515, Lat - 26.397145, Dept - PWD (Roads)), Barpeta - Suhabildolony Damaljhar Road | Suhabil Dolony Damaljhar | As per report received from PWD Roads Dept on 27/06/2023 Side berm and hard crust damage on several stretches | (Long - 91.063656, Lat - 26.268089, Dept - PWD (Roads)), Debradi to Kahikuchi Road | Debradi to Kahikuchi | As per report received from PWD Roads Dept on 27/06/2023 Road fully submerged | (Long - 91.120331, Lat - 26.318616, Dept - PWD (Roads)), Hahchara Bagodi to Bhairaguri Road | Hahchara Bagodi | As per report received from PWD Roads Dept on 27/06/2023 Road fully submerged | (Long - 91.124438, Lat - 26.353292, Dept - PWD (Roads)), Nagaon Khardhara Road to Kharuapara | Khardhara Kharuapara | As per report received from PWD Roads Dept on 28/06/2023 Road submerged & Side berm eroded & Hard Crust damaged at several stretches | (Long - 91.077755, Lat - 26.335180, Dept - PWD (Roads)), Bagodi Bhairaguri Road | Bagodi Bhairaguri | As per report received from PWD Roads Dept on 28/06/2023 Road fully submerged | (Long - 91.110189, Lat - 26.350418, Dept - PWD (Roads)), Nagaon Sikarvitha Road | Nagaon Sikarvitha | As per report received from PWD Roads Dept on 28/06/2023 Road side berm and hard crust damage at several strectshes and 3 nos. breach occurred (Long - 91.102025, Lat - 26.329067, Dept - PWD (Roads)), Baradi Tatikuchi to Taparbori Bazar | Baradi Tatikuchi | As per report received from PWD Roads Dept on 30/06/2023 Road submerged at several stretches | (Long - 91.049739, Lat - 26.331426, Dept - PWD (Roads)), Pohumara Temura Road | Hard crust damage & 2 nos. breach occurred and approach damage of SPT Br. No. 2/1 | As per report received from PWD Roads Dept on 30/06/2023 Hard crust damage & 2 nos. breach occurred and approach damage of SPT Br. No. 2/1 | (Long - 91.008286, Lat -26.276744, Dept - PWD (Roads)), Patbaushi Nangalkur Road | Patbaushi Nangalkur | As per report received from PWD Roads Dept on 30/06/2023 Bridge approach damage of SPT Br. No. 5/1 | (Long - 91.007623, Lat - 26.275767, Dept - PWD (Roads)), Kahibari to Barpeta Doulasal road via Majkuchi village, PMGSY Pkg. No. As-01-460 | Kahibari to Barpeta Doulasal | As per report received from PWD Roads Dept on 30/06/2023 Road submerged & hard crust damage at several stretches | (Long - 91.026440, Lat - 26.284068, Dept - PWD (Roads)) Agamoni - SIDE BERM & SIDE SLOPES DAMAGED ON ROAD FROM LOHAJANI BAZAR TO KOIMARI PT III AT 1ST KM (.) on dated 12-06-23 to 26-06-23 | KAIMARI PT-III | | (Long -89.818371, Lat - 26.269674, Dept - PWD (Roads)), SIDE BERM & SIDE SLOPES DAMAGED ON ROAD FROM NH31 TO BHAIBAZAR ROAD Dhubri 13 AT 1ST KM ON DATED 12-06-23 TO 26-06-23 | BHAIBAZAR | | (Long - 89.818371, Lat -26.269674, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 2/1 ON BIDYADABRI CHARAK MANDIR ROAD AT 2ND KM ON DATED 12-06-23 TO 26-06-23 | BIDYARDABRI PT-I NEAR MLA HOUSE | | (Long - 89.778740, Lat - 26.293822, Dept - PWD (Roads)),

		SIDE BERM & SIDE SLOPES DAMAGED ON ROAD FROM NH31 TO BIDYADABRI ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 BIDYARDABRI PT-I (Long - 89.781634,						
		Lat - 26.283198, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 1/1 ON NH31 TO BIDYADABRI POKALAGI ROAD AT 1ST KM(.) ON DATED 12-06-23 TO 26-06-23 BIDYARDABRI PT-I (Long - 89.768530, Lat - 26.277610, Dept - PWD (Roads)), SIDE BERM DAMAGED ON NH-31 HALAKURA TO DIGHALTARI ROAD AT 1ST 2nd KM (.) ON DATED 12-06-23 TO 26-06-23 BIDYARDABRI PT-I (Long - 89.801639, Lat - 26.250781, Dept - PWD (Roads)), ROAD SURFACE & SIDE BERM DAMAGED ON NH-31 HALAKURA BOTERHAT BAZAR TO SIMLABARI SATRA AT 1ST & 2ND KM ON DATED 12-06-23 TO 26-06-23 KAIMARI PT-III NEAR SATRA (Long - 89.819349, Lat - 26.279960, Dept - PWD (Roads)), SIDE BERM DAMAGED ON KGT ROAD TO SIMLABARI RAJUA SATRA AT 1ST & 2ND KM ON DATED 12-06-23 TO 26-06-23 KAIMARI PT-III NEAR SATRA (Long - 89.835441, Lat - 26.264385, Dept - PWD (Roads)), ROAD SUBMERGED & BOX CELL CULVERT APPROACHES DAMAGED ON KGT ROAD TO SIMLABARI PURANI SATRA AT 1ST & 2ND KM ON DATED 12-06-23 TO 26-06-23 KAIMARI PT-III NEAR SATRA (Long - 89.833091, Lat - 26.264753, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 4/1 ON HALAKURA POKALAGI PT-II TO SILGHAGRI BAZAR AT 1ST KM ON DATED 12-06-23 TO 26-02-23 POKALAGI PT-II TO SILGHAGRI BAZAR AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 CHOTO DIGHALTARI ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST KM ON DATED 12-06-23 TO 26-06-23 ROAD AT 1ST						
		POKALAGI (Long - 89.745240, Lat - 26.270687, Dept - PWD (Roads)) Barkhetri - Doulashal MV school to Sarukhetri border road Doulashal submerged by flood water from ch 650m to 1500m as reported by EE, PWRD, Nalbari on 01/07/2023 (Long -						
	Nalbari	0.000000, Lat - 0.000000, Dept - PWD (Roads)), Ghoga main chowk to chatemari ghoga submerged and side berm erosion by rain water as reported by EE, PWRD, Nalbari on 01/07/2023 (Long - 0.000000, Lat - 0.000000, Dept - P&RD), Nalbari - Khudia Rangafali road at Namati, road surface damaged, Nalbari RC Namati As per the report received vide WT msg no T/NDTRD/W.T/401-A dated 30.06.2023 from PWD, Roads department this road is damaged (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Khudia Rangafali to Sanskrit University road surface damaged Sanskrit University As per the report received vide WT msg no T/NDTRD/W.T/401-A dated 30.06.2023 from PWD, Roads						
	Total	department this road is damaged (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))						
Infrastructur e Damaged - Bridge	Nil							
Infrastructur e Damaged - Wildlife	Nil							
	District/Sub -division*	Other Details						
	Goalpara	Dudhnoi - Irrigation Canal/Scheme Damaged As per report received from Irrigation department, earthen canal of Kekreng FIS has been damaged by another extra 1.5 m length and 1.5 m height in Damra Patpara due to Heavy rainfall on 01.07.2023, Lat. 25.939918 Long. 90.772444						
Infrastructur e Damaged - Others	Nalbari	Barbhag - PWSS Damaged FHTC - 171 Nos, D/S - 3600 m, Electrical Components damaged as per report submitted by PHE on 30/06/2023, Ghograpar - Public Health Engineering (PHE) As per information received from PHE department, on 30/06/2023, 5 (five) PWSS namely 1. Balitara PWSS (Distribution system, D/S - 500 M), 2. Chengnoi PWSS (Soil Erosion -150 CUM), 3. Pub-Barsiral PWSS(Distribution System, D/S -50 M, FHTC -26 nos. Supporting Pillar - 4 nos., 4. Bhadrabangal PWSS(Distribution System, D/S - 50 M, FHTC - 10 nos. Supporting Pillar - 4 nos. and 5. Panimajkuchi PWSS(Submersible Pump for DTW) has been damaged due flood., Nalbari - Public Health Centre (PHC) Namati PWSS, Pipe line damaged as per report PHE, Nalbari dtd 1/07/2023, Public Health Centre (PHC) Sariahtoli PWSS, deep tube well damaged as per report PHE, Nalbari dtd 1/07/2023						
	Sonitpur	Chariduar - Agri Bundh Damaged one agricultural bund breached by Ghagrajan (sub-Tributory of River Dipota),length-10 m, latitude-26.711886 & longitude-92.707331 on DTD 29.06.2023 as reported by WR on DTD 1.07.2023						
	Udalguri	Mazbat - Irrigation Canal/Scheme Damaged Breach of canal embankment at around length- 12m, Breadth-						

		2.5m, depth- 2.30m at ch 3.2km of Bagaribari FIS on 1/7/2023(Lat: 26.762325, long: 92.228161)
Erosion	District/Sub -division*	Details
	Biswanath	Halem - 1.Paken 2.Uttar Chatrang Mazgaon 1. River Brahmaputra -Mild bank erosion is observed at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length =10m. (avg.width=0.10m) report on 1/07/2023 2.River Chatrang -Erosion observed at Uttar Chatrang Mazgaon area on R/Bank embankment of river Chatrang Ch. 6800m to 6880.Length=80m(Avg. width=0.10m) Report on 1/07/2023 0 (Long - 93.597925, Lat - 26.893817)
	Dhubri	South Salmara Part - Ravatari pt-i As per information received from WR and field visit by field officer, DM,. Erosion continue at village Ravatari pt-i village. 1 no family has been eroded due to Erosion by the river Brahmaputra aa on 30.06.22. area aprox leanth 300 m and breadth 20 m. 6 (Long - 90.032840, Lat - 25.921755)
	Sonitpur	Thelamara - Baligaon Bongali Date-01/07/2023, As reported by Tezpur Water Resource Tezpur Division on 01/07/2023 Bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri,Length = 200.00m, Latitude : 26.736022, Longitude: 92.558699 0 (Long - 92.558699, Lat - 26.736022)
Landslide	Nil	
Urban Flood	Nil	
		*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)