

## **FRIMS Assam**



## Flood Reporting And Information Management System

Assam Daily Flood Report as on 05-07-2023 at 4:00 PM												
Particulars	Situation as on 0	05-07-2023	(in last 24 l	nours)								
Rivers flowing above Danger Level (as per	Rivers flowing above danger level					Nil	Nil					
CWC bulletin issued at 8 AM)	Rivers flowing above highest flood level						Nil					
District/Sub- division Affected	No. of Districts/Sub- divisions* Affected	Name of Flood Affected Districts/Sub- divisions*					Name of Urban Flood Districts/Sub-divisions*					
	3	Bajali, Dhemaji, Kamrup										
No. Of Revenue Circles Affected	6											
Name Of	District/Sub- division*	Total	Revenue Circle									
Revenue	Bajali	2	Sarupeta.									
Circles	Dhemaji	1		Sissiborgaon								
Affected	Kamrup	3	North Gr	ıy, Hajo, Kar	nalpur							
	Total	6										
	District/Sub- division*	Total	Revenue Circle									
Villages	Bajali	4		( Sarupeta   1 ), ( Bajali   3 )								
Affected	Dhemaji	1		( Sissiborgaon   1 ) ( North Ghy   6 ), ( Hajo   32 ), ( Kamalpur   12 )								
	Kamrup	50 <b>55</b>	( North C	ny   6 ), ( Ha	ijo   32 ), (	Kan	naipur   12	)				
	Total	55							Crop			
	District/Sub- division*	Male	Female	Children	Total Populat	ion	Population Details		Area (in Hect.)	Crop Area Details		
Population	Bajali	3028	2803	726	6557		( Sarupeta   58 ), ( Bajali   6499 )		9.00	( Sarupeta   Bajali   9.00		
And Crop Area Affected	Dhemaji	136	146	85	367	( Sissiborgaon   15.00 ( Sissiborgao						
	Kamrup	2	2	4	8	( North Ghy   8 ), ( Hajo   0 ), ( Kamalpur   0 )			141.70	( North Ghy   5.00 ), ( Hajo   125.00 ), ( Kamalpur   11.70 )		
	Total	3166	2951	815	6932				165.70			
Relief Camps /	District/Sub- division*	Total	Relief Camp Relief Distribution Centres						Centres			
Centres	Bajali	3	0(Bajali   0)				3(Bajali   3)					
Opened	Kamrup	1	1(North Ghy   1)				0(North Ghy   0)					
	Total	4	1					3				
Inmates In Relief Camps	District/Sub- division*	Total	Revenue Circlewise				Male	Female	Children	Pregnant / Lactating Mother	Person with Disability	
	Kamrup	8	(Hajo   0), (Kamalpur   0), (North Ghy   8)				2	2	4	0	0	
	Total	8	+ · · · · · · · · · · · · · · · · · · ·				2	2	4	0	0	
Human Lives Lost - Confirmed	Nil											
Human Lives Lost Confirmed - Death Type	Nil											

	1										
Human Lives	Nil										
Lost - Missing											
Human Lives	Nil										
Lost Missing -	NII										
Туре	District/Sub-										
	division*	Total	Big	Small	Poultry						
Animals	Bajali	2855	1404	1039	412						
Affected	Dhemaji	175	80	55	40						
Affected	Kamrup	3950	3850	100	0						
	Total	6980	5334	1194	452						
Animals	Total	0700	3334	1174	432						
Washed Away	Nil										
Houses											
Damaged	Nil										
Rescue	27.1										
Operation	Nil										
						Cattle	Cattle				
	District/Sub-	Rice (in	Dal (in	Salt (in	M. Oil (in	Feed -	Feed -				
Relief	division*	Q)	Q)	Q)	L)	Green Fooder	Wheat Bran	Cattle Feed - Rice Bran (in Q)			
Distributed		<b>(</b> 2)		<b>Q</b> )							
	5 1 11	10.00	0.00	0.00	212.01	(in Q)	(in Q)	0.00			
	Bajali	48.00	8.89	0.00	263.91	0.00	0.00	0.00			
	Total	48.00	8.89	0.00	263.91	0.00	0.00	0.00			
Relief	District/Sub- division*	Baby Foo	d Liquid	Baby Foo	d Solid	Others					
Distributed	D : 1:	0.00 1		720 00 DI		Candle -	995.00-Pk	; Match Box -225.00-Pkt; Mosquito			
Others	Bajali	0.00-ml		720.00-Pk	t	Coil-425.00-Pkt					
Infrastructure Damaged -											
Embankment	Nil										
Breached											
Infrastructure											
Damaged -	Nil										
Embankments	NII										
Affected											
	District/Sub-	Number	Details								
	division*		<b>D</b>	DD 1	77 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1111					
Infrastructure Damaged - Road	Barpeta	Barpeta - BB road to Kayakuchi Newlarbhitha road via Dakhin Kuriha road   Kayakuchi Newlarbhitha Kuriha   As per report received from Asst. Executive Engineer, PWD Sarukhett TR Sub-Division, Sarthebari on 28/06/2023 BB road to Kayakuchi Newlarbhitha road via Dakhin Kuriha road hard crust damaged at 1st and 2nd km. Side berms heavily damaged   (Long - 91.068285, Lat - 26.392223, Dept - PWD (Roads)), Dakhin Bhowkamari to Pohumara River   Bhakuamari Pahumara   As per report received fron Asst. Executive Engineer, PWD Sarukhetri TR Sub-Division, Sarthebari on 28/06/2023 Dakh Bhowkamari to Pohumara River fully submerged. SPT Br. Approaches damaged in stretches (Long - 91.078985, Lat - 26.399808, Dept - PWD (Roads)), BB road to Gumirpahar SPT Br. No 2/1   Bariarpatahr   As per report received from Asst. Executive Engineer, PWD Sarukhetri TR Sub-Division, Sarthebari on 28/06/2023 4. BB road to Gumirpahar SPT Br. No 2/1 approaches damaged in stretches   (Long - 91.072965, Lat - 26.380122, Dept - PWD (Roads)),  Sarthebari - Kamarpara to Barkapla village road is submerged and damaged badly.   Kamarpara to Barkapla village road   As per the report received from PWD (Road) on 05-07-2023   (Long - 91.207699, Lat - 26.341938, Dept - PWD (Roads)),  Amrikhowa Majdia road submerged at many stretches damaged due to flood.   Amrikhowa Majdia road   As per the report received from PWD (Road) on 05-07-2023   (Long - 91.234535, Lat - 26.291985, Dept - PWD (Roads)),  Kathalbari to Khongra   MGSY Completed - Pkg - AS-01-182) side berms damaged in streche RCC Br approaches damaged.(lat- 26.289634, Long-91.188902, Under Sarthebari Rev Circle Kathalbari to Khongra   As per the report received from PWD (Road) on 05-07-2023   (Long - 91.188902, Lat - 26.289634, Dept - PWD (Roads)),  Naligaon (Era) to Newlarbhitha (Eratari) road completely submerged. (Lat- 26.375195, long-91.163734, under Sarthebari Rev Circle)   Naligaon (Era) to Newlarbhitha (Eratari) road   As per the report received from PWD (Road) on 05-07-2023   (Long - 91.163734, Lat									
	Bongaigaon	38	26.375195, Dept - PWD (Roads)) <b>Bongaigaon</b> - New Bongaigaon Dhaligaon Road via St. Albert School   New Bongaigaon   Pot hole developed on carriage way of the road from (1) from Ch. 500.00m to 700.00m (2) from 800.00m to 950.00m. as per report received from PWRD, Bongaigaon dated-05.07.2023								

(Long - 90.529734, Lat - 26.485835, Dept - PWD (Roads)),

Kukurmari sutarpara road near APDCL | Kukurmari | Side shoulder eroded at Ch. 3km. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.544963, Lat - 26.480408, Dept - PWD (Roads)),

Road from NH-31C Popragaon to Korebari | Popragaon | Hard crust including edge restrain nad ICBP damage and washed away at (1) at Ch. 300.00m to 310.00m (2) at Ch. 500.00m to 515.00m. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.610795, Lat - 26.489820, Dept - PWD (Roads)),

Bakhalgaon Dakuapara Road | Dakuapara | Approach of RCC Br No: 3/1 and shoulder damaged.as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.626749, Lat - 26.408947, Dept - PWD (Roads)),

Kashidoba Kakoijana Road to Betbari Road | Kashidoba | Approach of RCC Br. No: 1/1. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.564130, Lat - 26.425232, Dept - PWD (Roads)),

Sipansila Kahipara Road | Sipansila | Approach of RCC Br No: 1/1 & Embankment damaged. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.620900, Lat - 26.412820, Dept - PWD (Roads)),

Siponsila To Kahibari Road | Kahibari | Shoulder & core eroded and washed away at Ch. 1100.00m & 1300.00m. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.619555, Lat - 26.424966, Dept - PWD (Roads)),

Siponsila To Kathaguri pt-3. | Kathaguri | shoulder damaged at Ch. 5450.00m to 5550.0m.as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.622103, Lat - 26.426862, Dept - PWD (Roads)),

Mulagaon Chengmari Road | Mulagaon | shoulder damaged at 2500.00m. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.508600, Lat - 26.434300, Dept - PWD (Roads)),

Bholaguri to SH-2 via Dosimapara via Mulagaon Road | Dosimapara | shoulder damaged.as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.521285, Lat - 26.457652, Dept - PWD (Roads)),

**Boitamari** - Jogighopa Oudubi Salbari Road | Jogighopa | Land slide & Shoulder damage at Ch 16th km. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.486984, Lat - 26.296527, Dept - PWD (Roads)),

Jogighopa Oudubi Salbari Road | Oudubi | Shoulder and Geo bag damaged at Ch. 15th km.as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.485003, Lat - 26.290147, Dept - PWD (Roads)),

Kabaitary to Kabaitary VI | Kabaitary | hard crust and shoulder damaged at Ch. 400.00m. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.564405, Lat - 26.263090, Dept - PWD (Roads)),

Kabaitary to Kabaitary VI | Kabaitary | hard crust and shoulder damaged at Ch. 100.00m. as per report received from PWRD, Bongaigaon dated-05.07.2023 | (Long - 90.565692, Lat - 26.263246, Dept - PWD (Roads)),

**Manikpur** - Patiladoha Dhupuri Road | Dhupuri | Road surface damaged at Ch.50.00m,400.00m&850.00m. as per report received from PWRD Bongaigaon, Dated-05.07.2023 | (Long - 90.800739, Lat - 26.489743, Dept - PWD (Roads)),

Dangaigaon Kirtanpara road | Kirtanpara | Hard crust and shoulder damaged at Ch.2nd Km. as per report received from PWRD Bongaigaon, Dated- 05.07.2023 | (Long - 90.742132, Lat - 26.436118, Dept - PWD (Roads)),

Manikpur Chakihali Road | Manikpur | Approach of RCC Br No: 3/1, 4/1, & 5/1. as per report received from PWRD Bongaigaon, Dated- 05.07.2023 | (Long - 90.822465, Lat - 26.443540, Dept - PWD (Roads)),

Manikpur Nowagaon to Takabari Road | Nowagaon | Approach of RCC Br No: 2/1 and shoulder damaged at Ch. 2nd km and 3rd Km. as per report received from PWRD Bongaigaon, Dated- 05.07.2023 | (Long - 90.839409, Lat - 26.437932, Dept - PWD (Roads)),

T-4 Abadi Road | Abadi | Approach damage of RCC No 1/1 .as per report received from PWRD Bongaigaon, Dated- 05.07.2023 | (Long - 90.843080, Lat - 26.430090, Dept - PWD (Roads)),

Sidalsuti Gerukabari Road | Sidalsuti | Road surface damaged at 1st and 2nd Km . as per report received from PWRD Bongaigaon, Dated- 05.07.2023 | (Long - 90.692859, Lat - 26.457636, Dept - PWD (Roads)),

Manash Ghat to Sakihali Road | Sakihali | Hard Crust and shoulder damaged damaged at 1st Km, 2nd Km, 3rd Km & 4th Km.as per report received from PWRD Bongaigaon, Dated-05.07.2023 | (Long - 90.755595, Lat - 26.461597, Dept - PWD (Roads)),

Gerukabari Kirtanpara Road | Kirtanpara | Hard Crust, water logging & surface logging damaged at Ch at 2nd Km. as per report received from PWRD Bongaigaon, Dated- 05.07.2023 | (Long - 90.698775, Lat - 26.463197, Dept - PWD (Roads)),

Gerukabari Kirtanpara Road | Gerukabari | Hard Crust, shoulder damaged at Ch. 4th Km.as per report received from PWRD Bongaigaon, Dated- 05.07.2023 | (Long - 90.708918, Lat - 26.453824, Dept - PWD (Roads)),

Dangaigaon Kirtanpara Road | Dangaigaon | Hard Crust, shoulder damaged at Ch. 2nd Km.as

	T	,	
			per report received from PWRD Bongaigaon, Dated- 05.07.2023   (Long - 90.792132, Lat -
			26.436118, Dept - PWD (Roads)), Manikpur Sakihali Road   Manikpur   RCC Br No: 4/1, 4/2 & 5/1 approach damaged. as per
			report received from PWRD Bongaigaon, Dated- 05.07.2023   (Long - 90.826871, Lat -
			26.434161, Dept - PWD (Roads)),
			Gorimari Kawatika Road   Gorimari   shoulder damaged at 1st and 2nd Km.as per report
			received from PWRD Bongaigaon, Dated- 05.07.2023   (Long - 90.673449, Lat - 26.481138,
			Dept - PWD (Roads)), Monakosha Kawatika Road   Monakosha   shoulder damaged at 1st and 2nd Km.as per report
			received from PWRD Bongaigaon, Dated- 05.07.2023   (Long - 90.686945, Lat - 26.483188,
			Dept - PWD (Roads)),
			Bhandara Pt-I to Bhandara Pt-V PMGSY Road.   Bhandara   shoulder and Hard crust damaged
			at 1st and 2nd Km.as per report received from PWRD Bongaigaon, Dated- 05.07.2023   (Long
			- 90.793627, Lat - 26.466382, Dept - PWD (Roads)), Srijangram - NH -31 to Thakuranipara MPNA road   Thakuranipara   Shoulder and slope &
			hard crust of Bridge approach damage at Ch.55.00m. as per report received from PWRD,
			Bongaigaon dated- 05.07.2023   (Long - 90.652625, Lat - 26.417518, Dept - PWD (Roads)),
			Roha Chakla Kokila Road ( Kokila to Guinalguri Road )   Chakla   RCC Br No: 10/1 approach
			eroded at Ch. 10Km. road embankment damaged.as per report received from PWRD, Bongaigaon dated- 05.07.2023   (Long - 90.840543, Lat - 26.356656, Dept - PWD (Roads)),
			Nowagaon Rangapani Road   Nowagaon   Road Shoulder eroded at Ch. 1st, 2nd and 3rd Km.
			as per report received from PWRD, Bongaigaon dated- 05.07.2023   (Long - 90.820043, Lat -
			26.395041, Dept - PWD (Roads)),
			Chakla Kirtanpara Road.   Chakla   RCC Br No: 6/1, 7/1, aprroaches and at Road embankment
			at Ch. 6th and 7th Km.as per report received from PWRD, Bongaigaon dated- 05.07.2023   (Long - 90.778711, Lat - 26.382539, Dept - PWD (Roads)),
			Lotibari Barajana Road   Lotibari   Hard Crust and shoulder damaged at Ch. 3rd, 4th and 5th
			Km.as per report received from PWRD, Bongaigaon dated- 05.07.2023   (Long - 90.668048,
			Lat - 26.274030, Dept - PWD (Roads)),
			Lotibari Daspara Road   Daspara   shoulder damaged at 1st Km. as per report received from
			PWRD, Bongaigaon dated- 05.07.2023   (Long - 90.679860, Lat - 26.283520, Dept - PWD (Roads)),
			Abhayapuri College to Batabari Road   Abhayapuri   Approach of SPT Br. No 1/1. as per
			report received from PWRD, Bongaigaon dated- 05.07.2023   (Long - 90.658560, Lat -
			26.333220, Dept - PWD (Roads)),
			Barjana I to Barjana III   Barjana   Shoulder damaged at Ch. 0.00m to 480.00m. as per report received from PWRD, Bongaigaon dated- 05.07.2023   (Long - 90.657850, Lat - 26.358330,
			Dept - PWD (Roads)),
			Dangtol - Dhaligaon Chunga pota Road   Dhaligaon   Face wall of drain and shoulder of road
			eroded at Ch. 400.00m. as per report received from PWRD, Bongaigaon dated-05.07.2023
			(Long - 90.513174, Lat - 26.485866, Dept - PWD (Roads)),
			Chungapota Barpathar Road   Chungapota   Carriage way depressed and unworthy for traffic at Ch. 3km near Dhaligaon GP Office.as per report received from PWRD, Bongaigaon dated-
			05.07.2023   (Long - 90.504668, Lat - 26.496870, Dept - PWD (Roads))
			Matia - Nepalikhuti to Krishnai Road   Near Sardarpara   Approaches are damaged and sub
			sided of RCC Bridge No. 11/1 as reported by PWRD, Dudhnoi & Goalpara East Territorial
			Road Division, Goalpara on 05/07/2023   (Long - 90.676979, Lat - 26.046764, Dept - PWD (Roads)),
			Balijana - KARBALA GOVINDAPUR ROAD   KARBALA GOVINDAPUR ROAD   As per
			reported by PWDRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara on
			05/07/2023 via WhatsApp Group (Balijana Circle Task Force) Name of the Road: Karbala
			Govindapur Road Nature of damage: Carriage way and side berm damaged causing huge holes at Ch 1700.00 m and side berm heavily eroded at chainage 500.00 m to 750.00 m, Ch 900.00 m
	Goalpara	3	to 1100.00 m, Ch 1130.00 m to 1250.00 m, Ch 1300.00 m to 1500.00 m and Ch 2050.00 m to
			2300.00 m   (Long - 90.597441, Lat - 26.168231, Dept - PWD (Roads)),
			MESELKHOWA HATIGAON ROAD   MESELKHOWA HATIGAON   As per reported by
			PWDRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara on 05/07/2023 via
			WhatsApp Group (Balijana Circle Task Force) Name of the road: Meselkhowa Hatigaon Road Nature of Damage: Approaches are damaged and subsided of RCC Bridge No.1/1, 1/2, and 6/1
			on 1/1, Latitude: 25.9710977 Longitude: 90.5655099 on 1/2, Latitude: 25.9719402 Longitude:
			90.5632729 on 6/1, Latitude: 25.9834736 Longitude: 90.5215622   (Long - 90.565510, Lat -
			25.971098, Dept - PWD (Roads))
			<b>Nalbari</b> - Kendukuchi road near LP School   Kendukuchi   as per the report received from LM and local people on 04/07/2023, this road is affected due to flood on Dated: 24/06/2023.
	Nalbari	1	However no damage report received from PWD, road department till now for this particular
			road   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
1			
	Total	49	
Infrastructure Damaged -	Total  District/Sub- division*	49 Number	Details

Bridge	Bongaigaon	Manikpur - Patiladaha Kawadi to Sonalikhola Road   Patiladaha   Spt. Br No 1/1 damaged. as per reporet received from PWRD, Bongaigaon dated- 05.07.2023   (Long - 90.771368, Lat - 26.523520, Dept - PWD (Roads))					
	Total						
Infrastructure Damaged - Wildlife	Nil						
	District/Sub- division*	Other Details					
	Bongaigaon	Bongaigaon - Culvert Approach Road Damaged   Approach road of Nakkati Hill. HP Culvert damaged at Ch. 1700.00m. Long-90.52581, Lat-26.393261. as per report received from PWRD, Bongaigaon dated-05.07.2023,  Culvert Approach Road Damaged   Rachigaon to Chengmari Road. HP Culvert damaged at Ch. 1890.00m.Latitude: 26.3788, Longitude: 90.485986. as per report received from PWRD, Bongaigaon dated-05.07.2023,  Boitamari - Culvert Approach Road Damaged   Jogighopa Oudubi Salbari Road. HP Culvert damaged at Ch. 14500.00m. Latitude: 26.28896 Longitude: 90.485027 as per report received from PWRD, Bongaigaon dated-05.07.2023					
I.C.	Dibrugarh	<b>Chabua</b> - Protection Bundh Damaged   As per information received from WRD Flood damage observed in the ongoing protection work at Pukhurijan village as on 04.07.2023. Reach length-80 mtrs. Gps-27 33'30.81" N/95 11'57.35" E to 27 33'30.55" N/95 11'54.76" E					
Infrastructure Damaged - Others	Goalpara	Lakhipur - Power Dept. Conductors   As per report of APDCL Lakhipur ESD, LT conductor snapping 1 KM and HT conductor snapping 4 KM at Haldibari has been damaged on 04.07.2023 and information received on 05.07.2023,  Power Dept. Poles   As per report of APDCL Lakhipur ESD, 10 nos HT Pole and 2 nos LT Pole at Haldibari has been damaged due to overflow and side erosion of river Ghagua on 04.07.2023 and information received on 05.07.2023					
	Kamrup	North Ghy - Anganwadi Centres Affected   Bonmaja AWC was affected due to the flood waters on 04/07/2023 in village Bonmaja of Sila Sinduri Ghopa Mouza as per report received from CDPO, Bezera ICDS.					
	Karbi Anglong	Silonijan - Road Breaches   Due to heavy rain and increased of River water level of Diffollo River, Malasi road at Kosor Rongpi Village has been eroded .Length of eroded 60 m under DRDA, Karbi Anglong(Rongmonve Dev. Block) under Silonijan Rev. Circle. GPS coordinated Lat: 26.5867140 Long 93.569947 0 dated 4th June, 2023					
	Lakhimpur	<b>Dhakuakhana</b> - Bridge Approach Road Damaged   RCC Bridge no. 1/1 on Thekeraguri to Khajua Nepali road is damaged due to incessant rain and raising water level on 04/07/2023. Report submitted by Dhakuakhana Territorial Road Division, Ghilamara.					
	District/Sub- division*	Details					
	Baksa	Barama - 1. Dolbari 2. Saukuchi 3. Agchia 4. Niz Juluki   1. Erosion occurred on riverine L/B of Mora Pagladia river at village Dolbari (Gaibari supa) at a stretch of 400 m approx on 04/07/23. Lat: 26.582945 Lon: 91.391315 2. Erosion occurred on R/B of Mora Pagladia river at village Saukuchi (Muslim supa) at a stretch of 500 m approx. on 29/06/23. Lat: 26.585368 Lon: 91. 389909 3. Severe erosion at village Agchia on L/B of river Morapagladia at stretch of 800 m approx. Occurred on 26/06/2023. Lat: 26.596657 Lon: 91.400852 4. Erosion occurred on L/B of Mora Pagladia river at village Niz Juluki near Circle Office, Barama at a stretch of 150 m approx. on 02/07/23. Lat: 26.521221 Lon: 91. 351969   0   (Long - 91.391315, Lat - 26.582945)					
	Barpeta	<b>Kalgachia</b> - Kaurjahi   Ongoing erosion of river Beki at Kaurjahi Village (As per report of concern LM, 1 no. of house viz., Hunufa Khatun, D/o Lt. Abul Hussen, area-00B-01K-05L, shifted her house to another place) reported by LM on 04.07.2023   0   (Long - 90.895260, Lat - 26.373795)					
Erosion	Chirang	Bijni - Amguri village, Sisubari village   As reported by EE, Chirang Water Resource Division, Kajalgaon, bank erosion on R/B of river khanamakra at Amguri village. Length=150.00 mtr, Breadth=3.00 mtr, Depth=2.00 mtr. Latitude=26.641725 Longitude=90.568855. Date of Occurrence=04-07-2023. As reported by EE, Chirang Water Resource Division, Kajalgaon, bank erosion on R/B of river khanamakra at Sisubari village. Length=550.00 mtr, Breadth=5.50 mtr, Depth=2.00 mtr. Latitude=26.692927 Longitude=90.591724. Date of Occurrence=04-07-2023.   0   (Long - 0.000000, Lat - 0.000000)					
	Dibrugarh	<b>Tingkhong</b> - 4 no.Sopatoli village   As reported by WRD on 04 /07/2023 erosion has caused by river Disang at 4 no. Sopatoli village of approx. Length 200m.   0   (Long - 95.164779, Lat - 27.136724)					
	Majuli	<b>Majuli</b> - Kartik Chapori NC   Erosion occured on 5th July and one family has been shifted to a nearby splace. Approximately 2 katha of land area have been eroded.   2   (Long - 94.164901, Lat - 26.841096)					
	Nalbari	<b>Banekuchi</b> - Barkhetri Banekuchi in Burhadia river   Eroded On 26/06/2023 in Burhadia River at Barkhetri Banekuchi and report received from Gaon Pradhan on 04/07/2023   20   (Long - 0.000000, Lat - 0.000000)					
	Sonitpur	<b>Dhekiajuli</b> - Rangagarah   Erosion Report received from concern LM of Rangagarah Gaoan on 04-07-2023. As per LM report No people has not been affected till now.   0   (Long - 92.543500, Lat - 26.678390)					
	Tamulpur	<b>Tamulpur</b> - Kachubari   As pef the report received on 05/07/2023 from Tamulpur division Irrigation, erosion on the left bank of River Laldong at Village Kachubari from ch50.00m to ch.230.00m and from ch. 400.00m to ch.580.00m   0   (Long - 91.610010, Lat - 26.633163)					

Landslide	Nil
Urban Flood	Nil
	*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)