

## **FRIMS Assam**



## Flood Reporting And Information Management System

	Assam Daily Flood Report as on 16-06-2023 at 4:00 PM										
Particulars	Situation as		`	t 24 hours)	1 1						
Rivers flowing	Rivers flowing level	ng above da	anger	Nil	Nil						
above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing flood level	ng above hi	ghest	Nil							
District	No. of Districts Affected	Name of	Flood Aff	ected Districts		Name of Urban Flood Districts					
Affected	11			, Dhemaji, I ur, Udalguri	Dhemaji, Dibrugarh, r, Udalguri Cachar, Jorhat, Kamrup (M), Nalbari						
No. Of Revenue Circles Affected	17										
	District	Total	Revenue	e Circle							
	Biswanath	1	Halem								
	Cachar	1	Silchar								
	Darrang	2		loi, Dalgaon							
	Dhemaji	2		gaon, Dhema	aji						
Name Of	Dibrugarh	1	Chabua								
Revenue	Jorhat	1	Jorhat W	<sup>7</sup> est							
Circles Affected	Kamrup (M)	2	_	Dispur, Guwahati							
	Lakhimpur	4		Narayanpur,	Nowboicha, l	North Lakhimpur					
	Nalbari	1	Nalbari								
	Tamulpur	1	Goreswar								
	Udalguri	1	Kalaigaon								
	Total  District	17 Total	Dovers	Province Clark							
	Biswanath	10tal	Revenue Circle ( Halem   17 )								
	Darrang	18	( Halem   17 ) ( Mangaldoi   1 ), ( Dalgaon   17 )								
	Dhemaji	8		(Mangaidoi   1), (Daigaon   17) (Sissiborgaon   1), (Dhemaji   7)							
Villages	Dibrugarh	1		(Sissiborgaon   1 ), (Dilettiaji   7 ) (Chabua   1 )							
Affected	Lakhimpur	22	(Kadam   2), (Narayanpur   8), (Nowboicha   11), (North Lakhimpur   1)								
	Tamulpur	3	(Goreswar   3)								
	Udalguri	8	(Kalaigaon   8)								
	Total	77									
	District	Male	Femal e	Childre n	Total Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details			
	Biswanath	999	831	401	2231	( Halem   2231 )	12.50	( Halem   12.50 )			
	Darrang	1303	1013	915	3231	( Mangaldoi   54 ), ( Dalgaon   3177 )	70.00	( Mangaldoi   0.00 ), ( Dalgaon   70.00 )			
Population And Crop	Dhemaji	461	467	157	1085	( Sissiborgaon   366 ), ( Dhemaji   719 )	33.00	( Sissiborgaon   15.00 ), ( Dhemaji   18.00 )			
Area	Dibrugarh	1567	1240	1050	3857	( Chabua   3857 )	0.00	( Chabua   0.00 )			
Affected	Lakhimpur	11275	11026	1215	23516	( Kadam   0 ), ( Narayanpur   0 ), ( Nowboicha   22466 ), ( North Lakhimpur   1050 )	21.87	( Kadam   4.07 ), ( Narayanpur   17.80 ), ( Nowboicha   0.00 ), ( North Lakhimpur   0.00 )			
	Tamulpur	0	0	0	0	(Goreswar   0)	3.50	( Goreswar   3.50 )			
	Udalguri	122	98	49	269	( Kalaigaon   269 )	68.80	( Kalaigaon   68.80 )			

	Total	15727	14675	3787	34189			209.67		
D-1:-£	District	Total	Relief C	amp			Relief Distribution Centres			
Relief	Dhemaji	1	0(Dhemaji   0) 1(Dhemaji   1) 1(Nowboicha   0, North Lakhimpur   0) 8(Nowboicha   7, North Lakhimpur   1)							
Camps / Centres	Lakhimpur	8								
Opened	Udalguri	2	1(Kalaig	aon   1)			1(Kalaigaor	n   1)		
Opened	Total	11	1				10			
Inmates In Relief Camps	District	Total		e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y
	Udalguri	21	(Kalaiga	on   21)		12	8	0	1	0
	Total	21				12	8	0	1	0
Human Lives Lost - Confirmed	Nil									
Human Lives Lost Confirmed - Death Type	Nil									
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
	District	Total	Big	Small	Poultry					
	Biswanath	2300	1700	600	0					
,	Dhemaji	326	88	62	176					
Animals	Lakhimpur	3527	2686	841	0					
Affected	Tamulpur	2684	984	1700	0					
	Udalguri	282	50							
	Total	9119	5508	3283	328					
Animals Washed Away Houses Damaged	Nil Nil									
Rescue Operation	District	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopter s Deployed	Person Evacuated By Helicopter s	Medical Team Deploye d
	Lakhimpur				0	0	0	0	0	4
	Total				0	0	0	0	0	4
Relief Distributed	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)		
	Dhemaji	3.31	0.59	0.17	17.91	0.00	0.00	0.00		
	Lakhimpur	347.57	64.32	19.30	1930.00	0.00	0.00	331.66		
	Total	350.88	64.91	19.47	1947.91	0.00	0.00	331.66		
Relief Distributed Others	District	Liquid				Others				
	Dhemaji	0.00-Q		45.00-Pkt		Sanitary napkin-45.00-Pkt Candle-3175.00-Pkt; Sanitary Napkin-270.00-Pkt				
	Lakhimpur	0.00-Q		0.00-Q		Candle-317	5.00-Pkt; San	ıtary Napkin-2	/0.00-Pkt	
Infrastructur	District	Numbe r	Details						11	
e Damaged - Embankmen t Breached	Lakhimpur	2	Narayanpur - Farm bundh L/S-175 m R/S-175 m   Pulinaharani   On 16/06/2023 a farm bundh breached at dihiri river near dihiri high school. L/S 175 metre and R/S 175 m   (Long - 0.000000, Lat - 0.000000, Dept - P&RD),  Farm bundh L/S-900m R/S-700m   Pulinaharani   Farm bundh breached at dihiri river both side L/S 900 m and R/S 700 m as per report from P&RD on 16/06/2023   (Long - 0.000000, Lat - 0.000000,							

		1	Dept - P&RD)					
	Udalguri	2	Harisinga - No. 2 Singrimari Suklai river embankment.   No 2 Singribari   Last year breach point of No.2 Singrimari (Temporary restoration at river Suklai)has been damaged due to heavy rain. On 15.06.2023. APPROXIMATE DAMAGE: 50 meters.   (Long - 91.776100, Lat - 26.711700, Dept - Water Resource Deptt.),  Kalaigaon - Embnekment at Gerua in the R/B of river Noa   Gerua   Breached on 16/06/2023. Length 40 meters, Breadth 5 meters. Due to overtopping of river Noa   (Long - 91.986521, Lat - 26.562401, Dept - P&RD)					
	Total	4						
	District Numbe r		Details					
	Biswanath	4	Gohpur - Erosion is observed on R/Bank embankment of river Solengi.   Of length 30 mtr at Dakhin Deonabari dated 16/06/23   (Long - 93.627646, Lat - 26.807600, DeptSelect Department), Mild Erosion is observed on R/Bank of river Solengi   at Nalbari Marginal embankment of length 120 MTR on 16/06/23   (Long - 93.638512, Lat - 26.935275, Dept - Water Resource Deptt.), Mild erosion is observed on R/Bank of river Sessa.   at Gupsarguri marginal embankment of length 30 mtr on 16/06/23   (Long - 93.716944, Lat - 26.979166, Dept - Water Resource Deptt.), Mild bank Erosion is observed on R/Bank of river Sessa   at Baligaon marginal embankment near Gosarguri area of length 50 mtr on 16/06/23   (Long - 93.712256, Lat - 26.989844, Dept - Water Resource Deptt.)					
Infrastructur e Damaged -	Golaghat	2	<b>Bokakhat</b> - The Brahmaputra dyke from KRF boundary to Diffaloo pathar   Bohikhowa and Polashguri village   Affected due to heavy rain cut on 15.6.2023   (Long - 93.616420, Lat - 26.677046, Dept - PWD (Roads))					
Embankmen t Affected	Tamulpur	3	Goreswar - Tengajhar (Madalbari supa)   Village Tengajhar Mouza Betna   Due to incessant rain the water of River Suklai got overtopped of the Panchayat bandh R/B at village Tengajhar (Madalbari supa) date of occurrence 16/06/23 length of overtopped area 100 m approx. The water entered country side and affected crop area.   (Long - 91.690865, Lat - 26.604329, DeptSelect Department), Tengajhar (Ghotirpam supa)   Village Tengajhar Mouza Betna   Due to incessant rain the water of River Suklai got overtopped of the Panchayat bandh L/B at village Tengajhar (Ghotirpam supa ) date of occurrence 16/06/23 length of overtopped area 100 m approx. The water entered country side and affected crop area.   (Long - 91.692245, Lat - 26.599848, Dept - P&RD), Niz Jhargaon   Village Niz Jhargaon Mouza Defeli   Due to incessant rain the water of River Suklai got overtopped of the Panchayat bandh R/B at village Niz Jhargaon (Kujargaon) date of occurrence 16/06/23 length of overtopped area 100 m approx. The water entered country side and affected crop area.   (Long - 91.703099, Lat - 26.624359, Dept - P&RD)					
	Total	9						
	District	Numbe r	Details					
	Biswanath	3	Halem - Collegeguri road (Boro high school to Collegeguri road)   Mazgaon town part   Road is submerged by rain water due to incessant heavy rain, date- 16/06/2023   (Long - 93.604388, Lat - 26.879729, Dept - PWD (Roads)),  Tinikunia to kawripathar road   Nalanibari   Road is over topped by flood water of river Brahmajan sporadic erosion in road embankment have been noticed. date-16/06/2023   (Long - 93.477879, Lat - 26.908309, Dept - PWD (Roads)),  Gohpur - Borigaon to Deonabori Road   Road is over topped by flood water and sporadic erosion from Ch.300.00 m to Ch. 900.00m have been notiched. 16/06/2023   (Long - 93.638648, Lat - 26.908756, Dept - PWD (Roads))					
Infrastructur e Damaged -	Goalpara	1	Lakhipur - Lakhipur Tulsibari Road Pt-II   Takimari Tiniali Bazar to Cholakura Via Borbilla   As per report of PWD road department, Due to incessant rain fall for last 7 days, Lakhipur Tulsibari Road Pt-II (Takimari Tiniali Bazar to Cholakura Via Borbilla) From CH. 100 meter to CH. 115 meter affected length 15 meter eroded from 15.06.2023 to till date.   (Long - 90.298375, Lat - 26.050140, Dept - PWD (Roads))					
Road	Lakhimpur	3	Subansiri - Bangkleng to Konwarbari Road   Bangkleng to Konwarbari road is eroded at 1st KM (Ch. 350 to 470 M) (L= 120M) as per report submitted by Dhakuakhana PWD Territorial Road Division on 15/06/2023.     (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Narayanpur - Dhalpur Khalihamari road   Khalihamari   On 16/6/2023 due to over flow of pichala river dhalpur Khalihamari road eroded upto length of 10 m width 4 m and depth 1.4 m as per report from pwd roads   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Bihpuria - Garmur Block to Tunijan road (under PMGSY Package No. AS-15-194)   1) Ch. 650.00m to Ch. 750.00m 2) Ch. 1455.00m to Ch. 1700.00m   Road embankment and shoulder erosion due to impact of flood water of Gabharu river as reported by AEE, PWRD, Naoboicha Territorial Road SD on 16th June 2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))					
	Nalbari	3	Banekuchi - Nakerbari-Kaithalkuchi link Agree road breached 5mtr. Approx and submerged on 16/06/2023. reported by Gaon Pradhan at 8 AM.   Nakerbari     (Long - 91.387450, Lat - 26.457048, Dept - P&RD),  Tihu - PWD road(Haribhanga- Bali-Kaithalkuchi),   Bali   Length: 70 fts, submerged and eroded on 16/06/2023 reported by GP,   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),					

	1	1							
			ROAD OF WARD NO 7,TIHU TOWN   Tihu Town   Length: 400 mts, road is near Tihu river and eroded by accessive raining.Date:16/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - Municipal Road)						
	Tamulpur	1	Goreswar - Niz Kachula - Pukhuripar road   Village Niz Kachula   Due to incessant rain and overtopped of L/B panchayat bandh at village Tengajhar Ghotirpam supa the water entered village Niz Kachula and breach occurred on PWD road approx length 10 m. Date of occurrence 16/06/23. PWD Department is undertaking construction of bamboo footbridge for communication.   (Long - 91.692245, Lat - 26.599848, Dept - PWD (Roads))						
	Udalguri	1	Harisinga - Attarikhat jungle road   Attarikhat jungle basti   The suklai River has caused an sensations of the road in Attarikhat jungle basti road due to heavy rainfall. On 15.06.2023.  APPROXIMATE DAMAGE 70 meters.   (Long - 91.775600, Lat - 26.717500, Dept - PWD (Roads))						
	Total	12							
Infrastructur e Damaged - Bridge	Nil	•							
Infrastructur e Damaged - Wildlife	Nil								
	District	Other De							
	Baksa	Coordinate 91310289 uprooted: Power De 26.742652 26.71440	<b>Baska</b> - Power Dept. Poles   Electric pole uprooted: Total 6 nos. (A) Village: Chaulkara, 1 no. of pole uprooted, Coordinate: 26.742652, 91.381094, (B) Village: Doomni, 4 nos of pole uprooted, Coordinate: 26.714994, 91310289; 26.714407,91.310413; 26.714805, 91.310407; 26.714313, 91.310416 (C) Village: Geruapara, 1 pole uprooted: Coordinate: 26.572234, 91.337239, Date: 15/06/2023, Power Dept. Conductors   Total Conductor Damage: 700 metres, (A) Village Chaulkara: 200 metres, Coordinate: 26.742652, 91.381094, (B) Village: Doomni: 400 metres, Coordinate: 26.714994, 91310289; 26.714407,91.310413; 26.714805, 91.310407; 26.714313, 91.310416 (C) Village: Geruapara, Conductor 100 metres: Coordinate: 26.572234, 91.337239, Date: 15/06/2023						
	Biswanath	Halem - Anganwadi Centres Affected   (4nos. AWC) name-Bamunbari AWC, Chatrang Parpub AWC, Nonke Magoni AWC, Madhya Chatrang AWC Partially damaged report submitted by Chaiduar ICDS Project on 16/06/2023,  Anganwadi Centres Affected   (1 no) name-JYOUTI PARK AWC Partially damaged report submitted by Pub Chaiduar ICDS Project on 16/06/2023							
	Dhemaji		ower Dept. Poles   3 Nos. LT Poles uprooted at Bogori Chapori on 16/06/2023 by rising water from						
Infrastructur e Damaged -	Dibrugarh		<b>Chabua</b> - Anganwadi Centres Affected   Dodhia Kuligaon AWC affected as per information received from social welfare department on 16/06/2023 coordinats Lat 27.597042 Long 95.215409						
Others	Lakhimpur	ground, 2 Narayanj 16/06/202 Bihpuria water of S Nowboicl Borchala Fisheries/	Kadam - Protection Bundh Damaged   Const. of stone peripheral bundh at river gumnodi near seajuli cremation ground, 2 no.s boulder spur has been damaged. informed by P&RD, Boginadi on 16/06/2023,  Narayanpur - Fisheries/Pond   5 nos of pond 0.54 ha submerged as per report from Fishery department on 16/06/2023,  Bihpuria - Elementary Schools Damaged   1 no. of LPS (Dharmapur Block LPS) has been affected by flood water of Singra-Pabha River as reported by BEEO, Bihpuria Block on 16th June 2023,  Nowboicha - Culvert Approach Road Damaged   5/1 Culvert approach damaged at NH-15 to Mohghuli via Borchala Road on 16.06.2023. Report received from PWD (Roads),  Fisheries/Pond   Fishery overflow at Bharaluwa Village 120 Nos. (16 Hect.) on 16/06/2023. Report received						
	Nalbari	from Fishery Dept.  Banekuchi - Agri Bundh Damaged   On 16/06/2023 Nakerbari Kaithalkuchi link Agree Road at Mora Pagladia river breached at 8 AM report from Gaon Pradhan							
Erosion	Udalguri	Khairabari - Irrigation Canal/Scheme Damaged   As reported by the department, due to continuous downpouring of Rainwater, the embankment and the canal system of ria FIS has been eroded on 15. 06.2023, measuring 30M (approx.) GPS Coordinates: Lat- 26.66239 Long- 91.78524.,  Mazbat - Irrigation Canal/Scheme Damaged   Damage of RCC canal lining due to incessant rain on							
	District		3Lat: 26.834527, Long: 92.337633						
	<b>District</b> Biswanath	Biswanath - 4 No. Kumalia (Forciati)   continuous active bank erosion is observed at Forciati area in between Ch. 3rd to 4th Km of Biswanath-Panpur and 6th to 7th Km of Solmari Kalakati area of Biswanath - Panpur Dyk of river Brahmaputra. on 16/06/2023   0   (Long - 93.128236, Lat - 26.685182),  Halem - Paken   Mild bank erosion continues at Paken area of B Dyke from Jamagari to Kharoi outfall Length 3000m, date-16/06/2023 time-on 10 a.m   0   (Long - 93.627646, Lat - 26.800760),  Gohpur - At Auguri area.   Mild Erosion observed at R/Bank embankment of river Sessa. on 16/06/2023   0							
	Bongaigao n	(Long - 93.737047, Lat - 26.952548)  Srijangram - Tinkonia Pt 3   Severe erosion is still continuing where 4 no.s of houses are dismantled/damaged dated 16.06.2023   17   (Long - 90.642354, Lat - 26.238262)							
	Dibrugarh	Dibrugarh West - Bhogamur Block Gaon ring bund   Due to the rising water level of river Buridehing damage to the DRDA ring bund at Bhogamur Block Gaon has been observed on 15-06-2023 as per report received from Dibrugarh East Water Resources Sub-division. The distance to the DRDA ring bund from damaged bank is merely 4-5 m as on 16.06.2023.   0   (Long - 94.503880, Lat - 27.163641)							
	Golaghat		- Thuramukh Moinapara   Erosion at Thuramukh Moinapara date 16.06.2023. Erosion reach length						

200m   0   1 (1 org. +93.948472, 1.a26.498455),   Sarupathar - Dabroroni   1 Frostian an Dabroroni village, Reach length 220m on 15.06.2023, [0 ] (1 cang. +93.876470, 1.a26.289902)			
Jorhat West 1. Jolity Chapori, Sapekhati and Khokonguri -date 1.6006/2023   Irosion occurred at Lolity Chapori (56m), Sapekhati (250maat Khokonguri (700m)areas due to rise of water level in Brahmapturi river. 1 (Long. 94.045790, Lat. 26.795560)  Rarhi Anglong West All Change 9. 26.795560, Lat. 26.795560)  West All Change 9. 25.74000, Lat. 25.853000)  Lakhimpur 1 (1506/2023 at around 5:30 PM, as reported by Local public. The crossion length was about 12M. 15 (Long. 9. 25.74000, Lat. 25.853000)  Bharagaon. Kupatimari, Balldunga   As per Water Resource department. Morigaon. Burahmapura river crossion croded I meter at a length of 500 meter at Kupatimari and Baldunga Pan revenue village under Bharagaon. Kupatimari, Baldunga   As per Water Resource department. Morigaon. Burahmaputar river crossion croded I meter at a length of 500 meter at Kupatimari and Baldunga Pan revenue village under Bharagaon. Rev. Circle from 15-06-2023 to 16-06-2023   15 (Long. 2-06-11003, Lat. 92.251558), and the standard of the crossion croded I meter at a length of 500 meter at kupatimari and Baldunga Pan revenue village under Bharagaon. Rev. Circle from 15-06-2023 to 16-06-2023   15 (Long. 9-20.13168), Lat. 92.251558), and the standard of the crossion is observed at Chattau area on the R?Bank of river diabhara on DTD1 16.06-2023, and crossion (200m) observed at Chattau area on the R?Bank of river diabhara on DTD1 16.06-2023 landare crossion (200m) observed at Chattau area on the R?Bank of river Gabbara on DTD1 16.06-2023 landare crossion (200m) observed at Chattau area on the R?Bank of river Gabbara on DTD1 16.06-2023 landare crossion (200m) observed at Chattau area on the R?Bank of river Gabbara on DTD1 16.06-2023 landare crossion (200m) observed at the third of river Suklai at village Bholiphar (Kakati supa) porcupine of WR department got washed a			
Anglong Lakhimpur Lakhimpu		Jorhat	Jorhat West - Lolity Chapori, Sapekhati and Khokonguri . date : 16/06/2023   Erosion occurred at Lolity Chapori (65m), Sapekhati (250m)and Khokonguri (700m)areas due to rise of water level in Brahmaputra river.
Anglong Lakhimpur Lakhimpu		Karbi	<b>Donkamokam</b> - Harlongjuve, Hamren   Due to continuous rains an erosion was occurred at Harlongjuve, Hamren
Lakhimpu		Anglong	AGCC colony on 15/06/2023 at around 5:30 PM ,as reported by Local public. The erosion length was about 12M.
erosion eroded 1 meter at a length of 500 meter at Kupatimari and Balidunga Pam revenue village under Bhuragaon Rev. Circle from 15-06-2023 to 16-06-2023 [3 Is ] (Long - 26.411003, Lat - 22.21558), Laharighat - Kathani   As per Water Resource Department, Morigaon, River Brahmaputra erosion eroded 1 meter at a length of 500 meter at Kathani revenue village under Laharighat Revenue Circle from 15-06-2023 to 16-06-2023. [0   (Long - 92.3168, Lat - 26.457048)]    Nalbari   Banekuchi - Nakerbari (Kaithalkuchi) on 16/06-2023   Apr.5 mtr. erosion had seen at Mora Pagladia river   30   (Long - 91.387450, Lat - 26.457048)    Thelamara - Ginatua   Date-16/06/2023, As reported by Texpur Water Resource Division on 16/06-2023, Bank erosion is observed at Ghatua area on the R/Bank of river Gabharu. Length-200m   0   (Long - 92.630724, Lat - 26.699556).   Chariduar - I) Sonaipam 2/Ghatua   I)As reported by W.R bank erosion(450m) is observed on the R/Bank of river Jabharati at Sonaipam area on DTD 16.06.2023.]Bank erosion (200m) observed at Ghatua area on the R/Bank of river Gabharu on DTD 16.06.2023.]Bank erosion (200m) observed at Ghatua area on the R/Bank of river Gabharu on DTD 16.06.2023.] Due to incessant rain erosion occurred on the left bank of river Suklai at village Bholajhar (Kakati supa) parcupine of WR department got washed away as per information from WR department. Length of recision Approx 100 m   0   (Long - 91.742967, Lat - 26.68380)    Dittial		Lakhimpur	Narayanpur - No.1 garubandha   Erosion at upstream guide bundh of Pichala FIS at chainage 100 m to 200 m from head regulator at Shankarpur as per report from Bihpuria Irrigation department on 16/06/2023   0   (Long -
Nalbari		Morigaon	erosion eroded 1 meter at a length of 500 meter at Kupatimari and Balidunga Pam revenue village under Bhuragaon Rev. Circle from 15-06-2023 to 16-06-2023   35   (Long - 26.411003, Lat - 92.251558), Laharighat - Kathani   As per Water Resource Department, Morigaon, River Brahmaputra erosion eroded 1 meter at a length of 500 meter at kathani revenue village under Laharighat Revenue Circle from 15-06-2023 to
Positive   Sonitpur   Chariduar - 1   Sonaipam		Nalbari	Banekuchi - Nakerbari (Kaithalkuchi) 0n 16/06/2023   Apr.5 mtr. erosion had seen at Mora Pagladia river   30
river Jiabharali at Sonaipam area on DTD 16.06.2023.2)Bank erosion (200m) observed at Ghatua area on the R/Bank of river Gabharu on DTD 16.06.2023 Latitude -26.696956, Longitude -92.630724   0   (Long - 92.825120, Lat - 26.879842)  Tamulpur   Goreswar - Village Bholajhar (Kakati supa) 16.06/23   Due to incessant rain erosion occurred on the left bank of river Suklai at village Bholajhar (Kakati supa) parcupine of WR department got washed away as per information from WR department Length of erosion Approx 100 m   0   (Long - 91.742967, Lat - 26.683380)  Udalguri - Dhansiri Irrigation Project   RCC fall damaged at channel 6360.00m of D1B3M canal of Dhansiri Irrigation Project on dated 16.06.23   0   (Long - 92.073384, Lat - 26.750802)    Haflong - Fianpui, Sengya Tularam Raji, Kashipur, Dibarai, Saron, Songbung   1 Residence of Shri Lalparthang Thick, Saron Village, Lat-25.184085, Long:-93.118347 3. Residence of Shri Lalparthang Thick, Saron Village, Lat-25.184085, Long:-93.105384 3. Residence of Shri Bandana Gurung, Kashipur Village, Lat:-25.197172, Long:-93.007817. Dated: 16-06-2023   0   (Long - 0.000000, Lat - 0.000000)    Hajo - Hatimura   Due to incessant rainfall a stone rolled down the hill. On 16/06/2023. 1 no of family affected.   5   (Long - 26.172370, Lat - 91.472420)    District   Details   Silchar - National Highway, Link Road, Ambicapatty, N.S. AVENUE, Sonai Road, Malinibeel, Bilpar, Nagatilla   Flash flood due to heavy rain on dated 16.06.2023. As reported by Circle Officer Silchar Sadar.   0   (Long - 0.000000, Lat - 0.000000). Lat - 0.000000)    Dispur - Hatigaon, Wireless, Rukminigaon, Baghorbori, Kalitakuchi.   Water-logging at Sijubari-Hatigaon, Wireless BSNL office's back side, Rukminigaon, Manasha Mandir, near Rukminigaon, High School, Baghorbori, Kalitakuchi due to last night heavy rainfall. Dated: 16-06-2023   0   (Long - 0.000000), Lat - 0.000000)    Dispur - Hatigaon, Wireless, Rukminigaon Manasha Mandir, near Rukminigaon High School, Baghorbori, Kalitakuchi due to last night heavy ra		Sonitour	<b>Thelamara</b> - Ghatua   Date-16/06/2023, As reported by Tezpur Water Resource Division on 16/06/2023, Bank erosion is observed at Ghatua area on the R/Bank of river Gabharu. Length-200m   0   (Long - 92.630724, Lat - 26.696956),
Tamulpur river Suklai at village Bholajhar (Kakati supa) parcupine of WR department got washed away as per information from WR department. Length of erosion Approx 100 m   0   (Long - 91.742967, Lat - 26.683380)  Udalguri Dhansiri Irrigation Project   RCC fall damaged at channel 6360.00m of D1B3M canal of Dhansiri Irrigation Project on dated 16.06.23   0   (Long - 92.073384, Lat - 26.750802)    District   Details		Dompar	river Jiabharali at Sonaipam area on DTD 16.06.2023,2)Bank erosion (200m) observed at Ghatua area on the R/Bank of river Gabharu on DTD 16.06.2023 Latitude -26.696956, Longitude -92.630724   0   (Long - 92.825120, Lat - 26.879842)
Urban Flood   Urban Flood		Tamulpur	river Suklai at village Bholajhar (Kakati supa) parcupine of WR department got washed away as per information
Landslide   Dima- Hasao   Di		Udalguri	Udalguri - Dhansiri Irrigation Project   RCC fall damaged at channel 6360.00m of D1B3M canal of Dhansiri
Dima-Hasao		District	Details
District   Details	Landslide		Nampui, Fiangpui Village Lat:-25.172957, Long:-93006013 2. Residence of Shri Lalparthang Thiek, Saron Village Lat:-25.184085, Long:-93.118347 3. Residence of Shri Bandana Gurung, Kashipur Village Lat:-25.193727, Long:-93.015388 4. Residence of Shri Shanmaidao Kemprai, Dibarai Village, Lat:-25.171972,
Cachar    Cachar		Kamrup	
Cachar    Cachar   Nagatilla   Flash flood due to heavy rain on dated 16.06.2023. As reported by Circle Officer Silchar Sadar.   0		District	Details
Urban Water logging occurred due to Intense rain from last few days.   0   (Long - 0.000000, Lat - 0.000000)    Wireless BSNL office's back side, Rukminigaon Manasha Mandir, near Rukminigaon High School, Baghorbori, Kalitakuchi due to last night heavy rainfall . Dated: 16-06-2023   0   (Long - 0.000000, Lat - 0.000000), Guwahati - Pachim Boragaon   Due to rain on 16/06/2023 waterlogging took place on pachim Boragaon near excelcare hospital   0   (Long - 0.000000, Lat - 0.000000)    Nalbari - Commerce collage road, veterinary roas, malikuchi road, Debiram H.S -balilecha road, Nalbari-Hajo road, Bhakat para road, Forest office road, circuit house road, Law collage road, Agriculture office road, Block office road, L.N.B road, Palla road, Alternative road, Satra MV to Premoda hotel road, Bishnupur road   As per the LM report, on dated 16.06.2023, these area of Nalbari Town under Nalbari Rev Circle are submerged due to rain water   1800   (Long - 0.000000, Lat - 0.000000)	Urban Flood	Cachar	Nagatilla   Flash flood due to heavy rain on dated 16.06.2023. As reported by Circle Officer Silchar Sadar.   0
Urban Flood  Kamrup (M)  Wireless BSNL office's back side, Rukminigaon Manasha Mandir, near Rukminigaon High School, Baghorbori, Kalitakuchi due to last night heavy rainfall . Dated:16-06-2023   0   (Long - 0.000000, Lat - 0.000000),  Guwahati - Pachim Boragaon   Due to rain on 16/06/2023 waterlogging took place on pachim Boragaon near excelcare hospital   0   (Long - 0.000000, Lat - 0.000000)  Nalbari - Commerce collage road, veterinary roas, malikuchi road, Debiram H.S -balilecha road, Nalbari-Hajo road, Bhakat para road, Forest office road, circuit house road, Law collage road, Agriculture office road, Block office road, L.N.B road, Palla road, Alternative road, Satra MV to Premoda hotel road, Bishnupur road   As per the LM report, on dated 16.06.2023, these area of Nalbari Town under Nalbari Rev Circle are submerged due to rain water   1800   (Long - 0.000000, Lat - 0.000000)		Jorhat	
road, Bhakat para road, Forest office road, circuit house road, Law collage road, Agriculture office road, Block office road, L.N.B road, Palla road, Alternative road, Satra MV to Premoda hotel road, Bishnupur road   As per the LM report, on dated 16.06.2023, these area of Nalbari Town under Nalbari Rev Circle are submerged due to rain water   1800   (Long - 0.000000, Lat - 0.000000)		_	Dispur - Hatigaon, Wireless, Rukminigaon, Baghorbori, Kalitakuchi.   Water-logging at Sijubari-Hatigaon, Wireless BSNL office's back side, Rukminigaon Manasha Mandir, near Rukminigaon High School, Baghorbori, Kalitakuchi due to last night heavy rainfall . Dated:16-06-2023   0   (Long - 0.000000, Lat - 0.000000), Guwahati - Pachim Boragaon   Due to rain on 16/06/2023 waterlogging took place on pachim Boragaon near
*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)		Nalbari	road, Bhakat para road, Forest office road, circuit house road, Law collage road, Agriculture office road, Block office road, L.N.B road, Palla road, Alternative road, Satra MV to Premoda hotel road, Bishnupur road   As per the LM report, on dated 16.06.2023, these area of Nalbari Town under Nalbari Rev Circle are submerged due to
			*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)