

## **FRIMS Assam**





	Assam Daily Flood Report as on 04-07-2023 at 4:00 PM											
Particulars	Situation as on 04-07-2023 (in last 24 hours)											
Rivers flowing above Danger	S per lletin Pivers flowing shove highest flood level Nil											
Level (as per CWC bulletin issued at 8 AM)												
District/Sub-division	No. of Districts/Sub -divisions* Affected	Name of Flood Affected Districts/Sub- divisions*					Name of Urban Flood Districts/Sub-divisions*					
Affected	5	Bajali, Dhemaji, Kamrup, Kokrajhar, Udalguri										
No. Of Revenue Circles Affected	8	5										
	District/Sub- division*	Total	Revenue Circle									
Name Of	Bajali	2	Sarupeta, Bajali									
Revenue	Dhemaji	1	Sissiborgaon  North Chy Heir Konstern									
Circles Affected	Kamrup Kokrajhar	3	North Ghy, Hajo, Kamalpur									
Affected	Udalguri	1	Kokrajhar Mazbat									
	Total	8	Mazbat									
	District/Sub-		_									
	division*	Total	Revenue Circle									
	Bajali	4	(Sarupeta   1), (Bajali   3)									
Villages	Dhemaji	1	(Sissiborgaon   1)									
Affected	Kamrup	53	(North Ghy   6), (Hajo   35), (Kamalpur   12)									
	Kokrajhar	1	(Kokrajhar   1)									
	Udalguri	1	( Mazbat   1 )									
	Total	60										
	District/Sub- division*	Male	Femal e	Childre n	Total Popular n	tio	Population Details		Crop Area ( in Hect. )	Crop Area		
Population	Bajali	3042	2906	718	6666		Bajali   6608 )		15.00	( Sarupeta   Bajali   15.0	00)	
And Crop Area	Dhemaji	136	146	85	367		(Sissiborgaon   367)		15.00	( Sissiborga )	•	
Affected	Kamrup	2	2	4	8		( North Ghy   8 ), ( Hajo   0 ), ( Kamalpur   0 )		215.20	( North Ghy   10.50 ), ( Hajo   193.00 ), ( Kamalpur   11.70 )		
	Kokrajhar	41	39	33	113		( Kokrajhar   113		0.00	( Kokrajhar   0.00 )		
	Udalguri	53	52	20	125				( Mazbat   0	0.00 )		
	Total	3274	3145 860 7279				245.20					
	District/Sub- division*	Total	Relief Camp				<b>Relief Distribution Centres</b>					
Relief Camps	Bajali	9	0(Bajali   0)				9(Bajali   9)					
/ Centres	Dhemaji	1	0(Sissiborgaon   0)				1(Sissiborgaon   1)					
Opened	Kamrup	1	1(North Ghy   1)				0(North Ghy   0)					
_	Kokrajhar	1	1(Kokrajhar   1)				0(Kokrajhar   0)					
	Udalguri Total	13	0(Mazbat   0) 2				1(Mazbat   1) 11					
Inmates In	District/Sub-		Femal Childre Pregnant Per				Person					
Relief Camps	division*	Total	Revenue Circlewise				Male	e	n	/	with	

									Lactatin g Mother	Disabilit y	
	Kamrup	8	(Hajo   0 Ghy   8)	), (Kamalpui	(   0), (North	2	2	4	0	0	
	Kokrajhar Total	113 <b>121</b>	(Kokrajh	ar   113)		41 <b>43</b>	34 <b>36</b>	33 <b>37</b>	5 <b>5</b>	0	
Human Lives Lost - Confirmed	Nil	121				10	30	37	13	l v	
Human Lives Lost Confirmed - Death Type	Nil										
Human Lives Lost - Missing Human Lives	Nil										
Lost Missing - Type	Nil										
	District/Sub- division*	Total	Big	Small	Poultry						
Animals	Bajali	3006	1424	1111	471						
Affected	Dhemaji Kamrup	110 4550	55 4450	35 100	20						
	Total	<b>7666</b>	<b>5929</b>	1246	0 491						
Animals Washed Away	Nil										
Houses Damaged	Nil										
Rescue Operation	Nil										
Relief Distributed	District/Sub- division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Foode r (in	Cattle Feed - Wheat Bran (in Q)	cattle Feed - Rice Bran (in Q)			
	Dhemaji	6.06	1.01	0.33	32.85	<b>Q</b> )	0.00	0.00			
	Udalguri	2.13	0.38	0.11	11.25	0.00	0.00	0.00			
	Total	8.19	1.39	0.44	44.10	0.00	0.00	0.00			
Relief	District/Sub- division*	Baby Foo Liquid	od	Baby Food	d Solid	Others					
Distributed	Bajali	0.00-ml		0.00-Pkt		Tarpauli	Tarpaulin -3000.00-Pieces				
Others	Dhemaji	0.00-Q		0.00-Q							
Infrastructure Damaged - Embankment Breached	Udalguri										
Infrastructure Damaged - Embankment s Affected	Nil										
	District/Sub- division*	Numbe r	Details								
Infrastructure Damaged - Road	Barpeta	11	Barpeta - Baradi Tatikuchi to Taparbori Bazar   Baradi Taparbari   As per report received from the EE, PWRD, Barpeta Baghbar & Chenga Territorial Road Division Barpeta on 03/07/23 SPT Br. No. 1/1 in critical condition due to water hyacinth   (Long - 91.049739, Lat - 26.331426, Dept - PWD (Roads)), Howly CHC approach Road   Howly   As per report received from the EE, PWRD, Barpeta Baghbar & Chenga Territorial Road Division Barpeta on 03/07/23 Side berm and hard crust damage at several stretches   (Long - 90.977238, Lat - 26.412530, Dept - PWD (Roads)), Sarthebari - Rangia Nadir Pam MEM to Besimari Burhikharma village road SPT Br No 2/1 approaches damaged. (Lat- 26.458477, Long- 91.143478, under Sarthebari Rev Circle)   Rangia Nadir Pam MEM to Besimari Burhikharma village road   as per the report received from PWD (Road) on 04-07-2023   (Long - 91.143478, Lat - 26.458477, Dept - PWD								

	Goalpara	6	(Roads)), Nagon Sarthebari road submerged at many stretches and damaged road shoulder and hard crust also RCC bridge Approach damaged at Singra.   Nagon Sarthebari road   as per the report received from PWD (Road) on 04-07-2023   (Long - 91.169794, Lat - 26.335984, Dept - PWD (Roads)).  Belbari Nasatra Road SPT Br No 2/1 approaches damaged. (Lat- 26.352682, Long- 91. 196753, under Sarthebari Rev. Circle)   Belbari Nasatra Road   as per the report received from PWD (Road) on 04-07-2023   (Long - 91.196753, Lat - 26.352682, Dept - PWD (Roads)). Newlarbhitha to Bamundi (bamundi to Fulbari via Kuriharpam) road submerged. Road surface heavity damaged. (Lat- 26.378844, Long- 9.1181228, under Sarthebari Rev. Circle)   Newlarbhitha to Bamundi (bamundi to Fulbari via Kuriharpam) road   as per the report received from PWD (Road) on 04-07-2023   (Long - 91.181228, Lat - 26.335894, Dept - PWD (Roads)).  Singra to Bhogchara Road hard crust fully damaged. Road breached at 7 Nos stretches from 1st KM to 5th KM. (Lat- 26.355595, Long- 91.163943, Under Sarthebari Rev. Circle)   Singra to Bhogchara Road   as per the report received from PWD (Road) on 04-07-2023   (Long - 91.163943, Long- 91.1639
	Total	17	rengin of 280.00 m   (Long - 90.384387, Lat - 26.066472, Dept - PWD (Roads))
If	Total	17	
Infrastructure Damaged - Bridge	Nil		

Infrastructure Damaged - Wildlife	Nil	
	District/Sub- division*	Other Details
	Baksa	Baganpara - Culvert Approach Road Damaged   Baganpara to Thalukchi road damaged on 22/06/2023 report received on 04/07/2023.(26.636418,91.499615), Bamboo Foot Bridge   Ghoramara to jartaluk bamboo foot br washed away on 22/06/2023 report received from concerned authority on 04/07/2023.(26.581532,91.486513), Culvert Approach Road Damaged   Banduguri gerua asram road damaged on 22/06/2023 report received from concerned authority on 04/07/2023.(26.665698,91.488279)), Washed away Culverts   Khatbari khanti supa road rcc culvert washed way on 22/06/2023 report received from concerned authority on 04/07/2023.(26.668582,91.486686)), Culvert Damaged   Khatbari khanti supa road HPC culvert damaged on 22/06/2023 report received from concerned authority on 04/07/2023.(26.668925,91.490018)), Culvert Damaged   Baganpara to pakhamara road box cell culvert damaged on dated 22/06/2023 report received from concerned authority on 04/07/2023.(26.671255,91.424951))
	Chirang	Bijni - Irrigation Canal/Scheme Damaged   As reported by AEE, Bijni Sub Division (Irrigation), the D/S left side afflux bund of Bhawraguri Thaisobeel FIS damaged at from ch. 0 to 20 M at village Ashrabari. Length=20.00 mtr, Breadth=3.00 mtr, Depth=6.00 mtr. Latitude= 26.568571 Longitude=90.664911. Date of Occurrence=03-07-2023.,  Bengtal - Culvert Damaged   As reported by Executive Engineer, PWD Chirang (R&B), Kajalgaon, Hume Pipe Culvert damaged at village Salbari, @Ch-9.350km on NH-31C Kashikotra to Bengtol via Bamungaon road, damage details-Length= 8.5 m, Breadth=4 m, Depth = 3 m. Latitude=26.611685, Longitude=90.468422. Date of occurrence= 03/07/2023
	Dhemaji	Gogamukh - Bamboo Foot Bridge   Chutiakari to Milanpur via Gurathali Road; 2 (Two) nos. of Bamboo bridges are damaged and the road leading to the Bamboo bridge is also eroded of 100m length. From Ch. 520.00 m to Ch.800.00 m; Latitude: 27.339233°N Longitude: 94.365806°E, Latitude: 27.340662°N Longitude: 94.367131°E, Dated-04-07-2023
	Golaghat	Golaghat - Bridge Approach Road Damaged   Erosion of approach RCC Bridge No.1/1 on link road Singphura Torani to Sukanjan due to river Kakodonga on 03.07.2023. Lat 26.3758 Long 94.1249
Infrastructure Damaged - Others	Kokrajhar	Bhawraguri - Culvert Damaged   AS REPORTED BY AEE PWD RR, KACHUGAON ON DTD 04-07-23 DUE TO FLOOD AND INCESSANT HEAVY RAINFALL FROM 15TH JUNE TO TILL TODAY HUME PIPE CULVERT (TRIPLE OPENING) NO. 1/1 ON NH 31 C TO ISLAMPUR ROAD HAS BEEN DAMAGED AT VILLAGE- (i) ISLAMUR & (ii) CHARAIDEKA LOCATION- AT CH 230.00 M (LAT- 26.55057 LONG- 90.10323), Irrigation Canal/Scheme Damaged   AS REPORTED BY AEE KOKRAJHAR WEST SUB-DIVISION (IRRIGATION) RAMFALBIL ON DTD 3/7/23 DUE TO ONGOING FLOOD PATAKATA FIS AT VILL PATAKATA AFFLUX BUND & CANAL SYSTEM HAS BEEN DAMAGED (LAT-26.5380, 26.5351, 26.5350 LONG- 90.0832, 90.0841, 90.0849), Irrigation Canal/Scheme Damaged   AS REPORTED BY AEE KOKRAJHAR WEST SUB-DIVISION (IRRIGATION) RAMFALBIL ON DTD 3/7/23 DUE TO ONGOING FLOOD BAIRALI TABLAIJHORA FIS AT VILL BAIRALI CANAL SYSTEM HAS BEEN DAMAGED (LAT-26.5449, 26.5450, 26.5484 LONG- 90.0581, 90.0580, 90.0575), Irrigation Canal/Scheme Damaged   AS REPORTED BY AEE KOKRAJHAR WEST SUB-DIVISION (IRRIGATION) RAMFALBIL ON DTD 3/7/23 DUE TO ONGOING FLOOD MAHAMAYA FIS AT VILL NABINAGAR L/BANK, R/BANK GUIDE BUND HAS BEEN DAMAGED (LAT-26.5800 LONG- 90.0805),  Dotma - Irrigation Canal/Scheme Damaged   AS REPORTED BY ASSTT. EXE. ENG. KOKRAJHAR WEST SUB-DIVISION (IRRIGATION) RAMFALBIL RECEIVED ON 04.07.2023, CANAL SYSTEM OF LONGA FIS HAS BEEN DAMAGED,  Irrigation Canal/Scheme Damaged   AS REPORTED BY ASSTT. EXE. ENG. KOKRAJHAR WEST SUB-DIVISION (IRRIGATION) RAMFALBIL RECEIVED ON 04.07.2023, CANAL SYSTEM OF LONGA FIS HAS BEEN DAMAGED,  Irrigation Canal/Scheme Damaged   AS REPORTED BY ASSTT. EXE. ENG. KOKRAJHAR WEST SUB-DIVISION (IRRIGATION) RAMFALBIL RECEIVED ON 04.07.2023, CANAL SYSTEM OF ATHIABARI FIS HAS BEEN DAMAGED,  Gossaigaon - Culvert Approach Road Damaged   AS REPORTED BY AEE, PWD (RR) KACHUGAON SUB-DIVISION DUE TO FLOOD & INCSSANT OF HEAVY RAINFALL ON 15.06.2023 TO 04.07.2023 DAMAGED APPROACH OF RCC BOX CULVERT NO.1/2 ON DUMBAZAR TO MOTHAMBIL ROAD VIA DOLGAON HAS BEEN DAMAGED.
	Lakhimpur	Subansiri - Bridge Approach Road Damaged   As reported by the Dhakuakhana Territorial Road Division, Ghilamara the bridge approach road of RCC bridge No. 3/1 on Sonari Chapori to Nayabazar Road is damaged on 03/07/2023 (L=20M)  Harisinga - Irrigation Canal/Scheme Damaged   Due to incessant heavy rainfall for last few days embankment damaged and eroded at Dharamjuli khoiragrant village. LAT 26.78 28 LONG91.7128
	Udalguri	Scheme name: DEOSUNGA FIS. On-03-07-2023, Irrigation Canal/Scheme Damaged   Due to heavy rainfall last few days Kahibari FIS AFFLUX BUND damaged at Banseria village. LAT 36.6775 LONG:91.9139. On-03-07-2023
Erosion	District/Sub- division*	Details

		Kalgachia - Tarakandi   Ongoing erosion of river Beki at Tarakandi Village (as per report from concern
	Barpeta	LM there are 5 Nos. of houses were shifted their house to another place & 1 no. of School, viz.,
		Tarakandi ME School, Tarakandi, GPS: Lat. 26.243604, Long: 90.717474, shifting the school with in
		discussion with the School authority) reported by LM on 03.07.2023   0   (Long - 90.718932, Lat -
		26.244071)
		Gohpur - At No.2 Bikrampur area.   Mild erosion is observed at R/Bank embankment of river Sessa of
		length 30 mtr on 04/07/23   0   (Long - 93.728008, Lat - 26.962652),
		Halem - Tangia   River Chatrang -Bank erosion is occurred at Chatrang L/Bank at Tangla Village
		(Tangia Lakhipur) for a length of 250m on 04.07.2023 .   0   (Long - 9334552.000000, Lat -
	Biswanath	2655607.000000),
		<b>Biswanath</b> - 4 No. Kumalia (Forciati)   Active bank erosion at Forciati area in between Ch.4th to 5th km
		of Biswanath Panpur Dyke. Reach Length of erosion 125m. Average bank erosion width 12m (approx) as
		per WRD report on 04.07.2023   0   (Long - 93.123582, Lat - 26.685262)
		Manikpur - Nachankuri no 3   Erosion of around 60 mtr. 6(Six) nos of Kacha hut fully damaged due to
	D	erosion.date-04.07.2023   36   (Long - 90.663637, Lat - 26.458808),
	Bongaigaon	Srijangram - Santoshpur pt III   Dated 04/07/2023, Due to the ongoing erosion at Santoshpur Pt III, 2
		no.s of houses has been damaged.   8   (Long - 90.733391, Lat - 26.298364)
		Sidli - Tirimari   As reported by JE, WRD, Kajalgaon, Bank erosion on L/B of River Champamati at
	Chirang	Tirimari , Damage details- Length approx- 260m, Breadth Approx- 4.50m , Dept approx- 3.80m Date of
		occurrence- 02-07-2023   0   (Long - 90.401767, Lat - 26.501835)
		Gauripur - Boraibari Pt-IV & Boraibari Pt-V   Erosion is going on (by the river Gaurang) at village
	Dhubri	Boraibari Pt-IV & Boraibari Pt-V As per the field verification w.e.f 30/06/23 to 03/07/23 it is seen that
	Diluon	till now 1 no of family and 3 nos of shops has been affected (total area = 1Bigha-1Katha-5Lessa)   8
		(Long - 90.041443, Lat - 26.095051)
		Tengakhat - Guiakhati Village   As per information recieved from WaterResource Deptt. , Bank erosion
		caused at Sasoni Tingkhong Bund Ph-I on the L/B of river Buridehing in Guiankhati area and Length of
	Dibrugarh	Damagae-300mts as on 03.07.2023   0   (Long - 95.103971, Lat - 27.325865),
		Naharkatia - Uriamguri (Gor Chuk)   As per report recieved from AEE WR department Dibrugarh West
		as on 03-07-2023 erosion occurred at cultivated land for a length of 400m on L/B of river Buridehing   0
		(Long - 95.188763, Lat - 27.342909)
		Chamaria - Vill-Makeli   As per report AEE Boko Sub division irrigation department As reported
		earlier, flash flood occurred at Makeli FIS under Boko Sub Division (Irrigation). Now after decreasing
		the water level it is observed that the embankment of the FIS has been eroded upto a length of approx
	V	45m on dated:04/07/2023   0   (Long - 91.174398, Lat - 26.039812),
	Kamrup	<b>Hajo</b> - 1. kothalghopa 2. Notun Dihina   1. As per report submitted by water resource on 3/07/2023 an active erosion was seen on L/B of river pagladia from dusutimukh to adabari of 200m at kothalghopa. lat:
		26.361 long: 91.4706 2. Asper report submitted by water resource on 3/07/2023 an active erosion was
		seen on L/B of bhairatolajan river of 200m around 5a.m. Lat:26.318 long:91.52   0   (Long - 0.000000,
		Lat - 0.000000)
Landslide	Nil	
Urban Flood	Nil	
	1 .	*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)