

FRIMS Assam



Flood Reporting And Information Management System

	Assam Daily Flood Report as on 28-06-2023 at 4:00 PM										
Particulars	Situation as on	tion as on 28-06-2023 (in last 24 hours)									
Rivers flowing above Danger	Rivers flowing	above dan	ger level			Nil					
Level (as per CWC bulletin issued at 8 AM)	Rivers flowing	above hig	hest flood	level		Nil					
District/Sub-division	No. of Districts/Su b-divisions* Affected	Name of divisions		fected Distri	cts/Sub-	Name of Urban Flood I	Districts/Sub-	-divisions*			
Affected	12	Dhemaji,	Goalpara	swanath, Dari , Jorhat, Kam i, Sonitpur, T	rup,						
No. Of Revenue Circles Affected	20										
	District/Sub -division*	Total	Revenu	e Circle							
	Bajali	2	Sarupeta	a, Bajali							
	Barpeta	3	Chenga,	Sarthebari, I	Barpeta						
	Biswanath	1	Halem								
N 06	Darrang	1	Mangaldoi								
Name Of	Dhemaji	1	Dhemaji								
Revenue	Goalpara	1	Rongjuli								
Circles	Jorhat	2	Titabor,	Jorhat East							
Affected	Kamrup	3	North G	hy, Hajo, Ka	malpur						
	Lakhimpur	1	Nowboi	cha							
	Nalbari	3	Barbhag	g, Barkhetri, N	Valbari						
	Sonitpur	1	Charidu								
	Tamulpur	1	Tamulpi	ur							
	Total	20									
	District/Sub -division*	Total	Revenu	e Circle							
	Bajali	30	(Sarupeta 5), (Bajali 25)								
	Barpeta	75	(Chenga 15), (Sarthebari 31), (Barpeta 29)								
	Biswanath	1	(Halem 1)								
	Darrang	33	(Mangaldoi 33)								
Villages	Dhemaji	1	(Dhemaji 1)								
Affected	Goalpara	1	(Rongjuli 1)								
11110000	Jorhat	8	(Titabor 5), (Jorhat East 3)								
	Kamrup	142	(North Ghy 7), (Hajo 77), (Kamalpur 58)								
	Lakhimpur	10	`	oicha 10)							
	Nalbari	78	(Barbhag 14), (Barkhetri 54), (Nalbari 10)								
	Sonitpur	8	(Chariduar 8)								
	Tamulpur	8	(Tamul	pur 8)							
	Total 395										
Population	District/Sub -division*	Male	Femal e	Children	Total Populatio n	Population Details	Crop Area (in Hect.)	Crop Area Details			
And Crop Area	Bajali	8067	7999	1743	17809	(Sarupeta 3705), (Bajali 14104)	24.00	(Sarupeta 8.00), (Bajali 16.00)			
Affected	Barpeta	20276	18429	4261	42966	(Chenga 1750), (Sarthebari 27793), (Barpeta 13423)	194.00	(Chenga 19.00), (Sarthebari 45.00), (Barpeta 130.00)			

	Biswanath	61	59	55	175	(Halem 1	75)	0.00	(Halem 0.	00)
	Darrang	0	0	0	0	(Mangaldo	-	317.00	(Mangaldo	
	Dhemaji	0	0	0	0	(Dhemaji		2.00	(Dhemaji	
	Goalpara	0	0	0	0	(Rongjuli		4.00	(Rongjuli 4.00)	
						(Titabor 0			(Titabor 5	
	Jorhat	0	0	0	0	East 0)	,, (5011111	10.35	Jorhat East	
						(North Gh	y 4), ((North Ghy	
	Kamrup	1	1	2	4	Hajo 0), (Kamalpur	1105.23	Hajo 988.0	
						0)			Kamalpur	106.73)
	Lakhimpur	9108	8915	651	18674	(Nowboicl	na 18674)	0.00	(Nowboich	a 0.00)
						(Barbhag	922),((Barbhag 15.90), (
	Nalbari	532	287	103	922	Barkhetri	Barkhetri 0), (Barkhetri	137.50), (
						Nalbari 0)		Nalbari 46.00)		.00)
	Sonitpur	540	440	235	1215	(Chariduar 1215)		2.53	(Chariduar 2.53)	
	Tamulpur	417	383 400 1200 (Tamulpur 12		1200)					
	Total	39002	36513	7450	82965			1859.91		
	District/Sub -division*	Total	Relief C	Camp			Relief Dist	ribution Cen	tres	
	Bajali	72	0(Sarup	eta 0, Bajali	10)		72(Sarupeta	a 1, Bajali 7	71)	
Relief	Barpeta	27			pari 0, Barpe	eta 0)			i 21, Barpeta	12)
Camps /	Biswanath	1	0(Halen		· · · · · · · · · · · · · · · · · · ·	1 0 /	1(Halem 1	•	- 1 ,	1-/
Centres	Kamrup	1		Ghy 1)			0(North Gh			
Opened	Nalbari	2	0(Nalba				2(Nalbari	• • •		
· r · · · · · ·	Sonitpur	2	0(Chario	. /			2(Charidua			
	Tamulpur	1	0(Tamul				1(Tamulpu			
	Total	106	1	ipui (0)			105	. 1)		
		100	_				100		Pregnant	Person
	District/Sub	Total		G1 1 1		36.1		G1 11 1	/	with
Inmates In Relief Camps	-division*		Revenu	e Circlewise		Male	Female	Children	Lactating	Disabilit
									Mother	y
	Kamrup	4	(Hajo 0), (Kamalpur 0), (North Ghy 4)			1	1	2	0	0
	Total	4	(North Gily 4)			1	1	2	0	0
	District/Sub	-				_		<u> </u>	1 0	1 0
Human	-division*	Total	Male	Female	Children	Revenue C	Circlewise			
Lives Lost -	Goalpara	1	1	0	0	(Rongjuli	1)			
Confirmed	Total	1	1	0	0	(======================================				
		_	_	General	-					
Human	District/Sub	TD - 4 - 1	Flood	Drownin g (Non Flood)						
Lives Lost	-division*	Total	Death		Landslide					
Confirmed -										
Death Type	Goalpara	1	1	0	0					
	Total	1	1	0	0					
Human Lives Lost - Missing	Nil									
Human										
Lives Lost	Nil									
Missing -	1111									
Type	District/Sub	Total	Big	Small	Poultry					
	-division*		_		·					
	Bajali	7508	4117	2758	633					
Animals Affected	Barpeta	38605	17192	12240	9173					
	Kamrup	3850	3850	0	0	· · · · · · · · · · · · · · · · · · ·	·	<u>-</u>	·	
	Lakhimpur	2939	2279	660	0					
	Nalbari	11504	4152	7352	0					
	Sonitpur	1353	900	453	0					
	Total	65759	32490	23463	9806					
Animals										
Washed	Nil									
Away										
	District/Sub	Fully	Fully	Fully	Partially	Partially	Partially	Others	Others	Others
Houses		Kucch	•		_	_	•		Cattle	Total
Houses Damaged	-division* Tamulpur	Kucch a	Pukka	Total	Kuccha 74	Pukka 0	Total	Huts 0	Shed 0	Total

	Total	0	1	1	74	0	74	0	0	0	
Rescue	District/Sub -division*	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopte rs Deployed	Person Evacuate d By Helicopte rs	Medical Team Deploye d	
Operation	Barpeta	Fire & Emergency Services (F&ES)			1	1	0	0	0	0	
	Kamrup				0	0	0	0	0	1	
	Lakhimpur				0	0	0	0	0	4	
	Total				1	1	0	0	0	5	
	District/Sub -division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed	- Rice Bran (in Q)	
Relief	Bajali	0.00	0.00	0.00	0.00	0.00	882.62	0.00			
Distributed	Barpeta	125.08	24.00	7.18	718.00	0.00	409.20	0.00			
Distributed	Biswanath	1.88	0.35	0.00	0.00	0.00	0.00	0.00			
	Kamrup	0.10	0.02	0.00	0.60	0.00	0.00	0.00			
	Nalbari	0.00	0.00	0.00	0.00	0.00	220.00	0.00			
	Sonitpur	13.64	2.43	0.73	0.00	0.00	0.00	0.00			
	Tamulpur	19.20	3.60	1.08	108.00	0.00	0.00	0.00			
	Total	159.90	30.40	8.99	826.60	0.00	1511.82	0.00			
	District/Sub -division*	Baby Foo Liquid	od	Baby Food	l Solid	Others					
	Bajali	0.00-Q		0.00-Q							
Relief	Barpeta	0.00-Q 0.00-Q		0.00-Q 0.00-Q							
Distributed	Biswanath	0.00-Q	0.00-Q 0.00-Q								
Others	Kamrup	1.00-L		2.00-Pkt							
	Nalbari	0.00-Q			0.00-Q						
	Sonitpur	0.00-Q		0.00-Q							
	Tamulpur	0.00-Q	0.00-Q			0-0.00-Q					
	District/Sub	Numbe	Details								
Infrastructur e Damaged - Embankmen	-division* Biswanath	1	current o upstrean	of flood wate of Tinikuni	r eroded away a for a length	the Tea gard of 4.5m on R	len bund for a Bank of rive	a length of 210 er Brahmajan r	an Tinikunia om and breachd near Joregaon a	ed it at area.	
t Breached	Sonitpur	1	Report on 28/06/2023 (Long - 93.481104, Lat - 26.933649, Dept - Water Resource Deptt.) Chariduar - Amloga river embankment Amloga pathar Village 1 no embankment in Amloga pathar Village has been eroded (20m) by the river water of Amloga river DTD 28.06.2023 (Log 92.753871, Lat - 26.897990, Dept - P&RD)							mloga	
	Total	2									
Infrastructur e Damaged - Embankmen ts Affected	Nil										
	District/Sub -division*	Numbe r	Details								
Baksa 2 Jalah - Daodhara to Doomni Road on 21-06-2023 Hatijan As per Executive Engineer P.W.D Salbari (R & B) on 27-06-203 CUL.Bo 7 damagged at CH. 6850.00 M. (Long - 91.294178, Lat - 26.731009, Jalah to Rupahi road nil As per report received form Asstt Executi & B) on 27-06-2023 CUL.Bo 5/1 approaches has been damaged at C 91.170875, Lat - 26.765848, Dept - PWD (Roads))					JL.Bo 7/1 app 31009, Dept - Executive Eng ged at CH. 475	roaches has be PWD (Roads) gineer P.W.D S 50.00 M. (Lo	eeen)), Salbari (R ng -				
Infrastructur e Damaged - Road	Barpeta	22	Chenga - Suva to Jatradia NC via Bandali Barbhitha, Jatradia NC Side berm eroded & Hard damaged at several stretches. Damaged length approx. 1200.00M Received from PWRD on 28.06.2023 (Long - 91.166376, Lat - 26.257376, Dept - PWD (Roads)), Batgaon Haripur Road "Batgaon, Ganakpara, Bampara" Road submerged and Hard Crust damaged at several stretches. Damage length approx. 600.00 M Received from PWRD on 28.06.2023 (Long - 91.128604, Lat - 26.282763, Dept - PWD (Roads)), Batgaon Chutiapara Road "Batgaon, Chutiyapara, Motabari" Road submerged at several stretches. Damage length approx. 1.00 Km Received from PWRD on 28.06.2023 (Long - 91.111561, Lat - 26.290347, Dept - PWD (Roads)), Barpeta - BB road to Pakabetbari Pam 1629 No LP school (PMGSY completd- Pkg- AS-01-18) Pakabetbari Pam 1629 No LP school (PMGSY completd- Pkg- AS-01-188) submerged in stree				on ast al - -01-188) to				

Side berms damaged | (Long - 91.044303, Lat - 26.354414, Dept - PWD (Roads)), Barbala Nakkati Road SPT Br No 2/1 badly damaged | Barbala | As per report received from PWD Roads Dept on 28/06/2023 BarbalaNakkati Road SPT Br No 2/1 badly damaged | (Long -90.990320, Lat - 26.406180, Dept - PWD (Roads)), Bamunbari Kujarpith road (PMGSY completed- Pkg- AS-01-508) road | Bamunbari Kujarpith | As per report received from PWD Roads Dept on 28/06/2023 BamunbariKujarpith road (PMGSY completed- Pkg- AS-01-508) road submerged. Side berms heavily damaged | (Long - 91.066600, Lat - 26.402895, Dept - PWD (Roads)), Pohumara river at Colony Bazar SPT Br. No 1/1 | Pohumara river at Colony Bazar | As per report received from PWD Roads Dept on 28/06/2023 Pohumara river at Colony Bazar SPT Br. No 1/1 approches badly damaged | (Long - 91.064112, Lat - 26.256879, Dept - PWD (Roads)), Dangarkuchi Kaljhar road (NH-31 to Jarabari)Pkg- AS-01-493 PMGSY | Dangarkuchi Kaljhar | As per report received from PWD Roads Dept on 28/06/2023 DangarkuchiKaljhar road (NH-31 to Jarabari)Pkg- AS-01-493 PMGSY ongoing side berms damaged in streches. | (Long - 91.014338, Lat - 26.396882, Dept - PWD (Roads)), BB road to Kayakuchi Bhaktardoba PWD road via DakhinKuriha road | Kuriha | As per report received from PWD Roads Dept on 28/06/2023 BB road to KayakuchiBhaktardoba PWD road via DakhinKuriha road submergd. Side berms damaged in streches | (Long - 91.067600, Lat - -26.392230, Dept - PWD (Roads)), Jarabari to Dabaliapara road | Jarabari to Dabaliapara | As per report received from PWD Roads Dept on 28/06/2023 Jarabari to Dabaliapara road side berms badly damaged | (Long - 26.381928, Lat - 91.017327, Dept - PWD (Roads)), Deurikuhi to BetbariChariali road SPT Br No 1/1 | Deurikuchi | As per report received from PWD Roads Dept on 28/06/2023 Deurikuhi to BetbariChariali road SPT Br No 1/1 approaches badly damaged | (Long - 91.012931, Lat - 26.352187, Dept - PWD (Roads)), Dangarkuchi village road to BetbariChariali SPT Br No 1/1 | Dangarkuchi | As per report received from PWD Roads Dept on 28/06/2023 Dangarkuchi village road to BetbariChariali SPT Br No 1/1 approaches damaged | (Long - 91.012931, Lat - 26.353187, Dept - PWD (Roads)), BB road to Putlartari via Pakabetbari Pam SPT Br No 1/1 | Putlartari | As per report received from PWD Roads Dept on 28/06/2023 BB road to Putlartari via Pakabetbari Pam SPT Br No 1/1 badly damaged | (Long - 91.042564, Lat - 26.359317, Dept - PWD (Roads)), BB road to Keotpara road (PMGSY completed-Pkg- AS-01-306) road | BB Road | As per report received from PWD Roads Dept on 28/06/2023 BB road to Keotpara road (PMGSY completed-Pkg- AS-01-306) road submerged. Side berms and road surface damaged in streches | (Long -91.040022, Lat - 26.354476, Dept - PWD (Roads)), Kayakuchi Newlarbhitha Road RCC Br. No 4/1 | Kayakuchi Newlarbhita | As per report received from PWD Roads Dept on 28/06/2023 Kayakuchi Newlarbhitha Road RCC Br. No 4/1 approaches damaged | (Long - 91.094648, Lat - 26.393230, Dept - PWD (Roads)), DK road to Barbala Madrassa Road | Barbala | As per report received from PWD Roads Dept on 28/06/2023 DK road to Barbala Madrassa Road breahed at 1stKm . Side berms & hard crust damaged | (Long - 91.007298, Lat - 26.402153, Dept - PWD (Roads)), Kayakuchi Newlarbhitha road SPT Br No 6/1 | Kayakuchi Newlarbhita | As per report received from PWD Roads Dept on 28/06/2023 Kayakuchi Newlarbhitha road SPT Br No 6/1 in danger condition due to blockage of water way due to deposition of Water hyacinth | (Long - 91.094640, Lat - 26.393000, Dept - PWD (Roads)), Ata Bhowkamari to Madhya Bhowkamari via Kayakuchi Medical | Ata Bhakuamari | As per report received from PWD Roads Dept on 28/06/2023 Ata Bhowkamari to Madhya Bhowkamari via Kayakuchi Medical completely submerged | (Long - 91.069166, Lat - 26.402668, Dept - PWD BB road (At Lakhi Bazar) to Dakhin Khablarbhitha road | Khablarbhita | As per report received from PWD Roads Dept on 28/06/2023 BB road (At Lakhi Bazar) to Dakhin Khablarbhitha road side berms dmaged | (Long - 91.040019, Lat - 26.375522, Dept - PWD (Roads)), Kayakuchi Village road | Kayakuchi Village Road | As per report received from PWD Roads Dept on 28/06/2023 Kayakuchi Village road Side berms damaged in strehces | (Long - 0.000000, Lat -0.000000, Dept - PWD (Roads)), Uttar Maricha Tiniali to Pahumara River road | Maricha | As per report received from PWD Roads Dept on 28/06/2023 Uttar Maricha Tiniali to Pahumara River road submerged, ICBP surface damaged | (Long - 91.073630, Lat - 26.386619, Dept - PWD (Roads)), BB road to Fulorguri Bamunbari road | Fulorguri | As per report received from PWD Roads Dept on 28/06/2023 BB road to Fulorguri Bamunbari road submerged. | (Long - 91.068795, Lat -26.412334, Dept - PWD (Roads)) Agamoni - SIDE BERM & SIDE SLOPES DAMAGED ON ROAD FROM ROYPARA TO SILKURIRPAR ROAD AT 1ST KM (.) LONGITUTE: 89.762382 & LATITUDE: 26.201615 (.) (Dated 12-06-2023 to 26-06-2023) | LONGITUTE : 89.762382 & LATITUDE : 26.201615 (.) | | (Long - 89.762382, Lat - 26.201615, Dept - PWD (Roads)), Dhubri 4 SIDE BERM DAMAGED ON ASS ROAD AMTOLA TO BORO HARIRDHAM RANPAGLIRHAT ROAD AT 1ST KM (.) (.) LONGITUTE: 89.759262 & LATITUDE: 26.19316 (.)(Dated 12-06-2023 to 26-06-2023) | LONGITUTE : 89.759262 & LATITUDE : 26.19316 (.) | | (Long - 89.759262, Lat - 26.193160, Dept - PWD (Roads)),

CIDE DEDICE ANA CED ON DANDA CLIDATAD CHARACAL DOAD AT 3DD WALLY
SIDE BERM DAMAGED ON RANPAGLI BAZAR STARASAL ROAD AT 3RD KM (.)(.) LONGITUTE: 89.731494 & LATITUDE: 26.191224 (.)(Dated 12-06-2023 to 26-06-2023) LONGITUTE: 89.731494 & LATITUDE: 26.191224 (.) (Long - 89.731494, Lat - 26.191224,
Dept - PWD (Roads)), SIDE BERM & SIDE SLOPES DAMAGED ON ROAD FROM ASS ROAD TO KADAMTOLA HARIRDHAM ROAD AT 1ST KM (.)LONGITUTE: 89.759262 & LATITUDE: 26.19316
(Dated 12-06-2023 to 26-06-2023) LONGITUTE : 89.759262 & LATITUDE : 26.19316 (Long - 89.759262, Lat - 26.193160, Dept - PWD (Roads))
Lakhipur - A.T. Road (Old) to Medhipara Kaltibari Dhara Near Medhipara As per report of PWD road department, Due to incessant rainfall for last 7 days A.T. Road (Old) to Medhipara Kaltibari Dhara at 2nd KM, Affected length sidebum & road surface damage from 22.06.2023 to
26.06.2023 (Long - 90.337176, Lat - 26.018117, Dept - PWD (Roads)), Rongjuli - RANGJULI TO SIMLITOLA ROAD OPPOSITE AGVB BANK, RANGJULI As per reported by PWD(RR), Dudhnoi & Goalpara East TR Division via whatsapp message on 28/06/2023, rangjuli to simlitola road partially submerged due to water overflowing cause by flash flood like situation due to indecent rainfall over the Hills of Meghalaya. Submerged length 1. Ch
20.00 m to 120.00 m Avg. Depth. 0.50 m. 2. Ch. 400.00 m to 750.00 m. Avg. Depth 0.60 m. (Long - 90.935896, Lat - 25.968213, Dept - PWD (Roads)), NH 17 to BELPAR ROAD NEAR RANGJULI TD BLOCK OFFICE As per reported by
PWD(RR), Dudhnoi & Goalpara East TR Division via whatsapp message on 28/06/2023, NH 17 to Belpara road partially submerged due to water overflowing cause by flash flood like situation due to indecent rainfall over the Hills of Meghalaya. Submerged length ch.00 m to 500.00 m avg depth 0.40 m (Long - 90.940787, Lat - 25.968469, Dept - PWD (Roads)),
Balijana - Junkaipara to Rakhaldubi Road JUNKAIPARA As per PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur reported on 27/06/2023 via Whatsapp, road from Junkaipara to Rakhaldubi Road was partially submerged, lenght: 60 Mtr & Depth: 30 cm Lat: 26.102977 Long: 90.434762. Traffic disrupted as on 28/06/2023 (Long - 90.434762, Lat - 26.102977, Dept - PWD (Roads)),
Titapara village to Shivnath Road Titapara Village As per PWRD, Goalpara West & Jaleswar Territorial Road Division, Lakhipur reported on 27/06/2023 via Whatsapp, road from Titapara village to Shivnath Road was partially submerged, lenght: 200 Mtr & Depth: 40 cm Lat: 26.061418 Long: 90.373778 Traffic disrupted as on 28/06/2023 (Long - 90.373778, Lat - 26.061418, Dept - PWD (Roads))
Jorhat West - Malowali dhekorgora road . dated : 27th June 2023 Malowpam Seepage resulting erosion of Road Embankment has taken place due rise in water level of Bhogdoi river at 10th Km of Koiborta Gaon to Malow ali (Dhekorgorah to Solmora Road) near Solmora. (Long - 94.104212, Lat - 26.785235, Dept - PWD (Roads))
Karimganj - Shyamaprasadpur road Near Polytechnic due to incessant heavy rain from last few days the above road is damaged (road surface is badly damaged)at CH 0.00M to 3000.00M. The report was submitted by Asst. Executive Eng., Karimganj North Territorial Division. on 20/06/2023 (Long - 92.323194, Lat - 24.842248, Dept - PWD (Roads)), Longai Chandkhani road Longai due to incessant heavy rain from last few days the above road is
damaged (road surface is badly damaged)at CH 0.00M to 2000.00M. The report was submitted by Asst. Executive Eng., Karimganj North Territorial Division. on 20/06/2023 (Long - 92.336700, Lat - 24.807926, Dept - PWD (Roads)), F-N Raod to Krishnanagar Pt I Krishnanagar due to incessant heavy rain from last few days the
above road is damaged (side berm & hard crust is damaged & earthen road is washed away)at CH 0.00M to 250.00M. The report was submitted by Asst. Executive Eng., Karimganj North Territorial Division. on 20/06/2023 (Long - 92.329910, Lat - 24.775601, Dept - PWD (Roads)), Laxmi charan road Laxmi charan road due to incessant heavy rain from last few days the above road is damaged (sudden depression at some stretches & hard crust is damage)at CH 2800.00M to 2900.00M. The report was submitted by Asst. Executive Eng., Karimganj North Territorial Division. on 20/06/2023 (Long - 92.345352, Lat - 24.871928, Dept - PWD (Roads))
Banekuchi - On 23/06/2023 at 8 am Sahpur Harbhanga Road to Mora Pagladia submerged surface damaged report from Departmentrep Makrapar (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), On 23/06/2023 at 8.00 am Sandheli Nilakantha Mandir to Barpit Road submerged and damaged report from Department Makrapar (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
On 22/06/2023 at 8am Makrapar to Barpit road submerged and damaged report from Department Barpit (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), On 24/06/2023 at 7 am Kharsitha to Madhupur Road submerged and damaged report from Department Madhupur (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
Paschim Nalbari - Gadira SC Supa road Gadira Eroded due to rain water. Information received from PWD (R) Department via WT message on 27/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
Purni Barpit Road. Purni Temporary restoration of flood damaged. Information received from PWD (R) Department via WT message on 27/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Kharsitha to Madhupur road Kharsitha Temporary restoration of flood damaged. Information

	1	received from DWD (D) Department via WT massage on 27/04/2022 L(Long. 0.000000 Lot								
		received from PWD (R) Department via WT message on 27/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))								
	Total	45								
Infrastructur										
e Damaged -	Nil									
Bridge Infrastructur										
e Damaged -	Nil									
Wildlife										
	District/Sub -division*	Other Details								
	-division	Bajali - Culvert Damaged HPC damaged of a culvert on Kochdiga Maguri to pub Helana road.Lat 26.456145								
		Long 91.223573. This report is received from Executive Engineer, PWD Bhawanipur, Patacharkuchi &								
	Bajali	Sarukhetri Territorial Road Division, Pathsala on 27/06/2023, Fisheries/Pond Renovation cum expansion of Community Pond under Amrit Sarovar Scheme at Pachim								
		Kathalmuri village.Lat 26.622075 Long 91.148838Thios report is received from BDO,Bajali on 27/06/2023								
	Baksa	Baska - Road Breaches Dhanbil to Sirisbari (Chaibari) Road breached at village Chaibari. Date: 27/06/2023								
	Daksa	Coordinate: 26.640949, 91.390948 Powerto Public Health Engineering (PHE) As not received from Acet Evecutive Engineer (PHE) Remote Public Health Engineering (PHE) Remote Public Health Engineerin								
		Barpeta - Public Health Engineering (PHE) As per received from Asst Executive Engineer, (PHE), Barpeta Sub Division, Barpeta on 27/06/2023 4 nos of HTW are repaired at Jibanlata High School, Barpeta,								
	Barpeta	Public Health Engineering (PHE) As per received from Asst Executive Engineer, (PHE), Barpeta Sub								
		Division, Barpeta on 27/06/2023 1 nos of HTW are repaired at 3 No. Dakhin Hati LPS, Barpeta, Barpeta								
	Biswanath	Gohpur - Power Dept. Poles 4 Nos of 8.5 PSC pole is uprooted by erosion of Solengi River Bank on 27/06/23								
		Dudhnoi - Irrigation Canal/Scheme Damaged 2m of right side earthen canal embankment of Garojaan Dong								
	Goalpara	Bundh damaged at chainage 194 M from headwork at Rowmari Pt. II on 28/06/2023, Lat. 25.942953 Long.								
		90.908503								
	Jorhat	Titabor - Culvert Approach Road Damaged Dtd: 28/06/2023 Location-BurukBaruah Gaon Na-Ali Dhekiajuli Titabar Length-5Ft. Approx. (Lat: 26.674507 Long:94.19987, Source: P&RD)								
Infrastructur	Vommun	Boko - Irrigation Canal/Scheme Damaged Canals of Singua FIS has been submerged. Reported by AEE,								
e Damaged -	Kamrup	Irrigation, Boko Sub-Division. Date- 27/06/2023. Co-ordinates- 25.948124, 91.106829.								
Others	Nalbari	Tihu - Anganwadi Centres Affected As per CDPO,ICDS Project,Tihu on 28/06/2023 ,total 17 nos AWC partially damaged in recent flood .,								
		Elementary Schools Damaged As per BEEO, Pub Nalbari Block on 27/06/2023, tatal 4 nos LPS and 2 No								
		MES partially damaged on recent flood .,								
		Secondary Schools Damaged As per BEEO, Pub Nalbari Blook on 27/06/2023, total 1 no High School								
		partially damaged on recent flood. South Salmara - Fisheries/Pond As per report received from BDO, South Salmara on 26.06.23 Amrit								
	South Salmara	Sarobor scheme at Pondit para has been damaged due to heavy rainfall.(Latitude- 25.914228, Longitude-								
		90.018757),								
		Fisheries/Pond As per report received from BDO, South Salmara on 26.06.23 Amrit Sarobor scheme at seboltari has been damaged due to heavy rainfall.(Latitude- 25.899675, Longitude-90.025799),								
		Fisheries/Pond As per report received from BDO, South Salmara on 26.06.23 Amrit Sarobor scheme at								
		Baladoba has been damaged due to heavy rainfall.(Latitude- 25.89422, Longitude-90.019815),								
		Fisheries/Pond As per report received from BDO, South Salmara on 26.06.23 Amrit Sarobor scheme at Katdanga Satdobi Pt-II (1 of2)has been damaged due to heavy rainfall.(Latitude- 25.834803, Longitude-								
		89.967444),								
		Fisheries/Pond As per report received from BDO, South Salmara on 26.06.23 Amrit Sarobor scheme at								
		Katdanga Satdobi Pt-II (2 of2)has been damaged due to heavy rainfall.(Latitude- 25.833601, Longitude- 89.968219)								
		Udalguri - Irrigation Canal/Scheme Damaged Breaching of protection of canal embankment at Bhelapara								
	Udalguri	about 12m with the provision of Hume pipe at ch 14500 M of B1M canal on 26-06-2023 of Dhanisiri								
	District/Sub	Irrigation Project (Long-92.198958, Lat-26.732108)								
	-division*	Details								
	Baksa	Baganpara - Jartaluk As per SDO WR department the erosion took place at Jartaluk approx 400 meter on								
		R/B embankment of river Pagladia cause breach like situation on 23/06/2023 .The report received from concerned authority on 27/06/2023. 500 (Long - 91.499407, Lat - 26.593903),								
		Baska - Dihira (Dhansripur) Erosion at the bank of rivulet Sukia Boga near Dihira LP School (B) at village								
		Dihira. Date: 27/06/2023 0 (Long - 26.741937, Lat - 91.341354),								
Erosion		Jalah - 1. Pub Khagrabari, Jyoti Nagar, 2.Pokalagi, 3. Samuaghati 1. Msg received from Water Resources division Baksa on 28-06-2023 date of incident 28-06-2023 approaches 700.00m Kaldia River, Long-								
		91.233283, Lat-26.637323 2. Msg received from Water Resources division Baksa on 28-06-2023 date of								
		incident 28-06-2023 Pahumara River approaches 800.00 m Long-91.068774, Lat- 26.657606. 3. Msg received								
		from Water Resources division Baksa on 28-06-2023 date of incident 28-06-2023 Digjiri River approaches								
		200.00 m Long-0, Lat- 0. 0 (Long - 0.000000, Lat - 0.000000) Majuli - Kartik Chapori Erosion occurred on 27th June, 2023 and 11 nos. of families have been shifted to a								
	Majuli	nearby safe place. Approximately 3 Bigha of land area has been eroded. 40 (Long - 94.154450, Lat -								

Landslide	District/Sub -division*	Details
	Tinsukia	Doomdooma - Hatighuli A fresh River Bank Erosion is being observed at Hatighuli on the left bank of river Brahmaputra since 26/06/2023 till 28/06/2023. As per information received from WR department official. The affected stretch is about 200 m in length. 0 (Long - 95.537916, Lat - 27.755222)
	Tamulpur	Goreswar - 1. Village: Bihapara, 2. Lahapara (Paschim Suba), 3. Barghuli (Mowamari Suba) As per report of EE, Tamulpur WR Division received on 27/06/2023, erosion occured on 3 (Three) points namely- 1. L/B of River Borolia, at village- Bihapara approx length of erosion 200m. Coordinates Lat- 26.471046 Lon-91.608552 2. L/B of River Borolia, at village- Lahapara (Paschim Lahapara) approx length of erosion 200m. Coordinates- Lat- 26.487085, Lon- 91.61583 3. L/B of River Borolia, at village- Barghuli (Mowamari Suba) approx length of erosion 350m Coordinates- Lat- 26.3101 Lon- 91.3717 0 (Long - 91.608552, Lat - 26.471046)
	South Salmara	South Salmara - Salmara Pt-II As per report received from BDO, South Salmara and field visit by Field Officer, DM 2 nos Platform at South Salmara Pt-II has been damaged and eroded approx. 50 % due to erosion by the river Zinjiram. as on 26.06.23 area approx. length 25 m and breadth 15 m. 0 (Long - 90.017900, Lat - 25.891700)
	Sonitpur	Thelamara - Village- Baligaon Bongaligaon Date-28/06/2023, As reported by Tezpur Water Resource Tezpur Division on 28/06/2023 Bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri,Length = 200.00m, Latitude : 26.736022, Longitude: 92.558699 0 (Long - 92.558699, Lat - 26.736022), Tezpur - Kholaguti Kachari Dated: 28/06/2023. Erosion is observed on the R/B of Dipota river at Kholaguti Kachari village near Burhadangoria Than under Haleswar Mouza. Length: 15 ft (approx) 0 (Long - 92.725833, Lat - 26.696110)
	Nalbari	26.843128) Barkhetri - Bangnaputa, Kalarchar River Bank erosion of Brahmaputra occurring, 18 Nos of families affected due to erosion. dated: 28/06/2023 70 (Long - 0.000000, Lat - 0.000000), Nalbari - erosion at Goroimara due to pagaldia river R/B and Katara L/B at pagaldia river as per the report received from WR dept erosion takes place on 27.06.2023 0 (Long - 0.000000, Lat - 0.000000)