

## **FRIMS Assam**



## Flood Reporting And Information Management System

			Assam Daily Flood Report as on 2	20-06-2023 at 4:00 PM			
Particulars	Situation as on	20-06-202	3 (in last 24 hours)				
Rivers flowing above Danger Level (as	Rivers flowing	Nil					
per CWC bulletin issued at 8 AM)	Rivers flowing	; above higl	nest flood level		Nil		
District/Sub	No. of Districts/Su b-divisions* Affected	Name of divisions	Flood Affected Districts/Sub-	Name of Urban Flood Districts/Su	b-divisions*		
-division Affected	19	Darrang, Golaghat	arpeta, Biswanath, Chirang, Dhemaji, Dhubri, Dibrugarh, , Hojai, Kokrajhar, Lakhimpur, Nalbari, Sonitpur, Tamulpur,	Darrang, Jorhat, Kamrup (M), Kokra	ijhar, Nalbari		
No. Of Revenue Circles Affected	38						
	District/Sub -division*	Total	Revenue Circle				
	Baksa	1	Baska				
	Barpeta	1	Barpeta				
	Biswanath	2	Gohpur, Halem				
	Chirang	1	Bijni				
	Darrang	4	Patharighat, Mangaldoi, Sipajhar, Dalgaon				
	Dhemaji	1	Dhemaji				
	Dhubri	1	Bilasipara				
Name Of	Dibrugarh	2	Dibrugarh West, Chabua				
Revenue	Golaghat	1	Bokakhat				
Circles	Hojai	2	Doboka, Hojai				
Affected	Jorhat	2	Jorhat East, Jorhat West				
	Kamrup (M)	1	Dispur				
	Kokrajhar	5	Dotma, Bhawraguri, Bagribari, Gossaigaon, Kokrajhar				
	Lakhimpur	2	Narayanpur, Nowboicha				
	Nagaon	2	Kampur, Raha				
	Nalbari	5	Barbhag, Ghograpar, Tihu, Nalbari, Banekuchi				
	Sonitpur	1	Dhekiajuli				
	Tamulpur	1	Goreswar				
	Udalguri	3	Mazbat, Kalaigaon, Harisinga				
	Total	38					
	District/Sub -division*	Total	Revenue Circle				
	Baksa	2	( Baska   2 )				
	Barpeta	1	(Barpeta   1)				
	Biswanath	22	( Gohpur   3 ), ( Halem   19 )				
	Chirang	18	( Bijni   18 )				
Villages	Darrang	160		55), (Sipajhar   74), (Dalgaon   15)			
Affected	Dhemaji	2	(Dhemaji   2)				
	Dhubri	18	( Bilasipara   18 )				
	Dibrugarh	7	( Dibrugarh West   6 ), ( Chabua	1)			
	Golaghat	17	( Bokakhat   17 )				
	Hojai	13	( Doboka   6 ), ( Hojai   7 )				
	Kokrajhar	105		(Bagribari   19), (Gossaigaon   50),	(Kokrajhar   2)		
	Lakhimpur	19	( Narayanpur   6 ), ( Nowboicha	13)			

	Nagaon	31		( Kampur   10 ), ( Raha   21 ) ( Barbhag   33 ), ( Ghograpar   34 ), ( Tihu   10 ), ( Nalbari   14 ), ( Banekuchi   3 )							
	Nalbari	94	1		hograpar   34	), ( Tihu   10	), ( Nalbari   1	14 ), ( Banekuc	chi   3 )		
	Sonitpur Tamulpur	9	( Dhekia		amulpur   2 )						
	Udalguri	4	1		aigaon   1 ), ( ]	Harisinga   2	)				
	Total	523	( I.III E G	·   1 //, ( 12m2			<u>/</u>				
	District/Sub -division*	Male	Femal e	Childre n	Total Populatio n	Population	Details	Crop Area (in Hect.)	Crop Area	Details	
	Baksa	27	33	12	72	( Baska   72		0.00	( Baska   0.0	0)	
	Barpeta	45	32	28	105	(Barpeta   1		0.00	( Barpeta   0.00 )		
	Biswanath	445	390	247	1082	( Gohpur   0 ), ( Halem   1082 )		22.50	( Gohpur   7.00 ), ( Halem   15.50 )		
	Chirang	0	0	0	0	( Bijni   0 )		30.10	( Bijni   30.1		
	Darrang	370	389	433	1192	( Patharigha Mangaldoi Sipajhar   0 Dalgaon   0	994), ( ), (	2968.14	( Patharigha ( Mangaldoi ( Sipajhar   1 Dalgaon   20	751.40   457.00 ),	
	Dhemaji	0	0	0	0	( Dhemaji	0)	7.00	(Dhemaji   7	7.00)	
	Dhubri	0	0	0	0	( Bilasipara	. [0]	37.50	( Bilasipara		
	Dibrugarh	1567	1240	1050	3857	( Dibrugarh ( Chabua   3		185.19	( Dibrugarh 54.00 ), ( Ch	•	
	Golaghat	0	0	0	0	( Bokakhat	0)	200.00	( Bokakhat	200.00)	
Population And Crop	Hojai	0	0	0	0	( Hojai   0 ) 0 )	, ( Doboka	192.13	( Hojai   128 Doboka   64	, , ,	
Area Affected	Kokrajhar	1168	996	583	2747	( Kokrajhar   167 ), ( Dotma   2580 ), ( Bhawraguri   0 ), ( Bagribari   0 ), ( Gossaigaon   0 )		326.64	(Kokrajhar   159.93), (Dotma   0.00), ( Bhawraguri   59.36), ( Bagribari   32.86), ( Gossaigaon   74.49)		
	Lakhimpur	10562	10684	815	22061	( Narayanpı Nowboicha	ur   0 ), (	0.00	( Narayanpu Nowboicha	r   0.00 ),	
	Nagaon	0	0	0	0	( Kampur   0 ), ( Raha   0 )		1598.58	( Kampur   106.00 ), ( Raha   1492.58 )		
	Nalbari	470	492	162	1124	(Barbhag   0 ), ( Ghograpar   0 ), ( Nalbari   0 ), ( Tihu   862 ), ( Banekuchi		255.50	(Barbhag   3 Ghograpar   Nalbari   46. Tihu   60.00 Banekuchi	66.50), ( 00), ( ), (	
	Sonitpur	29	23	13	65	262 ) ( Dhekiajuli   65 )		0.00	( Dhekiajuli   0.00 )		
						( Goreswar			( Goreswar   0.00 ), (		
	Tamulpur	420	400	194	1014	Tamulpur	0)	0.00	Tamulpur   (	0.00)	
	Udalguri	367	294	109	770	( Mazbat   25 ), ( Kalaigaon   386 ), ( Harisinga   359 )		19.50	( Mazbat   0.00 ), ( Kalaigaon   19.50 ), ( Harisinga   0.00 )		
	Total	15470	14973	3646	34089		•	5842.78	11a15ingu   0.00 )		
D 1' 6	District/Sub -division*	Total	Relief C	amp			Relief Dist	tribution Centres			
Relief	Biswanath	6	0(Halen	1   0)			6(Halem   6)				
Camps / Centres	Kokrajhar	3	1(Dotma	a   1, Kokraj	har   0)		2(Dotma   0, Kokrajhar   2)				
Opened	Lakhimpur	14			owboicha   0)		14(Narayanpur   6, Nowboicha   8)				
- F	Udalguri	2		at   0, Kalaig	gaon   0)			1, Kalaigaon	1)		
	Total	25	1				24				
Inmates In	District/Sub -division*	Total	Revenue Circlewise			Male	Female	Children	Pregnant / Lactating Mother	Person with Disabil y	
Relief Camps	Kokrajhar	56	(Gossaig	(Bhawraguri   0), (Bagribari   0), (Gossaigaon   0), (Kokrajhar   15 0), (Dotma   56)		15	21	20	0	0	
	Total	56				15	21	20	0	0	
Human Lives Lost - Confirmed	Nil										
Human Lives Lost	Nil										

	ı									
Confirmed -										
Death Type										
Human	2.711									
Lives Lost -	Nil									
Missing										
Human Lives Lost										
Missing -	Nil									
Type										
Турс	District/Sub									
	-division*	Total	Big	Small	Poultry					
	Darrang	8784	4777	3427	580					
	Dibrugarh	5068	4118	950	0					
Animals	Lakhimpur	14699	10062	4637	0					
Affected	Nalbari	22491	3370	3261	15860					
	Tamulpur	1211	797	414	0					
	Udalguri	23	5	6	12					
	Total	52276	23129	12695	16452					
Animals Washed	Nil									
Away										
Houses Damaged	Nil									
Damageu									Person	
						Person	Animal	Helicopter	Evacuate	Medical
	District/Sub	Agency			Boats Deployed	Evacuate	Evacuate	S	d By	Team
	-division*					d By	d By	Deployed	Helicopte	Deploye
Rescue						Boats	Boats		rs	d
Operation	Biswanath				0	0	0	0	0	4
	Darrang				0	0	0	0	0	2
	Kokrajhar				0	0	0	0	0	2
	Lakhimpur				0	0	0	0	0	3
	Total				0	0	0	0	0	11
						Cattle	Cattle			
	District/Sub	Rice	Dal	Salt (in	M. Oil (in	Feed -	Feed -	Cottle Food Dies Busy (in O)		. 0)
	-division* (in Q)					C		Cattle Feed - Rice Bran (in Q)		
1	-division*	(in Q)	(in Q)	<b>Q</b> )	L)	Green	Wheat	Cattle Feed	- Rice Brail (	in Q)
Paliof	-division*	(in Q)	(in Q)	Q)	L)	Fooder	Bran (in	Cattle Feed	- Kice Draii ()	<b> Q</b> )
Relief					ŕ	Fooder (in Q)	Bran (in Q)		- Kice Draii (i	<b>(</b> )
Relief Distributed	Biswanath	17.99	3.42	0.00	0.00	Fooder (in Q) 0.00	Bran (in Q) 434.50	0.00	- Rice Draii (i	<b> 4</b> )
	Biswanath Kokrajhar	17.99 1.06	3.42 0.44	0.00	0.00 13.26	Fooder (in Q) 0.00 0.00	Bran (in Q) 434.50 0.00	0.00	- Kice Draii ()	<b> Q</b> )
	Biswanath Kokrajhar Lakhimpur	17.99 1.06 0.00	3.42 0.44 0.00	0.00	0.00 13.26 0.00	Fooder (in Q) 0.00	Bran (in Q) 434.50	0.00	- Kice Draii ()	<b> (</b> 2)
	Biswanath Kokrajhar	17.99 1.06 0.00 6.94	3.42 0.44 0.00 1.24	0.00 0.13 0.00 0.37	0.00 13.26 0.00 37.25	Fooder (in Q) 0.00 0.00 0.00	Bran (in Q) 434.50 0.00 0.00 0.00	0.00 0.00 1329.25 0.00	- Rice Draii ()	<b> Q</b> )
	Biswanath Kokrajhar Lakhimpur Udalguri	17.99 1.06 0.00 6.94 25.99	3.42 0.44 0.00 1.24 <b>5.10</b>	0.00 0.13 0.00 0.37 <b>0.50</b>	0.00 13.26 0.00 37.25 <b>50.51</b>	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00	Bran (in Q) 434.50 0.00 0.00	0.00 0.00 1329.25	- Rice Braii (i	<b> (</b> )
	Biswanath Kokrajhar Lakhimpur Udalguri Total	17.99 1.06 0.00 6.94	3.42 0.44 0.00 1.24 <b>5.10</b>	0.00 0.13 0.00 0.37	0.00 13.26 0.00 37.25 <b>50.51</b>	Fooder (in Q)  0.00  0.00  0.00  0.00  0.00	Bran (in Q) 434.50 0.00 0.00 0.00	0.00 0.00 1329.25 0.00	- Rice Draii (i	
	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub	17.99 1.06 0.00 6.94 25.99 Baby Foo	3.42 0.44 0.00 1.24 <b>5.10</b>	0.00 0.13 0.00 0.37 <b>0.50</b>	0.00 13.26 0.00 37.25 <b>50.51</b>	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 0.00	Bran (in Q) 434.50 0.00 0.00 0.00	0.00 0.00 1329.25 0.00	- Rice Draii (i	
Distributed	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt,	3.42 0.44 0.00 1.24 5.10	0.00 0.13 0.00 0.37 <b>0.50</b> <b>Baby Foo</b> 0.00-Q 0.00-Pkt,	0.00 13.26 0.00 37.25 50.51	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 Others  CANDLE-2 Pkt	Bran (in Q) 434.50 0.00 0.00 0.00 434.50	0.00 0.00 1329.25 0.00 1329.25	00-Pkt; M. CO	
Distributed  Relief Distributed	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt,	3.42 0.44 0.00 1.24 5.10 0.00-Q	0.00 0.13 0.00 0.37 <b>0.50</b> <b>Baby Foo</b> 0.00-Q 0.00-Pkt,	0.00 13.26 0.00 37.25 50.51 od Solid	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 Others  CANDLE-2 Pkt	Bran (in Q) 434.50 0.00 0.00 0.00 434.50	0.00 0.00 1329.25 0.00 1329.25	00-Pkt; M. CO	
Distributed  Relief Distributed	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q	3.42 0.44 0.00 1.24 5.10 0.00-Q	0.00 0.13 0.00 0.37 <b>0.50</b> <b>Baby Foo</b> 0.00-Q 0.00-Pkt,	0.00 13.26 0.00 37.25 50.51 od Solid	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 Others  CANDLE-2 Pkt	Bran (in Q) 434.50 0.00 0.00 0.00 434.50	0.00 0.00 1329.25 0.00 1329.25	00-Pkt; M. CO	
Relief Distributed Others	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt,	3.42 0.44 0.00 1.24 5.10 od 0.00-Q 6.00-Pkt Details	0.00 0.13 0.00 0.37 <b>0.50</b> <b>Baby Foo</b> 0.00-Q 0.00-Pkt, 0	0.00 13.26 0.00 37.25 <b>50.51</b> <b>cd Solid</b> 0.00-Q	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 Others  CANDLE-2 Pkt Candle-705	Bran (in Q) 434.50 0.00 0.00 0.00 434.50  2.00-Pkt; MA	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0	00-Pkt; M. CO	IIL-2.00-
Relief Distributed Others	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q Numbe	3.42 0.44 0.00 1.24 5.10 od 0.00-Q 6.00-Pkt Details Harisin	0.00 0.13 0.00 0.37 0.50 Baby Food 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10	0.00 13.26 0.00 37.25 50.51 od Solid 0.00-Q	Fooder (in Q) 0.00 0.00 0.00 0.00 0.00 Others  CANDLE-Candle-705	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0	00-Pkt; M. CO )-Pieces er embankmen	IIL-2.00-
Relief Distributed Others  Infrastructur e Damaged -	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q Numbe	3.42 0.44 0.00 1.24 5.10 od 0.00-Q 6.00-Pkt Details Harising damaged	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal	0.00 13.26 0.00 37.25 50.51 od Solid 0.00-Q	Candle-705	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  mabi   Newly of ferent places.	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0 Expaulin -291.00 constructed riv On 20 June 20	00-Pkt; M. CO 0-Pieces er embankmen 023. APPROX	IL-2.00- at is IMATE
Relief Distributed Others  Infrastructur e Damaged - Embankme	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q Numbe	3.42 0.44 0.00 1.24 5.10 0.00-Q 6.00-Pkt Details Harising damaged DAMAG	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal due to ove GE 50 meter	0.00 13.26 0.00 37.25 50.51 od Solid 0.00-Q	Candle-705	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  mabi   Newly of ferent places.	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0 Expaulin -291.00 constructed riv On 20 June 20	00-Pkt; M. CO )-Pieces er embankmen	IL-2.00- at is IMATE
Relief Distributed Others  Infrastructur e Damaged -	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q Numbe	3.42 0.44 0.00 1.24 5.10 0.00-Q 6.00-Pkt Details Harising damaged DAMAG	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal	0.00 13.26 0.00 37.25 50.51 od Solid 0.00-Q	Candle-705	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  mabi   Newly of ferent places.	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0 Expaulin -291.00 constructed riv On 20 June 20	00-Pkt; M. CO 0-Pieces er embankmen 023. APPROX	IL-2.00- at is IMATE
Relief Distributed Others  Infrastructur e Damaged - Embankme	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q 1.000-Q 1.0	3.42 0.44 0.00 1.24 5.10 0.00-Q 6.00-Pkt Details Harising damaged DAMAG Resource	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal due to ove GE 50 meter	0.00 13.26 0.00 37.25 50.51 od Solid 0.00-Q	Candle-705	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  mabi   Newly of ferent places.	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0 Expaulin -291.00 constructed riv On 20 June 20	00-Pkt; M. CO 0-Pieces er embankmen 023. APPROX	IL-2.00- at is IMATE
Relief Distributed Others  Infrastructur e Damaged - Embankme	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*  Udalguri Total	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q Number	3.42 0.44 0.00 1.24 5.10 0.00-Q 6.00-Pkt Details Harising damaged DAMAG	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal due to ove GE 50 meter	0.00 13.26 0.00 37.25 50.51 od Solid 0.00-Q	Candle-705	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  mabi   Newly of ferent places.	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0 Expaulin -291.00 constructed riv On 20 June 20	00-Pkt; M. CO 0-Pieces er embankmen 023. APPROX	IL-2.00- at is IMATE
Relief Distributed Others  Infrastructur e Damaged - Embankme nt Breached	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*  Udalguri  Total District/Sub -division*	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q 1 Numbe r  1 Numbe r	3.42 0.44 0.00 1.24 5.10 od  0.00-Q  6.00-Pkt  Details  Harisin damaged DAMAG Resourc	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal due to ove GE 50 meter e Deptt.)	0.00 13.26 0.00 37.25 50.51 d Solid  0.00-Q 6.00-Pkt habi embankn rflow of river	Fooder (in Q) 0.00 0.00 0.00 0.00 Others  CANDLE-Text Pkt Candle-705  ment   Dahalal Suklai on diff and 25 meters	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  nabi   Newly of ferent places.    (Long - 91	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0 Expaulin -291.00 constructed riv On 20 June 20 .758400, Lat -	00-Pkt; M. CO 0-Pieces er embankmen 023. APPROX	IL-2.00-  It is  IMATE  ept - Water
Relief Distributed Others  Infrastructur e Damaged - Embankme nt Breached	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*  Udalguri District/Sub -division*	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q 1 Numbe 1	3.42 0.44 0.00 1.24 5.10 od  0.00-Q  6.00-Pkt  Details  Harisin damaged DAMAG Resourd  Details  Gohpur mtr on 2	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal due to ove GE 50 meter e Deptt.)	0.00 13.26 0.00 37.25 50.51 0d Solid 0.00-Q 6.00-Pkt habi embankn rflow of river rs, 20 meters a	Fooder (in Q)  0.00  0.00  0.00  0.00  Others  CANDLE-2 Pkt  Candle-705  ment   Dahalal Suklai on diff suklai on diff suklai on diff and 25 meters	Bran (in Q) 434.50 0.00 0.00 0.00 434.50  2.00-Pkt; MA 60.00-Pkt; Tan nabi   Newly of ferent places.   (Long - 91	0.00 0.00 1329.25 0.00 1329.25 TCH BOX-1.0 paulin -291.00 constructed riv On 20 June 20 758400, Lat -	on-Pkt; M. CO on-Pieces er embankmen one one one of the control of	IL-2.00-  at is IMATE ept - Water  f length 30 nt)
Relief Distributed Others  Infrastructur e Damaged - Embankme nt Breached	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*  Udalguri  Total District/Sub -division*  Biswanath	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q 1 Numbe r  1 Numbe r	3.42 0.44 0.00 1.24 5.10 od  0.00-Q  6.00-Pkt  Details  Harisin damaged DAMAG Resource  Details  Gohpur mtr on 2  Mangal	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal d due to ove GE 50 meter e Deptt.)	0.00 13.26 0.00 37.25 50.51  d Solid  0.00-Q  6.00-Pkt  habi embankn rflow of river rs, 20 meters a  c erosion is ob Long - 93.737 ik Naharbari F	CANDLE-2 Pkt Candle-705  Candl	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  habi   Newly of ferent places.    (Long - 91)  k embankme 352548.0000 e Pariapara   1	0.00 0.00 1329.25 0.00 1329.25  TCH BOX-1.0  rpaulin -291.00  constructed riv On 20 June 20 .758400, Lat -	D0-Pkt; M. CO D-Pieces  er embankmen D23. APPROX 26.700700, De  Auguri area o elect Departme water level ero	IL-2.00-  at is IMATE ept - Water  f length 30 nt) sion
Relief Distributed Others  Infrastructur e Damaged - Embankme nt Breached  Infrastructur e Damaged -	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*  Udalguri  Total District/Sub -division*	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q 1 Numbe r  1 Numbe r	3.42 0.44 0.00 1.24 5.10 od  0.00-Q  6.00-Pkt  Details  Harising damaged DAMAG Resource  Details  Gohpur mtr on 2  Mangal occurred	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal d due to ove GE 50 meter e Deptt.)  - Mild bark 0.0/06/23     ( doi - Kulshi d at Guide B	0.00 13.26 0.00 37.25 50.51  d Solid  0.00-Q  6.00-Pkt  habi embankn rflow of river rs, 20 meters a  c erosion is ob Long - 93.737 k Naharbari F undh of Kulsh	CANDLE-2 Pkt Candle-705  ment   Dahalal Suklai on difund 25 meters  Served R/Bar 7047, Lat - 26 TS   At villag nik Naharbari	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  mabi   Newly of ferent places   (Long - 91)  ok embankme 352548.0000 e Pariapara   11 FIS with app	0.00 0.00 1329.25 0.00 1329.25  TCH BOX-1.0  paulin -291.00  constructed riv On 20 June 20 758400, Lat -	O0-Pkt; M. CO O-Pieces er embankmen O23. APPROX 26.700700, De Auguri area o elect Departme water level ero 100m. as repoi	IL-2.00-  It is IMATE ept - Water  f length 30 nt) sion rted by
Relief Distributed Others  Infrastructur e Damaged - Embankme nt Breached	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*  Udalguri  Total District/Sub -division*  Biswanath	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q 1 Numbe r  1 Numbe r	3.42 0.44 0.00 1.24 5.10 0.00-Q 6.00-Pkt Details Harising damaged DAMAG Resource Details Gohpur mtr on 2 Mangal occurred Irrigatio	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal d due to ove GE 50 meter e Deptt.) - Mild bark 0.0/06/23     ( doi - Kulshi d at Guide B n departmer	0.00 13.26 0.00 37.25 50.51  d Solid  0.00-Q  6.00-Pkt  habi embankn rflow of river rs, 20 meters a k erosion is ob Long - 93.737 k Naharbari F undh of Kulsh nt. Dated 19/0	Fooder (in Q)  0.00  0.00  0.00  0.00  Others  CANDLE-2 Pkt Candle-705  ment   Dahalal Suklai on diffund 25 meters  047, Lat - 26 TS   At villag nik Naharbari 6/2023.   (Lor	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  abi   Newly of Grent places.    (Long - 91)  k embankme 352548.0000  e Pariapara   1  FIS with apping - 26.50960	0.00 0.00 1329.25 0.00 1329.25  TCH BOX-1.0  constructed riv On 20 June 20 .758400, Lat -  nt of Sessa   at 00, DeptSe Due to rise of v rox. length of 0, Lat - 91.943	O0-Pkt; M. CO O-Pieces  er embankmen O23. APPROX 26.700700, De Auguri area o elect Departme water level ero 100m. as repoi	IL-2.00-  It is  IMATE  ept - Water  f length 30  nt)  sion  rted by  rigation)
Relief Distributed Others  Infrastructur e Damaged - Embankme nt Breached  Infrastructur e Damaged - Embankme	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*  Udalguri  Total District/Sub -division*  Biswanath	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q 1 Numbe r 1 1 Numbe r	3.42 0.44 0.00 1.24 5.10 0.00-Q  6.00-Pkt  Details Harising damaged DAMAG Resource  Details Gohpur mtr on 2 Mangal occurred Irrigatio Goresw	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal d due to ove GE 50 meter e Deptt.)  - Mild bark 0.0/06/23    ( doi - Kulshi at Guide B n departmer ar - R/B par	0.00 13.26 0.00 37.25 50.51  d Solid  0.00-Q  6.00-Pkt  habi embankn rflow of river rs, 20 meters a  k erosion is ob Long - 93.737 k Naharbari F undh of Kulsl nt. Dated 19/0 nchayat bandh	rooder (in Q)  0.00  0.00  0.00  0.00  0.00  Others  CANDLE-2 Pkt Candle-705	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  abi   Newly of Grent places.    (Long - 91)  k embankme 352548.0000  e Pariapara   1  FIS with apping - 26.50960  Sulaipara bord	0.00 0.00 1329.25 0.00 1329.25  TCH BOX-1.0  rpaulin -291.00  constructed riv On 20 June 20 .758400, Lat -  tof Sessa   at 00, DeptSe Due to rise of v rox. length of 0, Lat - 91.943 o supa )   Villag o supa )   Villag	O0-Pkt; M. CO O-Pieces  er embankmen O23. APPROX 26.700700, De  elect Departme water level ero 100m. as repoi 3700, Dept - Iri ge Tengajhar (	IL-2.00-  It is  IMATE  Ept - Water  f length 30  nt)  sion  rted by  rigation)  Sulaipara
Relief Distributed Others  Infrastructur e Damaged - Embankme nt Breached  Infrastructur e Damaged - Embankme	Biswanath Kokrajhar Lakhimpur Udalguri Total District/Sub -division* Biswanath Kokrajhar Lakhimpur Udalguri District/Sub -division*  Udalguri  Total District/Sub -division*  Biswanath	17.99 1.06 0.00 6.94 25.99 Baby For Liquid 0.00-Q 0.00-Pkt, 0.00-Q 1 Numbe r  1 Numbe r	3.42 0.44 0.00 1.24 5.10 0.00-Q  6.00-Pkt  Details  Harising damaged DAMAG Resource  Details  Gohpur mtr on 2  Mangal occurred Irrigatio  Goresw Boro sup	0.00 0.13 0.00 0.37 0.50 Baby Foo 0.00-Q 0.00-Pkt, 0.00-Q 0.00-Q, 10 ga - Dahalal d due to ove GE 50 meter e Deptt.)  - Mild bark 0/06/23    ( doi - Kulshi at Guide B n departmer ar - R/B par pa)   As per	0.00 13.26 0.00 37.25 50.51  d Solid  0.00-Q  6.00-Pkt  habi embankn rflow of river rs, 20 meters a  k erosion is ob Long - 93.737 k Naharbari F rundh of Kulsl nt. Dated 19/0 nchayat bandh information re	rooder (in Q)  0.00  0.00  0.00  0.00  0.00  Others  CANDLE-Pkt  Candle-705  C	Bran (in Q)  434.50  0.00  0.00  0.00  434.50  2.00-Pkt; MA  60.00-Pkt; Tan  abi   Newly of the second of the seco	0.00 0.00 1329.25 0.00 1329.25  TCH BOX-1.0  constructed riv On 20 June 20 .758400, Lat -  nt of Sessa   at 00, DeptSe Due to rise of v orox. length of 0, Lat - 91.943 o supa )   Villag in and rise of v	O0-Pkt; M. CO O-Pieces  er embankmen O23. APPROX 26.700700, De Auguri area o elect Departme water level ero 100m. as repoi	IL-2.00-  It is  IMATE  Ept - Water  f length 30  nt)  sion  rted by  rigation)  Sulaipara  iver Suklai

			country side. approx length of overtop and erosion 100m date 20/06/23   (Long - 91.690326, Lat - 26.601058, DeptSelect Department)
	Total	3	201001020, 2 spt. Boton 2 spatiment )
	District/Sub	Numbe	Details
	-division*  Biswanath	1	Halem - Tinikunia to Kawripathar Road via Possagula   Kawripathar   Road- Road from Tinikunia to Kawripathar Road via Possagula (A construction ongoing Road under MMPPNA-2022- 23) (from Ch.1060.00 m to 1360.00 m), sporadic erosion in the road embankment has been noticed on 20/06/2023. Details of damages will be assed as soon as flood water will be receded.   (Long - 9347579.000000, Lat - 26907961.000000, Dept - PWD (Roads))
Infrastructur e Damaged - Road	Bongaigaon	26	Dangtol - Pachim Bhadragaon to Digdari Road   Pachim Bhadragaon   Embankment Damaged at Ch. 1450.00m.asp er report received from PWRD, Bongaigaon dated-20.06.2023   (Long - 90.446261, Lat 26.425879, Dept PWD (Roads)), Bhadragaon to Digdari Road   Bhadragaon   Embankment damaged at Ch. 1690.00m. as per report received from PWRD, Bongaigaon dated-20.06.2023   (Long - 90.445417, Lat 26.440607, Dept PWD (Roads)), Boitamari - Chalantapara PWD Road to Khatapara   Chalantapara   Shoulder and C.D. damaged at Ch. 1st Km. as per report received from PWRD, Bongaigaon, date-20.06.2023   (Long - 90.459430, Lat 26.262880, Dept. PWD (Roads)), Joigopha Oudubi Salbari road   Jogigopha   Hard crust and Shoulder damaged at Ch. 2nd and 12Km. as per report received from PWRD, Bongaigaon dated-20.06.2023   (Long - 90.489960, Lat 26.262870, Dept PWD (Roads)), Novagaon Shivmandir road   Noyagaon   Water Hyacinth at Ch. 1st Km. as per report received from PWRD, Bongaigaon dated-20.06.2023   (Long - 90.622770, Lat 26.304980, Dept. PWD (Roads)), Manikpur - Oil N.T. Road   Old N.T. Road   N.T. Road   Old

	ı	
		Dumerguri Lotibari Road   Dumerguri   Shoulder damage and hard crust at Ch. 1st Km and 2nd Km.as per report received from PWRD, Bongaigaon, dated-20.06.2023   (Long - 90.677220, Lat - 26.283680, Dept - PWD (Roads)),  Barjana-I to Barjana-III Road   Barjana   Shoulder damage at damage at Ch. 2km.as per report received from PWRD, Bongaigaon, dated-20.06.2023   (Long - 90.670270, Lat - 26.259760, Dept - PWD (Roads)),  SH-2 Lengtisinga (Deohati to Sontoshpur) Road   Deohati   Shoulder damage and hard crust at Ch. 30th, 32nd and culvert at Ch. 33 Km.as per report received from PWRD, Bongaigaon, dated-20.06.2023   (Long - 90.721847, Lat - 26.314420, Dept - PWD (Roads)),  SH-2 Santoshpur Road   Santoshpur   Shoulder and hard crust damage at Ch. 1sta Km.as per report received from PWRD, Bongaigaon, dated-20.06.2023   (Long - 90.740630, Lat - 26.312900, Dept - PWD (Roads)),  Behulapara to Kochbari Road   Behulapara   Shoulder and R.C.C Bridge approach damaged.as per report received from PWRD, Bongaigaon, dated-20.06.2023   (Long - 90.697660, Lat - 26.316270, Dept - PWD (Roads)),  Behulapara to Bhadaipara Road   Behulapara   Shoulder and Hard crust damaged. as per report received from PWRD, Bongaigaon, dated-20.06.2023   (Long - 90.708790, Lat - 26.312240, Dept -
Chirang	1	PWD (Roads)) <b>Bijni</b> - Ledopara to Uttar Baldi Road.   Nangdarbari   As reported by PWD Chirang(R&B) Division, road embankment damaged at Ch 4000.00 m at Nangdarbari on 20-06-2023. Length=40 mtr, Breadth=6.00 mtr, Depth=3.00 mtr.   (Long - 90.592250, Lat - 26.592213, Dept - PWD (Roads))
Darrang	9	Patharighat - Duni Sareng Andherighat connecting Road N. 1 & 2   kahitoli   Submerged at length 500 m Height 0.50 mt. as on 20-06-2023   (Long - 91.816155, Lat - 26.496622, Dept - PWD (Roads)),  Bihaigaon to MPK Road   Bihaigaon   submerged at L= 2.00 km Ht. 0.30 m as on 20-06-2023   (Long - 91.823433, Lat - 26.499135, Dept - PWD (Roads)),  Bihaigaon to Duni Sareng connecting road   Bihaigaion   submerged at length 060 km depth 0.30 mt as on 20-06-2023   (Long - 91.827453, Lat - 26.489050, Dept - PWD (Roads)),  Duni College to Jaypur Road   Duni   submerged at length L= 0.50 km Ht40 mtr as on 20-06-2023   (Long - 91.804190, Lat - 26.466774, Dept - PWD (Roads)),  Bihaigaon to Bheruadol connecting Road   Bheruadol   submerged at length L= 0.80 km Ht40 mtr as on 20-06-2023   (Long - 91.827527, Lat - 26.498040, Dept - PWD (Roads)),  Duni College to Malibari Road   malibaritari   submerged at length L= 1.00 km km Ht45 mtr as on 20-06-2023   (Long - 91.805012, Lat - 26.470374, Dept - PWD (Roads)),  Hussainchubri to Andherighat Jayantipur Road   Hussainchubri   Submerged at length L= 600 mt height0.50 mt as on 20-06-2023   (Long - 91.814808, Lat - 26.490440, Dept - PWD (Roads)),  baneikuchi Matrisewa Sangha to Hatimara Sarabari connecting Road   Baneikuchi   Road partially submerged as reported by PWD Deptt. as on 20-06-2023   (Long - 91.877725, Lat - 26.489157, Dept - PWD (Roads)),  MPK to Kuddus Ali residence connecting Road   Borkumarpara village   Breach of Road occurred as reported by JE PNRD, Patharighat of around 6 mt. as on 20-06-2023   (Long - 91.895490, Lat - 26.436552, Dept - P&RD)
Dhubri	6	Golakganj - KANURI DIMAKURI ROAD AT 5TH KM TO 10TH KM (DATE 15-6-2023)   KANURI DIMAKURI ROAD    (Long - 26.047600, Lat - 89.810100, Dept - PWD (Roads)), DAMAGED AT SPT NO. 4/1 ON DK ROAD TO JALDOBA VIA ALOKJHARI (DATE 17-6- 2023)   DK ROAD TO JALDOBA VIA ALOKJHARI    (Long - 26.429300, Lat - 89.166200, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 2/1 ON KAMANDANGA TO RAMNATHPARA ROAD AT 2ND KM (DATE 17-6-2023)   KAMANDANGA TO RAMNATHPARA    (Long - 26.826500, Lat - 89.524500, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 3/1 AT 3RD KM & RCC BR. NO. 2/1 AT 2ND ON MADDHYAPETLA TO PATHANERKUTI ROAD (DATE 17-6-2023)   MADDHYAPETLA TO PATHANERKUTI ROAD    (Long - 26.127300, Lat - 89.023400, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 1/1 ON BASANTIPUR TO KAMANDANGA ROAD AT 1ST KM(DATE 17-6-2023)   BASANTIPUR TO KAMANDANGA ROAD    (Long - 26.967200, Lat - 89.621200, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BOX CELL CULVERT NO. 3/1 ON DK ROAD BISHKURA UZANPETLA ROAD AT 3RD KM (DATE 17-6-2023)   DK ROAD BISHKURA UZANPETLA ROAD    (Long - 26.023300, Lat - 89.524300, Dept - PWD (Roads))
Goalpara	1	Lakhipur - Katarihara Bhalukmari Road via Tekona   Near Tekona   As per report of PWD roads department, Due to the incessant rainfall for last 7 days, Katarihara Bhalukmari Road via Tekona at 3rd KM has been eroded and affected length 10 M from 17.06.2023 to till date i.e 20.06.2023   (Long - 90.196875, Lat - 26.038758, Dept - PWD (Roads))
Kamrup	8	Goroimari - Road submerged Length 100 m, Breadth 6 m Hatisolapam to Dakshin Laruajan as reported by AEE, PWRD Chhaygaon. Date: 19/06/2023.   Goroimari     (Long - 91.206634, Lat - 26.066046, Dept - PWD (Roads)), Road submerged Length 120 m, Breadth 6 m Goroimari to Kalatoli as reported by AEE, PWRD Chhaygaon. Date: 19/06/2023.   Goroimari     (Long - 91.223401, Lat - 26.107485, Dept - PWD

			(Roads)), Road submerged 150 m, Breadth 6 m Baghmara Topar Pathar road as reported by AEE, PWRD Chhaygaon. Date: 19/06/2023.   Goroimari     (Long - 91.207165, Lat - 26.119696, Dept - PWD (Roads)), Road submerged 130 m, Breadth 6 m Goroimari to Choudhurypam as reported by AEE, PWRD Chhaygaon. Date: 19/06/2023.   Goroimari     (Long - 91.221955, Lat - 26.081043, Dept - PWD (Roads)), Road submerged 100 m, Breadth 6 m Bihapara Kharidol road as reported by AEE, PWRD Chhaygaon. Date: 19/06/2023.   Goroimari     (Long - 91.281520, Lat - 26.083632, Dept - PWD (Roads)),  Hajo - Saniadi khopnikuchi road   On 19/06/2023 at vill-saklapar, saniadi khopnikuchi road 60m was submerged. As per information received by pwd road hajo   No population affected   (Long - 26.079000, Lat - 91.915000, Dept - PWD (Roads)), Hiragana babu boring akadi road   Vill-hirajani at 19/06/2023 20m hirajani bamunbori road was submerged. As per information received by pwd road hajo.   No population affected   (Long - 26.409000, Lat - 91.307000, Dept - PWD (Roads)), Saniadi barchapari road   On 19/06/2023 at village barchapari the saniadi barchapari road 40m got submerged. As informed by PWD road hajo.   No population affected   (Long - 26.264452, Lat - 91.492517, Dept - PWD (Roads))
	Karimganj	1	18/6/2023 to the above mentioned road has been got affected & slump down, the concern dept has been directed for taking immediate necessary action. Affected length-20 m   (Long - 92.348188, Lat - 24.755001, Dept - PWD (Roads))
	Kokrajhar	6	Bagribari - Debitola to Borvita Road   Debitola   As reported by AEE, PWD RR Gossaigaon Sub-Division the road has been submerged on 20-06-2023   (Long - 90.002614, Lat - 26.159232, Dept - PWD (Roads)),  Mahamaya to Snanghat Road   Snanghat   As reported by AEE PWD RR Gossaigaon Sub-Division the road has been wahshed out at Snanghat on 20-06-2023   (Long - 90.124510, Lat - 26.220478, Dept - PWD (Roads)),  Gossaigaon - MATIAPARA TO GAONCHULKA ROAD   MATIAPARA   AS REPORTED BY ASSTT. EXEC. ENGINEER, PWD GOSSAIGAON (RR) SUB-DIVISION DATE: 20-06-2023, DUE TO HEAVY RAINFALL MATIAPARA TO GAONCHULKA ROAD IS ERRODED.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  DK ROAD   DK ROAD   AS REPORTED BY ASSTT. EXEC. ENGINEER, PWD GOSSAIGAON (RR) SUB-DIVISION DATE: 20-06-2023, DUE TO HEAVY RAINFALL ROAD HAS BEEN DAMAGED IN SOME STRECHES AT DK ROAD.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  (Kokrajhar) At District - CHOIBARI TO BANGALDOBA ROAD   CHOIBARI   AS REPORTED BY ASSTT. EXE. ENG. PWD KOKRAJHAR RURAL ROADS SUB-DIVISOIN 20/06/2023. DUE TO THE HEAVY RAINFALL FROM 12/06/2023 TO 20/06/2023, ROAD AT CHAINAGE 1210.00M TO 1260.00M ON CHOIBARI TO BANGALDOBA ROAD ERRODED.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  TILAPARA TO MAHAJANPARA   TILAPARA   AS REPORTED BY ASSTT. EXE. ENG. PWD KOKRAJHAR RURAL ROADS SUB-DIVISOIN 20/06/2023. DUE TO THE HEAVY RAINFALL FROM 12/06/2023 DUE TO THE HEAVY RAINFALL FROM 12/06/2023. DUE TO THE HEAVY RAINFALL
	Nagaon	2	of Kallong river on dated 19.06.2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Mulankata Rahachaki Hariamukh Meteka Road on dated 19.06.2023   Mulankata   Heavy erosion took place at Raha purona Chariali to Sankar Mandir Tiniali Approx 1-200M on dated 19.06.2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Nalbari	2	Banekuchi - On 20/06/2023 at 5 AM Makrapar chowk via Barbara to Sahpur PWD Road submerged report from Gaon Pradhan of Sandheli   Pachim Sanora & Pub Sanora     (Long - 91.387450, Lat - 26.457048, Dept - PWD (Roads)), On 20/06/2023 at 4 AM Makrapar chowk via Majkuchi to Kaithalkuchi PWD road submerged report from Gaon Pradhan of Kaithalkuchi   Majkuchi -Bhagabatipara (Kaithalkuchi)     (Long - 91.323300, Lat - 26.439716, Dept - PWD (Roads))
	Tamulpur	1	<b>Tamulpur</b> - Anandabazar to Jamuguri via Borkajuli Road   Village - Garughutu   As per report received from PWDRR on 16-06-2023 due to heavy rain flood damaged and submerge Anandabazar to Jamuguri via Borkajuli Road   (Long - 91.544316, Lat - 26.664059, Dept - PWD (Roads))
	Total	64	
T.C.	District/Sub	Numbe	Details
Infrastructur e Damaged - Bridge	-division* Barpeta	<b>r</b>	Barpeta - Ata village Bamboo bridge   Ata village   As per field visit report, the Banboo bridge on river Pahumara at Ata village has washed away by the rising river of River Pahumara on 20/06/2023.   (Long - 91.091829, Lat - 26.425274, Dept - PWD (Roads))

			Manikpur - Manikpur Bashbari Road   Manikpur   SPT Bride no: 3/1 & SPT Bridge no 4/1 got						
	Bongaigaon	1	damaged. as per report received from PWRD, Bongaigaon, dated- 20.06.2023   (Long - 90.800412, Lat - 26.441907, Dept - PWD (Roads))						
	Kokrajhar	Gossaigaon - DWILUNG BRIDGE   NO. 2 DAWAGURI   AS REPORTED BY KACHUC  DEV. BLOCK DATE: 20-06-2023, DUE TO HEAVY RAINFALL DWILUNG BRIDGE I.  DAMAGED.   (Long - 26.450534, Lat - 89.891612, Dept - P&RD)							
	Total	3	Diministration (Bong 20160001, 200 071012, 20pt 1 0112)						
Infrastructur e Damaged - Wildlife	Nil								
	District/Sub -division*	Other D	Details Details						
	Chirang	Monesw Breadth: Public F 19-06-20 mtr. Lat Public F 19-06-20 Mtr. Lat Public F 19-06-20 Latitude	<b>Bijni</b> - Bamboo Foot Bridge   As reported by concerned LM, on 19-06-2023, bamboo bridge connecting Moneswari village and No 1 Supariguri is reported to be washed away. Length=18 metres(Approx), Breadth=2.4 metres(Approx), Latitude=26.491343 Longitude=90.731784, Public Health Engineering (PHE)   As reported by AEE, PHED, Bijni Sub Division, the damages occurred on 19-06-2023: Boundary Wall at South Barlawgaon damaged. Length= 20 mtr,Breadth=1.80 mtr, Depth=2.10 mtr. Latitude=26.539316 Longitude=90.698134, Public Health Engineering (PHE)   As reported by AEE, PHED, Bijni Sub Division, the damages occurred on 19-06-2023, Plinth Protection damaged at South Barlawgaon. Length=20 mtr, Breadth= 1.80 mtr, Depth=0.50 Mtr. Latitude=26.539316 Longitude=90.698134, Public Health Engineering (PHE)   As reported by AEE, PHED, Bijni Sub Division, the damages occurred on 19-06-2023, Drain damaged at South Barlawgaon. Length=20 mtr, Breadth=0.50 mtr, Depth= 0.50 mtr.						
Infrastructur	Darrang	protection 20-06 Road Bribreach of Mangal Approx. Power Dated 20 Power Dated are dama Dalgaor 92.2078 Fisherie	Latitude=26.539316 Longitude=90.698134.  Patharighat - Irrigation Canal/Scheme Damaged   As reported by JE, Irrigation Breach occurred at D/S protection work of Athkuria Kurarmukh FIS at village Bareri of length 20 mt (approx.) of Irrigation Deptt. as on 20-06-2023, Road Breaches   As reported by BDO, Sipajhar, MPK to Kulchipathar connecting Road damaged due to breach of road at 3 different locations/pin point of same road. as on 20-06-2023,  Mangaldoi - Fisheries/Pond   As per information of fishery Department 5 Nos of fish farmers are affected with Approx. water area of 1 Ha. Dated 20/06/2023.,  Power Dept. Poles   As per information received from APDCL Mangaldai approx. 5 Nos of poles are damaged. Dated 20/06/2023.,  Power Dept. Conductors   As per information received from APDCL Mangaldai approx. 1.8km of conductors are damaged. Dated 20/06/2023.,  Dalgaon - Irrigation Canal/Scheme Damaged   been damaged under dalgaon revenue circle.Lat-26.58658,Lon-92.20781.Date of occurrence-19-06-2023,  Fisheries/Pond   As per report received from Fishery department, 20nos of beneficiary,20 nos of tank of						
e Damaged - Others	Goalpara	4.95Ha water area has been affected under dalgaon revenue circle Dated 20-06-2023.  Dudhnoi - Irrigation Canal/Scheme Damaged   As per report submitted by Irrigation Department, left sie Earthen canal from Ch 2057.00m to 2101.00m of Right Bank Main Canal of Rongronga FIS damaged of 19.06.2023 due to heavy rainfall, Lat. 25.953154 N Long. 90.8885222 E, Irrigation Canal/Scheme Damaged   As per report submitted by Irrigation department, both side Earthen from Ch. 3101.00m to 3121.00m of Right Bank Main Canal of Rongronga FIS damaged on 19.06.2023 (heavy rainfall, Lat. 25.960196 N Long. 90.882685 E, Irrigation Canal/Scheme Damaged   As per report submitted by Irrigation department, both side Earthen of Right Bank Main Canal of Rongrongra FIS from Ch. 3976.00m to 3981.00m damaged on 19.06.2023 heavy rainfall, Lat. 25.96855 N, Long. 90.882051 E							
	Kokrajhar	at Fulku Damage Fulkuma Gossaig GOSSA VILLAG Bridge A (RR) SU COLLE Damage DIVISIG DAMAG Culvert (RR) SU DAMAG (Kokraj KOKRA 12/06/20	ari - Damaged SPT Bridge   As reported by AEE, PWD RR, Gossaigaon Sub-Division SPT Br No. 1/1 mari Tipkai Road has been damaged on 20-06-2023, d SPT Bridge   As reported by AEE, PWD RR, Gossaigaon Sub-Division SPT Br. No. 1/1 at Gendrabil ari Road has been damaged on 20-06-2023, laon - Bridge Approach Road Damaged   AS REPORTED BY ASSTT. EXEC. ENGINEER, PWD IGAON (RR) SUB-DIVISION DATE: 20-06-2023, DUE TO HEAVY RAINFALL SILPUR GE ROAD WOODEN BRIDGE IS DAMAGED., Approach Road Damaged   AS REPORTED BY ASSTT. EXEC. ENGINEER, PWD GOSSAIGAON UB-DIVISION DATE: 20-06-2023, DUE TO HEAVY RAINFALL GOSSAIGAON GUABARI VIA GE ROAD BRIDGE NO. 5/2 PARTIALLY DAMAGED, d SPT Bridge   AS REPORTED BY ASSTT. EXEC. ENGINEER, PWD GOSSAIGAON (RR) SUB- DIVISION DATE: 20-06-2023, DUE TO HEAVY RAINFALL SPT BRIDGE NO. 2/1 PARTIALLY GED WITH BOTH SIDE APPROACHES ON HUDUMKHATA TO ODALGURI ROAD, Approach Road Damaged   AS REPORTED BY ASSTT. EXEC. ENGINEER, PWD GOSSAIGAON UB-DIVISION DATE: 20-06-2023, DUE TO HEAVY RAINFALL CULVERT NO. 1/1 HAS BEEN GED ON NO.2 HUDUMKHATA VILLAGE ROAD, JHAR RURAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM DIATIONAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM DIATIONAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM DIATIONAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM DIATIONAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM DIATIONAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM DIATIONAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM DIATIONAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM DIATIONAL ROADS ERRODED.,						

		Damaged RCC Bridge   AS REPORTED BY ASSTT. EXE. ENG. PWD KOKRAJHAR RURAL ROADS SUB-DIVISOIN 19/06/2023. DUE TO THE HEAVY RAINFALL FROM 12/06/2023 TO 19/06/2023, APPROACHES OF RCC BRIDGE NO. 3/2 ON DOTMA BALAJAN ROAD ERRODED., Culvert Approach Road Damaged   AS REPORTED BY ASSTT. EXE. ENG. PWD KOKRAJHAR RURAL ROADS SUB-DIVISOIN 20/06/2023. DUE TO THE HEAVY RAINFALL FROM 12/06/2023 TO 20/06/2023, APPROACHES OF HP CULVERT NO. 2/1 ON MAGURMARI TO SESAPANI ROAD DAMAGED., Culvert Approach Road Damaged   AS REPORTED BY ASSTT. EXE. ENG. PWD KOKRAJHAR RURAL ROADS SUB-DIVISOIN 20/06/2023. DUE TO THE HEAVY RAINFALL FROM 12/06/2023 TO 20/06/2023, APPROACHES OF RCC BOX CULVERT ON 3/1 ON SIMBARGAON TO HEKAIPARA ROAD ERRODED., Culvert Approach Road Damaged   AS REPORTED BY ASSTT. EXE. ENG. PWD KOKRAJHAR RURAL ROADS SUB-DIVISOIN 20/06/2023. DUE TO THE HEAVY RAINFALL FROM 12/06/2023 TO 20/06/2023, APPROACHES OF HP CULVERT NO. 3/2 ON KASHIPARA TO MOLANDUBI ROAD
	Nagaon	DAMAGED.  Kampur - Elementary Schools Damaged   Due to rising water level of River Kopili 1 (One) No. of School namely Pachim Garukhunda New LPS of Garukhunda Village submerged on dated 19.06.2023. Location Details: Lat: 26.116334, Long: 92.715859. The School Belongs to Block Elementary Education Officer, Kathiatoli.
	Nalbari	Tihu - Agri Bundh Damaged   AGRIBUNDH OF BURHADIA RIVER BREACHED AT BIJULI SUPA OF BHOJKUCHI ON 20/06/2023 ,LENGTH IS APPROX 30 FTS AS PER REPORT GP , Agri Bundh Damaged   AGRIBUNDH OF RIVER BURHADIA AND MORAPAGOLDIA JOINING POINT BREACHED AT TIBENI GHAT ,BARPIT ,VILLAGE BHOJKUCHI ON 20/06/2023,LENGTH IS APPROX 15 MTS AS PER REPORT GP. , Agri Bundh Damaged   AGRIBUNDH OF MORAPAGOLDIA AT BAISHYA SUPA & KALITA SUPA BREACHED,ERODED AND SUBMERGED APPROX 145 FTS ,DATE OF REPORTING 19/06/2023 AS PER REPORT GP, Banekuchi - Culvert Approach Road Damaged   On 19/06/2023 at 10 AM the culvert of Naddya Suburi of Kathalbari Road damaged .Report from Gaon Pradhan . Lat 26.523867 & Long 91.386572
	District/Sub -division*	Details
	Barpeta	<b>Barpeta</b> - Dokreswar   As informd by the AE, Water Resources Dept on 20/06/2023 the B/dyke from Bahari to Baghbar of Brahputra River, some portion of the Embankment affected due to erosion of River Brahmaputra   0   (Long - 0.000000, Lat - 0.000000)
	Biswanath	Naduar RC part - No-2 Bhojmari   Dated 20/06/23, as reported by Biswanath WR Sub- division, active bank erosion is observed at No-2 Bhojmari area on the R/Bank of river Brahmaputra of Biswanath -Panpur dyke.  Length = 20.00 m.   0   (Long - 93.089423, Lat - 26.670388),  Gohpur - At Gopsarguri   Mild bank erosion is observed marginal embankment on R/Bank of river Sessa Length: 120 mtr on 20/06/23   0   (Long - 93.716944, Lat - 26.979166),  Halem - Paken   Mild bank erosion is observed at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length =10m. (avg.width=0.10m) on 20/06/2023   0   (Long - 93.625317, Lat - 26.979166)
	Bongaigaon	Boitamari - Chatpara NC   One culvert is eroded on 19/06/2023 due to heavy rainfall   0   (Long - 903314.000000, Lat - 261342.000000),  Srijangram - Boroichala   A Masjid was damaged due to erosion on 20/06/2023 under Jopea GP   0   (Long - 90.768411, Lat - 26.347823)
Erosion	Dhubri	Golakganj - PUB GAIKHOWA PT 2   EROSION OCURRED AT VILLAGE PUB GAIKHOWA PT-2 UNDER GOLAKGANJ REVENUE CIRCLE BY RIVER GANGADHAR FEROM 12-6-2023 TO 19-6-2023 (AREA ERODED 1B-2K-10L)   22   (Long - 26.091500, Lat - 89.829400), Chapar - Tarangapur Pt-I   Erosion occurred on dated 19-06-2023 to 20-06-2023 at Tarangapur Pt-I village under Chapar Revenue Circle where 0B-2K-10L of agriculture land has been eroded so far. The erosion caused by the river Champabati.   0   (Long - 90.251840, Lat - 26.149860)
	Dibrugarh	Chabua - GEREKI NEPALI GAON   As per information received from Water Resources Dept. on 20.06.2023 Erosion occurred from 18.06.2023 to 20.06.2023 . Reach length -70 mtrs.   0   (Long - 27.569141, Lat - 95.240761)
	Golaghat	Sarupathar - No 1 Padumoni Parghat   Erosion at Padumoni Parghat date 20/06/2023 Reach length -1000m   0   (Long - 93.854283, Lat - 26.215034),  Dergaon - Dakhin Dalijaliya, Ward No. 2   Severe erosions have been observed at two locations in Dakhin Dalijaliya village, Ward No. 2 for a reach length of 120 M and 160 M respectively on dated 19-06-2023.   0   (Long - 93.958257, Lat - 26.714607),  Bokakhat - Riri Teliabari near Riri Gaon   the length of erosion reach is 300m at downstream of existing geobag protection work of river Brahmaputra at Riri Teliabari Gaon on 20.06.2023   0   (Long - 93.421530, Lat - 26.414918)
	Kamrup	<b>Kayan</b> - Dodotia   As per report of SDO water Resource Division, Nalbari, 80 Mtr. erosion occurred at village Dodotia on Dated- 19-06-23 under Kayan Revenue Circle, and visited with Gaonpradhan, & LM .   0   (Long - 91.542200, Lat - 26.409300)
	Morigaon	<b>Bhuragaon</b> - Balidunga Pam, Kupatimari   As per Water Resource department, Morigaon, Bhrahmaputra river erosion eroded 1 meter at a length of 700 meter at Kupatimari and Balidunga Pam revenue village under Bhuragaon Rev. Circle from 19-06-2023 to 20-06-2023."   0   (Long - 26.411003, Lat - 92.251558)

	Nalbari	<b>Barkhetri</b> - Larkuchi, Pub Hanapara   Severe damage have been occurring due to erosion of Brahmaputra in B/Dyke at D/S of Larkuchi, Length 150m. as reported by AEE, WRD, Mukalmua on 20/06/2023. River Bank erosion occurring at Pub Hanapara. 3 nos. of families have shifted due to erosion of river Pagaldia.   0   (Long - 0.000000, Lat - 0.000000)
	Sivasagar	Nazira - Raghuguri,Kheluwa Gaon   Form of Slump down on 19/06/2023 at left bank embankment of river Darika at Raghuguri   0   (Long - 94.691182, Lat - 26.987327),  Demow - Laibeel   Erosion at country side, Left Bank of Dehing River Embankment at Laibeel village.  Placement of Sand bag pitching & Bambo palisading is being carried out by WR officials. Date of occurrence: 20/6/20223.   0   (Long - 94.722057, Lat - 27.243820)
	Sonitpur	Thelamara - Village- Baligaon Bongaligaon   Date-20/06/2023, As reported by Water Resource Division Tezpur on 20/06/2023, Active bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri of Length: 200.00m, Latitude: 26.736022, Longitude: 92.558699   0   (Long - 92.558699, Lat - 26.736022),  Dhekiajuli - Kathalu Pathar   As per information received from concern Gaonpradhan of Kathalu Pathar as on 20/06/2023 that erosion was observed at Kathalu Pathar area of Gorujuli River under the jurisdiction of Dhekiajuli Revenue Circle.   0   (Long - 26.732099, Lat - 92.533566),  Chariduar - 1) Rajgarh area,2)Sonaipam Area   1)As per the WR department active erosion is going on the R/Bank of river Jiabharali at Rajgarh area (length 180 m)since 13.06.2023 to till today DTD 20.06.2023, Latitude-26.736501, Longitude-92.846335 2) As per the WR department active erosion is going on the R/Bank of river Jiabharali at Sonaipam area (length -450 m) since 16.06.2023 to till today DTD 20.06.2023, Latitude - 26.879842, Longitude -92.82512   0   (Long - 0.000000, Lat - 0.000000)
	Udalguri	Khairabari - GHOGAPARA   Due to downpour of rainfall and rise in water level of Khaplang river, the boundary wall of the BPF Office located at Ghogapara (Bhergaon) has collapsed due to erosion on 19.06.2023.   5   (Long - 91.825904, Lat - 26.633794),  Harisinga - No2 Bholatar   Due to heavy rainfall erosion occurred by River Suklai on 20th June 2023. Approximate damage 200meters   0   (Long - 91.813500, Lat - 26.811900)
	District/Sub -division*	Details
	Cachar	<b>Lakhipur</b> - Jhumtilla, Jirighat   Landslide at Jhumtilla, Jirighat dated 20.06.2023, As reported by Sub-Divisional Engineer APDCL.   0   (Long - 93.107258, Lat - 24.807751)
	Dima-Hasao	Haflong - Sengya Tularam, Lodi, Gunjung, Upper Bagetar   1. Landslide at Thangmanon Dibragede Village:- Sengya Tularam on 20-06-2023:- Lat:- 25.167978 Long:- 93.025078   0   (Long - 0.000000, Lat - 0.000000)
Landslide	Karimganj	Nilambazar - vill- Chandrapur, GP- Subashnagar   dated reported on 20/62023, 2 nos of landslide occured at vill- Chandrapur at the house of 1) Sadhan Das, S/o- Lt Subudh Das (Kuttcha House) & (2) Monosha Das, W/o- Subir Das (Pucca House). both are partially affected as per LM report.   0   (Long - 92.484550, Lat - 24.774954),  Karimganj - Vill.Ranigram Pt.II, Krishnanagar GP   Landslide Occured at Vill.Ranigram Pt.II, Krishnanagar GP on 19/06/2023. The owner of the house is Abdul Latif S/O Abdul Goni. The house is damaged partially.   7   (Long - 92.329151, Lat - 24.800141),  Badarpur - West Alekhargool under Anglarbazar GP   Due to incessant rainfall from past few days, a landslide incident has taken place on 19-06-23 at about 5:00 PM at Village West Alekhargool resulting a slump down of soil is observed in the pucca house of Mastan Uddin, S/O Siraj uddin. No casualty reported.   0   (Long - 92.546427, Lat - 24.842777)
	District/Sub -division*	Details
	Darrang	<b>Dalgaon</b> - Kharupetia Town (ward no.1,2,3,4,7,8,9 and 11)   As per report received from LM, waterlogging at kharupetia town (ward no.1,2,3,4,7,8,9 and 11) under dalgaon revenue circle as on 20-06-2023   1500   (Long - 92.149805, Lat - 26.519547)
Urban	Jorhat	Jorhat East - 1 no Chengeli Gaon   Artificial Water logging at 1 No Chengeli Gaon at PWD Road (approx. 245 Meters) due to continuous railfall and insufficient drainage on 19/06/2023 and 20/06/2023   0   (Long - 94.232583, Lat - 26.772333),  Jorhat West - Water logging occured at Sastripith and Manikpur area . Date : 20/06/2023   Due to continuous rain Water logging occured at Sastripith and Manikpur area . (approx. 300 Meters)   30   (Long - 0.000000, Lat - 0.000000)
Flood	Kamrup (M)	<b>Dispur</b> - hatigaon, rukminigaon, baghorbari revenue village   Date: 20/06/2023 Water logging at hatigaon, wireless, rukminigaon, baghorbari. Roads are inundated. No houses affected   0   (Long - 0.000000, Lat - 0.000000)
	Kokrajhar	Dotma - Fakiragram MB   Due to incessant rainfall, Waterlogging at Various wards under Fakiragram MB, dated - 20/06/2023 1. WARD NO.1 2. WARD NO.3   520   (Long - 0.000000, Lat - 0.000000), Kokrajhar - Ward no.1 to 10   DUE TO INCESENT RAINFALL FROM 12.06.2023, WATER LOGGED AT KOKRAJHAR URBAN AREA VIDE WARD NO. 1 TO 10, dated - 20/06/2023   17852   (Long - 0.000000, Lat - 0.000000)
	Nalbari	Nalbari - Hajo- Nalbari road, collage road, forest office road, debiram h.s to - bslilesha road, gurdon hs to barkura road   As per the LM report, these roads are submerged due to rain water dtd 20/06/2023   1200   (Long - 0.000000, Lat - 0.000000)
	· <u> </u>	*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)