



			Assam Floo	od Report as on 07-07-2024								
Particulars			Assar	m Flood Report as on 07-07-2024								
flowing above Danger				Brahmaputra (Neamatighat), Brahmaputra (Tezpur), Brahmaputra (Dhubri), Burhidihing (Chenimari(Khowang)), Dikhou (Sivasagar), Disang (Nanglamuraghat), Dhansiri (S) (Numaligarh), Kopili (Dharamtul), Beki (Road Bridge), Sankosh (Golokganj) Barak (B P Ghat), Kushiyara (Karimganj)								
Level (as per CWC bulletin issued at 8 AM)		wing above	e highest flood level	Nil								
Affected	No. of Distircts Affected	Name of A	Affected Districts									
	28		-	aon, Hailakandi, Bongaigaon, South Salmara, Dibrugarh, Karimganj, Lakhimpur, Hojai, hemaji, Barpeta, Sonitpur, Kokrajhar, Majuli, Kamrup (M), Darrang, Sivasagar, Chirang,								
No. Of Revenue Circles Affected	97											
	District	Total	Revenue Circle									
	•	4	Kalgachia, Barpeta, Chenga, Baghbar									
Circle Affected	Biswanat h		Gohpur, Halem, Biswanath									
	Bongaiga on		Srijangram, Boitamari									
			Silchar, Katigorah, Sonai									
	Charaide o	3	Mahmora, Sonari, Sapekhati									
	0	2	Bengtal, Bijni									
	Darrang		Sipajhar, Pub-Mangaldai, Dalgaon, Mang									
	Dhemaji		Sissiborgaon, Jonai, Gogamukh, Dhemaji									
	Dhubri Dibrugar			iolakganj, Chapar, South Salmara Part, Athani oran, Naharkatia, Dibrugarh East, Tengakhat								
	n Goalpara	3	Matia, Lakhipur, Balijana									
	Golaghat		Bokakhat, Khumtai, Dergaon									
	Hailakan di		Hailakandi, Algapur									
	Hojai	2	Hojai, Doboka									
	Jorhat	3	Teok, Jorhat East, Jorhat West									
		8	Chamaria, Kamalpur, North Ghy, Goroim	ari, Palashbari, Rangia, Nagarbera, Hajo								
	(M)	2	Sonapur, Chandrapur									
	Karimga nj		Nilambazar, Patherkandi, Karimganj, Bac	darpur								
	Kokrajha r		Bagribari, Gossaigaon, Dotma									
	Lakhimp ur		Bihpuria, Kadam, Subansiri, North Lakhir	mpur, Narayanpur								
	Majuli Morigao	2 4	Majuli, Ujani Majuli Bhuragaon, Morigaon, Mayong, Laharigh	nat								
	n Nagaon	6	Kaliabor, Raha, Dhing, Kampur, Samagur	i, Nagaon								
		1	Barkhetri									
	Sivasagar		Nazira, Sonari RC part, Demow, Sivsagar									
	Sonitpur		Tezpur, Dhekiajuli									
	Salmara	2	South Salmara, Mankachar									
			Margherita									
\/:!!==		97 Tatal	Davida Cirala									
		Total	Revenue Circle	Chy   20) (Caroimari   42) (Palachhari   20) (Panaia   45) (Nagarhara   20) (Unit								
mecteu	Kamrup	391	(Chamaria   60), (Kamaipur   75), (North 102)	n Ghy   29), (Goroimari   43), (Palashbari   39), (Rangia   15), (Nagarbera   28), (Hajo								





	Nagaon	217	(Kaliabor   5	53), (Ra	ha   46), (Dhing   15)	), (Kampur   57), (Samagu	ri   26), (Nagaon   20)							
	Cachar	157	(Silchar   26	5), (Kati	gorah   116), (Sonai	15)								
	Dhubri	656	(Dhubri   10 (Athani   11		uripur   73), (Agamo	ni   37), (Bilasipara   43),	(Golakganj   67), (Chapar   59), (South Salmara Part   164),							
	Goalpara	268	<u> </u>		ipur   185), (Balijana	38)								
	Morigao					yong   113), (Laharighat	29)							
	Hailakan 	19	(Hailakandi	8), (A	lgapur   11)									
	di Bongaiga	33	(Srijangram	19), (	Boitamari   14)									
	on South	66	(South Salm	nara   3	7), (Mankachar   29)									
	Salmara Dibrugar	131	(Tingkhong	9), (D	ibrugarh West   37),	(Chabua   3), (Moran   30	D), (Naharkatia   14), (Dibrugarh East   6), (Tengakhat   32)							
	h Karimga		(Nilambazaı	r   25).	(Patherkandi   2). (Ka	arimganj   15), (Badarpur	18)							
	nj Lakhimp		,		adam   7), (Subansiri   28), (North Lakhimpur   66), (Narayanpur   38)									
	ur					20), (NOITH LAKIIIII)uli	oo), (warayanpur   36)							
	•	5	(Hojai   3), (Doboka   2) (Barkhetri   59)											
		59		Mahmora   51), (Sonari   4), (Sapekhati   8)										
	Charaide o													
	Biswanat 13 (Gohpur   1), (Halem   11), (Biswanath   1)													
	Golaghat				humtai   22), (Derga									
		47			East   14), (Jorhat W									
	Dhemaji		1			nukh   6), (Dhemaji   2)								
	Barpeta		(Kalgachia   36), (Barpeta   5), (Chenga   52), (Baghbar   84) (Tezpur   18), (Dhekiajuli   1)											
	Sonitpur													
	Kokrajha r	33	(Bagribari	26), (G	ossaigaon   1), (Dotn	na   6)								
	Majuli	78			i Majuli   11)									
	Kamrup (M)		(Sonapur   8	8), (Cha	ndrapur   12)									
	Darrang		(Sipajhar   1	13), (Pu	b-Mangaldai   34), ([	Dalgaon   10), (Mangaldoi	28)							
	Sivasagar				i RC part   2), (Demo	w   38), (Sivsagar   64)								
	Tinsukia		(Margherita											
	Chirang	11	(Bengtal   3	), (Bijni	8)									
	Total	3446				-								
	District	Male	Female Childr Total Population Total Crop Area Population and Crop Area Details											
Population  And Crop		iviale	Female	en	Total Population	l otal Crop Area	Population and Crop Area Details							
and Crop	Barpeta			en	134328	1931.46	(Kalgachia   Population Affected: 14127   Crop Area: 2), (Barpeta   Population Affected: 852   Crop Area: 0), (Cheng							
And Crop Area Affected	Biswanat h	56543 1316		en 33553 16809	134328		(Kalgachia   Population Affected: 14127   Crop Area: 2), (Barpeta   Population Affected: 852   Crop Area: 0), (Cheng   Population Affected: 57988   Crop Area: 433), (Baghbar							
And Crop Area Affected	Biswanat	56543 1316	44232	<mark>en</mark> 33553	134328	1931.46	(Kalgachia   Population Affected: 14127   Crop Area: 2), (Barpeta   Population Affected: 852   Crop Area: 0), (Cheng   Population Affected: 57988   Crop Area: 433), (Baghbar   Population Affected: 61361   Crop Area: 1496.46) (Gohpur   Population Affected: 209   Crop Area: 14.7), (Halem   Population Affected: 18975   Crop Area: 0),							
And Crop Area Affected	Biswanat h Bongaiga on	56543 1316	1059 10088	en 33553 16809 10458	134328	1931.46 14.7	(Kalgachia   Population Affected: 14127   Crop Area: 2), (Barpeta   Population Affected: 852   Crop Area: 0), (Cheng   Population Affected: 57988   Crop Area: 433), (Baghbar   Population Affected: 61361   Crop Area: 1496.46) (Gohpur   Population Affected: 209   Crop Area: 14.7), (Halem   Population Affected: 18975   Crop Area: 0), (Biswanath   Population Affected: 0   Crop Area: 0) (Srijangram   Population Affected: 28664   Crop Area: 0),							
And Crop Area Affected	Biswanat h Bongaiga on	56543 1316 10701 60107	1059 10088	en 33553 16809 10458 56814 14579	134328 19184 31247 177928	1931.46 14.7	(Kalgachia   Population Affected: 14127   Crop Area: 2), (Barpeta   Population Affected: 852   Crop Area: 0), (Cheng   Population Affected: 57988   Crop Area: 433), (Baghbar   Population Affected: 61361   Crop Area: 1496.46) (Gohpur   Population Affected: 209   Crop Area: 14.7), (Halem   Population Affected: 18975   Crop Area: 0), (Biswanath   Population Affected: 0   Crop Area: 0) (Srijangram   Population Affected: 28664   Crop Area: 0), (Boitamari   Population Affected: 2583   Crop Area: 0) (Silchar   Population Affected: 25300   Crop Area: 0), (Katigorah   Population Affected: 144520   Crop Area: 0),							
And Crop Area Affected	Biswanat h Bongaiga on Cachar Charaide o	56543 1316 10701 60107	1059 10088 61007	en 33553 16809 10458 56814 14579	134328 19184 31247 177928	1931.46 14.7 0	(Kalgachia   Population Affected: 14127   Crop Area: 2), (Barpeta   Population Affected: 852   Crop Area: 0), (Cheng   Population Affected: 57988   Crop Area: 433), (Baghbar   Population Affected: 61361   Crop Area: 1496.46) (Gohpur   Population Affected: 209   Crop Area: 14.7), (Halem   Population Affected: 18975   Crop Area: 0), (Biswanath   Population Affected: 0   Crop Area: 0) (Srijangram   Population Affected: 28664   Crop Area: 0), (Boitamari   Population Affected: 2583   Crop Area: 0), (Silchar   Population Affected: 25300   Crop Area: 0), (Katigorah   Population Affected: 144520   Crop Area: 0), (Sonai   Population Affected: 8108   Crop Area: 0) (Mahmora   Population Affected: 49347   Crop Area: 290.9 (Sonari   Population Affected: 5212   Crop Area: 2.6), (Sapekhati   Population Affected: 954   Crop Area: 310)							
And Crop Area Affected	Biswanat h Bongaiga on Cachar Charaide o	56543 1316 10701 60107 23034	1059 10088 61007 19086	en 33553 16809 10458 56814 14579 788	134328 19184 31247 177928 56699	1931.46 14.7 0 0 603.5	(Kalgachia   Population Affected: 14127   Crop Area: 2), (Barpeta   Population Affected: 852   Crop Area: 0), (Chengle   Population Affected: 57988   Crop Area: 433), (Baghbar   Population Affected: 61361   Crop Area: 1496.46) (Gohpur   Population Affected: 209   Crop Area: 14.7), (Halem   Population Affected: 18975   Crop Area: 0), (Biswanath   Population Affected: 0   Crop Area: 0) (Srijangram   Population Affected: 28664   Crop Area: 0), (Boitamari   Population Affected: 2583   Crop Area: 0), (Katigorah   Population Affected: 144520   Crop Area: 0), (Sonai   Population Affected: 8108   Crop Area: 0), (Sonai   Population Affected: 49347   Crop Area: 290.9, (Sonari   Population Affected: 5212   Crop Area: 2.6), (Sapekhati   Population Affected: 2140   Crop Area: 310) (Bengtal   Population Affected: 954   Crop Area: 0), (Bijni   Population Affected: 1143   Crop Area: 0)							
And Crop Area Affected	Biswanat h Bongaiga on Cachar Charaide o	56543 1316 10701 60107 23034 636 76062	1059 10088 61007 19086 673 33521	en 33553 16809 10458 56814 14579 788	134328 19184 31247 177928 56699 2097	1931.46 14.7 0 0	(Kalgachia   Population Affected: 14127   Crop Area: 2), (Barpeta   Population Affected: 852   Crop Area: 0), (Chengle   Population Affected: 57988   Crop Area: 433), (Baghbar   Population Affected: 61361   Crop Area: 1496.46) (Gohpur   Population Affected: 209   Crop Area: 14.7), (Halem   Population Affected: 18975   Crop Area: 0), (Biswanath   Population Affected: 0   Crop Area: 0) (Srijangram   Population Affected: 28664   Crop Area: 0), (Boitamari   Population Affected: 2583   Crop Area: 0) (Silchar   Population Affected: 25300   Crop Area: 0), (Katigorah   Population Affected: 144520   Crop Area: 0), (Sonai   Population Affected: 8108   Crop Area: 0) (Mahmora   Population Affected: 49347   Crop Area: 290.9 (Sonari   Population Affected: 5212   Crop Area: 2.6), (Sapekhati   Population Affected: 954   Crop Area: 310)							





						1202.62), (Gogamukh   Population Affected: 3215   Area: 595), (Dhemaji   Population Affected: 1121   C Area: 433)
Dhubri	296950	288115	16072	754791	2198.46	·
Dhubri	290950	200113		/54/91	2198.46	(Dhubri   Population Affected: 192277   Crop Area:
			6			(Gauripur   Population Affected: 152216   Crop Are
						99.36), (Agamoni   Population Affected: 10320   Cro
						50), (Bilasipara   Population Affected: 38333   Crop
						(Golakganj   Population Affected: 32906   Crop Are
						208.4), (Chapar   Population Affected: 29425   Crop
						102), (South Salmara Part   Population Affected: 27
						Crop Area: 1184), (Athani   Population Affected: 273
						Crop Area: 373.5)
Dibrugar	11730	10261	6302	28293	3290.8	(Tingkhong   Population Affected: 962   Crop Area:
h						(Dibrugarh West   Population Affected: 6410   Crop
						2226), (Chabua   Population Affected: 3857   Crop
						55.6), (Moran   Population Affected: 10572   Crop A
						488), (Naharkatia   Population Affected: 2647   Cro
						7), (Dibrugarh East   Population Affected: 318   Cro
						170.7), (Tengakhat   Population Affected: 3527   Cr
						325.5)
Goalpara	31938	29800	22259	83997	1635.35	(Matia   Population Affected: 12784   Crop Area: 13
						(Lakhipur   Population Affected: 69075   Crop Area:
	1	1				(Balijana   Population Affected: 2138   Crop Area: 3
Calselier	F2C2C	45570	1244	112222	402	
Golaghat	<b>೨</b> ೮೮४	45570	13114	112322	493	(Bokakhat   Population Affected: 85761   Crop Area
	1	1				(Khumtai   Population Affected: 15960   Crop Area:
	1	1				(Dergaon   Population Affected: 10601   Crop Area:
Hailakan	2233	1899	842	4974	20	(Hailakandi   Population Affected: 1119   Crop Area
di	1	1				(Algapur   Population Affected: 3855   Crop Area: 2
	1	1				Population Affected: 0   Crop Area: 0), (Katlicherra
						Population Affected: 0   Crop Area: 0)
Hojai	682	542	519	1743	24	(Hojai   Population Affected: 286   Crop Area: 24), (
						Population Affected: 1457   Crop Area: 0)
Jorhat	10452	8934	6301	25687	8	(Teok   Population Affected: 3831   Crop Area: 0), (J
						East   Population Affected: 2190   Crop Area: 8), (Jo
						West   Population Affected: 19666   Crop Area: 0)
	F.C.1.0	4750	4707	12405	4042.24	
Kamrup	5610	4758	1737	12105	4012.21	(Chamaria   Population Affected: 0   Crop Area: 103
						(Kamalpur   Population Affected: 0   Crop Area: 97.
						(North Ghy   Population Affected: 0   Crop Area: 52
						(Goroimari   Population Affected: 6600   Crop Area
						(Palashbari   Population Affected: 4550   Crop Area
						(Rangia   Population Affected: 0   Crop Area: 56),
						(Nagarbera   Population Affected: 0   Crop Area: 32
						Population Affected: 955   Crop Area: 1300)
Kamrup	13655	9045	3906	26606	20	(Sonapur   Population Affected: 24878   Crop Area:
(M)	1	1				(Chandrapur   Population Affected: 1728   Crop Are
Karimga	14569	14195	11858	40622	0	(Nilambazar   Population Affected: 5100   Crop Are
nj						(Patherkandi   Population Affected: 445   Crop Area
,	1	1				
						(Karimganj   Population Affected: 19951   Crop Are
		1				(Badarpur   Population Affected: 15126   Crop Area
Kokrajha	11980	8142	12507	32629	19	(Bagribari   Population Affected: 31247   Crop Area
r	1	1				(Gossaigaon   Population Affected: 435   Crop Area
	1	1				(Dotma   Population Affected: 947   Crop Area: 0)
Lakhimp	20226	29372	8927	76625	732.5	(Bihpuria   Population Affected: 10597   Crop Area: 0)
	50320	23312	0527	, 5023	732.3	
ur	1	1				(Kadam   Population Affected: 7678   Crop Area: 0)
						(Subansiri   Population Affected: 0   Crop Area: 584
	1	1				(Nowboicha   Population Affected: 0   Crop Area: 0
	1	1				Lakhimpur   Population Affected: 58350   Crop Area
	1	1				(Narayanpur   Population Affected: 0   Crop Area: 0
N 4 a : ! ·	22050	22522	17001	72572	10754 35	
Majuli	32958	23523	1/091	73572	18751.35	(Majuli   Population Affected: 68227   Crop Area: 1
	1	1				(Ujani Majuli   Population Affected: 5345   Crop Are
	1	1				678.15)
L	23821	24663	22855	71339	1980	(Bhuragaon   Population Affected: 46717   Crop Are
Morigan		003		1 2000		(Morigaon   Population Affected: 40717   Crop Area
	1	1				, , , , , , , , , , , , , , , , , , , ,
Morigao n		1				(Mayong   Population Affected: 11245   Crop Area:
					1	Violatichat   Danilation Affactad, 6417   Cran Aras
_						(Lananghat   Population Affected: 6417   Crop Area
n	29460	24327	19315	73102	18858.3	
n	29460	24327	19315	73102	18858.3	(Kaliabor   Population Affected: 53010   Crop Area:
	29460	24327	19315	73102	18858.3	(Laharighat   Population Affected: 6417   Crop Area (Kaliabor   Population Affected: 53010   Crop Area: 14279.8), (Raha   Population Affected: 2494   Crop
n	29460	24327	19315	73102	18858.3	(Kaliabor   Population Affected: 53010   Crop Area:





	1	1		1	1	1		(Samaguri   Population Affected: 13904   Crop Area: 775.5),			
								(Nagaon   Population Affected: 13904   Crop Area: 775.5),			
	Nalbari	24260	22680	23300	70240	115		(Barkhetri   Population Affected: 70240   Crop Area: 115)			
	Sivasagar	21678	18959	11335	51972	705		(Nazira   Population Affected: 217   Crop Area: 0), (Sonari RC part   Population Affected: 110   Crop Area: 0), (Demow			
								Population Affected: 30452   Crop Area: 105), (Sivsagar			
								Population Affected: 21193   Crop Area: 600)			
	Sonitpur	n	0	0	0	140		(Tezpur   Population Affected: 0   Crop Area: 140),			
	Somtpui	ľ		١		140		(Dhekiajuli   Population Affected: 0   Crop Area: 0)			
	South	32758	34380	33788	100926	585		(South Salmara   Population Affected: 55561   Crop Area:			
	Salmara	32738	34300	33700	100320	565		585), (Mankachar   Population Affected: 45365   Crop Area:			
	Samuara							0)			
	Tinsukia	2339	1345	1256	4940	8556		(Doomdooma   Population Affected: 0   Crop Area: 0),			
	Imsuna	2333	13 13	1230	15 10	0330		(Sadiya   Population Affected: 0   Crop Area: 0), (Margherita			
								Population Affected: 4940   Crop Area: 8556)			
	Udalguri	0	0	0	0	0		(Harisinga   Population Affected: 0   Crop Area: 0), (Udalguri			
								Population Affected: 0   Crop Area: 0), (Khairabari			
								Population Affected: 0   Crop Area: 0), (Kalaigaon			
								Population Affected: 0   Crop Area: 0)			
	Total	922462	802319	54950	2274289	68432.75					
				8							
Relief	District	Total	Relief Camp				Relief Distribution	on Centres			
Camps /	Barpeta	18	1 (Kalgachia	a   0), (I	Barpeta   0), (Chenga	l 0),	17 (Kalgachia   0	0), (Barpeta   0), (Chenga   7), (Baghbar   10)			
Centres			(Baghbar		1 1 1 7 7 7 5	1 - 1/	, , ,	,, ( · ; · · · ·   · // ( · · · · · · · · · · · · · · · ·			
Opened	Biswanat	2			alem   0), (Biswanath	0)	2 (Gohpur   1), (	Halem   0), (Biswanath   1)			
	h			,,,	. " .	. ,		. ,,			
	Bongaiga	24	5 (Srijangra	m   0),	(Boitamari   5)		19 (Srijangram	19), (Boitamari   0)			
	on		' '	1 "	,		-5 (5.13.1.8) and 1 25/1 (55/16/16/16/11   0)				
	Cachar	105	62 (Silchar	42), (k	Katigorah   13), (Sonai	i   7)	43 (Silchar   25), (Katigorah   17), (Sonai   1)				
	Charaide	24	-		Sonari   1), (Sapekhat			5), (Sonari   13), (Sapekhati   0)			
	0		0 (	a   5// (	20.1a   2,, (Superman	0/	20 (	5)) (55).dir   25)) (54)pe.maa   5)			
	Chirang 13 5 (Bengtal   0), (Bijni   5)						8 (Bengtal   3), (	Bijni   5)			
	Darrang							, (Pub-Mangaldai   1), (Dalgaon   0), (Mangaldoi   7)			
	Darrang	13	(Mangaldoi		as mangalaar   0), (5)	aigaoii   o <sub>jj</sub>	,13 (3)pajilai   3/,	, (i de Mangaldar   1), (edigaen   0), (Mangalder   7)			
	Dhemaji	11			), (Jonai   1), (Gogam	ukh   0).	10 (Sissiborgaon	0), (Jonai   10), (Gogamukh   0), (Dhemaji   0)			
	'		(Dhemaji		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	. "					
	Dhubri	39	19 (Dhubri	16), (0	Gauripur   2), (Agamo	ni   0),	20 (Dhubri   1), (Gauripur   0), (Agamoni   1), (Bilasipara   7), (Golakganj				
					olakganj   0), (Chapar		(Chapar   10), (South Salmara Part   0), (Athani   0)				
			(South Salm	nara Pa	rt   0), (Athani   0)						
	Dibrugar	48						5), (Dibrugarh West   2), (Chabua   2), (Moran   0),			
	h		0), (Morai	n   4), (	Naharkatia   2), (Dibr	ugarh East	(Naharkatia   0), (Dibrugarh East   0), (Tengakhat   10)				
			0), (Tenga								
	Goalpara	14	13 (Matia	3), (Lal	khipur   0), (Balijana	10)	1 (Matia   1), (Lakhipur   0), (Balijana   0)				
	Golaghat	25	12 (Bokakha	at   12)	, (Khumtai   0), (Derg	aon   0)	13 (Bokakhat   4	l), (Khumtai   2), (Dergaon   7)			
	Hailakan		-		(Algapur   2), (Lala   0			), (Algapur   2), (Lala   0), (Katlicherra   0)			
	di		(Katlicherra	. ,,			· ·				
	Hojai	6	6 (Hojai   2)	), (Dob	oka   4)		0 (Hojai   0), (Do	oboka   0)			
		4	0 (Teok   0)	, (Jorha	nt East   0), (Jorhat W	est   0)	4 (Teok   0), (Jor	hat East   0), (Jorhat West   4)			
	Kamrup	18						, (Kamalpur   0), (North Ghy   0), (Goroimari   1), (Palashbari			
					alashbari   3), (Rangia			, (Nagarbera   2), (Hajo   3)			
			(Nagarbera			. "	. ,, , , 3.2   0/				
	Kamrup	0	_		handrapur   0)		0 (Sonapur I 0).	(Chandrapur   0)			
	(M)			. ,, ,-	,			· · ·			
	Karimga	51	43 (Nilamba	azar   1	3), (Patherkandi   0),	(Karimgani	8 (Nilambazar   0	0), (Patherkandi   0), (Karimganj   6), (Badarpur   2)			
	nj		21), (Bada					2 22 2 2 7 7			
	Kokrajha	6	3 (Bagribari	i   2), (d	Gossaigaon   0), (Dotn	na   1)	3 (Bagribari   0),	(Gossaigaon   1), (Dotma   2)			
	r										
	Lakhimp	12	0 (Bihpuria	0), (K	adam   0), (Subansiri	0),	12 (Bihpuria   1)	, (Kadam   4), (Subansiri   0), (Nowboicha   0), (North			
	ur		(Nowboicha	a   0), (I	North Lakhimpur   0),	,	Lakhimpur   1), (	(Narayanpur   6)			
			(Narayanpu	ır   0)			<u> </u>				
	Majuli	44	1 (Majuli   :	1), (Uja	ni Majuli   0)		43 (Majuli   43), (Ujani Majuli   0)				
	Morigao	26	0 (Bhuragad	on   0),	(Morigaon   0), (May	ong   0),					
	n		(Laharighat	0)	• • •	-	1	<del>-</del> · · ·			
	Nagaon	33	21 (Kaliabo	r   8), (I	Raha   4), (Dhing   2),	, (Kampur	ampur   12 (Kaliabor   8), (Raha   0), (Dhing   0), (Kampur   0), (Samaguri   3),				
			0), (Samagu	ıri   2),	(Nagaon   5)		(Nagaon   1)				
	Nalbari	1	1 (Barkhetri	i   1)			0 (Barkhetri   0)				
	1	1	1 (barkhetii   1)				U (Barkhetri   0)				





	Sivasagar	35	6 (Nazira   2), (Sonari RC part   0), (Dem (Sivsagar   4)	ow   0),	29 (Nazira   0), (Sonari RC part   0), (Demow   11), (Sivsagar   18)						
	Sonitpur	0	0 (Tezpur   0), (Dhekiajuli   0)		0 (Tezpur   0), (Dhekiajuli   0)						
		26	1 (South Salmara   0), (Mankachar   1)		25 (South Sal	mara   8), (Mai	nkachar   17)				
	Salmara										
	Tinsukia	23	18 (Doomdooma   0), (Sadiya   1), (Mar <sub>1</sub> 17)	gherita	5 (Doomdooma   5), (Sadiya   0), (Margherita   0)						
	Udalguri		0 (Harisinga   0), (Udalguri   0), (Khairab (Kalaigaon   0)	ari   0),	0 (Harisinga   0), (Udalguri   0), (Khairabari   0), (Kalaigaon   0)						
	Total	630	269		361						
Inmates In Relief	District	Total	Revenue Circlewise	Male	Female	Children	Lactating	Person with Disability			
Camps	Barpeta	173	(Kalgachia   0), (Barpeta   0), (Chenga   0), (Baghbar   173)	65	66	42	Mother 0	0			
	Biswanat	0	(Gohpur   0), (Halem   0), (Biswanath	0	0	0	0	0			
	Bongaiga	2583	(Srijangram   0), (Boitamari   2583)	896	878	747	60	2			
	on Cachar	16859	(Silchar   14483), (Katigorah   2030), (Sonai   346)	6371	6135	4341	12	0			
	Charaide o	1065		401	455	191	14	4			
	Chirang	1050	(Bengtal   0), (Bijni   1050)	329	327	353	39	2			
		0	(Sipajhar   0), (Pub-Mangaldai   0), (Dalgaon   0), (Mangaldoi   0)	0	0	0	0	0			
	Dhemaji	105	(Sissiborgaon   0), (Jonai   105), (Gogamukh   0), (Dhemaji   0)	30	28	40	7	0			
	Dhubri 4320 (Dhubri   3907), (Gauripur   270), (Agamoni   0), (Bilasipara   143), (Golakganj   0), (Chapar   0), (South			1460	1742	1115	3	0			
	Dibrugar h	2613	(Tingkhong   377), (Dibrugarh West   767), (Chabua   0), (Moran   250), (Naharkatia   357), (Dibrugarh East   0), (Tengakhat   862)	1043	979	517	37	37			
	Goalpara	4493	(Matia   2375), (Lakhipur   0), (Balijana   2118)	1307	1788	1392	5	1			
	Golaghat	4305	(Bokakhat   4305), (Khumtai   0), (Dergaon   0)	1915	1914	462	11	3			
	Hailakan di	924	(Hailakandi   207), (Algapur   717), (Lala   0), (Katlicherra   0)	360	372	191	1	0			
	Hojai	273	(Hojai   118), (Doboka   155)	131	90	52	0	0			
	Jorhat	0	(Teok   0), (Jorhat East   0), (Jorhat West   0)	0	0	0	0	0			
	Kamrup	1248	(Chamaria   0), (Kamalpur   0), (North Ghy   0), (Goroimari   0), (Palashbari   293), (Rangia   0), (Nagarbera   0), (Hajo   955)	476	575	182	13	2			
	Kamrup (M)		(Sonapur   0), (Chandrapur   0)	0	0	0	0	0			
	Karimga nj		(Karimganj   2510), (Badarpur   591)	1431	1195	921	5	0			
	Kokrajha r		(Dotma   406)	184	164	125	0	0			
	Lakhimp ur	U	(Bihpuria   0), (Kadam   0), (Subansiri   0), (Nowboicha   0), (North Lakhimpur   0), (Narayanpur   0)	O	0	0	0	0			
	Majuli	24	(Majuli   24), (Ujani Majuli   0)	8	5	11	0	0			
	Morigao n	Morigao 0 (Bhuragaon   0), (Morigaon   0), (Mayong   0), (Laharighat   0) (Nagaon 5820 (Kaliabor   3595), (Raha   527), (Dhing 219), (Kampur   0), (Samaguri   484), (Nagaon   995)			0	0	0	0			
	Nagaon				2052	1434	77	2			
	Nalbari	43	(Barkhetri   43)	21	11	11	0	0			
	Sivasagar	809	(Nazira   53), (Sonari RC part   0), (Demow   0), (Sivsagar   756)	287	336	164	20	2			





	Sonitpur	0	(Tezpur   0), (Dhekiajuli   0)	0	0	0	0	0			
		175	(South Salmara   0), (Mankachar   175)	54	57	57	5	2			
	Salmara Tinsukia	2782	(Doomdooma   0), (Sadiya   11),	1341	833	608	0	0			
	Udalguri	0	(Margherita   2771) (Harisinga   0), (Udalguri   0),	0	0	0	0	0			
			(Khairabari   0), (Kalaigaon   0)								
N C		53689		20365	20002	12956	309	57			
Non Camp Inmates in		Total	Revenue Circlewise	Male	Female	Children	Big		nals ultry		
Relief	Barpeta	0	(Kalgachia   0), (Barpeta   0), (Chenga	n	0	0	32718	248040	uitiy		
Distributio	bai peta		0), (Baghbar   0)	Ĭ		Ĭ	52710	240040			
n Centers	Biswanat h	209	(Gohpur   209), (Halem   0), (Biswanath	108	72	29	911	80010			
	Bongaiga on	28664	(Srijangram   28664), (Boitamari   0)	9803	9150	9711	0	00			
	Cachar	63981	(Silchar   44306), (Katigorah   18800), (Sonai   875)	16772	20470	26739	0	00			
	Charaide o	11301	(Mahmora   2253), (Sonari   9048), (Sapekhati   0)	5739	4630	932	0	00			
	Chirang	1047	(Bengtal   954), (Bijni   93)	299	314	434	789	9100			
	Darrang	24499	(Sipajhar   0), (Pub-Mangaldai   19206), (Dalgaon   0), (Mangaldoi   5293)	11962	8641	3896	12615	52490			
	Dhemaji	15292	(Sissiborgaon   0), (Jonai   15292), (Gogamukh   0), (Dhemaji   0)	6143	5799	3350	1337	12050			
	Dhubri	42787	(Dhubri   5144), (Gauripur   0), (Agamoni   5718), (Bilasipara   0), (Golakganj   2500), (Chapar   29425), (South Salmara Part   0), (Athani   0)	19523	16240	7024	14565	60620			
	Dibrugar h	3734	(Tingkhong   458), (Dibrugarh West   1762), (Chabua   0), (Moran   0), (Naharkatia   0), (Dibrugarh East   0), (Tengakhat   1514)	1512	1263	959	13870	16180			
	Goalpara	569	(Matia   569), (Lakhipur   0), (Balijana   0)	192	170	207	0	00			
	Golaghat	25107	(Bokakhat   6790), (Khumtai   7716), (Dergaon   10601)	11052	10389	3666	10694	64070			
	Hailakan di	1979	(Hailakandi   80), (Algapur   1899), (Lala   0), (Katlicherra   0)	900	835	244	0	00			
	Hojai	0	(Hojai   0), (Doboka   0)	0	0	0	0	00			
	Jorhat	1417	West   1417)	622	364	431	0	00			
	Kamrup	0	(Chamaria   0), (Kamalpur   0), (North Ghy   0), (Goroimari   0), (Palashbari   0), (Rangia   0), (Nagarbera   0), (Hajo   0)	O	0	O	70971	391060			
	Kamrup (M)	0	(Sonapur   0), (Chandrapur   0)	0	0	0	0	00			
	Karimga nj		(Karimganj   18383), (Badarpur   1247)	8344	7105	4181	0	00			
	Kokrajha r		(Dotma   541)	339	348	289	0	00			
	Lakhimp ur	8658	(Bihpuria   980), (Kadam   7678), (Subansiri   0), (Nowboicha   0), (North Lakhimpur   0), (Narayanpur   0)	2340	3415	2903	6903	52850			
	Majuli	0	(Majuli   0), (Ujani Majuli   0)	0	0	0	16171	88610			
	Morigao n	49821	(Bhuragaon   46717), (Morigaon   2235), (Mayong   869), (Laharighat   0)	16610	17553	15658	5194	752545	4		
	Nagaon	4460		1760	1687	1013	0	00			
	Nalbari	(Nagaon   69)  (Barkhetri   0)		0	0	0	0	00			
	Sivasagar	vasagar 7600 (Nazira   0), (Sonari RC part   0), (Demow   844), (Sivsagar   6756)		3183	3251	1166	0	00			
	6onitpur 0 (Tezpur   0), (Dhekiajuli   0)			0	0	0	0	00			
		0	(South Salmara   0), (Mankachar   0)	0	0	0	79065	504660			
	Salmara										





	Tinsukia	3789	(Doomdooma   3789), (Sadiya   0), (Margherita   0)		1450	1413	926	10778	2330	2114					
	Udalguri	0	(Harisinga	0), (Ud	lalguri   0), alaigaon   0)	0	0	0	0	0	0				
	Total	315520	(	1 - // (		118653	113109	83758	276581	160628	2578				
Human	District	Total	Male	Femal	Children		Others	Revenue C	Revenue Circlewise						
Lives Lost -				e	Male	Female									
Confirmed	Kamrup	0	0	0	0	0	0	0 (Chamari	a   0), (Kamal	pur   0), (	North Ghy   0), (Goroimari				
											(Nagarbera   0), (Hajo   0)				
	Nagaon	0	0	0	0	0	0		0), (Raha     0), (Nagaon		0), (Kampur   0),				
	Cachar	1	1	0	0	0	0		1), (Katigorah		nai   0)				
	Dhubri	2	1	0	0	1	0		0), (Chapar		amoni   0), (Bilasipara   1), th Salmara Part   0),				
	Goalpara	1	1	0	0	0	0	1 (Matia   0	0), (Lakhipur	0), (Balij	ana   1)				
	Morigao	0	0	0	0	0	0	0 (Bhuraga	on   0), (Mori	gaon   0)	, (Mayong   0), (Laharighat				
	n							0)							
	Hailakan di	0	0	0	0	0	0				ala   0), (Katlicherra   0)				
	Bongaiga on	0	0	0	0	0	0	0 (Srijangra	ım   0), (Boita	ımari   0)					
	Udalguri	0	0	0	0	0	0	0 (Harisinga 0)	a   0), (Udalgı	uri   0), (K	hairabari   0), (Kalaigaon				
	South Salmara	0	0	0	0	0	0	0 (South Sa	lmara   0), (N	/lankacha	r   0)				
	Dibrugar h	0	0	0	o	0	0		), (Naharkatia		ot   0), (Chabua   0), orugarh East   0),				
	Karimga nj	0	0	0	0	0	0	0 (Nilamba (Badarpur		erkandi	0), (Karimganj   0),				
	Lakhimp ur	0	0	0	0	0	0	0 (Bihpuria			ansiri   0), (Nowboicha				
	Hojai	0	0	0	0	0	0		), (Doboka   (						
	_	2	0	0	1	1	0	2 (Barkhetr		<u>,                                      </u>					
	Charaide o	0	0	0	0	0	0	0 (Mahmor	ra   0), (Sonar	i   0), (Sa <sub>l</sub>	pekhati   0)				
	Biswanat h	0	0	0	0	0	0	0 (Gohpur	0), (Halem	0), (Biswa	anath   0)				
	Golaghat	0	0	0	0	0	0	0 (Bokakha	t   0), (Khumi	tai   0), (D	ergaon   0)				
	Jorhat	0	0	_	0	0	0		), (Jorhat East						
	Dhemaji	1	1		0	0	0				ogamukh   1), (Dhemaji				
	Barpeta	0	0	0	0	0	0	0 (Kalgachi	a   0). (Barpe	ta   0). (C	henga   0), (Baghbar   0)				
	Sonitpur		0	0	0	0	0		0), (Dhekiaju		3 1 1 1,7 ( 18 11 1 1 1 1				
	Kokrajha r		0	0	0	0	0		i   0), (Gossai		(Dotma   0)				
	' Majuli	0	0	0	0	0	0	0 (Maiuli l	0), (Ujani Maj	juli l 0)					
	Kamrup (M)		0	0	0	0	0		0), (Chandr						
	Darrang	0	0	0	0	0	0			ingaldai	0), (Dalgaon   0),				
	Sivasagar	1	1	0	0	0	0	1 (Nazira	(Mangaldoi   0)  1 (Nazira   0), (Sonari RC part   0), (Demow   0), (Sivsagar						
	Tinsukia	0	0	0	0	0	0		1) 0 (Doomdooma   0), (Sadiya   0), (Margherita   0)						
	Chirang		0		0	0	0	0 (Bengtal   0), (Bijni   0)							
		8	5		1	2	0	Congrai	, <i>2),</i> (2), 11   0	<u>,                                      </u>					
		Total	Male	Femal	Children	Ľ	Others	Revenue C	Revenue Circlewise						
Lives Lost -		2.2.7		e	Male	Female	+								
	Kamrup	0	0	0	0	0	0		0 (Chamaria   0), (Kamalpur   0), (North Ghy   0), (Goroima   0), (Palashbari   0), (Rangia   0), (Nagarbera   0), (Hajo   0						
	Nagaon	0	0	0	0	0	0	0 (Kaliabor		0), (Dhing	0), (Kampur   0),				
	Cachar	0	0	0	0	0	0	0 (Silchar   0), (Katigorah   0), (Sonai   0)							
L	L	l	<u> </u>	<u> </u>	<u> </u>		<u>I</u>	P (Shehar   0), (Naugoran   0), (Sonal   0)							





Golakganj   O), (Chapar   O), (South Salmara Part   O),   Althani   O	-				_				
Scalpara D		Dhubri	0	0	0	o	0	0	
Marigan   0		Goalnara	n	n	0	0	h	0	
National   Colorable   Color						-			
Bi		n							[ 0)
December   December			0	0	0	0	0	0	0 (Hailakandi   0), (Algapur   0), (Lala   0), (Katlicherra   0)
South   D			0	0	0	0	0	0	0 (Srijangram   0), (Boitamari   0)
South O D D D D D D D D D D D D D D D D D D		Udalguri	0	0	0	0	0	0	
Dibrugar   D.   D.   D.   D.   D.   D.   D.   D			0	0	0	0	0	0	,
Norman   N			0	0	0	0	6		0 /Tingkhang   0) /Dibrugarh West   0) /Chabua   0)
Karimga   D		h	O		U	O	U		(Moran   0), (Naharkatia   0), (Dibrugarh East   0),
Section   Description   Desc			0	0	0	0	0	0	0 (Nilambazar   0), (Patherkandi   0), (Karimganj   0),
Hojai   D		Lakhimp	0	0	0	0	0	0	0 (Bihpuria   0), (Kadam   0), (Subansiri   0), (Nowboicha
Naibari   D			0	0	0	0	0	0	
Charalde									
Designate   Desi									
Normation   Norm		О							
Dorhard   D		Biswanat h	0	0	0	0	0	0	0 (Gohpur   0), (Halem   0), (Biswanath   0)
Dhemaji   Dhem		Golaghat	0	0	0	0	0	0	0 (Bokakhat   0), (Khumtai   0), (Dergaon   0)
Sarpeta		Jorhat	0	0	0	0	0	0	0 (Teok   0), (Jorhat East   0), (Jorhat West   0)
Sonitpur   O		Dhemaji	0	0	0	0	0	0	0 (Sissiborgaon   0), (Jonai   0), (Gogamukh   0), (Dhemaji
Sonitpur   O	-	Barneta	0	0	0	0	0	0	0 (Kalgachia   0), (Barneta   0), (Chenga   0), (Baghbar   0)
Kokrajha   0						0	0		
Majuli   0						_			
Karrup D (M) Darrang O D O D O D O D O O D O O O O O O O O		r							
(M) Darrang 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			0						
Sivasagar   Composition   Co			0			0	0	0	
Finsukia   Company   Com				0	0	0	0	0	(Mangaldoi   0)
Chirang 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Sivasagar	0	0	0	0	0	0	
Total   D		Tinsukia	0	0	0	0	0	0	0 (Doomdooma   0), (Sadiya   0), (Margherita   0)
Total   D		Chirang	0	0	0	0	0	0	
Animals Affected  Barpeta 164362 69146 50134 45082  Biswanat 7358 4313 3045 0  Bongaiga 0 0 0 0 0 0  Cachar 0 0 0 0 0  Charaide 15622 5348 4224 6050  Chirang 1699 789 910 0  Darrang 83124 43589 24890 14645  Dhemaji 36864 27546 9318 0  Dhubri 316102 193338 12276 0  Dhubri 316102 193338 12276 0  Au  Dibrugar 24729 18214 6515 0  Goalpara 84677 49499 23622 11556  Golaghat 27916 17649 10267 0  Hailakan 492 181 81 230				0	0	0	0	0	, , , , , , , , , , , , , , , , , , ,
Affected Barpeta 164362 69146 50134 45082 Biswanat 7358 4313 3045 0 Bongaiga 0 0 0 0 0 0 Cachar 0 0 0 0 0 Charaide 15622 5348 4224 6050 O Chirang 1699 789 910 0 Darrang 83124 43589 24890 14645 Dhemaji 36864 27546 9318 0 Dhubri 316102 193338 12276 0 Dibrugar Afree 1754 6515 0 Goalpara 84677 49499 23622 11556 Golaghat 27916 17649 10267 0 Hailakan 492 181 81 230	Animals		Total		Small	Poultry			
Biswanat 7358	Affected					=			
on Cachar 0 0 0 0 0 Charaide 15622 5348 4224 6050									
Cachar 0 0 0 0 0 Charaide 15622 5348 4224 6050			0	0	0	0			
Charaide 15622 5348 4224 6050 Chirang 1699 789 910 0 Darrang 83124 43589 24890 14645 Dhemaji 36864 27546 9318 0 Dhubri 316102 193338 12276 0 4 Dibrugar 24729 18214 6515 0 Goalpara 84677 49499 23622 11556 Golaghat 27916 17649 10267 0 Hailakan 492 181 81 230			0	n	0	0			
o       Chirang       1699       789       910       0         Darrang       83124       43589       24890       14645         Dhemaji       36864       27546       9318       0         Dhubri       316102       193338       12276       0         A       0       4       0         Dibrugar       24729       18214       6515       0         Goalpara       84677       49499       23622       11556         Golaghat       27916       17649       10267       0         Hailakan       492       181       81       230						6050			
Darrang       83124       43589       24890       14645         Dhemaji       36864       27546       9318       0         Dhubri       316102       193338       12276       0         4       0       0       4         Dibrugar       24729       18214       6515       0         Goalpara       84677       49499       23622       11556         Golaghat       27916       17649       10267       0         Hailakan       492       181       81       230		О							
Dhemaji       36864       27546       9318       0         Dhubri       316102       193338       12276       0         Dibrugar       24729       18214       6515       0         h       Goalpara       84677       49499       23622       11556         Golaghat       27916       17649       10267       0         Hailakan       492       181       81       230			1			*			
Dhubri 316102 193338 12276 0 4					_				
A									
h Goalpara 84677 49499 23622 11556 Golaghat 27916 17649 10267 0 Hailakan 492 181 81 230		Dhubri	316102	193338	4				
Golaghat 27916 17649 10267 0 Hailakan 492 181 81 230		Dibrugar h	24729	18214	6515	0			
Golaghat 27916 17649 10267 0 Hailakan 492 181 81 230		Goalpara	84677	49499	23622	11556			
Hailakan 492 181 81 230									





		1	1		
		0	0		0
		22412	15555		0
	Kamrup	217392	141010	75882	500
	Kamrup (M)	29066	14391	14675	0
	Karimga nj	0	0	0	0
	Kokrajha r	19813	12375	6638	800
	Lakhimp ur	42605	27326	15279	0
		41299	26766	6313	8220
	Morigao		27552	24447	
	Nagaon	66587	40629	18791	7167
		25044			0
	Sivasagar		45808	18967	
	Sonitpur		12833	10520	
		134433		51708	
	Salmara				
	Tinsukia		10778		2114
	Udalguri		0		0
				7	142875
Animals		Total			Poultry
Washed		1	0	1	0
Away	Biswanat h		0	0	0
	Bongaiga on		0		0
	Cachar	0	0	0	0
	Charaide o	0	0	0	0
		0	0	0	0
	Darrang		0	0	0
	Dhemaji	0	0	0	0
	Dhubri	0	0	0	0
	Dibrugar h	9	8	1	0
	Goalpara	0	0	0	0
	Golaghat	142	42	100	0
	Hailakan di	0	0	0	0
	Hojai	0	0	0	0
	Jorhat	0	0	0	0
	Kamrup	0	0	0	o
	Kamrup (M)	0	0	0	0
	Karimga nj	0	0	0	0
	Kokrajha r	0	0	0	0
	Lakhimp ur	0	0	0	0
	Majuli	22	8	14	0
	Morigao n	1	1	0	0
	Nagaon	39	0	39	o
		0	0	0	o
	Sivasagar		0		0
	Sonitpur		0		0
		0	0		0
	Tinsukia	0	0	0	0





	Udalguri	h	О	0	0			
					<b>0</b>			
Houses			Fully Pukka			Partially	Partially Pukka	Partially Total
Damaged		Kuccha	rully rukka	rully I	otai	Kuccha	raitially rukka	raitially local
		0	0	0		0	0	0
		0	0	0		0	0	0
		0	0	0		0	0	0
	Dhubri	19	0	19		112	23	135
	Goalpara	0	0	0		0	0	0
	Morigao	0	0	0		0	0	0
	n							
	Hailakan 	0	0	0		0	0	0
	di Dangaiga	0	0	0		0	0	
	Bongaiga on	U	U	U		U	O	0
	Udalguri	0	0	0		17	0	17
		0	0	0		0	0	0
	Salmara							
	Dibrugar	0	0	0		0	0	0
	h							
	Karimga	0	0	0		0	0	0
	nj	0				0	<u></u>	
	Lakhimp	U	0	0		0	0	0
	ur Hojai	0	0	0		0	0	0
	1 -			0		0	0	0
	Charaide		0	0		0	0	0
	0	ľ		U				
	Biswanat	0	0	0		0	0	0
	h							
	Golaghat	1	0	1		3	0	3
	Jorhat	0	0	0		0	0	0
	Dhemaji	0	0	0		0	0	0
	Barpeta	0	0	0		0	0	0
	Sonitpur	0	0	0		0	0	0
	Kokrajha	0	0	0		0	0	0
	r							
		0		0		0	0	0
	Kamrup	О	0	0		0	0	0
	(M)	0	0	0		0	0	
	Darrang			0			0	0
	Sivasagar			0		17	0	17
	Tinsukia			0		0	0	0
	Chirang <b>Total</b>			2 <b>22</b>		149	0 <b>23</b>	0
Houses		Others Hu			Others Cattle Shed	143	23	Others Total
	Kamrup				0			0
Others	Nagaon				0			0
		0			0			0
		51			42			93
	Goalpara				42 0			0
	Goalpara Morigao				0			0
	n	<u> </u>						
	Hailakan	0			0			0
	di							
	Bongaiga	0			0			0
	on							
1	Udalguri				0			0
		0			0			0
	Salmara							
	Dibrugar	U			0			0
	n Karimga	0			0			0
	nj	Ĭ						
	6. با	1						





	Lakhimp	0	0		0				
	ur Hojai	0	0		0				
	Nalbari	0	0		0				
	Charaide		0		0				
	0				Ĭ				
	Biswanat h	0	0		0				
	Golaghat	1	0		1				
		0	0		0				
	Dhemaji	0	0		0				
		0	0		0				
	Sonitpur	0	0		0				
	Kokrajha		0		0				
	r Majuli	0	0		0				
	Kamrup	0	0		0				
	(M)								
	Darrang	0	0		0				
	Sivasagar	0	0		0				
	Tinsukia	0	0		0				
	Chirang	0	0		0				
	Total	52	42		94				
Rescue	District	Agency	Other Agencies Involved					Helicopt	Person
Operation				Deployed			Evacuat		Evacuated By
								Deploye	Helicopters
	Develo			1	11			d	2
	Barpeta			1		0		-	0
	Biswanat h			C	0	0	0	0	0
		Circle Office/Local		2	36	0	0	0	0
		Administration							
		SDRF		28		0			0
	Charaide o	SDRF		8	1	52	0	0	0
	Chirang			0		0	0	0	0
		Circle Office/Local		7	32	0	0	0	0
		Administration							
	Dhemaji			1		_			0
		Circle Office/Local Administration		35			J	J	0
		Civil Defence/Trained Volunteers, NDRF, SDRF		60	3	17	217	0	0
	Goalpara	Local People		3	15	0	0	0	0
	Golaghat			3	0	0	0	0	0
	Hailakan di			C	0	0	0	0	0
	Hojai			C	0	0	0	0	0
	Jorhat			10	0	0	0	0	0
	Kamrup			O	0	0	0	0	0
	Kamrup			O	0	0	0	0	0
	(M) Karimga			C	0	0	0	0	0
	nj				U	0	١	١	U
	Kokrajha r			C	0	0	0	0	0
	Lakhimp			C	0	0	0	0	0
	ur Majuli			C	0	0	0	0	0
		Local People		7		0			0
	n								
	Nagaon		0	10					0
		Local People		C					0
	Sivasagar			6		1	0		0
	Sonitpur			0	0	0	0	0	0





Tin Ud <b>To</b>	nsukia	Administra Circle Offic Administra	ce/Local				40	0	0				
Ud <b>To</b> Relief <b>Dis</b>	dalguri						40	0	0	0		-	
To Relief Dis	dalguri	Administra	ation				18	1 4	Y	U		0	0
To Relief Dis													
Relief Dis	otal						0	_	0	0		0	0
			1				212		70	459		0	0
d		Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Feed -	Cattle Feed - Wheat Bran (in Q)	Cattle Feed -	Rice Bran (ir	ıQ)			
Ba	arpeta	0	0	0	0		1250	0					
L	iswanat		0.42	0	0	0	65	0					
h													
Bo on	ongaiga n	470.89	88.43	26.54	2653.22	0	0	0					
Ca	achar	1673	313.09	89.4	8940	0	0	0					
Ch	haraide	125.04	22.77	6.85	684.99	0	0	0					
Ch	hirang	25.65	4.83	1.45	144.8	40	36.99	0					
	arrang		76.5		2294.45		0	1899.61					
l —	hemaji		43.82		1380.96		71.05	0					
			142.94		4287.99		6038.23	0					
	ibrugar		28.8		185		264.82	0					
h					•								
Go	oalpara	34.72	7.23	3.7	157.7	0	120	120					
Go	olaghat	755.34	137.65	41.11	1966.18	0	0	580.84					
На	ailakan	35.65	6.83	2.04	204.09	0	65	0					
di													
Но	ojai	0	0	0	0	0	0	0					
Jor	rhat	22.92	3.23	1.01	100.5	0	261.13	0					
Ka	amrup	11.4	1.63	0.5	49	0	4176.25	0					
Ka (M	amrup ⁄I)	0	0	0	0	0	0	0					
Ka nj	arimga	328.09	60.38	18.16	1816.4	0	0	0					
Ko r	okrajha	14.39	2.79	0.84	83.91	0	0	0					
Lal ur	akhimp r	138.43	25.97	7.79	779	0	69.3	800					
Ma	lajuli	0	0	0	0	0	993.5	0					
Mo	lorigao	554.25	103.12	30.93	3093.61	0	504	0					
Na	agaon	87.21	13.57	3.98	14.55	0	483.82	0					
			0.09		2.58		0	0					
	vasagar		49.27	14.78			0	0					
	onitpur		0		0		14.91	0					
So		0	0		0		0	0					
	nsukia	162.36	29.09	8.76	292.7	0	301.7	0					
	dalguri		0		0		0	0					
			1162.45	_	29168.63			3400.45					
Relief Dis	istrict	Baby Food	Liquid		ood Solid	Others							
Distribute Ba	arpeta		-1,000		0.00-Kg								
d - Others Bis	iswanat				et, 0.00-Kg		ablet-1100.00-No	s, Bleaching I	Powder-300.0	0-Kg, N	1ineral	Water-	4000.00-Ltr.,
h Bo	ongaiga	0.00-Kg, 4	50.00-Pkt	0.00-Kg	g, 67.00-Pkt		ur-22.50-Kg, Chee				-Pck., S	anitary	Napkins-
on							.00-Pck., Charger Light-13.00-Nos, Candle-50.00-Pcs						
							Cheera-122.10-Kg, Sanitary Napkins-258.00-Pck., Juggery/Gur-37.90-Kg						
О		106.60-Kg,			(g, 0.00-L								
Ch	=					1 -	238.00-Pcs, Mosq 18.00-Pck., Candle	-		ch Box-	1760.0	0-Pcs, S	Sanitary





	Darrang	0.00-Kg, 0 Pkt	).00-L, 0.00-	0.00-Kg, 0.00-Pkt	Tarpaulin-	4975.00-Pcs						
	Dhemaji	0.00-Kg		0.00-Pieces	Juggery/Gi	ur-21.78-Kg, Tarp	aulin-66.00-Pcs, Soap-	-98.00-Pck.				
		0.00-Kg, 0 0.00-L, 0.0 Pieces	0.00-ml, 00-Pkt, 0.00-	0.00-L, 0.00-Pieces, 0.00-Kg, 0.00-Pkt	Tarpaulin-!	5479.00-Pcs, Can	dle-300.00-Pcs, Match	Box-300.00	)-Pcs			
	Dibrugar h	371.20-L		661.80-Kg	Tarpaulin-: 45.00-Pck.	· ·	ary Napkins-508.00-Pc	ck., Candle-4	100.00-Pc	s, Mosquito Coil-		
	Goalpara	0.00-Kg, C	).00-L	0.00-Kg, 0.00-Pkt	Bleaching	Powder-190.00-k	(g, Mineral Water-2840	0.00-Ltr., Ha	logen Ta	blet-25000.00-Nos		
		0.00-Kg, 0 0.00-L	).00-Pkt,	, ,		cs, Mosquito Net	•	quito Coil-3385.00-Pck., Match Box- ary Napkins-440.00-Pck., Mineral Water-				
	Hailakan di	445.00-Pk	t	21.00-Pkt		· ·	lle-786.00-Pcs, Sanitary uito Coil-92.00-Pck.	y Napkins-2	20.00-Pck	c., Phenyl-23.00-		
	Hojai											
	Jorhat	0.00-L, 0.0	00-Kg	0.00-Kg, 0.00-L								
	Kamrup Kamrup	55.00-Pkt 0.00-Kg	, 0.00-L,	0.00-Pkt, 0.00-Kg, 0.00-Q	Tarpaulin-670.00-Pcs, Cheera-318.00-Kg, Juggery/Gur-55.00-Kg, C Sanitary Napkins-30.00-Pck., Mosquito Coil-30.00-Pck.				Kg, Candl	e-180.00-Pcs,		
	(M)											
	Karimga nj	0.00-Kg, 8	80.00-Pkt		Biscuits-65 Pck.	5.00-Pck., Candle	-55.00-Pcs, Mosquito C	Coil-30.00-P	ck., Sanita	ary Napkins-50.00-		
	Kokrajha r	0.00-ml, 0	).00-Kg	2.00-Pkt, 0.00-Kg	Biscuits-15.00-Pck., Candle-50.00-Pcs, Match Box-35.00-Pcs, Soap-10.00-Pck., Mosquito Coil-5.00-Pck.							
	Lakhimp ur	0.00-Q, 0. Kg	00-ml, 0.00-	0.00-Q, 1324.00-Pkt, 0.00- Kg	Biscuits-180.00-Pck., HTW-5.00-Nos							
	Majuli	0.00-L		0.00-L								
	Morigao n	0.00-L, 0.0	00-Q	· •	HTW-60.00-Nos, Tarpaulin-430.00-Pcs, Cheera-12494.91-Kg, Juggery/Gur-629.55-Kg Bleaching Powder-100.00-Kg, Halogen Tablet-1500.00-Nos, Mineral Water-1000.00 kt Candle-1633.00-Pcs, Bleaching Powder-130.00-Kg, Cheera-216.60-Kg, Sanitary Napl							
	Nagaon	192.80-L			147.00-Pcl	k., Juggery/Gur-8 00-Pck., Dustbin-	ning Powder-130.00-Kg 4.70-Kg, Tarpaulin-140 9.00-Nos, Mosquito Ne	0.00-Pcs, Ph	enyl-1685	5.00-Ltr., Mosquito		
	Nalbari	0.00-Pkt		0.00-Pkt								
				0.00-Kg, 0.00-L		4.00-Pcs, Match I ulin-80.00-Pcs	Box-372.00-Pcs, Mosqu	uito Coil-374	1.00-Pck.,	Phenyl-104.00-		
	Sonitpur	0.00-L		0.00-L								
	South Salmara	0.00-Piece	es, 0.00-L	0.00-Pieces, 0.00-Kg	Tarpaulin-:	2504.00-Pcs, HTV	V-217.00-Nos, Sanitary	/ Napkins-12				
	Tinsukia	1.80-L		0.00-Kg, 9.00-Pieces	Cheera-3.60-Kg, Juggery/Gur-0.90-Kg, Fruits-0.90-Kg							
	Udalguri											
Infrastruct ure		Number	Revenue Circle		Departme nt	Village	Location	Longitu de	Latitude	Remarks		
Damaged - Road	Barpeta	11	(Kalgachia 0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil		
			(Barpeta   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil		
			(Chenga   2)	Mahchara Hollongapara NC Road	PWD (Roads)	Mahchara K	Mahchara	91.07	26.15	Received from PWRD on		
				Mahchara Changbandha NC	DWD	Kachumara K	Kachumara	01.07	26.15	06.07.2024 Received from		
				Road	(Roads)	NdCHullidid N	Kachumara	91.07	20.13	PWRD on 06.07.2024		
			(Baghbar   9)	Pkg No.As-01-211	PWD (Roads)	Chaysimana NC	via Rahmania MEM			As reported by PWD roads dept		
										on 03/07/24 side berm and Hard crust damaged,breach occurred,washed away on Paschim Chaysimana to Baladmari via Rahmania MEM road (PMGSY Pkg No.AS-01-211) location		





	1	1		1	<u> </u>		linates
						26.14	linates- 543
						90.96	
		Pkg No-AS-01-242	PWD	Agmandia	Near Agarjan beel		orted by
		J	(Roads)				roads dept
							/07/24 side
							and Hard
						crust	
							ged,breach
							red on
							aan beel to
							iyapara (PMGSY Pkg
							5-01-242).
		Pkg No-AS-01-270	PWD	1 No	way to 3 No Baghmara		orted by
			(Roads)	Baghmarachar			roads dept
				NC			/07/24 side
						berm	and Hard
						crust	
							ged,breach
							red on 1 no
						to 3 N	
							mara char (PMGSY Pkg
							(PIVIGSY PKg 5-01-270)
						locatio	
							linates-
						26.10	
						90.88	
		Pkg No-AS-01-267	PWD	kapoha	via Dapnashing	As rep	oorted by
			(Roads)				roads dept
							/07/24 side
							and Hard
						crust	
							ged,breach red on 4 No
							oloni to
						Kapol	
							asingh road
							SY Pkg
							5-01-267).
		Pkg No-AS-01-280	PWD	Morabhaj Gaon	Near Indiara Nagar	As rep	oorted by
			(Roads)				roads dept
							/07/24 side
							and Hard
						crust	
							ged,breach
							red,washed on Indira
						Nagar	
							bhaj road
							SY Pkg
							5-01-280)
						location	on
							linates-
						26.24	
				<u> </u>		90.85	
		Pkg.No-AS-01-331	PWD	Satrakanara NC	Near Barakata chariali		ported by
			(Roads)				roads dept
							/07/24 side
						crust	and Hard
[	ĺ	1		1			
							UDO Droach
							ged,breach
						occur	red on
						occur Barak	red on ata Chariali
						occur Barak to 4 N	red on





	1	I,	Pkg No.AS-01-281	PWD	Mand:-	Near Marsdis CD - ff: -			As reported by
				(Roads)	Mandia Bardolini NC	Near Mandia GP office			PWD roads dept on 03/07/24 side berm and Hard crust damaged,breach occurred, Culvert damaged on Mandia GP office to 2 No Bardoloni road (PMGSY Pkg No.AS-01-281) location coordinates- 26.263749, 90.948207.
				PWD (Roads)		Way to Bhageshwari			As reported by PWD roads dept on 03/07/24 side berm and Hard crust damaged,breach occurred on Satrakanara12 to Bhageshwari road (PMGSY Pkg No.AS-01-259) location coordinates-26.245687, 90.89473.
			Pkg No-AS-01-241	PWD (Roads)	Agmandia	via ED bund			As reported by PWD roads dept on 03/07/24 side berm and Hard crust damaged,breach occurred on Agmandia chariali to Mandia gaon via ED road (PMGSY Pkg No.AS-01-241).
Biswana h	1)		Kharoi Bundh to Nabill village Road		BHERBHERI PATHAR	From Ch. 400.00 m to Ch.650.00 m (approx)		26.86	As reported yesterday evening the hard crust of Kharoi Bundh to Nabill village Road from Ch. 400.00 m to Ch.650.00 m has been damaged partially by the flood water of river Solengi in the evening of 05-07-2024
		alem   0) iswanath		Nil Nil	Nil Nil			Nil Nil	Nil Nil
	] (	0)							
Bongaig on	a 2 (Si		Borigaon Merechar Road	PWD (Roads)	Borigaon	Borigaon	90.71	26.28	Road submerged at 7th and 8th KM and side berm eroded. as per report received from PWRD, Dated- 0707.2024





			Borjana Pt-I to Borjana Pt-III Road (PMGSY Package No. AS-02-151)	PWD (Roads)	Barjana Pt-I	Barjana Pt. I	90.67	26.26	Side berm eroded and hard crust also damaged at several stretches. as per report received from PWRD, Dated- 0707.2024
	l l		Nil	Nil	Nil	Nil	Nil	Nil	Nil
Cachar		0) Silchar   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	l —							Nil	Nil
		0)							
	(5			(Roads)	– XV	Sonai Motinagar	92.89		Submerged Ch 3150 to Ch 3740.00m, Depth of Submergnce 0.5m to 0.9m, Shoulders and Hard Crust in stretches damaged One Box Culvert at Ch 1550.00m damaged. as reported by EE Sonai Dholai T Road division, on dated 07.07.2024
			Swadhin Bazar to LRA Road via Dubrikandi		Dungripar Part – I			24.71	Submerged Ch 1650.00m to Ch 1700.00m, Depth of Submergnce 0.3m to 0.50m, Road formation eroded, Shoulders and Hard crust in stretches damaged as reported by EE Sonai Dholai T Road division, on dated 07.07.2024
			Road	(Roads)	Mohanpur Part – II	Dakshin Mohanpur Pt-II	92.89		Submerged Ch 50 to Ch 850.00m, Depth of Submergnce 0.3m to 0.75m, Road formation eroded as reported by EE Sonai Dholai T Road division, on dated 07.07.2024
			Road from Govindanagar Bazar point to KK Road Ph-II		Gobindanagar Part – II	Gobindanagar Pt-II	92.92	24.71	Submerged Ch 630.00m to Ch 2050.00m, Depth of Submergnce 1.2m to 1.75m, Road formation eroded, Shoulders and Hard crust in stretches damaged as reported by EE Sonai Dholai T





									Road division, on dated 07.07.202
			Sonai to Sanaibarighat Road	PWD (Roads)	Sonabarighat Part – II	Sonabarighat Pt-II	92.84	24.75	Submerged Ch 5630 to Ch 5850.00m, Depth of Submergnce 0.3m to 0.65m, Shoulders and Hard crust in stretches damaged as reported by EE Sonai Dholai T Road division, or
Charaide	0 (Ma		Nil	Nil	Nil	Nil	Nil	Nil	dated 07.07.202 Nil
O	. ,	nari   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
				Nil	Nil	Nil		Nil	Nil
	[ 0)								
Chirang	0)	0 1	Nil	Nil	Nil	Nil	Nil	Nil	Nil
				Nil	Nil	Nil		Nil	Nil
Darrang	0)	, ,		Nil	Nil	Nil		Nil	Nil
	(Pub Mar   0)	ngaldai	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	(Dal 0)	lgaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	(Ma   0)	angaldoi	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dhemaji	6 (Siss on	2)	Sissikalghar to Deorighat, Brahmaputra (from Ch- 100579.00 m to Ch- 107879.00 m)	PWD (Roads)	SissikalGhar	At different locations.	94.67		Ramps are severely damaged and side shoulder eroded. Extend of damaged is 1800.00 m. Population effected is 25500. Dated, 30-06-2024 to 06-07-2024.
			RCC Br.No 1/1 over Ghagra on the road from No-2 Phulbari to Zepoo Basti.	PWD (Roads)	GhagaraAadi	Protection work and Approach of Br.No. 1/1	94.73	27.64	Protection work and Approach is eroded. Extend of damage is 100.00 M. Population effected is 7500 Dated on 06-07- 2024
	(Jon	nai   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	(Goç	gamukh	SBG road from Bordoloni to Khalihamari road	PWD (Roads)	Kalita Gubhuriyal	At Ch.110.00m and at Ch 1370.00 M to Ch 2600.00 M	94.77	27.6	Culvert over Kalita gavorialja and Road different stretches of road damage,d Lengt around 1230 Meters on 07-07
	(Dhe 3)		,, ,	PWD (Roads)	No. 1 Karmipathar	At Ch 2550.00 M to Ch 2700.00 M	94.58	27.3	Road damaged a Ch 2550.00 M to Ch 2700.00 M, Length around





									150 Meters on 07-07-2024
			Road	PWD (Roads)	Puwasaikia	At Ch.2550.00m	94.492		Culvert over Kalakatajan damaged . Date 05/07/2024
			Laguabora to Burabhakat Road	PWD (Roads)	Chengamari	Ch 2100.00 M to Ch 3000.00 M	94.482	27.34	Culvert over Dulungjan and Chengamarijan damaged. Length around 900 Meters on 07-07- 2024
Dhu	ıbri 108	(Dhubri   41)	Kachuarkhas Pt-I to Kachuarkhas Pt-II Road ,	PWD (Roads)		Kachuarkhas Pt-I to Kachuarkhas Pt-II Road			Kachuarkhas Pt-I to Kachuarkhas Pt-II Road , side berm erroded at 1st km to 5th km in stretches Damaged Due to flood Date of incident 05/07/2024 to 06/07/2024
			Burimari	PWD (Roads)	Kismathasdaha Pt.II	Kalahat			Gauripur Kalahat Road to Burimari Providing bamboo foot bridge Damaged Due to flood Date of incident 05/07/2024 to 06/07/2024
				PWD (Roads)	Gewmari	Kismathadaha Pt-II to Ghewmari BSF Camp Road,			Kismathadaha Pt- II to Ghewmari BSF Camp Road, Road side berm erroded at 1st km to 7th km in stretches Damaged Due to flood Date of incident 05/07/2024 to 06/07/2024
			Kismathasdaha to Tistarpar M.V.School via Pachchim Dharmasala Road ,	PWD (Roads)	Tistarpar	Kismathasdaha to Tistarpar M.V.School via Pachchim Dharmasala Road			Kismathasdaha to Tistarpar M.V.School via Pachchim Dharmasala Road , Side berm erroded and hard crust damaged at 1st km to 5th km in stretches) Damaged Due to flood Date of incident 05/07/2024 to 06/07/2024
			Rajakatlidham Kismathasdaha to Dharmasala Pt-V Road	PWD (Roads)	Kismathasdaha Pt.II	Rajakatlidham Kismathasdaha to Dharmasala Pt-V			Rajakatlidham Kismathasdaha to Dharmasala Pt-V Road , Side berm erroded and damaged badly at 1st km to 5th km in





					stretches
					Damaged Due to
					flood
					Date of incident
					05/07/2024 to
	Dhubri Tistarpar ( Bidyapara	DWD	Tistarpar	Dhubri Tistarpar (	06/07/2024
	Pr-II ) to Tistarpar ( Bidyapara	(Roads)	ı ıstaı þai	Bidyapara Pr-II ) to	Dhubri Tistarpar ( Bidyapara Pr-II )
	i i i j to ristarpai Noau ,	, roaus)		Tistarpar Road	to Tistarpar Road
					, Side berm
					erroded at 1st
					km to 5th km in
					stretches
					Damaged Due to
					flood Date of incident
					05/07/2024 to
					06/07/2024 to
	Dhubri Patamari Road ,	PWD	Patamari	Dhubri Patamari Road	Dhubri Patamari
	· · · · · · · · · · · · · · · · · · ·	(Roads)			Road ,Road side
		,			berm erroded at
					6th km to 11th
					km in stretches
					Damaged Due to
					flood Date of incident
					05/07/2024 to
					06/07/2024 to
	Durahati PWD Road to	PWD	Durahati	Durahati PWD Road to	Durahati PWD
	Baladoba Parghat Road,	(Roads)		Baladoba Parghat Road	Road to Baladoba
		,			Parghat Road,
					side berm
					erroded and hard
					crust damaged at
					1st km to 4th km
					in stretches Damaged Due to
					flood
					Date of incident
					05/07/2024 to
					06/07/2024
		PWD	Binnachara Pt.I	Dhubri Binnachara Road	14th Km of
	Binnachara Road to	(Roads)		to Tistarpar BADP Road	Dhubri
	Tistarpar BADP Road,				Binnachara Road
					to Tistarpar BADP
					Road , Road side berm erroded
					and Road
					formation
					damaged badly
					at 1st km to 3rrd
					km in stretches
					Damaged Due to
					flood
					Date of incident
					05/07/2024 to
	Dhubri Gauripur Road	PWD	Falimari Pt.I.	Dhubri Gauripur Road	06/07/2024 Dhubri Gauripur
	Dilubii Gauripui Nodu	(Roads)	ramman Ft.I.	Dirabit Gauripul Nodu	Road submerged
		,			in some
					Stretches at 1st,
					2nd and 3rd Km
					and several
					leakage occurred
					at 5th qnd 6th
					Km
					Damaged Due to
					flood
					Date of incident





						05/07/2	
		Dharmasala Kachuarkhas	PWD	Dharmasala Pt.V	Dharmacala	06/07/2 Dharma	
		PWD Road Near to	(Roads)	Dilaiiiiasala Pt. V	Kachuarkhas PWD Road	Kachuar	
		Kachuarkhas Pt-II ,	(maus)		Near to Kachuarkhas Pt-		ad Near
		Raemaarkiias i e ii ,			II	to Kachı	
						Pt-II , Sic	
						erroded	
						km to 6t	th km in
						stretche	
							ed Due to
						flood	
							incident
						05/07/2	
		NS Road submerged Ch.	PWD	Dhubri Town	NS Road	06/07/2 NS Road	
		100.00m to 900.00m	(Roads)	khasmahal	NS Rodu	submer	
		100.00111 10 300.00111	(Nodus)	Kilasillallal		100.00m	
						900.00m	
						Damage	ed Due to
						flood	
							incident
						05/07/2	
						06/07/2	
		Road from Tistarpar PWD	PWD	Tistarpar	Road from Tistarpar	Road fro	
		Road to Durahati PWD Road	(Roads)		PWD Road to Durahat	Tistarpa	
		,					Durahati ad , side
						berm er	
						and sub	
							l water of
							er mighty
						Brahma	putra at
						1st to 3r	
							ed Due to
						flood	
							incident
						05/07/2	
		Motirchar Dharmasala Road	4DWD	Sagolchara Pt.I	Motirchar	06/07/2 Motirch	
		to Howrarpar village road	(Roads)	Sagoichara Ft.i	iviotii ciiai		isala Road
		to nowraipar vinage road	(Nodus)			to Howr	
						village re	-
						bridge N	
						and 3/1	
						approac	
						damage	
						including	
						berm er	oded ed Due to
						flood	ים שמה נס
							incident
						05/07/2	
						06/07/2	
		Vimalpur to pestirpar road	PWD	Durahati	pestirpar road	Vimalpu	
			(Roads)			pestirpa	
						submerg	
						side ber	
						damage	
						2nd Km	
							ed Due to
						flood	incido+
						Date of 1 05/07/2	incident
						06/07/2	
	ı		1	1	Character PCF accorde	Road fro	
		Road from Ghewmari BSF	PW/D	Gewmari	(Inewmari KXF camp to 1		nm .
		Road from Ghewmari BSF camp to Dubirpar Road	PWD (Roads)	Gewmari	Ghewmari BSF camp to Dubirpar Road		
		Road from Ghewmari BSF camp to Dubirpar Road	PWD (Roads)	Gewmari	Dubirpar Road	Ghewma	





	<del>                                     </del>	1		_	1			
								pproaches of
								RCC Bridge No.
								./1 badly eroded
								Damaged Due to
								lood
								Date of incident
								05/07/2024 to
								06/07/2024
			3rd Km of DB Road to	PWD	Rowa Pt.I	Rowa		ard Km of DB
			Rowah Pt-II (Baroghoripara	(Roads)				Road to Rowah
			) road					Pt-II
								Baroghoripara )
								oad submerged
								nd side at 1st
								ind 2nd Km
								Damaged Due to
								lood
								Date of incident
								05/07/2024 to
								06/07/2024
			Kalahat Ghewmari Road to		Gewmari	Kalahat Ghewmari Road		(alahat
			Velakoba Road ,	(Roads)		to Velakoba Road		Shewmari Road
								o Velakoba Road
							ı r	side berm
							I I	erroded at 1st
								m to 5th km in
								tretches
								Damaged Due to
								lood
								Date of incident
								05/07/2024 to
				51115	v 1 11	10. 11. 11. 11.		06/07/2024
			Kismathasdaha Pt-I to	PWD	Kachuarkhas	Kismathasdaha Pt-I to		(ismathasdaha
			Kacuarkhas Pt-II Road,	(Roads)	Pt.II	Kacuarkhas Pt-II Road,		Pt-I to
								(acuarkhas Pt-II
								Road, Side berm
								erroded and
								lamaged badly It 1st km to 4th
								m in stretches
								Damaged Due to lood
								Date of incident 05/07/2024 to
								06/07/2024 to
			Dhubri Patamari PWD Road	1 DWD	Patamari	Dhubri Patamari PWD		Ohubri Patamari
			to Dharmasala Road		r ataillall	Road to Dharmasala		WD Road to
			to pilatiliasaia koad	(Roads)		Road to Dharmasala Road		איט אסמט נס Dharmasala Road
						ivoau		it 1st to 5th Km
								n stretches
								Damaged Due to
								lood
								Date of incident
								05/07/2024 to
								06/07/2024 to
			Durahati Tistarpar Road to	PWD	Durahati	Durahati Tistarpar Road		Ourahati
					Duranau	to Char Durahati L.P		
			Char Durahati L.P School, Road	(Roads)		School		istarpar Road to Char Durahati L.P
			nodu			BUIDUI		
								school, Road side berm erroded at
								st km to 6th km
								n stretches
								Damaged Due to
								lood
								Date of incident
								05/07/2024 to 06/07/2024
1			Character and the least of	DWD	Dhuk -: Tarri	Charmain		
Ī			Charmain road submerged	PWD	Dhubri Town	Charmain road	l C	Charmain road
			from ch. 0.00m to 800.00m	(Doods)	khasmahal		l_	ubmerged from





	ch. 0.00m to
	800.00m Damaged Due to
	flood Date of incident
	05/07/2024 to 06/07/2024
2nd km of Kacharihat PWD Dharmasala Pt.V Dharmasala	2nd km of
Dhepdhepi Road to (Roads) Soulmari Bazar Road	Kacharihat Dhepdhepi Road
	to Soulmari Bazar Road approaches
	of RCC Bridge No.
	1/1 and 2/1 badly eroded
	Damaged Due to flood
	Date of incident
	05/07/2024 to 06/07/2024
Dharmasala to Durahati via PWD Dharmasala Pt.II Dharmasala Dharmasala Police out post (Roads)	Dharmasala to Durahati via
road (Roads)	Dharmasala
	Police out post road Bridge
	approaches of
	RCC Bridge No. 1/1 and 2/1
	badly eroded Damaged Due to
	flood
	Date of incident 05/07/2024 to
Bridge approaches of RCC PWD Binnachara Pt.I Binnachara	06/07/2024 Bridge
Bridge No. 12/1 and 13/1 (Roads)	approaches of
on Kanuri Dimakuri Road	RCC Bridge No. 12/1 and 13/1 on
	Kanuri Dimakuri Road are badly
	damaged.
	Damaged Due to flood
	Date of incident 05/07/2024 to
	06/07/2024
Kachuarkhas Pt-I PWD Road PWD Kachuarkhas Pt.I PwD Road PWD Kachuarkhas Pt.I Kachuarkhas Pt	
High School to Chandakhola Memorial High Scho	ool Umaruddin Memorial High
beel, Nodu	School to
	Chandakhola Beel, Road side
	berm erroded
	and Road formation
	damaged badly at 1st km to 7th
	km in stretches
	Damaged Due to flood
	Date of incident 05/07/2024 to
	06/07/2024
Kismathasdaha Pt-I to PWD Kismathasdaha Kismathasdaha Pt-I Kacuarkhas Pt-II Road, (Roads) Pt.I Kacuarkhas Pt-II Ro	
	Kacuarkhas Pt-II Road, Side berm
	erroded and





	<u> </u>	1	1	1	1	1	т.	
								amaged badly t 1st km to 4th
								m in stretches
								amaged Due to
								ood
								ate of incident
								5/07/2024 to
								6/07/2024
			Bridge approaches of RCC	PWD	Binnachara Pt.III	Binnachara		ridge
			Bridge No. 5/1 and 7/1 on	(Roads)			а	pproaches of
			Kanuri Dimakuri road				R	CC Bridge No.
								/1 and 7/1 on
								anuri Dimakuri
								oad are badly
								roded
								amaged Due to
								ate of incident
								5/07/2024 to
								6/07/2024
			Motirchar Dharmasala Road	PWD	SagolcharaPt.II	Motirchar Dharmasala		Notirchar
			to Howrarpar village road	(Roads)		Road to Howrarpar		harmasala Road
				[		village		) Howrarpar
							vi	illage road
								ridge No. 2/1
								nd 3/1
								pproaches
								amaged
								ncluding side
								erm eroded
								amaged Due to
								ate of incident
								5/07/2024 to
								6/07/2024
			Kachuarkhas Pt-I PWD Road	PWD	Kachuarkhas Pt.I	Kachuarkhas Pt-I PWD		achuarkhas Pt-I
				(Roads)		Road near Umaruddin		WD Road near
			High School to Chandakhola			Memorial High School	U	maruddin
			Beel, Road				N	1emorial High
							S	chool to
								handakhola
								eel, Road side
								erm erroded
								nd Road
								ormation
								amaged badly t 1st km to 7th
								m in stretches
								amaged Due to
								ood
								ate of incident
							o	5/07/2024 to
								6/07/2024
			Dhubri Patamari PWD Road	PWD	Patamari	Dhubri Patamari PWD	D	hubri Patamari
			to Dharmasala Road	(Roads)		Road to Dharmasala		WD Road to
1								
						Road		harmasala Road
						Road	a	harmasala Road t 1st to 5th Km
						Road	a ir	harmasala Road t 1st to 5th Km n stretches
						Road	a ir D	harmasala Road t 1st to 5th Km n stretches amaged Due to
						Road	a ir D fl	harmasala Road t 1st to 5th Km n stretches amaged Due to ood
						Road	a ir D fl D	harmasala Road t 1st to 5th Km n stretches ramaged Due to ood ate of incident
						Road	a ir D fl D 0	harmasala Road t 1st to 5th Km n stretches ramaged Due to ood ate of incident 5/07/2024 to
			1ST VM OF DUADAASSALA	DWD	Dharmacala		a ir D fl D 0 0	harmasala Road t 1st to 5th Km n stretches ramaged Due to ood rate of incident 5/07/2024 to 6/07/2024
				PWD (Roads)	Dharmasala	Road  Dharmasala	a ir D fl D 0 0	tharmasala Road t 1st to 5th Km in stretches lamaged Due to lood ate of incident 5/07/2024 to 6/07/2024 ST KM OF
			DURAHATI ROAD TO	PWD (Roads)	Dharmasala Pt.III		a ir D ffl D 0 0	harmasala Road t 1st to 5th Km i stretches lamaged Due to lood late of incident 5/07/2024 to 6/07/2024 ST KM OF HARMASALA
			DURAHATI ROAD TO VELAKOBA VIA SINGIMARI				a ir D ffl D 0 0	harmasala Road t 1st to 5th Km i stretches amaged Due to ood ate of incident 5/07/2024 to 6/07/2024 ST KM OF HARMASALA URAHATI ROAD
			DURAHATI ROAD TO				a ir D ffl D 0 0 1 D D	tharmasala Road t 1st to 5th Km in stretches lamaged Due to lood late of incident 5/07/2024 to 6/07/2024 ST KM OF HARMASALA





	1	, ,			ı	<u> </u>	
							5TH KM ROAD
							SIDE BERM
							ERRODED,
							BRIDGE APPROACHES OF
							RCC BRIDGE NO.
							3/1 DAMAGED
							BY FLOOD
							WATER
							Damaged Due to
							flood
							Date of incident
							05/07/2024 to
							06/07/2024
			Dharmasala Kachuarkha	s PWD	Dharmasala Pt.V	/Dharmasala	Dharmasala
			PWD Road Near to	(Roads)		Kachuarkhas PWD Road	Kachuarkhas
			Kachuarkhas Pt-II ,			Near to Kachuarkhas Pt-	PWD Road Near
						II	to Kachuarkhas
							Pt-II , Side berm
							erroded at 1st
							km to 6th km in
							stretches
							Damaged Due to flood
							Date of incident
							05/07/2024 to
							06/07/2024
			Gauripur Kalahat Road to	o PWD	Kismathasdaha	Kalahat	Gauripur Kalahat
			Burimari Providing bamb		Pt.I	Kalariat	Road to Burimari
			foot bridge	(110000)			Providing
			ğ				bamboo foot
							bridge
							Damaged Due to
							flood
							Date of incident
							05/07/2024 to
							06/07/2024
			Kalahat Ghewmari Road		Bhelakoba	Kalahat Ghewmari Road	Kalahat
			Velakoba Road ,	(Roads)		to Velakoba Road	Ghewmari Road
							to Velakoba Road , side berm
							erroded at 1st
							km to 5th km in
							stretches
							Damaged Due to
							flood
							Date of incident
							05/07/2024 to
							06/07/2024
			Kalahat to Durahati	PWD	Durahati	Kalahat to Durahati	Kalahat to
			Tistarpar Road via	(Roads)		Tistarpar	Durahati
			Kacharihat Bazar				Tistarpar Road
							via Kacharihat
							Bazar Bridge
							approaches of
							RCC Bridge No.
							9/1, 10/1 and
							12/1 badly eroded
							Pamaged Due to
							flood
							Date of incident
							05/07/2024 to
							06/07/2024
			Durahati Tistarpar Road	to PWD	Durahati	Durahati	Durahati
			Char Durahati L.P School				Tistarpar Road to
Ī	1	1	Road	ĺ			Char Durahati L.P
1						·	
			1.000				School, Road side





				1st km to 6th km in stretches Damaged Due to flood Date of incident 05/07/2024 to
42. KALAHAT GHEWMARI ROAD TO DURAHATI VIA VELAKOBA ROAD	PWD (Roads)	Gewmari	GHEWMARI	06/07/2024  42. KALAHAT GHEWMARI ROAD TO DURAHATI VIA VELAKOBA ROAD AT 1ST TO 4TH KM AND bridge No. 1/1 approaches damaged including side berm eroded Damaged Due to flood Date of incident 05/07/2024 to
DHARMASALA PWD ROAI TO KISMATHASDAHA PT-I ROAD		Kismathasdaha Pt.II	DHARMASALA PWD ROAD TO KISMATHASDAHA PT-II	DS/07/2024 to 06/07/2024  DHARMASALA PWD ROAD TO KISMATHASDAHA PT-II ROAD AT 1ST TO 5TH KM IN STRETCHES Damaged Due to flood Date of incident 05/07/2024 to 06/07/2024
DHARMASALA PWD ROAI TO KISMATHASHDADA PT BINNACHARA PWD ROAD	T-II (Roads)	Kismathasdaha Pt.II	DHARMASALA PWD ROAD TO KISMATHASHDADA PT-II	DHARMASALA PWD ROAD TO KISMATHASHDA DA PT-II BINNACHARA PWD ROAD Damaged Due to flood Date of incident 05/07/2024 to 06/07/2024
GASPARA BAZAR TO MOTIRCHAR BUND CUM ROAD AT 1ST TO 6TH KM ROAD	PWD (Roads)	Gaspara	Gaspara	GASPARA BAZAR TO MOTIRCHAR BUND CUM ROAD AT 1ST TO 6TH KM ROAD SIDE BERM ERRODAED BY FLOOD WATER OF MIGHTLY BRAHMAPUTRA RIVER Damaged Due to flood Date of incident 05/07/2024 to 06/07/2024
(Gauripur   NH 17to Sarkarpara 14)	PWD (Roads)	GauripurTown Pt.III	NH 17to Sarkarpara	NH 17to Sarkarpara at 1st km under Gauripur Revenue circle ( Road submerged) Damaged due to





					flood Date of
					Incident- 5-7-24
					to 6-7-24
	3rd KM OF ALAMGANJ	PWD	Selairparpt.I	ALAMGANJ SILAIRPAR	3rd KM OF
	SILAIRPAR ROAD TO	(Roads)		ROAD TO	ALAMGANJ
	SYMSARENERKUTI			SYMSARENERKUTI	SILAIRPAR ROAD TO
					SYMSARENERKUT
					I AT 1ST KM (
					ROAD
					SUBMERGED
					,SIDE BERM
					DAMAGED
					,BRIDGE
					APPROACHES
					DAMAGE OF
					BRIDGE NO 1/1)
					Damaged due to flood Date of
					Incident- 5-7-24
					to 6-7-24
	ASHARIKANDI BAZAR TO	PWD	Asarikhandi	ASHARIKANDI BAZAR TO	ASHARIKANDI
	KANAIMORE	(Roads)	Jankiala	KANAIMORE	BAZAR TO
	I Suvuivione	(			KANAIMORE AT
					3RD AND 4TH KM
					( SIDE BERM
					ERODED )
					Damaged due to
					flood Date of
					Incident- 5-7-24
					to 6-7-24
	Lawokhowa embankment		Chapgarh Pt.I	Chapgarh	Lawokhowa
	to Khudimari via Chapgarh	(Roads)			embankment to
	High School				Khudimari via
					Chapgarh High School at 2nd to
					4th km under
					Damaged due to
					flood Date of
					Incident- 5-7-24
					to 6-7-24
	GHAGERALGA ROAD , BUG	6 PWD	Ghegeralga. Pt.I	GHAGERALGA ROAD ,	GHAGERALGA
	BRIDGE TO BORAIBARI	(Roads)		BUG BRIDGE TO	ROAD , BUG
				BORAIBARI	BRIDGE TO
					BORAIBARI (
					SUBMERGED
					AND SIDE BERM DAMAGED )
					Damaged due to
					flood Date of
					Incident- 5-7-24
					to 6-7-24
1 1	ALOMGANG TO FULKATAI		Alomganj Pt.IV	ALOMGANG TO	ALOMGANG TO
	ROAD	(Roads)		FULKATARI ROAD	FULKATARI ROAD
					FROM 1ST KM TO
					4TH KM UNDER
					GAURIPUR
					GAURIPUR REVENUE CIRCLE
					GAURIPUR REVENUE CIRCLE ( ROAD SIDE
					GAURIPUR REVENUE CIRCLE ( ROAD SIDE BERM AND
					GAURIPUR REVENUE CIRCLE ( ROAD SIDE BERM AND BRIDGE
					GAURIPUR REVENUE CIRCLE ( ROAD SIDE BERM AND BRIDGE APPROACHES
					GAURIPUR REVENUE CIRCLE ( ROAD SIDE BERM AND BRIDGE APPROACHES DAMAGED)
					GAURIPUR REVENUE CIRCLE ( ROAD SIDE BERM AND BRIDGE APPROACHES DAMAGED) Damaged due to
					GAURIPUR REVENUE CIRCLE ( ROAD SIDE BERM AND BRIDGE APPROACHES





 1	1	1		
KHUDIMARI TO GAURIPUR BASHBARI ROAD	PWD (Roads)	Khudimari pt.I	KHUDIMARI TO GAURIPUR BASHBARI ROAD	KHUDIMARI TO GAURIPUR BASHBARI ROAD AT 1ST AND 2ND KM ( SIDE BERM AND HARD CRUST DAMAGED ) Damaged due to flood Date of
ASHARIKANDI GAURIPUR BEPARIPATTY ROAD	PWD (Roads)	Geramari Pt.IV	ASHARIKANDI GAURIPUR BEPARIPATTY ROAD	Incident- 5-7-24 to 6-7-24 ASHARIKANDI GAURIPUR BEPARIPATTY ROAD (FROM GERAMARI PART- IV ,KANAIMORE TO BEGUNTOLI
				AT 1ST AND 2ND KM ( ROAD SUBMERGED ,SIDE BERM DAMAGED) Damaged due to flood Date of Incident- 5-7-24 to 6-7-24
HINDUPARA TO BEGUNTOL BUG	(Roads)	Geramari Pt.II	HINDUPARA TO BEGUNTOLI	HINDUPARA TO BEGUNTOLI BUG AT 1ST AND 2ND KM SIDE BERM ERODED Damaged due to flood Date of Incident- 5-7-24 to 6-7-24
ALOMGANG BAZAR TO SILAIRPAR	PWD (Roads)	Selairparpt.I	ALOMGANG BAZAR TO SILAIRPAR	ALOMGANG BAZAR TO SILAIRPAR AT 2ND TO 4TH KM UNDER GAURIPUR REVENUE CIRCLE (SIDE BERM ERODED ) Damaged due to flood Date of Incident- 5-7-24 to 6-7-24
PANBARI TO CHITALKATI ROAD	PWD (Roads)	Alomganj Pt.VII	PANBARI TO CHITALKATI ROAD	PANBARI TO CHITALKATI ROAD AT 2ND TO RTH KM UNDER GAURIPUR REVENUE CIRCLE ( SIDE BERM DAMAGED ) Damaged due to flood Date of Incident- 5-7-24 to 6-7-24
Lawokhowa embankment to Khudimari via Chapgarh High School	PWD (Roads)	Chapgarh Pt.I	Lawokhowa embankment to Khudimari via Chapgarh	Lawokhowa embankment to Khudimari via Chapgarh High School at 2nd to 4th km under Gauripur





			Γ	1	Revenue Circle
					Side berm
					damaged )
					Damaged due t flood Date of
					Incident- 5-7-24
					to 6-7-24
BRIDGE APPROACHES OF PW		Alomganj Pt.IX	alomganj		BRIDGE
	oads)				APPROACHES C
THENGMALA BAZAR ROAD					BRIDGE NO 1/1 ON THENGMAL
					BAZAR ROAD
					Damaged due t
					flood Date of
					Incident- 5-7-24
NH17 to Sarkarpara PW	VD G	GauripurTown	NH17 to Sarkarpara		to 6-7-24 NH17 to
		Pt.III	iviii / to Sarkarpara		Sarkarpara at 1
					km under
					Gauripur
					Revenue circle Road submerge
					NH17 to
					Sarkarpara Date
					of Incident- 5-7
(Assessed I DV DOAD NEAD CIDGLE	<u> </u>	(aldoba Pt 3	KALDODA DART III	26.262	24 to 6-7-24
(Agamoni   PK ROAD NEAR CIRCLE PW 10) OFFICE TO KALDOBA PART (Ro.	VD K pads)	kaidopa Pt 3	KALDOBA PART III	26.289	9.8 SIDE SHOULDEI and CORE
III ROAD	Jaasj				DAMAGED AT F
					ROAD NEAR
					CIRCLE OFFICE
					TO KALDOBA PART III ROAD
					due to heavy
					rainfall. Date of
					Incident from 3
HALAKURA RAIL GATE TO PW	VD 1	inkata Pt 1	HALKATA DT I	00.7720	6-24 to 6-7-24
	oads)	INKATA PT 1	JINKATA PT-I	89.7726	5.25 SIDE SHOULDEI and CORE
I SKALAGINOAD (NO.	Jaasj				DAMAGED AT
					HALAKURA RAI
					GATE TO
					POKALAGI ROA due to heavy
					rainfall Date of
					Incident from 3
					6-24 to 6-7-24
NH17 TO CHOTO PW			CHOTO DIGHALTARI ROAD	89.7826	
DIGHALTARI ROAD (Ro.	oads)		NOAD		and CORE DAMAGED AT
					NH17 TO CHOT
					DIGHALTARI
					ROAD due to
					heavy rainfall Date of Inciden
					from 30-6-24 to
					6-7-24
RATIADAHA TO PW			PACHIM RATIADAHA PT	89.7826	
LAUKHOWARKUTI ROAD (Ro.	oads) [	Daha Pt 1	II		and CORE
					DAMAGED AT RATIADAHA TO
					LAUKHOWARKI
					I ROAD due to
					heavy rainfall
					Date of Inciden
					from 30-6-24 to
					6-7-24
NH17 TO GHARIALDANGA PW	VD G	Shorialdanga Pt	GHARIALDANGA PT-II	89.7826	6-7-24 5.24 10. SIDE





	SATRASAL BAZAR TO RANPAGLI ROAD		Jhapushabari Pt 2	JHAPUSHBARI PT-II	89.7326.16	CORE DAMAGED AT NH17 TO GHARIALDANGA ROAD due to heavy rainfall Date of Incident from 30-6-24 to 6-7-24 SIDE SHOULDER and CORE DAMAGED AT SATRASAL BAZAR TO RANPAGLI ROAD due to heavy rainfall Date of Incident from 30-6-24 to
	POKALAGI PART II TO SILGHAGRI BAZAR ROAD	PWD (Roads)	Pokalagi Pt 2	POKALAGI PART II	26.2889.74	SIDE SHOULDER and CORE DAMAGED AT POKALAGI PART II TO SILGHAGRI BAZAR ROAD due to heavy rainfall Date of Incident from 30-6-24 to 6-7-24
	SATRASAL BAZAAR TO JHAUKUTI ROAD	PWD (Roads)	Ramrai Kuti Pt 2	RAMRAIKUTI PT-II	89.7326.17	SIDE SHOULDER and CORE DAMAGED AT SATRASAL BAZAAR TO JHAUKUTI ROAD due to heavy rainfall Date of Incident from 30- 6-24 to 6-7-24
	RANPAGLI SATRASAL ROAD	(Roads)	3	JHAPUSHBARI PT-III	89.7326.19	SIDE SHOULDER and CORE DAMAGED AT 1ST OF RANPAGLI SATRASAL ROAD due to heavy rainfall Date of Incident from 30- 6-24 to 6-7-24
	KGT ROAD KUTI GHARIALDANGA ROAD		Ghorialdanga Pt 2	GHARIALDANGA PT-II	89.7626.23	SIDE SHOULDER and CORE DAMAGED AT KGT ROAD KUTI GHARIALDANGA ROAD due to heavy rainfall Date of Incident from 30-6-24 to 6-7-24
(Bilasipara   12)	BS ROAD TO KHEJURBARI PT-I	PWD (Roads)	Khejurbari Pt-I	KHEJURBARI PT-I	90.1626.25	HPC. NO 1/1 CULVERT ON 4THKM OF BS ROAD TO KHEJURBARI PT-I (.) CULVERT AND APPROCHES DAMAGED DUE TO FLOOD WAER OF RIVER SANKOSH RIVER





					Date of Incident from 4-7-24 to 6- 7-24
BS ROAD TO DAUTPARA VIA SANTIPUR ASHRAM	PWD (Roads)	Dautpara	DAUTPARA	90.1326.33	15TH KM OF BS ROAD TO DAUTPARA VIA SANTIPUR ASHRAM (.) ERRODED AT CH 710.00M FLOOD WATER BY HELL RIVER Date of Incident from 4- 7-24 to 6-7-24
NAYAHAT TO SOULMARI ROAD	PWD (Roads)	Soulmari	SOULMARI	90.1426.26	NH-31 AT NAYAHAT TO SOULMARIROAD (.) ERRODED AT CH 5200.00M FLOOD WATER BY TIPKAI RIVER Date of Incident from 4-7-24 to 6-7-24
STH KM OF FS ROAD TO BAMUNKURA	PWD (Roads)	Bamunpara Pt-IV	BAMUNPARA	90.1626.34	5TH KM OF FS ROAD TO BAMUNKURA (.) BREACH AT CH 450.00M FLOOD WATER BY HELL RIVER. Date of Incident from 4- 7-24 to 6-7-24
BANGALIPARA FAKIRAGRAM ROAD	PWD (Roads)	Fakiranirjhar Pt-	BANGALIPARA	90.1926.35	RCC BR.NO 16/1 ON BANGALIPARA FAKIRAGRAM ROAD BOTH SIDE APPROACHES DAMGED FLOOD WATER BY HELL RIVER. Date of Incident from 4- 7-24 to 6-7-24
DHANPUR TO SURIPARA ROAD	PWD (Roads)	Dhanpur	DHANPUR	90.1526.32	HPC. NO 1/1 ON DHANPUR TO SURIPARA ROAD (.) CULVERT APPROCHES DAMAGED DUE TO FLOOD WAER OF RIVER TIPKAI RIVER Date of Incident from 4- 7-24 to 6-7-24
KHARAGHAT TO CHOWGURI ROAD	PWD (Roads)	Choruavita	CHOURAVITA	90.1326.33	NH-31 AT KHARAGHAT TO CHOWGURI ROAD (.) ERRODED AT CH 4610.00M FLOOD WATER BY TIPKAI RIVER Date of Incident from 4- 7-24 to 6-7-24
CHOURAVITA ROAD TO ATHIABARI	PWD (Roads)	Choruavita	CHOURAVITA	90.1826.27	RCC BR.NO 3/1 ON 2ND KM OF CHOURAVITA ROAD TO





### PANNGANE TO DHANPUR   PWO   PWO								ATHIABARI
MATER BY   SANKOSH RIVER   Date of Incident   PWD   SANKOSH RIVER   Date of Incident   PWD   SANKOSH RIVER   Date of Incident   PWD   SANKOSH   PWD   PWD   SANKOSH   PWD								
SANKOSH RIVER   Date of incident from 47-73 to 7-72								
RANICANI TO DHANPUR   ROAD								SANKOSH RIVER
PANISANI TO DHANPUR   ROAD   ROE SHOULD								
RANIGAN TO DHANPUR   PWD   Roads   PWD   R								
DHAMPUR ROAD   DHAMPUR DHE of incident from 4-7-24 to 6-7-24 to 6-7-2					Dhanpur	DHANPUR	90.1726.31	RCC BR.NO 1/1
BOTH SIDE			ROAD	(Roads)				
DAMGED FLOOD WATER BY HELL RIVER Date of condent from 4-2-24 to 6-7-24								
Martin								APPROACHES
RIVER Date of Incident from 4-2-24 to 6-7-24								
7.24 to 6-7-24								
2. RCC BR.NO 3/1 DN 5TH   PVD   Roads   Sutipara Pt   SUTIPARA   90.1726.27   RCC BR.NO 3/1 DN 5TH KM OF BS ROAD TO GUTIPARABOTH SIDE APPROACHES BEDLY DAMGED PLOD WATER BY SANKOSH RIVER   PVD   ROAD PTO CHORD PLOD WATER BY SANKOSH RIVER BY SANKOSH RIVER BATE OF INCIDENT BY SANKOSH RIVER BY SANKOSH RIVER BATE OF INCIDENT BY SANKOSH RIVER BATE OF INCIDENT BY SANKOSH RIVER DATE OF INCIDENT BY SANKOSH RIVER BATE OF INCIDENT BY SANKOSH RIVER DATE								Incident from 4-
MASPARA TO PURAN   PWD   Maspara   MASPARA   90.1926.23   MH-31 AT   MASPARA TO PURAN   ROAD TO   MATER BY TIRKAL   MASPARA   PWD   Mater BY TIRKAL   PWD			2 RCC RR NO 2/1 ON ETT	D/V/D	Gutinara P+ 1	GUTIDARA	90 1726 27	
SUTIPARABOTH SIDE APPROACHES REDLY DAMGED FLOOD WATER BY SANKOSH RIVER   MURABARI  NAYAHAT TO MURABARI ROAD  NAYAHAT TO MURABARI ROAD  MURABARI  MURABARI  NAYAHAT TO MURABARI ROAD  MURABARI  MURABARI  MURABARI  90.1426.23  RC BR. NO 1/1  ON NH-31 AT NAYAHAT TO MURABARI ROAD  MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  MASPARA  ROAD  MASPARA  MASPARA  MASPARA  PUD MASPARA  MASPARA  PUD MASPARA  MASPARA  PUD MASPARA  MASPARA  PUD MASPARA  PUD MASPARA  MASPARA  PO.1526.23  NH-31 AT MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  MASPARA  ROAD  MASPARA  PUD MASPARA  P			-		Outipara Ft-1	COTIFANA	30.1720.27	•
DAMGED FLOOD WATER BY SANKOSH RIVER   SIDE   APPROACHES BEDLY DAMGED FLOOD WATER BY SANKOSH RIVER Date of incident from 4-7-24 to 6-7-24				,				BS ROAD TO
SANKOSH RIVER								
ROAD   NAYAHAT TO MURABARI   PWD   Roads   NAYAHAT TO MURABARI   PWD   Roads   PWD								
NAYAHAT TO MURABARI   PWD   Nurabari   MURABARI   90.1426.23   RCC BR.NO.1/1   N. N. H. S. N.								
RIVER Date of incident from 4-7-24 to 6-7-24								
NAYAHAT TO MURABARI   PWD   Murabari   MURABARI   90.14 26.23   RCC BR.NO 1/1   ON NH-31 AT   NAYAHAT TO MURABARI   PWD   MURABARI   PWD   MURABARI   NAYAHAT TO MURABARI ROAD BOTH SIDE   APPROACHES   DAMGED FLODO   WATER BY TIPKAI RIVER. Date of Incident from 4-7-24 to 6-7-24   PARAMED   PWD   Maspara   MASPARA   90.19 26.23   NH-31 AT   MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD DAMAGED   ROAD   PURAN FALIMARI VIA TULUPARA ROAD DAMAGED AT 1ST, AND 2ND   KM Date of Incident from 4-7-24 to 6-7-24 to 6-7-24   PWD   SIDE SHOULDER   PWD   SIDE SHOULDER   SILVER COMPACY TO REGISTARY OFFICE   Roads   Revenue Town   Block-2   SILVER COMPACY TO REGISTARY OFFICE AT 1ST KM DATE OF NAIGHT   NAIGHT   NAIGHT   ROAD   SIDE SHOULDER   DAMAGED SILVER COMPACY TO REGISTARY OFFICE AT 1ST KM GOAD SILVER COMPACY OF THE TOTAL SILVER COMPACY TO REGISTARY OFFICE AT 1ST KM GOAD SILVER COMPACY TO REGISTAR								
NAYAHAT TO MURABARI   ROAD   Roads   ROAD								
ROAD   Roads			NAYAHAT TO MURABARI	PWD	Murabari	MURABARI	90.1426.23	
MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  MASPARA FALIMARI VIA TULUPARA ROAD  MASPARA  MASPARA  MASPARA  PWD (Roads)  Golakganj 1 17)  GIRCLE OFFICE  SILVER COMPACY TO REGISTARY OFFICE  ROAD  MASPARA  PWD (Roads)  MASPARA  MASPARA  MASPARA  PO.19 26.23  MASPARA  PO.19 26.23  MASPARA  PO.19 26.23  MASPARA  PURAN FALIMARI VIA TULUPARA ROAD DAMNAGED SUBMARGED ATD Incident from 4-7-24 to 6-7-24  SOLINGROUP TO CIRCLE OFFICE  SILVER COMPACY TO REGISTARY OFFICE  ROAD  SILVER COMPACY TO REGISTARY OFFICE  SILVER COMPACY TO REGISTARY OFFICE  ROAD  SILVER COMPACY TO REGISTARY OFFICE  SILVER COMPACY TO REGISTARY OFFICE  SILVER COMPACY TO REGISTARY OFFICE  ROAD  SILVER COMPACY TO REGISTARY OFFICE  SILVER COMPACY TO REGISTARY OFFICE AT 1ST							30.1 (20.23	
BOTH SIDE APPROACHES   DAMGED FLOOD WATER BY TIPKAI RIVER. Date of incident from 4-7-24 to 6-7-24   N-31 AT GOLAKGANJ TO PURAN ROAD   PWD (Roads)   Revenue Town Block-2   SILVER COMPACY TO REGISTARY OFFICE   Roads)   Roads   Road DAMGED SUBMAGED SILVER COMPACY TO REGISTARY OFFICE   Roads)   Roads   Road DAMGED SILVER COMPACY TO REGISTARY OFFICE AT 15T   Roads   Road DAMGED SILVER COMPACY TO REGISTARY OFFICE AT 15T   Roads   Road DAMGED SILVER COMPACY TO REGISTARY OFFICE AT 15T   Roads   Road DAMGED SILVER COMPACY TO REGISTARY OFFICE AT 15T   Roads								
APPROACHES DAMGED FLOOD WATER BY TIPKAI RIVER. Date of incident from 4- 7-24 to 6-7-24 MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  MASPARA  PWD (Roads)  MASPARA  PWD (Roads)  MASPARA  PWD PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED AT 15T, AND 2ND KM Date of incident from 4- 7-24 to 6-7-24 10 6-7								
MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  MASPARA  MASPARA  MASPARA  MASPARA  MASPARA  MASPARA  90.19 26.23  NH-31 AT MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED T 1ST, AND 2ND KM Date of Incident from 4- 7-24 to 6-7-24  (Golakganj I 17)  CIRCLE OFFICE  Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  Roads)  Revenue Town Block-2  Roads)  Revenue Town Block-2  MASPARA  90.19 26.23  NH-31 AT MASSPARA  90.19 26.23  NH-31 AT MASSPARA  PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED AND ERODED ON OLD NH AT GOLAKGANI TO CIRCLE OFFICE AT 1ST KM DATE OF INCIDENT- 6-7-24  SILVER COMPACY TO REGISTARY OFFICE  Roads) Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE AT 1ST  ROAD SUBMERGD AND ERODED ON OLD NH AT GOLAKGANI TO SIDE SHOULDER DAMAGED SILVER COMPACY TO REGISTARY OFFICE AT 1ST								
MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  MASPARA  MASPARA  MASPARA  MASPARA  MASPARA  PWD Roads)  MASPARA  MASPARA  PWD PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED AT 1ST, AND 2ND KM Date of Incident from 4- 7-24 to 6-7-24  (Golakgan) I 17)  CIRCLE OFFICE  (Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  Roads)  Revenue Town Block-2  ROAD  AT- 26.107579, LONG- 89.84 26.11  ROAD SUBMERGD AND ERODED ON OLD NI A T GOLAKGANJ TO CIRCLE OFFICE AT 1ST KM DATE OF NICIDENT: 6-7-24  SILVER COMPACY TO REGISTARY OFFICE  Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  ROAD  Revenue Town Block-2  SILVER COMPACY TO ROADS REVENUE TOWN Block-2  SILVER COMPACY TO REGISTARY OFFICE AT 1ST								
MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  Maspara  MASPARA  MASPARA  MASPARA  MASPARA  MASPARA  MASPARA  90.1926.23  NH-31 AT MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED AT 1ST, AND 2ND KM Date of Incident from 4- 7-24 to 6-7-24  (Golakgan)  [17)  CIRCLE OFFICE  (Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  Roads)  Revenue Town Block-2  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE AT 1ST ROAD  SUBMERGD AND REVENUE Town Block-2  SILVER COMPACY TO REGISTARY OFFICE AT 1ST								
MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD  MASPARA  ROAD  MASPARA  MASPARA  MASPARA  MASPARA  MASPARA  PUND PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED AT 1ST, AND 2ND KM Date of Incident from 4- 7-24 to 6-7-24  (Golakganj I 17)  CIRCLE OFFICE  (Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  Roads)  Revenue Town Block-2  MASPARA  PO.19 26.23  NH-31 AT MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED AT 1ST, AND 2ND KM Date of Incident from 4- 7-24 to 6-7-24  ROAD SUBMERGD AND ERODED ON OLD NH AT GOLAKGANJ TO CIRCLE OFFICE AT 1ST KM DATE OF INCIDENT - 6-7-24  SILVER COMPACY TO REGISTARY OFFICE  Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE AT 1ST OFFICE AT 1ST								
FALIMARI VIA TULUPARA ROAD  MASHPARA TO PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED AT 15T, AND 2ND KM Date of Incident from 4-7-24 to 6-7-24  (Golakganj OLD NH AT GOLAKGANJ TO IT)  (Tr)  (Golakganj OLD NH AT GOLAKGANJ TO CIRCLE OFFICE  (Roads)  Golakganj Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  (Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  (Roads)  Revenue Town Block-2  AT- 26.102549, LONG- 89.8326.1  SIDE BERM AND SIDE SHOULDER DAMAGED SILVER COMPACY TO REGISTARY OFFICE AT 1ST NEW COMPACY TO REGISTARY OFFICE AT			MACHDADA TO DUDAN	DWD	Macnara	MASDADA	00.1026.22	_
ROAD  ROAD  PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED AT 1ST, AND 2ND KM Date of Incident from 4-7-24 to 6-7-24  (Golakganj OLD NH AT GOLAKGANJ TO PWD CIRCLE OFFICE (Roads)  PURAN FALIMARI VIA TULUPARA ROAD DAMAGED SUBMARGED ATD 1ST, AND 2ND KM Date of Incident from 4-7-24 to 6-7-24  REVENUE TOWN Block-2  SILVER COMPACY TO PWD REGISTARY OFFICE (Roads)  Revenue Town Block-2  SILVER COMPACY TO PWD REGISTARY OFFICE (Roads)  Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE (Roads)  Revenue Town Block-2  ROAD  89.8426.11  ROAD  SUBMARGED ATD 1ST KM DATE OF INCIDENT 6-7-24  1ST KM DATE OF INCIDENT 6-7-24  SIDE BERM AND SIDE SHOULDER DAMAGED  SILVER COMPACY TO REGISTARY OFFICE AT 1ST					iviaspara	IVIASPARA	90.1926.23	
ROAD DAMAGED SUBMARGED AT 1ST, AND 2ND KM Date of Incident from 4-7-24 to 6-7-24  (Golakganj OLD NH AT GOLAKGANJ TO PWD CIRCLE OFFICE (Roads) Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE (Roads) Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE (Roads) Revenue Town Block-2  ROAD MARGED SUBMARGED AT 1ST AND 2ND KM Date of Incident from 4-7-24 to 6-7-24  ROAD SUBMERGD AND ERODED ON OLD NH AT GOLAKGANJ TO CIRCLE OFFICE AT 1ST KM DATE OF INCIDENT- 6-7-24  SILVER COMPACY TO REGISTARY OFFICE (Roads) Revenue Town Block-2  ROAD SUBMARGED AT 1ST 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24  SILVER COMPACY TO REGISTARY OFFICE AT 1ST				,				PURAN FALIMARI
SUBMARGED AT 1ST, AND 2ND KM Date of Incident from 4-7-24 to 6-7-24 (Golakganj OLD NH AT GOLAKGANJ TO PWD (Roads)   LAT- 26.107679, LONG- SUBMERGD AND ERODED ON OLD NH AT GOLAKGANJ TO CIRCLE OFFICE   SILVER COMPACY TO REGISTARY OFFICE   Revenue Town Block-2   SILVER COMPACY TO REGISTARY OFFICE   Revenue Town Block-2   SILVER COMPACY TO REGISTARY OFFICE AT 1ST KM ADED SILVER COMPACY TO REGISTARY OFFICE AT 1ST KM ADED SILVER COMPACY TO REGISTARY OFFICE AT 1ST KM ADED SILVER COMPACY TO REGISTARY OFFICE AT 1ST								
Golakganj OLD NH AT GOLAKGANJ TO PWD Golakganj I7) CIRCLE OFFICE (Roads) Block-2 (Roads) Block-2 (Roads) Golakganj I7) Golakganj								
Colakgani   Circle Office								1ST, AND 2ND
Golakganj OLD NH AT GOLAKGANJ TO PWD Golakganj Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  Golakganj OLD NH AT GOLAKGANJ TO PWD Golakganj Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  Golakganj Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE  Golakganj Revenue Town Block-2								
CIRCLE OFFICE  (Roads) Revenue Town Block-2  SUBMERGD AND ERODED ON OLD NH AT GOLAKGANJ TO CIRCLE OFFICE AT 1ST KM DATE OF iNCIDENT- 6-7-24  SILVER COMPACY TO REGISTARY OFFICE  (Roads) Revenue Town Block-2  Block-2  SILVER COMPACY TO REGISTARY OFFICE  (Roads) Revenue Town Block-2  Block-2  Block-2  SUBMERGD AND ERODED ON OLD NH AT GOLAKGANJ TO CIRCLE OFFICE AT 1ST KM DATE OF iNCIDENT- 6-7-24  SILVER COMPACY TO REGISTARY OFFICE  OFFICE AT 1ST COMPACY TO REGISTARY OFFICE AT 1ST								
Block-2  Blo							89.8426.11	ROAD
SILVER COMPACY TO REGISTARY OFFICE (Roads) Revenue Town Block-2 REGISTARY OFFICE AT 1ST KM DATE OF TO REGISTARY OFFICE (Roads) Revenue Town Block-2 REGISTARY OFFICE (Roads) Revenue Town Block-2 Registary Office AT 1ST		17)	CIRCLE OFFICE	(Roads)		89.836099		
CIRCLE OFFICE AT 1ST KM DATE OF iNCIDENT- 6-7-24  SILVER COMPACY TO PWD Golakganj LAT- 26.102549, LONG-REGISTARY OFFICE (Roads) Revenue Town Block-2  Block-2  CIRCLE OFFICE AT 1ST KM DATE OF iNCIDENT- 6-7-24  SILVER COMPACY TO PWD Golakganj LAT- 26.102549, LONG-Revenue Town Block-2  SILVER COMPACY TO REGISTARY OFFICE AT 1ST					DIOCK*Z			
SILVER COMPACY TO PWD Golakganj LAT- 26.102549, LONG-REGISTARY OFFICE (Roads) Revenue Town Block-2  Block-2  SILVER COMPACY TO PWD Golakganj LAT- 26.102549, LONG-89.83 26.1 SIDE BERM AND SIDE SHOULDER DAMAGED SILVER COMPACY TO REGISTARY OFFICE AT 1ST								
SILVER COMPACY TO PWD Golakganj LAT- 26.102549, LONG-REGISTARY OFFICE (Roads) Revenue Town Block-2 Block-2 SILVER COMPACY TO REGISTARY OFFICE AT 1ST								
REGISTARY OFFICE (Roads) Revenue Town 89.831398 SIDE SHOULDER Block-2 SILVER COMPACY TO REGISTARY OFFICE AT 1ST								
Block-2  Block-2  DAMAGED  SILVER COMPACY  TO REGISTARY  OFFICE AT 1ST							89.8326.1	
SILVER COMPACY TO REGISTARY OFFICE AT 1ST			REGISTARY OFFICE	(Roads)		89.831398		
OFFICE AT 1ST					2100K 2			
i								
incident- 6-7-24						<u>                                       </u>		





NH-31 TO GOLAKGANJ PHC	(Roads)	Golakganj Revenue Town Block-2	LAT- 26.108399, LONG- 89.841279	89.8426.11	ROAD SURFACE DAMAGED ON NH-31 TO GOLAKGANJ PHC AT 2ND KM DATE OF INCIDENT- 6- 7-24
KHEJURTOLA TO DAULATRAM ITT BHATA	PWD (Roads)	Golakganj Revenue Town Block-1	LAT- 26.113074, LONG- 89.844545	89.8426.11	ROAD SUBMERGED AND EORODED ON KHEJURTOLA TO DAULATRAM ITT BHATA AT 1ST KM DATE OF INCIDENT- 6-7-24
OLD NH TO SATSANGA BIHAR ROAD	PWD (Roads)	Golakganj Revenue Town Block-2	LAT-26.109284 , LONG- 89.843404	89.8426.11	SIDE BERM AND SIDE SLOEPS DAMAGED ON OLD NH TO SATSANGA BIHAR ROAD AT 1ST KM DATE OF INCIDENT- 6-7-24
LP SCHOOL	PWD (Roads)	Golakganj Revenue Town Block-1	LAT- 26.112983, LONG- 89.838293	89.8426.11	SIDE BERM AND SHOULDER DAMAGED ON NH-31 TO 131 ANATH NO. LP SCHOOL FROM 1ST TO 5TH KM IN STRETCHES DATE OF INCIDENT- 6-7-24
GOLAKGANJ SOULMARI ROAD TO GOLAKGANJ STADIUM	PWD (Roads)	Golakganj Revenue Town Block-1	LAT- 26.11298, LONG- 89.838267	89.8426.11	SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD TO GOLAKGANJ STADIUM AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24
GOLAKGANJ BAZAR TO BIRAT NAGAR CHARIALI	PWD (Roads)	Golakganj Revenue Town Block-1	LAT- 26.117861 LONG- 89.841447	89.84 26.12	SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ BAZAR TO BIRAT NAGAR CHARIALI FROM 1ST KM TO 4TH KM IN STRETCHES DATE OF INCIDENT- 6- 7-24
OLD NH TO GOLAKGANJ CHOWK BAZAR ROAD	PWD (Roads)	Golakganj Revenue Town Block-2	LAT- 26.106950, LONG- 89.827816	89.8326.11	ROAD SUBMERGED AND ERODED ON OLD NH TO GOLAKGANJ CHOWK BAZAR ROAD AT 1ST KM DATE OF INCIDENT- 6-7-24
CHINMOYEE SCHOOL TO GOLAKGANJ BAZAR	PWD (Roads)	Golakganj Revenue Town Block-2	LAT- 26.105639, LONG- 89.827774	89.8326.11	SIDE BERM  DAMAGED ON  OLD NH AT  CHINMOYEE  SCHOOL TO  GOLAKGANJ





OLD NH TO GOLAKGANJ PWD Golakganj Revenue Town Block-2  NH-31 TIE BUND PWD Golakganj LAT- 26.152407, LONG- 89.82 26.15  (Roads) Revenue Town Block-2  GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA  PWD Golakganj LAT- 26.152407, LONG- 89.82 26.15  GOLAKGANJ SOULMARI ROAD DAKHIN Roads) Revenue Town Block-2  PRATAPGANJ PESTIRGHAT TO GK ROAD  PRATAPGANJ PESTIRGHAT Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2  GOLAKGANJ SOULMARI Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Roads) Revenue Town 89.8303066	BAZAR AT 1ST KM DATE OF INCIDENT- 6-7-24 ROAD SURFACE DAMAGED ON OLD NH TO GOLAKGANJ POLICE STATION AT CH. 4TH KM DATE OF INCIDENT- 6-7-24 SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SLOPES
OLD NH TO GOLAKGANJ POLICE STATION  PWD Roads)  NH-31 TIE BUND  PWD Rolakganj (Roads)  Revenue Town Block-2  GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA  PWD Roads)  PWD Golakganj (Roads)  Revenue Town Block-2  GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA  Roads)  Revenue Town Block-2  GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA  Roads)  Revenue Town Block-2  Block-2  AT-26.153828, LONG- 89.8326.15  Revenue Town Block-2  PRATAPGANJ PESTIRGHAT TO GK ROAD  Roads)  Roads)  Roads)  Roads)  Roads)  AT-26.106842, LONG- 89.8326.11  Roads)  Roads)	INCIDENT- 6-7-24 ROAD SURFACE DAMAGED ON OLD NH TO GOLAKGANJ POLICE STATION AT CH. 4TH KM DATE OF INCIDENT- 6-7-24 SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
POLICE STATION (Roads) Revenue Town Block-2  NH-31 TIE BUND PWD Golakganj Revenue Town Block-2  GOLAKGANJ SOULMARI ROAD DAKHIN (Roads) Block-2  GOLAKGANJ FESTIRGHAT TO GK ROAD (Roads) Block-2  PRATAPGANJ PESTIRGHAT TO GK ROAD (Roads) Block-2  OLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2  GOLAKGANJ PESTIRGHAT PWD Golakganj Revenue Town Block-2  GOLAKGANJ PESTIRGHAT PWD Golakganj Revenue Town Block-2  GOLAKGANJ PWD Golakganj Rat-26.153828 , LONG-89.8326.15  GOLAKGANJ PWD Golakganj Rat-26.106842 , LONG-89.8326.11  GOLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2	DAMAGED ON OLD NH TO GOLAKGANJ POLICE STATION AT CH. 4TH KM DATE OF INCIDENT- 6-7-24 SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
NH-31 TIE BUND	OLD NH TO GOLAKGANJ POLICE STATION AT CH. 4TH KM DATE OF INCIDENT- 6-7-24 SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
NH-31 TIE BUND	GOLAKGANJ POLICE STATION AT CH. 4TH KM DATE OF INCIDENT- 6-7-24 SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
NH-31 TIE BUND PWD Golakganj LAT- 26.152407, LONG- 89.8226.15 Revenue Town Block-2  GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA PWD Golakganj LAT- 26.095854, LONG- 89.8426.1  PRATAPGANJ PESTIRGHAT TO GK ROAD (Roads) Revenue Town Block-2  PRATAPGANJ PESTIRGHAT TO GK ROAD (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.153828 , LONG- 89.8326.15 Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 Revenue Town 89.830306	POLICE STATION AT CH. 4TH KM DATE OF INCIDENT- 6-7-24 SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
NH-31 TIE BUND	DATE OF INCIDENT- 6-7-24 SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
NH-31 TIE BUND	INCIDENT- 6-7-24 SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
NH-31 TIE BUND	SIDE BERM EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
Revenue Town   89.81763	EORODED ON NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
GOLAKGANJ SOULMARI PWD Golakganj LAT- 26.095854, LONG- 89.84 26.1 ROAD DAKHIN TOKRERCHARA  PRATAPGANJ PESTIRGHAT TO GK ROAD (Roads) Revenue Town Block-2  PRATAPGANJ PESTIRGHAT TO GK ROAD (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2  AT-26.106842, LONG- 89.83 26.11  ROAD Revenue Town Block-2	NH-31 TIE BUND AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA  PWD Golakganj Revenue Town Block-2  PRATAPGANJ PESTIRGHAT TO GK ROAD  Golakganj Revenue Town Block-2  Golakganj Revenue Town Block-2  Roads)  Revenue Town Block-2  Golakganj Revenue Town Block-2	AT 1ST KM AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
GOLAKGANJ SOULMARI ROAD DAKHIN (Roads) Revenue Town Block-2  PRATAPGANJ PESTIRGHAT TO GK ROAD (Roads) Revenue Town Block-2  PRATAPGANJ PESTIRGHAT (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.153828 , LONG-89.8326.15  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG-89.8326.11  (Roads) Revenue Town Block-2	INCIDENT- 6-7-24 SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA  PRATAPGANJ PESTIRGHAT TO GK ROAD  CROads)  PRATAPGANJ PESTIRGHAT TO GK ROAD  CROads)  Revenue Town Block-2  Block-2  Block-2  AT-26.153828, LONG- 89.8326.15  Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj Revenue Town Block-2  Golakganj Revenue Town Block-2  AT-26.106842, LONG- 89.8326.11  Revenue Town Block-2  Revenue Town Block-2  Revenue Town Block-2	SIDE BERM AND SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
ROAD DAKHIN TOKRERCHARA  (Roads) Revenue Town Block-2  PRATAPGANJ PESTIRGHAT TO GK ROAD  (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD (Roads) Revenue Town Roads)	SIDE SHOULDER DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
PRATAPGANJ PESTIRGHAT PWD Golakganj Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD (Roads) Revenue Town Roads) Revenue Town Roads) Revenue Town Block-2	DAMAGED ON GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
PRATAPGANJ PESTIRGHAT PWD Golakganj LAT-26.153828 , LONG- 89.8326.15 TO GK ROAD (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	GOLAKGANJ SOULMARI ROAD DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
PRATAPGANJ PESTIRGHAT PWD Golakganj LAT-26.153828 , LONG-89.8326.15 CROAD (Roads) Revenue Town 89.832599 Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG-89.8326.11 CROADS Revenue Town 89.830306	DAKHIN TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
PRATAPGANJ PESTIRGHAT PWD Golakganj LAT-26.153828 , LONG- 89.8326.15 TO GK ROAD (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	TOKRERCHARA AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
PRATAPGANJ PESTIRGHAT PWD Golakganj LAT-26.153828 , LONG- 89.8326.15 TO GK ROAD (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	AT 1ST AND 2ND KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
PRATAPGANJ PESTIRGHAT PWD Golakganj LAT-26.153828 , LONG- 89.8326.15 TO GK ROAD (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	KM DATE OF INCIDENT- 6-7-24 SIDE BERM AND
PRATAPGANJ PESTIRGHAT PWD Golakganj LAT-26.153828 , LONG- 89.83 26.15 TO GK ROAD (Roads) Revenue Town Block-2  OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842 , LONG- 89.83 26.11 (Roads) Revenue Town B9.830306	SIDE BERM AND
OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	
OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	SIDE SLOPES
OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	DANAACEDONI
OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	DAMAGED ON PRATAPGANJ
OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	PESTIRGHAT TO
OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	GK ROAD AT 1ST
OLD NH AT GOLAKGANJ PWD Golakganj LAT-26.106842, LONG- 89.8326.11 (Roads) Revenue Town 89.830306	KM DATE OF
(Roads) Revenue Town 89.830306	INCIDENT- 6-7-24 SIDE BERM, SIDE
	SLOPES AND
	HARD CRUST
	DAMAGED ON
	OLD NH AT
	GOLAKGANJ FROM 1ST TO
	4TH KM DATE OF
	INCIDENT- 6-7-24
	SIDE BERM AND
	HARD CRUST
	DAMAGED ON NH-17 TO
	MZAUMDARPAR
	A AT 1ST KM
	DATE OF
	INCIDENT- 6-7-24
	SIDE BERM AND SIDE SHOULDER
	DAMAGED ON
	GOLAKGANJ
	SOULMARI AT
	3RD KM DATE OF
	INCIDENT- 6-7-24 NH 31 AT
	AREARJHAR TO
	DHIRGHAT
	DUTUMAADI
	PUTHIMARI
	ROAD HAS BEEN
	ROAD HAS BEEN SUBMERGED
, , , , , , , , , , , , , , , , , , , ,	ROAD HAS BEEN SUBMERGED FROM CH. 100.00
	ROAD HAS BEEN SUBMERGED





								CHAMPABATI RIVER. Date of
			PWD (Roads)	Areajhar Pt. III	AREARJHAR	90.4	26.24	Incident- 6-7-24 NH31 AT DHIRGHAT PUTHIMARI ROAD AT CH.540.00MSIDE BERM AND HARD CRUST DAMAGED DUE
								TO FLOOD WATER OF CHAMPABATI RIVER. Date of Incident- 6-7-24
		TOWARDS AMRIT SAROVER	and Rural Deptt.	Rowmari Pt-II	ROWMARI PT II	90.41	26.26	APPROACH ROAD FROM SAHA ALOM MIR HOUSE TOWARDS AMRIT SAROVER ID NO 88176 UNDER MGNREGA Date of Incident- 6-7- 24
			PWD (Roads)	Arearjhar Pt. I	AREARJHAR	90.4	26.24	BRIDGE NO. 1/1 ON NH31 AT DHIRGHAT PUTHIMARI ROAD APPROACH DAMAGED AT CH. 710.00 M DUE TO FLOOD WATER OF CHAMPABATI RIVER. Date of Incident- 6-7-24
S	South almara art   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
(/	Athani   .0)	JHARNERCHAR PT-V	(Roads)		ihornarchar pt-v	90.08		JHARNERCHAR PT-III TO JHARNERCHAR PT-V ROAD LENGTH 3.00 KM, SLAB CULVERT AT CH.800.00M AND CH.2100.00M, APPROACHES DAMAGED, SIDE BERM ERODED BY RIVER BRAHMAPUTRA Date of Incident 5-7-24
				Mayerchar Pt- VII	mayerchar pt VII	90.19	26.16	MAYERCHAR PT- VII TO NAYERALGA PT- IV ROAD LENGTH 9.04 KM, BRIDGE AT CH2500.00M, CH.4525.00M APPROCHES DAMAGED AND SIDE BERM AND HARD CRUST ERODED BY RIVER GAURANG





							Date of Incident 5-7-24
	SIMULTOLA BAZAR TO DIMATOLA PARGHAT ROAD	PWD (Roads)	Dimatola Pt-I	dimatola pt- i	90.112	26.02	SIMULTOLA BAZAR TO DIMATOLA PARGHAT ROAD LENGTH 2.00 KM,SLAB CULVERT AT CH100.00M, AND CH.800. APPROCHES DAMAGED AND SIDE BERM ERODED BY RIVER BRAHMAPUTRA Date of Incident 5-7-24
	EXTENSION OF CHOUDHURIRCHAR PMGSY ROAD TO CHIRAKHOWA HIGH SCHOOL ROAD	PWD (Roads)	Chaudhurychar Pt-I	Chaudhurychar Pt-I	90.052	26.11	EXTENSION OF CHOUDHURIRCH AR PMGSY ROAD TO CHIRAKHOWA HIGH SCHOOL ROAD LENGTH 2.50 KM, SLAB CULVERT AT CH.1950.00M, APPROACHES WASHED OUT SIDE BERM ERRODED BY RIVER TIPKAI Date of Incident 5-7-24
		PWD (Roads)	Bandihana	BANDIHANA	90.042	26.06	MAJERCHAR TO BANDIHANA ROAD LENGTH 2.50 KM, BRIDGE AT CH.16800.00M, APPROCHES DAMAGED SIDE BERM AND HARD CRUST ERODED BY RIVER BRAHMAPUTRA Date of Incident 5-7-24
		PWD (Roads)	Fulkatari	FULKATARI	90.042	26.11	BOROCHIRAKHO WA TO ALAMGANJ FULKATARI ROAD LENGTH 2.00KM, SIDE BERM ERODED BY RIVER TIPKAI Date of Incident 5-7-24
		PWD (Roads)	Fulkatari	fulkatari	90.072	26.12	EXTENSION OF JHARNERCHAR JUNIOR COLLEGE TO FULKATARI BRIDGE APPROACE LENGTH 2.00 KM, SIDE BERM ERODED BY RIVER





										BRAHMAPUTRA
										Date of Incident
				JHARNERCHAR PT-II TO	PWD	Ihornarchar Pt	JHARNERCHAR PT-III	90.09	26.11	5-7-24 JHARNERCHAR
					(Roads)	III	JIIANNENCHAN FI-III	30.00	20.11	PT-II TO
					(					JHARNERCHAR
										PT-III ROAD
										LENGTH 2.50 KM
										SIDE BERM ERODED BY
									RIVER	
										BRAHMAPUTRA
										Date of Incident
										5-7-24
				BANDIHANA TO MAJERCHAR ROAD	PWD	Bandihana	Bandihana	90.07	26.09	BANDIHANA TO MAJERCHAR
				IVIAJERCHAR ROAD	(Roads)					LENGTH 2.00 KM,
										BRIDGE AT
										CH.9850.00M
										APPROCHES
										DAMAGED AND
										SIDE BERM HARD CRUST ERODED
										BY RIVER
										BRAHMAPUTRA
										Date of Incident
				CHOUDHURIRCHAR TO	PWD	Chinikhowa	CHIRAKHOWA	00.00	26.12	5-7-24 CHOUDHURIRCH
				CHIRAKHOWA ROAD	(Roads)	Chinikhowa	CHIRAKHUWA	90.06	26.12	AR TO
				CHINAKITOWA KOAD	(Nodus)					CHIRAKHOWA
										ROAD LENGTH
										1.00 KM, SIDE
										BERM ERODED
										BY RIVER TIPKAI  Date of Incident
										5-7-24
	Dibrugar	0	(Tingkhong	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	h		0) (Dibrugarh	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			West   0)	IVII	INII			INII	INII	IVII
				Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)							
			(Moran   0)		Nil	Nil	Nil	1	Nil	Nil
			(Naharkatia   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Dibrugarh	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			East   0)		]			[		[ "
			(Tengakhat	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)							
	Goalpara	0	(Matia   0)		Nil	Nil	Nil	1	Nil	Nil
			(Lakhipur   0)	INII	Nil	Nil	Nil	Nil	Nil	Nil
				Nil	Nil	Nil	Nil	Nil	Nil	Nil
			() ()							
	Golaghat	0	(Bokakhat	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)							
			(Khumtai	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0) (Dergaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Dergaon   0)		[ ]					1311
	Hailakan	0	(Hailakandi	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	di		0)							
				Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0) (Lala L 0)	Nii	NI:I	NII	Niil	NE	NI:I	NI:I
			(Lala   0) (Katlicherra	Nil	Nil Nil	Nil Nil	Nil Nil		Nil Nil	Nil Nil
			(Katilcherra   0)	INII		1411	INII	l'NII	INII	IVII
	Hojai	0	(Hojai   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	- ,	l	, 1 9/	1		1	<u> </u>	1	1	1





		(Doboka   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil			
Jorhat	0		Nil	Nil	Nil	Nil	Nil	Nil	Nil			
		(Jorhat East	Nil	Nil	Nil	Nil	Nil	Nil	Nil			
		0) (Jorhat West   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil			
Kamrup	29		Jawkata to Nimutari road	PWD (Roads)	Jaukatadia	Jawkatadia			Road submer on dated 06/07/2024 a per report of Asstt. Executi Engineer PWI Chamaria territorial roa sub division Goroimari			
			Selosuti to badla Pathar road	PWD (Roads)	Selosuti	Selosuti			Road submer on dated 06/07/2024 a per report of Asstt. Executi Engineer PWI Chamaria territorial roa sub division Goroimari			
			Santoli to bardiyanayapara road	PWD (Roads)	Santoli Satra	Santoli satra			Road submer on dated 06/07/2024 a per report of Asstt. Executi Engineer PW Chamaria territorial roa sub division Goroimari			
			Kalatoli Bazar to niz kashmi road	PWD (Roads)	Niz Kathmi	Niz kathmi			Road submer on dated 06/07/2024 a per report of Asstt. Execut Engineer PW Chamaria territorial roa sub division Goroimari			
						Dekasang to Mandira NC road	PWD (Roads)	Dekachang	Dekachang			Road submer on dated 06/07/2024 a per report of Asstt. Execut Engineer PW Chamaria territorial roa sub division Goroimari
			Sontoli to lutardia NC road	PWD (Roads)	Santoli Satra	Sontoli satra			Road submer on dated 06/07/2024 aper report of Asstt. Execut Engineer PW Chamaria territorial roa sub division Goroimari			
1			Sontoli to lutartari road	PWD	Santoli Satra	Santoli satra			Road submer			





	ı	1	T	1	1	1	1			<del>, , , , , , , , , , , , , , , , , , , </del>
										06/07/2024 as
										per report of
										Asstt. Executive
										Engineer PWRD
										Chamaria
										territorial road
										sub division
										Goroimari
				Mahtoli to rangapani road	PWD	Mahtoli	Mahtoli			Road submerged
					(Roads)					on dated
										06/07/2024 as
										per report of
										Asstt. Executive
										Engineer PWRD
										Chamaria territorial road
										sub division
										Goroimari
				Santoli to luturia gaon	PWD	Santoli Satra	Santoli satra			Road submerged
				Santon to luturia gaon		Santon Satia	Santon Satia			on dated
					(Roads)					06/07/2024 as
										per report of
										Asstt. Executive
										Engineer PWRD
										Chamaria
										territorial road
										sub division
										Goroimari
			(Kamalpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)						L	<u>                                       </u>
			(North Ghy	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)							
			`	KANHARA TO BAGHMARA	PWD	Kanhara	KANHARA TO			As per report
			18)	ROAD	(Roads)		BAGHMARA			from ASSTT.
										EXECUTIVE
										ENGINEER, PWD
										CHAMARIA
										TEERITORIAL
										ROAD SUB- DIVISION
										GOROIMARI,
										KANHARA TO BAGHMARA
										ROAD,SUBMERG
										ENCE OCCURRED
										FROM CH. 0.4
										KM TO 1.2 KM
				GOROIMARI TO DAKSHIN	PWD	Goroimari Satra	GOROIMARI TO			As per report
		Ī	Ī						1	1 - 1 - 1 - 1 - 2 - 2
	Ì			TUKRAPARA ROAD	(Roads)		DAKSHIN TUKRAPARA			from ASSTT.
1				TUKKAPAKA KUAD	(Roads)		DAKSHIN TUKRAPARA			
1				TUKKAPAKA KUAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE
				TURKAPAKA KUAD	(Roads)		DAKSHIN TUKRAPARA			
				TUKKAPAKA KOAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD
				TUKKAPAKA KOAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA
				TUKKAPAKA KOAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL
				TURRAPARA ROAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB-
				TURRAPARA ROAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION
				TUKKAPAKA KOAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI,
				TUKKAPAKA KOAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO
				TUKKAPAKA KOAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN
				TUKKAPAKA KOAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN TUKRAPARA
				TUKKAPAKA KOAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN TUKRAPARA ROAD,
				TURRAPARA ROAD	(Roads)		DAKSHIN TUKRAPARA			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN TUKRAPARA ROAD, SUBMERGENCE OCCURRED FROM CH. 0.35
										EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN TUKRAPARA ROAD, SUBMERGENCE OCCURRED FROM CH. 0.35 KM TO 0.78 KM.
				PASCHIM MAHIMARI TO	PWD	Mahimari	PASCHIM MAHIMARI TO			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN TUKRAPARA ROAD, SUBMERGENCE OCCURRED FROM CH. 0.35 KM TO 0.78 KM. As per report
						Mahimari				EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN TUKRAPARA ROAD, SUBMERGENCE OCCURRED FROM CH. 0.35 KM TO 0.78 KM. As per report from ASSTT.
				PASCHIM MAHIMARI TO	PWD	Mahimari	PASCHIM MAHIMARI TO			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN TUKRAPARA ROAD, SUBMERGENCE OCCURRED FROM CH. 0.35 KM TO 0.78 KM. AS per report from ASSTT. EXECUTIVE
				PASCHIM MAHIMARI TO	PWD	Mahimari	PASCHIM MAHIMARI TO			EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO DAKSHIN TUKRAPARA ROAD, SUBMERGENCE OCCURRED FROM CH. 0.35 KM TO 0.78 KM. As per report from ASSTT.





1				ı		ı	TEERITORIAL
							TEERITORIAL ROAD SUB- DIVISION
							GOROIMARI,PAS CHIM MAHIMARI
							TO BHARIRAVITA
							ROAD, 0.270 KM
							(SUBMERGENCE OCCURRED AT
							DIFFERENT
		HATISOLAPAM TO DAKSHIN	PWD	Hathisala Paam	HATISOLAPAM TO		STRETCHES) As per report
		LARUAJAN ROAD	(Roads)	Tracinisala Faam	DAKSHIN LARUAJAN		from ASSTT.
							EXECUTIVE ENGINEER, PWD
							CHAMARIA
							TEERITORIAL
							ROAD SUB- DIVISION
							GOROIMARI,
							HATISOLAPAM TO DAKSHIN
							LARUAJAN ROAD,
							SUBMERGENCE OCCURRED
							FROM CH. 1.3
		DUA ODIANJULA TO	D14/D	Diametric la	DUA ODIAN/IUA TO		KM TO 1.85 KM.
		BHAORIAVIHA TO MANJURIBIL ROAD	PWD (Roads)	Bhauriabhitha	BHAORIAVIHA TO MANJURIBIL		As per report from ASSTT.
							EXECUTIVE
							ENGINEER, PWD CHAMARIA
							TEERITORIAL
							ROAD SUB- DIVISION
							GOROIMARI,
							BHAORIAVIHA TO MANJURIBIL
							ROAD,
							SUBMERGENCE OCCURRED
							FROM CH. 0.7
		LIATICOLABANATO DAVICIUNI	D14/D	Halliada Bassa	LIATICOLA DANA TO		KM TO 1.15 KM.
		HATISOLAPAM TO DAKSHIN LARUAJAN LP SCHOOL	(Roads)		HATISOLAPAM TO DAKSHIN LARUAJAN LP		As per report from ASSTT.
		ROAD			SCHOOL		EXECUTIVE
							ENGINEER, PWD CHAMARIA
							TEERITORIAL
							ROAD SUB- DIVISION
							GOROIMARI,
							HATISOLAPAM
							TO DAKSHIN LARUAJAN LP
							SCHOOL ROAD,
							0.570 KM (SUBMERGENCE
							OCCURRED AT
							DIFFERENT STRETCHES)
				Pukhuripar	PUKHURIPAR TO		As per report
		MAHIMARI BILARPATHAR ROAD	(Roads)		MAHIMARI BILARPATHAR		from ASSTT. EXECUTIVE
					5.5 m / / / / / / / / / / / / / / / / / /		ENGINEER, PWD
							CHAMARIA TEERITORIAL
							ROAD SUB-
							DIVISION





	BAGHMARA TO TOPAR PATHAR ROAD	PWD (Roads)		BAGHMARA TO TOPAR PATHAR	GOROIMARI, PUKHURIPAR TO MAHIMARI BILARPATHAR ROAD, 0.600 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BAGHMARA TO TOPAR PATHAR ROAD, 0.670 KM (SUBMERGENCE OCCURRED AT DIFFERENT
	GOROIMARI TO CHOUDHURYPAM ROAD	PWD (Roads)	Goroimari Satra	GOROIMARI TO CHOUDHURYPAM	AS per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, GOROIMARI TO CHOUDHURYPA M ROAD, SUBMERGENCE OCCURRED FROM CH. 0.68 KM TO 1.42 KM.
	JORSHIMULI TO PURANKUSHIYA ROAD	PWD (Roads)		JORSHIMULI TO PURANKUSHIYA	As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, JORSHIMULI TO PURANKUSHIYA ROAD, SUBMERGENCE OCCURRED FROM CH. 0.5 KM TO 1.2 KM.
	PUB MAHIMARI TO MADHYA TUKRAPARA ROAD	PWD (Roads)	Mahimari	PUB MAHIMARI TO MADHYA TUKRAPARA	As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, PUB MAHIMARI TO MADHYA TUKRAPARA





			1	1	
					ROAD,
					SUBMERGENCE
					OCCURRED
					FROM CH. 0.9
					KM TO 1.4 KM.
	TUKRAPARA TO	PWD	Tukrapara	TUKRAPARA TO	As per report
	CHOUDHURYPAM ROAD	(Roads)		CHOUDHURYPAM	from ASSTT.
					EXECUTIVE
					ENGINEER, PWD
					CHAMARIA
					TEERITORIAL
					ROAD SUB-
					DIVISION
					GOROIMARI,
					TUKRAPARA TO
					CHOUDHURYPA
					M ROAD,
					SUBMERGENCE
					OCCURRED
					FROM CH. 0.65
	M14	A T D) 4 / 5	IZI III	(/// / // / // / / / / / / / / / / / /	KM TO 0.93 KM.
	KHALIHAMARI TO BORKH		Khalihamari	KHALIHAMARI TO	As per report
	ROAD	(Roads)	1	BORKHAT	from ASSTT.
			1		EXECUTIVE
			1		ENGINEER, PWD CHAMARIA
					TEERITORIAL
					ROAD SUB- DIVISION
					GOROIMARI,
					KHALIHAMARI TO
					BORKHAT ROAD,
					0.430 KM
					(SUBMERGENCE
					OCCURRED AT
					DIFFERENT
					STRETCHES)
	BHULUBARI TO GOROIMA	ARIPWD	Bhalukabari	BHULUBARI TO	As per report
	ROAD	(Roads)		GOROIMARI	from ASSTT.
		Ì			EXECUTIVE
					ENGINEER, PWD
					CHAMARIA
					CHAMARIA TEERITORIAL
					TEERITORIAL
					TEERITORIAL ROAD SUB-
					TEERITORIAL ROAD SUB- DIVISION
					TEERITORIAL ROAD SUB- DIVISION GOROIMARI,
					TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO
					TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI
					TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM
					TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE
					TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT
	PURANKUSHIYA TO	PWD	Purankuchia	PURANKUSHIYA TO	TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT
	PURANKUSHIYA TO KANDULIMARI ROAD	PWD (Roads)	Purankuchia	PURANKUSHIYA TO KANDULIMARI	TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES)
			Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report
			Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT.
			Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA
			Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL
			Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB-
			Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION
		II .	Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI,
		II .	Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION
		II .	Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, PURANKUSHIYA TO
		II .	Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, PURANKUSHIYA TO KANDULIMARI
		II .	Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, PURANKUSHIYA TO KANDULIMARI ROAD, 0.340 KM
		II .	Purankuchia		TEERITORIAL ROAD SUB- DIVISION GOROIMARI, BHULUBARI TO GOROIMARI ROAD, 0.640 KM (SUBMERGENCE OCCURRED AT DIFFERENT STRETCHES) As per report from ASSTT. EXECUTIVE ENGINEER, PWD CHAMARIA TEERITORIAL ROAD SUB- DIVISION GOROIMARI, PURANKUSHIYA TO KANDULIMARI





								T	T	DIFFERENT
								<u> </u>	<u> </u>	STRETCHES)
				BIHAPARA KHARIDOL ROAD		Bihapara	BIHAPARA KHARIDOL			As per report
					(Roads)					from ASSTT.
										EXECUTIVE
										ENGINEER, PWD CHAMARIA
										TEERITORIAL
										ROAD SUB-
										DIVISION
										GOROIMARI,
										BIHAPARA
										KHARIDOL ROAD,
										0.260 KM
										(SUBMERGENCE OCCURRED AT
										DIFFERENT
										STRETCHES
				AGGUMI HATHIPARA ROAD	PWD	Aag Gumi	AGGUMI HATHIPARA	1	+	As per report
					(Roads)					from ASSTT.
										EXECUTIVE
										ENGINEER, PWD
										CHAMARIA
										TEERITORIAL ROAD SUB-
										DIVISION
										GOROIMARI,
										AGGUMI
										HATHIPARA
										ROAD,
										SUBMERGENCE
										OCCURRED
										FROM CH. 4.20 KM TO 4.60 KM.
				BHALUKABARI TO	PWD	Bhalukabari	BHALUKABARI TO	<del>                                     </del>	+	As per report
				CHAUTARA ROAD	(Roads)	Dilaidkabaii	CHAUTARA			from ASSTT.
					(**************************************					EXECUTIVE
										ENGINEER, PWD
										CHAMARIA
										TEERITORIAL
										ROAD SUB-
										DIVISION GOROIMARI,
										BHALUKABARI TO
										CHAUTARA
										ROAD, 0.470 KM
										(SUBMERGENCE
										OCCURRED AT
										DIFFERENT
			(Palashbari	Nil	Nil	Nil	Nil	Nil	Nil	STRETCHES) Nil
			(Palashbari   0)	INII	IVII	IVII	IVII	IVII	INII	INI
			(Rangia   0)		Nil	Nil	Nil	Nil	Nil	Nil
				Bhakharadia road	PWD	Bhakhuradiya	bhakhuradia			Road submerged
			2)		(Roads)					on 6/7/2024 as
										per report of
										PWD SUBDIVISION
										GOROIMARI
				NAGARBERA PAHARPARA	PWD	Nagarbera	NAGARBERA	+	+	Road submerged
					(Roads)					on 6/7/2024 as
					ĺ					per report of
										PWD
										SUBDIVISION
					L		<u> </u>	<u> </u>		GOROIMARI
1										
<u></u>					Nil	Nil	Nil	Nil	Nil	Nil
	amrup M)	0			Nil Nil	Nil Nil	Nil	Nil	Nil	Nil





		(Samaguri   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0)		Nil					
		(Dhing   0)		Nil	Nil Nil	Nil Nil			Nil Nil
				Nil	Nil	Nil		Nil	Nil
									submitted by Kaliabor Territorial Road Sub- Division, Jakhalabandha
									0.90 m.) and eroded in stretches at 1st km report
Nagaon	1	(Kaliabor   1)	Missa Hatbagan to Kellyden Road in Stretches at 1st km and 2nd km		Kellyden	Missa Hatbagan to Kellyden			Missa Hatbagan to Kellyden Road in Stretches at 1st km and 2nd km (up to Hight
		(Laharighat   0)		Nil	Nil	Nil	Nil		Nil
		(Mayong   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Morigaon   0)		Nil	Nil	Nil			Nil
Morigao n	0	(Bhuragaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Ujani Majuli   0)	Nil	Nil	Nil	Nil	Nil		Nil
Majuli	1	(Majuli   1)		PWD (Roads)	Laholial	Laholial	94.14		Completely submerged fron ch. 0 m. to 2500 m.
		(Narayanpu r   0)		Nil	Nil	Nil			Nil
		(North Lakhimpur   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0) (Nowboich a   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Subansiri		Nil	Nil	Nil	Nil		Nil
ur		0) (Kadam   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Lakhimp	0	(Bihpuria		Nil	Nil	Nil			Nil
		n   0) (Dotma   0)		Nil	Nil	Nil	Nil		Nil
r		0) (Gossaigao		Nil	Nil	Nil			Nil
Kokrajha	0	(Bagribari		Nil	Nil	Nil			Nil
		0) (Badarpur		Nil	Nil	Nil			Nil
		di   0) (Karimganj		Nil	Nil	Nil			Nil
nj		r   0) (Patherkan	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Karimga	0	r   0) (Nilambaza	Nil	Nil	Nil	Nil	Nil	Nil	Nil





				Rajgarh Road	PWD (Roads)	Lakwa Cha Baghicha	Chalapother			Overtopped by flood warter
			(Demow   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Sivsagar   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Sonitpur	0	(Tezpur   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Dhekiajuli   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	South Salmara		(South Salmara   6)	Patakata tiniali to Dawakandi Raod	PWD (Roads)	Patakata	Patakata			Patakata Tiniali to Dawakandi SR madrasa via holholi pt.i road submerged various stretches
				South Salmara Patakata To Gotabari road	PWD (Roads)	Gotabari	Gotabari			South Salmara Patakata to Gotabari road submerge various stretches
				Tumni To Fershatary Road	PWD (Roads)	Rajabala Fershertari	Fershatary			Tumni to fershatary road submerge various stretches
				South Salmara Patakata Road	PWD (Roads)	Patakata	Patakata			South salmara To Patakata road submerge various stretches
				Kalabari Bhalukkandi road	PWD (Roads)	Rajabala Bhalukkandi	Bhalukkandi			Kalabari Bhalukkandi road submerge various stretches
				road	PWD (Roads)	Katdanga Satdubi Pt-II	Katdanga			Satdobi to Jinjiram parghat road submerge various stretches
			(Mankacha r   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Tinsukia	0	(Doomdoo ma   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Sadiya   0)		Nil	Nil	Nil	Nil		Nil
			(Margherit a   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Udalguri	0	(Harisinga   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Udalguri   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Khairabari   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
				Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Total	172								
Infrastruct ure			Circle	Bridge Name	Departme nt		Location	de		Remarks
Damaged - Bridge	Barpeta	4	(Kalgachia   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Barpeta   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Chenga   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Baghbar   4)	RCC Br No 7/1	PWD (Roads)	Bhatkuchi	Near Bhatkuchi Bhanga center			As reported by PWD roads dept on 03/07/24 Br approch damaged, side shoulder damaged in Barpeta Baghbar





									road RCC Br No.7/1 in Bhatkuchi.
			RCC Br 1/1	PWD (Roads)	Satrakanara NC	Milijuli to Alengi road			As reported by PWD roads dept on 03/07/24 Br approch damaged, side shoulder damaged in Milijuli to Alengi road RCC Br No.1/1. Location 26.243029, 90.886183
			RCC Br No 10/1	PWD (Roads)	Digirpam	Mandia to Digirpam			As reported by PWD roads dept on 03/07/24 Br approch damaged, side shoulder damaged in Mandia to Digirpam road RCC Br No.10/1. Location-26.346785, 90.9156432
			RCC Br No11/1	PWD (Roads)	Tedhara Pathar	Mandia to Tedhera pathar			As reported by PWD roads dept on 03/07/24 Br approch damaged, side shoulder damaged in Mandia to Tedhera Pathar via Digirpam roa RCC Br No.11/1.
Biswanat h		0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Halem   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Biswanath   0)		Nil	Nil	Nil	Nil	Nil	Nil
Bongaiga on	1		SPT Br. 1/1 on Kuchbari Bazar to Kuchbari Pt-III	PWD (Roads)	Kushbari Pt-I	Kuchbari	90.7	726.28	Water Hyacinth covered. as per report received from PWRD, Dated- 7.07.202
		(Boitamari   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Cachar	0	(Silchar   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Katigorah		Nil	Nil	Nil	Nil	Nil	Nil
		(Sonai   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Charaide	0	(Mahmora		Nil	Nil	Nil	Nil	Nil	Nil
0		0) (Sonari   0)		Nil	Nil	Nil	Nil	Nil	Nil
		(Sapekhati		Nil	Nil	Nil	Nil	Nil	Nil
Chirang	0	0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0)							
	1	(Bijni   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Da :::	0		N I : I	N I C	NI:I	N 1:1	N 1 * 1	N I : I	N I : I
Darrang	0	(Sipajhar   0)	Nil Nil	Nil Nil	Nil Nil	Nil Nil	Nil Nil	Nil Nil	Nil Nil





		(Dalgaon   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Mangaldoi   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dhemaji	0	(Sissiborga on   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Gogamukh   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dhubri	0	(Dhubri   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Gauripur   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Agamoni   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Bilasipara   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Golakganj   0)		Nil	Nil	Nil		Nil	Nil
		0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(South Salmara Part   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Athani   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dibrugar h	0	(Tingkhong   0)		Nil	Nil	Nil	Nil	Nil	Nil
		(Dibrugarh West   0)		Nil	Nil	Nil	Nil	Nil	Nil
		0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Moran   0)		Nil	Nil	Nil		Nil	Nil
		(Naharkatia		Nil	Nil	Nil	Nil	Nil	Nil
		(Dibrugarh East   0)		Nil	Nil	Nil		Nil	Nil
Carlana		(Tengakhat		Nil	Nil	Nil	Nil	Nil	Nil
Goalpara	U	(Matia   0) (Lakhipur   0)		Nil Nil	Nil Nil	Nil Nil	Nil Nil	Nil Nil	Nil Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
Golaghat	0	(Bokakhat   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Khumtai   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Dergaon   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Hailakan di	0	(Hailakandi   0)		Nil	Nil	Nil	Nil	Nil	Nil
		0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil		Nil	Nil
	-	(Katlicherra		Nil	Nil	Nil	Nil	Nil	Nil
Hojai	0		Nil	Nil	Nil	Nil		Nil	Nil
		0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Jorhat	0		Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Jorhat East   0)		Nil	Nil	Nil	Nil	Nil	Nil
Vam	0	West   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Kamrup	U	(Chamaria   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil





Sivasagar	1	(Nazira   0)	Nil RCC Br No7/2 on sepon	Nil PWD	Nil Siklakuti Bhakot	Nil silakuti	Nil	Nil	Nil erosion at b
		0)							
Nalbari	0	0) (Barkhetri	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Nagaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Samaguri   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0)							
		(Dhing   0) (Kampur	Nil Nil	Nil Nil	Nil	Nil Nil	Nil Nil	Nil Nil	Nil
			Nil	Nil	Nil Nil	Nil	Nil	Nil	Nil Nil
9=5		0)							
Nagaon	0	0) (Kaliabor	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Laharighat	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Mayong   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0)		Niil	Niil	Niil	NI:1	Niil	Niil
11		(Morigaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Morigao n	0	(Bhuragaon   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Majuli   0)							
iviajuii	•		Nil	Nil	Nil	Nil	Nil	Nil	Nil
Majuli	0	r   0) (Majuli   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Narayanpu	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0)							
		(North Lakhimpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		a   0)							
		0) (Nowboich	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Subansiri	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		, (Kadam   0)		Nil	Nil	Nil	Nil	Nil	Nil
ur	U	(Binpuria   0)	IVII	INII	1411	I WII	INII	I'VII	I VIII
Lakhimp	0	(Dotma   0) (Bihpuria		Nil Nil	Nil Nil	Nil Nil	Nil Nil	Nil Nil	Nil Nil
		n   0)				A.1.1	A		A col
1		(Gossaigao	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Kokrajha r	0	(Bagribari   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0)							
		0) (Badarpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Karimganj	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		di   0)							
nj		r   0) (Patherkan	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Karimga	0	(Nilambaza	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Chandrapu r   0)	INII	Nil	Nil	Nil	Nil	Nil	Nil
(M)		(Chandranii	NI:I	NII	NEL	Niil	NI:I	NI:I	NII
Kamrup	0		Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Nagarbera   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Rangia   0)		Nil	Nil	Nil	Nil	Nil	Nil
		0)	1411	INII	IVII				
		0) (Palashbari	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Goroimari	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		ì o)							
		(North Ghy	NII	Nil	Nil	Nil	Nil	Nil	Nil





			i .	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0) (Sivsagar	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Sivsagai   O)	IVII	INII	INII	IVII	INII	INII	IVII
	Sonitpur	0	(Tezpur   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Dhekiajuli	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	South	0	0) (South	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Salmara		Salmara							
			0)							
			(Mankacha r   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Tinsukia		(Doomdoo	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			ma   0)							
			(Sadiya   0)			Nil	Nil			Nil
			(Margherit a   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Udalguri		a   0) (Harisinga	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)							
			(Udalguri	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0) (Khairabari	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)							
			(Kalaigaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Total	6	0)							
Infrastruct			Revenue	Embankment Breached	Departme	Village	Location	Longitu	Latitude	Remarks
ure	District		Circle	Name	nt	· mage		de	Latitude	remarks
Damaged -	Barpeta	0	(Kalgachia	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Embankm ent			0)	A.C.I	A L'I	N. C.	A L'I	A 1 " 1	N 1*1	N I T
Breached			(Barpeta   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Chenga	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0) (Baghbar	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Bagiibai   O)	IVII	INII	INII	INII	INII	INII	INII
	Biswanat	0	(Gohpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	h		0) (Halem   0)	Niil	Nil	Nil	Nil	Nil	Nil	Nil
			(Biswanath			Nil	Nil	Nil		Nil
			0)							
	Bongaiga	0	(Srijangram	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	on		0) (Boitamari	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)							
	Cachar	0	(Silchar   0)		1	Nil	Nil			Nil
			(Katigorah   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
				Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Charaide	0	(Mahmora	Nil	Nil	Nil	Nil	1		Nil
	o		(Sonari   0)	Niil	Niil	Nil	Nil	Niil	Niil	Nil
			(Sonari   0) (Sapekhati			Nil	Nil			Nil Nil
			0)					[ "	. • • • • • • • • • • • • • • • • • • •	
	Chirang		(Bengtal	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0) (Bijni   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Darrang			Nil		Nil	Nil			Nil
	6		0)							
				Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Mangaldai   0)							
				Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)	NI:I	N I : I	NI:I	NISI	NI:I	N I : I	N I : I
			(Mangaldoi   0)	NII	Nil	Nil	Nil	Nil	Nil	Nil
			Ι <i>'')</i>		1			1	l	





Dhemaji	0	(Sissiborga	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		on   0)							
			Nil	Nil	Nil	Nil	Nil		Nil
		(Gogamukh   0)		Nil	Nil	Nil	Nil		Nil
		(Dhemaji   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dhubri	0	(Dhubri   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Gauripur		Nil	Nil	Nil	Nil		Nil
		0) (Agamoni	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0) (Golakganj	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		1	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(C - · · + l-	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(South Salmara Part   0)	INII	NII	INII	NII	NII	INII	INII
		(Athani   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dibrugar	0	(Tingkhong		Nil	Nil	Nil	Nil		Nil
h	Ī	0)	* ***	[	[		[ ···		<u> </u>
		(Dibrugarh West   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Moran   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Naharkatia   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Dibrugarh East   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Tengakhat	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Goalpara	0	(Matia   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Lakhipur   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
Golaghat	0	(Bokakhat   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Khumtai   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Dergaon   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Hailakan di	0	(Hailakandi   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Katlicherra   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Hojai	0		Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil		Nil
Jorhat	0		Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Jorhat East		Nil	Nil	Nil	Nil		Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
Kamrup	0		Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Kamalpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(North Ghy	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Ì		0)		1	l "				1





	(Goroimari	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	0) (Palashbari	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	0)							
	(Rangia   0)							Nil
	(Nagarbera   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Nil	Nil	Nil	Nil	Nil	Nil	Nil
Kamrup 0 (M)	(Sonapur   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
(***,	(Chandrapu r   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Karimga 0	(Nilambaza	Nil	Nil	Nil	Nil	Nil	Nil	Nil
nj	r   0) (Patherkan	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	di   0) (Karimganj	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	0) (Badarpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Kokrajha 0	0) (Bagribari	Niil	Nil	Nil	Nil	Nil	Nil	Nil
r	0)							
	(Gossaigao n   0)							Nil
	(Dotma   0)							Nil
Lakhimp 0 ur	(Bihpuria   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	(Kadam   0)							Nil
	(Subansiri   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	(Nowboich a   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Nil	Nil	Nil	Nil	Nil	Nil	Nil
	0)							
	(Narayanpu r   0)		Nil			Nil	Nil	Nil
Majuli 0	(Majuli   0)					Nil		Nil
	(Ujani Majuli   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Morigao 0 n	(Bhuragaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	(Morigaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	(Mayong	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	0) (Laharighat	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Nagaon 0	1	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	0) (Raha   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	(Dhing   0)							Nil
	(Kampur	Nil						Nil
	0) (Samaguri	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Nil	Nil	Nil	Nil	Nil	Nil	Nil
Nalbari 0	0) (Barkhetri	Nil	Nil	Nil	Nil	Nil	Nil	Nil
i I	0)	Niil	Nil	Nil	Nil	Nil	Nil	Nil
Sivasaara		וואון	INII					Nil Nil
Sivasagar0	(Nazira   0)		Nil	Niil	Nil	Niil	Niil	
Sivasagar 0	(Sonari RC part   0)	Nil						
Sivasagar0	(Sonari RC part   0) (Demow   0)	Nil Nil	Nil	Nil	Nil	Nil	Nil	Nil Nil





	Sonitpur	h	(Tezpur   0)	Niil	Nil	Nil	Nil	Nil	Nil	Nil
	Somtpur	U								
			(Dhekiajuli   0)	IVII	Nil	Nil	Nil	Nil	Nil	Nil
	South	0		Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Salmara		Salmara	IVII	IVII	IVII	IVII	INII	INII	IVII
			0) (Mankacha	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Tinsukia		r   0) (Doomdoo	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			ma   0) (Sadiya   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Margherit a   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Udalguri	0	(Harisinga   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			,	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Khairabari   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Kalaigaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Total	0	0)							
Infrastruct ure		Number	Revenue Circle	Embankment Affected Name	Departme nt	Village	Location		Latitude	Remarks
Damaged - Embankm	Barpeta		(Kalgachia   0)			Nil	Nil	<b>de</b> Nil	Nil	Nil
ent Affected				Nil	Nil	Nil	Nil	Nil	Nil	Nil
Anceted				Nil	Nil	Nil	Nil	Nil	Nil	Nil
			,	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Biswanat b			Nil	Nil	Nil	Nil	Nil	Nil	Nil
	"		(Halem   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Biswanath	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			0)							
	Bongaiga on	0	(Srijangram   0)			Nil	Nil	Nil		Nil
			(Boitamari   0)		Nil	Nil	Nil	Nil	Nil	Nil
	Cachar		(Silchar   0)		Nil	Nil	Nil	Nil	Nil	Nil
			(Katigorah   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Sonai   5)	to Tillanagar	Water Resource Deptt.	Islamabad	Islamabad , Saptagram, Ramprasadpur			Dyke along L/B of river Sonai from S.M. Road to Dharmikhal (L/B of Rukni) Length - 250 M, As reported by WRD Silchar on dated 07.07.2024
					Water Resource Deptt.	Punirmukh	Punirmukh Sluice, RukniPt-II			Dyke along L/B of river Sonai from S.M. Road to Dharmikhal (R/B of Rukni) Length - 20 m, As reported by WRD Silchar on dated 07.07.2024
				Dyke along R/B of river Sonai from Palonghat to Upwards	Water Resource Deptt.	Bongram	Bontarapur	92.91	24.64	Dyke along R/B of river Sonai from Palonghat to Upwards, length-80m , As reported by WRD





									Silchar on dated 07.07.2024,
			Dyke along L/B of river Sonai from S.M. Road to Dharmikhal	Water Resource Deptt.		"Chandpur, Nagdirgram Pt. II, Tulargram	92.88	24.69	Dyke along L/B o river Sonai from S.M. Road to Dharmikhal, Length- 550 M, As reported by WRD Silchar on dated
Charaide	0	(Mahmora	Nil	Nil	Nil	Nil	Nil	Nil	07.07.2024, Nil
0		0) (Sonari   0)	Niil	Nil	Nil	Nil	Nil	Nil	Nil
		(Sapekhati		Nil	Nil	Nil		Nil	Nil
		0)							
Chirang	0	(Bengtal   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		-	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Darrang	0		Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0) (Pub-	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Mangaldai   0)							
		0)	Nil	Nil	Nil	Nil		Nil	Nil
		(Mangaldoi   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dhemaji	0	(Sissiborga on   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil		Nil	Nil
		(Gogamukh   0)		Nil	Nil	Nil		Nil	Nil
		(Dhemaji   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dhubri	0	(Dhubri   0)		Nil	Nil	Nil		Nil	Nil
		(Gauripur   0)		Nil	Nil	Nil		Nil	Nil
		(Agamoni   0)		Nil	Nil	Nil		Nil	Nil
		(Bilasipara   0)		Nil				Nil	Nil
		(Golakganj   0)		Nil	Nil	Nil		Nil	Nil
		0)	Nil	Nil	Nil	Nil		Nil	Nil
		(South Salmara Part   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Athani   0)		Nil	Nil	Nil		Nil	Nil
Dibrugar h	0	(Tingkhong		Nil	Nil	Nil		Nil	Nil
		(Dibrugarh West   0)		Nil	Nil	Nil		Nil	Nil
		0)	Nil	Nil	Nil	Nil		Nil	Nil
		(Moran   0)		Nil	Nil	Nil		Nil	Nil
		(Naharkatia   0)		Nil	Nil	Nil		Nil	Nil
		(Dibrugarh East   0)		Nil	Nil	Nil		Nil	Nil
		(Tengakhat   0)		Nil	Nil	Nil		Nil	Nil
Goalpara	0	(Matia   0)		Nil	Nil	Nil		Nil	Nil
	Ì	(Lakhipur	Nil	Nil	Nil	Nil	Nil	Nil	Nil





i '			Nil	Nil	Nil	Nil	Nil	Nil	Nil
Golaghat	n	0) (Bokakhat	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Golagilat		(DOKAKHAT   0)	IVII		IVII				1411
		(Khumtai   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Dergaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Hailakan di	0	0) (Hailakandi   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
ui		(Algapur	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0) (Lala   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Katlicherra			Nil				Nil
Haiai	0	0)	Nil	Nil	Nil	NI:1	Nil	Nil	Nil
Hojai	0		Nil		Nil				Nil
		0)							
Jorhat	0		Nil		Nil				Nil
		(Jorhat East   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
.,		West   0)	A.U.		A 171	h.e.			
Kamrup	U	(Chamaria   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(North Ghy	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Goroimari	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Palashbari   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Rangia   0)		Nil	Nil	Nil	Nil	Nil	Nil
		(Nagarbera   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Nil		Nil				Nil
Kamrup (M)	0	0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Chandrapu r   0)		Nil	Nil	Nil	Nil	Nil	Nil
Karimga	0	(Nilambaza r   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
nj		(Patherkan di   0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		(Karimganj	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		0) (Badarpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil
							1	I	
Kokrajha 	0	0) (Bagribari	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Kokrajha r	0	(Bagribari   0) (Gossaigao			Nil Nil				Nil Nil
Kokrajha r	0	(Bagribari   0)	Nil	Nil		Nil	Nil	Nil	
r Lakhimp		(Bagribari   0) (Gossaigao n   0) (Dotma   0) (Bihpuria	Nil Nil	Nil Nil	Nil	Nil	Nil Nil	Nil Nil	Nil
r		(Bagribari   0) (Gossaigao n   0) (Dotma   0) (Bihpuria   0)	Nil Nil Nil	Nil Nil Nil	Nil Nil Nil	Nil Nil Nil	Nil Nil Nil	Nil Nil Nil	Nil Nil
r Lakhimp		(Bagribari   0) (Gossaigao n   0) (Dotma   0) (Bihpuria   0) (Kadam   0) (Subansiri	Nil Nil Nil	Nil Nil Nil Nil	Nil Nil	Nil Nil Nil	Nil Nil Nil Nil	Nil Nil Nil	Nil Nil
r Lakhimp	0	(Bagribari   0) (Gossaigao n   0) (Dotma   0) (Bihpuria   0) (Kadam   0) (Subansiri   0) (Nowboich	Nil Nil Nil Nil	Nil Nil Nil Nil	Nil Nil Nil	Nil Nil Nil Nil	Nil Nil Nil Nil	Nil Nil Nil Nil	Nil Nil Nil
r Lakhimp	0	(Bagribari   0) (Gossaigao n   0) (Dotma   0) (Bihpuria   0) (Kadam   0) (Subansiri   0) (Nowboich a   0) (North	Nil Nil Nil Nil	Nil Nil Nil Nil Nil	Nil Nil Nil Nil	Nil Nil Nil Nil	Nil Nil Nil Nil Nil	Nil Nil Nil Nil Nil Nil	Nil Nil Nil Nil
r Lakhimp	0	(Bagribari   0) (Gossaigao n   0) (Dotma   0) (Bihpuria   0) (Kadam   0) (Subansiri   0) (Nowboich a   0)	Nil Nil Nil Nil Nil Nil	Nil Nil Nil Nil Nil Nil Nil	Nil Nil Nil Nil Nil	Nil Nil Nil Nil Nil Nil	Nil Nil Nil Nil Nil Nil Nil	Nil Nil Nil Nil Nil Nil Nil	Nil Nil Nil Nil Nil





2) embankment of Mitong Resource Bukajan Bank River was occurred at Deptt. Demoruguri area due to Seepage and lekage etc. Demoruguri area due to Seepage and lekage etc.	
0     0	
Mayong   O	
Claharighat Nii	
Nagaon   O	
(Dhing   0) Nil	
(Kampur   Nil	
O)   (Samaguri   Nil	
O)   (Nagaon   Nil   N	
Nalbari O (Barkhetri   Nil	
O) Sivasagar 3  (Nazira   1) Bahgarh to A.T road  Water Resource Deptt.  (Sonari RC part   0) (Demow   Nil	
Sivasagar 3 (Nazira   1) Bahgarh to A.T road Water Resource Deptt.  (Sonari RC part   0) (Demow   Nil	
(Sonari RC part   0)  (Demow   Nil	
(Demow   Nil	
(Sivsagar   Damage of Left Bank Water Napamua Napam Bukajan 94.4526.96 Damag Bank embankment of Mitong Resource Bukajan Deptt.  Demoruguri area due to Seepage and lekage etc.	
Damage of embankment of Dorika River from Bhagarh to AT road and AT road to Dhai ali was occured at Khatopathar and Kathpar area due to Seepage and lekage etc.  Water Resource Deptt.  Water Resource Whatopathar and Watopathar area due to Seepage and lekage etc.  Water Resource Whatopathar Dorika Bhagar road are to Dhai occured that the part of	guri area eepage ige report I from artment 7-2024 of ment of civer from to AT d AT road ali was at thar and area due age and tc. The eccived R anent on
Sonitpur 0         (Tezpur   0) Nil	
0	
Salmara   Salmara   0)	
(Mankacha Nil	
Tinsukia 0 (Doomdoo Nil	
(Sadiya   0) Nil Nil Nil Nil Nil Nil Nil Nil	





_	1	1		1		1	I	1	1	1	I .
			(Margherit a   0)	Nil		Nil	Nil	Nil	Nil	Nil	Nil
	Udalguri		(Harisinga   0)	Nil		Nil	Nil	Nil	Nil	Nil	Nil
			, (Udalguri   0)	Nil		Nil	Nil	Nil	Nil	Nil	Nil
			, (Khairabari   0)	Nil		Nil	Nil	Nil	Nil	Nil	Nil
				Nil		Nil	Nil	Nil	Nil	Nil	Nil
	Total	8	,								
Infrastruct	District	Revenue	Damages	Numb	Name	Departme	Village	Location	Longitu	Latitude	Remarks
ure		Circle		er		nt			de		
Damaged -	Barpeta	Kalgachia	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Others		Barpeta	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Chenga	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Baghbar	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Biswanat	Gohpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	h	Halem	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Biswanath	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Bongaiga		Nil		Nil	Nil	Nil	Nil	Nil	Nil	Nil
	on	m									
		Boitamari	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Cachar	Silchar	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Katigorah	Nil		Nil	Nil	Nil			Nil	Nil
			Fisheries/P	1	Fishery Damage	Fishery	Panichowki	Palonghat			34 Nos of Fish
	Charaida		ond (in Hect.)		Report  GRAVELLING AT	P&RD					Farmers affected, Total area affected 8.20 Hactor. as reported by District Fishery Development Officer on dated 07.07.2024. Infrastructure
	o o		Canal/Sche me Damaged		BISHRAMPUR JATIYA VIDYALYA APPROACH ROAD		Jajalihabi	Desangpani, Desangpani GP			Damaged of 15th F.C.
			(in Nos)		Construction of Amrit Sarovar at Hingrijan Telbari line	P&RD	1 No. KhoomtaiT.E.	Telbari line, Khumtai GP	94.95	27.14	Infrastructure Damaged of Amrit Sarovar
					Amrit Sarovar at Khumtai	P&RD	1 No. KhoomtaiT.E.	Bamline, Khumtai GP	94.96	27.15	Infrastructure Damaged of Amrit Sarovar
					Construction of Amrit Sarovar at Biptaghat	P&RD	1 No. KhoomtaiT.E.	Biptaghat, Khumtai GP	94.97	27.16	Infrastructure Damaged of Amrit Sarovar
						P&RD	Niz Khaloighugura	Sagarbera, Nizkhaloighugura GP	94.85	27.03	Infrastructure Damaged of Amrit Sarovar
					·	P&RD	LaichengGaon	Laichang, Nizkhaloighugura GP	94.9	27.05	Infrastructure Damaged of Amrit Sarovar
						P&RD	Jajali Gaon	Desangpani GP			Infrastructure Damaged of 14th F.C.
					KRISHNA BARBARUAH	P&RD	Likson Gaon	LIKSON, Bhoralipukhuri GP	95.02	27.1	Infrastructure Damaged of PMAY-G Individual House
					BIJULI KISHAN	P&RD	Dadhora Cheleng	DADHARA, Bhoralipukhuri GP	95.01	27.11	Infrastructure Damaged of PMAY-G Individual House





BIBHISAN KISHAN	P&RD	Dadhora Cheleng	DADHARA, Bhoralipukhuri GP	95.0127.11	Infrastructure Damaged of PMAY-G Individual House
RITU MONI GOGOI	P&RD	Konowar Gaon	KONWAR GAON, Bhoralipukhuri GP	94.9927.09	Infrastructure Damaged of PMAY-G Individual House
PURNIMA BORAH	P&RD	Japidhara Gaon	JAPIDHARA, Bhoralipukhuri GP	95.0127.07	Infrastructure Damaged of PMAY-G Individual House
AGRIBANDH CHANDRAJYOTI TO LASAIHABI	P&RD	Jajalihabi	JAJALIHABI, Desangpani GP	27.07	Infrastructure Damaged of MGNREGA
DEV OF NAKUL BARUAH PATH	P&RD	Jajalihabi	JAJALIHABI, Desangpani GP	94.9427.08	Infrastructure Damaged of MGNREGA
LAND DEV. AT BLOCK HEAD QUARTER CAMPUS		Dhemajibil Gaon	DHEMAJI BEEL, Desangpani GP		Infrastructure Damaged of MGNREGA
CONSTRUCTION A EARTH RAISE PLATFORMAT BLOCK HEAD QUARTER	P&RD	Dhemajibil Gaon	DHEMAJI BEEL, Desangpani GP	94.9527.05	Infrastructure Damaged of MGNREGA
AGRIBANDH AT MOHAN DEODHAI SANTIPUR TO HIGHLAND	P&RD	Mohan Deodhai	MOHAN DEODHAI, Desangpani GP	94.9427.05	Infrastructure Damaged of MGNREGA
DUMURU TINIALI TO BETONICHUK	P&RD	Bonamali T.E.	BONOMALI, Desangpani GP	94.9527.05	Infrastructure Damaged of MGNREGA
LAND DEV. AT BLOCK HEAD QUARTER CAMPUS PH 2		Dhemajibil Gaon	Desangpani GP	94.9227.04	Infrastructure Damaged of MGNREGA
MONIKA TINIALI TO BETONICHUK	P&RD	Bonamali T.E.	BONOMALI, Desangpani GP	94.9527.05	Infrastructure Damaged of MGNREGA
AGRIBANDH SILONITING TO MOINAMOTI PH 2	P&RD	Mohan Deodhai	SILONITING, Desangpani GP		Infrastructure Damaged of MGNREGA
SAFETY FENCING AT SANTIPUR VILLAGE ENTRY ROAD WITH PLANTATION	P&RD	Mohan Deodhai	MOHAN DEODHAI, Desangpani GP	94.9227.05	Infrastructure Damaged of MGNREGA
AGRIBUNDH AT BHADHARACHUK PADDY FIELD TO MOHANCHUK	P&RD	Jajalihabi	JAJALI HABI, Desangpani GP	94.9327.08	Infrastructure Damaged of MGNREGA
DE. OF AGRIBANDH AT BETONICHUK	P&RD	Bonamali T.E.	BONOMALI, Desangpani GP	94.9527.05	Infrastructure Damaged of MGNREGA
AGRIBANDH AT AKASH BARUAH PATH	P&RD	Mohan Deodhai	SILONITING, Desangpani GP	94.9727.08	Infrastructure Damaged of MGNREGA
PODMA BARUAH	P&RD	Mohan Deodhai	MOHAN DEODHAI, Desangpani GP	94.9427.04	Infrastructure Damaged of PMAY-G Individual House
MONI DAS	P&RD	Mohan Deodhai	MOHAN DEODHAI, Desangpani GP		Infrastructure Damaged of PMAY-G Individual House
BIRESWAR DAS	P&RD	Mohan Deodhai	MOHAN DEODHAI, Desangpani GP		Infrastructure Damaged of PMAY-G Individual House
MOUSUMI DAS	P&RD	Mohan Deodhai	MOHAN DEODHAI, Desangpani GP	94.9427.04	Infrastructure Damaged of





						PMAY-G
	i i					Individual House
	RUPALI DAS	P&RD	Mohan Deodhai	MOHAN DEODHAI,		Infrastructure
				Desangpani GP		Damaged of
				=-		PMAY-G
						Individual House
	PURNIMA DAS	P&RD	Mohan Deodhai	MOHAN DEODHAI,		Infrastructure
				Desangpani GP		Damaged of
						PMAY-G
						Individual House
	BABITA PHUKAN	P&RD	Buragohainbari	BURAGOHAINBARI,	94.9427.05	Infrastructure
				Desangpani GP		Damaged of
						PMAY-G
						Individual House
	PITAMBER BHYAN	P&RD	Bonamali T.E.	BONOMALI, Desangpani		Infrastructure
				GP		Damaged of
						PMAY-G
						Individual House
	DIPIKA DAS	P&RD	Mohan Deodhai	MOHAN DEODHAI,		Infrastructure
				Desangpani GP		Damaged of
						PMAY-G
						Individual House
	BUBU MUNDA	P&RD	Bonamali T.E.	BONOMALI, Desangpani		Infrastructure
				GP		Damaged of
						PMAY-G
						Individual House
	MANGAL SINGH	P&RD	Bonamali T.E.	BONOMALI, Desangpani		Infrastructure
	MALI			GP		Damaged of
						PMAY-G
						Individual House
	IPTAR BARJO	P&RD	Kachupathar	KACHUPATHER,	94.9427.04	Infrastructure
			Gaon	Desangpani GP		Damaged of
						PMAY-G
						Individual House
	DIPJYOTI BOURAH	P&RD	Jajalihabi	JAJALIHABI, Desangpani		Infrastructure
				GP		Damaged of
						PMAY-G
						Individual House
	MIRA ORANG	P&RD	Dhemajibil Gaon			Infrastructure
				Desangpani GP		Damaged of
						PMAY-G
	Bus-2	5055			04 5 15= -:	Individual House
	PUNESHER PHUKON	r&RD	Jajalihabi	JAJALIHABI, Desangpani	94.9427.05	Infrastructure
				GP		Damaged of
						PMAY-G
	DIRAAAIAAC	D 0 C C	Lata Director	IAIAI III ABI B	04 00 07 05	Individual House
	BIMAN MOHAN	P&RD	Jajalihabi	JAJALIHABI, Desangpani	94.9327.05	Infrastructure
				GP		Damaged of PMAY-G
						Individual House
	MONTH CHETIA	P&RD	laialihah:	IAIAIIHADI Docasasas		Individual House
1	MONTU CHETIA	raku	Jajalihabi	JAJALIHABI, Desangpani		
				GP		Damaged of PMAY-G
						Individual House
	USHA MOHAN	P&RD	Jajalihabi	JAJALIHABI, Desangpani		Infrastructure
		ו מאט	pajamiaui	GP		Damaged of
	OSHA WOHAN			O1		PMAY-G
	OSHA WOHAN			i l	i	FIVIAT-G
	OSTIA WOTIAN					Individual House
		D& RU	lajalihahi	IAIAI IHARI. Dasangnani	94 9427 00	Individual House
		P&RD	Jajalihabi	JAJALIHABI, Desangpani	94.9427.09	Infrastructure
		P&RD	Jajalihabi	JAJALIHABI, Desangpani GP	94.9427.09	Infrastructure Damaged of
		P&RD	Jajalihabi		94.9427.09	Infrastructure Damaged of PMAY-G
	KHAGEN PHUKON			GP		Infrastructure Damaged of PMAY-G Individual House
	KHAGEN PHUKON	P&RD P&RD		GP JAJALIHABI, Desangpani	94.9427.09	Infrastructure Damaged of PMAY-G Individual House Infrastructure
	KHAGEN PHUKON			GP		Infrastructure Damaged of PMAY-G Individual House Infrastructure Damaged of
	KHAGEN PHUKON			GP JAJALIHABI, Desangpani		Infrastructure Damaged of PMAY-G Individual House Infrastructure Damaged of PMAY-G
	KHAGEN PHUKON PUNESHER CHETIA		Jajalihabi	GP JAJALIHABI, Desangpani		Infrastructure Damaged of PMAY-G Individual House Infrastructure Damaged of





							PMAY-G
							Individual House
	PUNA PHUKON	P&RD	Jajalihabi	JAJALIHABI, Desangpani			Infrastructure
				GP			Damaged of
							PMAY-G
	BISON MUNDA	P&RD	Bonamali T.E.	BONOMALI, Desangpani	04.05	27.09	Individual House Infrastructure
	BISON WIONDA	FAND	Bonaman 1.L.	GP	34.33	27.03	Damaged of
							PMAY-G
							Individual House
	PAPORI PHUKON	P&RD	Jajalihabi	JAJALIHABI, Desangpani			Infrastructure
				GP			Damaged of
							PMAY-G
							Individual House
		P&RD	Jajalihabi	JAJALIHABI, Desangpani			Infrastructure
	PHUKON			GP			Damaged of
							PMAY-G
	AAUL BARING	00.00		KACIUIDATUED			Individual House
	ANIL BADING	P&RD	Kachupathar	KACHUPATHER,			Infrastructure
			Gaon	Desangpani GP			Damaged of PMAY-G
							Individual House
	PONKAJ MOHAN	P&RD	Jajali Gaon	JAJOLIGAON,	94.93	27.06	Infrastructure
	i civio s ivicinati	I WILD	Jujun Guon	Desangpani GP	31.33	27.00	Damaged of
				Jan Oliva			PMAY-G
							Individual House
	DIPA BHUYAN	P&RD	Dhemajibil Gaon	DHEMAJI BEEL,	94.93	27.06	Infrastructure
				Desangpani GP			Damaged of
							PMAY-G
							Individual House
	SANJAY BHUYAN	P&RD	Dhemajibil Gaon		94.94	27.05	Infrastructure
				Desangpani GP			Damaged of
							PMAY-G Individual House
	MUNU GARH	P&RD	Garkush	GARKUSH, Desangpani	0/ 01	27.06	Infrastructure
	MONO GARIT	FOND	Garkusii	GP	34.31	27.00	Damaged of
							PMAY-G
							Individual House
	RAJ KUMAR	P&RD	Dhemajibil Gaon	DHEMAJI BEEL,	94.95	27.09	Infrastructure
			-	Desangpani GP			Damaged of
							PMAY-G
							Individual House
	JOSHUDA BHUYAN	P&RD	Dhemajibil Gaon		94.93	27.06	Infrastructure
				Desangpani GP			Damaged of
							PMAY-G
	27// : 0/ / 12	- 1 .:					Individual House
Elementary Schools			Buragohainbari	Kakowani Chuk LP School			
Damaged	School Disangporia LP	Deptt.	Kakotibari habi	Disangporia LP School			
(in Nos)	School	Deptt.	Kakutibari ilabi	Disalignolia LP School			
(	Mahmara MV School		Frabari	Mahmara MV School			
		Deptt.					
	Bhalukaguri Adarsha		Bhalukaguri habi	Bhalukaguri Adarsha LP			
	LP School	Deptt.	Gaon	School			
	Late Durgeswar	Education	Dhemajibil Gaon	Late Durgeswar Phukan			
	Phukan LP School	Deptt.		LP School			
	2 No,Hatimuria LP	Education	Hatimuria	2 No,Hatimuria LP			
	School	Deptt.	Pathar	School			
			_	Bhalukaguri Nepali Bosti			
	Bosti LP School	Deptt.	Gaon	LP School			
	Chetrikorna LP		Bonamali T.E.	Chetrikorna LP School			
	School	Deptt.					ļ
			Desangkushhabi	2 No,Chengelimora LP			
	LP School	Deptt.	Erahari	School			+
	Sr Secondary School Mahmora	Education Deptt.	Erapari	Sr Secondary School Mahmora			
			Dhemaiihil Gaan	Dhemaji Desangpani HS			
	HS School	Deptt.	Diremajivii GaOII	School			
1 1			1			1	1





1		Engineering			Ī	Ī	i l			ĺ
	Sonari	Public Health		RETROFITTING OF MOHAN GAON	PHE	Mohan Gaon	SONARI			SUBMERGED
	Cono-:	Dublic		Chiloniting PWSS	PHE	Erabari Mohan Gaon	Chiloniting PWSS	94.97	27.08	CLIDAACDOCCO
					PHE	Konowar Gaon	Konwar Gaon PWSS	94.99		
				Vanuar Caar DIAGO	DHE	Gaon Kanawar Gaon	Vonuar Gaan DMCC	04.00	27.07	
				Bahboria Habi Gaon	PHE	Bahboria Habi	Bahboria Habi Gaon			
				Dhemajibil PWSS	PHE	Dhemajibil Gaon	Dhemajibil PWSS	94.92	27.05	
				Japidhara PWSS	PHE	Japidhara Gaon	Japidhara PWSS	95.02	27.07	
				Doba Grant	PHE	Doba Grant	Doba Grant		27.08	
				Borbill No2	PHE	Borbil No.2	Borbill No2	94.96	27.09	
					PHE	Kakotibari habi	Kakotibari Habi PWSS	95.03	27.07	
		(in Nos)		Hatimuria Pathar PWSS	PHE	Kakotibari habi	Hatimuria Pathar PWSS			
		Damaged	10			Grant		33.07	∠/. <b>1</b> 1	
		PWSS		School Timon T.E PWSS	Deptt. PHE	TimonHabi	Timon T.E PWSS	95.07	27 11	
				Mahmora High	Education	Erabari	Mahmora High School			
				Likson Japidhora LP Schoo	Education Deptt.	Likson Gaon	Likson Japidhora LP Schoo			
				LP School	Deptt.	Likson Gaon	School			
				1046 No, Moinapa	Deptt. Education	Japidhara Gaon	1046 No, Moinapa LP			
				Japidhora LP School		Japidhara Gaon	Japidhora LP School			
				School	Deptt.	papianara Gaon	Taxotiouri iviv ociiooi			
				School Kakotibari MV	Deptt. Education	Lawjan Gaon Janidhara Gaon	Kakotibari MV School			
				Garh Basti MV		Khukamara	Garh Basti MV School			
				Sistinusan Li 3	Deptt.	Grant	DISTITUDUIT ET S			
				Bishnubari LPS	Deptt. Education	TimonHabi	Bishnubari LPS			
				37 No Kundaru LPS	Education	Borbil No.1	37 No Kundaru LPS			
				Orianighat LPS	Education Deptt.	TimonHabi Grant	Uriamghat LPS			
				Uriamghat LPS	Deptt.	Pathar TimonHabi	Uriamaha+ LDC			
				Hatimuria LPS	Education		Hatimuria LPS			
				Disangporia LP School	Education Deptt.	Kakotibari habi	Disangporia LP School			
					Deptt.	-				
				LP Schoo Jojolihabi LP School	Deptt. Education	Jajalihabi	Schoo Jojolihabi LP School			
				No 2 Parachani Habi		Parachonihabi	No 2 Parachani Habi LP			
				628 No Mohan Deodhai LP School	Education Deptt.	INIOHAN DEOGNAL	628 No Mohan Deodhai LP School			
				629 No Mahar	Deptt.	Mohan Daraka	C29 No Mober Deadle			
				Moranjan LP School		Moranjan Gaon	Moranjan LP School			
				Bonomali TE LP School	Education Deptt.	Bonamali T.E.	Bonomali TE LP School			
				School	Deptt.	_	School			
				SChool Buragohainbari LP	Deptt. Education	Buragohainbari	Buragohainbari LP			
						Bonamali T.E.	Tawkokmukh LP SChool			
				School	Deptt.	Grant	School			
				LP School  Doomur Dullong MS	Deptt. Education	Gaon Doomardolang	School Doomur Dullong MS			
				Bhuyanline Mazdue			Bhuyanline Mazdue LP			
				IVIOIIIIIIOU EF SCHOOL	Deptt.	Konowai Gaon	IVIOIIIIIOti EF SCHOOL			
				Moinmoti LP School	Deptt.	Konowar Gaon	Moinmoti LP School			
				Borbil ME School		Borbil No.1	Borbil ME School			
				Borhula Kush LP School	Education Deptt.	Kachupathar Gaon	Borhula Kush LP School			
				H School	Deptt.		School			
							Milonpur Deogharia H			
				School	Deptt.	Kachupathar Gaon				





		(PHE) (in Nos)		SINGARITALI PWSS	PHE	Singarajan Bagicha	SONARI			SUBMERGED
		1403)			PHE	Nara Gaon	LAKWA			SUBMERGED
	Canaldaati	N I : I	NI:I	PWSS	N I : I	Nil	NI:I	NI:I	N I I I	NI:1
	Sapekhati		Nil		Nil		Nil	Nil	Nil	Nil
_	Bengtal	Nil	Nil		Nil	Nil	Nil	Nil	Nil	Nil
	Bijni	Nil	Nil		Nil	Nil	Nil	Nil	Nil	Nil
Darrang		Nil	Nil		Nil	Nil	Nil	Nil	Nil	Nil
	Pub- Mangalda i	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Dalgaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Mangaldo i	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Sissiborga on	PWSS Damaged (in Nos)	-	Sunarighat PWSS	РНЕ	Sunarighat	At No.2 Sunarighat.	94.77	27.51	Damage of Distribution lii Approach Roa FHTC damage approximately Nos, Silting ov Drain and Plin Protection wo Population effected is 350 (Approx.) Date on 02-07-2024
	Jonai	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Ì				Nil	Nil	Nil	Nil		Nil	Nil
	Gogamuk	INII	Nil	INII	INII	INII	INII	Nil	INII	INII
	n Dhemaji	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Dhubri	Dhubri	Fisheries/P ond (in Hect.)		Fisheries farmer Name-Elias Hoque S/O-S/O-Lt. Sahid Ali	Fishery	FalimariPt.II	Falimari Pt-II	89.97	26.05	Damaged due flood, 35 Hect
				Name Abdul Monnaf S/O-Lt. Sahid Ali		FalimariPt.II	Falimari Pt-II	89.97	26.65	Damaged due flood, 25 Hect
				Fisheries farmer Name-Nur Islam S/O-S/O-Lt. Amzad Ali	Fishery	Kismathasdaha Pt.II	Kismathasdaha Pt-II	89.88	26.05	Damaged due flood, 15 Hect
				Fisheries farmer Name-Enamul Hoque S/O-S/O-Lt. Sahid Ali	Fishery	FalimariPt.II	Falimari Pt-II			Damaged due flood, 25 Hect
				Fisheries farmer	Fishery	Kismathasdaha	Kismathasdaha Pt-II			Damaged due
				Name-Moynul Hoque S/O-S/O-Lt. Aynal Hoque		Pt.II				flood, 15 Hect
	Gauripur	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Agamoni	Bridge Approach Road Damaged (in Nos)	-	IRCC BRIDGE NO. 1/1 DAMAGED ON RANPAGLI TO CHAR RANPAGLI ROAD	PWD (Roads)	Jhapushabari Pt 3	Jhapushbari Pt-3	89.73	26.19	SIDE SHOULD OF APPROACH OF RCC BRIDG NO. 1/1 DAMAGED ON RANPAGLI TO CHAR RANPAG ROAD due to heavy rainfall
	Bilasipara	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Golakganj			2Const. of Amrit Sarovar at village Bahakati for pisciculture alongwith plantation and beautification (ID No 767)	P&RD	Bahakati	Bahakati			Due to the flo water level had been increase the area and the mentioned Ar Sarovar is presently und the water and





 		1		<del>,                                      </del>	T T
					constructed soil
					bank of the Amrit
					Sarovar has been
					highly affected.
		P&RD	West Ratidaha	Pachim Ratiadaha Pt-III	Due to the flood,
	Sarovar at village		Pt.III		water level has
	Pachim Ratiadaha				been increased in
	Pt-III Naldoba Beel				the area and all
	for Pisciculture				these three Amrit
	alongwith Plantation				Sarovar are
	and Beautification				presently under
	(ID No 5371)				the water and for
					which newly
					constructed soil
					bank of these
					Amrit Sarovar
					have been highly
					affected.
Agri Bundh	18MGNREGA 2022-23).	P&RD	Purni	Puri	Damaged in
Damaged	Construction of Agril				earth work
(in Nos)	bundh start from				
	Sibendra Nath Ray				
	Land to Manasha				
	Mandir via Harikanta				
	Ray Land at Vill –				
	Purni				
	(MGNREGA 2020-	P&RD	Pub-	Pub Marragadadhar	Damaged in
	21). Const of		Moragodadhor		earth work
	Irrigation Canal from				
	Hanif Alis Land Via				
	Sahid Alis Land to				
	River Near Honufa				
	Bewas Land				
	0401001/IC/901025				
	4701				
	(MGNREGA 2023-	P&RD	West Kanuri Pt.	West Kanuri Pt.III	Damaged in
	24). Construction of		Ш		earth work
	Agril bundh from				
	Sudhir Ray house to				
	International Market				
	road via Dulal house				
	(MGNREGA 2020-	P&RD	Bhati Petla	Bhatipetla	Damaged in
	21). Const. of Agril				earth work
	bundh cum road				
	near Jahan Alis land				
	to Jaydar Alis home				
	via Sukur Alis house				
	MGNREGA 2022-23).	P&RD	Borocharaikhola	Baracharaikhola	Damaged in
	Construction of Agril				earth work
	bundh start from				
	Surajit Barman Land				
	to Habrardara at Vill				
	– Baracharaikhola				
	MGNREGA 2022-23).	P&RD	Purni	Purni	Damaged in
	Construction of Agril	י מווט	i uiiii	41111	earth work
	bundh start from				Cartii WUIK
	Kesori Mohan Ray				
	land to Gangadhar				
	River at Vill - Purni	0000	Pub-	Dub Marage de de es	Damas di.
	,	P&RD		Pub Moragadadhar	Damaged in
	21). Const of Agril		Moragodadhor		earth work
	Bundh Cum Road				
	from Esab Alis Land				
	to Bellal Alis Land	-0	-1 /		
	(MGNREGA 2020-21.		Bhati Petla	Bhatipetla	Damaged in
1	Const. of Agril Bundh		1		earth work
	cum road near				





	Bhatipetla				
	0401001/WC/90102				
	38091				
	(MGNREGA 2020-	P&RD	Bhati Petla	Bhatipetla	Damaged in
	21). Const of Agril				earth work
	bundh cum road				
	from D.K. Road to				
	Hasen Ali land via				
	Lavanya Prova Rays				
	land				
	(MGNREGA 2020-	P&RD	Pub-	Pub Moragadadhar	Damaged in
	21). Const. of Agril		Moragodadhor		earth work
	bundh cum road				
	near Rahim Mandal				
	house to Jamser Alis				
	land at Pub				
	Maragadadhar				
	(MGNREGA 2020-	P&RD	North	North Kachakhana	Damaged in
	21). Const of Agril		Kachakhana		earth work
	bundh cum road				
	from Bishnu Modak				
	land to Gadadhar				
	River at North				
	Kachakhana				
	(MGNREGA 2020-	P&RD	K. Harinchara	Kachakhana Harinchara	Damaged in
	21). Const. of agril		Paglaganj	Paglaganj	earth work
	bundh cum road				
	near from				
	Kacharighat to				
	Parghat			<u> </u>	
	(MGNREGA 2020-	P&RD	Pub-	Pub Maragadadhar	Damaged in
	21). Const. of Agril.		Moragodadhor		earth work
	Bundh cum road				
	from plat form to				
	Chanmiah land				
	(MGNREGA 2020-	BRO	North	North Kachakhana	Damaged in
	21). Const. of Agril		Kachakhana		earth work
	bundh near				
	Musererjan L.P.				
	School to kabarsthan				
	at North Kachakhana				
	(MGNREGA 2020-	P&RD	Pub-	Pub Moragadadhar	Damaged in
	21). Const of agril		Moragodadhor		earth work
	bundh cum road				
	from Mozid Munshis				
	house to Ali Mozibar				
	house at Pub				
	Maragadadhar				
	l l	P&RD	Pub-	Pub Moragadadhar	Damaged in
	21). Const of Agril		Moragodadhor		earth work
	Bundh Cum Road				
	from Mazid Munshis				
	Land to Gangadhar				
	River Via Fazal				
	Mandal Land				
		P&RD	Pub-	Pub Moragadadhar	Damaged in
	21). Land devp at		Moragodadhor		earth work
	Pachim				
	Moragadadhar L.P.				
	School playground at				
	Pub Maragadadhar				
	l l	P&RD	North	North Kachakhana	Damaged in
	21). Const of Agril		Kachakhana		earth work
	bundh cum road				
	from Parghat Bridge				
			1	1	
	to Paresh Ray land at			ļ	
	to Paresh Ray land at North Kachakhana				





	Elementary Schools Damaged	3705 No. Rowarkuti LP School	Education Deptt.	Rowarkuti	Rowarkuti		Submerged due to raising River Water.
	(in Nos)	Gaikhowa FM LP School	Education Deptt.	Gaikhowa Pt. III	Pachim Gaikhowa		Submerged due to raising River Water.
		Uttar Tokrerchara SC LP School	Deptt.	Tokrerchara Pt. I			Submerged due to raising River Water.
Сһараі	Culvert Approach Road Damaged (in Nos)	2BOX CULVERT DHIRERCHAR PT II NEAR BELLAL HUSSAIN HOUSE	Panchayat and Rural Deptt.	Dhirerchar Pt-II	DHIRERCHAR PT II	90.1726.98	CONST OF BOX CULVERT DHIRERCHAR PT II NEAR BELLAL HUSSAIN HOUSE
		BOX CULVERT KAZIPARA PT III NEAR NABAB ALI HOUSE	Panchayat and Rural Deptt.	Kajipara Pt- III	KAZIPARA PT III	90.5626.9	CONST OF BOX CULVERT KAZIPARA PT III NEAR NABAB ALI HOUSE
	Agri Bundh Damaged (in Nos)	2LAKHIPURPARA MASJID TOWARDS RIVER CHAMPAWATI	and Rural	Dhirerchar Pt-II	DHIRERCHAR	90.2526.17	AGRIL BANDH FROM LAKHIPURPARA MASJID TOWARDS RIVER CHAMPAWATI
		CHAMPAWATI RIVER TO GHORABANDHA YUVA CLUB TARANGAPUR	Panchayat and Rural Deptt.	Tarangapur Pt-I	TARANGAPUR	90.7826.46	AGRIL BANDH FROM GHORABANDHA YUVA CLUB TOWARDS RIVER CHAMPAWATI
	Fisheries/P ond (in Hect.)	9POND OF FULBAR HUSSEN PRAMANIK	Fishery	Simlabari Pt III	SIMLABARI PT III	90.426.23	DAMAGE OF EMBANKMENT AND INUNDATION/FIS H LOSS
		AMRIT SAROVER ID NO 83081	Panchayat and Rural Deptt.	Chirakuta Pt-I	CHIRAKUTA	90.2926.22	AMRIT SAROVER SUBMERGED BY RISING WATER OF RIVER BRAHMAPURA
		AMRIT SAROVER ID NO 619	Panchayat and Rural Deptt.	Chirakuta Pt-I	CHIRAKUTA	90.326.21	AMRIT SAROVER SUBMERGED BY RISING WATER OF RIVER BRAHMAPURA
			Panchayat and Rural Deptt.	Kamardihi Pt-I	TILAPARA	90.3126.22	AMRIT SAROVER SUBMERGED BY RISING WATER OF RIVER BRAHMAPURA
		AMRIT SAROVER ID NO 124482	Panchayat and Rural Deptt.	Kamardihi Pt-I	TILAPARA	90.3226.22	AMRIT SAROVER SUBMERGED BY RISING WATER OF RIVER BRAHMAPURA
		AMRIT SAROVER ID NO 133556	Panchayat and Rural Deptt.	Dhirbeel	DHIRBEEL	90.3926.29	AMRIT SAROVER SUBMERGED BY RISING WATER OF RIVER BRAHMAPURA
		AMRIT SAROVER ID NO 88176	Panchayat and Rural Deptt.	Barunitara Pt-I	BARUNITARA	90.1726.13	AMRIT SAROVER SUBMERGED BY RISING WATER OF RIVER BRAHMAPURA
		AMRIT SAROVER ID NO 93830	Panchayat and Rural Deptt.	Simlabari Pt I	PUTHIMARI	90.3126.12	AMRIT SAROVER SUBMERGED BY RISING WATER





										OF RIVER BRAHMAPURA
				AMRIT SAROVER ID NO 124477	Panchayat and Rural Deptt.	Kamardihi Pt-I	TILAPARA	90.32	26.22	AMRIT SAROVER SUBMERGED BY RISING WATER OF RIVER BRAHMAPURA
	Salmara	Fisheries/P ond (in Hect.)	3	Fishery	Fishery	Sundarpara Pt- IV	Sundarpara Pt-IV			As per report received from Fishery Dept. 2 nos fishery hsa been damade due to flood water as on
				Fishery	Fishery	Barkolia Naskara	Barkalia Naskara			07/07/24 area 0.75 hac As per report received from
										Fishery Dept. 1 nos fishery hsa been damade due to flood water as on 07/07/24 area 0.20 hac
	Athani	Nil	Nil	Nil		Nil	Nil	Nil	Nil	Nil
	Tingkhong		Nil	Nil		Nil	Nil	Nil	Nil	Nil
	Dibrugarh West	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Chabua	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Fisheries/P ond (in Hect.)		Fishery Ponds	Fishery	CHEIIIIIAII BIOCK	1. Chenimari block and Serepakhati , 2. Goroimari gaon, 3. Kholiamari 4.Betoni, 5. Ahom Kotoki pukhuri, 6. Senchuwa pukhuri, 7. Padumoni nagaon			Water Area 0.9 Hect. report received from Fishery department on 07.07.2024
	Naharkati a		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	East	Fisheries/P ond (in Hect.)	1	Fishery Ponds	Fishery	Teporchalibam Gaon	Teporchali Gaon			Water Area 0.9 Hect. report received from Fishery Department on 07.07.2024
	Tengakha †	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Goalpara		PWSS Damaged (in Nos)	4	Bahati Char Pt-II River Block PWSS		Bahati River Block Pt-II	Bahati River Block Pt-II	90.85	26.11	PWSS Submerge as per report submitted by SO PHED
				Pt-I No. 2 PWSS	PHE	Bahati River Block Pt-I	Bahati River Block Pt-I		26.13	PWSS Submerge as per report submitted by SO PHED
				Bahati Pt-II PWSS	PHE	Bahati Pt-II	Bahati Pt-II	90.84	26.1	PWSS Submerger as per report submitted by SO, PHED
				Nabagata Simlitola No. 2 PWSS		Nabagota Simlitola	Nabagata Simlitola		26.08	PWSS Submerged as per report submitted by SO, PHED
		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	,	Nil Agri Bundh	Nil 1	Nil agri bandh of Sohola	Nil Panchayat	Nil Digoli Ati	Nil Sohola	Nil	Nil	Nil Kuruabahi GP
_		Damaged (in Nos)		LPS	and Rural Deptt.					





	Khumtai	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Hailakand i		Nil		Nil	Nil	Nil	Nil	Nil	Nil
	ı Algapur	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Lala	Nil			Nil	Nil	Nil	Nil	Nil	Nil
	Katlicherr									
	a	Health		PWSSS	PHE	Dholai Pt-IX	DHOLAI - IX		24.48	Barge got damaged.
		Engineering (PHE) (in Nos)		DHOLAI MOLAI - VI PWSS	PHE	Dholai Pt-VI	DHOLAI - VI	92.58	324.46	Barge got damaged.
Hojai	Hojai	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Doboka	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Jorhat	Teok	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Jorhat	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	East Jorhat	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	West							INII	INII	
Kamrup	Chamaria	Anganwadi Centres Affected (in		rangapani	Child Developm	2 No. Dakshin Rangapani NC	2 no dakshin rangapani			AWC submerged on 06/07/2024 as per report of
		Nos)			ent					CDPO Chamaria ICDS project nagarbera
				67 south rangapani 2		2 No. Dakshin Rangapani NC	2 no dashing rangapani			AWC submerged on 06/07/2024 as per report of CDPO Chamaria
				116 dakshin	Women &	2 No. Dakshin	2 no dakshin rangapani			ICDS project nagarbera AWC submerged
				rangapani 2	Child Developm	Rangapani NC	_ no danomin rangapam			on 06/07/2024 as per report of
					ent					CDPO Chamaria ICDS project nagarbera
				pathar pub	Women & Child Developm ent	Malibari Pathar	Malibari pathar			AWC submerged on 06/07/2024 as per report of CDPO Chamaria ICDS project
						2 No. Dakshin Rangapani NC	2 no dakshin rangapani			nagarbera AWC submerged on 06/07/2024 as per report of CDPO Chamaria ICDS project nagarbera
				3 no		3 No. Uttar Rangapani	3 no uttar rangapani			AWC submerged on 06/07/2024 as per report of CDPO Chamaria ICDS project nagarbera
				rangapani 3		3 No. Dakshin Rangapani	3 no dakshin rangapani			AWC submerged on 06/07/2024 as per report of CDPO Chamaria ICDS project nagarbera
				rangapani		3 No. Dakshin Rangapani	3 no dakshin rangapani			AWC submerged on 06/07/2024 as per report of CDPO Chamaria ICDS project nagarbera
				180 dakshin	Women &	3 No. Dakshin	3 no dakshin rangapani			AWC submerged
					Child	Rangapani	- 12 22			on 06/07/2024 as





	Developm		Γ Γ	per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
170 no 2 malibari	Women &	Malibari Pathar	Malibari pathar nc	AWC submerged
pathar awc	Child	NC		on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
109 no 3 no malibari		Malibari Pathar	Malibari pathar	AWC submerged
pathar	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project nagarbera
284 dakshin	Momon &	3 No. Dakshin	3 no dakshin rangapani	AWC submerged
		Rangapani	5 110 daksiiiii rangapaiii	on 06/07/2024 as
khanda	Developm			per report of
Kilanaa	ent			CDPO Chamaria
				ICDS project
				nagarbera
285 dakshin	Women &	3 No. Dakshin	3 no dakshin rangapani	AWC submerged
rangapani anchalik	Child	Rangapani	[	on 06/07/2024 as
maktab	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
45 no dekachang		Dekachang	Dekachang	AWC submerged
awc	Child			on 06/07/2024 a
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project nagarbera
50 no 1 no malibari	Women &	Malibari Pathar	Malihari nathar	AWC submerged
pathar damapara	Child	Ivialibali i atilal	ivialibari patriai	on 06/07/2024 as
patriar damapara	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
171 malibari pathar	Women &	Malibari Pathar	Malibari pathar	AWC submerged
reserve	Child			on 06/07/2024 a:
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
40	M	n de liber d' C. C.	Malihari nathar	nagarbera
49 no malibari pathar awc		Malibari Pathar	ivialibari pathar	AWC submerged
patriar awc	Child Developm			on 06/07/2024 as per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
51 no 2 malibari	Women &	Malibari Pathar	Malibari pathar	AWC submerged
pathar awc	Child			on 06/07/2024 a
[	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
		<u> </u>		nagarbera
214 no dekachang		Dekachang	Dekachang	AWC submerged
pub awc	Child			on 06/07/2024 a
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
	<del> </del>			
6 no kahibari		Kahibari	Kahibari	AWC submerged
				on 06/07/2024 as
	-			
6 no kahibari	Women & Child Developm ent		Kahibari	nagarbera AWC submer





				ICDS project
				nagarbera
1 no Chamaria	Women &	2 No.	2 no Barua pathar	AWC submerged
25 6.16.114114		Baruapathar	5a. aa patriar	on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
120 no Chamaria	Women &	Chamaria Satra	Chamaria satra	AWC submerged
	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
197 Puthimari	Women &	Puthimari	Puthimari	AWC submerged
madhyapara	Child			on 06/07/2024 as
, ,	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
131 no kahibari	Women &	Kahibari	Kahibari	AWC submerged
reserve	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
189 no Puthimari	Women &	Puthimari	Puthimari	AWC submerged
	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
164 no baralipara	Women &	Trilochan	Trilochan	AWC submerged
	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
7 no Puthimari	Women &	Puthimari	Puthimari	AWC submerged
	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
196 no kahibari uttar		Kahibari	Kahibari	AWC submerged
suba	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
210				nagarbera
210 no salmara	Women &	Salmara	Salmara	AWC submerged
	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
460 1 "				nagarbera
	Women &	i rilochan	Trilochan	AWC submerged
Das para awc	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
240		Landard P	Land Land	nagarbera
=		Jaukatadia	Jawkatadia	AWC submerged
uttar	Child			on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project nagarbera





 ı	Т	_	1	
15 no 2 no makeli		1 No. Makeli	1 no makeli	AWC submerged
Das para awc	Child			on 06/07/2024 a:
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
169 no 2 no	Women &	Trilochan	Trilochan	AWC submerged
trilochan awc	Child	Trilocitati	rinochan	on 06/07/2024 a
ti ilochan awc				
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
200 no 1 no makeli	Women &	1 No. Makeli	1 no makeli	AWC submerged
awc	Child			on 06/07/2024 a
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
174 no jawkatadia	Moman &	Jaukatadia	Jawkatadia	AWC submerged
	Child	Jaukataula	Jawkatadia	_
dakshin paschim				on 06/07/2024 as
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
38 no jawkatadia	Women &	Jaukatadia	Jawkatadia	AWC submerged
	Child			on 06/07/2024 a:
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
102		C - I II	Calarathan	
193 no solapathar		Solapathar	Solapathar	AWC submerged
awc	Child			on 06/07/2024 a
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
41 no jawkatagaon	Women &	Jawkatagaon	Jawkatagaon	AWC submerged
	Child	_		on 06/07/2024 a:
	Developm			per report of
	ent			CDPO Chamaria
	CITE			ICDS project
				nagarbera
220 no jawkatadia		Jaukatadia	Jawkatadia	AWC submerged
madhypara	Child			on 06/07/2024 a:
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
39 no jawkatadia	Women &	Jaukatadia	Jawkatadia	AWC submerged
jamadada	Child			on 06/07/2024 a
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
173 no niz kathmi	Women &	Niz Kathmi	Niz kathmi	AWC submerged
dakhin	Child			on 06/07/2024 a:
	Developm			per report of
	ent			CDPO Chamaria
	1			ICDS project
24		C-li	Calaa di	nagarbera
34 uttar selosuti	Women &	pelosuti	Selosuti	AWC submerged
	Child			on 06/07/2024 a:
	Developm			per report of
	ent			CDPO Chamaria
				ICDS project
				nagarbera
1		ļ	+	
229 rowmari uttar	Woman 9	Rowmari	Rowmari	AMC cuhmorand
229 rowmari uttar	Women &	Rowmari	Rowmari	AWC submerged
229 rowmari uttar suba	Women & Child	Rowmari	Rowmari	AWC submerged on 06/07/2024 as per report of





			Developm			CDPO Chamaria
			ent			ICDS project
				1		nagarbera
		35 Chamariapam	Women &	Chamaria Pam	Chamaria pam	AWC submerged
			Child			on 06/07/2024 a
			Developm			per report of
			ent			CDPO Chamaria
			CITC			ICDS project
						nagarbera
		30 no Sontoli	Momon 9	Santoli Satra	Santoli satra	AWC submerged
		50 110 30111.011	Child	Santon Satia	Salituli Sati a	on 06/07/2024 a
			Developm			
						per report of
			ent			CDPO Chamaria
						ICDS project
			<u> </u>			nagarbera
		135 nimburtari		Nimburtari	Nimbutari	AWC submerged
			Child			on 06/07/2024 a
			Developm			per report of
			ent			CDPO Chamaria
						ICDS project
				<u> </u>		nagarbera
		32 chourdia	Women &	Changardia NC	Chourdia	AWC submerged
			Child			on 06/07/2024 a
			Developm			per report of
			ent			CDPO Chamaria
						ICDS project
						nagarbera
		228 Choudhury pam	Women &	Choudhurynam	Choudhary nam	AWC submerged
		220 Choddhary pani	Child	choudhar y pani	choddhary pann	on 06/07/2024 a
			Developm			per report of
			ent			CDPO Chamaria
			CIIL			ICDS project
	Public	00.4= =+= :	PHE	Mahtoli	N 4 =   + =   :	nagarbera
		8 Mahtoli pwss	PHE	Mantoli	Mahtoli	PWSS submerged
	Health					on dated
	Engineering					06/07/2024 as
	(PHE) (in					per report of JE
	Nos)					PHE boko sub
						division boko
						Guwahati
						division -l
		Malibari pathar NC	PHE	Malibari Pathar	Malibari pathar nc	PWSS submerged
		no 3 pwss		NC		on dated
						06/07/2024 as
						per report of JE
						PHE boko sub
						division boko
			1			Guwahati
	1 1					Guwanati
1						division -l
		Malibari pathar NC	PHE	Malibari Pathar	Malibari pathar nc	
		Malibari pathar NC no 2 pwss	PHE	Malibari Pathar NC	Malibari pathar nc	division -l
			PHE		Malibari pathar nc	division -l PWSS submerged on dated
			PHE		Malibari pathar nc	division -I PWSS submerged on dated 06/07/2024 as
			PHE		Malibari pathar nc	division -I PWSS submerged on dated 06/07/2024 as per report of JE
			PHE		Malibari pathar nc	division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub
			PHE		Malibari pathar nc	division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko
			PHE		Malibari pathar nc	division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati
		no 2 pwss		NC		division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I
					Malibari pathar nc	division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged
		no 2 pwss		NC		division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated
		no 2 pwss		NC		division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated 06/07/2024 as
		no 2 pwss		NC		division -I  PWSS submerged on dated 06/07/2024 as per report of JE  PHE boko sub division boko Guwahati division -I  PWSS submerged on dated 06/07/2024 as per report of JE
		no 2 pwss		NC		division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub
		no 2 pwss		NC		division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko
		no 2 pwss		NC		division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub
		no 2 pwss		NC		division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko
		no 2 pwss		NC		division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati
		no 2 pwss  Santoli satra pwss	PHE	NC Santoli Satra	Santoli satra	division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I
		no 2 pwss  Santoli satra pwss  Goroimari bilorjan	PHE	NC Santoli Satra Garoimari	Santoli satra	division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I PWSS submerged





										PHE boko sub division boko Guwahati division -l
				No 2 dashing rangapani pwss	PHE	2 No. Dakshin Rangapani NC	2 no dakshin rangapani			PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I
				Malibari Pathar no 3 pwss	РНЕ	Malibari Pathar	Malibari pathar			PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I
				1 no Dakshin rangapani pwss	PHE	1 No. Dakshin Rangapani	1 no dakshin rangapani			PWSS submerged on dated 06/07/2024 as per report of JE PHE boko sub division boko Guwahati division -I
	Kamalpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Irrigation Canal/Sche me Damaged (in Nos)	4		Š	Sila Sindurighopa Mouza: Athiyabai	Athiyaboi		26.27	Solar powered DTW scheme belonging to Koilash Kalita affected as per report received from AEE, Jalukbari Sub Div, Irrigation on 06.07.2024
				Solar powered DTW	U	Sila Sindurighopa Mouza: Athiyabai	Athiyaboi	91.65	26.27	Solar powered DTW scheme belonging to Haledhar Kalita affected as per report received from AEE, Jalukbari Sub Div, Irrigation on 06.07.2024
						Bonmaja	Bonmaja	91.66	26.26	Solar powered DTW scheme belonging to Subhash Kalita affected as per report received from AEE, Jalukbari Sub Div, Irrigation on 06.07.2024
				Solar powered DTW	Irrigation	Sila Sindurighopa Mouza: Athiyabai	Athiyaboi	91.65	26.27	Solar powered DTW scheme belonging to Surjya Kalita affected as per report received from AEE, Jalukbari Sub Div, Irrigation on 06.07.2024





Go	oroimari Anganwadi Centres Affected (in Nos)	19Uttar Topar Pather - 83	Women & Child Developm ent		Uttar Topar Pather	As per report from CDPO, Goroimari ICDS Project, AWC Uttar Topar Pather - 83 is damaged due to flood, 2024.
		Dighal Duba - 74	Women & Child Developm ent	Dighal dova	Dighal Duba	As per report from CDPO, Goroimari ICDS Project, AWC Dighal Duba - 74 is damaged due to flood, 2024.
		Uttar Baghmara- 42	Women & Child Developm ent	Baghmara	Uttar Baghmara- 42	As per report from CDPO, Goroimari ICDS Project, AWC Uttar Baghmara- 42 is damaged due to flood, 2024.
		Pachim Kathalguri- 70	Child Developm ent	guri2	Pachim Kathalguri	As per report from CDPO, Goroimari ICDS Project, AWC Pachim Kathalguri- 70 is damaged due to flood, 2024.
		Bhakuamari 82  Uttar Pachim	Child Developm ent		Bhakuamari	As per report from CDPO, Goroimari ICDS Project, AWC Bhakuamari 82 is damaged due to flood, 2024.
		Ottar Pachim Batahidia - 68	Women & Child Developm ent		Uttar Pachim Batahidia	As per report from CDPO, Goroimari ICDS Project, AWC Uttar Pachim Batahidia - 68 is damaged due to flood, 2024.
		Uttar Achalpara - 44	Child Developm ent	mara	Uttar Achalpara	As per report from CDPO, Goroimari ICDS Project, AWC Uttar Achalpara - 44 is damaged due to flood, 2024.
		Kalartop 77	Child Developm ent	Kalardia Top	Kalartop	As per report from CDPO, Goroimari ICDS Project, AWC Kalartop 77 is damaged due to flood, 2024.
		No. 2 Topar Pather 85	Women & Child Developm ent	ToparPathar	No. 2 Topar Pather	As per report from CDPO, Goroimari ICDS Project, AWC No. 2 Topar Pather 85 is damaged due to flood, 2024.





Pachim Khetrapara - 69 Naljuhi - 73	Child Developm ent  Women & Child	NaljuhiPathar	Pachim Khetrapara	As per report from CDPO, Goroimari ICDS Project, AWC Pachim Khetrapara - 69 is damaged due to flood, 2024. As per report from CDPO,
	Developm ent			Goroimari ICDS Project, AWC Naljuhi - 73 is damaged due to flood, 2024.
Saralpara 76	Women & Child Developm ent		Saralpara	As per report from CDPO, Goroimari ICDS Project, AWC Saralpara 76 is damaged due to flood, 2024.
Kaltoli Pather - 78	Women & Child Developm ent	Kaltalipathar	Kaltoli Pather	As per report from CDPO, Goroimari ICDS Project, AWC Kaltoli Pather - 78 is damaged due to flood, 2024.
Salmara - 72	Women & Child Developm ent		Salmara	As per report from CDPO, Goroimari ICDS Project, AWC Salmara - 72 is damaged due to flood, 2024.
Duramari - 71	Women & Child Developm ent		Duramari	As per report from CDPO, Goroimari ICDS Project, AWC Duramari - 71 is damaged due to flood, 2024.
Nayapara 75	Child Developm ent		Nayapara	As per report from CDPO, Goroimari ICDS Project, AWC Nayapara 75 is damaged due to flood, 2024.
Chaudhurypara 80	Women & Child Developm ent	Choudhury para	Chaudhurypara	As per report from CDPO, Goroimari ICDS Project, AWC Chaudhurypara 80 is damaged due to flood, 2024.
Bogerdia 81	Child Developm ent		Bogerdia	As per report from CDPO, Goroimari ICDS Project, AWC Bogerdia 81 is damaged due to flood, 2024.
Maguabill Pather - 79	Women & Child	MaghuabilarPat har	Maguabill Pather	As per report from CDPO, Goroimari ICDS





Palashben Nil	Project, AWC
Palashbar   Ni	Maguabill Pather
Palashban Nil	- 79 is damaged
Palasbom/Nul   Nil   N	due to flood,
Nagarber Anganwadi a Certires a C	2024.
Nagarber Angamwadi a Affected (in Afoc) BHAKHURADIA AWC Child Pevelopm ent E	Nil
Affected (in Nos)  BHAKHURADIA AWC Child Developm ant I NO UTTAR  RANGAPANI AWC Child Rangapani RANGAPANI Developm ent Child Developm ent Child Developm ant Child Pathar Developm ent Child Developm ent C	Nil
Affected (in Nos)  I 43 NO UTTAR RANGAPANI AWC Child Developm Ent  POPORE POPORE POPORE I 143 NO UTTAR RANGAPANI AWC Child Developm Ent  POPORE POPORE POPORE I 143 NO UTTAR RANGAPANI DEVELOPM Ent  I 143 NO UTTAR RANGAPANI DEVELOPM RANGAPANI DEVELOPM Ent  POPORE POPORE POPORE I 143 NO UTTAR RANGAPANI DEVELOPM RANGAPA	AS PER REPORT
Pole   APDCL   Hadala   No Uttar   No Utta	OF CDPO
143 NO UTTAR RANGAPANI AWC Developm ent  97 NO NATUN BADLA PATHER Chiid Developm ent  2 NO TUPAMARI Developm ent  2 NO TUPAMARI BADLA PATAHER Chiid Developm ent  2 NO TUPAMARI BADLA PATAHER BADLA PATAHER Chiid Developm ent  15 Pole APDCL Sendhelitari AADLA PATHER A	CHAMARIA
143 NO UTTAR RANGAPANI AWC Child Rangapani RANGAPANI Developm ent  97 NO NATUN BADLA PATHER Child Developm ent  2 NO TUPAMARI Child Developm ent  2 NO TUPAMARI Child Developm ent  2 NO TUPAMARI Child Developm ent  3 RADLA PATHER ADLA	DEVELOPMENT
143 NO UTTAR   Momen & I NO UTTAR   RANGAPANI AWC   Child   Developm   RANGAPANI   Develo	BLOCK ON
RANGAPANI AWC Child Developm ent Women & Badla Bilar Pathar Developm ent Developm e	DATED 6/7/2024 AS PER REPORT
Developm ent  97 NO NATUN BADLA PATHER Child Child Pathar Developm ent  2 NO TUPAMARI Child Developm ent  2 NO TUPAMARI Child Developm ent  290 NO TUPAMARI BADLA PATHER Child Developm ent  3 Developm ent  4 Developm ent  5 Developm ent  6 Developm ent  7 Developm ent  8 Badla Bilar Child Developm ent 6 Developm ent 7 Developm ent 8 Badla Bilar Pathar Developm ent 8 Badla Bilar Pathar Developm ent 9 Developm ent 9 Developm ent 8 Badla Bilar Pathar Developm ent 9 Devel	OF CDPO
ent  97 NO NATUN BADLA PATHER Child Development  2 NO TUPAMARI Child Development Child Child Development Child Chi	CHAMARIA
97 NO NATUN BADLA PATHER Child Developm ent  2 NO TUPAMARI Women & Badla Bilar Child Developm ent  290 NO TUPAMARI BADLA PATHER Child Developm ent  3 BADLA PATHER Child Developm ent  4 BADLA PATHER Child Developm ent  5 BADLA PATHER Child Developm ent  4 BADLA PATHER Child Developm ent  6 C C Developm ent  7 BADLA PATHER Child Developm ent 8 Badla Bilar Pathar Child Developm ent 8 BADLA PATHER A BADLA PATHER	DEVELOPMENT
97 NO NATUN BADLA PATHER Child Pathar Child Developm ent Developm ent Tupamari Tupamari Tupamari Tupamari Developm ent Dev	BLOCK ON
BADLA PATHER Developm ent  2 NO TUPAMARI Child Developm ent  290 NO TUPAMARI BADLA PATHER Child Developm ent  290 NO TUPAMARI Child Developm ent  BADLA PATHER Child Developm ent Child Developm ent  15Pole APDCL Gendhelitari Hirapara  A A A A A A A A A A A A A A A A A A	DATED 6/7/2024
Developm ent  2 NO TUPAMARI Momen & Tupamari TUPAMARI Child Developm ent  290 NO TUPAMARI Women & Badia Bilar BADLA PATHER BADLA PATAHER Child Pathar Developm ent  Hajo Power Dept. Poles (in Nos) Pole APDCL Gendhelitari Hirapara  Pole APDCL Manahkuchi Baramboi  Pole APDCL I No. Bagta Koyajani  Pole APDCL Hadala hadala	AS PER REPORT
ent    Developm	OF CDPO
Pole APDCL Hadala hadala	CHAMARIA
2 NO TUPAMARI Women & Tupamari TUPAMARI A Child Developm ent BADLA PATHER BADLA PATAHER Child Developm ent BADLA PATHER Child Pathar Child Pathar Developm ent BADLA PATHER Child Pathar Developm ent BADLA PATHER Child Pathar Developm ent BADLA PATHER Child Pathar Child Pathar Developm ent BADLA PATHER Child Pathar Developm ent BA	DEVELOPMENT BLOCK ON
2 NO TUPAMARI Develorm ent TUPAMARI TUPAMARI DE DEVELORM ENT DE	DATED 6/7/2024
Child Developm ent Child Developm ent Badla Bilar BADLA PATHER ADLA PATHER Child Pathar Developm ent BDD Developm ent Child Pathar Developm ent Child Pole Child Pathar Child Pathar Child Pole Child Pole Child Pathar Child Path	AS PER REPORT
Developm ent  290 NO TUPAMARI Women & Badla Bilar BADLA PATHER  BADLA PATAHER Child Pathar Developm ent  B D Developm ent  Hajo Power Dept. Poles (in Nos)  15Pole APDCL Gendhelitari Hirapara  A O Developm ent  B D Developm ent  APDCL Gendhelitari Hirapara  A O Developm ent  B D Developm ent  APDCL Gendhelitari Hirapara  A O Developm ent  B D D D Developm ent  B D D D D D D D D D D D D D	OF CDPO
290 NO TUPAMARI BADLA PATAHER  290 NO TUPAMARI BADLA PATAHER  Child Developm ent  Power Dept. Poles (in Nos)  Pole  APDCL Gendhelitari Hirapara  APDCL Baramboi  APDCL Baramboi  Pole  APDCL I No. Bagta Koyajani  Pole  APDCL Hadala hadala	CHAMARIA
290 NO TUPAMARI Women & Badla Bilar Pathar O O C C C D D B B D D D D D D D D D D D D D	DEVELOPMENT
290 NO TUPAMARI BADLA PATAHER Child Developm ent  Hajo Power Dept. Poles (in Nos)  Pole APDCL Gendhelitari Hirapara  APDCL Hanahkuchi Baramboi  Pole APDCL I No. Bagta Koyajani A On Hirapara  Pole APDCL AP	BLOCK ON
BADLA PATAHER Child Developm ent  Hajo Power Dept. Poles (in Nos)  15Pole APDCL Gendhelitari Hirapara  A O O O O O O O O O O O O O O O O O O	DATED 6/7/2024
Pole APDCL I No. Bagta Koyajani  Pole APDCL Hadala hadala  APDCL C C D D B B D D D D D D D D D D D D D D	AS PER REPORT
Hajo Power Dept. Poles (in Nos)  Pole APDCL Gendhelitari Hirapara A St. A On the Company of the	OF CDPO
Hajo Power Dept. Poles (in Nos)  Pole APDCL Gendhelitari Hirapara AA SISA AA OO	CHAMARIA DEVELOPMENT
Hajo Power Dept. Poles (in Nos)  Pole APDCL Gendhelitari Hirapara St. A. O.	BLOCK ON
Hajo Power Dept. Poles (in Nos)  Pole APDCL Gendhelitari Hirapara A Si Si A Di Appendi	DATED 6/7/2024
Dept. Poles (in Nos)  Pole APDCL Manahkuchi Baramboi Assi Ado On the pole APDCL I No. Bagta Koyajani Assi Ado On the pole APDCL I No. Bagta Koyajani Assi Ado On the pole APDCL I No. Bagta Koyajani Assi Ado On the pole APDCL I No. Bagta Koyajani Assi Ado On the pole APDCL I No. Bagta Koyajani Assi Ado On the pole APDCL I No. Bagta Koyajani Assi Ado On the pole APDCL I No. Bagta Koyajani Assi Ado On the pole APDCL I No. Bagta Koyajani Assi Ado On the pole I No. Bagta I No	As per report
Pole APDCL Manahkuchi Baramboi As Sanah Apper Ap	submitted by
Pole APDCL Manahkuchi Baramboi AA OI Pole APDCL 1 No. Bagta Koyajani A OI Pole APDCL Hadala hadala ASG	APDCL Hajo on
Pole APDCL Manahkuchi Baramboi AAOU AAOU AAOU AAOU AAOU AAOU AAOU AAO	06/07/2024 1
Pole APDCL Manahkuchi Baramboi A  Su A  Oi  Pole APDCL 1 No. Bagta Koyajani A  Oi  Pole APDCL Hadala hadala A  Su A	nos pole was
Pole APDCL Manahkuchi Baramboi Assi Adoli Assi Adoli Andrews Appela Appe	damaged during flood 2024.
Pole APDCL 1 No. Bagta Koyajani Asu Ali	As per report
Pole APDCL 1 No. Bagta Koyajani Asu Al Ori Apdres A	submitted by
Pole APDCL 1 No. Bagta Koyajani Asu Albaharan Apdala Apdala Asu Albaharan Asu Albaharan Asu Apdala Asu Abadala	APDCL Hajo on
Pole APDCL 1 No. Bagta Koyajani Asu AOO mh	06/07/2024 1
Pole APDCL 1 No. Bagta Koyajani A  Su A Oi ni dd ffli Pole APDCL Hadala hadala A Su A	nos pole was
Pole APDCL 1 No. Bagta Koyajani Asu A Oi ni di Fili Pole APDCL Hadala hadala Asu A	damaged during
Signal Apple Apple Apple Hadala hadala Asu	flood 2024.
Pole APDCL Hadala hadala A SU	As per report
Pole APDCL Hadala hadala A su	submitted by
Pole APDCL Hadala hadala Asu	APDCL Hajo on 06/07/2024 1
Pole APDCL Hadala hadala A su A	nos pole was
Pole APDCL Hadala hadala A sı	damaged during
Pole APDCL Hadala hadala A su	flood 2024.
SI A	As per report
	submitted by
	APDCL Hajo on
	06/07/2024 1
	nos pole was
	damaged during
	flood 2024.
	As per report submitted by
	APDCL Hajo on
	06/07/2024 1





Pole	APDCL	1 No. Gondhmow	Gondhmow	As per report submitted by APDCL Sualkuchi
Dala	ADDCI	4 No	Condhaou	submitted by APDCL Hajo on 06/07/2024 1 nos HT pole was damaged during flood 2024.
HT pole	APDCL	Hablakha	Hablakha	nos HT pole was damaged during flood 2024. As per report
HT Pole	APDCL	Bongshar	Bhelamari	As per report submitted by APDCL Hajo on 06/07/2024 1
				APDCL Hajo on 06/07/2024 1 nos HT pole was damaged during flood 2024.
HT Pole	APDCL	Kalitakuchi	Bezpara	flood 2024.  As per report submitted by
HT Pole	APDCL	Khopanikuchi	khopnikuchi	As per report submitted by APDCL Hajo on 06/07/2024 1 nos HT pole was damaged during
				submitted by APDCL Hajo on 06/07/2024 1 nos HT pole was damaged during flood 2024.
HT Pole	APDCL	Tokradia	tokradia	submitted by APDCL Hajo on 06/07/2024 1 nos HT pole was damaged during flood 2024. As per report
HT Pole	APDCL	1 No. Soulmari	Soulmar	submitted by APDCL Hajo on 06/07/2024 1 nos HT pole was damaged during flood 2024. As per report
HT Pole  HT pole	APDCL APDCL	Barni Kumarpur	dakhin Barni Kowarpur	As per report submitted by APDCL Hajo on 06/07/2024 1 nos HT pole was damaged during flood 2024. As per report
Pole	APDCL	1 No. Kholihamari	Kholihamari	As per report submitted by APDCL Hajo on 06/07/2024 1 nos pole was damaged during flood 2024.
				nos pole was damaged during flood 2024.





		Power Dept. Conductors (in Nos)		Conductor		Dakhin Pakorkona	Pakorkona, bezpara, hirapara,1no velkar, ramdia, pachtola,hablakha,napa rapam, tapabari, bhelamari.			on 06/07/2024 8.5 kilometer conductor was damaged during flood 2024. As per report submitted by APDCL Hajo on 06/07/2024 8.5 Kilometer Conductor was damaged during
Kamrup	Sonapur	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	flood 2024. Nil
(M)	Chandrap ur			Nil		Nil	Nil	Nil	Nil	Nil
Karimga nj	Nilambaz ar	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Patherkan di					Nil		Nil	Nil	Nil
	Karimganj					Nil	Nil	Nil	Nil	Nil
L	Badarpur	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Kokrajha	Bagribari	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
r	Gossaigao n	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Dotma	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Lakhimp ur		Breaches (in Nos)		road to Abu Takir Sorkar Chuburi	and Rural Deptt.					said road damaged as reported by officials of Karunabari Development Block on 07/07/2024
					Panchayat and Rural Deptt.	2No.Kehutoli	2 No. Kehutoli near Sub Centre			About 30 m of the said road damaged as reported by officials of Karunabari Development Block on 07/07/2024
			Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Subansiri			Nil		Nil	Nil	Nil	Nil	Nil
		Approach Road Damaged (in Nos)		Link Road from Khanajan Lothow PWD to Singra Borbam Pathar Power House	P&RD	Singra	Singra			As per report received from BDO, Nowboicha on 07.07.2024, The Link Road from Khanajan Lothow PWD to Singra Borbam Pathar Power House in Singra village under Pahumora Gaon Panchayat has sustained considerable breached about 50 Mtrs. in length, with a width of 40 Mtrs. affected. The damaged includes a crack





										in the culvert ar surface erosion due to heavy
	North	Fisheries/P		Eighorics/Dos-1	Eichor:	Adiqu+: N. C	Adicuti Villaga			rainfall in the area.  Adisuti 4 Nos. o
	Lakhimpu		2	Fisheries/Pond	Fishery	Adisuti N.C	Adisuti Village			Pond submerge  1 Hector
		,		Fisheries/Pond	Fishery	Gowalbari N.C.	Gowalbari			Gowalbari 4 No of Pond submerged 1
				Fisheries/Pond	Fishery	Korachapori N.C.	Korhachapori			Hector  Karhachapori 1  Nos. of Pond  submerged 1
				Fisheries/Pond	Fishery	Bandarkota N.C.	Bandarkata			Hector Bandarkata 4 Nos. of Pond submerged 1
	Narayanp	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Hector Nil
Majuli	-	PWSS Damaged (in Nos)	63	Solar Powered Mini PWSS	PHE	Boruachuk NC	Boruachuk		26.82	1. Solar Panel Control Board along with Lithium Ion Battery Damag 2. Clog in Deeptube Well 3. Damage in Distribution Pip Clog in Pipe 4. Household T Connection Poi Damage 5. Chlorine Doz affected partial
				Baghmora Subidha Chapori Solar Mini PWSS	PHE	Subidha Chapori NC	Baghmora	93.89	26.81	1. Solar Panel Control Board along with Lithium Ion Battery Damag 2. Household 1 Connection Po Damage 3. Chlorine Do: affected partia
				Ahotguri Satra No 2 Solar Mini PWSS	PHE	Kath Chapori NC	Kath Chapori	93.88	26.8	1. Solar Panel Control Board along with Lithium Ion Battery Damage 2. Damage in Distribution Pi Clog in Pipe 3. Household Connection Po Damage 4. Chlorine Do affected partia
				AUNIATI JUNGLE Solar Powered Mini PWSS	PHE	Auniati Jungle NC	Auniati Jungle	93.83	27.01	1. Solar Panel Control Board along with Lithium Ion Battery Damag 2. Clog in Deeptube Wel 3. Damage in Distribution Pi





	<del>.</del>				_		
							Clog in Pipe
							4. Household Tap
							Connection Point
							Damage 5. Chlorine Dozer
							affected partially.
		Bilotia No 1 Solar	PHE	Kangkho	Kangkho Chapori 1	93.9226.8	
		Mini PWSS		Chapori NC		33.3220.0	Control Board
				. ,			along with
							Lithium Ion
							Battery Damaged
							2. Household Tap
							Connection Point
							Damage
							3. Chlorine Dozer
		Ahotguri Satra No 3	PHF	Burha Chapori	Baghmora	93.9526.8	affected partially.  1. Solar Panel
		Solar Mini PWSS		NC	Dugilliora	33.3320.0	Control Board
							along with
							Lithium Ion
							Battery Damaged
							2. Clog in
							Deeptube Well
							3. Damage in
							Distribution Pipe/ Clog in Pipe
							4. Household Tap
							Connection Point
							Damage
							5. Chlorine Dozer
							affected partially.
		BHANGON MARA	PHE	Borfakua NC	Bhangunmari	93.926.8	
		Solar Powered Mini					Control Board
		PWSS					along with Lithium Ion
							Battery Damaged
							2. Clog in
							Deeptube Well
							3. Damage in
							Distribution Pipe/
							Clog in Pipe
							4. Household Tap  Connection Point
							Damage
							5. Chlorine Dozer
							affected partially.
		Ahotguri Satra No 1	PHE	Burha Chapori	Burha Chapori	93.9426.8	
		Solar Mini PWSS		NC			Control Board
							along with
							Lithium Ion
							Battery Damaged
							2. Clog in Deeptube Well
							3. Damage in
							Distribution Pipe/
							Clog in Pipe
							4. Household Tap
							Connection Point
							Damaged
							5. Chlorine Dozer
		Pilotia No 2 Calar	PHE	Kangkha	Kanakha Chanari 2	02.0126.6	affected partially.  1. Solar Panel
1		Bilotia No 2 Solar Mini PWSS	PHE	Kangkho Chapori NC	Kangkho Chapori 2	93.9126.8	1. Solar Panel Control Board
		WIIII WVJJ		Спароптис			along with
							Lithium Ion
							Battery Damaged
							2. Household Tap
							Connection Point
	i	I	i	1	1	1 1	Damage





							3. Chlorine Dozer
							affected partially.
	BARUAH CHUCK	PHE	Burha Chapori	Bilotia	93.93	26.82	1. Solar Panel
	Solar Powered Mini		NC				Control Board
	PWSS						along with
							Lithium Ion
							Battery Damaged
							<ol><li>Clog in Deeptube Well</li></ol>
							3. Damage in
							Distribution Pipe/
							Clog in Pipe
							4. Household Tap
							Connection Point
							Damage
							5. Chlorine Dozer
	RAIOTI GAON Solar	PHE	Namati NC	Namati Davati	02.01	26.81	affected partially.  1. Solar Panel
	Powered Mini PWSS	PHE	Namati NC	Namati Rayati	93.91	26.81	Control Board
	l owered willing was						along with
							Lithium Ion
							Battery Damaged
							2. Clog in
							Deeptube Well
							3. Damage in
							Distribution Pipe/
							Clog in Pipe
							<ol><li>Household Tap Connection Point</li></ol>
							Damage
							5. Chlorine Dozer
							affected partially.
	GOPAL CHAPORI	PHE	Gopalchuk NC	Gopal Chapori	93.91	26.91	1. Solar Panel
	Solar Powered Mini						Control Board
	PWSS						along with
							Lithium Ion
							Battery Damaged
							2. Clog in
							Deeptube Well  3. Damage in
							Distribution Pipe/
							Clog in Pipe
							4. Household Tap
							Connection Point
							Damage
							5. Chlorine Dozer
	WEDWED C. :	5115				26.62	affected partially.
		PHE	Kerker NC	Kerker	93.89	26.89	1. Solar Panel
	Powered Mini PWSS						Control Board
							along with Lithium Ion
							Battery Damaged
							2. Clog in
							Deeptube Well
							3. Damage in
							Distribution Pipe/
							Clog in Pipe
							4. Household Tap
							Connection Point
							Damage 5. Chlorine Dozer
							affected partially.
	Hotter No 2 Solar	PHE	Huttar NC	Huttar no. 2	93.93	26.8	Solar Panel
	Mini PWSS						Control Board
							along with
							Lithium Ion
1							Battery Damaged
							2. Household Tap Connection Point





				$\overline{1}$		Damage
						3. Chlorine Dozer
CARLICUARCEIC	DUE	Dames de J. 200	Damies de la	02.02	20.0	affected partially.
GARU CHAPORI Solar Powered Mini PWSS	PHE	Boruachuk NC	Boruachuk	93.862	26.8	<ol> <li>Solar Panel</li> <li>Control Board</li> </ol>
I OWEIEU WIIII PWSS						along with
						Lithium Ion
						Battery Damaged
						2. Chlorine Dozer
						affected partially.
Bilotia No 3 Solar Mini PWSS	PHE	Kerker NC	Kerker	93.892	26.89	Solar Panel Control Board
IVIIIII PVV33						along with
						Lithium Ion
						Battery Damaged
						2. Clog in
						Deeptube Well
						3. Damage in
						Distribution Pipe/ Clog in Pipe
						4. Household Tap
						Connection Point
						Damage
						5. Chlorine Dozer
COTONICA C. I	DUE	House Alc	ALIATOLIBICATE	00.01	20.0	affected partially.
GOTONGA Solar Powered Mini PWSS	PHE	Huttar NC	AHATGURI SATRA	93.912	26.8	Solar Panel Control Board
rowered willi PWSS						along with
						Lithium Ion
						Battery Damaged
						2. Clog in
						Deeptube Well
						3. Damage in
						Distribution Pipe/ Clog in Pipe
						4. Household Tap
						Connection Point
						Damage
KUMALIA Solar	PHE	Kumolia Projap	Kumolia Chapori	93.91	26.91	1. Solar Panel
Powered Mini PWSS		Chapori NC				Control Board along with
						Lithium Ion
						Battery Damaged
						2. Clog in
						Deeptube Well
						3. Damage in
						Distribution Pipe/ Clog in Pipe
						4. Household Tap
						Connection Point
						Damage
						5. Chlorine Dozer
Hutton No. 4 Color	DUE	Llutto - NC	Huttor v = 1	02.00	26.04	affected partially.
Huttar No 1 Solar Mini PWSS	PHE	Huttar NC	Huttar no. 1	93.922	26.81	<ol> <li>Solar Panel</li> <li>Control Board</li> </ol>
IVIIIII PVV 33						along with
						Lithium Ion
						Battery Damaged
						2. Clog in
						Deeptube Well
						3. Damage in
						Distribution Pipe/
						Clog in Pipe 4. Household Tap
						Connection Point
						Damage
RANGAMURI Solar	PHE	Sarufakua NC	Sesuguri	93.92	26.8	1. Solar Panel
Powered Mini PWSS						Control Board
						along with





	1						Lithium Ion
							Lithium Ion Battery Damaged
							2. Clog in
							Deeptube Well
							3. Damage in
							Distribution Pipe/
							Clog in Pipe
							4. Household Tap
							Connection Point
							Damage
		BORPHAKUA Solar	PHE	Borfakua NC	Borfakua	93.926.81	1. Solar Panel
		Powered Mini PWSS	PNE	BOITAKUA INC	DOITAKUA	95.920.61	Control Board
		rowered Willin FW33					along with
							Lithium Ion
							Battery Damaged
							2. Clog in
							Deeptube Well
							3. Damage in
							Distribution Pipe/
							Clog in Pipe
							4. Household Tap
							Connection Point
							Damage
		HOTTER NO.1 Solar	PHE	Huttar NC	Huttar	93.9626.8	1. Solar Panel
		Powered Mini PWSS	''-	Tattai NC	i i decidi	33.3020.8	Control Board
		i owered willing wood					along with
							Lithium Ion
							Battery Damaged
							2. Clog in
							Deeptube Well
							3. Damage in
							Distribution Pipe/
							Clog in Pipe
							4. Household Tap
							Connection Point
							Damage
							5. Chlorine Dozer
							affected partially.
		JUGUNI DHARI	PHE	Jugunidhari	Jugunidhari	94.1426.92	Scheme was
		AUNIATI PWSS		-8			submerged
							under fresh
							flood.
							illoou.
							1.UGR plinth
							1.UGR plinth protectrion
							1.UGR plinth protectrion damaged
							1.UGR plinth protectrion damaged 2. Clog in deep
							1.UGR plinth protectrion damaged
							1.UGR plinth protectrion damaged 2. Clog in deep tube well
							1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection
							1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged
							1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in
		Huttar No 2 Solar	PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged
		Huttar No 2 Solar Mini PWSS	PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion
			РНЕ	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Clog in
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Clog in Deeptube Well
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Clog in Deeptube Well 3. Damage in
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Clog in Deeptube Well 3. Damage in Distribution Pipe/
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Clog in Deeptube Well 3. Damage in Distribution Pipe/Clog in Pipe
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Clog in Deeptube Well 3. Damage in Distribution Pipe/Clog in Pipe 4. Household Tap
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Clog in Deeptube Well 3. Damage in Distribution Pipe/Clog in Pipe 4. Household Tap Connection Point
			PHE	Huttar NC	Huttar	93.9226.81	1.UGR plinth protectrion damaged 2. Clog in deep tube well 3.Filter Plinth Protection Damaged 4. Affected in Boundary Wall 1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Clog in Deeptube Well 3. Damage in Distribution Pipe/Clog in Pipe 4. Household Tap





PURON CHAPORI Solar Powered Mini PWSS	PHE	Bhakat Chapori NC	Modarguri	93.8926.8	1. Solar Panel Control Board
IF VV-55					along with Lithium Ion Battery Damaged 2. Clog in Deeptube Well 3. Damage in
					Distribution Pipe/ Clog in Pipe 4. Household Tap Connection Point
					Damage 5. Chlorine Dozer affected partially.
Kolia Gaon Solar Mini PWSS	PHE	KoliaGaon	Kolia gaon	93.9526.82	1. Solar Panel Control Board along with Lithium Ion Battery Damaged 2. Chlorine Dozer
Bamun Gaon PWSS	PHE	KamalabariSatra	Bamun gaon	94.1726.92	affected partially.  1. Clog in DeepTube Well
Santipur PWSS	PHE	KamalabariSatra	Santipur	94.1626.94	1. Plinth Protection of the scheme damaged 2. Affected in Barge Horse Pipe Line (RWPM) 3. Affected in
•	PHE	Ujonijokaibuwa	Ajarguri Miligaon	94.1827.02	Boundary Wall Affected
PWSS ALIMUR KOIBORTTA Solar Powered Mini PWSS	PHE	NC	Alimur gaon	94.1226.92	1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall 3. Clog in Deeptube Well
Santipur PWSS	PHE	KamalabariSatra	Santipur	94.1626.94	1. Plinth Protection of the scheme damaged 2. Affected in Barge Horse Pipe Line (RWPM) 3. Affected in Boundary Wall
PWSS	PHE	Sumoimari	Lower Sumoimari	94.2326.93	1. Clog in Deeptube Well 2. Damage in Distribution Pipe/ Clog in Pipe 3. Household tap connection point damage 4. Clorine dozer damage affected partialy
Nambotiamari PWSS	PHE	KamalabariSatra	Nambotiamari	94.1726.93	1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall
KACHIKATA NATUN CHAPORI Solar Powered Mini PWSS	PHE	Kachikota NC	Kachikota Notun Chapori	93.8726.8	1. Solar Panel Control Board along with Lithium Ion





						Battery Damaged 2. Clog in Deeptube Well
						3. Damage in Distribution Pipe/Clog in Pipe
						4. Household Tap Connection Point Damage
						<ol><li>Chlorine Dozer affected partially.</li></ol>
NAMATI Solar Powered Mini PWSS	PHE	Namati NC	Namati	93.912	6.81	Solar Panel     Control Board     along with
						Lithium Ion Battery Damaged 2. Damage in
						Distribution Pipe/ Clog in Pipe 3. Household Tap
						Connection Point Damage 4. Chlorine Dozer
Sumoimari 1 Mini	PHE	Sumoimari	Sumoimari	94.242	6.93	affected partially.  1. Clog in
PWSS						Deeptube Well  2. Damage in  Distribution Pipe/
						Clog in Pipe  3. Household tap
						connection point damage 4.Clorine dozer
						damage affected partialy
Gual Gaon PWSS	PHE	Guwalgaon	Guwalgaon	94.062	6.94	<ol> <li>Due to heavy rainfall and rise of water level,</li> </ol>
						the soil is eroded from the scheme
						and damaged back wash line of the scheme.
AUNIATI SATRA Solar Powered Mini PWSS	PHE	Jugunidhari	Auniati Satra	94.112	6.92	1. House Hold Tap Connection point submerged
						2. Affected in Boundary Wall
						<ul><li>3. Clog in</li><li>Deeptube Well</li><li>4. Solar</li></ul>
						Controller damaged 5. FRP Vessel and
						controller affected
CHENGELI CHUTI (2) Solar Powered Mini PWSS	PHE	Auniati Jungle NC	Chengelisuti	94.12	6.92	House Hold     Tap Connection     point submerged     Affected in
						Boundary Wall 3. Clog in Deeptube Well 4. Distribution leakages found
JAMUGURI Solar Powered Mini PWSS	PHE	Bhakat Chapori NC	Modarguri, Bhakat Chapori	94.092	6.92	1. House Hold Tap Connection point submerged 2. Affected in





П	1 1	1	1		T	<del>                                     </del>	D - 1 ··· "
							Boundary Wall  3. Affected in
							3. Affected in solar controller
							3. Clog in
							Deeptube Well
							4. Distribution
							leakages found
		DARBAR CHAPORI	PHE	Kartik Chapori	Darbar Chapori	94.1826.8	5 1. House Hold
		Solar Powered Mini	1	NC			Tap Connection
		PWSS					point submerged
							2. Affected in
			1				Boundary Wall  3. Clog in
							Deeptube Well
							4. Distribution
							leakages found
		SADHU CHAPORI	PHE	Kachikota NC	Purona Kachikota	93.8726.8	1. Solar Panel
		Solar Powered Mini					Control Board
		PWSS					along with
							Lithium Ion
							Battery Damaged
							<ol><li>Chlorine Dozer affected partially.</li></ol>
		BORTANI Solar	PHE	Jugunidhari	Bortani	94.1626.8	
		Powered Mini PWSS	[	- Sagarmanian		31020.0	Tap Connection
							point submerged
							2. Affected in
							Boundary Wall
			1				3. Clog in
							Deeptube Well
		KARTIK CHAPORI	PHE	Kartik Chapori	Kartik Chapori	94.1726.8	
		Solar Powered Mini PWSS		NC			Tap Connection point submerged
		1 4433					2. Affected in
							Boundary Wall
							3. Affected in
							solar controller
							4. Clog in
							Deeptube Well
							5. Distribution
							leakages found
							6. Raw Water Pumping Main
							Damaged
		Missamora No. 2(1)	PHE	Missamora NC	Misamora no. 2	93.9326.9	
		Dum Chuk Solar Mini					Deeptube Well
		PWSS					
			PHE	Missamora NC	Misamora no. 2	93.9226.9	
		CHAPORI Solar					Tap Connection
		Powered Mini PWSS					point submerged
							<ol><li>Affected in Boundary Wall</li></ol>
							3. Affected in
							solar controller
							4. Clog in
							Deeptube Well
							5. Distribution
							leakages found
			PHE	MalapindhaMiri	Bordua Balijan	94.0426.9	
		Solar Powered Mini					tap point
		PWSS	PHE	Auniati lungis	Congoli Suti No. 2	02.0526.0	leakages found
		Sengeli Suti No. 2 Mini PWSS	rnc r	Auniati Jungle NC	Sengeli Suti No. 2	93.9526.9	<ol> <li>Clog in DeepTube Well</li> </ol>
1			PHE	Auniati Jungle	Sengelisuti	93.9426.9	
		Mini PWSS	[	NC	Denbenado	33.3420.3	DeepTube Well
			1		<del> </del>	00.000.0	
		Missamora No. 2(1)	PHE	Missamora NC	Misamora no. 2	93.9326.9	1 [1.Clog in
		Missamora No. 2(1) Solar Mini PWSS	PHE	Missamora NC	Misamora no. 2	93.9326.9	<ol> <li>1.Clog in Deeptube Well</li> </ol>
				Missamora NC  Bhakat Chapori		94.0826.9	Deeptube Well





							point submerged
							2. Affected in Boundary Wall
							3. Affected in
							solar controller
							4. Clog in
							Deeptube Well
							5. Distribution
		NA:NI2	DUE	1.4°	14:	02.0526.0	leakages found
			PHE	Missamora NC	Misamora no. 2	93.9526.9	1. Distribution
		Mini PWSS					tap point
		Davidson Charact	DUE	N 4 - I II N 4	David an Channel	04.0426.06	leakages found
		•	PHE	iviaiapindnaiviiri	Borduar Chapori	94.0426.96	1. Distribution
		Retrofitting					tap point
		Pokimuri Mini PWSS	חור	Bhakat Chapori	Dolainouri	94.0726.92	leakages found  1. Distribution
		POKIIIIUII IVIIIII PVV33	FIL		Pokilluli	94.0726.92	
				NC			tap point
							leakages found
							2.Clog in
		Podumoni Solar Mini	DHE	Bhakat Chapori	Podumoni	94.0926.91	Deeptube Well  1. House Hold
		PWSS	FUE	NC	FOUUIIIOIII	54.0926.91	
		r vv 33		INC			Tap Connection point submerged
							2. Affected in
							solar controller
							3. Clog in
							Deeptube Well
							4. Distribution
							leakages found
		Kuli Chapori Mini	PHE	Bebejia	Kuli Chapori	9426.94	1. Distribution
		PWSS		Debejia	Kull Chapori	3420.34	tap point
							leakages found
		AUNIATI	PHE	Jugunidhari	Jugunidhari	94.1226.94	1. Distribution
		JUGINIDHARI (NEW)		Jagamanan	Jugumumum	31.1220.31	pipe line eroded
		PWSS					(approx 200m)
							due to failure of
							embankment
							dyke at
							Juginidhari
							2.Plinth
							Protection Work
							Damaged
							3. Affected in
							boundary wall
							4. Affected in
							foundation of
			1				sedimentation
	1 1						Sedimentation
							work
1		BEBEJIA (NEW) PWSS	PHE	Bebejia	Bebejia	94.0126.92	
		BEBEJIA (NEW) PWSS	PHE	Bebejia	Bebejia	94.0126.92	work
		BEBEJIA (NEW) PWSS	PHE	Bebejia	Bebejia	94.0126.92	work  1. Distribution
		BEBEJIA (NEW) PWSS	PHE	Bebejia	Bebejia	94.0126.92	work  1. Distribution tap point
		BEBEJIA (NEW) PWSS	PHE	Bebejia	Bebejia	94.0126.92	work  1. Distribution tap point leakages found
		BEBEJIA (NEW) PWSS	PHE	Bebejia	Bebejia	94.0126.92	work  1. Distribution tap point leakages found 2. Plinth
		BEBEJIA (NEW) PWSS	PHE	Bebejia	Bebejia	94.0126.92	work  1. Distribution tap point leakages found 2. Plinth Protection and
			PHE PHE	Bebejia  Bhakat Chapori		94.0126.92	work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall
							work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected 1. House Hold
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected 1. House Hold Tap Connection
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected 1. House Hold Tap Connection point submerged
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected  1. House Hold Tap Connection point submerged 2. Affected in
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected  1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected  1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall 3. Affected in
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected  1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall 3. Affected in solar controller
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected  1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall 3. Affected in solar controller 4. Clog in
		MODAR GURI Solar		Bhakat Chapori			work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected  1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall 3. Affected in solar controller 4. Clog in Deeptube Well 5. Distribution
		MODAR GURI Solar	PHE	Bhakat Chapori		94.0926.92	work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected  1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall 3. Affected in solar controller 4. Clog in Deeptube Well 5. Distribution leakages found
		MODAR GURI Solar Powered Mini PWSS	PHE	Bhakat Chapori NC	Modarguri		work  1. Distribution tap point leakages found 2. Plinth Protection and boundary wall affected  1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall 3. Affected in solar controller 4. Clog in Deeptube Well 5. Distribution





										2. Affected in
										Solar Controller
				MOLOYA CHAPORI PWSS.	PHE	Missamora NC	Moloya Chapori	93.97	26.91	1. House Hold Tap Connection point submerged 2. Affected in Boundary Wall 3. Intake point submerged and damage
										centrifugal pump (both standby and working) 4. Distribution leakages found
				Arjunguri Mini PWSS	PHE	Chilakola Koibort a	Birinabari	94.09	26.96	Distribution tap point leakages found     Clog in Deeptube Well
				Sriramporia Mini PWSS	PHE	Ukhol chuck	Sriramporia okhala chuk	94.02	26.92	Distribution     tap point     leakages found
	Ujani Majuli	Fisheries/P ond (in	7	Niranjan Padun	Fishery		Uper Sumaimari, P.O- Dakhinpat		26.92	Water area- 0.10 Ha
		Hect.)		Satyanath Pegu	Fishery		Uper Sumaimari, P.O- Dakhinpat		26.92	Water area- 0.10 Ha
				Jiboram Charoh	Fishery		Uper Sumaimari, P.O- Dakhinpat		26.93	Water area- 0.15
				Bijoy Doley Ajit pegu	Fishery Fishery		Uper Sumaimari, P.O- Dakhinpat Uper Sumaimari, P.O-		26.92 26.92	Water area- 0.20 Ha Water area- 0.10
				Ajit Pegu	Fishery		Dakhinpat Uper Sumaimari, P.O-		26.92	Ha Water area- 0.15
				Amrit Sarovar at	P&RD	Jengrai	Dakhinpat Vill- Borpumuwa,			Ha water area- 1 Ha
Morigao	Bhuragao	Nil	Nil	Deori Beel Nil	Nil	Moghuwachuk Nil	Jengrai Moghuachuk Nil	Nil	Nil	Nil
n	n									
	Morigaon Mayong	N <sub>I</sub> I Irrigation	Nil	Nil Chotabori PC 1,2,3	Nil Irrigation	Nil Chatabari	Nil CHATABARI	Nil	Nil 26.19	Nil D1 canal
		Canal/Sche me Damaged (in Nos)			J					damaged ch.froi 5m to 45m as reported by Irrigation department on 06/07/2024
	Laharigha t	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Nagaon	Kaliabor	Irrigation Canal/Sche me Damaged (in Nos)		Canal Structure like adequate was affected by Water Hyacinth under Kaliaboe LIS.		Jakhalabandha Town Jakhalabandha	Jakhalabandha		1	Canal Structure like adequate was affected by Water Hyacinth under Kaliaboe LIS. However, clearing oh Hyacinth was being carried ou with the help of local administration.
				Pump House of Jakhalabandha LIS, Chatial LIS, Uluoni LIS	Irrigation	Jakhalabandha Town	۲		1	Jakhalabandha LIS, Chatial LIS, Uluoni LIS were also submerged. Hence, it is





					mechanical equipment are
					damaged.
Elementary Schools	44 No Bhurbandha New LP School	Education Deptt.	Bhurbandha No.2	Bhurbandha No.2	4 No Bhurbandha New LP School
Damaged (in Nos)	New Li School	Бери.	140.2		were damage due to Flood
(III NOS)					water.
	2 No. Bhurbandha Binapani LP School	Education Deptt.	Bhurbandha No.2	Bhurbandha No.2	2 No. Bhurbandha
	·				Binapani LP
					School were damage due to
	Bhurbandha Bazar	F-1	Bhurbandha	Bhurbandha	Flood water. Bhurbandha
	gaon LP school	Deptt.	No.2	Briurbariuria	Bazar gaon LP
					school were damage due to
					Flood water.
	Bhurbandha ME school	Education Deptt.	Bhurbandha No.2	Bhurbandha No.2	Bhurbandha ME school were
		.			damage due to Flood water.
Handloom	2Loom and	Handloom	Kuthari	Dhekialgaon, Sensuwa,	15 nos. of Loom
& Textile Deptt (in	Accessories	& Textile		Miribheti, Kuthori,Bagori,	and Accessories were damage
Nos)				Dakhinpat, Kolongpar,	due to flood
	Raw Materials	Handloom	Kuthari	Borbhetigaon Dhekialgaon, Sensuwa,	water. 10 nos. of raw
		& Textile		Miribheti,	material were
				Kuthori,Bagori, Dakhinpat, Kolongpar,	damage due to flood water.
Anganwadi	10Sarubhagia PT-3	Women &	Sarubhagia	Borbhetigaon KotiyariGaon	AWC Damaged
Centres	AWC	Child			due to flood
Affected (in Nos)		Developm ent			water report submitted by
					Kaliabor ICDS Project
	Namgaon AWC	Women &	Namgaon	Namgaon	AWC Damaged
		Child Developm			due to flood water report
		ent			submitted by
					Kaliabor ICDS Project
	Purani Satra AWC		Chatial Gaon	Chatial	AWC Damaged
		Child Developm			due to flood water report
		ent			submitted by Kaliabor ICDS
					Project
	Chatial 1 AWC	Women & Child	Chatial Gaon	Chatial	AWC Damaged due to flood
		Developm			water report
		ent			submitted by Kaliabor ICDS
	5			D 1100 H 1	Project
	Dulal Madhab TB2 AWC	Women & Child	Dulal Madhab	Dulal Madhab	AWC Damaged due to flood
		Developm			water report
		ent			submitted by Kaliabor ICDS
	1 No Halowagaon	Momes o	Halowa Gaon	Halowagaon	Project AWC Damaged
	AWC	Child		ITAIUWAKAUII	due to flood
		Developm ent			water report submitted by
					Kaliabor ICDS
					Project





			151 No dergaon Chuk AWC	Women & Child	Mariagaon	MariaGaon			AWC Damaged due to flood
			CHUK AWC	Child Developm ent					water report submitted by
									Kaliabor ICDS Project
			Pubtharia AWC	Child	Niz Pubthoria	Niz Pubthoria			AWC Damaged due to flood
				Developm ent					water report submitted by Kaliabor ICDS
			140 No Daidanais	M/2	N.A	Daideania Chul			Project
			140 No Raidengia Chuk	Child Developm ent	Mariagaon	Raidengia Chuk			AWC Damaged due to flood water report submitted by Kaliabor ICDS Project
			Jayantipur Kekurabari AWC	Women & Child Developm ent	Mariagaon	Mariagaon			AWC Damaged due to flood water report submitted by Kaliabor ICDS
	Bridge Approach Road Washed Away (in Nos)	1	One Foot Bridge over river Kollong was washed away at Gumutha Gaon of Jakhalabandha of Irrigation	Irrigation	Jakhalabandha Town	Jakhalabandha			Project  One Foot Bridge over river Kollong was washed away at Gumutha Gaon of Jakhalabandha of
			Deparment.						Irrigation Deparment.
	Health Sub- Centre (in Nos)	2	Sarbura Engti HWC/AAM	Health & Family Welfare	Bagari	Kanchanjuri			Sarbura Engti HWC/AAM were submerged due to flood water .
			Thankur Chang HWC/AAM	Health & Family Welfare	Bagari	Kanchanjuri			Thankur Chang HWC/AAM were submerged due to flood water.
Raha	Irrigation Canal/Sche me Damaged (in Nos)		Laopani Lift Irrigation Dcheme	Irrigation	Laupani	Laupani	92.59	26.19	Canal Damage due to flood water
	Power Dept. Conductors (in Nos)		Raha SDE	APDCL	Chenga Jan	Chengajan, Dharmukh, Bajbatamari, Nalduba, Cheoguri, Magurgaon, Guimari, Dangori bill, Dabalu, Hagaltoli, Hatimura, Bajbatamari, udaybheti, bagalajan, pahupuri hariapar, pahupuri, kajalajan, Namrangagarah			8km conductor were damaged due to flood water
	Power Dept. Poles (in Nos)				Chenga Jan	Chengajan, Dharmukh, Bajbatamari, Nalduba, Cheoguri, Magurgaon, Guimari, Dangori bill, Dabalu, Hagaltoli, Hatimura, Bajbatamari, udaybheti, bagalajan, pahupuri hariapar, pahupuri, kajalajan, Namrangagarah			Total 18 nos. of poles were damaged due to flood water
Dhing	Nil	Nil	Nil		Nil	Nil		Nil	Nil
Kampur	Nil	Nil	Nil		Nil	Nil		Nil	Nil
Samaguri	NII	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil





	Nagaon	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Sivasagar		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Sonari RC		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	part	INII	INII	INII	INII	INII	INII	INII	INII	INII
	-	Anganwadi	-	32 No. Miripathar	Women &	Miri Pather	Miri Pathar	94.72	27.24	
		Centres	,	AWC	Child		······	"""		
		Affected (in			Developm					
		Nos)			ent					
				Ekorani Pathar AWC	Women &	Ekorani	Ekorani	94.76	27.12	
					Child					
					Developm					
					ent					
				Samukjan AWC	Women &	Samukjan	Samukjan			
					Child					
					Developm					
					ent					
	Ü	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Sonitpur	Tezpur	Public	1	Jarani Solar PWSS	PHE	1 No Jharani	Jharani	92.68	26.64	Dated
		Health				Chapori				07.07.3024. As
		Engineering	5							reported by PHE,
		(PHE) (in								Tezpur Division
		Nos)								no. II and
										Dhekiajuli Jarani Solar PWSS is
1										water logged.
	Dhekiajuli	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	South	PWSS		LPWSS	PHE	Monirchar	Monirchar	-		11. Mandurgaon
		Damaged	1.	LF VV33	FIIL	ivioriii criai	Wiorini Criai			pwss
Jannara	Samuara	(in Nos)		PWSS	PHE	Tumni	Tumni			9. LAWKHOWA
		(1111103)		1 ***55	''-					SHAULIARTEK
				PWSS	PHE	Patakata	Patakata			1. Patakata pwss
						a didikata	ratanata			Retrofitting
										2. Talukdarpara
										pwss
										3. Kurakanda
										pwss
										4. CHEDAMARI
										PWSS
										5. Boro Patakata
										6. Ghunergaon
										pwss
										7. Char satdubi
				DIAKES	DUE	C. I It	Calcalia	<u> </u>		pwss
İ				PWSS	PHE	Seboltary	Seboltary			10. sebaltary
				DIA/CC	DUE	Colmore Di i	Courth Calman	1		pwss
				PWSS	PHE	Salmara Pt-I	South Salmara			8. South Salmara pwss of
										pwss of retrofitting
	Mankacha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	r	T 111		1411		1411	1411	ANII	1.411	1411
Tinsukia	Doomdoo	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	ma	. <del></del>			[			ļ	[ <del></del>	<u> </u>
	Sadiya	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Margherit		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	a				[ "	[		'''	. • • • • • • • • • • • • • • • • • • •	[ ]
Udalguri	Harisinga	Fisheries/P	43	BFishery Pond	Fishery	Jabanga Pathar	Jabangapathar	91.82	26.67	
		ond (in	"	affected	,			31.02		
		Hect.)		Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.83	26.65	1
				affected	',					
					Fishery	Parbahu Chuba	Parbahuchuba	91.83	26.66	1
				affected	'					1
					Fishery	Jabanga Pathar	Jabangapathar	91.82	26.67	
				Fishery Pond	i isiici y					
				Fishery Pond affected	i isriei y					
					Fishery		Jabangapathar	91.82	26.67	
				affected				91.82	26.67	
				affected Fishery Pond affected	Fishery				26.67 26.65	





_				
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8426.66
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.66
Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.66
affected Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.8426.66
affected	risticty	r arbana chaba	i di bandenaba	
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.66
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8426.66
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8426.66
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.65
Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
affected Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
affected		Parbanu Chuba	Parbanucnuba	91.8320.03
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.66
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.66
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.64
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
affected Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.8826.65
affected Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.65
affected Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
affected Fishery Pond	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
affected				
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8426.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.66
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.8326.65
Fishery Pond affected	Fishery	Parbahu Chuba	Parbahuchuba	91.83 26.65
Fishery Pond affected	Fishery	Babarikhat	Babarikhat	91.8626.66
Fishery Pond	Fishery	Babarikhat	Babarikhat	91.8526.66
affected Fishery Pond	Fishery	Babarikhat	Babarikhat	91.8526.66
affected		1		





		1			Fishery Pond	Fishery	Babarikhat	Babarikhat	91.85	26.66	1
					affected	i isrici y	Babarikilat	Basarikilat	31.03	20.00	
					Fishery Pond affected	Fishery	Babarikhat	Babarikhat	91.85	26.66	
		_	Irrigation Canal/Sche me Damaged (in Nos)		Breach of Earthen canal embankment	Irrigation	Borigaon No.2	No. 2 Borigaon ( near Ahom Mokha)	92.16	26.77	Breach of earthen canal embankment of D3B1M canal at Ch. 2340.00 meters, measuring Length - 10.00 meters, Breadth - 4.00 meters, Height - 3.30 meters.
					Damage of RCC box culvert			No. 2 Borigaon (near Ahom Mokha)		26.77	Damage of RCC box culvert of D3B1M canal at Ch. 2350.00 meters, measuring Length - 6.00 meters, Breath - 4.00 meters, Height - 3.00 meters.
		Khairabari		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			Irrigation Canal/Sche me Damaged (in Nos)		Bokrajhar FIS Makelikanda FIS	Irrigation	Uttar Bokorajhar Niz Dalgaon	Near Paddy ground  Covering an wider area		26.55 26.61	The canal embankment damaged due to post flood erosion by the receding water at ch 0.00 and at ch 3500.00 m on 07/07/2024  The canal
								at village Hirapara, Naharbari and Habijhar			embankment has damaged remarkably due to post flood erosion by the receding water at ch 3500.00m on 07/07/2024
Wildlife	District	Details									
	Barpeta	(Chenga -	0)								
	Biswanat	(Gohpur -	0)								
	h Rongaiga										
	Bongaiga on										
	Cachar										
	Charaide										
	o Chirang										
	Darrang										
	Dhemaji										
	Dhubri										
	Dibrugar b										
	h Goalpara										
1	1	i									





	_	(Bokakhat - KAZIRANGA NATIONAL PARK AND TIGER RESERVE BOKAKHAT REPORT ON 07-07-2024 AGRATOLI, KAZIRANGA, BAGORI, BURHAPAHAR, BOKAKHAT, BISWANATH WL DIVISION, NAGAON WL DIVISION TOTAL CAMPS 233 nos. INNUNDATED CAMPS AS ON DATE UPTO 5 FEET 69 nos.
		CAMP VACATED AS ON DATE 5 nos. No of Animal rescued 96 nos. Cumulative No of Animal died 125 nos. Cumulative )
	Hailakan di	
	Hojai	
	Jorhat	
	Kamrup	(Nagarbera - 0)
	Kamrup (M)	
	Karimga nj	
	Kokrajha r	
	Lakhimp ur	
	Majuli	
	Morigao n	(Mayong - 15 nos of Camps inundated under Pobitora WLS as reported by Range Officer.)
	Nagaon	
	Nalbari	
		(Nazira - 0)
	Sonitpur	
	South Salmara	
	Tinsukia	
	Udalguri	
Remarks	District	Details
	Barpeta	
	Biswanat h	
	Bongaiga on	
	Cachar	
	Charaide o	
	Chirang	
		(Sipajhar - Report submitted based on the reports received from Lot mandal, Gaonpradhan and officials of concerned departments. Dated 07-07-2024.), (Pub-Mangaldai - Today, (7-7-2024) 11 no boats are deployed for GR for human and cattle feed distribution from Mowamari Ghat(sereng Ghat) and Rangamati Ghat to various villages under Pub Mangaldai Revenue Circle.  And Yesterday (6-6-2024) evening 2 boats were deployed for GR distribution. Therefore all total Boats 13 no's.), (Dalgaon - 1000 nos of tarpaulin distributed on 05-07-2024 under Dalgaon Revenue Circle), (Mangaldoi - 3000 nos of tarpaulin distributed on 07-07-2024 under Mangaldai Revenue Circle.)
		(Jonai - At Gali Ghat, Gali Kachari, Naharjun, Madhupur, Amarpur, Bandana, Siker Selek, Malbhug Mishing , 1334 L 250 ml Mustrad oil has been issued against 14827 Population.
		(Golakganj - Out of total affected 67 villages, 17 nos are fully affected and 50 are partially affected.), (Chapar - PWD ROADS, FISHERY, MGNREGA AND AMRIT SAROVER SCHEMES ARE ONLY SURMERGED BY RISING WATER OF RIVER BRAHMAPUTRA AND DAMAGES MAY BE ASSESSED AFTER WATER RECEDE)
		(Tingkhong - Baby diaper 536 nos), (Dibrugarh West - Baby diaper 10 nos), (Moran - Animal Health Treatment camp 1 no.), (Dibrugarh East - Animal Health Treatment Camp - 1 no), (Tengakhat - Baby diaper 318 nos)
	Goalpara	
		(Bokakhat - 1. PMAY-G ID- AS 145413212 of Bohikhuwa on 5.7.2024 2. PMAY-G ID- AS 148438480 of Polashguri on 5.7.2024
		3. PMAY-G ID- AS 2604965 of Bohikhuwa on 5.7.2024 4. PMAY-G ID- AS 147445606 of Polashguri on 5.7.2024
		5. PMAY-G ID- AS 147024279 of beloguri on 5.7.2024
		6. Community toilet near at Bamungaon tiniali under water on 5.7.2024
		7. Community toilet near at Bezgaon END mathauri, under water on 5.7.20248.
		8. Total 26 Nos PMAY-G houses of Jugonia Ati Village, Ward No 4, Damaged not identified on 5.7.2024
		9. Constrution of CC block road from Suren Gogoi house, ward No-7 to Keshab Gogoi house, ward No-10 of Pub- kaziranga GP, screening





		material flew away on 5.7.2024 )
	Hailakan di	
	Hojai	
	Jorhat	(Jorhat East - As per information received from women and child development, total Rice-31.5 kg, Dal-14.5 kg, vegetables-10 kg, egg-225 Nos. Were distributed in the flood prone areas under Jorhat East Revenue Circle. Dated-07-07-2024)
	Kamrup	(Palashbari - Reports are prepared on the basis of Gaonpradhan, LRA and Concerned depertment officials.)
	Kamrup (M)	
	Karimga nj	
	Kokrajha r	
	Lakhimp ur	
	Majuli	
	Morigao n	
	Nagaon	
	Nalbari	
	Sivasagar	
	Sonitpur	
	South Salmara	(South Salmara - 244 nos. of Pit latrine has been constructed in the Patakata GP, Tumni GP, Monirchar GP, South Salmara GP, Baladoba GP, Seboltari GP, Hazirhat GP and Gotabari Khopati GP under the South Salmara Rev. Circle.), (Mankachar - 41 nos. of Pit latrine has been constructed in Borariaralga, Maliralga and Sukchar GP under Mankachar Rev. Circle.)
	Tinsukia	(Sadiya - Items distributed at relief camp- egg- 9 pic)
	Udalguri	
_		Report Generated On: 07-07-2024 07:43 PM





				Α	ssam Urban	Flood Repor	t as on 07-0	07-2024				
Particulars					Assam	urban Floo	d Report as	on 07-07-2	024			
District	No. of	Name of A	Affected Dis	tricts								
Affected	Districts											
	Affected											
		Dibrugarh,	, Kamrup (N	l), Karbi Ar	nglong							
No. Of	3											
Revenue												
Circles Affected												
Name Of	District	Total	Revenue C	ircle								
Revenue Circle			Dibrugarh									
Affected	Kamrup	1	Guwahati	Lasi								
	(M)	1	Guwanau									
	Karbi	1	Diphu									
	Anglong	_	2.5									
		3										
Villages	District	Total	Revenue C	ircle								
Affected	Dibrugarh	4	(Dibrugarh	East   4)								
	Kamrup	1	(Guwahati									
	(M)		ľ									
	Karbi	1	(Diphu   1)									
	Anglong											
		6										
Population	District	Male	Female	Children		Population [	Details		Ward		Total Ward	Locality
Affected					Population							
	Dibrugarh	507	432	89	1028	Dibrugarh Ea	ast 1028		Ward 4, Wa	ard 16,	3	Police reserve,
									Ward 17			ushapur, jail
												road, bapuji path, breeywhite
												colony, gandhi
											nagar, guala	
												patty,
	Kamrup	0	0	0	0	Kamrup (M)	10					0
	(M)						•					
	Karbi	14	12	16	42	Karbi Anglon	ıg 42		Ward 4		1	Baghmari, Diphu
	Anglong											
	Total	521	444	105	1070						4	
Relief Camps /	District	Total	Relief Cam	р			Relief Dist	tribution Ce	ntres			
Centres	Dibrugarh	1	1 (Dibrugai	rh East   1)	)		0 (Dibruga	rh East   0)				
Opened	Kamrup	0	0 (Guwaha	ti   0)			0 (Guwaha	ati   0)				
	(M)											
	Karbi	0	0 (Diphu	0)			0 (Diphu	0)				
	Anglong	_					_					
		1	1			1 .	0	1		1		
Inmates In	District	Total	Revenue C	irclewise		Male	Female	Children		Person wit	h Disability	
Relief Camps									Lactating Mother			
	Dibrugarh	102	(Dibrugarh	Eact   193	))	67	67	45	3	0		
	Kamrup	0	(Guwahati			0	0	0	0	0		
	(M)	0	Guwanati	ı <i>0)</i>			5		J	ĭ		
	Karbi	0	(Diphu   0)			0	0	0	0	0		
	Anglong	ſ	(2.510   0)			Ĭ		ſ		Ĩ		
		182				67	67	45	3	0		
Human Lives		Total	Male	Female		ldren	Others	Revenue Ci				
Lost -						Female			-			
Confirmed	Dibrugarh	0	0	0		0	0	0 (Dibrugar	h East   0)			
	Kamrup	1	0	0		0	0	1 (Guwaha				
	(M)	_	Ĭ	Ĭ	_	Ĭ	ſ	Cawaila	··   <del>-</del> /			
	Karbi	0	0	0	0	0	0	0 (Diphu   0	0)			
	Anglong	ĺ	Ī	Ī		-	Ī	, 1 20.04.6	- /			
		1	0	0	1	0	0					
Human Lives	District	Total	Male	Female		ldren	Others	Revenue C	irclewise			
Lost - Missing						Female			-			
	Dibrugarh	0	0	0		0	0	0 (Dibrugar	h East I (1)			
		<u> </u>		1-	<u></u>	-	<u> </u>	- \=.~.ugui				





	L.	1_	1_	I_	I_	I-	1_	I- /				
	Kamrup	0	0	0	0	0	0	0 (Guwahat	:i   0)			
	(M) Karbi	0	0	0	0	0	0	0 (Diphu   0	וו			
	Anglong		U	U	U	U		ן טוואוט) ט	וי			
		0	0	0	0	0	0					
Livestocks		Total	Big	-	Poultry	<u> </u>	<u> </u>					
		0	0	0	0							
	Kamrup	0	0	0	0							
	(M)		ľ	U								
	Karbi	26	0	3	23							
	Anglong											
		26	0	3	23							
Livestocks	District	Total	Big	Small	Poultry							
Washed Away	Dibrugarh	0	0	0	0							
		0	0	0	0							
	(M)											
	Karbi	0	0	0	0							
	Anglong											
	Total	0	0		0							
Houses		Fully	Fully Pukka	Fully Tota	al		Partially	Partially To	tal		Severely	Severely Total
Damaged		Kuccha					Pukka	_		Kuccha	Pukka	
	Dibrugarh		0	0		0	0	0		0	0	0
		0	0	0		0	0	0		0	0	О
	(M) Karbi	0	0	0		0	0	0		0	0	0
	Karbi Anglong	U	۲	۲		٢	V	U		۲	۲	٢
	Total	0	0	0		0	0	0		n	0	0
Rescue		Agency			Other Agen	cies Involved		Person	Animal	Number of	_	Medical Team
Operation	District	Agency			Other Agen	cies ilivolveu	of Boat	Evacuated		Helicopter		
o peration							Deployed		by Boat	Deployed	by	Deployeu .
							,	,	.,	., .,	Helicopter	
	Dibrugarh						C	0	C	) C	C	0
	Kamrup						C	0	C	) C	C	0
	(M)											
	Karbi						C	0	C	0	0	0
	Anglong											
	Total		_				C				0	О
Relief	District	Rice (in Q)	Dal (in Q)		M. Oil (in L)	Cattle Feed -		Cattle Feed	- Rice Bran	(in Q)		
Distributed				Q)		Green Fooder (in	Feed - Wheat					
							Bran (in					
						-	Q)					
	Dibrugarh	0	0	0	0	0	0	0				
	Kamrup	0	0	0	0	0	0	0				
	(M)											
	Karbi	0	0	0	0	0	0	0				
	Anglong											
	Total	0	0		0		0	0				
Relief		Baby Food	Liquid	Baby Foo	d Solid	Others						
Distributed -	Dibrugarh											
Others				1		1						
	Kamrup											
	(M) Karbi			<u> </u>		1						
	Karbi Anglong											
Infrastructure		Number	Revenue	Road Nar	ne	Department	Village	Location		Longitude	Latitude	Remarks
Damaged -	J.531160		Circle		-	_ cpartment						
	Dibrugarh	0	(Dibrugarh	Nil		Nil	Nil	Nil		Nil	Nil	Nil
			East   0)									
	Kamrup	0	(Guwahati	Nil		Nil	Nil	Nil		Nil	Nil	Nil
	(M)		0)									
	Karbi	0	(Diphu   0)	Niil		Nil	Nil	Nil		Nil	Nil	Nil
I		0	(Dipilu   U)	1411								
	Anglong		(Dipliu   0)	IVII								
	Anglong <b>Total</b>	0										
	Anglong <b>Total</b>			Bridge Na	ame	Department		Location		<b>Longitude</b>	<b>Latitude</b>	Remarks





Infrastructure	Dibrugarh	0	(Dibrugarh	Nil		Nil	Nil	Nil	Nil	Nil	Nil	
Damaged -			East   0)									
Bridge	Kamrup	0		Nil		Nil	Nil	Nil	Nil	Nil	Nil	
	(M)		0)									
	Karbi	0	(Diphu   0)	Nil		Nil	Nil	Nil	Nil	Nil	Nil	
	Anglong											
	Total	0										
Infrastructure	District	Revenue	Damages	Number	Name	Department	Village	Location	Longitude	Latitude	Remarks	
Damaged -		Circle										
Others	_	Dibrugarh East	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	
	Kamrup (M)	Guwahati	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	
	Karbi	Diphu	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	
	Anglong											
Remarks	District	Details										
	Dibrugarh											
	Kamrup (M)	due to hea GMC, SDRI	uwahati - This is regarding the case of missing boy Abhinash Sarkar, Age- 8 years, s/o- Horolal Sarkar who got drowned in the drain e to heavy rain on thursday (04-07-2024) in the area Jyotinagar, Bamunimaidam. After search operation by District Administration, AC, SDRF, NDRF and local police finally today (07-07-2024) the body has been recovered in the area Rajgarh, Apurba Sinha Path er 60 hours.)									
	Karbi Anglong											
								Rep	ort Genera	ted On: 07-0	07-2024 07:35 PM	