

## **FRIMS Assam**



## Flood Reporting And Information Management System

				Daily Flood Report as on 2	3-06-2023 at 4:00 PM			
Particulars	Situation as on 23-06-2023 (in last 24 hours)							
Rivers flowing above Danger Level (as	Rivers flowing	; above dan	ger level	Manas (Nh Road Crossing), Pagladiya (Nt Road Crossing), Puthimari (Nh Road Crossing), Brahmaputra (Dhubri; Neamatighat)				
per CWC bulletin issued at 8 AM)	Rivers flowing flood level	; above hig	nest	Nil				
District/Sub	No. of Districts/Su b-divisions* Affected	Name of divisions		ected Districts/Sub-	Name of Urban Flood Districts/Sub-divisions*			
-division Affected	19	Bongaiga Dhubri, I Kamrup,	on, Chirar Dibrugarh,	eta, Biswanath, ng, Darrang, Dhemaji, Goalpara, Golaghat, , Lakhimpur, Nagaon, Udalguri	Darrang, Kokrajhar			
No. Of Revenue Circles Affected	54			-				
	District/Sub -division*	Total	Revenue	e Circle				
	Bajali	2	Sarupeta	ı. Bajali				
	Baksa	4		Baska, Barama, Baganpara, Jalah				
	Barpeta	3	Barpeta, Chenga, Sarthebari					
	Biswanath	2	Gohpur, Halem					
	Bongaigaon	3	Boitamari, Bongaigaon, Srijangram					
	Chirang	2	Bijni, Sidli					
	Darrang	4	Patharighat, Sipajhar, Dalgaon, Mangaldoi					
Name Of	Dhemaji	1	Dhemaji					
Revenue	Dhubri	6	Golakganj, Dhubri, Athani, South Salmara Part, Bilasipara, Agamoni					
Circles	Dibrugarh	4		Γingkhong, Dibrugarh Wes				
Affected	Goalpara	1	Lakhipu		.,,			
	Golaghat	1	Bokakha					
	Kamrup	5		North Ghy, Kayan, Kamalpur, Rangia, Hajo				
	Kokrajhar	3	Gossaigaon, Dotma, Kokrajhar					
	Lakhimpur	2		, Nowboicha				
	Nagaon	1	Raha					
	Nalbari	7		ri, Banekuchi, Barbhag, Na	ılbari, Tihu, Paschim Nalbari, Ghograpar			
	Tamulpur	2	Goreswa	r, Tamulpur	· -			
	Udalguri	1	Khairaba	ari				
	Total	54						
	District/Sub -division*	Total	Revenue	e Circle				
	Bajali	191	( Sarupe	ta   80 ), ( Bajali   111 )				
	Baksa	41		16), (Barama   7), (Bag	anpara   15 ), ( Jalah   3 )			
	Barpeta	73		a   17), (Chenga   9), (Sa				
	Biswanath	8	( Gohpu	r   1 ), ( Halem   7 )				
Villages	Bongaigaon	123		nari   57 ), ( Bongaigaon   8	5), (Srijangram   58)			
Affected	Chirang	25	(Bijni	18), (Sidli   7)				
	Darrang	178	( Pathari	ghat   13 ), ( Sipajhar   74 )	), ( Dalgaon   16 ), ( Mangaldoi   75 )			
	Dhemaji	1	( Dhema	ji   1 )				
	Dhubri	309	( Golakg Agamon		( Athani   51 ), ( South Salmara Part   115 ), ( Bilasipara   10 ), (			
	Dibrugarh	10	Ū	•	Dibrugarh West   6 ), ( Chabua   1 )			
	Goalpara	5	( Lakhip					
		1	г					

	Golaghat	17	( Bokak	hat   17 )						
	Kamrup	205	( North	Ghy   7 ), ( K	ayan   16 ), (	Kamalpur   75 ), ( Rangia	74), (Hajo	33)		
	Kokrajhar	5			Kokrajhar   4 )					
	Lakhimpur	15			wboicha   11)					
	Nagaon	11		Raha   11 ) Barkhetri   64 ), ( Banekuchi   11 ), ( Barbhag   49 ), ( Nalbari   34 ), ( Tihu   30 ), ( Paschim						
	Nalbari	276	Nalbari	albari   25 ), ( Ghograpar   63 )  Goreswar   20 ), ( Tamulpur   24 )						
	Tamulpur	44			amulpur   24	)				
	Udalguri Total	1 1538	( Khaira	bari   1 )						
		1336			Total		Crop			
	District/Sub -division*	Male	Femal e	Children	Populatio n	Population Details	Area (in Hect.)	Crop Area Details		
	Bajali	123447	11974 9	24057	267253	( Sarupeta   90575 ), ( Bajali   176678 )	368.30	( Sarupeta   264.30 ), ( Bajali   104.00 )		
	Baksa	3559	2862	861	7282	( Baska   381 ), ( Barama   952 ), ( Jalah   1737 ), ( Baganpara   4212 )	597.00	( Baska   5.00 ), ( Barama   4.00 ), ( Jalah   588.00 ), ( Baganpara   0.00 )		
	Barpeta	33124	27684	12425	73233	(Barpeta   30744), ( Chenga   2251), ( Sarthebari   40238)	252.50	(Barpeta   223.00), ( Chenga   12.50), ( Sarthebari   17.00)		
	Biswanath	0	0	0	0	( Gohpur   0 ), ( Halem   0 )	29.00	( Gohpur   0.00 ), ( Halem   29.00 )		
	Bongaigaon	0	0	0	0	( Boitamari   0 ), ( Bongaigaon   0 ), ( Srijangram   0 )	447.00	( Boitamari   347.50 ), ( Bongaigaon   27.50 ), ( Srijangram   72.00 )		
	Chirang	377	323	244	944	( Bijni   0 ), ( Sidli   944 )	93.39	( Bijni   93.39 ), ( Sidli   0.00 )		
	Darrang	5113	4777	4693	14583	( Patharighat   804 ), ( Sipajhar   630 ), ( Dalgaon   0 ), ( Mangaldoi   13149 )	3888.02	( Patharighat   1013.72 ), ( Sipajhar   1486.00 ), ( Dalgaon   206.00 ), ( Mangaldoi   1182.30		
	Dhemaji	0	0	0	0	( Dhemaji   0 )	3.00	( Dhemaji   3.00 )		
Population And Crop Area Affected	Dhubri	477	430	270	1177	( Golakganj   0 ), ( Dhubri   0 ), ( Athani   38 ), ( South Salmara Part   0 ), ( Bilasipara   860 ), ( Agamoni   279 )	1546.00	( Golakganj   402.50 ), ( Dhubri   72.50 ), ( Athani   45.00 ), ( South Salmara Part   949.50 ), ( Bilasipara   4.00 ), ( Agamoni   72.50 )		
	Dibrugarh	22	36	10	68	( Moran   0 ), ( Tingkhong   0 ), ( Chabua   0 ), ( Dibrugarh West   68 )	207.00	( Moran   1.00 ), ( Tingkhong   2.00 ), ( Chabua   136.00 ), ( Dibrugarh West   68.00 )		
	Goalpara	2045	2015	690	4750	( Lakhipur   4750 )	0.00	( Lakhipur   0.00 )		
	Golaghat Kamrup	110	82	36	228	( Bokakhat   0 ) ( Kayan   0 ), ( Kamalpur   0 ), ( Rangia   228 ), ( Hajo   0 ), ( North Ghy   0 )	887.92	( Bokakhat   200.00 ) ( Kayan   20.25 ), ( Kamalpur   217.63 ), ( Rangia   311.54 ), ( Hajo   328.00 ), ( North Ghy   10.50 )		
	Kokrajhar	943	594	652	2189	( Kokrajhar   1911 ), ( Gossaigaon   278 )	0.00	( Kokrajhar   0.00 ), ( Gossaigaon   0.00 )		
	Lakhimpur	10832	10843	902	22577	( Bihpuria   517 ), ( Nowboicha   22060 )	0.00	( Bihpuria   0.00 ), ( Nowboicha   0.00 )		
	Nagaon	0	0	0	0	( Raha   0 )	752.65	(Raha   752.65)		
	Nalbari	32855	29547	17659	80061	(Barkhetri   1550), ( Barbhag   3630), ( Nalbari   2263), (Tihu   19780), (Ghograpar   41126), (Banekuchi   2337), (Paschim Nalbari   9375)	1466.60	(Barkhetri   245.10), ( Barbhag   71.60), ( Nalbari   93.90), ( Tihu   312.00), ( Ghograpar   356.00), ( Banekuchi   118.00), ( Paschim Nalbari   270.00)		

	Tamulpur	5639	4871	3670	14180	( Goreswar Tamulpur		44.29	( Goreswar   Tamulpur		
	Udalguri	0	0	0	0	( Khairabar	i   0 )	0.13	( Khairabari	0.13)	
	Total	218543	20381 3	66169	488525			10782.80			
	District/Sub -division*	Total	Relief C	Camp			Relief Distribution Centres				
	Bajali	73		peta   33, Baj			1(Sarupeta	1, Bajali   0)			
	Baksa	13	5)		1, Baganpar	a   1, Jalah			Baganpara   0,	Jalah   0)	
	Barpeta	27	2(Sarthe				25(Sartheba				
	Biswanath	5	0(Gohpu				5(Gohpur	5)			
5 H 4	Chirang	7	0(Sidli	0) righat   0, Ma	11.110)		7(Sidli   7)	at   2, Mangal	1:16)		
Relief Camps /	Darrang Dhubri	8			ira   4, Agamo	ni   1)			0, Agamoni   (	<u>,, , , , , , , , , , , , , , , , , , ,</u>	
Centres	Dibrugarh	1		garh West   0		/III   1 <i>)</i>	1(Dibrugarl		o, rigamoni j	')	
Opened	Goalpara	2	1(Lakhi)		,		1(Lakhipur				
1	Kamrup	2	2(Rangia				0(Rangia   0				
	Kokrajhar	5	_	igaon   1, Ko	krajhar   4)			on   0, Kokrajl	nar   0)		
	Lakhimpur	4		ria   0, Nowb				3, Nowboich			
	Nalbari	34	33(Bane	kuchi   3, Ba	rbhag   2, Nal lbari   11, Gh			ni   0, Barbhag albari   0, Gho	;   0, Nalbari   0 grapar   0)	), Tihu   1,	
	Tamulpur	28	10(Gore	swar   1, Tan	nulpur   9)			ar   6, Tamulpi	ur   12)		
	Total	215	140				75				
	District/Sub -division*	Total	Revenue	e Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y	
	Bajali	18929	(Sarupet 4917)	ta   14012), (I	Bajali	8636	7166	2865	253	9	
	Baksa	2970		382), (Baran ara   631), (J		1319	1254	375	5	17	
	Barpeta	272	(Sartheb	a   0), (Cheng pari   272)		142	100	30	0	0	
Inmates In	Dhubri	1091		anj   0), (Dhu   38), (Bilasi <sub>]</sub> ni   193)		450	395	246	0	0	
Relief	Goalpara	136	(Lakhipı	ur   136)		62	47	24	2	1	
Camps	Kamrup	228		Ghy   0), (Kay our   0), (Hajo   228)		115	77	36	0	0	
	Kokrajhar	2189		gaon   278), (	Kokrajhar	943	594	652	0	0	
	Nalbari	7355	249), (B Nalbari	tri   0), (Bane arbhag   489)   1697), (Gho Nalbari   560	), (Paschim ograpar	3374	2573	1104	273	31	
	Tamulpur	1972	(Goresw 1901)	var   71), (Tar	nulpur	800	779	376	12	5	
	Total	35142				15841	12985	5708	545	63	
Human	District/Sub -division*	Total	Male	Female	Children	Revenue C					
Lives Lost - Confirmed	Nalbari	1	1	0	0			g   0), (Barkhe [albari   0), (Ti	etri   0), (Ghog ihu   0)	rapar   1),	
	Total	1	1	0	0						
Human Lives Lost Confirmed -	District/Sub -division*	Total	Flood Death	General Drownin g (Non Flood)	Landslide						
Death Type	Nalbari	1	1	0	0	·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			
	Total	1	1	0	0						
Human Lives Lost - Missing	Nil										
Human	Nil										

Lives Lost Missing -											
Type					1						
	District/Sub -division*	Total	Big	Small	Poultry						
	Bajali	125455	81752	32649	11054						
	Baksa	7835	3778	4057	0						
	Barpeta	65410	17653	18053	29704						
	Biswanath	2615	1765	850	0						
	Darrang	10203	4971	2992	2240						
Animals	Dibrugarh	5256	4197	1059	0						
Affected	Goalpara	643	150	170	323						
	Kamrup	16392	12948	3444	0						
	Lakhimpur	6071	4406	1665	0						
	Nalbari	184995	84729	67186	33080						
	Tamulpur	2599	1443	1156	0						
	Total	427474	21779 2	133281	76401						
Animals	District/Sub -division*	Total	Big	Small	Poultry						
Washed	Baksa	9	0	9	0						
Away	Nalbari	205	2	3	200						
•	Total	214	2	12	200						
Houses											
Damaged	Nil										
	District/Sub	Agency			Boats Deployed	Person Evacuate d By	Animal Evacuate d By	Helicopte rs Deployed	Person Evacuate d By Helicopte	Medical Team Deploye	
						Boats	Boats	2 oproj cu	rs	d	
Rescue Operation	Bajali	Administ Police, S	DRF	cal People,	5	5	0	0	0	50	
Operation	Darrang	Administ	fice/Local ration, Civ Trained V	vil	0	0	0	0	0	2	
	Goalpara				0	0	0	0	0	1	
	Kokrajhar				0	0	0	0	0	4	
	Lakhimpur				0	0	0	0	0	6	
	Total		1	_	5	5	0	0	0	63	
	District/Sub -division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)			
	Bajali	82.30	14.46	5.70	570.00	0.00	407.60 60.00	0.00			
	Baksa	57.76	19.65	14.28	14.28	0.00		0.00			
	Barpeta	21.69 0.00	3.76	1.72 0.00	154.95 0.00	0.00	0.00	0.00 3084.00			
D 11 C	Biswanath	10.75	0.00	0.00	57.69	0.00	0.00	0.00			
Relief	Chirang	76.61	1.92	4.18	418.00	0.00	0.00	289.80			
Distributed	Darrang Dhubri	0.40	0.08	0.02	2.28	0.00	0.00	0.00			
	Dibrugarh	1.16	0.08	0.02	3.80	0.00	0.00	0.00			
	Goalpara	2.21	0.20	0.19	12.24	0.00	0.00	0.00			
	Kamrup	2.59	0.41	0.12	13.68	0.00	0.00	0.00			
	Kamup	7.23	1.30	0.14	39.00	0.00	0.00	0.00			
	Lakhimpur	8.48	1.30	0.39	44.00	0.00	0.00	150.77			
	Nalbari	1.52	0.29	0.44	8.55	0.00	2966.65	0.00			
	Tamulpur	352.08	65.30	19.60	2264.68	0.00	1928.80	207.24			
	Total	624.78	123.22	47.45	3603.15	0.00	5363.05	3731.81			
	District/Sub	Baby Fo	1				3303.03	3/31.01			
Relief	-division*	Liquid	ou	Baby Food	l Solid	Others					
Distributed	Bajali	0.00-Q, 0	0.00-ml	0.00-Q, 43	5.00-Pkt	•	250.00-Pieces Box-145.00-		0.00-Pkt; M. C	oil-290.00-	
Others	Baksa	0.00-Q, 0	0.00-Pkt	366.00-Pkt	t	0-0.00-Q	·				
	Barpeta	0.00-Q		0.00-Q		0-0.00-Q					

	Biswanath	0.00-Q		0.00-Q					
	Chirang	0.00-Q		0.00-Q	Chira-159.20-Kg; Gur-30.30-Kg				
	Darrang	0.00-Q, 66.00-L		0.00-Q, 132.00-Pkt	0-0.00-Q; Matchbox-100.00-Pkt; Candle-140.00-Pkt; Mosquito Coil-80.00-Pkt				
	Dhubri	0.00-Q		0.00-Q					
	Dibrugarh	0.00-Q		0.00-Q					
	Goalpara	0.00-Q		0.00-Q	Cheera-25.00-Kg				
	Kamrup	0.00-Q		8.00-Pkt	Candle-30.00-Pkt; Mosquito coil-20.00-Pkt				
	Kokrajhar	0.00-Q		0.00-Q	CANDLE (MEDIUM)-62.00-Pkt; MATCH BOX-62.00-Pieces; M. COIL-62.00-Pieces; Chira-67.50-Kg; Gur-13.75-Kg; Sanitary Napkins-72.00-Pkt; Candle-104.00-Pkt; Match Box-104.00-Pieces; M. Coil-104.00-Pkt				
	Lakhimpur	0.00-Q		75.00-Pkt, 0.00-Q	Tarpaulin-594.00-Pieces				
	Nalbari	0.00-Q		0.00-Q					
	Tamulpur	0.00-Q		0.00-Q	Tarpaulin-2316.00-Pieces; Chira-416.04-Q; gur-31.07-Q; biscuit-15462.00-Pkt; mosquito coil-286.00-Pkt; match box-313.00-Q; candle-313.00-Q; drinking water-626.00-Q				
Infrastructu	District/Sub -division*	Numbe r	Details						
re Damaged - Embankme nt Breached	Biswanath	1	22/06/23		I   At L/Bank or River Chatrang   the breach was reported on s been increased from 35 mtr to 40 mtr   (Long - 93.609539, Lat - the Deptt.)				
nt Bredened	Total	1							
	District/Sub	Numbe	Details						
	-division*  Biswanath	2	Gohpur 60 mtr   Mild Ba 23/06/23	Gohpur - Mild Bank Erosion is observed at R/Bank of Sessa river   At Auguri area on 23/06/23 for 60 mtr     (Long - 93.733716, Lat - 26.951885, Dept - Water Resource Deptt.), Mild Bank Erosion is observed at R/Bank of Sessa river   At Gupsarguri Marginal Embankment in 23/06/23 for 50 mtr     (Long - 93.716944, Lat - 26.979166, Dept - Water Resource Deptt.)					
Infrastructu re Damaged - Embankme nt Affected	Darrang	4	Sipajhar - Saktola Right Bank Embankment, Bornodi Embankment   Saktola (From Bordoulguri to RK Embankment), Bornodi(NH 15 to Lenga Kurua Embankment) dated.22/06/2023     (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.),  Mangaldoi - Sonalipam   At Sonalipam   As reported by WRD Dept. due to rise of water level of Mangaldai River Active bank Erosion took place. Dated 22/06/2023.   (Long - 92.022000, Lat - 26.459800, DeptSelect Department),  Faraz Nagar   At Faraz Nagar   As reported by WRD Dept. due to rise of water level of Mangaldai River Active bank Erosion took place. Dated 23/06/2023.   (Long - 92.023520, Lat - 26.455010, Dept - Water Resource Deptt.)						
	Kokrajhar	8	WR KO DURAE LENGT BAMUN REACH 600M, F JOGDO REACH - Water BANK A DIVISIO REACH ADIBAS GARUP BANK A ON 23.0 500M, O L/B, NA Lat - 0.0 BANK A DIVISIO SIMLAI 23.06.20 BANK A DIVISIO R/B, MO Lat - 0.0 BANK A	KRAJHAR DIVISION OBIL (RANJINGPARA) RE H 350M, HARINPUR RI NIGAON REACH LENG I LENGTH 350M, ON R/RIMIJHIMIGHOP REACH LENGTH 400M, ON L/RESOURCE DEPIT.), AT MOKRAMBIL   MOID ON ON 23.06.2023, BAN I LENGTH 500M, ON L/SHI BASTI, KOIMARI E PHELLA.   (Long - 0.0000 AT DHEPDHEPI   DHEP 106.2023, BANK EROSIO ON R/B, BOWAGURI NIKAWARBHITA AND MUR 1000000, Dept - Water Resource DIVID 1000000, LAT VILLAGE BAGDOGON ON 23.06.2023, BANK BARI & BORGHOPA OR 1023   (Long - 0.000000, LAT VILLAGE HEKAIPA ON ON 23.06.2023, BANK DGORMARI ON L/B, BANK BARI ON L/B, BANK BARI ON L/B, BANK BARI ON DEPT - Water RESOURCE PROBLEM ON L/B, BANK BARI ON L/B, BANK BANK BANK BANK BANK BANK BANK BANK	RRA   BAGDOGRA   AS REPORTED BY EE WR KOKRAJHAR K EROSION OBSERVED AT VILLAGE BAGDOGRA N L/B OF RIVER SONKOSH, EROSION IS CONTUINUING at - 0.000000, Dept - Water Resource Deptt.), ARA   HEKAIPARA   AS REPORTED BY EE WR KOKRAJHAR K EROSION OBSERVED AT VILLAGE HEKAIPARA ON ARUAPARA ON L/B OF RIVER GAURANG   (Long - 0.000000,				

	1	ı	
			MADHYA KALUGAON ON L/B, AT MOUZABARI(BOROBASTI) ON R/B OF RIVER SAMUKHA   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.), BANK AT VILLAGE SIMBARGAON   SIMBARGAON   AS REPORTED BY EE WR KOKRAJHAR DIVISION ON 23.06.2023, BANK EROSION OBSERVED AT VILLAGE SIMBARGAON OF RIVER SAMUKHA(DWIKHIPI) ON R/B   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.), BANK AT VILLAGE SIMBARGAON BAZAR   SIMBARGAON BAZAR   AS REPORTED BY EE WR KOKRAJHAR DIVISION ON 23.06.2023, BANK EROSION OBSERVED AT VILLAGE SIMBARGAON BAZAR U/S AREA OF RIVER SAMUKHA ON R/B.   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.)
	Total  District/Sub	14 Numbe	
	-division*	r	Details
Infrastructu re Damaged - Road	Bajali	18	Sarupeta - Bhawanipur Madhapur road submerged   Madhapur   Report received from AEE, PWD, Bhawanipur G Sub-Division, Bhawanipur G 22/6/2023   (Long - 91.094046, Lat - 26.461702, Dept - PWD (Roads)), Bhawanipur diversion road submerged   Bhawanipur   Report received from AEE, PWD, Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.423000, Lat - 26.264412, Dept - PWD (Roads)), NH-31 to Namati village road submerged   Namati   Report received from AEE, PWD, Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.421500, Lat - 26.264500, Dept - PWD (Roads)), Medhikuchi to Uzan barbari road submerged   Medhikuchi   Report received from AEE, PWD, Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.421100, Lat - 26.215400, Dept - PWD (Roads)), Cheki to Kardeguri road via Barbari submerged   Cheki   Report received from AEE, PWD, Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.451200, Lat - 26.215400, Dept - PWD (Roads)), Simlartal to Sialmari road submerged   Sialmari   Report received from AEE, PWD, Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.451200, Lat - 26.234700, Dept - PWD (Roads)), Swahid Khargeswar Talukdar road submerged   Chauliabori   Report received from AEE, PWD, Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.451700, Lat - 26.214500, Dept - PWD (Roads)), Chauliabori to kenduguri road submerged   Kenduguri   Report received from AEE, PWD, Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.471200, Lat - 26.214500, Dept - PWD (Roads)), Office campus of Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.471200, Lat - 26.124500, Dept - PWD (Roads)), Office campus of Bhawanipur TR Sub-Division, Bhawanipur on 22/6/2023   (Long - 91.471200, Lat - 26.231470, Dept - PWD (Roads)),  Phila to Kahara village road submerged   Bhawanipur on 22/6/2023   (Long - 91.451200, Lat - 26.25870, Dept - PWD (Roads)),  Phila to Kahara village road submerged   Bhawanipur on 22/6/2023   (Long - 91.451200, Lat - 26.2
	Baksa Barpeta	30	Barama-Alagjar Road damaged at charanpara supa   Alagjar   occured due to flood on 21-06-23   (Long - 91.358734, Lat - 26.531402, Dept - PWD (Roads))  Baghbar - Agmandia chariali PMGSY road   Agmandia chariali to Mandia Gaon (Near
L	Бшреш	50	2 Marion Charles 1 1700 1 1000   Agniandia Charles to Malida Caon (Near

Nakumuddin house) | Due to increasing flood water Agmandia chariali PMGSY road to Mandia Gaon road breach occurred at Ch.500.00M, length-17.00m.Date-22/06/2023 | (Long - 90.978129, Lat - 26.269725, Dept - PWD (Roads)),

**Barpeta** - Belortari to Patbaushi Palhaji Tarabari Road via Pajarbhanga and Dakreswar | Belortari | As per report of PWD Dept on 21/06/2023, Side berm eroded at Belortari to Patbaushi Palhaji Tarabari Road via Pajarbhanga and Dakreswar | (Long - 91.078613, Lat - 26.258505, Dept - PWD (Roads)),

RCC Br. No. 2/1 on Sila Suha Road | Sila Suha | As per report of PWD Dept on 21/06/2023, Approaches damage, Side berm eroded & rain cut at RCC Br. No. 2/1 on Sila Suha Road | (Long - 91.082781, Lat - 26.269585, Dept - PWD (Roads)),

Palhaji to Temura via Charakpara and Dongra Road | Palhaji Temura | As per report of PWD Dept on 21/06/2023 Side berm eroded at Palhaji to Temura via Charakpara and Dongra Road | (Long - 91.035824, Lat - 26.267018, Dept - PWD (Roads)),

Jogirpam Sonkuchi Road via Donakuchi village | Jogirpam Sonkuchi | As per report of PWD Dept on 21/06/2023 Side berm eroded & 4 nos. breach occurred Jogirpam Sonkuchi Road via Donakuchi village | (Long - 90.986872, Lat - 26.353112, Dept - PWD (Roads)),

Bahmura Uttam Ghosh house to Brihaspati Bazar Road | BAhmura | As per report of PWD Dept on 21/06/2023 Side berm eroded & 4 nos. breach occurred at Breach occurred and road submerged Bahmura Uttam Ghosh house to Brihaspati Bazar Road | (Long - 90.963158, Lat - 26.342179, Dept - PWD (Roads)),

SH-2 at Jaharpam Bazar to E&D Bund via 1311 No. Jaharpam LPS | Jahurpam | 3 nos. Breach occurred & side berm eroded at SH-2 at Jaharpam Bazar to E&D Bund via 1311 No. Jaharpam LPS | (Long - 90.954010, Lat - 26.318503, Dept - PWD (Roads)),

Khandakarpara Duttakuchi Road | Khandakarpara Duttakuchi | As per report of PWD Dept on 21/06/2023, Road submerged and side berm eroded Khandakarpara Duttakuchi Road | (Long - 90.944870, Lat - 26.400223, Dept - PWD (Roads)),

Sonkuchi Colony to Garemari Bazar Road | Sonkuchi Garemari | As per report of PWD Dept on 21/06/2023 Side berm eroded & rain cut Sonkuchi Colony to Garemari Bazar Road | (Long - 90.973270, Lat - 26.353910, Dept - PWD (Roads)),

Jahurpam Garemari Road | Jahurpam Garemari | As per report of PWD Dept on 21/06/2023 Side berm eroded & Hard Crust damaged at several stretches | (Long - 90.957713, Lat - 26.332349, Dept - PWD (Roads)),

Itervita Duttakuchi Road | Itervita Duttakuchi | As per report of PWD Dept on 21/06/2023 Road submerged and severe damage at several stretches | (Long - 90.985205, Lat - 26.403775, Dept - PWD (Roads)),

Barpeta Bhawanipur Road (BB road) | Barpeta Bhawanipur | As per report of PWD Dept on 21/06/2023 Barpeta Bhawanipur Road (BB road) submerged in Stretches from 9km to 12km Side berms heavily damaged. Road hard crust damaged in stretches | (Long - 91.068641, Lat - 26.410808, Dept - PWD (Roads)),

Kayakuchi to Newlarbhitha (PMGSY Ongoing- Pkk No- AS-01 -493) | Fulorguri | As per report of PWD Dept on 21/06/2023 Kayakuchi to Newlarbhitha (PMGSY Ongoing- Pkk No- AS-01 -493) submerged in stretches. Side berms heavily dmaged in stretches. | (Long - 91.094648, Lat - 26.393230, Dept - PWD (Roads)),

BB road to 3 No Colony via Cliarak Puja Thali (PMGSY completed- Pkg- AS-01 - 186) road | Pakabetbari Pam | As per report of PWD Dept on 21/06/2023 BB road to 3 No Colony via Cliarak Puja Thali (PMGSY completed- Pkg- AS-01 - 186) road breached at 4 starches. Road side berms and hard cnist heavily damaged | (Long - 91.051462, Lat - 26.367320, Dept - PWD (Roads)), Fulorguri Bamunbari Road HP culvert | Fulorguri | As per report of PWD Dept on 21/06/2023 Fulorguri Bamunbari Road HP culvert washed away at 2" Km, hard Crust damaged at 4\* (3 Nos) | (Long - 91.043643, Lat - 26.422219, Dept - PWD (Roads)),

Kadamguri Chariachain Road | Kadamguri | As per report of PWD Dept on 21/06/2023 Kadamguri Chariachain Road breached at 1 s' & 3" Km. Side berms heavily eroded | (Long - 9.014704, Lat - 26.392456, Dept - PWD (Roads)),

Dk road to Domorghat road | Kadamguri | As per report of PWD Dept on 21/06/2023 Dk road to Domorghat road side berms heavily damaged in stretches | (Long - 91.009940, Lat - 26.409753, Dept - PWD (Roads)),

DK road to Betbari road | Kadamguri | As per report of PWD Dept on 21/06/2023 DK road to Betbari road side berms heavily damaged in stretches | (Long - 91.014254, Lat - 26.403037, Dept - PWD (Roads)),

Jarabari to Dabaliapara road | Jarabari | As per report of PWD Dept on 21/06/2023 Jarabari to Dabaliapara road side berms heavily damaged in stretches | (Long - 91.017351, Lat - 26.381919, Dept - PWD (Roads)),

DK road to Bantipur road | Dewrikuchi | As per report of PWD Dept on 21/06/2023 DK road to Bantipur road side berms heavily damaged in stretches | (Long - 91.019196, Lat - 26.365907, Dept - PWD (Roads)),

T09 to Bamunbari Reserve( PMGSY completed — Pkg- AS-01- 191, road | Kaljhar | As per report of PWD Dept on 21/06/2023 T09 to Bamunbari Reserve( PMGSY completed — Pkg- AS-01- 191, road fully submerged. side berms heavily damaged | (Long - 91.041770, Lat - 26.420700, Dept - PWD (Roads)),

DK Road RCC Bridge PMGSY-Completed | Dangarkuchi | As per report of PWD Dept on 21/06/2023 DK Road RCC Bridge PMGSY-Completed approaches eroded on both sides | (Long -91.017380, Lat - 26.350900, Dept - PWD (Roads)), BB road to Panimaricha road (PMGS Y completed road —Pkg No- AS-0 1 -309) | Bamuna | As per report of PWD Dept on 21/06/2023 BB road to Panimaricha road (PMGS Y completed road —Pkg No- AS-0 1 -309) road side beriris & hard crust heavily damaged by river Pohumara . I IP culvert heavily damaged at 1't KM | (Long - 91.048907, Lat - 26.361605, Dept - PWD (Roads)), Pohumara RCC Bridge to Bhakuamari (PMGSY completed road- Pkg- AS-01 -307) | MAricha | As per report of PWD Dept on 21/06/2023 Pohumara RCC Bridge to Bhowkarnari (PMGSY completed road- Pkg- AS-01 -307) submerged and hard crust and side berms heavily damaged by river Pahumara | (Long - 91.087837, Lat - 26.398659, Dept - PWD (Roads)), Jarabari to Kamalpur Pam road | JArabari | As per report of PWD Dept on 21/06/2023 Jarabari to Kamalpur Pam road (PMGS Y Coinp lctcd- Pkg —A S-01 -303) road side berms heavily damaged. RCC Bi idgc approaches damaged | (Long - 91.016021, Lat - 26.387682, Dept - PWD (Roads)), Ata Bhowkamari to Pohumara River road | Ata | As per report of PWD Dept on 21/06/2023 Ata Bhowkamari to Pohumara River road surface and shoulder damaged at 1" & 2' d Km road eroded by river Pohumara and damaged SPT Br No 2/1 | (Long - 91.079593, Lat - 26.399838, Dept - PWD (Roads)). BB road to Ata Bhowkamari road | Bonbaha | As per report of PWD Dept on 21/06/2023 BB road to Ata Bhowkamari road submerijed completely. Side berms & hard crust damaged in streches. (Long - 91.075075, Lat - 26.409680, Dept - PWD (Roads)), BB road to Uttar Maricha via Maricha Masjid approaches of Culvert damaged | Bariarpathar | As per report of PWD Dept on 21/06/2023 BB road to Uttar Maricha via Maricha Masjid approaches of Culvert damaged | (Long - 91.070630, Lat - 26.381740, Dept - PWD (Roads)), Kujarpith Banbahar road to DK road (PMGSY completed road- Pig- AS-01-302) road | Barbala | As per report of PWD Dept on 21/06/2023 Kujarpith Banbahar road to DK road (PMGSY completed road-Pig-AS-01-302) road side berms heavily damaged in streches | (Long - 91.018713, Lat -26.406310, Dept - PWD (Roads)), BB road to Pub Chakirbhitha road | Chakirbhita | As per report of PWD Dept on 21/06/2023 BB road to Pub Chakirbhitha road side berms damaged in streches. | (Long - 91.090791, Lat -26.359072, Dept - PWD (Roads)) Silchar - KASHIPUR BERENGA ROAD (BADRI BRIDGE APPROACH ROAD). | KASHIPUR BERENGA | KASHIPUR BERENGA ROAD (BADRI BRIDGE APPROACH ROAD) Length 1.600 As reported by EE PWD Silchar Road (T) Division on dated 17.06.2023. | (Long - 24.812483, Lat - 92.855731, Dept - PWD (Roads)), S.F. ROAD. | Silchar | S.F. ROAD length 0.045 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.819701, Lat - 92.806996, Dept - PWD (Roads)), MOTHER TERESA ROAD. | Silchar | MOTHER TERESA ROAD length 2.100 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.820367, Lat - 92.730710, Dept -PWD (Roads)). MAHADEB BARI ROAD, | MAHADEB BARI | MAHADEB BARI ROAD Length-2,000 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.812333, Lat -92.810719, Dept - PWD (Roads)). NORMAL SCHOOL TO JAIL ROAD. | NORMAL SCHOOL TO JAIL | NORMAL SCHOOL TO JAIL ROAD Length- 0.910 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.829180, Lat - 92.792796, Dept - PWD (Roads)), SHIBCOLONY ROAD. | SHIBCOLONY | SHIBCOLONY ROAD Length 0.500 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.814133, Lat - 92.795547, Dept - PWD (Roads)), SHYAMANANDA ASHRAM ROAD. | SHYAMANANDA ASHRAM | SHYAMANANDA 37 Cachar ASHRAM ROAD Length- 0.900 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.812079, Lat - 92.803375, Dept - PWD (Roads)), GOPAL AKHRA ROAD. | GOPAL AKHRA | GOPAL AKHRA ROAD Length- 1,200 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.807943, Lat - 92.807273, Dept - PWD (Roads)), D.C. OFFICE ROAD TO TREASURY OFFICE. | D.C. OFFICE | D.C. OFFICE ROAD TO TREASURY OFFICE Length- 0.140 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.829539, Lat - 92.803151, Dept - PWD (Roads)), SILCHAR MUNICIPALITY OFFICE ROAD. | SILCHAR MUNICIPALITY OFFICE | SILCHAR MUNICIPALITY OFFICE ROAD Length-0.300 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.830931, Lat - 92.802182, Dept - PWD (Roads)), BSNL OFFICE ROAD. | BSNL OFFICE | BSNL OFFICE ROAD Length-0.100 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.832652, Lat - 92.802391, Dept -PWD (Roads)), N.M. GUPTA ROAD. | N.M. GUPTA ROAD | N.M. GUPTA ROAD Length-0.250 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.829220, Lat - 92.793100, Dept - PWD (Roads)), DAS COLONY PANCHAYAT ROAD. | DAS COLONY | DAS COLONY PANCHAYAT ROAD Length 1.500 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long -

24.809474, Lat - 92.790709, Dept - PWD (Roads)), S.H.ROAD C.R. AVENUE POINT TO CHIRUKANDI RAMNAGAR NH-37 POINT. | NH-37 POINT | S.H.ROAD C.R. AVENUE POINT TO CHIRUKANDI RAMNAGAR NH-37 POINT Length-4.330 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long -24.805585, Lat - 92.794473, Dept - PWD (Roads)), DOLOO MOINERBOND ROAD CH. 15650.00M to 16950.00M. | DOLOO MOINERBOND | DOLOO MOINERBOND ROAD CH. 15650.00M to 16950.00M Length-1.300 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.853228, Lat - 92.828098, Dept -PWD (Roads)). OLD LAKHIPUR ROAD NEAR RCC BRIDGE TO FERRYGHAT. | OLD LAKHIPUR ROAD | OLD LAKHIPUR ROAD NEAR RCC BRIDGE TO FERRYGHAT Length-0.210 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.811194, Lat - 92.842145, Dept - PWD (Roads)), TARAPAUR SHIBBARI ROAD. | TARAPAUR SHIBBARI | TARAPAUR SHIBBARI ROAD Length-0.180 As reported by EE PWD Silchar Road (T) Division on dated 21.06.2023. | (Long -24.835781, Lat - 92.781127, Dept - PWD (Roads)), CHURCH ROAD 300.00M DAMAGED, 2 NOS DAMAGED CULVERT. | CHURCH ROAD | CHURCH ROAD 300.00M DAMAGED, 2 NOS DAMAGED CULVERT Length 0.680 As reported by EE PWD Silchar Road (T) Division on dated 21.06.2023. | (Long - 24.822419, Lat -92.796155, Dept - PWD (Roads)), BERENGA BASHAN (BISHRJAN) ROAD. | BERENGA BASHAN | BERENGA BASHAN (BISHRJAN) ROAD Length-0.200 As reported by EE PWD Silchar Road (T) Division on dated 21.06.2023. | (Long - 24.811440, Lat - 92.842141, Dept - PWD (Roads)), Udharbond - DUMURGHAT GUABARI ROAD (EROSIION AT APPROACH TO BR. NO. 4/2). | DUMURGHAT GUABARI | DUMURGHAT GUABARI ROAD (EROSIION AT APPROACH TO BR. NO. 4/2) Length-0.040 As reported by EE PWD T Road Division on Dated 17.06.2023 | (Long - 24.923869, Lat - 92.912886, Dept - PWD (Roads)), JAGANNATH SINGLE COLLEGE ROAD. LENGTH = 1.95 KM. | JAGANNATH SINGLE COLLEGE | JAGANNATH SINGLE COLLEGE ROAD. LENGTH = 1.95 KM Length- 1.950 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.870537, Lat - 92.880428, Dept - PWD (Roads)), LARSING BAGAN ROAD. LANDSLID OCCURRED AT. CH. 350.00M TO CH.675.00M IN STRETCHES. | LARSING BAGAN | LARSING BAGAN ROAD. LANDSLID OCCURRED AT. CH. 350.00M TO CH.675.00M IN STRETCHES Length-6.500 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.907767, Lat - 92.895464, Dept - PWD (Roads)), NH-53 TO 5TH KM OF S.K. ROAD VIA MADHURAMUKH AND BAHADURPUR. LENGTH = 3.033 KM. | MADHURAMUKH AND BAHADURPUR | NH-53 TO 5TH KM OF S.K. ROAD VIA MADHURAMUKH AND BAHADURPUR. LENGTH = 3.033 KM. As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.847565, Lat - 92.845287, Dept - PWD (Roads)), PURBA SALGANGA KALIMANDIR ROAD (LAND SLIDE AT 1ST KM). | PURBA SALGANGA KALIMANDIR | PURBA SALGANGA KALIMANDIR ROAD (LAND SLIDE AT 1ST KM) Length- 0.750 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long-24.919459, Lat - 92.965147, Dept - PWD (Roads)), SILCHAR KUMBHIRGRAM ROAD (VIP ROAD). | SILCHAR KUMBHIRGRAM | SILCHAR KUMBHIRGRAM ROAD (VIP ROAD) Length- 0.100 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.914355, Lat - 92.975144, Dept - PWD (Roads)), PANGRAM AMARANAGAR ROAD. | PANGRAM AMARANAGAR | PANGRAM AMARANAGAR ROAD Length-0.510 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.933511, Lat - 92.906422, Dept - PWD (Roads)), AMRANAGAR INDRANAGAR ROAD. | AMRANAGAR INDRANAGAR | AMRANAGAR INDRANAGAR ROAD. Length- 2.100 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.980945, Lat - 92.866427, Dept - PWD (Roads)), UDHARBOND BANSKANDI (MDR) ROAD (CH. 3857.00M TO CH. 8951.20M) DAMAGED DUE TO RAIN. | UDHARBOND BANSKANDI (MDR) | UDHARBOND BANSKANDI (MDR) ROAD (CH. 3857.00M TO CH. 8951.20M) DAMAGED DUE TO RAIN Length-5.100 As reported by EE PWD T Road Division on Dated 19.06.2023. | (Long - 24.851481, Lat - 92.941477, Dept -PANGRAM PHE POINT TO BLOCK H.Q. VIA PATHARIA (CH.150.00M TO CH. 2980.00M ERROSION BY RIVER MADHURA IN STRETCHES. | PANGRAM, PATHARIA | PANGRAM PHE POINT TO BLOCK H.Q. VIA PATHARIA (CH.150.00M TO CH. 2980.00M ERROSION BY RIVER MADHURA IN STRETCHES Length-3.230 As reported by EE PWD T Road Division on Dated 19.06.2023. | (Long - 24.885219, Lat - 92.891672, Dept - PWD (Roads)) Bijni - Bwripara(Andhargaon) village road. | Bwripara(Andhargaon) | As reported by BDO, Borobazar TD Block, Bwripara(Andhargaon) village road damaged at Bwripara(Andhargaon) on 22-06-2023. Length=10 mtr, Breadth=3.5 mtr, Depth= 1.5 mtr. | (Long - 90.798960, Lat -Chirang 6 26.594438, Dept - P&RD), Uttar Burikhamar to Niz Damugaon Road | Jaldhara Niz damugaon | As per report of AEE, PWD Sorbhog(R&B) Sub Division, Sorbhog, Uttar Burikhamar to Niz damugaon road and culvert damaged at Jaldhara Niz damugaon on 22-06-2023. Length=7.50 mtr, Breadth=3.00 mtr, Depth=

1	1	
		0.60 mtr.   (Long - 90.855061, Lat - 26.568546, Dept - PWD (Roads)),
		No 3 Bishnupur to Sikajhora Road   No 3 Bishnupur   As reported by AEE, PWD Bijni(R&B) Sub
		Division, No 3 Bishnupur to Sikajhora Road damaged at No 3 Bishnupur at two points on 22-06-
		2023. (1) Length=6.50 mtr, Breadth= 3.00 mtr, Depth=3.00 mtr. (2) Length=6.00 mtr, Breadth=3.00
		mtr, Depth=2.50 mtr.   (Long - 90.756658, Lat - 26.617200, Dept - PWD (Roads)), Kawadi No 2 to Sonaikhola Road   Kawadi No 2   As reported by AEE, PWD Bijni(R&B) Sub
		Division, Kawadi No 2 to Sonaikhola Road damaged at Kawadi No 2 on 22-06-2023. Length=8.00
		mtr, Breadth=7.00 mtr, Depth=0.50 mtr.   (Long - 90.772998, Lat - 26.524781, Dept - PWD
		(Roads)),
		Patiladoha To Dhupuri Road   Dhupuri   As reported by AEE, PWD Bijni(R&B) Sub
		Division, Patiladoha To Dhupuri Road damaged at Dhupuri on 22-03-2023. Length=15 mtr,
		Breadth=6.00 mtr, Depth=2 mtr.   (Long - 90.797741, Lat - 26.493881, Dept - PWD (Roads)),
		Sidli - Lauripara village road damaged   Lauripara Village   As reported by AE, PWD, Chirang
		(R&B) Division, Kajalgaon Road surface damaged, length-400.00 m, Breadth-5.00m, Depth-0.30m
		,date of Occurrence- 22-06-2023   (Long - 90.387728, Lat - 26.564935, Dept - PWD (Roads))
		Sipajhar - BORDOULGURI(AGRIBUNDH FROM SAKTOLA EMBANKMENT TO
		BARPATHAR), MAROI (EARTHEN BUNDH FROM RAMPARA HARIMANDIR TO
Darrang	3	BARUAPARA HARIMANDIR), SIPAJHAR (EARTHEN BUNDH FROM GARAKHIA
		MANDIR TO BATHAPAR VETI) dated.22/06/2023   Bordoulguri, Maroi, Sipajhar     (Long -
		0.000000, Lat - 0.000000, Dept - P&RD)
		Jonai - PWRD, territorial road Bahir Jonai to Bera Chapori via Bolaipam   From Ch. 4370.00M to
Dhamaii	1	Ch.4470.00M   PWRD, territorial road Bahir Jonai to Bera Chapori via Bolaipam under PMGSY
Dhemaji	1	Package No. AS-04-12 from Ch. 4370.00M to Ch.4470.00M 100 meter partially damaged due to
		incessant rain on 21/06/2023.   (Long - 95.239388, Lat - 27.759317, Dept - PWD (Roads))
		Dhubri - SIDE BERM, EMBANKMEMNT & HARD CRUST PARTIALLY DAMAGED &
		ERODED BY HEAVY RAINFALL ON FALIMARI PMGSY ROAD TO FALIMARI PT-II
		ROAD (FROM CH. 0.00 KM TO 2.00 KM) (Date-21-06-23)   FALIMARI     (Long - 89.976127,
		Lat - 26.040335, Dept - PWD (Roads)),
		APPROACHES OF BUG BR. NO. 1/1 AND ROAD SIDE BERM, EMBANKMENT PARTIALLY
		DAMAGED DUE TO HEAVY RAINFALL ON DG ROAD NEAR DHUBRI SAMSHAN
		MONDIR TO GAURIPUR ROAD (LENGTH = 0.50 KM) (Date-21-06-23)   DHUBRI SAMSHAN
		MONDIR TO GAURIPUR     (Long - 89.978485, Lat - 26.028434, Dept - PWD (Roads)),
		ROAD SUBMERGED AND CULVERT APPROACH DAMAGED ON KHUDIMARI
		DUMARDAHA KALAHAT BINNACHARA ROAD AT 8TH KM (Date-21-06-23)   KALAHAT
		(Long - 89.890834, Lat - 26.067836, Dept - PWD (Roads)),
		SIDE BERM ERODED INCLUDING BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 5/1 ON DURAHATI TISTERPAR VIA GERAMARI BSF CAMP ROAD AT CH. 6.00 KM (Date-
		· ·
		21-06-23)   DURAHATI TISTERPAR     (Long - 89.861156, Lat - 26.001724, Dept - PWD (Roads)),
		SIDE BERM DAMAGED ON MOTIRCHAR DHARMASLA ROAD 1ST TO 3RD KM IN
		STRETCHES (Date-21-06-23)   MOTIRCHAR     (Long - 89.907258, Lat - 26.023652, Dept - PWD
		(Roads)),
		SIDE BERM & SIDE SHOULDER DAMAGED ON KISMAT HASDAH MV SCHOOL ROAD
		TO SILGHAGRI ROAD (TISTERPAR) FROM 1ST KM TO 3RD KM(Date-21-06-23)
		TISTERPAR   (Long - 89.907385, Lat - 26.023915, Dept - PWD (Roads)),
		SIDE BERM ERODED AND SUBMERGED ON PWD GODWON APPROACH ROAD AT 1ST
Dhubri	84	KM (Date-21-06-23)   PWD GODWON ROAD     (Long - 89.968514, Lat - 26.024254, Dept -
		PWD (Roads)),
		SIDE BERM ERODED ON DHUBRI BINNACHARA ROAD AT 1ST KM (Date-21-06-23)
		BINNACHARA     (Long - 89.962008, Lat - 26.021795, Dept - PWD (Roads)),
		SIDE BERM ERODED ON GASPARA BAZAR TO MOTOIRCHAR BUND CUM ROAD FROM
		1ST KM TO 4TH KM (Date-21-06-23)   GASPARA BAZAR TO MOTOIRCHAR     (Long -
		89.874055, Lat - 26.003207, Dept - PWD (Roads)),
		SIDE BERM ERODED ON GASPARA SLUICE GATE TO PURANGAON LP SCHHOL FROM
		1ST KM TO 3RD KM (Date-21-06-23)   GASPARA     (Long - 89.874127, Lat - 26.003160, Dept -
		PWD (Roads)),
		SIDE BERM & SIDE SHOULDER DAMAGED ON GHEWMARI BSF CAMP TO IBB
		FENCING BORDER ROAD AT 1ST KM (Date-21-06-23)   GHEWMARI     (Long - 89.876367,
		Lat - 26.002846, Dept - PWD (Roads)),
		SIDE BERM ERODED ON GHEWMARTI BSF CAMP TO TISTARPAR BSF CAMP FROM 1ST
		KM TO 4TH KM (Date-21-06-23)   GHEWMARTI BSF CAMP TO TISTARPAR     (Long -
		89.861252, Lat - 26.000207, Dept - PWD (Roads)),
		SIDE BERM & SIDE SHOULDER DAMAGED ON TOSTARPAR WATER SUPPLY TO
		TISTARPAR BAF CAMP ROAD FROM CH. 1ST KM TO 3RD KM (Date-21-06-23)   TISTARPAR     (Long - 89.862823, Lat - 26.000032, Dept - PWD (Roads)),
		SIDE BERM & SIDE SHOULDER DAMAGED HARIALI ROAD BALDOBA BAZAR Ch. 1st
		KM to 4th KM IN STRETCHES (Date-21-06-23)   BALDOBA   (Long - 89.846305, Lat -
		26.025712, Dept - PWD (Roads)),
		SIDE BERM & SIDE SHOULDER DAMAGED ON GASPARA PANCHAYAT OFFICE TO BSF
	<u> </u>	SIDE DERIVER SIDE SHOULDER DANIAGED ON GASTAKA PANCHATAT OFFICE TO BSF

TENT OFFICE PARGHAT FROM CH.1ST KM TO 3RD KM IN STRETCHES (Date-21-06-23) | GASPARA | | (Long - 89.872255, Lat - 26.000920, Dept - PWD (Roads)), SIDE BERM & SIDE SHOULDER DAMAGED ON DHUBRI BINNACHERA PWD ROAD TO CHAUDHURYPARA FROM CH. AT 1ST KM IN STRETCHES (Date-21-06-23) | BINNACHERA | | (Long - 89.884793, Lat - 26.021772, Dept - PWD (Roads)), SIDE BERM & SIDE SLOPES DAMAGED ON DURAHATI TISTARPAR ROAD TO CHARDURAHATI L.P. SCHOOL FROM 1ST TO 2ND KM(Date-21-06-23) | DURAHATI TISTARPAR | | (Long - 89.853861, Lat - 26.035355, Dept - PWD (Roads)), SIDE BERM & SIDE SLOPES DAMAGED ON VELAKOBA SINGIMARI ROAD FROM 1ST TO 3RD (Date-21-06-23) | VELAKOBA SINGIMARI ROAD | | (Long - 89.871396, Lat - 26.033367, Dept - PWD (Roads)),

SIDE BERM & SIDE SLOPES DAMAGED ON KISMAT HASDAHA SINGIMARI ROAD TO TISTARPAR ROAD AT 1ST KM, 2ND KM & 4TH KM(Date-21-06-23) | KISMAT HASDAHA | | (Long - 89.867570, Lat - 26.016532, Dept - PWD (Roads)),

SIDE BERM & SIDE SLOPES DAMAGED ON DHUBRI PATAMARI ROAD TO JUNGLIA VILLAGE ROAD FROM 1ST KM TO 2ND KM (Date-21-06-23) | PATAMARI | | (Long - 89.906815, Lat - 26.009660, Dept - PWD (Roads)),

SIDE BERM & SIDE SLOPES DAMAGED ON KISMAT HASDAHA SILGHAGRI ROAD TO TISTARPAR ROAD FROM 1ST KM TO 3RD KM (Date-21-06-23) | TISTARPAR | | (Long - 89.867578, Lat - 26.015882, Dept - PWD (Roads)),

SIDE BERM & SIDE SLOPES DAMAGED ON DURAHATI PWD ROAD TO BALADOBA PARGHAT ROAD AT 1ST & 2ND KM (Date-21-06-23) | DURAHATI | | (Long - 89.844839, Lat - 26.028104, Dept - PWD (Roads)),

SIDE BERM & SIDE SLOPES DAMAGED ON DHARMASALA MOTIRCHAR TO DHARMASALA GIRLS LP SCHOOL FROM 1ST TO 2ND KM (Date-21-06-23) | MOTIRCHAR | (Long - 89.889167, Lat - 26.022174, Dept - PWD (Roads)),

SIDE BERM & SIDE SLOPES ERRODED OF DHUBRI PATAMARI ROAD FROM CH. 11100.00 M TO 11500.00 M (Date-21-06-23) | PATAMARI | | (Long - 89.876455, Lat - 25.999979, Dept - PWD (Roads)),

SIDE BERM & SIDE SLOPES ERRODED OF KANURI DIMAKURI ROAD AT 10TH KM & 11TH KM (Date-21-06-23) | Binnachara | | (Long - 89.822909, Lat - 26.022217, Dept - PWD (Roads)),

Chapar - MRL09 SALKOCHA UDMARI SATIPURA ROAD TO SREEGRAM PT-II UNDER PMGSY PACKAGENO AS-05-212 PT-III ROAD(.) ROAD SHOULDER ERRORED OCCOURED AT CH. 1600.00M, 1700.00M AND 2800.00M on dated 22-06-23 PARTIALLY SUBMERGED AT IST AND 2ND KM OF ROAD DUE TO HEAVY RAIN(.)(Latitude:-26.255509, Longitude:-90.333384), (Latitude:-26.257905, Longitude-90.329291), (Latitude:-26.256618,Longitude:-90.332515),(Latitude:-26.256077,Longitude:-90.333261)(.) | Srigram Pt-II | Due to heavy rain | (Long - 90.333261, Lat - 26.256077, Dept - PWD (Roads)), BAHALPUR KOKRAJHAR ROAD(.) AT 6TH KM AND 7TH KM ROAD SURFACE AND SIDE BERM DAMAGED on dated 22-06-23 DUE TO HEAVY RAIN (.)( At 6th Km Latitude:-26.335567, Longitude:-90.413099 and At 7th Km Latitude:-26.336723, Longitude:-90.408119) | Bahalpur Barpara Pt-I | Due to heavy Rain | (Long - 90.408119, Lat - 26.336723, Dept - PWD (Roads)).

BAHALPUR TO PATALPUR SIDDHA ASHRAM ROAD(.)HPC CULVERT NO 1/1 DAMAGED DUE TO HEAVY RAIN on dated 22-06-23 (.)( At Culvert No. 1/1 Latitude:-26.319579, Longitude:-90.468117) | Bahalpur Barpara Pt-I | Due to heavy rain | (Long - 90.468117, Lat - 26.319579, Dept - PWD (Roads)),

- . MAJERGAON TO SASTAPARA ROAD(.)AT 2ND KM SIDE BERM ERRODED DUE TO FLOOD WATER OF RIVER on dated 22-06-23 CHAMPABATI(.)(At Ch. 1200.00 M Latitude:-26.344424, Longitude:-90.434977) | Majergaon | Due to river Gaurng | (Long 90.434977, Lat 26.344424, Dept PWD (Roads)),
- . AREARJHAR TO PUTHIMARI ROAD(.) SIDE BERM ERRODED AND ROAD SURFACE DAMAGED DUE TO on dated 22-06-23 HEAVY RAIN.(.) ( At Ch. 550.00 M Latitude:-26.247803,Longitude:-90.408863) | Puthmari | Due to heavy rain | (Long 90.408863, Lat 26.247803, Dept PWD (Roads)),

DHIRGHAT TO PUTHIMARI ROAD(.) BRIDGE NO 1/1 APPROACH DAMAGED AND SIDE BERM ERRODED on dated 22-06-23 AT 2ND AND 3RD KM DUE TO HEAVY RAIN (.) (At Br. No 1/1 Latitude:-26.244897,Longitude:-90.395707) | Dhirghat | Due to heavy rain | (Long - 90.395707, Lat - 26.244897, Dept - PWD (Roads)),

L066 NH-31 AT TILAPARA BAZAR TO JAMDUAR PT-II ROAD(.) ROAD UDER PMGSY FOR THE YEAR OF 017-18 PACKAGE NO AS-05-121 SUBMERGED AT CH.6900.00 M AND 8TH KM on dated 22-06-23 DUE TO HEAVY RAIN(.)(Latitude:-26.23975, Longitude:-90.293006),(Latitude:-26.239692, Longitude-90.292899) and Latitude:-26.239704,Longitude:-90.292591),(Latitude:-26.238079, Longitude:-90.293803). | Jmduar Pt-II | Due to heavy rain | (Long - 90.293803, Lat - 26.238079, Dept - PWD (Roads)),

. NH 31 AT CHIRAKUTA TO TOKRABANDHA QUARRY ROAD(.) ROAD SURFACED DAMAGED DUE TO LAST FEW DAYS INCESSANT RAIN AT 1ST KM AND 2ND KM OF ROAD on dated 22-06-23(.)(Latitude:-26.233098, Longitude:-90.279167),(Latitude:-26.233104,

Longitude-90.277928) and (Latitude:-26.233087, Longitude:-90.277913). | Chirakuta | Due to heavy rain | (Long - 90.277913, Lat - 26.233087, Dept - PWD (Roads)),

ROAD FROM CHIRAKUTA TO JAMDUAR PT I ROAD(.)ROAD SUBMRGED DUE TO LAST FEW DAYS INCESSANT RAIN FROM CH. 0.00 M TO CH. 200.00 M on dated 22-06-23 (.)(Latitude:-26.232983, Longitude:-90.271801),(Latitude:-26.23303, Longitude-90.275118) and Latitude:-26.23314,Longitude:-26.23314). | Jasmduar Pt-I | | (Long - 90.271800, Lat - 26.233140, Dept - PWD (Roads)),

**Gauripur** - ALOMGANG PT-VIII TO HAZARIJHORNA (ROAD WASHED FOR A LENGTH OF 15M AT CHAINAGE 850.00 MTR) (Date-21-06-23) | ALOMGANG | | (Long - 90.043521, Lat - 26.141364, Dept - PWD (Roads)),

PANBARI TO CHITALKATI PMGSY ROAD ( RETURN WALL OF CULVERT DAMAGED AT CHAINAGE 1925M AND SIDE BERM ERODED AT 2ND TO 4TH KM) (Date-21-06-23) | PANBARI | | (Long - 90.058618, Lat - 26.145458, Dept - PWD (Roads)),

KHUDIMARI DUMUDAHA KALAHAT BINNACHARA ROAD AT 3RD KM AND 6TH KM ( SIDE BERM DAMAGED AND HARD CRUST DAMAGED (Date-21-06-23) | KHUDIMARI | | (Long - 89.894802, Lat - 26.079135, Dept - PWD (Roads)),

SIDE BERM & SIDE SLOPES DAMAGED ON GOLAKGANJ SOULMARI ROAD FROM 1ST TO 3RD KM(Date-21-06-23) | D.Hasdaha | | (Long - 89.853187, Lat - 26.063345, Dept - PWD (Roads)).

Athani - NH-31 AT PANBARI TO KAUNBARI ROAD (.) (PMGSY, PACKAGE NO. AS-05-43D) LENGTH=2.50KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF RIVER TIPKAI (.) (LATITUDE: 26.154481 & LONGITUDE: 90.060288) (.) | NH-31 AT PANBARI TO KAUNBARI ROAD (.) | date of occurance- 21/06/2023 | (Long - 90.060288, Lat - 26.154481, Dept - PWD (Roads)),

NH-31 AT BAGRIBARI TO BANIAMARI PART-III ROAD (.) (PMGSY, PACKAGE NO. AS-05-43C) LENGTH=2.40KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF RIVER TIPKAI (.) (LATITUDE: 26.195339 & LONGITUDE: 90.124693) (.) | NH-31 AT BAGRIBARI TO BANIAMARI PART-III ROAD | date of occurance- 21/06/2023 | (Long - 90.124693, Lat - 26.195339, Dept - PWD (Roads)),

TOPPARA JHAUPARA PART-I TO TOPPARA JHAUPARA PART-II ROAD (.) (PMGSY, PACKAGE NO. AS-05-54A) LENGTH= 1.00KM SIDE BURM AND ROAD SURFACE DAMAGED DUE TO FLOOD WATER OF RIVER TIPKAI (.) (LATITUDE: 26.164513 & LONGITUDE: 90.086609) (.) | TOPPARA JHAUPARA PART-I TO TOPPARA JHAUPARA PART-II ROAD | date of occurance- 21/06/2023 | (Long - 90.086609, Lat - 26.164513, Dept - PWD (Roads)).

MAHAMAYA IB TO GUTIPARA ROAD (.) (PMGSY, PACKAGE NO. AS-05-21) LENGTH=2.50KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER (.) (LATITUDE: 26.199108 & LONGITUDE: 90.139246) (.) | MAHAMAYA IB TO GUTIPARA ROAD | date of occurance- 21/06/2023 | (Long - 90.139246, Lat - 26.199108, Dept - PWD (Roads)),

NH-31 AT ARIANI TO NOISERDHAP ROAD (.) (PMGSY, PACKAGE NO. AS-05-54A) LENGTH=0.70KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER (.) (LATITUDE: 26.195768 & LONGITUDE: 90.139743) (.) | NH-31 AT ARIANI TO NOISERDHAP ROAD | date of occurance- 21/06/2023 | (Long - 90.139743, Lat - 26.195768, Dept - PWD (Roads)),

BANIAMARI PART IV TO SADHUBHASA ROAD (.) LENGTH=3 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER (.) (LATITUDE: 26.174145 & LONGITUDE: 90.101736) (.) | BANIAMARI PART IV TO SADHUBHASA ROAD | date of occurance- 21/06/2023 | (Long - 90.101736, Lat - 26.174145, Dept - PWD (Roads)), PIAZBARUI BAZAR TO BANIAMARI PART-III ROAD (.) LENGTH=4 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER (.) (LATITUDE: 26.174528 & LONGITUDE: 90.101305) (.) | PIAZBARUI BAZAR TO BANIAMARI PART-III ROAD | date of occurance- 21/06/2023 | (Long - 90.101305, Lat - 26.174528, Dept - PWD (Roads)).

NH-31 AT BAGRIBARI TO JAHARMURI ROAD (.) LENGTH=0.55KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER (.) (LATITUDE: 26.194366 & LONGITUDE: 90.131345) (.) | NH-31 AT BAGRIBARI TO JAHARMURI ROAD | date of occurance- 21/06/2023 | (Long - 90.131345, Lat - 26.194366, Dept - PWD (Roads)), NH-31 AT MAKRIJHORA TO SATAGURI VIA PIAZBARI ROAD (.)(PMGSY, PACKAGE NO. AS-05-213) LENGTH=5KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF TIPKAI RIVER (.) (LATITUDE: 26.169345 & LONGITUDE: 90.901041) (.) | NH-31 AT MAKRIJHORA TO SATAGURI VIA PIAZBARI ROAD | date of occurance- 21/06/2023 | (Long - 90.901041, Lat - 26.169345, Dept - PWD (Roads)),

 $\label{eq:bilasipara} \textbf{Bilasipara} - \text{NH-31 AT NAYAHAT TO DUBACHURI ROAD SUBMERDGE AT 3RD KM DUE TO SANKOSH RIVER WATER | NAYAHAT TO DUBACHURI ROAD | Dated:- 18-06-2023 to 22-06-2023 | (Long - 90.155867, Lat - 26.202727, Dept - PWD (Roads)),$ 

KADAMTOLA PT-II TO KADAMTOLA PT-III ROAD, SIDE BERM AND SURFACE DAMAGED 1st KM DUE TO WATER OF SANKOSH RIVER | KADAMTOLA PT-II TO KADAMTOLA PT-III ROAD | Dated:- 18-06-2023 to 22-06-2023 | (Long - 90.179843, Lat -

26.207728, Dept - PWD (Roads)), DUBACHURI (AT MAMABAZAR) TO SAGUNMARI PT-IV ROAD, PMGSY, PACKAGE NO. AS-05-43 SIDE BERM, RCC BRIDGE APPROACHES AND SURFACE DAMAGED 3RD KM DUE TO WATER OF SANKOSH RIVER | DUBACHURI (AT MAMABAZAR) TO SAGUNMARI PT-IV ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.205743, Lat -26.217579, Dept - PWD (Roads)), BILASIPARA TO SANKOSH NH POINT VIA SAGUNMARI DUBACHURI ROAD SIDE BERM DAMAGED AT CH. 7TH KM AND 8THh KM DUE TO WATER OF SONKOSH RIVER | BILASIPARA TO SANKOSH NH POINT VIA SAGUNMARI DUBACHURI ROAD | Dated:-18-06-2023 to 22-06-2023 | (Long - 90.222588, Lat - 26.223820, Dept - PWD (Roads)), KAZAIKATA HIGH SCHOOL TO NAYERALGA VILLAGE IROAD, SIDE BERM AND SURFACE DAMAGED DUE TO GOURANG RIVER WATER | KAZAIKATA HIGH SCHOOL TO NAYERALGA VILLAGE ROAD | Dated:- 18-06-2023 to 22-06-2023 | (Long - 90.197585, Lat - 26.188671, Dept - PWD (Roads)), NH-31 AT SONKOSH TO GOBARDHANPARA ROAD SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO SONKOSH RIVER WATER | NH-31 AT SONKOSH TO GOBARDHANPARA ROAD | Dated:- 18-06-2023 to 22-06-2023 | (Long -90.161470, Lat - 26.234524, Dept - PWD (Roads)), NH-31 TO BANGALIPARA II ROAD SUBMERGED 1ST KM, DUE TO SONKOSH RIVER WATER, SIDE BERM AND SURFACE DAMAGED | NH-31 TO BANGALIPARA II ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.202045, Lat - 26.238645, Dept - PWD (Roads)), NH-31 NAYAHAT TO MURABARI ROAD, PMGSY, PACKAGE NO. AS-05-43 RCC BRIDGE APPROACHES DAMAGED, DUE TO TIPKAI RIVER WATER | NH-31 NAYAHAT TO MURABARI ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.125984, Lat - 26.339759, Dept - PWD (Roads)), 1th KM OF BS ROAD TO SONKOSH ROAD SUBMERGED 1ST AND 2ND KM, DUE TO SONKOSH RIVER WATER, SIDE BERM AND SURFACE DAMAGED | BS ROAD TO SONKOSH ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.159063, Lat - 26.229405, Dept - PWD (Roads)). NAYAHAT TO SAPATGRAM ROAD SIDE BERM ERRODED AT CH. 7TH AND 13TH KM, DUE TO TIPKAI RIVER WATER | NAYAHAT TO SAPATGRAM ROAD | Dated: - 18-06-2023 to 22-06-2023 | (Long - 90.115431, Lat - 26.329510, Dept - PWD (Roads)), NH-31 AT NAYAHAT TO SOULMARI ROAD SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO TIPKAI RIVER WATER | NAYAHAT TO SOULMARI ROAD Dated: 18-06-2023 to 22-06-2023 | (Long - 90.125984, Lat - 26.339759, Dept - PWD (Roads)), FAKIRAGRAM SAPATGRAM ROAD, SIDE BERM ERRODED AT CH. 2ND AND 3RD KM, DUE TO HELL RIVER WATER | FAKIRAGRAM SAPATGRAM ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.181238, Lat - 26.358834, Dept - PWD (Roads)), 6TH KM OF BS ROAD TO SOULMARI ROAD SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO TIPKAI RIVER WATER | BS ROAD TO SOULMARI ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.143845, Lat - 26.262612, Dept - PWD (Roads)), 4TH KM OF NAYAHAT MURABARI ROAD TO SNANGHAT SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO TIPKAI RIVER WATER | NAYAHAT MURABARI ROAD TO SNANGHAT | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.138603, Lat - 26.242600, Dept - PWD (Roads)), 3RD KM OF BS ROAD TO JOGIRMAHAI II, SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO SONKOSH RIVER WATER | BS ROAD TO JOGIRMAHAI II | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.164017, Lat - 26.237988, Dept - PWD (Roads)), 3RD KM OF BS ROAD TO TUSHPARA ROAD SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO TIPKAI RIVER WATER | BS ROAD TO TUSHPARA ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.165705, Lat - 26.322367, Dept - PWD (Roads)), 3RD KM OF BS ROAD AT JOGIRMAHAL TO SALMARA ROAD, SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO SONKOSH RIVER WATER | BS ROAD AT JOGIRMAHAL TO SALMARA ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long -90.168506, Lat - 26.250768, Dept - PWD (Roads)), 5TH KM OF BS ROAD TO GUTIPARA ROAD SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO HELL RIVER WATER | BS ROAD TO GUTIPARA ROAD | Dated: 18-06-2023 to 22-06-2023 | (Long - 90.165603, Lat - 26.262476, Dept - PWD (Roads)), 4TH KM OF BS ROAD TO KHEJURBARI PT-I ROAD, RCC BRIDGE APPROACHES DAMAGED BR.NO.2/1 & 4/1 DUE TO SONKOSH RIVER WATER | 19. 4TH KM OF BS ROAD TO KHEJURBARI PT-I ROAD, RCC BRIDGE APPROACHES DAMAGED BR.NO.2/1 & 4/1 DUE TO SONKOSH RIVER WATER | Dated:- 18-06-2023 to 22-06-2023 | (Long -90.163953, Lat - 26.253756, Dept - PWD (Roads)), 13TH KM OF BS ROAD TO BARKUTI ROAD SIDE BERM AND SURFACE DAMAGED AT

1st KM AND 2ND KM, DUE TO HELL RIVER WATER | BS ROAD TO BARKUTI ROAD | Dated:- 18-06-2023 to 22-06-2023 | (Long - 90.152596, Lat - 26.308209, Dept - PWD (Roads)), 9TH KM OF BS ROAD TO BARUAPARA ROAD, RCC BRIDGE APPROACHES DAMAGED DUE TO HEAVY RAIN WATER | BS ROAD TO BARUAPARA ROAD, | Dated:- 18-06-2023 to

22-06-2023 | (Long - 90.167497, Lat - 26.308969, Dept - PWD (Roads)),

4TH KM OF FS ROAD TO ODLARTOL ROAD, SIDE BERM AND SURFACE DAMAGED AT 1st KM AND 2ND KM, DUE TO HELL RIVER WATER | FS ROAD TO ODLARTOL ROAD | Dated:- 18-06-2023 to 22-06-2023 | (Long - 90.165705, Lat - 26.312367, Dept - PWD (Roads)), 2ND KM OF CHORUARVITA ROAD TO ATHIABARI ROAD, RCC BRIDGE APPROACHES DAMAGED, DUE TO HEAVY RAIN WATER | CHORUARVITA ROAD TO ATHIABARI ROAD | Dated:- 18-06-2023 to 22-06-2023 | (Long - 90.182260, Lat - 26.274793, Dept - PWD (Roads)),

MARKET MODERNIZATION AND IMPROVEMENT PROGRAMME (MMIP) OF BILASIPARA CHILLI MARKET(.)IN DHUBRI DISTRICT UNDER APART ( PACKAGE NO NOCP/MARKETS/DH-03) PARTIALLY SUBMERGED DUE TO HEAVY RAINFALL | BILASIPARA CHILLI MARKET | Dated:- 18-06-2023 to 22-06-2023 | (Long - 90.271801, Lat - 26.232983, Dept - PWD (Roads)),

MAYERCHAR PART-VII TO NAYERALGA PART-IV ROAD (.) (PMGSY, PACKAGE NO. AS-05-42) LENGTH=9.04 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | MAYERCHAR PART-VII TO NAYERALGA PART-IV ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.184465, Lat - 26.167563, Dept - PWD (Roads)),

SUAPATA PART-III TO NAYERALGA PART-III ROAD (.) (PMGSY, PACKAGE NO. AS-05-25) LENGTH=15.50 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | SUAPATA PART-III TO NAYERALGA PART-III ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.197590, Lat - 26.160141, Dept - PWD (Roads)), SUAPATA PART-III TO MAYERCHAR ROAD (.) LENGTH= 5 KM SIDE BURM AND ROAD SURFACE DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | SUAPATA PART-III TO MAYERCHAR ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.278652, Lat - 26.193312, Dept - PWD (Roads)),

MAYERCHAR PART-I TO NAYERALGA PART-III ROAD (.) (PMGSY, PACKAGE NO. AS-05-26) LENGTH=7.25 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | MAYERCHAR PART-I TO NAYERALGA PART-III ROAD | Dated: - 20-06-2023 to 21-06-2023 | (Long - 90.221753, Lat - 26.147802, Dept - PWD (Roads)), NAYERALGA GAURANG GHAT TO GUTIPARA PART-IV ROAD (.) (PMGSY, PACKAGE NO. AS-05-41) LENGTH=9.06 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | NAYERALGA GAURANG GHAT TO GUTIPARA PART-IV ROAD ( | Dated: - 20-06-2023 to 21-06-2023 | (Long - 90.184384, Lat - 26.176886, Dept - PWD (Roads)),

DUBACHURI AT MAMABAZAR TO SAGUNBARI PART-IV ROAD (.) (PMGSY, PACKAGE NO. AS-05-43F) LENGTH=4.50 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | DUBACHURI AT MAMABAZAR TO SAGUNBARI PART-IV ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.204980, Lat - 26.218359, Dept - PWD (Roads)),

KADAMTOLA PART-II TO KADAMTOLA PART-I ROAD (.) (PMGSY, PACKAGE NO. AS-05-143) LENGTH=3.50 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | KADAMTOLA PART-II TO KADAMTOLA PART-I ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.210358, Lat - 26.227330, Dept - PWD (Roads)), KRISHNANAGAR KAJAIKATA HUDURCHAR ROAD (.) LENGTH=6 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | KRISHNANAGAR KAJAIKATA HUDURCHAR ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.218616, Lat - 26.201409, Dept - PWD (Roads)),

KKH ROAD TO BABURHAT BAZAR ROAD (.) LENGTH=2.50 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | KKH ROAD TO BABURHAT BAZAR ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.198960, Lat - 26.183278, Dept - PWD (Roads)),

MAYERCHAR BAZAR TO NOONKHOWAPARA MOSJID ROAD (.)LENGTH=3 KM SIDE BURM AND ROAD SURFACE DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | MAYERCHAR BAZAR TO NOONKHOWAPARA MOSJID ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.198600, Lat - 26.143796, Dept - PWD (Roads)),

MAMABAZAR TO SAGUNMARI PART-IV ROAD (.) LENGTH=2.50 KM SIDE BURM AND HARD CRUST DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | MAMABAZAR TO SAGUNMARI PART-IV ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.204980, Lat - 26.218359, Dept - PWD (Roads)),

MAYERCHAR PART-I (T04) TO NAYERALGA PART-III, PART-II | MAYERCHAR PART-I (T04) TO NAYERALGA PART-III, PART-II | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.192977, Lat - 26.165766, Dept - PWD (Roads)),

5TH KM OF KKH ROAD (BHERAKHOWA) (T04) TO KAZAIKATA PART-IV ROAD (.) (FROM CH 0.00M TO CH 1000.00M) (PACKAGE NO- MAINT/MMPPNA/59) LENGTH=1.00KM SIDE BURM AND GSB LEVEL DAMAGED DUE TO FLOOD WATER OF GAURANG RIVER | 5TH KM OF KKH ROAD (BHERAKHOWA) (T04) TO KAZAIKATA PART-IV ROAD | Dated:- 20-06-2023 to 21-06-2023 | (Long - 90.203588, Lat - 26.194853, Dept - PWD (Roads))

			department, Due to incessant rainfall for several days Simlabari to Haloipara Kaborsthan Road at 1st KM submerged and affected length 60M from 18.06.2023 to till date i.e 23.06.2023   (Long - 90.195105, Lat - 25.966827, Dept - PWD (Roads)), Khalisavita Hindupara to Khalisavita Muslimpara Road   Near Khalisavita Hindupara   As per report of PED road department, Due to incessant rainfall for several days Khalisavita Hindupara to Khalisavita Muslimpara Road at 2nd KM eroded and affected length 100M from 18.06.2023 to till date i.e 23.06.2023   (Long - 90.150377, Lat - 25.979591, Dept - PWD (Roads)), Kharmuja Nichinpur Dyke Road (From CH. 1800 M to CH. 2100M)   Near Nichinpur   As per report of PED road department, Due to incessant rainfall for several days Kharmuja Nichinpur Dyke Road at CH. 350 M to 2800 M eroded and affected length 460M from 18.06.2023 to till date i.e 23.06.2023   (Long - 90.333128, Lat - 26.088011, Dept - PWD (Roads)), Takimari Tiniali ti Ratangaon Road, PMGSY Package No. 249   Near Takimari Tiniali † As per report of PED road department, Due to incessant rainfall for several days Takimari Tiniali † Ratangaon Road, PMGSY Package No. 249 eroded and affected length 125M from 18.06.2023 to till date i.e 23.06.2023   (Long - 90.307362, Lat - 26.050484, Dept - PWD (Roads)), Dhopakura Village Road, PMGSY Package No. AS-07-251   At Dhopakura   As per report of PED road department, Due to incessant rainfall for several days Dhopakura Village Road, PMGSY Package No. AS-07-251   At Dhopakura Village Road, PMGSY Package No. AS-07-251   At Dhopakura Village Road, PMGSY Package No. AS-07-251   At Dhopakura Village Road, PMGSY Package No. AS-07-251   Near Dhopakura   As per report of PED road department, Due to incessant rainfall for several days Pantaibeel to Dhopakura MV School Road, PMGSY Package No. AS-07-250   Near Dhopakura   As per report of PED road department, Due to incessant rainfall for several days Pantaibeel to Dhopakura MV School Road, PMGSY Package No. AS-07-250 culvert approach road embankm
			(Long - 90.336853, Lat - 26.041543, Dept - PWD (Roads)), Jaleswar College to Bashmura Road, PMGSY Package No. AS-07-144   Near Jaleswar   As per report of PED road department, Due to incessant rainfall for several days Jaleswar College to Bashmura Road, PMGSY Package No. AS-07-144 at 1st KM eroded and affected length 25M from
K	Carimganj	2	18.06.2023 to till date i.e 23.06.2023   (Long - 90.208724, Lat - 26.034635, Dept - PWD (Roads))  Karimganj - Longai road near fashion queen   Longai ghat   Due to incessant heavy rain from last few days the above road is damaged partially (Hard crust damaged ) at CH 250.00 M -450.00 M  The above report was submitted by Asst. Executive Engineer ,Karimganj North Territorial Road division on 17/06/2023 .   (Long - 92.357320, Lat - 24.869720, Dept - PWD (Roads)),  DC office approach road   near dc office   Due to incessant heavy rain from last few days the above road is damaged partially (sudden depression at some stratches & Hard crust damaged ) at CH 50.00 M -150.00 M .The above report was submitted by Asst. Executive Engineer ,Karimganj North Territorial Road division on 17/06/2023 .   (Long - 92.356081, Lat - 24.868906, Dept - PWD
K	Cokrajhar	8	Ragribari - Lalmati Tumbagan Road   Lalmati   As reported by Asstt. Executive Engineer, PWD, Gossaigaon Rural Road Sub-Division, Lalmati Tumbagan road has been damaged in stitches due to heavy rainfall Dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Paglahat Joldoba Road   Joldoba   As reported by Asstt. Executive Engineer, PWD, Gossaigaon Rural Road Sub-Division, Paglahat Joldoba road has been damaged in stitches due to heavy rainfall Dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Debitola Bazar to Khotabagra Road   Debitola   As reported by Asstt. Executive Engineer, PWD, Gossaigaon Rural Road Sub-Division, Debitola Bazar to Khotabagra road has been submerged due to heavy rainfall Dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Khoraghat to Khamar Road   Khoraghat to Khamar Road At 2nd KM   As reported by Executive Engineer, PWD, Bilasipara Civil Sub-Division, Territorial Road Division, Khoraghat to Khamar Road side berm and surface has been damaged due to heavy rainfall w.e.f 18/06/2023 to 22/06/2023   (Long - 90.123012, Lat - 26.215617, Dept - PWD (Roads)), Kharkharia to Goraimari Via Lalmati Road   Kharkharia to Goraimari Via Lalmati Road   Kharkharia to Goraimari Via Lalmati Road Division, Kharkharia to Goraimari Via Lalmati Road   Sub-Division, Territorial Road Division, Kharkharia to Goraimari Via Lalmati Road   Kharkharia to Goraim

			road   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), <b>Dotma</b> - Boragari-Narengury Road   Boragari   Date: 23/06/2023 Breach of Boragari-Narenguri road. Reported by Village man   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Habrubari-Khunthaibari road   Habrubari   Dated: 23/06/2023 Damage of Habrubari-khunthaibari
			road and approach bamboo bridge. Reported by villageman   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Majuli	3	Majuli - Alimur Bhakat Chapori Road Got Submerged from CH 3100M to 3160M on 23.06.2023   Alimur Bhakat Chapori Road   Rise of flood waterof two tributary of river Brahmaputra communication through this road have been cut off   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Kuli Chapori to Major chapori Road Got Submerged from CH 5450M to 5520M on 23.06.2023   Major chapori   Rise of flood waterof two tributary of river Brahmaputra communication through this road have been cut off   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Ujani Majuli - Bongaon to Mrragarh Colony Road CH 100.00M to 400.00M got submerged on
	Nalbari	6	22.06.2023   Mrragarh     (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))  Banekuchi - On 23/06/2023 at 8 am Akhra Bihampur Road submerged and damaged report from Gaon Pradhan   madhupur   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Nalbari - Bidyapur malikuchi connecting road, ward no 1   ward no 1   As per the report from PWRD, this road is submerged due to rain water on 22.06.23   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Embankment cum road from nalbari NT road to Sonkuriha, side beam damaged   NT road   As per the report from PWRD, this road is submerged due to rain water on 22.06.23   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),  Ghograpar - Koliya Gohain Road   Bhithamahal   As per PWRD Report, Koliya Gohain Road has been submerged dtd 22/06/2023   (Long - 91.540000, Lat - 26.500000, Dept - PWD (Roads)),  Ghograpar tamulpur Road   Alliya   As per PWRD Report, Road has been submerged dtd 22/06/2023   (Long - 0.000000, Dept - PWD (Roads)),  Sita Ram Akana Road to Akana Das Road   Akana   As per PWRD Report, Road has been submerged dtd 22/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Tamulpur	3	Goreswar - Madalbari to Betagaon Road   Tengajhar (Madalbari)   As per report received from AEE (PWD) Goreswar Rural Roads RCC Bridge Approach eroded at Village Tengajhar (Madalbari Suba) Dated: 22/06 2023.   (Long - 91.691084, Lat - 26.606571, Dept - PWD (Roads)), 12 No chowk to Naramari Chowk   Garogaon   As per report received from AEE (PWD) Goreswar Rural Roads a Culvert got damaged at Village Garogaon Dated: 22/06 2023   (Long - 91.721678, Lat - 26.496246, Dept - PWD (Roads)), Naramari to Gopchar Road   Silkijhar   As per report received from AEE (PWD) Goreswar Rural Roads road embankment eroded and damaged at Village Silkijhar Dated: 22/06 2023   (Long - 91.761392, Lat - 26.502659, Dept - PWD (Roads))
	Total	213	
	District/Sub -division*	Numbe r	Details
	Bajali	2	Sarupeta - RCC Br. No. 2/1   Sarupeta Gaon   RCC Br. No. 2/1 approaches eroded and damaged at Sarupeta Gaon,Report received from AEE,PWD,Bhawanipur TR Sub-Division,Bhawanipur on 22/6/2023   (Long - 91.060159, Lat - 26.497506, Dept - PWD (Roads)), RCC Br. No. 1/1   Majgaon   RCC Br. No. 1/1 approaches eroded and road side berm & side slopes damaged at Majgaon ,Report received from AEE,PWD,Bhawanipur TR Sub-Division,Bhawanipur on 22/6/2023   (Long - 91.018109, Lat - 26.489024, Dept - PWD (Roads))
Infrastructu re Damaged - Bridge	Barpeta	3	Baghbar - 1. RCC BR No. 7/1 (Barpeta Baghbar road)   Near Bhatkuchi area   Due to heavy rainfall Bridge App damage of RCC Br No 7/1 on Barpeta Baghbar road. Damage length approx 20.00m.Date-21/06/2023   (Long - 90.982974, Lat - 26.284949, Dept - PWD (Roads)), RCC Br NO.16/1 (Barpeta Baghbar Road)   Near Satrakanara Bazar   Due to heavy rainfall Bridge App damage of RCC Br No 16/1 near satrakanara bazar on Barpeta Baghbar road. Damage length approx 30.00m.Date-21/06/2023   (Long - 90.926093, Lat - 26.246134, Dept - PWD (Roads)), RCC Br No.2/1 (Mandia to Dongra road)   Near Bamundongra area   Due to heavy rainfall Bridge App damage of RCC Br No 2/1 on Mandia-Dongra road. Damage at Ch.1150.00 m to 1350.00 m.Date-22/06/2023   (Long - 90.982734, Lat - 26.264881, Dept - PWD (Roads))
	Dhubri	7	Dhubri - BRIDGE APPROACHES DAMAGED AND ERODED OF RCC BR. NO. 1/1 ON D.G ROAD AT SAMSHANGHAT TO FALIMARI ROAD AT 1ST KM (21-06-23)   FALIMARI   (Long - 89.978474, Lat - 26.028429, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 1/1 ON KACHARIHAT PWD ROAD TO SINGIMARI ROAD AT 1ST KM(21-06-23)   KACHARIHAT   (Long - 89.871236, Lat - 26.045560, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 1/1, 1/2 & 2/3 ON DHARMASALA DURAHATI ROAD VIA SINGIMARI ROAD AT 1ST KM(21-06-23)   DHARMASALA DURAHATI   (Long - 89.875581, Lat - 26.025424, Dept - PWD (Roads)), BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 1/1 ON MOTIRCHR DHARMASALA ROAD AT 1ST KM(21-06-23)   MOTIRCHR   (Long - 89.889988, Lat - 26.021714, Dept - PWD (Roads)),

	Kokrajhar	SPT BRIDGE NO. 1/1 & APPROCH PARTIALLTY DAMAGED ON GAURIPUR KALAHAT ROWA ROAD TO BURIRIMARI FROM CH. 0.00 M TO 500.00 M (21-06-23)   KALAHAT ROWA     (Long - 89.913426, Lat - 26.060873, Dept - PWD (Roads)),  BRIDGE APPROACHES & SIDER BERM ERODED ON KACHARIHAT BAZAR TO TISTERPAR WATER SUPPLY FROM 1ST TO 4TH KM IN STRETCHES (21-06-23)   TISTERPAR     (Long - 89.852822, Lat - 26.029480, Dept - PWD (Roads)),  Gauripur - BRIDGE APPROACH DAMAGED OF RCC BR. NO. 2/1 ON HASDAHA PT-III TO SOULMARI AT 1ST KM (Date-21-06-23)   D.Hasdaha     (Long - 89.852822, Lat - 26.029480, Dept - PWD (Roads))  Bagribari - Bridge No.1/1 on Paglahat Joldoba Raod   Joldoba   As reported by Asstt. Executive Engineer, PWD, Gossaigaon Rural Road Division, approaches of Bridge No.1/1 on Paglahat Joldoba Raod has been damaged due to heavy rainfall. Date: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Nalbari	Nalbari - Nalbari kamarkuchi road at Barmurikona, Bridge approch damage   Barmurikona   As per the report received from PWRD, this bridge approch is damaged due to flood on 22.06.23   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Total	14
Infrastructu re Damaged - Wildlife	Nil	
	District/Sub -division*	Other Details
	Bajali	Sarupeta - Agri Bundh Damaged   Agri bundh of Pahumara River damaged at Nakuchi Pather (Longitude: 91.086815,Latitude: 26.437753),Report received from concern LM on 21 June,2023.,  Bajali - Road Breaches   Bhogeswari Mandir to Pipla road breached at a point with length 7Mtrs, Breadth 4Mtrs and height 2 Mtrs. latitude-26.592116 longitude- 91.238003. This report is received from AEE,PWD Roads on 23-06-2023,  Agri Bundh Damaged   Agribundh at left side of Burhadia river breached at Parahkuchi village. This report is received from concerned LM on 23/06/2023,  Agri Bundh Damaged   Agribundh at left side of Burhadia river breached at Parahkuchi village. This report is received from concerned LM on 23/06/2023,  Agri Bundh Damaged   Agribundh at left side of Burhadia river breached at Kharia village. This report is received from concerned LM on 23/06/2023,  Agri Bundh Damaged   Agribundh at left side of Burhadia river breached at Kalatali Pathar village. This report is received from concerned LM on 23/06/2023,  Agri Bundh Damaged   Agribundh at left side of Burhadia river breached at Parahkuchi village. This report is received from concerned LM on 23/06/2023,  Agri Bundh Damaged   Agribundh at right side of Burhadia river breached at Parahkuchi village. This report is received from concerned LM on 23/06/2023
Infrastructu re Damaged - Others	Baksa	Baska - Washed away Culverts   Dihira MV School to Bhutankhuti HPC Culvert washed away at village Arampur on 21/06/2023 Coordinate: 26.644772, 91.347040 as WT msg. recieved from AEE, PWD, Culvert Approach Road Damaged   Tihu Doomni Road surface & Double HPC Culvert Damage at village Chutiapara on 21/06/2023 Coordinate: 26.586958, 91.269935 as WT msg. recieved from AEE, PWD, Culvert Approach Road Damaged   Dihira PHC to Bhtankhuti road RCC culvert damaged at village Dhansripur on 21/06/2023 Coordinate: 26.746664, 91.365142 as WT msg. recieved from AEE, PWD, Culvert Approach Road Damaged   Doomni Bagan to Batabari RF Road Bridge no 2/1 approach road damaged at village Arnibil 21/06/2023 Coordinate: 26.857778, 91.572500 as WT msg. recieved from AEE, PWD, Culvert Approach Road Damaged   Narayanpur Simlaguri to 2 No Narayanpur Road RCC Culvert Damaged with approach at village No. 2 Narayan pur 21/06/2023 Coordinate: 26.676814, 91.345569 as WT msg. recieved from AEE, PWD, Culvert Approach Road Damaged   Sujit Narzary Road Surface and Bridge approach damaged at village Singrapara on 21/06/2023 Coordinate: 26.335220, 91.180900 as WT msg. recieved from AEE, PWD, Culvert Approach Road Damaged   Dihira Simbliguri to Arnibil road RCC Culvert approach road damage at village Dihira near Bikram Singh House on 21/06/2023 Coordinate: 26.740496, 91.352429, Barama - Bridge Approach Road Damaged   Thanguri Lakhi river bridge approach damaged due to flood on 21-06-23. Lat: 26.585328 Lon: 91.433718, Baganpara - Washed away Culverts   Dhamdhama to Angardhowa via Santipur HPC culvert damaged on dated 21/06/2023 as per sdo pwd Officals (lat 26.58610, long 91.464237).), Bridge Approach Road Damaged   Maithabari to chaulkara road rcc bridge approach have been damaged on dated 21/06/2023 (lat- 26.728001, long- 91.436715), Bridge Approach Road Damaged   Dongbima FIS left side boulder pitching at the downstream of the FIS has been washed way on dtd 22/06/2023 (lat 26.732822, long- 91.434876)  Bijni - Culvert Approach Road Damaged   As repor
	Chirang	

Dhubri	Culvert Approach Road Damaged   As reported by AEE,PWD, Sorbhog (R&B) Sub DIvision, Niz Damugaon to Fenchi bazar Road and culvert damaged at Niz damugaon on 22-03-2023. Length=2.50 mtr, Breadth=3.56 mtr, Depth=0.50 mtr. Latitude=26.570328 Longitude=90.848648,  Road Breaches   As reported by concerned LM, Boupara to Bishdoba road damaged at Boupara on 22-06-2023. Length=6.09 mtr, Breadth=4.87 mtr, Depth=1.21 mtr. Latitude=26.565531 Longitude=90.805987,  Culvert Approach Road Damaged   As reported by PWD, Bijni(R&B) Sub Division, approaches of Bagargaon Road damaged at Bagorgaon on 22-06-2023. Length=20.00 mtr, Depth=3.00 mtr, Depth=4.00 mtr. Latitude=26.543959 Longitude=90.743183,  Damaged SPT Bridge   As reported by PWD, Bijni(R&B) Sub Division, Kawadi No 2 to Sonaikhola road SPT bridge at Kawadi No 2 in dilapidated condition. Length=65 mtr, Breadth=4.10 mtr, Depth=Nil. Date of Occurrence=22-06-2023,  Sidli - Power Dept. Poles   As reported by SDE, BESD,APDCL, Basugaon, Pole Damage- 2 Nos of Village Fulguri. Lat- 26.520371,Long-90.395825 date of Occurrence-23-06-2023  Dhubri - Culvert Approach Road Damaged   BOX CELL CULVERT APPROACHES DAMAGED ON TISTARPAR BOP ROAD TO TISTARPAR PT-I ROAD AT 1ST KM,(.) (LAT- 26.015995, LONG-89.85517) (Date-21-06-23), Location-Tistarpar),
	Athani - Power Dept. Poles   7.5 M PSC POLES-5 NOs. 9.75 M PSC POLES-25 Nos. on dated 21-06-23,
Goalpara	Power Dept. Conductors   CONDUCTOR LT-1.2 KM AND LT-0.23 KM on dated 21-06-23  Lakhipur - Irrigation Canal/Scheme Damaged   As per report of Irrigation department, Due to incessant rainfall for several days, overflow of river Ghagua F.I.S., The RHS Affiux Bund is completely submarged from CH. 750M to 850M and CH. 1050M to CH. 1150M flood water has breached the afflux bund and entered the village from 22.06.2023 to till date i.e 23.06.2023. Lat-25.96803 Long-90.199927, Irrigation Canal/Scheme Damaged   As per report of Irrigation department, Due to incessant rainfall for several days, overflow of river Ghagua F.I.S., The LHS Affiux Bund is completely submerged from CH. 176M to 300M and CH. 700M to CH. 1000M from 22.06.2023 to till date i.e 23.06.2023. Lat-25.956246 Long-90.18395,  Balijana - Culvert Approach Road Damaged   As per PWD (RR) a culvert in Pnacharatna Kharmuja Road has been clogged with accumulated soil and subsided beyond the existing road level causing water logging in the adjacent areas as on 23/06/2023. Lat: 26.19347 Long: 90. 545948
Kamrup	Rangia - Power Dept. Conductors   0.500km conductor damaged at Milanpur GPS Location Latitude 26°43889 and Longtitude 91°63296, 0.300 Km conductor Damaged at Nakul (Kekenikuchi) GPS Latitude 26°427619 and Longtitude 91°663195 and 0.300 km damaged at Hiragata GPS Location Latitude 26°454226 and Longtitude 91°683827 reported by APDCL ESD 1 dated 22/06/2023, Power Dept. Poles   2 HT Pole & 1 Lt Pole damaged at Milanpur GPS Location Latitude 26°43889 and Longtitude 91°63296, 2 HT Pole damaged at Nakul(Kekenikuchi) GPS Location Latitude 26°427619 and Longtitude 91°663195 and 1 HT Pole damaged at Hiragata GPS Location Latitude 26°454226 and Longtitude 91°683827 dated 22/06/2023 reported by APDCL ESD 1, Power Dept. Transformers   1 Transformer damaged 100 KVA at Dhorampur GPS location Latitude 26°429815 and Longtitude 91°624918 dated 22/06/2023 Reported by APDCL ESD 1
Karimganj	Karimganj - Bridge Approach Road Damaged   NH -151 To Barpurahuria Pt II BRIDGE approach road is badly damaged , CH - 2800.00M TO 2900.00M . LAT . 24.887368 , LONG .92.263621 The above report was submitted by Asst. Executive Engineer ,Karimganj North Territorial Road division on 17/06/2023
Kokrajhar	Bhawraguri - Bamboo Foot Bridge   As reported by AEE PWD RR, GOSSAIGAON on 23-06-2023 due to heavy rainfall in this month Bridge no 6/3 has been damaged at Bhawraguri Bhumka Road via Patialpara (location- Mokrambil lat- 26.385559, long- 90.046273),  Gossaigaon - Damaged SPT Bridge   As reported Gossaigaon Municipal Board on 23.06.2023 due to heavy rain Wooden bridge damaged and washed away at Gossaigaon near Ananta Kutir L.P. School connecting Ward No.2 and Ward No.3,  Culvert Approach Road Damaged   As per reported by AEE PWD RR Gossaigaon on date 23.06.2023 due to heavy rain both side approaches of box culvert No.1/1 at Sapkata to Jailbasti road has been damaged
Lakhimpur	<b>Bihpuria</b> - Fisheries/Pond   69 nos. of ponds (14 hectares) affected at Dharmapur Block as reported by FDO, Karunabari Block on 23/06/2023
Majuli	Majuli - Elementary Schools Damaged   As the water level of river Brahmaputra is rising, 204 no. Auniati Alimur LP School submerged on 23.06.2023
Nalbari	Barkhetri - Fisheries/Pond   Tentative Ponds & Tanks Submerged Report under Barkhetri Dev. Block as on 23/06/2023, Affected Water area 35.0 Ha and 250 Nos. of Farmers affected may be increase or decrease during post flood assessment as reported by FDO, Barkhetri on 23/06/2023,  Tihu - Agri Bundh Damaged   BREACHED OF AGRIBUNDH AT MORA PAGOLDIA RIVAR NEAR DAKHIN BHOJKUCHI LPS ON 23/06/2023 AS PER REPORT GP ,LENGTH IS APPROX 60 FTS , Fisheries/Pond   AS PER REPORT DFDO ON 22/06/2023 TOTAL 192.10 HA LAND'S POND SUBMERGED ,  Paschim Nalbari - Fisheries/Pond   210 nos. farmers family and 62 ha area affected by flood and rain water. Information received from Fishery Department on 23/06/2023,  Power Dept. Conductors   Total 13.8 conductor damaged by flood water at Nadala and Khataruiabathan. Information received from APDCL Department on 20/03/2023 ,  Power Dept. Poles   Total 6 nos. LT Poles and 4 nos. HT poles are damaged due to flood water. Information received from APDCL Department on 20/06/2023 ,  Irrigation Canal/Scheme Damaged   Total 15 nos. of irrigation schemes are submerged due to rain and flood

		1. I.C. 1. 1. 1. 1. 1. 1. 20/07/2022
		water. Information received from Irrigation department on 23/06/2023, <b>Ghograpar</b> - Culvert Approach Road Damaged   1. Culvert No 11/1 Ghograpar Tamulpur Road Damaged, 2.  Ghograpar tamulpur Road Culvert Ch. 10600 Culvert washed away width of damaged 12.00M as per PWD report dtd 22/06/2023
		Harisinga - Culvert Approach Road Damaged   Due to heavy rainfall on 22nd June 2023 culvert damage at village Merbangchuba. LAT 26.7193 LON 91.6631, Culvert Approach Road Damaged   Due to heavy rainfall on 22nd June 2023 culvert damage at village
	Udalguri	Totolapara. Lat 26.6650 Long 91.8320., <b>Khairabari</b> - Fisheries/Pond   As reported by the department, due to continuous downpour and rise in water level, 4.3 Ha. of water area is affected in villages namely Jalukbari, Sukuliapara, Senialpara, Dewaguri,
	District/Sub	Kacharidag and Gharanikhat on 22-06-2023  Details
	-division*	
	Baksa	Jalah - MILANBAZAR   As per Soil Conservation Range Officer report EROSION at MILANBAZAR ULTA KHUNDA DONG AND ITS ADJACENTPADDY AREA OF MILANBAZAR VILLAGE as on date 22-06-2023.   0   (Long - 90.932355, Lat - 26.557231)
	Biswanath	Gohpur - At No. 2 Bickrampur   Mild Bank erosion at R/Bank of River Sessa of length 30 mtr on 23/06/23   0   (Long - 93.728440, Lat - 26.964250),  Halem - Paken   Mild bank erosion is observed at paken area of b/dyke from Jamuguri to Kharoi outfall.
		Length =10 m (avg.width=0.10m) on 23/06/2023   0   (Long - 93.625861, Lat - 26.798845)
	Bongaigaon	Manikpur - Nagarjhar   Manas river erosion bundh at nagarjhar. Erosion of around length=10mtr.  Breadth=6mtr. daate-23/06/2023   0   (Long - 90.749283, Lat - 26.463376)
	Chirang	Sidli - Athiabari Village   As reported by JE, WRD, Chirang, Bank erosion on L/B of river Suthi, Length Appx. 200m, Breadth Appx.5.00m, Depth appx.4.50m date of occurrence- 22-06-2023   0   (Long - 90.422938, Lat - 26.557335)
		<b>Chapar</b> - Majergaon   Erosion took place on dated 21-06-23 to 23-06-23 at Magergaon village by the river Champabati where 0B-1K-08L of agricultural land has been eroded so far.   0   (Long - 90.441700, Lat - 26.344100),
	Dhubri	Athani - Salmara Pt-II, Jhelturchar Pt-III, Gutipara Pt-VI   Erosion occurred at village Salmara Pt-II by River Tipkai from dated 19/06/2023 to 22/06/2023. Total 6(Six) Nos. of dwelling houses of six families were eroded and the families were shifted to their another places. No people become landless due to the erosion. Residential land measuring about 2B-1K-10L have been eroded.(Lat-26.156649, Long- 90.135816) Erosion occurred at
		village Jhelturchar Pt-III by River Tipkai from dated 19/06/2023 to 22/06/2023. Total 5(Five) Nos. of dwelling houses of 5 families were eroded and the families were shifted to their another places. No people become landless due to the erosion. Residential land measuring about 2B-0K-0L have been eroded.(Lat-26.165967,
		Long- 90.137553) Erosion occurred at village Gutipara Pt-VI by River Tipkai from dated 19/06/2023 to 22/06/2023. Total 4(Four) Nos. of dwelling houses of 4 families were eroded and the families were shifted to their another places. No people become landless due to the erosion. Residential land measuring about 1B-2K-
Erosion		10L have been eroded.(Lat-26.159245, Long- 90.14712)   80   (Long - 90.135816, Lat - 26.156649),  Bilasipara - Nayeralga pt-I, Mayerchar pt-I & Mayerchar pt-II under Bilasipara Revenue Circle   Recently
		erosion has taken place by the river Gaurang at village: Nayeralga pt-I, Mayerchar pt-I & Mayerchar pt-II under Bilasipara Revenue Circle. Date of incident:- 21-06-2023 to 22-06-2023 1 Nayeralga pt-I Lat:- 26.156801 N Long:- 90.257039 E Land measuring around :- 26 Bigha 01 Katha 05 Lessa 2 Mayerchar pt-I
		Lat:- 26.146919 N Long:- 90.229553 E Land measuring a round :- 13 Bigha 03 Katha 05 Lessa 3 Mayerchar pt-II Lat:- 26.147125 N Long:- 90.229626 E Land measuring around :- 26 Bigha 0 Katha 0 Lessa   21   (Long - 90.257039, Lat - 26.156801)
		Naharkatia - 1.Naga Gaon   As per report received from JE, WR department Dibrugarh, as on 22-06-2023 erosion at Nagagaon (Nokte Gaon) ,L/B of river Buridehing, for a length of 270 m.   0   (Long - 95.386767, Lat
	Dibrugarh	- 27.285771), <b>Tingkhong</b> - Disang Borbill   As reported by WRD on 23-06-23 erosion occurred by River-Disam at Balioni Chuk,Disang Borbill village ,Length-30m   0   (Long - 95.125880, Lat - 27.317780)
		Bhawraguri - Durabil (Ranjingpara & Bwigriguri), Mukuldang No I (Harinpur), No 2 Chekadani, Bamunigaon, Rimijhimighat Pt I, Rmijhimighop, Faluguri, Badlagaon, Mokrambil, Koimari (Adibashi & Bodo Basti)   As reported by Executive Engineer, Kokrajhar WRD & Sectional Officer, Gossaigaon WRD on dated
		23-06-2023 1. River Bank Erosion observed at village Durabil (Ranjingpara) Reach Length 500 M on R/B of River Gongia 2. River Bank Erosion observed at village Durabil (Bwigriguri) Reach Length 350 M, 3. River Bank Erosion observed at village Harinpur Reach Length 520 M on R/B of River Gongia 4. River Bank
	Kokrajhar	Erosion observed at village Chekadani Reach Length 500 M on R/B of River Gongia 5. River Bank Erosion observed at village Bamunigaon Reach Length 650 M on R/B of River Gongia 6. River Bank Erosion observed at village Rimijhimi Reach Length 480 M on R/B of River Gongia 7. River Bank Erosion observed at village
		Badlagaon Reach Length 500 M on R/B of River Gongia 8. River Bank Erosion observed at village Faluguri Reach Length 500 M on L/B of River Gongia. 9. River Bank Erosion observed at village Mokrambil Reach Length 500 M on L/B of River Guruphella 10. River Bank Erosion observed at village D/S of Koimari
		Adibashi Basti of River Guruphella 11. River Bank Erosion observed at village Koimari Bodo Basti on L/B of River Guruphella   0   (Long - 90.100085, Lat - 26.527055),
		Gossaigaon - (1) Simlabari F.V. (2).Boroghopa F.V.   1. As reported AEE WRD Gossaigaon Sub Division on 23.06.2023, due to rain severe bank erosion observed at village simlabari of river sonkosh on its L/B erosion length 550.00 M 2. As reported AEE WRD Gossaigaon Sub Division on 23.06.2023, due to heavy rain sever

	T	
		bank erosion observed at Boroghopa vilage of river Sonkosh on its L/B erosion Length 400.00M erosion is continuing(23.06.2023)   0   (Long - 0.000000, Lat - 0.000000)
		<b>Demow</b> - 1. Saniboria Bazar 2. koibortadoloni 3. 2 no konwar gaon   1. Bank Damage at Saniboria Bazar area
		of Brahmaputra dyke from Laibeel to Tengapani from ch. 11000 m to 11400 m. Geocordinate: 27.1843694N
		94.6471361E from 22/06/2023 to 23/06/2023 . 2. River bank erosion from AT road to Dhai ali at
		Koibortadoloni village for a length of 450 m Geo coordinate: 27.18436N 94.647136E from 22/06/2023 to
		23/06/2023 3. Sloughing and river bank erosion has been observed at Desang right bank from Bahgarh to AT
		road for a length of 550 m.Geocoordinate: 27.03894N 94.72015E from 22/06/2023 to 23/06/2023   0   (Long -
		0.000000, Lat - 0.000000),
		Sivsagar - 1. Gowal Gayan (Saraguri Chapori), 2. Chenglibari, 3. Dwari Gaon, 4. Kuwamora Satra
		1.Damages have been observed in the from of slump down on 22-06-2023 at south bank of River Brahmaputra
	Sivasagar	near Saraguri Chapori under Sivasagar Revenue Circle. The report received from WR Sivasagar
		Div.(94.469094 E,27.011937 N) 2. The sloughing and river bank erosion has been observed on 29-04-2023 at
		Desang river left bank from Bhagarh to AT Road & AT road to Akhoiphutia Ghat at Cheglibari under
		Sivasagar Revenue Circle. The report received from WR Sivasagar Div (94.4336 E, 27.057 N) 3. The
		sloughing and river bank erosion has been observed on 29-04-2023 at Desang river left bank from Bhagarh to
		AT Road & AT road to Akhoiphutia Ghat at Dowari Gaon under Sivasagar Revenue Circle. The report
		received from WR Sivasagar Div (94.4151 E, .27.23 N) 4. The sloughing and river bank erosion has been
		observed on 29-04-2023 at Desang river left bank from Bhagarh to AT Road & AT road to Akhoiphutia Ghat
		at Kuwamora Satra under Sivasagar Revenue Circle. The report received from WR Sivasagar Div (94.406 E,
		27.155N)   0   (Long - 94.469094, Lat - 27.011937)
		Thelamara - Village- Kalakuchi   Date-23/06/2023, As reported by Water Resource Division Tezpur on
	Conitmum	23/06/2023, Bank erosion is observed at Kalakuchi(Ch 200m to 350m) on the R/Bank of river Gabharu since
	Sonitpur	
		22/06/2023. Latitude-26.746466 and Longitude-92.616082   0   (Long - 92.616082, Lat - 26.746466)
	South Salmara	Mankachar - Nepurer Alga   As per report received from the Gaon Pradhan, erosion is going on in revenue
		village Nepurer Alga by the river Brahmaputra. 6 Nos. of temporary house hold from Nepurer Alga are shifted
		to other safe place for this purpose, 2 Nos. of engine Boat deployed on 23-06-2023.   76   (Long - 25.747482,
	Tamulpur	Lat - 89.843548)
		<b>Tamulpur</b> - 1.kuliakur & 2. Kalbari of Soil Dept   1.Breaching of RCC Check bund 100 metre at Village
		Kuliakur on 22 june 2023 2. Breaching of water harvesting structure and water distribution project at vill-
		Kalbari on 22 june 2023   0   (Long - 91.558741, Lat - 26.665193)
	Udalguri	Harisinga - 1. Uttar jungle Para 2. Merbangchuba   (1) Due to heavy rainfall on 22nd June 2023 erosion
		continuing at Uttar jangalpara village by Huduma river. Approximate damage 200meter. Lat:26.6567 Long
		91.9365. (2) Due to continuous rainfall on 22nd June 2023 erosion occurred at Merbangchuba village by
		Bhotia river. Approximate damage 70 meters. Lat 26.7167 Long 91.9643   0   (Long - 0.000000, Lat -
		0.000000)
Landslide	District/Sub -division*	Details
		Badarpur - Rabbania Pt-2 under Anglarbazar GP   Yesterday i.e. on 22-06-2023 at about 12:30 PM, a
	Wi	landslide incident has taken place at Rabbania Pt-2 under Anglarbazar GP resulting 04 nos of houses got
	Karimganj	affected. GR and tarpaulin is being provided as an immediate assistance   18   (Long - 92.542036, Lat -
		24.780988)
Urban Flood	District/Sub	Details
	-division*	<b>Dalgaon</b> - Kharupetia Town(Ward No-1)   Water logging at kharupetia town (ward no.1) under dalgaon
	Darrang	revenue circle. Dated 23-06-2023.   100   (Long - 92.149805, Lat - 26.519547)
	Kokrajhar	<b>Dotma</b> - Fakiragram MB   Dated: 23/06/2023 Waterlogging at ward no1 and ward no3 due to inccessant
		rainfall.   520   (Long - 0.000000, Lat - 0.000000),
		Kokrajhar - Ward No. 1 to 3   DUE TO INCESSANT RAINFALL FROM 12.06.2023, WATER LOGGED
		AT KOKRAJHAR URBAN AREA VIDE WARD NO. 1 TO 3, dated-22/06/2023   9367   (Long - 0.000000,
	1	Lat - 0.000000)
		*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)