

FRIMS Assam



Flood Reporting And Information Management System

	Assam Daily Flood Report as on 06-07-2023 at 4:00 PM										
Particulars	Situation as o				-						
Rivers flowing above Danger	Rivers flowir	ng above d	langer	Nil							
Level (as per CWC bulletin issued at 8 AM)	Rivers flowir flood level	ng above h	ighest	Nil							
District/Su b-division Affected	No. of Districts/S ub- divisions* Affected	Districts	s/Sub-div	Flood Affected /Sub-divisions* Name of Urban Flood Districts/Sub-divisions*							
	6		Biswanath , Lakhim	, Dhemaji, pur	Jorhat,						
No. Of Revenue Circles Affected	12										
	District/Su b-division*	Total		ie Circle							
Name Of	Bajali	1	Sarupet								
Revenue	Biswanath	2		Gohpur							
Circles	Dhemaji	2		rgaon, Dhe	maji						
Affected	Jorhat	2		Jorhat East, Teok							
	Kamrup	2	North Ghy, Hajo								
	Lakhimpur	3	Bihpuria, Kadam, Narayanpur								
	Total	12									
	District/Su b-division*	Total	Revenue Circle								
	Bajali	1	(Sarupeta 1)								
Villages	Biswanath	8	(Halem 6), (Gohpur 2)								
Affected	Dhemaji	6	(Sissiborgaon 2), (Dhemaji 4)								
	Jorhat	5	(Jorhat East 3), (Teok 2)								
	Kamrup	36	(North Ghy 6), (Hajo 30)								
	Lakhimpur	15	(Bihpuria 5), (Kadam 2), (Narayanpur 8)								
	Total	71			Total		Cwon				
	District/Su b-division*	Male	Fema le	Childr en	Populati on	Population Details	Crop Area (in Hect.)	Crop Area Details			
	Bajali	30	22	6	58	(Sarupeta 58)	0.00	(Sarupeta 0.00)			
	Biswanath	0	0	0	0	(Halem 0), (Gohpur 0)	52.00	(Halem 11.00), (Gohpur 41.00)			
Population And Crop Area Affacted	Dhemaji	1141	998	380	2519	(Sissiborgaon 1372), (Dhemaji 1147)	58.00	(Sissiborgaon 40.00), (Dhemaji 18.00)			
Affected	Jorhat	207	187	178	572	(Jorhat East 0), (Teok 572)	5.50	(Jorhat East 5.50), (Teok 0.00)			
	Kamrup	0	0	0	0	(North Ghy 0), (Hajo 0)	125.00	(North Ghy 5.00), (Hajo 120.00)			
	Lakhimpur	604	488	903	1995	(Bihpuria 0), (Kadam 1995), (74.90	(Bihpuria 60.00), (Kadam 0.00), (

						Narayanpur 0)			Narayanpur 14.90)			
	Total	1982	1695	1467	5144			315.40				
Relief	District/Su b-division*	Total	Relief (Camp			Relief Distribution Centres					
Camps /	Dhemaji	2	0(Dhen	0(Dhemaji 0)				2(Dhemaji 2)				
Centres Opened	Lakhimpur	1	1(Kadam 1)				0(Kadam 0)					
Opened	Total	3	1				2					
Inmates In Relief	District/Su b-division*	Total	Revenu	ie Circlew	ise	Male	Female	Children	Pregnant / Lactatin g Mother	Person with Disabili ty		
Camps	Lakhimpur	15		ria 0), (Na dam 15)	rayanpur	4	8	3	0	0		
	Total	15				4	8	3	0	0		
Human Lives Lost - Confirmed Human	Nil											
Lives Lost Confirmed - Death Type Human	Nil											
Lives Lost - Missing	Nil											
Human Lives Lost Missing - Type	Nil											
	District/Su	Total	Big	Small	Poultry							
	b-division*		Ü		· ·							
	Bajali	17	12	5	0							
Animals	Biswanath	2300	1700	600	0							
Affected	Dhemaji	1020	431	378	211							
	Kamrup	3950 4788	3850 2804	100 1984	0							
	Lakhimpur Total	12075	2804 8797	3067	211							
Animals	District/Su b-division*	Total	Big	Small	Poultry							
Washed Away	Lakhimpur	1	0	1	0							
Away	Total	1	0	1	0							
Houses Damaged	Nil											
Rescue Operation	District/Su b-division*	Agency			Boats Deploye d	Person Evacuat ed By Boats	Animal Evacuat ed By Boats	Helicopt ers Deployed	Person Evacuate d By Helicopt ers	Medica l Team Deploy ed		
	Dhemaji	SDRF			1	23	0	0	0	0		
	Lakhimpur		Fire & Emergency Services (F&ES)			38	0	0	0	2		
	Total				2	61	0	0	0	2		
Relief Distributed	District/Su b-division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)		d - Rice Bra	n (in Q)		
	Dhemaji Total	14.55 14.55	2.54 2.54	0.76 0.76	76.23 76.23	0.00 0.00	0.00 0.00	0.00 0.00				

Relief	Dictrict/G	Dob- E	204		
Distributed	District/Su b-division*	Baby Fo	ooa	Baby Food Solid	Others
Others	Dhemaji	0.00-Q		0.00-Q	
Infrastruct ure Damaged - Embankm ent	Nil	, -			
Breached					
Infrastruct ure	District/Su b-division*	Numb er	Details		
Damaged - Embankm ent	Nagaon	1	Nelipar	eroded length- 260m	L/B OF KAPILI FROM CHARAIHAGI TO TUKLAITUP neter (Bank Erosion, offset from embankment 140 meter) 3 (Long - 26.115209, Lat - 92.311945, Dept - BRO)
Affected	Total	1			
	District/Su b-division*	Numb er	Details		
Infrastruct ure Damaged - Road	Dhubri	11	BHAIB 26.2690 receive 89.8183 SIDE B JINKA 26.2493 receive 89.7478 SIDE B SONAI 26.2193 receive 89.7482 26.2313 conduct SIDE B AGOM 1ST, 2N LONGI 26/06/2 Lat - 26 SIDE B LOWD 89.7823 26.2618 conduct ROAD PROGO 5TH KI 89.8053 field ve 26.2152 SIDE B TALLI LATIT on the r 06/07/2 SIDE B KATHAL LONGI	AZAR ROAD AT 1S' 574 LONGITUTE: 8 d on 27/06/2023 a field 371, Lat - 26.269674, I EERM & SIDE SLOPE TA AT 1ST KM AND 563 LONGITUTE: 8 d on 27/06/2023 a field 859, Lat - 26.249563, I EERM & SIDE SLOPE KHULI ROAD AT 1S' 693 LONGITUTE: 8 d on 27/06/2023 a field 259, Lat - 26.219393, I EERM DAMAGED ON 41 & LATITUDE: 26. 165 Based on the reported on 06/07/2023. (I EERM & SIDE SLOPE CONI CIRCLE OFFICE ND & 4TH KM (LONGITUTE: 89.796114 & 1023 a field verification 15.207975, Dept - PWD 16.207975, Dept - PWD 16.207975, Dept - PWD 16.207975, Dept - PWD 16.207979999999999999999999999999999999999	ES DAMAGED ON ROAD FROM KGT ROAD TO 2 2ND KM LONGITUTE: 89.747859 & LATITUDE: 9.747859 & LATITUDE: 26.249563 Based on the report diverification has been conducted on 06/07/2023. (Long-Dept - PWD (Roads)), ES DAMAGED ON ROAD FROM NH17 TO TKM LONGITUTE: 89.790259 & LATITUDE: 9.790259 & LATITUDE: 9.790259 & LATITUDE: 26.219393 Based on the report diverification has been conducted on 06/07/2023. (Long-Dept - PWD (Roads)), NKGT ROAD TO JINKATA AT 6TH KM LONGITUTE: 231165 LONGITUTE: 89.74841 & LATITUDE: ort received on 27/06/2023 a field verification has been long - 89.748410, Lat - 26.231165, Dept - PWD (Roads)), ES AND RCC BRIDGE APPROACHES DAMAGED ON ETO KALDOBA PT-I VIA CHARAKBARI ROAD AT GITUTE: 89.796114 & LATITUDE: 26.207975 LATITUDE: 26.207975 Based on the report received on a has been conducted on 06/07/2023. (Long - 89.796114, or (Roads)), ES DAMAGED ON HALAKURA KATHALTOLI TO HAN MANDIR AT 1ST, 2ND & 3RD KM LONGITUTE: ort received on 26/06/2023 a field verification has been long - 89.782139, Lat - 26.261876, Dept - PWD (Roads)), BERM & SIDE SHOULDER DAMAGED ON NH-31 AT HANGADULI VIA CHIKARGHAT AT 1ST, 2ND, 4TH & 805166 & LATITUDE: 26.215248 LONGITUTE: 6.215248 Based on the report received on 26/06/2023 a nducted on 06/07/2023. (Long - 89.805166, Lat -

	T	T	1. 1. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.						
			has been conducted on 06/07/2023. (Long - 89.784431, Lat - 26.265244, Dept - PWD						
			(Roads)), SIDE BERM & SIDE SLOPES DAMAGED ON KGT ROAD AT KALDOBA TO						
			SUPARIKUTI AT 1ST, 2ND & 3RD KM LONGITUTE : 89.761318 & LATITUDE :						
			26.222116 LONGITUTE : 89.761318 & LATITUDE : 26.222116 Based on the report						
			received on 26/06/2023 a field verification has been conducted on 06/07/2023. (Long -						
			89.761318, Lat - 26.222116, Dept - PWD (Roads)),						
			SIDE BERM & SIDE SLOPES DAMAGED ON KGT ROAD TO GHARIALDANGA						
			AT 1ST KM, 2ND KM & 4TH KM LONGITUTE: 89.756872 & LATITUDE:						
			26.229841 LONGITUTE : 89.756872 & LATITUDE : 26.229841 Based on the report						
			received on 26/06/2023 a field verification has been conducted on 06/07/2023. (Long - 89.756872, Lat - 26.229841, Dept - PWD (Roads))						
			Bagribari - NH-31 to Jangirkilla Pt-I Jangirkilla Pt-I. from Ch.0.00 M to Ch. 1087.00 M						
	Kokrajhar	1	As reported by Executive Engineer PWD Bilasipara Civil Sub-Division Territorial Road						
	3		Division Bilasipara on 04/07/2023, construction of the road has been affected due to 1st						
			Wave of Flood. (Long - 90.090527, Lat - 26.186460, Dept - PWD (Roads)) Bihpuria - Baligaon-Joriguri road Ch 0.00 m to Ch 400.00 m Baligaon-Joriguri road						
			affected by flood water of Gabharu river as reported by PWRD, Nowboicha Territorial						
			Road Sub Division on 06/07/2023 (Long - 93.905500, Lat - 27.141000, Dept - PWD						
			(Roads)),						
	Lakhimana	3	Narayanpur - Today i.e july 6 2023 Rangati Dhemagarh Balipathar Road eroded at CH						
	Lakhimpur	3	400m Total Damage length-20 m Breadth -2.60 m depth-2.40 m At chainage 440 total						
			damaged length-10 m Breath-1.5 m and depth -2.40 m as per report from PWD road						
			division No.2 Rangati (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),						
			250 m CC Road with 1 nos RCC culvert and 1 Nos HP culvert. No 2 Rangati (Long - 0.000000, Lat - 0.000000, Dept - P&RD)						
	Total	15	0.000000, Lat - 0.000000, Dept - P&RD)						
Infrastruct	Total	15							
ure Damaged -	Nil								
Bridge Infrastruct									
ure									
Damaged -	Nil								
Wildlife									
	District/Su b-division*	Other Details							
	Baksa	authority	ara - Agri Bundh Damaged As per report received on 05/07/2023 from concerned y BDO dhamdhama block and WR department on 25/06/2023 ,80 meter approx reach length dh have been damaged at village Adla/simlabari area.(26.69256,91.440569)),						
		Agri Bundh Damaged As per report received on 05/07/2023 from BDO dhamdhama block on							
		25/06/2023 agri bundh approx 30 meter reach length have been damaged at Bagulamari							
			26.683148,91.429719))						
		_	- Public Health Engineering (PHE) As per report received from The Executive Engineer						
	Barpeta	(PHE), Barpeta Division, Barpeta and Junior Engineer (PHE), Bahari Division on 05/07/2023, 04							
Infrastruct			HTW installed at various raised platforms under Barpeta Rev. Circle						
ure	Lakhimpur	_	a - Culvert Damaged Damaged slab Culvert at Ch. 1700m of Bahbari Tunijan to Gabharu						
Damaged -		Tunijan road as reported by PWRD, Nowboicha Territorial Road Sub Division on 06/07/2023, Culvert Approach Road Damaged Approximately 60 meters of Culvert approach road damaged at							
Others		Gabharu Tunijan due to the affect of Gabharu river (Uttar Laluk GP) under Karunabari							
		Development Block on 06/07/2023,							
		Fisheries/Pond 25 nos. Ponds (2.5 ha) affected at Gabharu Tunijan, Rangajan as reported by FDO,							
		Karunabari Circle on 06/07/2023,							
		Agri Bundh Damaged Approximately 300 meters of the bundh under MGNREGA scheme at Anil							
		Morang Chuburi damaged as reported by officials of Karunabari Development Block on 06/07/2023,							
			- Fisheries/Pond Due to incessant rain and raising of water level of the River kakoi total 8						
			of water area got affected, reported by Fishery Officer, dated 06/07/2023,						
		hectare o	npur - Culvert Approach Road Damaged Damaged of RCC culvert slab and approach at						
		hectare of Narayan chainage	· · · · · · · · · · · · · · · · · · ·						

	Udalguri	Khairabari - Culvert Damaged As reported by the department on 04.07.2023, due to incessant rainfall for last few days the slab culvert measuring 3.0M approx. on Jalukbari Chowk to Banderi village was damaged. GPS Coordinates: Lat: 26.58589 Long.: 91.87753
	District/Su b-division*	Details
Erosion	Biswanath	Gohpur - At Dakhin Deonabari Bank erosion is oberserved on R/B of river Solengi for a length of 30 mtr on 06/07/23 0 (Long - 93.642885, Lat - 26.910851)
	Cachar	Katigorah - Kunapara T.E. to Sindura XI As reported by PWD Borkhola-Katigorah (T) Road Division and as per field inspection by Circle Officer Katigorah Revenue Circle along with Field Officer (DM) and AEE, CID (W.R) Div. Badarpur, it was observed that the Kunapara T.E. to Sindura XI PMGSY road is under the severe threat of erosion because of river larang which is flowing adjacent to it. An area of 250 mts (approx) has been severely eroding and if it continues the road connectivity will be closed. Severe erosion has been observed at the stretch since 01.07.2023 to still today i.e. 06.07.2023 15000 (Long - 24.583739, Lat - 92.321867)
	Dhemaji	Sissiborgaon - At No.1 Sunarighat (Rev. Village) The Brahmaputra floods have caused erosion in No.1 Sunarghat. None of the houses have been washed away by the erosion so far. The area of the landslide is about 40 bighas (As per Lot Mondal reported).dated 05-07-2023 317 (Long - 94.782028, Lat - 27.501328)
	Dhubri	Dhubri - Aminerchar Erosion is going on (by the river Brahmaputra) at village Aminerchar As per the field verification w.e.f 30/06/23 to 05/07/23 it is seen that till now 36 nos of family has been affected (total area = 20Bigha-1Katha-5Lessa) 214 (Long - 89.928875, Lat - 25.987545), Agamoni - village Lohajani Riverine area of River Gangadhar at village Lohajani under Boterhat GP under Agomani Revenue Circle is getting eroded day by day. The detail of the area eroded is given below for your kind perusal: • Name of the village: Lohajani under Boterhat GP. • Date of Incident: 30th June'2023 to 6th July'2023. • Time: 3.00 PM. • GPS Co-ordinates: Lat: 26.254122, Long: 89.834342 • Land: 0B-1K-5L. • Population and household damage: NIL 0 (Long - 89.834342, Lat - 26.254122), Bilasipara - Sinamari, under Bilasipara Revenue Circle recently erosion has taken place by the river Gaurang at village: Sinamari, under Bilasipara Revenue Circle. A field visit in this connection has been done on 06-07-2023 by me along with Field Officer, Disaster Management, Bilasipara. The detail of the area is given below for your kind perusal: • Name of Village:- Sinamari. • Date of incident:- 03-07-2023 to 06-07-2023 • GPS co-ordinates:- Lat:- 26.296915 N & Long:- 90.23658 E Lat:- 26.296873 N & Long:- 90.236552 E • Land eroded:- Land measuring around :- 01 Bigha 02 Katha 10 Lessa. • Population:- 18 No's (3 No's of families) 18 (Long - 90.236580, Lat - 26.296915)
	Kamrup	Kamalpur - Gathijan area on L/B of Puthimari Embankment Active erosion seen at Gathijan area on L/B of Puthimari River Embankment. Reach is about 500m and width is about 3m. Reported by AEE, Rangia-Kamalpur WR Sub-Division on 05.07.2023. 0 (Long - 91.382111, Lat - 26.187470)
	Kokrajhar	Bhawraguri - Badlagaon As per report received from Section Officer, Gossaigaon WR Sub Division on dated 06-07-2023. 1. Bank Erosion Observed at Badlagaon on R/B of Gangiya River (Length- 450M). 0 (Long - 90.099700, Lat - 26.361800)
	Nalbari	Nalbari - Sandha As per the report received from Water Resource department on 05,07.2023, erosion takes place on L/B of pagaldia embankment at Sandha village 0 (Long - 0.000000, Lat - 0.000000)
	South Salmara	Mankachar - Jordanaga Barmanpara, Mankachar As per report received from I/C Control Room Hatsingimari W.R Sub-Division, Hatsingimari an erosion due to River Kaloo at Jordanga Barmanpara, Mankachar, land measuring Length-200M, Breadth-5M on 06-07-2023. 0 (Long - 25.544958, Lat - 89.872199)
Landslide	Nil	
Urban Flood	Nil	
		*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)