

FRIMS Assam



Flood Reporting And Information Management System

		Ass	sam Daily I	Flood Report	as on 02-07-20	023 at 4:	00 PM				
Particulars	Situation as on (02-07-2023	(in last 24	hours)							
Rivers flowing	Rivers flowing a	above dange	er level	Nil							
above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing a level	above highe	ood Nil								
District/Sub- division Affected	No. of Districts/Sub- divisions* Affected	divisions*					Name of Urban Flood Districts/Sub-divisions*				
	5	Bajalı, Dr Kokrajhaı		aghat, Kamr	up,						
No. Of Revenue Circles Affected	9										
	District/Sub- division*	Total	Revenue	Circle							
Name Of	Bajali	1	Sarupeta								
Revenue	Dhemaji	2		, Sissiborgao	n						
Circles	Golaghat	1	Dergaon								
Affected	Kamrup	3		ny, Hajo, Kai	nalpur						
	Kokrajhar	2	Kokrajha	ır, Dotma							
	Total	9									
	District/Sub- division*	Total		Revenue Circle							
	Bajali	1		(Sarupeta 1)							
Villages	Dhemaji	3			iborgaon 2)						
Affected	Golaghat	6	(Dergao								
	Kamrup	83			ajo 60), (Kar	nalpur	17)				
	Kokrajhar	2	(Kokraji	(Kokrajhar 1), (Dotma 1)							
	Total	95		1	ı	1			<u> </u>		
	District/Sub- division*	Male	Female	Children	Total Population	Population Details		Crop Area (in Hect.)	Crop Area Details		
	Bajali	30	22	6	58		oeta 58)	4.00	(Sarupeta	4.00)	
Population	Dhemaji	526	527	226	1279	(Dhemaji 644), (Sissiborgaon 635)		44.00	(Dhemaji 4.00), (Sissiborgaon 40.00)		
And Crop Area Affected	Golaghat	0	0	0	0	(Derg	aon 0)	12.10	(Dergaon	12.10)	
Area Affected	Kamrup	2	2	4	8	(North Ghy 8), (Hajo 0), (Kamalpur 0)		522.90	(North Ghy 10.50), (Hajo 485.00), (Kamalpur 27.40)		
	Kokrajhar	73	60	41	174	(Kokrajhar 113), (Dotma 61)		0.00	(Kokrajhar 0.00), (Dotma 0.00)		
	Total	631	611 277 1519			583.00					
Relief Camps	District/Sub- division*	Total	Relief Ca	amp			Relief Di	stribution (ibution Centres		
/ Centres	Kamrup	1	1(North Ghy 1)			0(North Ghy 0)					
Opened	Kokrajhar	1	1(Kokrajhar 1)			0(Kokrajhar 0)					
	Total	2	2				0				
Inmates In Relief Camps	District/Sub- division*	Total	Revenue	· Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disability	

	Kamrup	8	(Hajo 0 Ghy 8)), (Kamalpui	r 0), (North	2	2	4	0	0
	Kokrajhar	113	(Kokrajh	ar 113)		41	34	33	5	0
Human Lives	Total	121				43	36	37	5	0
Lost - Confirmed	Nil									
Human Lives Lost Confirmed - Death Type	Nil									
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
	District/Sub- division*	Total	Big	Small	Poultry					
Animals	Bajali	17	12	5	0					
Affected	Dhemaji	180	80	55	45					
	Kamrup Total	4550 4747	4450 4542	100 160	0 45					
Animals	Total	7/4/	4344	100	43					
Washed Away	Nil									
Houses Damaged	Nil									
Rescue Operation	Nil									
Relief Distributed	Nil									
Relief Distributed Others	Nil									
Infrastructure Damaged - Embankment Breached	Nil									
Infrastructure Damaged - Embankments	Nil									
Affected	District/Sub-	Number	Details							
l	division*	Number								
Infrastructure Damaged - Road	Barpeta	20	embankn stretches Rev Circ PWD(Ro (Roads)) Rajakhat Long- 91 received PWD (Ro Hathinap submerge Under Sa report red Dept - Po Hathinap embankn Sartheba PWD(Ro (Roads)) Mohanba approach	nent eroded lands. Side berms le) Mohan load) Dept on loads. Barsimla Ro loads), but to Rajakh led by river Karthebari Reviceived from WD (Roads) but to Rajaka lent eroded lari Rev. circle load) Dept on loads on both sides on both si	Bazar to Kayal by the river Pal heavily damag Bazar to Kayak 01/07/2023 (1/2) ad (MDR) sub Sarthebari Rev Road) Dept on the tat Barsimla via Kaldia. Side ber Circle) Hath PWD(Road) D), ht Barsimla (PM) by river Kaldia b) Hathinapur 01/07/2023 (1/2) andha PMGSY tides damaged b. 130792, under	humara ged. (Lat kuchiGa Long - 9 merged. v. Circle 01/07/2 Kawain ms heav inapur t ept on 0 MGSY c at 6th H to Rajal Long - 9 ' comple by river	at 1st& 3rd t- 26.42555 on road A pl.096309, Road surfa pl Rajakha pl Rajakha pl Rajakha pl Rajakhatl	KM. (PMG: 4,Long- 91.0 s per report i Lat - 26.425. cee badly dar tBarsimla Rog - 91.131500 SY Completed. (Lat- 26.43arsimla via (Long - 91. oad- PKg. N 6.43434, Long As per re Lat - 26.434. ckg No- AS-0 ide berms he	SY Complete 196309, under 1963	ed road) in er Sarthebari n PWD 26.4665, As per report 66500, Dept - AS-01-516) g- 91.14652, As per - 26.430367, 9) road 35, under d from PWD

per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.130792, Lat - 26.429038, Dept - PWD (Roads)),

T-02 Kawaimari 7 No Block (PMGSY completed-Pkg No-AS-01-197) side berms heavily damaged in stretches (Lat- 26.391227, Long- 91.169056, in Sarthebari Rev Circle) | T-02 Kawaimari 7 No Block | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.169056, Lat - 26.391227, Dept - PWD (Roads)),

 $T02-to\ Nalirpam\ (PMGSY\ Completed-\ Pkg\ No-AS-01-304)\ road\ submerged\ and\ side\ berms\ heavily\ damaged\ in\ strecches\ (Lat-\ 26.393471,\ Long-\ 91.126938,\ Under\ Sarthebari\ Rev\ Circle)\ |\ T02-to\ Nalirpam\ |\ As\ per\ report\ received\ from\ PWD(Road)\ Dept\ on\ 01/07/2023\ |\ (Long-\ 91.126938,\ Lat-\ 26.393471,\ Dept-\ PWD\ (Roads)),$

Pithadi to Baithabhanga (PMGSY completed –Pkg No- AS-01-311) road side berms and hard crust severly damaged by river Kaldia. HP Culvert heavily damaged at 2nd KM.(Lat-26.369293, Long- 91.147162, inderSartehbari rev circle) | Pithadi to Baithabhanga | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.147162, Lat - 26.369293, Dept - PWD (Roads)),

Naligaon to Bhaktardoba Bazar (PMGSY Completed road –Pkg No- AS-01-310) road side berms & hard crust heavily damaged in stretches(Lat- 26.399819, Long- 91.121687, under Sarthebari Rev Circle) | Naligaon to Bhaktardoba Bazar | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.121687, Lat - 26.399819, Dept - PWD (Roads)),

Besimari to AgdiaPathar road (PMGSY completed-Pkg No- AS-01-180) road side berms & hard crust heavily damaged. RCC Br No 1/1 approaches eroded. (Lat- 26.31795, Long-91.141982, Under Sarthebari Rev Circle) | Besimari to AgdiaPathar road | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.141982, Lat - 26.317950, Dept - PWD (Roads)).

Chengdi to Byaskuchi road (PMGSY completed- Pkg- AS-01-179) RCC Bridge No 1/1 & 3/1 approaches damaged by river Mora Chaolkhuwa. Side berms & hard crust damaged in streches (Lat- 26.384083, Long- 91.210375, under Sarthebari Rev. Circle) | Chengdi to Byaskuchi road | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.210375, Lat - 26.384083, Dept - PWD (Roads)),

Kawaimari LP School to Balapara (PMGSY completed –Pkg- AS-01-305) road submerged in streches Side berms heavily damaged. (Lat- 26.400481, Long- 91.136189, under Sarthebari Rev Circle) | Kawaimari LP School to Balapara | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.136189, Lat - 26.400481, Dept - PWD (Roads)).

NewlarbhithaSatrapaka via Jabrikuchi road (PMGSY completed- Pkg- AS-01-189) road side berms and hard crust damaged in streches from 1st to 4th KM. RCC BridgeNo 1/1 approaches damaged(Lat- 26.384083, Long-91.187383, under Sarthebari Rev circle) | NewlarbhithaSatrapaka via Jabrikuchi road | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.187383, Lat - 26.384083, Dept - PWD (Roads)),

KapahartariThekargaonBherabhitha road SPT br No 6/1 approaches damaged, side berms of road damaged. (Lat- 26.359072,Long- 91.090791, under Sarthebari Rev circle) | KapahartariThekargaonBherabhitha road | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.090791, Lat - 26.359072, Dept - PWD (Roads)),

Bhaktardoba to Zero bazar via Pithadi road submerged in streches. (lat- 26.365585, Long-91.128182, under Sarthebari Rev Circle) | Bhaktardoba to Zero bazar via Pithadi road | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.128182, Lat - 26.365585, Dept - PWD (Roads)),

RajakahatBarsimla road to KaharparaBesimariKirtanghar road submerged (Lat- 26.466535, Long- 91.131518, under Sarthebari Rev Circle) | RajakahatBarsimla road to KaharparaBesimariKirtanghar road | As per report received from PWD(Road) Dept on

01/07/2023 | (Long - 91.131518, Lat - 26.466535, Dept - PWD (Roads)),

Balapara to Kirkira Road submerged (Lat- 26.430369, Long- 91.14651, under Sarthebri Rev. Circle) | Balapara to Kirkira Road | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.146510, Lat - 26.430369, Dept - PWD (Roads)),

BharegaonHatirtari Road submerged. Road surface badly damaged. (lat- 26.451822, Long-91.113014,under Sarthebari Rev. Circle) | BharegaonHatirtari Road | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.113014, Lat - 26.451822, Dept - PWD (Roads)).

Balapara to Rampur (RajakhatBarsimla Road Segment-2) road surface damaged. (lat-26.423438, Long-91.159143, under Sarthebari Rev Circle). | Balapara to Rampur | As per report received from PWD(Road) Dept on 01/07/2023 | (Long - 91.159143, Lat - 26.423438, Dept - PWD (Roads)),

 $KaharparaBesimariKirtanGhar\ road\ submerged.\ Side\ berms\ damaged\ (Lat-\ 26.466181,\ Long-\ 91.132509,\ under\ SarthebariRevCircle).\ |\ KaharparaBesimariKirtanGhar\ road\ |\ As\ per\ report\ received\ from\ PWD(Road)\ Dept\ on\ 01/07/2023\ |\ (Long-\ 91.132509,\ Lat-\ 26.466181,\ Dept-\ PWD\ (Roads))$

	Nalbari	1	Ghograpar - Nizkhagta- burburi road Nizkhagta, Burburi Aa per PWRD report, on 01/07/2023 nizkhagta burburi road surface has been damaged due to flood. Length - 1.10 km (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Total	21	
Infrastructure Damaged - Bridge	Nil		
Infrastructure Damaged - Wildlife	Nil		
	District/Sub- division*	Other D	etails
Infrastructure Damaged - Others	Baksa	Division damage of Damage Irrigation Division Course (of bed ar Irrigation Division Course (of bed ar Irrigation Division Course (of Damage 91.21528 Irrigation Division Course (Damage 91.23559 Irrigation Division Course (Damage Objective Objecti	n Canal/Scheme Damaged As per information received from Executive Engineer, Tihu (Irrigation) Tihu Date of Received-01-07-2023. Date of Occurrence :- 26-06-2023 Water Brick lined) at Chainage 2330.00 M of branch canal-3 of Bhumki FIS. Nature of Damage-of bed and wall of water course at branch canal-3 of Bhumki FIS. Lat-26.699690 Long-

		field to Saudhrvitha village link road. Date of Occurrence-21-06-2023. Lat-26.580944 Long-91.094693.
		Culvert Damaged As per information received from Asstt. Ex Engineer PWD (R &B) Salbari. Date of Received-01-07-2023. Culvert no 0/1 has been damaged at ch-100.00 on Roumari to Amrarabati.Date of Occurrence-21-06-2023. Lat-26.6061 long-91.080994, Bamboo Foot Bridge As per information received from Asstt. Ex. Engineer PWD (R &B) Salbari. Date of receipt-01-07-2023. The foot bridge has been wasted away on the road Ghoramara to Pub-Rajabil
		over River Rupahi. Date of occurrence-Midnight 14-06-2023. lat- 26.670091 long-91.097989
	Dibrugarh	Tingkhong - Culvert Approach Road Damaged As reported by PWD(roads) on 01/07/2023 due to recent heavy rainfall the water level in Longboi Jaan river suddenly raised due to which the road of "Rajgarh T.E to Puwali Pather and culvert face wall are badly affected that cause movement of traffic and pedestrian disrupted. Total Length of Road=100 m, Approx. road damage-100m, Revenue village-3 no. Sepatoli, Date of Occurence-30/6/2023, Lat-27.167084, Long-95.13989
	Kamrup	North Ghy - Irrigation Canal/Scheme Damaged Solar powered DTW Irrigation scheme under SOPD for the year 2021-22 belonging to village Athiaboi and Bonmaza was affected on 01.07.2023 as per report received from AEE, Jalukbari Sub-Div (Irrigation), Amingaon
	Kokrajhar	Bagribari - Irrigation Canal/Scheme Damaged As per reported by AEE, Gossaigaon Sub Division (Irrigation) Gossaigaon on 26.06.2023 report received on 02.07.2023 due to heavy rain Damaged R/S Main Canal Shilai FIS at Village Harjhora, (Kokrajhar) At District - Irrigation Canal/Scheme Damaged As per reported by AEE, Gossaigaon Sub Division (Irrigation) Gossaigaon on 26.06.2023 report received on 02.07.2023 due to heavy rain Damaged Embankment, R/S Afflux Bundh 50.00mtrs. at Kharkhari FIS at Village Thakurpur Pt-II
	Lakhimpur	Kadam - Bamboo Foot Bridge Bamboo foot bridge no 1/1 at 1st KM over Anaighoria jaan damaged due to incessant raining. Road name Rangpuria to Lalpani road. Bridge length 20m reported by PWD (R) department on 02/07/2023
	D1 / 1 / 10 1	
	District/Sub- division*	Details
		Details Kalgachia - Kaurjahi PMGSY Road from Kalgachia to Balaipathar at Kaurjahi village,near Eshab Bazar is badly affected due to ongoing erosion of river Beki, reported by LM on 01.07.2023 0 (Long - 90.894993, Lat - 26.373439)
	division*	Kalgachia - Kaurjahi PMGSY Road from Kalgachia to Balaipathar at Kaurjahi village,near Eshab Bazar is badly affected due to ongoing erosion of river Beki, reported by LM on 01.07.2023 0 (Long -
	division* Barpeta	Kalgachia - Kaurjahi PMGSY Road from Kalgachia to Balaipathar at Kaurjahi village,near Eshab Bazar is badly affected due to ongoing erosion of river Beki, reported by LM on 01.07.2023 0 (Long - 90.894993, Lat - 26.373439) Halem - Paken River Brahmaputra- 1) Mild bank erosion is observed at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length = 10m, on 2/07/2023 0 (Long - 93.628300, Lat - 26.801150), Gohpur - At No.2 Bikrampur area. Mild erosion is observed at R/Bank embankment of river Sessa of
Erosion	division* Barpeta Biswanath	Kalgachia - Kaurjahi PMGSY Road from Kalgachia to Balaipathar at Kaurjahi village,near Eshab Bazar is badly affected due to ongoing erosion of river Beki, reported by LM on 01.07.2023 0 (Long - 90.894993, Lat - 26.373439) Halem - Paken River Brahmaputra- 1) Mild bank erosion is observed at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length = 10m, on 2/07/2023 0 (Long - 93.628300, Lat - 26.801150), Gohpur - At No.2 Bikrampur area. Mild erosion is observed at R/Bank embankment of river Sessa of 60 mtr length on 02/07/2023 0 (Long - 93.726193, Lat - 26.967468) Srijangram - Numberpara, Kacharipetty Dated 01/07/2023, As per WRD Bank erosion on L/B of river Manas at numberpara area for a reach of 1000m and on R/B of river Aie at Kacharipetty area for a reach
Erosion	division* Barpeta Biswanath Bongaigaon	Kalgachia - Kaurjahi PMGSY Road from Kalgachia to Balaipathar at Kaurjahi village,near Eshab Bazar is badly affected due to ongoing erosion of river Beki, reported by LM on 01.07.2023 0 (Long - 90.894993, Lat - 26.373439) Halem - Paken River Brahmaputra- 1) Mild bank erosion is observed at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length = 10m, on 2/07/2023 0 (Long - 93.628300, Lat - 26.801150), Gohpur - At No.2 Bikrampur area. Mild erosion is observed at R/Bank embankment of river Sessa of 60 mtr length on 02/07/2023 0 (Long - 93.726193, Lat - 26.967468) Srijangram - Numberpara, Kacharipetty Dated 01/07/2023, As per WRD Bank erosion on L/B of river Manas at numberpara area for a reach of 1000m and on R/B of river Aie at Kacharipetty area for a reach of 2000M is observed. (26.359629, 90.732508) 0 (Long - 90.814671, Lat - 26.399192) Tingkhong - Revenue village-Disang As reported by WRD on 01/07/2023 erosion occured by Disam river at Bor Disam gaon,Revenue village-Disang,Damage length-30m 0 (Long - 95.125790, Lat -
Erosion	Biswanath Bongaigaon Dibrugarh	Kalgachia - Kaurjahi PMGSY Road from Kalgachia to Balaipathar at Kaurjahi village,near Eshab Bazar is badly affected due to ongoing erosion of river Beki, reported by LM on 01.07.2023 0 (Long - 90.894993, Lat - 26.373439) Halem - Paken River Brahmaputra- 1) Mild bank erosion is observed at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length = 10m, on 2/07/2023 0 (Long - 93.628300, Lat - 26.801150), Gohpur - At No.2 Bikrampur area. Mild erosion is observed at R/Bank embankment of river Sessa of 60 mtr length on 02/07/2023 0 (Long - 93.726193, Lat - 26.967468) Srijangram - Numberpara, Kacharipetty Dated 01/07/2023, As per WRD Bank erosion on L/B of river Manas at numberpara area for a reach of 1000m and on R/B of river Aie at Kacharipetty area for a reach of 2000M is observed. (26.359629, 90.732508) 0 (Long - 90.814671, Lat - 26.399192) Tingkhong - Revenue village-Disang As reported by WRD on 01/07/2023 erosion occured by Disam river at Bor Disam gaon,Revenue village-Disang,Damage length-30m 0 (Long - 95.125790, Lat - 27.317816) Sivsagar - 1. Barichuk, 2. Bhatibon Gaon 1.The damaged has been observed in the form of slump down on 30-06-2023 at Left bank embankment of Dikhow river from AT road to Namdung outfall at Barichuk under Sivasagar Revenue Circle. (26.96196, 94.5633) the report received from Water Resources department, Sivasagar 2. The damaged has been observed in the form of slump down on 30-06-2023 at left bank of river Dikhow near Bhatibon gaon under Sivasagar Revenue Circle. (26.9737672, 94.565188) the report received from Water Resources department, Sivasagar 0 (Long - 26.961960, Lat -
Landslide	Biswanath Bongaigaon Dibrugarh Sivasagar	Kalgachia - Kaurjahi PMGSY Road from Kalgachia to Balaipathar at Kaurjahi village,near Eshab Bazar is badly affected due to ongoing erosion of river Beki, reported by LM on 01.07.2023 0 (Long - 90.894993, Lat - 26.373439) Halem - Paken River Brahmaputra- 1) Mild bank erosion is observed at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length = 10m, on 2/07/2023 0 (Long - 93.628300, Lat - 26.801150), Gohpur - At No.2 Bikrampur area. Mild erosion is observed at R/Bank embankment of river Sessa of 60 mtr length on 02/07/2023 0 (Long - 93.726193, Lat - 26.967468) Srijangram - Numberpara, Kacharipetty Dated 01/07/2023, As per WRD Bank erosion on L/B of river Manas at numberpara area for a reach of 1000m and on R/B of river Aie at Kacharipetty area for a reach of 2000M is observed. (26.359629, 90.732508) 0 (Long - 90.814671, Lat - 26.399192) Tingkhong - Revenue village-Disang As reported by WRD on 01/07/2023 erosion occured by Disam river at Bor Disam gaon,Revenue village-Disang,Damage length-30m 0 (Long - 95.125790, Lat - 27.317816) Sivsagar - 1. Barichuk, 2. Bhatibon Gaon 1.The damaged has been observed in the form of slump down on 30-06-2023 at Left bank embankment of Dikhow river from AT road to Namdung outfall at Barichuk under Sivasagar Revenue Circle. (26.96196, 94.5633) the report received from Water Resources department, Sivasagar 2. The damaged has been observed in the form of slump down on 30-06-2023 at left bank of river Dikhow near Bhatibon gaon under Sivasagar Revenue Circle. (26.9737672, 94.565188) the report received from Water Resources department, Sivasagar 0 (Long - 26.961960, Lat - 94.563300) Thelamara - Baligaon Bangaligaon Date-02/07/2023, As reported by Tezpur Water Resource Tezpur Division on 02/07/2023 Bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri, Length = 200.00m, Latitude : 26.736022, Longitude: 92.558699 0 (Long - 92.558699, Lat
	Biswanath Bongaigaon Dibrugarh Sivasagar	Kalgachia - Kaurjahi PMGSY Road from Kalgachia to Balaipathar at Kaurjahi village,near Eshab Bazar is badly affected due to ongoing erosion of river Beki, reported by LM on 01.07.2023 0 (Long - 90.894993, Lat - 26.373439) Halem - Paken River Brahmaputra- 1) Mild bank erosion is observed at Paken area of B-dyke from Jamuguri to Kharoi outfall. Length = 10m, on 2/07/2023 0 (Long - 93.628300, Lat - 26.801150), Gohpur - At No.2 Bikrampur area. Mild erosion is observed at R/Bank embankment of river Sessa of 60 mtr length on 02/07/2023 0 (Long - 93.726193, Lat - 26.967468) Srijangram - Numberpara, Kacharipetty Dated 01/07/2023, As per WRD Bank erosion on L/B of river Manas at numberpara area for a reach of 1000m and on R/B of river Aie at Kacharipetty area for a reach of 2000M is observed. (26.359629, 90.732508) 0 (Long - 90.814671, Lat - 26.399192) Tingkhong - Revenue village-Disang As reported by WRD on 01/07/2023 erosion occured by Disam river at Bor Disam gaon,Revenue village-Disang,Damage length-30m 0 (Long - 95.125790, Lat - 27.317816) Sivsagar - 1. Barichuk, 2. Bhatibon Gaon 1.The damaged has been observed in the form of slump down on 30-06-2023 at Left bank embankment of Dikhow river from AT road to Namdung outfall at Barichuk under Sivasagar Revenue Circle. (26.96196, 94.5633) the report received from Water Resources department, Sivasagar 2. The damaged has been observed in the form of slump down on 30-06-2023 at left bank of river Dikhow near Bhatibon gaon under Sivasagar Revenue Circle. (26.9737672, 94.565188) the report received from Water Resources department, Sivasagar 0 (Long - 26.961960, Lat - 94.563300) Thelamara - Baligaon Bangaligaon Date-02/07/2023, As reported by Tezpur Water Resource Tezpur Division on 02/07/2023 Bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri, Length = 200.00m, Latitude : 26.736022, Longitude: 92.558699 0 (Long - 92.558699, Lat