

FRIMS Assam



Flood Reporting And Information Management System

	Assam Daily Flood Report as on 30-06-2023 at 4:00 PM										
Particulars	Situation as on	30-06-202									
Rivers flowing above Danger	Rivers flowing above danger level				Nil						
Level (as per CWC bulletin issued at 8 AM)	Rivers flowing	above high	nest flood	level	Nil						
District/Sub -division	No. of Districts/Su b-divisions* Affected	Name of divisions		ected Dist	tricts/Sub- Name of Urban Flood Districts/Sub-divisions*						
Affected	7		arpeta, Go Lakhimpu		laghat, Jorhat,						
No. Of Revenue Circles Affected	13										
	District/Sub -division*	Total	Revenue	e Circle							
	Bajali	2	Sarupeta, Bajali								
Name Of	Barpeta	3	Chenga, Barpeta, Sarthebari								
Revenue	Goalpara	1	Rongjuli								
Circles	Golaghat	1	Dergaon								
Affected	Jorhat	2	Teok, Jorhat West								
	Kamrup	3	North Ghy, Kamalpur, Hajo								
	Lakhimpur	1	Nowboicha								
	Total	13									
	District/Sub -division*	Total	Revenue Circle								
	Bajali	15	(Sarupeta 1), (Bajali 14)								
	Barpeta	9	_		rpeta 3), (Sa	rthebari 4)					
Villages	Goalpara	2	(Rongju								
Affected	Golaghat	3	(Dergao								
	Jorhat	6	(Teok 2), (Jorhat West 4)								
	Kamrup	116	(North Ghy 6), (Kamalpur 33), (Hajo 77)								
	Lakhimpur	7	(Nowboicha 7)								
	Total 158							La	T		
	District/Sub -division*	Male	Femal e	Childre n	Populatio n	Population 1	Details	Crop Area (in Hect.)	Crop Area Details		
	Bajali	1678	1604	318	3600	(Sarupeta 58), (Bajali 3542)		19.00	(Sarupeta 8.00), (Bajali 11.00)		
Population And Crop Area Affected	Barpeta	2180	1718	629	4527	(Chenga 113), (Barpeta 1156), (Sarthebari 3258)		4.00	(Chenga 2.00), (Barpeta 0.00), (Sarthebari 2.00)		
	Goalpara	0	0	0	0	(Rongjuli 0)		3.00	(Rongjuli 3.00)		
	Golaghat	0	0	0	0	(Dergaon 0)		9.70	(Dergaon 9.70)		
	Jorhat	0	0	0	0	(Teok 0), (Jorhat West 0)		12.90	(Teok 4.90), (Jorhat West 8.00)		
	Kamrup	2	2	4	8	(North Ghy 8), (Kamalpur 0), (Hajo 0)		1065.13	(North Ghy 10.50), (Kamalpur 66.63), (Hajo 988.00)		
	Lakhimpur	5565	5564	392	11521	(Nowboicha 11521)		0.00	(Nowboicha 0.00)		
	Total	9425	8888	1343	19656			1113.73			
Relief Camps /	District/Sub -division*	Total	Relief C	amp			Relief Dist	ribution Cent	tres		

Centres	Kamrup	1		North Ghy 1) 0(North Ghy 0)						
Opened	Lakhimpur	5	`	oicha 0)			5(Nowboicha 5)			
	Total	6	1				5			_
Inmates In Relief	District/Sub -division*	Total	Revenue	e Circlewise)	Male	Female	Children	Pregnant / Lactating Mother	Person with Disability
Camps	Kamrup	8	(Kamalpur 0), (Hajo 0), (North Ghy 8)			2	2	4	0	0
	Total	8				2	2	4	0	0
Human Lives Lost - Confirmed Human	Nil									
Lives Lost Confirmed - Death Type	Nil	1								
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
	District/Sub -division*	Total	Big	Small	Poultry					
Animals	Bajali	2499	1136	977	386					
Affected	Barpeta	5488	2641	1452	1395					
	Kamrup	22185	18518	3667	0					
	Total	30172	22295	6096	1781					
Animals Washed Away	Nil									
Houses	District/Sub -division*	Fully Kucch a	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
Damaged	Bajali	5	1	6	401	1	402	0	5	5
	Kamrup	0	0	0	1	0	1	0	0	0
	Total	5	1	6	402	1	403	0	5	5
Rescue Operation	District/Sub -division*	Agency			Boats Deployed	Person Evacuate d By Boats	Animal Evacuate d By Boats	Helicopte rs Deployed	Person Evacuate d By Helicopte rs	Medical Team Deploye d
	Kamrup				0	0	0	0	0	1
Relief Distributed	Total District/Sub	Rice	Dal	Salt (in	M. Oil (in	Cattle Feed - Green	Cattle Feed - Wheat	Cattle Feed - Rice Bran (in Q)		
	-division* Lakhimpur	(in Q) 189.00	(in Q) 34.56	Q) 10.37	L) 1037.00	Fooder (in Q) 0.00	Bran (in Q)			
	Total	189.00	34.56	10.37	1037.00	0.00	0.00	0.00		
Relief Distributed	District/Sub -division*	Baby Foo		Baby Foo		Others		0.00		
Others	Lakhimpur	0.00-Q		0.00-Q						
Infrastructur e Damaged . Embankme nt Breached	Nil									
Infrastructur e Damaged	District/Sub -division*	Numbe r	Details							
e Damaged - Embankme nt Affected	Nalbari Banekuchi - Road cum embankment along right bank Nadla Drainage Channel Nakerbari (Kaithalkuchi Village) On 21/06/2023 Seepage and boiling occurs on road cum embankment alright bank Nadla Drainage Channel at ch.800.00M of Nakerbari, report from PWRD Department (Long - 0.000000, Lat - 0.000000, Dept - BRO)					ment along				

	Total	1	
	District/Sub	Numbe	Details
	-division*	r	Baghbar - 1254 No Paharpur LPS to Bhairarpam chariali Pkg No.As-01-350 Bhairarpam area As
Infrastructur e Damaged - Road	Barpeta	12	Baghbar - 1234 No Pahappur LPS to Bhararapam charali Pkg No. As-01-350 [Bhararapam area As report received from PWD(Roads) dept on 3006/23, 1254 no Pahaprur LPS to Bhararapam charali road Pkg no As-01-350 (road submerged from ch 650.00 m to 2250.00 m partially, shoulder & hard crust damage at streatches & one breach occurrence - 25/06/23. [(Long - 91.006214, Lat - 26.29643, Long.) 1,006214, Date of occurrence - 25/06/23. [(Long - 91.006214, Lat - 26.29643, Dept - PWD (Roads)). Milijuil Bazar to Allengi Pulhar road Pkg No. As-01-236 [Satrakanara 15 no seat area As report received from PWD(Roads) dept on 3006/23, Milijuil Bazar to Allengi Pulhar road Pkg no As-01-236 (Road submerged in partially). Shoulder & hard crust damaged in streaches) location coordinate: Lat.26.254495, lon.90.887627, Date of occurrence- 26/06/23 [(Long - 90.887627, Lat - 26.254495. popt - PWD (Roads)). Nabanoor MEM to Garalapam LPS roar Pkg. As-01-210 [Garalapam area As report received from PWD(Roads) dept on 3006/23, Nabanoor ME Madrassa to Garalapam LPS road Pkg no As-01-210 (road submerged partially, Shoulder & Hard crust damaged in streatches) Location Co ordinate. Lat.26.251498, 90.896402. Date of occurrence- 26/06/23 [(Long - 90.896402, Lat - 26.251488, Dept - PWD (Roads)). Mandia Dighirpam road to Dighirpam bazar road Pkg No. As-01-243 [Dighirpam bazar area As report received from PWD(Roads) dept on 3006/23, Mandia Dighirpam road to Dighirpam Bazar road Pkg no As-01-243 (road submerged partially, shoulder& hard crust damaged) Location. Coordinate Lat.26.2514219, lont.90.963974, Date of occurrence-26/06/23 [(Long - 90.996497, Lat - 26.251422, Dept - PWD (Roads)), dept on 3006/23, Mandia Dighirpam road to Dighirpam Bazar road Pkg no As-01-243 (road submerged partially, shoulder & hard crust damaged in streatches) Location Coordinate; Lat.26.2514219, lont.90.963974, Lat - 26.251420, Dept - PWD (Roads)), dept on 3006/23, Mandia Dighirpam road to Mourigan area As report received from PWD(Roads) dept on 3006/23,
	Dhubri	3	89.73356 & LATITUDE : 26.210283 (.) LONGITUTE : 89.73356 & LATITUDE : 26.210283 (.) 12/06/2023 to 26/06/2023 (Long - 89.733560, Lat - 26.210283, Dept - PWD (Roads)), SIDE BERM DAMAGED ON GHARIALDANGA PT-II TO JINKATA ROAD AT 1ST & 2ND

		I	VIVA A ON CHENTED OF BEACH A VICTORIAN CONTRACTOR OF THE CONTRACTO
			KM (LONGITUTE: 89.753674 & LATITUDE: 26.228957(.) (LONGITUTE: 89.753674 & LATITUDE: 26.228957(.) 12/06/2023 to 26/06/2023 (Long - 89.753674, Lat - 26.228957, Dept - PWD (Roads)), SIDE BERM & SIDE SLOPES DAMAGED ON ROAD FROM KUTI GHARIALDANGA PT II TO JINKATA AT 1ST KM (.) LONGITUTE: 89.754697 & LATITUDE: 26.231907 (.) LONGITUTE: 89.754697 & LATITUDE: 26.231907 (.) 12/06/2023 to 26/06/2023 (Long - 89.754697, Lat - 26.231907, Dept - PWD (Roads))
	Karimganj	4	Karimganj - F N Road near A.K. Azad F N Road near A.K. Azad Due to incessant rains from last few days the above road was damaged (road & hardcrust damaged) at CH 450.00M to 550.00M. The report was submitted by Asst. Executive Engineer P.W.R.D North Karimganj Territorial road on 20/06/2023 (Long - 92.281969, Lat - 24.858878, Dept - PWD (Roads)), F N Road (Jatua) Jatua Due to incessant rains from the last few days the above road was damaged (road surface is damaged & a hole is formed on either side of the road. A pothole is formed on the H.P.Culvert) at CH 1250.00M. The report was submitted by Asst. Executive Engineer P.W.R.D North Karimganj Territorial Road on 20/06/2023 (Long - 92.281045, Lat - 24.858676, Dept - PWD (Roads)), PWD Road over Bund opposite civil hospital at subash road PWD Road over Bund opposite civil hospital at subash road Due to incessant rains from the last few days the above road was damaged (a hole is formed on either side of the road) at CH 700.00M -750.00M. The report was submitted by Asst. Executive Engineer P.W.R.D North Karimganj Territorial Road on 20/06/2023 (Long - 92.362037, Lat - 24.866493, Dept - PWD (Roads)), RK Nagar - Nivia Bazar to Magura Nivia Bazar to Magura As information received form Assistant Executive Engineer PWRD Patharkandi and Ratabari Touritial Road Division Dullabchara due heavy rain last few days a Road of Nivia Bazar to Magura damaged partially
	Nalbari	3	damage upto 300m (Long - 92.242500, Lat - 24.242700, Dept - PWD (Roads)) Banekuchi - On 22/06/2023 Jowardi Bali road HPC submerged and damaged report from PWRD Department. Kaithalkuchi Village (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Kashimpur Ambari chuburi to Batabari Bazar Kashimpur On 22/06/2023 Kashimpur Ambari chuburi to Batabari Bazar road submerged report from PWRD Department. (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Kashimpur Bapuji High School to Burinagar road Kashimpur On 22/06/2023 Kashimpur Bapuji High School to Burinagar road submerged report from PWRD Department . (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Sonitpur	3	Thelamara - Kawaimari to Bamunpukhuri road Village- Bamunpukhuri, Thelamara Date-30-06-2023, As reported by PWD, Dhekiajuli Territorial Roads Sub- Division on 28-06-2023, Dighalijan has damaged the embankment, shoulder upto hard crust & H.P culvert facewall on 27th June on NH-15 at Kawoimari to Bamunpukhuri road (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Chariduar - Guwabasti to Meat supply via Ganesh guwala L.P School road eroded badly by Flood water of river Jarasar in different stretches likely from Ch.0.00m to Ch 60.00 m, Ch 230.00 m to Ch. 380.00 m and Ch.920.00 m to Ch.1010.00 m respectively (as per PWD WT message received on DTD 30.06.2023 Guwalabasti to Meatsupply (Long - 92.785758, Lat - 26.775086, Dept - PWD (Roads)), NH-15 TO GUWALABASTI ROAD ERODED BADLY BY FLOOD WATER OF RIVER JARASAR FROM CH. 570.00 M TO CH 690.00 M (as per PWD WT message received on DTD 30.06.2023) NH-15 TO GUWALABASTI (Long - 92.783427, Lat - 26.776520, Dept - PWD (Roads))
	Total District/Sub	25 Numbe	
	-division*	r	Details
Infrastructur e Damaged - Bridge	Sonitpur	6	Chariduar - CULVERT NO 1/1 AND CULVERT NO 1/2 AT CHAINAGE 220.00 AND 450.00 M RESPECTIVELY ON GHOIRALEE TE ROAD IS DAMAGED BADLY BY FLOOD WATER.(as per PWD WT message received on DTD 30.06.2023) GHOIRALEE TE ROAD (Long - 26.796685, Lat - 92.648150, Dept - PWD (Roads)), CULVERT NO 2/1 AND SIDE BERM AT CHAINAGE 1180.00 M ON KHELMATI TO BORJULI HATKHOLA IS DAMAGED BADLY BY FLOOD WATER (as per PWD WT message received on DTD 30.06.2023) KHELMATI TO BORJULI (Long - 92.643196, Lat - 26.747888, Dept - PWD (Roads)), CULVERT NO 3/1 AND APPROACH ROAD AT CHAINAGE 2100.00 M ON UPPER KACHARI GAON KERA BASTI ROAD IS DAMAGED BADLY BY FLOOD WATER(as per PWD WT message received on DTD 30.06.2023) UPPER KACHARI GAON (Long - 92.670907, Lat - 26.853488, Dept - PWD (Roads)), CULVERT NO 1/1 AND APPROACH ROAD AT CHAINAGE 210.00 ON KACHARIGAON TE ROAD IS DAMAGED BADLY BY FLOOD WATER.(as per PWD WT message received on DTD 30.06.2023) KACHARIGAON TE (Long - 92.685854, Lat - 26.829303, Dept - PWD (Roads)), CULVERT NO 3/1 AND APPROACH ROAD AT CHAINAGE 2350.00 ON RUPAJULI TO RANGAPARA MISSAMARI ROAD IS DAMAGED BADLY BY FLOOD WATER RUPAJULI TO RANGAPARA (Long - 92.671620, Lat - 26.821703, Dept - PWD (Roads)), CULVERT NO 3/1 AT CHAINAGE 2250.00 M ON GHANAPHULGURI TO KHELMATI PWD

			ROAD IS DAMAGED BADLY BY FLOOD WATER.(as per PWD WT message received on DTD 30.06.2023) GHANAPHULGURI TO KHELMATI (Long - 92.654177, Lat - 26.747061, Dept - PWD (Roads))							
	Total	6								
Infrastructur e Damaged - Wildlife	Nil									
	District/Sub -division*	Other Details								
Infrastructur e Damaged - Others	Dhubri	Agamoni - Bridge Approach Road Damaged BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 2/1 ON KHUNIARVITA ROAD TO KHERBARI BAZAR ROAD AT 2ND KM(.) LONGITUTE: 89.743423 & LATITUDE: 26.211961 (.) 12/06/2023 to 26/06/2023 , Bridge Approach Road Damaged BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 7/1 ON KHERBARI PROTAPGANJ ROAD AT 7TH KM(.) LONGITUTE: 89.725189 & LATITUDE: 26.22738 (.) 12/06/2023 to 26/06/2023 , Bridge Approach Road Damaged BRIDGE APPROACHES AND SIDE BERM DAMAGED OF RCC BR. NO. 1/1 PK ROAD TO KHERBARI PT III ROAD AT 1ST KM(.) LONGITUTE: 89.792702 & LATITUDE: 26.200705 (.) 12/06/2023 to 26/06/2023, Bridge Approach Road Damaged BRIDGE APPROACHES DAMAGED OF RCC BR. NO. 2/1 ON PK ROAD TO BHAMANDANGA WEST BENGAL BORDER ROAD AT 1ST KM (.) LONGITUTE: 89.733674 & LATITUDE: 26.210309 (.) 12/06/2023 to 26/06/2023 , Culvert Approach Road Damaged APPROCHES OF RCC BOX CELL CULVERT NO. 1/1 DAMAGED ON RANPAGLI SATRASAL ROAD AT 1ST KM (.) LONGITUTE: 89.73176 & LATITUDE: 26.191383 (.) 12/06/2023 to 26/06/2023								
	Goalpara	m(approx to heavy	Dudhnoi - Irrigation Canal/Scheme Damaged Earthen canal got damaged creating a hole of length 1.5 m(approx) and height 1.5 m (approx) at Kekreng FIS under Damra Patpara revenue village on 30/06/2023 due to heavy rainfall, Lat. 25.938658, Long 90.772343							
	Nalbari	_	- PWSS Damaged FHTC - 130 Nos, D/S - 4100 M, Drain Approne - 15 m, Electrical Components, B/WALL as per report submitted by PHE department on 29/06/2023							
	District/Sub -division*	Details								
Erosion	Chirang	WRD, Ka Length ap 26.45742 of River I Approx. 3 06-2023. Village, - 90.4046 Bijni - A Division, mtr(approx As report Kawadi of Latitude= bank eros mtr(approx 0 (Long	makumari(Kinaborgaon), Pub Bhadra Pt 2(Bhumkipara) and Batagaon As reported by EE ,Chirang ajalgaon, Bank erosion on R/B of River Kujia at Dimakumari(Kinaborgaon) Village , Damage details-prox. 450.00m, Breadth Approx. 3.00m , Depth approx. 2.00m , Longitude - 90.475679, Latitude-date of occurrence - 30-06-2023. As reported by EE ,Chirang WRD, Kajalgaon, Bank erosion on L/B Kujia at Pub Bhadra Pt 2(Bhumkipara) Village , Damage details- Length approx. 300.00m, Breadth 3.50m , Depth approx. 2.50m , Longitude - 90.462932, Latitude-26.422838 date of occurrence - 30-As reported by JE ,Chirang WRD, Kajalgaon, Active Bank erosion on L/B of River Suthi at Batagaon Damage details- Length approx. 250.00m, Breadth Approx. 4.00m , Depth approx. 3.80m , Longitude 166, Latitude-26.512312 date of occurrence - 30-06-2023. 0 (Long - 0.000000, Lat - 0.000000), grong, No.2 Kawadi, Gwjwnpuri (Borobazar VCDC) As reported by EE, Chirang Water Resource Kajalgaon, bank erosion on B/B of river Agrong at Agrong on 30-06-2023. Length= 600 bx), Breadth=3.00 mtr(approx), Depth=2.50 mtr (approx). Latitude=26.596451 Longitude=90.726208. ed by EE, Chirang Water Resource Division, Kajalgaon, bank erosion on L/B of river Manas at No 2 m 30-06-2023. Length=700 mtr(approx), Breadth=4.00 mtr(approx), Depth=2.00 mtr(approx). e26.511228 Longitude=90.757819. As reported by EE, Chirang Water Resource Division, Kajalgaon, bank erosion on L/B of river Dulani at Gwjwnpuri(Borobazar VCDC) on 30-06-2023. Length=400 bx), Breadth=3.00 mtr(approx), Depth=2.00 mtr(approx). Latitude=26.549394 Longitude=90.660893 -0.000000, Lat - 0.000000).							
	Jorhat	Teok - Ouguri Nepali Gaon South Part An area of road cum ring bund measuring approx length 40 feets slump down at Ouguri Nepali Gaon South part of the river Jhanji. Date= 30-06-2023. 0 (Long - 94.428791, Lat - 26.894255)								
	Sonitpur	Division	ra - Baligaon Bangaligaon Date-30/06/2023, As reported by Tezpur Water Resource Tezpur on 30/06/2023 Bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river ength = 200.00m, Latitude : 26.736022, Longitude: 92.558699 0 (Long - 92.558699, Lat - 2)							
Landslide	Nil									
Urban Flood	Nil									
	·		*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)							