

FRIMS Assam



Flood Reporting And Information Management System

			Assa	am Daily Flood Report as on	24-06-2023 at 4:00 PM				
Particula rs	Situation as on 24-06-2023 (in last 24 hours)								
Rivers flowing above Danger Level (as	Rivers flow level	ing above da	inger	Brahmaputra (Tezpur; Nea	Brahmaputra (Tezpur; Neamatighat)				
per CWC bulletin issued at 8 AM)	Rivers flow flood level	ing above hi	ghest	Nil					
District/S ub- division	No. of Districts/ Sub- divisions* Affected	divisions*		ted Districts/Sub-	Name of Urban Flood Districts/Sub-divisions*				
Affected	15	Dhubri, Di	brugarh, G	a, Chirang, Darrang, oalpara, Golaghat, Jorhat, Nagaon, Nalbari,	Darrang				
No. Of Revenue Circles Affected	42								
	District/S ub- division*	Total		Revenue Circle					
	Bajali	2	Bajali, Sa						
	Baksa	4		a, Barama, Baska, Jalah					
	Barpeta	4	Barnagar, Sarthebari, Chenga, Barpeta						
	Chirang	1	Sidli						
	Darrang	4	Patharighat, Dalgaon, Mangaldoi, Sipajhar						
Name Of	Dhubri	3	Golakganj, Bilasipara, South Salmara Part						
Revenue	Dibrugarh	4	_	Tingkhong, Naharkatia, Dibrugarh West, Chabua					
Circles	Goalpara	1	Lakhipur						
Affected	Golaghat	1	Bokakhat						
	Jorhat	1	Jorhat East						
	Kamrup	5	North Ghy, Kamalpur, Rangia, Hajo, Kayan						
	Lakhimpu r	2	Nowboicha, Bihpuria						
	Nagaon	1	Raha						
	Nalbari	7			ni, Nalbari, Tihu, Barbhag, Ghograpar				
	Tamulpur	2	Goreswar	, Tamulpur					
	Total	42							
	District/S ub-	Total	Revenue	Circle					
	division*	107	/ D : 1: 1	77.) (C 100.)					
	Bajali Baksa	137 32		57), (Sarupeta 80)	ogka 16) (Jalah 2)				
	Baksa Barpeta	112		ara 11), (Barama 2), (Ba					
	Chirang	4	(Sidli 4	(Barnagar 1), (Sarthebari 76), (Chenga 9), (Barpeta 26)					
Villages	Darrang	168		-	Mangaldoi 75), (Sipajhar 72)				
Affected	Darrang Dhubri	216		mat 14), (Daigaon 7), (N mj 68), (Bilasipara 33), (
	Dibrugarh	11		2	Dibrugarh West 6), (Chabua 1)				
	Goalpara	5	(Lakhipu		Diorugum mest 0 /, (emauta 1 /				
	Golaghat	17	(Bokakh						
	Jorhat	1	(Jorhat E						
	Kamrup	174			Rangia 16), (Hajo 47), (Kayan 18)				
	Lakhimpu	174	•	cha 11), (Bihpuria 1)	Kangia 10), (11aj0 47), (Kayall 10)				
	Lакипири	14	(TAOMOOI	cna 11), (D ilipulia 1)					

	r								
	Nagaon	9	(Raha 9						
	Nalbari	202	(Barkheti), (Ghogi		chim Nalbari	25), (Baneku	ichi 5), (Nal	bari 20), (T	"ihu 30), (Barbhag 49
-	Tamulpur	18	(Goreswa	ar 6), (Tamı	ulpur 12)				
	Total	1118		1		ı		1	
	District/S ub- division*	Male	Female	Children	Total Populatio	Population	Details	Crop Area (in Hect.)	Crop Area Details
-	Bajali	109039	98232	14316	n 221587	(Bajali 139 Sarupeta 82		396.10	(Bajali 185.40), (Sarupeta 210.70)
	Baksa	1398	779	266	2443	(Barama 2 Baska 0), 1501), (Ba 678)	64), ((Jalah	5.00	(Barama 0.00), (Baska 0.00), (Jalah 5.00), (Baganpara 0.00)
	Barpeta	42456	36308	25232	103996	(Sarthebari Chenga 23 Barpeta 34 Barnagar 4	10), (268), (361.75	(Sarthebari 63.75), (Chenga 20.00), (Barpeta 278.00), (Barnagar 0.00)
	Darrang	2909	2841	2743	8493	(Patharigha Dalgaon 0 Mangaldoi Sipajhar 35), (7334), (3387.50	(Patharighat 692.20), (Dalgaon 38.00), (Mangaldoi 1182.30), (Sipajhar 1475.00)
Populatio :	Dhubri	357	333	170	860	(Golakganj Bilasipara South Salma	860), (ara Part 0)	828.90	(Golakganj 205.90), (Bilasipara 28.50), (South Salmara Part 594.50)
n And Crop Area	Dibrugarh	0	0	0	0	Dibrugarh V Chabua 0)	(Tingkhong 0), (Dibrugarh West 0), (Chabua 0), (Naharkatia 0)		(Tingkhong 2.00), (Dibrugarh West 49.00), (Chabua 118.50), (Naharkatia 2.53)
Affected	Goalpara	2045	2015	690	4750	(Lakhipur	4750)	0.00	(Lakhipur 0.00)
	Golaghat	0	0	0	0	(Bokakhat		197.00	(Bokakhat 197.00)
	Jorhat	0	0	0	0	(Jorhat East	t 0)	21.40	(Jorhat East 21.40)
	Kamrup	76	68	20	164	Kamalpur	(North Ghy 0), (Kamalpur 0), (Rangia 164), (Hajo 0), (Kayan 0)		(North Ghy 10.50), (Kamalpur 226.73), (Rangia 180.91), (Hajo 678.00), (Kayan 10.50)
	Lakhimpu r	10562	10683	815	22060	(Nowboich Bihpuria 0	a 22060), (226.00	(Nowboicha 226.00), (Bihpuria 0.00)
-	Nagaon	0	0	0	0	(Raha 0)		548.28	(Raha 548.28)
	Nalbari	16944	15368	8356	40668	Nalbari 22 19780), (B 8300), (Gh 2464), (Pas Nalbari 65 Banekuchi	(Barkhetri 0), (Nalbari 2263), (Tihu 19780), (Barbhag 8300), (Ghograpar 2464), (Paschim Nalbari 6521), (Banekuchi 1340)		(Barkhetri 229.00), (Nalbari 0.00), (Tihu 312.00), (Barbhag 71.60), (Ghograpar 150.00), (Paschim Nalbari 272.00), (Banekuchi 63.50)
	Tamulpur	1328	911	511	2750	(Goreswar		120.86	(Goreswar 0.00), (
ŀ	Total	187114	167538	53119	407771	Tamulpur '	134)	8469.56	Tamulpur 120.86)
	District/S	10/114	10/330	33117	70///1			0707.30	
	ub- division*	Total	Relief Ca	ımp			Relief Distr	ribution Cent	res
•	Bajali	110	53(Baiali	27, Sarupeta	1 26)		57(Bajali I S	3, Sarupeta 49	9)
-	Baksa	2		1 1, Jalah 0)			1(Barama 0		· /
-	Barpeta	36		ari 2, Barpet			34(Sarthebari 16, Barpeta 18)		
Relief	Chirang	4	0(Sidli 0		1 */		4(Sidli 4)		
Camps /	Darrang	7		ghat 1, Sipajl	har 0)			at 1, Sipajhai	: (5)
Centres	Dhubri	4			1 7		0(Bilasipara		. /
Opened		3	4(Bilasipara 4)						
	Goalpara	3	1(Lakhipur 1)			2(Lakhipur 2)			
·	Goalpara Kamrup	5		4, Kayan 0)		1(Rangia 0, Kayan 1)		
	Kamrup Lakhimpu r		4(Rangia		·		1(Rangia 0		a 1)

	Tamulpur	11	7(Goreswar 1, Tamulpur 6)				4(Goreswar 4, Tamulpur 0)					
	Total	220	101				119					
	District/S ub- division*	Total	Revenue	Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disabilit y		
	Bajali	73718	(Bajali 2	566), (Sarupe	ta 71152)	32346	38208	3145	11	8		
	Baksa	264	(Baganpa	ra 0), (Baska na 264)	0), (Jalah	84	139	40	1	0		
	Barpeta	279		0), (Sarthebar	ri 279)	118	128	33	0	0		
	Darrang	92		0), (Mangalo		30	26	36	0	0		
Inmates				0), (Patharig								
In Relief Camps	Dhubri	860		sipara 860)		357	333	170	0	0		
Camps	Goalpara	136	(Lakhipu			62	47	24	2	1		
	Kamrup	164		ny 0), (Kama 164), (Hajo 0		71	68	20	2	3		
	Nalbari	5232	2872), (N (Ghograp 282), (Ba	i 0), (Paschir albari 51), (T ar 1542), (Ba rbhag 485)	Tihu 0), nnekuchi	2359	2113	713	30	17		
	Tamulpur	607	(Goreswa	r 71), (Tamu	lpur 536)	246	221	137	3	0		
	Total	81352				35673	41283	4318	49	29		
Human Lives	District/S ub- division*	Total	Male	Female	Children	Revenue C	irclewise					
Lost - Confirme	Nalbari	1	1	0	0			g 0), (Barkhet albari 0), (Tib	ri 0), (Ghogra	ıpar 0),		
d	Total	1	1	0	0	(Transari 0)	, (I usellill I te		14 0)			
Human	District/S			General								
Lives Lost Confirme	ub- division*	Total	Flood Drowning Death (Non Landslide									
d - Death	Nalbari	1	1	Flood)	0							
Type	Total	1	1	0	0							
Human Lives Lost - Missing Human	Nil											
Lives Lost Missing - Type	Nil											
	District/S ub- division*	Total	Big	Small	Poultry							
	Bajali	149965	80948	55185	13832							
	Barpeta	67030	25644	25476	15910							
	Darrang	9085	5830	3115	140							
Animals	Dibrugarh	5068	4118	950	0							
Affected	Goalpara Kamrup	643 6618	150 3821	170 2797	323							
	Lakhimpu	5403	4091	1312	0							
	r Nalbari	134093	56546	44467	33080							
	Tamulpur	32150	20732	11418	0							
	Total	410055	201880	144890	63285							
Animals	District/S ub- division*	Total	Big	Small	Poultry							
Washed Away	Bajali	764	0	0	764							
Away	Nalbari	200	0	0	200							
	Total	964	0	0	964	D	n	0.1		0.1		
Houses	District/S	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle	Others Total		
Damaged	ub-	Kuccha	I umu						l .	20002		

Buks		division*								Shed			
Tamulpur		Baksa	3	0	3	183	0	183	0	0	0		
Total S		Kamrup	0	0	0	79	0	79	0	0	0		
DistrictS Unbodivision* Agency		Tamulpur	0	0	0	28	2	30	0	0	0		
DetrictS Helicopt Care of Mec Local People Boats Deployed Helicopt Evenuate Helicopt Hel		Total	3	0	3	290	2	292	0	0	0		
Rescue Operation Page Page SDR		ub-	,				Evacuate d By	Evacuate d By	rs	Evacuate d By Helicopte	Team Deploye		
Operation Darrang		Bajali			People	3	0	0	0	0	9		
Name		Barpeta		ina/Lagal	-	1	14	1	0	0	0		
Relief Point Poi	n	C				_	_		_				
Lakhimpu		_				-	•		,				
Nalbari Total To						0	0	0	0	0	2		
Total		r				0	_		0	0	4		
District/S Nice (in ubdivision) Dal (i									_		-		
Relief District/S ub		Total		1		5			0	0	18		
Relief Distributed Balasa 0.00		ub-	`	`	`	`	Feed - Green Fooder	Feed - Wheat Bran (in	Cattle Feed - Rice Bran (in Q)				
Relief Distributed Part		Bajali	1243.55	209.22	153.50	379.37	0.00	704.00	0.00	0.00			
Chirang 0.00										0.00			
Distributed	Daliaf												
Darrang 2.25 0.42 0.13 12.50 0.00 0.00 20.50													
Daubri													
Kamrup 1.96 0.38 0.11 11.34 0.00 60.00 0.00 0.00 100.00	- Cu												
Lakhimpu r 0.00 0.00 0.00 0.00 0.00 0.00 0.00 10													
Tamulpur 106.93 17.99 5.39 539.22 0.00 4489.97 0.00 0.00 100.00			1.96	0.38	0.11	11.34	0.00	60.00	0.00				
Tamulpur 62.02 11.03 3.31 330.75 0.00 94.71 0.00		r		0.00	0.00	0.00	0.00	0.00					
Total 1475.53 247.49 165.59 1535.75 0.00 5717.28 462.73		Nalbari	106.93	17.99		539.22	0.00	4489.97	0.00				
District/S U-			62.02	11.03		330.75	0.00	94.71	0.00				
Bajali 0.00-ml, 0.00-Q 329.00-Pkt Candle-600.00-Pkt; Match Box-75.00-Pkt; M.Coil-150.00-Pkt; Tarpaulin-10446.00-Pieces; Wheat bran-1040.40-Q			1475.53	247.49	165.59	1535.75	0.00	5717.28	462.73				
Relief Baksa 0.00-Pkt, 0.00-Q 0.00-Pkt, 0.00-Q 0-0.00-Pkt Tarpaulin-10446.00-Pieces; Wheat bran-1040.40-Q		ub-	Baby Food Liquid		Baby Food	Solid	Others						
Relief Distribut ed Others District/S Nalbari District/S Tamplur Darrang District/S Darrang Darrang Darrang Darrang District/S Darrang		Bajali	0.00-ml, 0	.00-Q	329.00-Pkt								
Chirang 97.00-L 97.00-Kg Tarpaulin-15.00-Pieces		Baksa	0.00-Pkt, 0).00-Q	0.00-Pkt, 0.0	00-Q							
Darrang 2.00-L, 0.00-Q 2.00-Pkt, 0.00-Q 2.00-Pkt, 0.00-Q 2.00-Pkt; sanitary nakpin-26.00-Pkt; o-0.00-Q 0.00-Q 0.00-Q 0.00-Pkt; sanitary nakpin-26.00-Pkt; o-0.00-Q 0.00-Pkt; sanitary nakpin-26.00-Pkt; o-0.00-Q 0.00-Pkt; sanitary nakpin-26.00-Pkt; o-0.00-Q 0.00-Pkt; sanitary nakpin-26.00-Pkt; o-0.00-Pkt; o-0.00-Q 0.00-Pkt; o-0.00-Pkt; o-0.00-		Barpeta	0.00-Q		0.00-Q								
Relief Distribut ed Others Dhubri 0.00-Q 0.00-Q 0.00-Q 0.00-Q 0.00-Pkt; sanitary nakpin-26.00-Pkt; 0-0.00-Q 0.00-Q 0.00-Pkt Others Others Cheera-0.34-Q; Gur-0.08-Q Others		Chirang	97.00-L		97.00-Kg		candles-15.00-Pkt; mosquito repellent coil-10.00-Pkt; matchbo 5.00-Pkt; sanitary nakpin-26.00-Pkt; 0-0.00-Q						
Distribut ed Others Distribut ed Others Goalpara 25.00-Pkt 75.00-Pkt Cheera-0.34-Q; Gur-0.08-Q	D 11 6	Darrang	2.00-L, 0.0	00-Q	2.00-Pkt, 0.00-Q								
ed Others Goalpara 25.00-Pkt 75.00-Pkt Cheera-0.34-Q; Gur-0.08-Q		Dhubri	0.00-Q		0.00-Q								
Kamrup		Goalpara	25.00-Pkt				Cheera-0.34-Q; Gur-0.08-Q						
Lakhimpu r 0.00-Q 0.00-Q Tarpaulin-297.00-Pieces O-0.00-Q; Masquito Coil-758.00-Pkt; Candle-2358.00-Pkt; Phenyl-431.00-Pkt; Wheat bran -1367.00-Q; Masquito coil-640.00-Pkt; Match -640.00-Pkt; Sanitary Napkin-124.00-Pkt Tamulpur 0.00-Q 0.00-Q Tarpaulin -20.00-Q; Chira-28.19-Q; Gur-39.18-Q; Mosquito coil-323.00-Pkt; Match box-323.00-Pkt; Candle -323.00-Pkt; Water bottle -6460.00-L Infrastru cture Damaged division* Details Degrang 4 Mangaldoi - CM Dutta Bund FIS At village Mollapara As reported by Dept. embankment breach	ou ouicis	Kamrup	10.00-Pkt,	0.00-Q	10.00-Pkt, 0	.00-Q	Candle-30.00-Pkt; Mosquito Coil-20.00-Pkt; Sanitary Napkin-						
Nalbari Nalbari Nalbari O-0.00-Q; Masquito Coil-758.00-Pkt; Candle-2358.00-Pkt; Phenyl-431.00-Pkt; Wheat bran -1367.00-Q; Masquito coil-640.00-Pkt; Match -640.00-Pkt; Sanitary Napkin-124.00-Pkt Tamulpur O-0.00-Q Tamulpur O-0.00-Q; Masquito Coil-758.00-Pkt; Wheat bran -1367.00-Q; Masquito coil-640.00-Pkt; Match -640.00-Pkt; Sanitary Napkin-124.00-Pkt Tarpaulin -20.00-Q; Chira-28.19-Q; Gur-39.18-Q; Mosquito coil-323.00-Pkt; Match box-323.00-Pkt; Candle -323.00-Pkt; Water bottle -6460.00-L Infrastru cture Damaged District/S ub- division* Mangaldoi - CM Dutta Bund FIS At village Mollapara As reported by Dept. embankment breach		_	0.00-Q		0.00-Q								
Tamulpur 0.00-Q 0.00-Q coil-323.00-Pkt; Match box-323.00-Pkt; Candle -323.00-Pkt; Water bottle -6460.00-L Infrastru cture Damaged division* Details Details Mangaldoi - CM Dutta Bund FIS At village Mollapara As reported by Dept. embankment breach			0.00-Q		0.00-Q		Phenyl-431.00-Pkt; Wheat bran -1367.00-Q; Masquito coil-						
cture Damaged - Degrang Degran		Tamulpur	0.00-Q		0.00-Q		coil-323.00-Pkt; Match box-323.00-Pkt; Candle -323.00-Pkt;						
	cture	ub-	Number										
	- Embank	Darrang	4										

	I	I	D . 104/04/0000 L/G 01/004/00 Y 05/14/01/0 D Y 1
ment Breached	Total District/S ub- division*	4 Number	Dated 24/04/2023. (Long - 91.994520, Lat - 26.444710, Dept - Irrigation), CM Dutta Bund FIS At village Bezpara As reported by Dept. embankment breach occurred at Main Canal of CM Dutta Bund FIS at Ch 10500m. Approx. length of damage is 10-11m. Dated 24/04/2023. (Long - 91.994520, Lat - 26.444710, Dept - Irrigation), CM Dutta Bund FIS At village Mollapara As reported by Dept. embankment breach occurred at Main Canal of CM Dutta Bund FIS at Ch 8800m. Approx. length of damage is 5-6m. Dated 24/04/2023. (Long - 91.994500, Lat - 26.444700, Dept - Irrigation), CM Dutta Bund FIS At village Bezpara As reported by Dept. embankment breach occurred at Main Canal of CM Dutta Bund FIS at Ch 10470m. Approx. length of damage is 6-7m. Dated 24/04/2023. (Long - 91.994520, Lat - 26.444710, Dept - Irrigation) Details
	Biswanat	1	Gohpur - Mild bank erosion is observed at R/Bank embankment of Sessa at Auguri area for a length of
	h Golaghat	1	30 mtr on 24/06/23 (Long - 93.733716, Lat - 26.951885, Dept - BRO) Bokakhat - Un embankment portion of Alengmari area at ch. 13000m (Alengmari) Inundation of Berkep, Alengmari village area about 25m that took place on 23.06.2023 was caused by the back water from the riever Dhansiri (Long - 93.412223, Lat - 26.412980, Dept - Water Resource Deptt.)
	Kamrup	3	Hajo - Puthimari embankment Hadal manakuchi On 23/06/2023 as per water resource department seepage,boiling, leakage was observed . The restoration work done at L/B embankment of river puthimari of 2.76 km from gallipar to hadal by WRD. (Long - 26.282500, Lat - 91.575000, Dept - Water Resource Deptt.), Puthimari embankment Kaya Jani, boromboi Boiling and seepage reported by water resource department on 23/06/2023 on R/B embankment of puthimari river at kayajoni and ulletia and boromboi for 5.7km (Long - 26.287700, Lat - 91.585000, Dept - Water Resource Deptt.), Brahmaputra dyke Hatimura to adabari B/dyke T tangonmari is a level crossing of the embankment with village road. Was damaged for 25m length by tractor on 23/06/2023 asreported by WRD . (Long - 26.240000, Lat - 91.580000, Dept - Water Resource Deptt.)
Infrastru cture Damaged - Embank ment Affected	Nalbari	10	Nalbari - Pagaldia embankment Bhadra As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - BRO), Pagaldia embankment Barmurikona As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.), Pagaldia embankment at poila Poila As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.), Pagaldia embankment Balilcha As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.), Pagaldia embankment Digheli As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.), Pagaldia embankment Digeli balajan suburi As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.), Ghograpar - Noona Embankment Gargari On 22/06/2023 as per WRD, Embankment overtopped occurs near Gargari area on L/B of river noona at Ch 500 m. (Long - 91.570000, Lat - 26.550000, Dept - BRO), Noona Embankment Namati On 22/06/2023 as per WRD, Embankment overtopped occurs near Namati area on R/B of river noona at Ch 3500 m. (Long - 26.580000, Lat - 91.560000, Dept - Water Resource Deptt.), Noona Embankment Bilpar On 22/06/2023 as per WRD, Embankment overtopped occurs near Namati area on R/B of river noona at Ch 3500 m. (Long - 91.550000, Lat - 26.440000, Dept - Water Resource Deptt.), Pagaldia Embankment Pub-Barsira(Bhadar) On 19/06/2023 as per WRD, Embankment overtopped occurs near Bhadar (Pub-Barsiral) area on L/B of river pagaldia ch - 3th KM (Long - 91.530000, Lat - 26.560000, Dept - Water
	Total District/S	15	
	ub- division*	Number	Details
Infrastru cture Damaged - Road	Bajali	23	Sarupeta - Galia to Tapa via Gathiapara Gathiapara Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Datirbori to Rajakhat Road Rajakhat Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Karagari Bazar area Road Karagari Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept -

PWD (Roads)), Majgaon Anandapur road | Majgaon | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), Bhawanipur Gopal Ata Satra Road | Bhawanipur | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat -0.000000, Dept - PWD (Roads)), BB road to Gathiapara via Dangarpar | Gathiapara | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat -0.000000, Dept - PWD (Roads)), Tihu Palha Simlaguri Road | Simlaguri | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), ADP road to Majgaon | Majgaon | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), Galia Sukmanah Road | Sukmanah | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), Banglipara Sarupeta road | Banglipara | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), ADP Bazar to Gohain Kamal Ali road | Pota | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat -0.000000, Dept - PWD (Roads)), NH-31 to Banglipara Shivmandir road | banglipara | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat -0.000000, Dept - PWD (Roads)), Majgaon Kaljar road | Kaljar | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), Majgaon Dulirvitha road | Majgaon | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), Phulartal Porabharal road | Porabharal | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), Sukmanah MPNA road | Sukmanah | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), MPNA to Galia Sukmanah road | Galia | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)). Sukmanah Bazar road | Sukmanah | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), NH-31 to Kahara gaon road | Kahara Gaon | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat -0.000000, Dept - PWD (Roads)), Laogaon Hudukhata road | Hudukhata | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)), Chaulabari to Palla river via Kahalpara road | Kahalpara | Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Gopal Ata Satra road | Bhawanipur | Road submerged and bridge approaches erroded as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 | (Long -0.000000, Lat - 0.000000, Dept - PWD (Roads)) Jalah - Bh College to Bunmajapam road | Bunmajapam | As per the information received from PWD deptt. Due to continous havy rainfall the road surface and side berm has been damaged and hp culcert washed away at (CH 400.00M & 4050) on 21-06-2023 | (Long - 91.000470, Lat - 4000.000000, Dept -PWD (Roads)), Tanagamari to Mushalbari Road | Tangamari | As per the information received from PWD deptt. Surface Baksa 6 has been breached 1500.00 M on 21-06-2023 | (Long - 26.631759, Lat - 91.086400, Dept - PWD Kawimari to Borghopa road | kawiamri | As per the information received from PWD deptt. The HP culvert has been damaged at 500.00 m on 21-06-2023 | (Long - 91.045465, Lat - 26.557869, Dept -PWD (Roads)), Samuhathi Market to Baharuddin House | Pokalagi | As per the information received from PWD deptt.

Surface and side been damage at (CH 900.00 M, CH 1000.00, Ch1100.00 M and CH 1300.00M) on on 21-06-2023. | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), No 2Dakhin Dumriguri Prathomik Vidayalay Road | Santi bazar to sansuma basumatary house kalbari | As per the information received from PWD deptt. Approch has been damage at ch 2150, Dated -21/06/2023 | (Long - 91.053218, Lat - 26.600486, Dept - PWD (Roads)), Hazua Nalbari road | hazua nalbari | As per the information received from PWD deptt. Surface side beam has been damage 6400.00 M on 21-06-2023 | (Long - 91.291314, Lat - 26.732984, Dept - PWD (Roads)) Barpeta - BB road to DK road via Madhya Chakirbhitha road | Chakirbhitha | As per report received from PWD Roads Dept BB road to DK road via Madhya Chakirbhitha road fully submerged, Side berms and road surface damaged in stTetches. Reported by PWD .Date-23-06-2023 | (Long - 0.000000, Lat -0.000000, Dept - PWD (Roads)), BB road at Lakhi bazar to Khablarbhtiha | Khablarbhitha | As per report received from PWD Roads Dept BB road at Lakhi bazar to Khablarbhtiha road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD Dangarkuchi to Deurikuchi road | Deurikuchi | As per report received from PWD Roads Dept Dangarkuchi to Deurikuchi road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), NIJ-31 to Pub Kaljhar road | Kaljhar | As per report received from PWD Roads Dept NIJ-31 to Pub Kaljhar road fully submerged. Side berms and road surface do maged in stretches. Reported by PWD .Date-23-06-2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), UK road (NI1-31 to Jarabari) PMGS Y road | Jarabari | As per report received from PWD Roads Dept UK road (NI1-31 to Jarabiiri) PMGS Y road subniergcil iii stretches. Side bcmis and road surfacti damaged in stretches. Reported by PWD .Date-23-06-2023 | (Long - 0.000000, Lat - 0.000000, Dept -PWD (Roads)). Putlartary Chowk to Bantipiir road | Putlartari Bantipur | As per report received from PWD Roads Dept Putlartary Chowk to Bantipiir road fully submergetl. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023. | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Putlartary Tini Ali to Bantipur Road | Putlartari Bantipur | As per report received from PWD Roads Dept Putlartary Tini Ali to Bantipur Road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023. | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), DK road to Bhalukabari Pathar via Bhalukabari Gaon | Bhulukabari Gaon- Bhulukabari Pathar | As per report received from PWD Roads Dept DK road to Bhalukabari Pathar via Bhalukabari Gaon. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), BAmunbari Kujarpith road | Baminbari- Kujarpith | As per report received from PWD Roads Dept Bamunbari Kujarpith road fully submerged. Side berms and road surface damaged in stretches, (PMGSY completed Pkg- AS-01-508).Reported by PWD .Date-23-06-2023 | (Long - 0.000000, Lat - 0.000000, Barpeta 22 Dept - PWD (Roads)), Kayakuchi Village road | Bhakuamari, Maricha | As per report received from PWD Roads Dept Kayakuchi Village road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Barpeta Patbaushi Keotkuchi Road | Patbaushi Keotkuchi | As per report received from PWD Roads Dept Side berm eroded & Hard Crust damaged at several stretches .Reported by PWD .Date-23-06-2023 (Long - 91.032534, Lat - 26.298922, Dept - PWD (Roads)), Baradi Tatikuchi Road | Baradi Tatikuchi | As per report received from PWD Roads Dept Road submerged and breach occurred at several stretches .Reported by PWD .Date-23-06-2023 | (Long -91.038035, Lat - 26.325899, Dept - PWD (Roads)), 918 No. Metuakuchi LPS Road | Metuakuchi | As per report received from PWD Roads Dept Side berm eroded & Hard Crust damaged at several stretches. Reported by PWD .Date-23-06-2023 | (Long -90.995401, Lat - 26.319517, Dept - PWD (Roads)), arpeta Guwahati PWD road to Keotkuchi Namghar and app. Of RCC Br. No 3/1 on BD Road | Keotkuchi | As per report received from PWD Roads Dept Barpeta Guwahati PWD road to Keotkuchi Namghar and app. Of RCC Br. No 3/1 on BD Road. Reported by PWD .Date-23-06-2023 | (Long-91.046317, Lat - 26.312914, Dept - PWD (Roads)), Keotkuchi Mailkuchi Road | Keotkuchi Mailkuchi | As per report received from PWD Roads Dept Road submerged. Reported by PWD. Date-23-06-2023 | (Long - 91.054898, Lat - 26.305494, Dept - PWD (Roads)), Pohumara Temura Road | Pohumara Temura | As per report received from PWD Roads Dept Road submerged and side berm damage in several stretches. Reported by PWD .Date-23-06-2023 | (Long -91.017738, Lat - 26.281450, Dept - PWD (Roads)), Patbaushi Nangalkur Road to Barpeta Baghbar Road via Majorgaon and Nalirpam | Patbaushi Nangalkur As per report received from PWD Roads Dept Side berm and hard crust damage in several stretches. Reported by PWD .Date-23-06-2023 | (Long - 91.008945, Lat - 26.293674, Dept - PWD (Roads)), Bhella Tatikuchi Road | Bhella Tatikuchi | As per report received from PWD Roads Dept Approach of RCC Br. No. 2/1 is erroding due to heavy flood of water. Reported by PWD .Date-23-06-2023 | (Long -91.076617, Lat - 26.321520, Dept - PWD (Roads)), Barpeta Howly Road to Barpeta Medical College Road (SH-2). | Dabaliapara | As per report received from PWD Roads Dept Side berm eroded and hard crust damaged. Reported by PWD .Date-23-06-2023

(Long - 90.995506, Lat - 26.336415, Dept - PWD (Roads)), Nakhanda E&D Road | Nakhanda area | As per report received from PWD Roads Dept Side berm eroded. Reported by PWD .Date-23-06-2023 | (Long - 91.020083, Lat - 26.302272, Dept - PWD (Roads)), Ganakkuchi to Karertal via Barpeta Polytechnic Institue and Model School at Barpeta | Ganakkuchi | As per report received from PWD Roads Dept Side berm eroded. Reported by PWD .Date-23-06-2023 | (Long - 91.001025, Lat - 26.306051, Dept - PWD (Roads)), Nagaon Sikarvitha Road | Nagaon | As per report received from PWD Roads Dept Side berm eroded and hard crust damaged .Reported by PWD .Date-23-06-2023 | (Long - 91.101908, Lat - 26.329283, Dept -PWD (Roads)) Bongaigaon - Kashidoba Kakoijana Road | Kashidoba Kakoijana Road | Road hard crust damaged at various stretches from Ch. 800.00m to 1500.00m and Embankment damaged at 5th Km, as per report received from PWRD, Bongaigaon dated-23.06.2023 | (Long - 90.601127, Lat - 26.419829, Dept - PWD (Roads)), Nakkati Hill approach road | Nakkati Hill approach road | Road submarged from Ch. 2000.00m to Ch. 2160.00m and Bridge approach of Bridge No. 3/1 damaged, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.529457, Lat - 26.398712, Dept - PWD (Roads)), Nakkati Hill approach road | Nakkati Hill approach road | Bridge approach of Br. No. 3/2 damaged completely. As per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.533769, Lat - 26.398341, Dept - PWD (Roads)), Dholagaon Tilapara(Dewangaon) road | Dholagaon Tilapara(Dewangaon) road | Breached out from Ch.1500.00m to Ch.1535.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.526484, Lat - 26.405792, Dept - PWD (Roads)), Majgaon Nigamghola(Kandulimari Pahar NC) | Majgaon Nigamghola(Kandulimari Pahar NC) | Embankment damaged at Ch.400.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.572449, Lat - 26.413344, Dept - PWD (Roads)), New Bongaigaon Dhaligaon Road | New Bongaigaon Dhaligaon Road | Surface damaged, water logged and muddy surface formed from Ch.0.00m to Ch.500.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.523670, Lat - 26.490165, Dept - PWD (Roads)), New Bongaigaon Dhaligaon Road | New Bongaigaon Dhaligaon Road | Surface damaged and water logged from Ch.500.00m to Ch.900.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.523272, Lat - 26.490535, Dept - PWD (Roads)), Bagheswari temple to Chitkagaon Road | Bagheswari temple to Chitkagaon Road | Side slope erroded and hard crust damaged, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long -90.565225, Lat - 26.469981, Dept - PWD (Roads)), NH-31C Popragaon PMGSY Road to Korebari | NH-31C Popragaon PMGSY Road to Korebari | Side slope erroded at Ch.1st Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.619676, Lat - 26.489413, Dept - PWD (Roads)), Boitamari - Sankarghola kherpuji road | Kherpuji | Hard crust & shoulder damage at ch 6th km on Bongaiga 43 23/06/2023 | (Long - 90.547499, Lat - 26.280913, Dept - PWD (Roads)), on Sankarghola kherpuji road | Kherpuji | Landslide at ch 6th km submitted on 23/06/2023 by pwdr | (Long - 90.517716, Lat - 26.289992, Dept - PWD (Roads)). Sankarghola to kherpuji road | Kherpuji | Landslide at ch 1st km and ch 2nd km submitted on 23/06/2023 by PWDR | (Long - 90.519196, Lat - 26.264915, Dept - PWD (Roads)), Dangtol - Talguri Basugaon Road | Talguri Basugaon Road | Embankment Damaged at Ch. 13050.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.437166, Lat -26.425305, Dept - PWD (Roads)), Fulkumari to Durgamandir road | Fulkumari to Durgamandir road | Embankment damaged at various stretches from 800.00m to 2100.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.431975, Lat - 26.360219, Dept - PWD (Roads)), Paltanbazar to Hollaguri road | Paltanbazar to Hollaguri road | Embankment damaged at various stretches from 2000.00m to 3000.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.423056, Lat - 26.383126, Dept - PWD (Roads)), Manikpur - Gerukabari to Kirtanpara road | Kirtanpara | Road submered from Ch.9300.00m to Ch.9400.00m, as per report received from PWRD, Bongaigaon, dated - 23.06.2023 | (Long - 90.754335, Lat - 26.410217, Dept - PWD (Roads)), Hapachara Barbila to Nachanguri Road | Nachanguri | Hard crust, side slope and shoulder got damaged, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.662334, Lat -26.433170, Dept - PWD (Roads)), Patiladaha Monakoch to Baobari Road | Baobari | Breached out for about 20m at Ch.970.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 | (Long - 90.797627, Lat - 26.494121, Dept - PWD (Roads)), Gerukabari Jamdoha PMGSY Road | Jamdoha | Breached out at Ch.752.00m to Ch.970.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 | (Long - 90.701968, Lat - 26.451735, Dept - PWD (Roads)), NH-31 to Dankinamari village Road | Dankinamari | Submerged for a lenth of 200.00m at Ch.720.00m to Ch.920.00m(Depth is 30cm), as per report received from PWRD, Bongaigaon, dated - 23.06.2023 (Long - 90.641590, Lat - 26.493949, Dept - PWD (Roads)), Manasghat Sakisali Road | Sakisali | Road shoulder damaged/eroded from Ch.1st Km to Ch.9th Km, as

per report received from PWRD, Bongaigaon, dated- 23.06.2023 | (Long - 90.755204, Lat - 26.462392, Dept - PWD (Roads)),
Roha Chakla Kokila Road | Kokila | Road surface damaged at Ch.10th Km, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 | (Long - 90.840281, Lat - 26.358849, Dept - PWD (Roads)),

Dhupuri Garoleti road | Garoleti | Submarged from Ch. 100.00 to Ch. 150.00m and Ch.250.00m to Ch. 300.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.795634, Lat -

26.485596, Dept - PWD (Roads)), Purana Bijni to Patiladoha road | Patiladaha | Bridge approach of SPT Br. No. 8/1 partially damaged, clearing of water hyacinth on urgent basis, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.788278, Lat - 26.489028, Dept - PWD (Roads)),

Gerukabari Jamdoha PMGSY road | Jamdoha | Approaches of culvert No. 1/2 and culvert No. 1/3 damaged, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 | (Long - 90.704193, Lat - 26.453973, Dept - PWD (Roads)),

Patiladoha Lungijhar road | Lingjhar | Submarged from Ch. 900.00 to Ch. 9400.00m (depth of submargenece=45cm), as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long-90.795054, Lat - 26.497138, Dept - PWD (Roads)),

Sialmari Salmara road to Lungijhar village road | Salmara | Shoulder damaged from Ch.0.00 to Ch.600.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 | (Long - 90.777098, Lat - 26.490723, Dept - PWD (Roads)),

Dhupuri No.2 to Bhatipara road | Bhatipara | Submarged from Ch.0.00 to Ch.300.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.793977, Lat - 26.481545, Dept - PWD (Roads)),

Siamari Salmara road | Salmara | Submarged at Ch. 1st ,2nd and 3rd Km at a depth of 45cm, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 | (Long - 90.773557, Lat - 26.487288, Dept - PWD (Roads)),

Patiladoha Monakocha to Baobari road | Baobari | Submarged from Ch. 200.00 to Ch. 300.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 | (Long - 90.797646, Lat - 26.493940, Dept - PWD (Roads)),

Patiladoha to Dhupuri road | Dhupuri | Submarged from Ch. 200.00 to Ch. 220.00m, Ch.2800.00 to Ch.2830.00m and Ch.2900.00m to Ch. 2925.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.798906, Lat - 26.489634, Dept - PWD (Roads)),

Srijangram - Ujanpara Ambari Road | Ujanpara Ambari | Submarged at Ch.2600.00m to Ch.2630.00m(Depth is 10cm), as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.705871, Lat - 26.356202, Dept - PWD (Roads)),

Tilapara to Ambari Kacharipety Road | Tilapara to Ambari Kacharipety | Embankment erosion at Ch.200.00m, Ch. 250.00m and Ch.400.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.704720, Lat - 26.343670, Dept - PWD (Roads)),

Tilapara to Ambari Kacharipety Road | Tilapara to Ambari Kacharipety | Road surface damaged at different stretches from Ch.630.00m, Ch. 2600.00m. As per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.710783, Lat - 26.344962, Dept - PWD (Roads)),

Tulungia Borghola Road | Tulungia Borghola | Aproach of Br No.6/1 damaged at one End at Ch. 5400.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.680562, Lat - 26.389148, Dept - PWD (Roads)),

Ambari PWD road to Gauranga mandir Road | Ambari PWD road to Gauranga mandir | Shoulder and hard crust damaged at 1st Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.723220, Lat - 26.337210, Dept - PWD (Roads)),

SH-2 to Anganbadi centre Road | SH-2 to Anganbadi centre | Shoulder and hard crust damaged at 1st Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.709410, Lat - 26.330510, Dept - PWD (Roads)),

Abhayapuri to Malegarh road. | Abhayapuri to Malegarh | Land slide & shoulder erroded at Ch. 12th km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.647675, Lat - 26.271010, Dept - PWD (Roads)),

Abhayapuri to Malegarh road | Abhayapuri to Malegarh | Shoulder damaged at Ch. 11th km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.647620, Lat - 26.270745, Dept - PWD (Roads)),

Abhayapuri to Malegarh road | Abhayapuri to Malegarh | Shoulder damaged at Ch. 10th km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.645970, Lat - 26.268709, Dept - PWD (Roads)),

Tulungia Borghola road | Tulungia Borghola | Hill land slide disrupted drain water flow and damaged hard crust at three places of hill portion Ch. 5th & 4th Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.671399, Lat - 26.386708, Dept - PWD (Roads)), Sidalsuti Mererchar road cum embankment. | Sidalsuti Mererchar | Shoulder and brick drain damaged at Ch.9th , 10th and 11th Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.730473, Lat - 26.389184, Dept - PWD (Roads)),

SH2 road | SH2 road | Shoulder and hard crust damaged at Ch.37940.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 | (Long - 90.780225, Lat - 26.311685, Dept - PWD (Roads))

Chapar - SATYAPUR LAKSHIMANDIR TO SAGALKHUTI ROAD LATITUDE:-26.271719 LONGITUDE -90.428868 (Dated 23-06-2023) | Satyapur | Due to rain | (Long - 90.428868, Lat - 26.271719, Dept - PWD (Roads)),

Dhubri 22

BANIAPARA TO CHIRAKUTA ROAD(.)LATITUDE:-26.231677 LONGITUDE -90.262603, (Dated 23-06-2023) | Baniapara | Due to rain | (Long - 90.264782, Lat - 26.231677, Dept - PWD (Roads)), TILAPARA TO NOONMATI ROAD(.) UNDER PMGSY –I FOR THE YEAR 2017-18 PACKAGE NO AS -05-116 BOTH SIDE APPROACH DAMAGE AND ERRODED DUE TO HEAVY RAIN WATER(.) LATITUDE:-26.201662, LONGITUDE -90.331209 AND LATITUDE:-26.201935, LONGITUDE -90.330932 (Dated 23-06-2023) | Noonmati Pt-I | Due to heavy rain | (Long - 90.330932, Lat - 26.201935, Dept - PWD (Roads)),

NH-31 TO BALOKERKHAL ROAD(.) UNDER PMGSY I AT CH. 3.50 KM ERROSION OF SIDE SLOPE OF ROAD AND DAMAGE OF EXISTING ICBP CARRIAGEWAY DUE TO HEAVY RAIN WATER(.) LATITUDE:-26.197589, LONGITUDE -90.339693 (Dated 23-06-2023) | Balokerkhal | Due to rain | (Long - 90.339693, Lat - 26.197589, Dept - PWD (Roads)),

NH-31 TO BALOKERKHAL ROAD(.) UNDER PMGSY I BRIDGE NO. 4/1BOTH SIDE APPROACH DAMAGED DUE TO HEAVY RAIN WATER(.) LATITUDE:-26.20127, LONGITUDE :-90.340139 (Dated 23-06-2023) UNDER PMGSY –I FOR THE YEAR 2017-18 PACKAGE NO AS -05-128 | Balokerkhal | Due to rain | (Long - 90.340139, Lat - 26.201270, Dept - PWD (Roads)), Gauripur - ROAD FROM KENDRIYA VIDYALAYA PANBARI TO ITI ALOMGANG (SIDE BERM ERODED) (Date-22-06-23) | ALOMGANG | (Long - 90.037335, Lat - 26.135215, Dept - PWD (Roads)),

Ghageralga Road BUG Br. To Boraibari Road (.) (HPC DAMAGED AND SIDE BERM DAMAGED) (Date-22-06-23) | Ghageralga | | (Long - 90.027112, Lat - 90.027112, Dept - PWD (Roads)), PANBARI IDGAH TO NOVODOY VIDAYALAYA AT 2ND KM (SIDE BERM DAMAGED) | PANBARI | | (Long - 90.046290, Lat - 26.133457, Dept - PWD (Roads)),

Dhubri - SIDE BERM, SIDE SLOPES WITH HARD CRUST FULLY DAMAGED ON KANURI DIMAKURI ROAD AT BINNACHARA AT CH. 12TH ,13TH & 14TH KM (DATE-22-06-23) | BINNACHARA | | (Long - 89.827607, Lat - 25.992487, Dept - PWD (Roads)),

Bilasipara - T03-UDMARI SALKOCHA ROAD(.) UNDER PMGSY –III FOR THE YEAR 2020-21 PACKAGE NO AS -05-209 SIDE BERM ERROSION AT CH. 5400.00M, 5300.00M, AT SEVERAL STREATCHES | UDMARI SALKOCHA ROAD | dated 21-06-23 to 22-06-2023 | (Long - 90.318317, Lat - 26.260265, Dept - PWD (Roads)),

BAMUNPARA PT-4 TO KAZAIKATA PT-I ROAD | BAMUNPARA PT-4 TO KAZAIKATA PT-I ROAD | dated 21-06-23 to 22-06-2023 | (Long - 90.255290, Lat - 26.226128, Dept - PWD (Roads)), SUAPATA PT-I TO KAZAIKATA PT-I ROAD | SUAPATA PT-I TO KAZAIKATA PT-I ROAD | dated 21-06-23 to 22-06-2023 | (Long - 90.280969, Lat - 26.205678, Dept - PWD (Roads)), KATHALDI PT-III VILLAGE ROAD(.) RCC BRIDGE NO 1/1 | KATHALDI PT-III VILLAGE ROAD | dated 21-06-23 to 22-06-2023 | (Long - 6.902317, Lat - 5.262219, Dept - PWD (Roads)), South Salmara Part - Airkata Jaleswar road to Gunaipani under PMGSY pk AS05153 | Airkata | As per report recived from EE PWRD Airkata Jaleswar road to Gunaipani under PMGSY pk AS05153 road has been damaged at Ch 1500m to ch 1800 lenth 300 m as on 23.06.23 due to heavy rainfall. | (Long - 90.101700, Lat - 25.959000, Dept - PWD (Roads)),

Tarangajhar steel bridge to Airkata road | Tarangajhar | As per report recived from EE PWRD Tarangajhar steel bridge to Airkata road has been damaged at Ch 5th km lenth 50 m as on 23.06.23 due to heavy rainfall. | (Long - 90.148000, Lat - 25.985000, Dept - PWD (Roads)),

Athani - NH-31 AT MAKRIJHORA TO PIAZBARI 1, SIDE BERM AND SURFACE DAMAGED 2NDKM ADN 3RD KM DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.93654 & LONGITUDE: 90.174300). | NH-31 AT MAKRIJHORA TO PIAZBARI 1 | AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 | (Long - 90.174300, Lat - 26.936540, Dept - PWD (Roads)), NH-31 AT SATAGURI TO DALANERALGA PT-II ROAD, SIDE BERM AND SURFACE DAMAGED 1ST KM 2ND KM DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.160343 & LONGITUDE: 90.054166). | NH-31 AT SATAGURI TO DALANERALGA PT-II ROAD, | AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 | (Long - 90.054166, Lat - 26.160343, Dept - PWD (Roads)),

MAHAMAYA IB TO GUTIPARA ROAD, PMGSY, PACKAGE NO. AS-05-43 ROAD SUBMERGED 1ST KM DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.264072 & LONGITUDE: 90.15236). | MAHAMAYA IB TO GUTIPARA ROAD | AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 | (Long - 90.152360, Lat - 26.264072, Dept - PWD (Roads)), NH-31 AT BAGRIBARI TO MAKRIJHORA ROAD, SIDE BERM AND SURFACE DAMAGED AT CH. 2ND KM AND 3RD KM DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.188784 & LONGITUDE: 90.116537). | NH-31 AT BAGRIBARI TO MAKRIJHORA ROAD | AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 | (Long - 90.116537, Lat - 26.188784, Dept - PWD (Roads)), 2ND KM OF BAGRIBARI BANIAMARI ROAD TO SADHUBHASA PT-IROAD SIDE BERM AND SURFACE AT CH.1ST & 2ND KM DUE TO WATER OF GOURANG RIVER (.) (LATITUDE: 26.180808 & LONGITUDE: 90.12114). | 2ND KM OF BAGRIBARI BANIAMARI ROAD TO SADHUBHASA PT-IROAD | AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 | (Long - 90.121140, Lat - 26.180808, Dept - PWD (Roads)),

TOPRAJHOWPARA PT-I TO TOPRAJHOWPARA PT-II ROAD ,SIDE BERM AND SURFACE DAMAGED AT CH. 1ST KM DUE TO WATER GOURANG RIVER (.) (LATITUDE: 26.322367 & LONGITUDE: 90.165705). | TOPRAJHOWPARA PT-I TO TOPRAJHOWPARA PT-II ROAD | AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 | (Long - 90.165705, Lat - 26.322367, Dept - PWD (Roads)),

ı		NIL 21 AT ADIANI TO NOVICED DI AD DOAD CIDE DEDMAND CUDE ACE DANA CRED 10T VAL
		NH-31 AT ARIANI TO NOISERDHAB ROAD SIDE BERM AND SURFACE DAMAGRED 1ST KM , DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.195951 & LONGITUDE: 90.141323).
		NH-31 AT ARIANI TO NOISERDHAB ROAD AFFECTED W.E.F. 18/06/2023 TO 22/06/2023
		(Long - 90.141323, Lat - 26.195951, Dept - PWD (Roads))
		Lakhipur - Kurshakati Salmara PMGSY Road Near Kurshakati As per report of PWD Road
		department, Due to incessant rainfall for several days Kurshakati Salmara PMGSY Road RCC Br. No.
		2/1 & 3/1 CH. 2600M to CH. 2900M Av. depth of submergence 45CM and Bridge approach eroded and affected length 300M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.353121, Lat - 26.057240,
		Dept - PWD (Roads)),
		Rakhalkilla Bazar to To Tikrikilla Shibbari Road Near Rakhalkilla As per report of PWD Road
		department, Due to incessant rainfall for several days Rakhalkilla Bazar to To Tikrikilla Shibbari Road
		at 2nd KM to 3rd KM has been submarged 45 CM and affected length 200M from 18.06.2023 to till date
		i.e. 24.06.2023 (Long - 90.217851, Lat - 25.958184, Dept - PWD (Roads)),
		Chataimari Gumaijhar Road Near Gumaijhar As per report of PWD Road department, Due to
		incessant rainfall for several days Chataimari Gumaijhar Road SPT Br. No. 1/1 at 1st KM, Av. depth of submergence of flash flood from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.213784, Lat -
		25.962286, Dept - PWD (Roads)),
		Lakhipur Khalisabhita Road Near Khalisabhita As per report of PWD Road department, Due to
		incessant rainfall for several days Lakhipur Khalisabhita Road at 14th KM to 15th KM, Bridge No. 15/1
		road submarged 45CM & Bridge Approach eroded and affected length 45M from 18.06.2023 to till date
		i.e. 24.06.2023 (Long - 90.185618, Lat - 25.993028, Dept - PWD (Roads)),
		Gournagar Chataimari Road Near Gournagar As per report of PWD Road department, Due to incessant rainfall for several days Gournagar Chataimari Road at 5th Km road submergence 45CM and
		affected length 50M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.208543, Lat - 25.968998,
		Dept - PWD (Roads)),
		Morichbari to Bausatary Road Near Bausatary As per report of PWD Road department, Due to
Goalpara	12	incessant rainfall for several days Morichbari to Bausatary Road at 1st KM and road submerged 45CM
1		from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.187013, Lat - 25.994671, Dept - PWD (Roads)),
		Lakhipur Jaleswar Road Near Jaleswar As per report of PWD Road department, Due to incessant rainfall for several days Lakhipur Jaleswar Road subway at Rajmita road submarged 60CM from
		18.06.2023 to till date i.e. 24.06.2023 (Long - 90.244209, Lat - 26.031399, Dept - PWD (Roads)),
		Sarkarergaon PWD road to Dharai PWD Road Near Dharai As per report of PWD Road department,
		Due to incessant rainfall for several days Sarkarergaon PWD road to Dharai PWD Road at 1st KM
		sideberm eroded and affected length 110M from 18.06.2023 to till date i.e. 24.06.2023 (Long -
		0.000000, Lat - 0.000000, Dept - PWD (Roads)),
		Gumaijhar to NEC Rd Tikrikilla Near Gumaijhar As per report of PWD Road department, Due to incessant rainfall for several days Gumaijhar to NEC Rd Tikrikilla at 1st KM road breached and affected
		length 90M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD
		(Roads)),
		Hasdoba to Kolabari Majipara Road Near Kolabari As per report of PWD Road department, Due to
		incessant rainfall for several days Hasdoba to Kolabari Majipara Road at CH. 40M Box cell culvert
		Damaged and affected length 3M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
		Lakhipur Khalisavita Road Near Khalisavita As per report of PWD Road department, Due to incessant
		rainfall for several days Lakhipur Khalisavita Road at CH. 850M & CH. 10200M sideberm eroded and
		affected length 30M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000,
		Dept - PWD (Roads)),
		Gournagar Chataimari Road Near Gournagar As per report of PWD Road department, Due to
		incessant rainfall for several days Gournagar Chataimari Road at CH. 4th KM HP No 4/1 damage from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
		Golaghat - Sapekhati cholong pathor road Gomariguri Development Block As per the information
		received from PWD Deptt. road affected due to flash flood of ghiladhari river on 24.06.2023 (Long -
		0.000000, Lat - 0.000000, Dept - PWD (Roads)),
Colo 1 ·	2	Lakhimipathar road Gomariguri Development Block As per the information received from PWD
Golaghat	3	Deptt. road affected due to flash flood of ghiladhari river on 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),
		No1. Lilapur to Indrapur connecting road Gomariguri Development Block As per the information
		received from PWD Deptt. road affected due to flash flood of ghiladhari river on 24.06.2023 (Long -
		0.000000, Lat - 0.000000, Dept - PWD (Roads))
		Rangia - Dipteswari Temple Road. Nakul Report given by pwd (R) Rangia of road eroded Length
		100m, Breath 6m at ch 2.00 Km. Dated 23/06/23 (Long - 91.640577, Lat - 26.426479, Dept - PWD
		(Roads)), Rangia Dhamdhama road Gurkuchi Report given by pwd (R) Rangia of road damage Length 30m,
		Breath 6m at ch 4km Dated 23/06/23 (Long - 91.598102, Lat - 26.454051, Dept - PWD (Roads)),
Kamrup	4	Palashbari - kulshi Garubandha Bangelibia Baregaon Road kulshi Garubandha Bangelibia Baregaon
		Road Erosion due to rainfall on kulshi Garubandha Bangelibia Baregaon Road under Palashbari
		Territorial Road Sub-div as reported by PWRD, Mirza on 23/06/2023 (Long - 25.959410, Lat -
		91.417585, Dept - PWD (Roads)),
		Batarhat Jharobori Lengta Loharghat Road Batarhat Jharobori Lengta Loharghat Road Submerge of

			Road due to Rainfall on Batarhat Jharobori Lengta Loharghat Road under Palashbari Territorial Road Sub-div as reported by PWRD, Mirza on dated 23/06/2023 (Long - 26.014321, Lat - 91.474725, Dept - PWD (Roads))
			Patherkandi - Adamtilla DLF PWD road Lonagai TE Adamtilla DLF PWD road at Longai TE a portion of road has been eroded on 20/06/2023 due to heavy rainfall. approx stretch is 10 sq/ft. (Long - 24.566113, Lat - 92.293053, Dept - PWD (Roads)),
	Karimgan j	3	Adamtilla road to Mohangool BSF Camp road Adamtilla On 18/06/2023 due to heavy rainfall Adamtilla road to Mohangool BSF Camp road at Adamtilla due to landslide the road has been damaged . approx stretch is 120 meter. (Long - 24.596248, Lat - 92.266734, Dept - PWD (Roads)), Adamtilla road to Mohangool BSF Camp road. Adamtilla On 18/06/2023 due to heavy rainfall
			Adamtilla road to Mohangool BSF Camp road at Adamtilla the road has been damaged . approx stretch is 37.3 sq/meter (Long - 24.595505, Lat - 92.267770, Dept - PWD (Roads))
	Kokrajhar	1	Dotma - MONAKOCHA VILLAGE ROAD MONAKOCHA AS PER REPORTED BY VILLAGE MAN ON 24.06.2023, DUE TO WATER LOGGING MONAKOCHA VILLAGE HAS BEEN
	3		DAMAGED (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Nalbari	17	Barkhetri - Dagapara to Balitpar Road": Side-berm erroded & damaged, road surface damaged. Affected length: 4 KM. Dagapara, Lautola, Ghoga, Loharkatha, Sutarkuchi, Adabari As reported by AEE, PWRD, Barkhetri on 24-06-23. (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), hamlakur to kurabori sumberged from ch10.00m to 200.00m and side berm eroded at ch 1.50to 1.80KM. Hamlakur As reported by AEE, PWRD, Barkhetri on 24-06-23. (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Nalbari - Sonamati Katra road Katra As per the report of PWD roads this road is submerged due to rain water dtd 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Tihu - TiHu AKHARA LINK ROAD BALI,SATHIKUCHI SUBMERGED ROAD,LENGTH IS APPROX 2KMS AS PER REPORT JE, PWD ROAD , ON 23/06/23 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), PWD ROADS HARIBHANGA HARIBHANGA, BHOJKUCHI SUBMERGED ROAD,AS PER REPORT JE, PWD ROADS , TOTAL LENGTH APPROX 1.5 KMS,REPORTED ON 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), BARAMA KAITHALKUCHI ROADS SATHIKUCHI SUBMERGED ROAD AS PER REPORT JE, PWD ROADS, LENGTH IS APPROS 500 MTS, REPORTED ON 23/06/23 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Barbhag - Raimadha Village Road Raimadha Flood Affected Report Submitted by AEE, PWD (Roads)), Dokoha Kowarpur Road Dokoha Flood Affected Report Submitted by AEE, PWD (Roads)), Dokoha Kowarpur Road Dokoha Flood Affected Report Submitted by AEE, PWD (Roads)), Pajipar Deharkuchi Road Pajipar Flood Affected Report Submitted by AEE, PWD (Roads)), Pajipar Deharkuchi Road Pajipar Flood Affected Report Submitted by AEE, PWD (Roads)), Parsimulia Barbukia Road Barsimulia Flood Affected Report Submitted by AEE, PWD (Roads)), Parsimulia Barbukia Road Barsimulia Flood Affected Report Submitted by AEE, PWD (Roads)), Ramarkuchi to Kotalkuchi Kotalkuchi Flood Affected Report Submitted by AEE, PWD (Roads)), Parsimulia Barbukia Road Barsimulia Flood Affected Re
	Tamulpur	1	Goreswar - Barghuli Rangia Road Village Bihapara As per report of AEE PWD Goreswar Rural road subdivision, the road from Barghuli to Rangia Road at 2.20 Km got submerged and breached at village Bihapara date of report received 23/06/23 (Long - 91.624028, Lat - 26.476729, Dept - PWD (Roads))
	Total	157	Dinapara date of report received 25/00/25 [(Long - 71.024026, Lat - 20.4/0/27, Dept - r wD (R0ads))
	District/S	X 7 .	
Infrastru	ub- division*	Number	Details
cture Damaged - Bridge	Dhubri	1	Dhubri - APPROACHES OF SPT BR. NO. 3/1 AND ROAD SIDE BERM PARTIALLY DAMAGED AT 2nd, 3RD & 4TH KM ON FALIMARI PMGSY ROAD TO FALIMARI PT. – II (Ch. 1.75 km to
	Total	1	3.50km) (Date-22-06-2023) FALIMARI (Long - 89.979187, Lat - 26.054810, Dept - PWD (Roads))
Infrastru	10.01	1	
cture Damaged	Nil		

- Wildlife		
	District/S ub- division*	Other Details
Infrastru cture Damaged - Others	Bajali	Bajali - Anganwadi Centres Affected 241 No. Daloigaon, Muguria Anganwadi Centre completely damaged, Lat-26.520882 Long- 91.169655. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 235 No. Balattary, Bamunkuchi Anganwadi Centre completely damaged. Lat-26.507139 Long- 91.220878. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 177 No. Bhatigomura, Tihu Dekhata Anganwadi Centre completely damaged. Lat-26.480514, Long- 91.229286. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 53 No. Panara (M), Tihu Dekhata Anganwadi Centre completely damaged. Lat-26.480562, Long- 91.229313. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 157 No. Kuwara , Patacharkuchi Anganwadi Centre completely damaged. Lat-26.515546, Long- 91.253620. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 170 No. Bezkuchi, Patacharkuchi Anganwadi Centre completely damaged. Lat-26.515601, Long- 91.253702. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 39 No. Dumuria, Dumuria Anganwadi Centre completely damaged. Lat-26.669074, Long- 91.25404 Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 98 No. Panpara, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.669074, Long- 26.669074. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 334 No. Dakhin Batiamari, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.592718, Long- 91.611099. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 343 No. Chenglimari, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.661588, Long- 91.216842. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 342 No. Uttar Dhumarpathar, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.66158
	Baksa	Baganpara - Irrigation Canal/Scheme Damaged As per reported SDO irrigation on dated 22/06/2023 Gerua FIS embankment have been damaged (lat-26.6590974,long- 91.4808644), Power Dept. Poles As per nalbari ESD 1 sde total HT pole 2 nos and LT poles 7 nos have been damaged on 23/06/2023 at villages Odla, Borikadonga,Gerua and Tupulia. Odla GPS(lat-26.6823,long-91.4506), Borikadonga (lat-26.6823,long-91.4781), Baska - Culvert Approach Road Damaged Dhanbil to Chaibari Connecting CC Block Road damaged. Cordinate: 26.640733, 91.390791 3)Culvert Breach approach road damaged near Dhira LP School connecting Nikashi Arampur to Nikashi road dated 23/6/2023.(coordinate: 26.745295, 91.373774), Agri Bundh Damaged Agri Bund at Paschim Atiabari dated 23/6/2023 3) Agri Bund at Charaimari dated 23/6/20023 4)Agri bund at village Ahop dated 23/6/2023 5)Agri bund damaged Palashguri Natsupa dated 23/6/2023, Bridge Approach Road Damaged Road breached at Tekelibhanga to Doomni village Doomni Coordinate: 26.644772, 91.34704 date: 21/06/2023. 2)Road – Ahop to palashguri road damaged dated 23/6/2023 3)Bebejia to Chutiapara village road dated 23/6/2023 4)Dihira MV School to Bhutankhuti Road Broken dated 23/6/2023, Washed away Culverts Dihira MV School to Bhutankhuti HPC Culvert washed away at village Arampur on 21/06/2023 Coordinate: 26.644772, 91.347040., Jalah - Power Dept. Poles As per the information received from APDCL, Vill-Bakua Lat-26.689861 Long-91248368 electric conductor 800m, Dated- 21/06/2023, Power Dept. Poles As per the information received from APDCL, Vill Simla Lat-26.728176 Long-91.204357. LT Pole damage dated- 24/06/2023
	Barpeta	Sarthebari - Fisheries/Pond 53 nos of fish pond (total 14.27 Hect) submerged in singra village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 46 nos of fish pond (total 29.30 Hect) submerged in garartari village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 26 nos of fish pond (total 9.06 Hect) submerged in Agdia pathar village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 29 nos of fish pond (total 4.26 Hect) submerged in Besimari pam village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 125 nos of fish pond (total 24.60 Hect) submerged in joshoda pam village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 30 nos of fish pond (total 8.66 Hect) submerged in Bogchara village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 56 nos of fish pond (total 8.93 Hect) submerged in Kaljahi pathar village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 56 nos of fish pond (total 7.27 Hect) submerged in Buri khamar village, Report submit by fishery

	deptt on 23/6/2023, Fisheries/Pond 25 nos of fish pond (total 10.60 Hect) submerged in Rangia gaon village, Report submit by fishery
	deptt on 23/6/2023,
	Fisheries/Pond 25 nos of fish pond (total 10.73 Hect) submerged in Rangia nadir pam village, Report submit by fishery deptt on 23/6/2023,
	Fisheries/Pond 18 nos of fish pond (total 3.40 Hect) submerged in Gohiya nadir pam village, Report submit by
	fishery deptt on 23/6/2023, Fisheries (Pand 00 ness of fish pand (total 22.80 Heat) submarged in carivable will acc. Percent submit by fishery
	Fisheries/Pond 90 nos of fish pond (total 22.80 Hect) submerged in sariyahkuchi village, Report submit by fishery deptt on 23/6/2023,
	Chenga - Road Breaches Niz Chenga to Bampara Road breach length 7 m. Reported by pwd roads.Date-24-06-2023
Biswanat h	Gohpur - Power Dept. Poles 3 nos 8.5 PSC pole uprooted at Chengmora Jaranigaon on 22/06/23
11	Boitamari - Fisheries/Pond 2 no of fisheries damaged at vill- Borghola pt II (2 ha) and Sankarghola Pt-II (0.6 ha)
	submitted on 23/06/2023 by Fishery Dept. GPS cordination: Lat:26.27479, Long: 90.60014 (Borghola Pt-II) and lat:
	26.301541, long: 90.535311 (sankarghola pt-II), Culvert Approach Road Damaged Shankarghola Kherpuji Road, Nature of damage: CD damage at 1st km.
	Longitude- 90.532007, Latitude- 26.309694. As per report received from PWRD, Bongaigaon. dated- 23/06/2023,
	Manikpur - Fisheries/Pond 7 nos of fisheries damaged at vill-Nowagaon 2.4 hac. submitted on 23/06/2023 by Fishery Dept. GPS coordinate is-
	26.406434/90.827182,26.40647/90.827136,26.407253/90.827217,26.412411/90.84218,26.412742/90.842662,26.407
	274/90.826512,26.410221/90.844995,
Bongaiga	Bridge Approach Road Damaged Nowagaon Rangapani road to Numberpara Bazar road, SPT Bridge No. 1/1 over Manas river damaged and road with approach eroded. Latitude: 26.400121 Longitude: 90.813742, as per report
on	received from PWRD, Bongaigaon, dated-23.06.2023,
	Bridge Approach Road Damaged Bashbari Chalabila Road, SPT Bridge No. 1/1 partially damaged along with both side approach. Latitude: 26.420455 Longitude: 90.7763, as per report received from PWRD, Bongaigaon, dated-
	23.06.2023,
	Culvert Approach Road Damaged Hapachara Barbila to Silghagri road, Submarged at Ch. 2nd, 3rd and 4th Km and slab culvert No. 4/1 partially damaged Latitude: 26.438659 Longitude: 90.744471, as per report received from
	PWRD, Bongaigaon, dated-23.06.2023,
	Srijangram - Culvert Approach Road Damaged Narayan Das Thakur Ata Satra road, HP culvert damaged at
	Ch.1200.00m and road side slope damaged at various point at Ch. 1st k.m. Longitude- 90.7830946, Latitude- 26.315759. As per report received from PWRD, Bongaigaon, dated- 23.06.2023.
	Mangaldoi - Culvert Approach Road Damaged As reported by Irrigation Dept. damaged road crossing slab culvert
Darrang	in main canal at CH 10000m of CM Dutta Bund FIS at village Bezpara. Approx. length of damage is 4-5m Dated 24/06/2023.
	Gauripur - Culvert Approach Road Damaged APPROCHES OF CULVERT NO. 1/1 & 2/1 & SIDE BERM
	ERRODED AT 1ST KM, 2ND KM ON DG ROAD AT RLY. LEVEL CROSSING TO TIAMARI PT. II VIA
DI 1 :	ROYPARA ,(Location-Tiamari),(Date-22-06-23),(LAT – 26.061613 LONG – 89.962487), Dhubri - Culvert Approach Road Damaged APPROACHES OF CULVERT NO. 1/1 AND ROAD SIDE BERM
Dhubri	ERRODED BY HEAVY RAINFALL ON 4TH KM OF DJG ROAD TO 1384 NO JHAGRARPAR PT. IV LP
	SCHOOL ,(Location-Jhagrapar),(Date-22-06-23),(LAT- 26.054167, LONG- 89.959457), Bilasipara - Power Dept. Poles PSC Pole - 7.5 mtr-6 No's 8.5 mtr-7 No's Damaged Conductor (in KM) HT- 2, LT-
	3 Nos. on dated 23-06-23,
	Golaghat - Road Breaches As per the information received from BRO (Gomariguri) Breach at Main road section near rupkolia bridge under Chowdang Pathar GP due to flash flood of ghiladhari river on 24.06.2023,
Golaghat	Agri Bundh Damaged As per the information received from BRO (Gomariguri) Breach of Agribund at 2 No.
	chowdandpathar LP school due to flash flood of ghiladhari river on 24.06.2023
	North Ghy - Irrigation Canal/Scheme Damaged 5 Nos. of electrical/solar pump(PMKSY-HKKP) of beneficiary belonging to village Athiaboi and Bezera were affected on 23.06.2023 as per report received from AEE, Jalukbari
Kamrup	Sub-Div (Irrigation), Amingaon,
Kamrup	Palashbari - Culvert Approach Road Damaged Damage culvert due to rainfall on Loharghat Bazar to Bagan via
	kochpara Road under palashbari Territorial Road sub-div, as reported by PWRD Mirza on Dated: 23-06-2023, GPS Cordinates 25.973052, 91.47445
	Nowboicha - Power Dept. Conductors 15.20 KM conductor damaged due to Singra River Flood on 17.06.2023 to
Lakhimpu	22.06.2023. Report received from APDCL, Nowboicha on 23.06.2023., Power Dept. Poles 13 Nos. of poles damaged due to Singra River Flood on 17.06.2023 to 22.06.2023. Report
r	received from APDCL, Nowboicha on 23.06.2023.,
	Subansiri - Bamboo Foot Bridge As reported by the Dkakuakhana territorial road division, Ghilamara the Bamboo foot Bridge on Napam to Koibatra Gaon is damaged (L=100M) on 23/06/2023
	Paschim Nalbari - PWSS Damaged Total 8 nos. of PWSS namely Barhelacha PWSS, Kheluwa- Barbila PWSS,
	Lakhopur PWSS, Ghilzari PWSS, Jagara PWSS, Kendubari MPWSS, Pahlangpara PWSS, Gamarimuri PWSS are
Nalbari	partially submerged by flood and rain water. Information received from PHE Department on 23/06/2023, Banekuchi - PWSS Damaged on 23/06/2023 at 12 PM Distribution of pipe line of Uttar Pub Dharmapur PWSS has
1.310411	been damaged appr. 60 mtr. length near Madhupur to Bihampur road report from Line department.,
	Fisheries/Pond Tentative ponds & Tanks submerged .Affected water area 22 Ha and aprroxi.220 nos of farmer
	affected may be increase or decrease during post flood assessment reported by fishery department on 23/06/2023.,

r	ı	
		PWSS Damaged On 22/06/2023 the PWSS Schemes of 1)Nakerbari PWSS,2)Balizar PWSS ,3)Garber PWSS ,4)Uttar Bausiapara PWSS,5)Uttar Kaithalkuchi PWSS, 6)Kaithalkuchi PWSS and 7)Madhupur PWSS submerged and partially damaged report by Line department,
		Nalbari - Handloom & Textile Deptt 80 nos of handloom weavers are sumberged due to flood as per the report of handloom and textile department on 23.06.23,
		Tihu - Fisheries/Pond TOTAL SUBMERGED POND LAND 158 HA AS PER REPORT DFDO,FISHERY, ON 23/06/23,
		Health Sub-Centre AS PER REPORT DY.SUPERINTENDENT, TIHU FRU HWS & JALKHANA MPHC SUBMERGED ,DATE OF REPORTING 23/06/2023, Public Health Engineering (PHE) TOTAL SUBMERGED PWSS 6 NOS UNDER TIHU & GOBARADAL PHE
		SUB DIVISION AS PER REPORT SUBMITTED BY JE,PHE, ON 23/06/2023,
		Ghograpar - Power Dept. Poles 7 HT & 5 LT pole has been damaged due to recent flood on 23/06/2023 as per reported APDCL,
		Power Dept. Conductors 3.94 KM conductor has been damaged due to flood on 23/06/2023 as per reported APDCL ,
		Handloom & Textile Deptt On 23/06/2023, 40-45 nos of weavers has been affected by recent flood as per reported handloom and Textile dept.,
		Anganwadi Centres Affected 19 nos of AWC centre has been damaged on 23/06/2023 due to recent flood as per reported by Social welfare Dept.,
		Secondary Schools Damaged Borajol HS School has been damaged on 22/06/2023 due to flood occures at village Borajol as per reported Head Master Borajal HS
		Harisinga - Irrigation Canal/Scheme Damaged Geruapara FIS Chainage- 1080 m broken culvertlongitude: 91.83• latitude: 26.63• Village- Patala due to heavy rainfall on 21st June 2023,
	Udalguri	Irrigation Canal/Scheme Damaged Geruapara FIS. Erosion of embankment of canal due to flood. Chainage 1400 m. Village- Patala on 21stJune2023.,
		Udalguri - Irrigation Canal/Scheme Damaged CC lining damaged at Ch. 7730m of B2M canal (Approx 10 Mtrs.) under DIP of village No.1 Chandana Tea Estate Lat- 26.754808 Long- 92.088783 on 23-06-2023,.
	District/S ub-	Details
	division*	
	Baksa	Baska - River Bank Erosion L/B of Mora Pagladiya river at Village 3 No Lokpala 2) River Bank Erosion R/B of Mora Pagladiya river at Village 2 No Lokpala near Lokpala LP School River Bank Erosion L/B of Mora Pagladiya river at Village 3 No Lokpala 2) River Bank Erosion R/B of Mora Pagladiya river at Village 2 No Lokpala near Lokpala LP School 0 (Long - 26.624869, Lat - 91.404756)
	Barpeta	Chenga - Chatta, Roumari Gaon, Roumari Pathar, Chenimari Near the B/dyke on R/B of river Brahmaputra from Adabari to Kukarjan from ch 5.80 km to 33.232 kmbreach occurred in three stretches 400 m, 550 m and 500 m respectively Report received from water resource department on 24.06.2023 0 (Long - 0.000000, Lat - 0.000000)
	Biswanat h	Gohpur - at No 2 Bickrampur area. Mild erosion is observed at R/Bank embankment of river Sessa of 30 mtr on 24/06/23 0 (Long - 93.728440, Lat - 26.964250), Halem - Paken Mild shador of the color of the co
	Dhubri	to Kharoi outfall.Length =10m.(avg.width=0.10m) on 24/06/2023 0 (Long - 93.625660, Lat - 26.798990) South Salmara Part - Sundarpara Pt-III, Sundarpara Pt- IV As per field information recived fro LM 44 nos families has been eroded due erosion by river Brahmaputra at village Sundarpara PT-III on 19.06.23 to 23.06.23. area aprox leanth 1500 m breadth 500 m. As per field information recived fro LM 62 nos families has been eroded due erosion by river Brahmaputra at Village Sundarpara PT-IV on 19.06.23 to 23.06.23. area aprox leanth 2 km breadth 700 m. 287 (Long - 90.089000, Lat - 25.963300)
Erosion		Kamalpur - Bhehbari area on L/B of Puthimari Embankment. Active erosion found at up stream of Bhehbari of about 150 mtr on L/B of Puthimari Embankment. Reported by Rangia WR Sub-Division on 23.06.2023. 0 (Long - 91.687136, Lat - 26.463514),
	Kamrup	Rangia - Barlesakona, Madhukuchi, Assam. As per report given by AEE, WR Department, Rangia dated 23/06/2023 river bank erosion at left bank of river puthimari breath-300m approx. 0 (Long - 91.682713, Lat - 26.424333),
		Hajo - AdhiarpR Erosion of R/B of river bhairatula Jaana at village deharkuria for length of 55m at 23/062023 as reported by WRD 0 (Long - 26.410000, Lat - 91.280000)
	Kokrajhar	Bhawraguri - Rimijhimighop As reported by Executive Engineer, Kokrajhar WRD & Sectional Officer, Gossaigaon WRD on dated 23-06-2023 1. River Bank Erosion observed at village Rimijhimighop Reach Length 200 M on L/B of River Gongia. 0 (Long - 90.118611, Lat - 26.403055)
	Nalbari	Barkhetri - Hanapara, Burlitpar L/B of river pagladia from From dusutimukh to adabari at Burlitpar, length 350m as reported by AEE, WRD, Mukalmua on 24-06-23. Six(6) nos of families shifted their houses due to erosion of river pagaldia at Hanapara & Burlitpar. 25 (Long - 0.000000, Lat - 0.000000), Barbhag - Kamarkuchi, Ganagpar, Sadhnapar,Bihdia, Koria Erosion on L/B of river Pagladia from Sonkuriha to Dusutimukh from ch 28.20 K.M. to 35.50 K.M. as per report submitted by Asst. Executive Engineers, Mukamua W.R. Sub-Division, Mukalmua. Population affected 20000. Longitude: 91.4779 Latitude: 26.3511 Erosion on R/B of river Pagladia from Bijulighat to Adabari from ch 0.00 K.M. to 5.80 K.M. as per report submitted by Asst. Executive Engineers, Mukamua W.R. Sub-Division, Mukalmua on 24/06/2023. Population affected 20000, 15000 Longitude: 91.4480 Latitude: 26.3224 Erosion on R/B of river Pagladia from NT road to Bijulighat from ch 31.00 K.M. to 41.00 K.M. as per report submitted by Asst. Executive Engineers, Mukamua W.R. Sub-Division, Mukalmua on 24/06/2023. Population affected 20000, 15000 Longitude: 91.4553, 91.4722 Latitude: 26.3753, 26.3535 0

		(Long - 0.000000, Lat - 0.000000)
	Sonitpur	Thelamara - 1. Baligaon Bangaligaon 2. Kalakuchi Date-24/06/2023, As reported by Tezpur Water Resource Tezpur Division on 24/06/2023-1) Active bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri,Length = 200.00m, Latitude: 26.736022, Longitude: 92.558699 2) Bank erosion is observed at Kalakuchi(Ch 200m to 350m) on the R/Bank of river Gabharu since 22.6.2023. Latitude-26.746466 and Longitude-92.616082 0 (Long - 92.558699, Lat - 26.736022)
	South Salmara	Mankachar - Nepurer Alga As per report received from Gaon Pradhan, erosion is going on in revenue village Nepurer Alga by the river Brahmaputra. 7 Nos. temporary house hold from Nepurer Alga are shifted to safe place, for these purpose 2 Nos. of engine Boat deployed on 24-06-2023. 65 (Long - 25.748368, Lat - 89.844128)
	Tamulpur	Goreswar - Village Bholabatabari As per information received on dated 23/06/2023 from Soil conservation department R/B of subtributary river Naobandha about 60 m of Naobandha Suklai Erosion protection got eroded at village Bholabatabari 0 (Long - 0.000000, Lat - 0.000000), Tamulpur - 1. Hatiduta 2. Kandulimara 1. As per the reports date 22/06/23 from Tamulpur Sub-division (Irrigation Head workI.S. due Division(Irrigation) recieved on 24/06/2023 mentions head work of Daranga I.S. at village Cblock- Tamulpur) due to flash flood. 2. As per report received on date 24/06/2023 from Water Resource Dept. severe erosion have been occured at L/B of Pagladia river at Kandulimara Village. Total length of erosion is 100M. (Long- 91.5030174, Lat-26.6629458) 0 (Long - 91.598244, Lat - 26.590530)
	Udalguri	Mazbat - 1. Mazgaon 2. Kalbari 3. No.1 & No 2 Kadabil village 1. Severe erosion occurred on B/B of river Pagla at Mazgaon village for a length of 500m on 23/6/2023(Lat: 26.731623, Long: 92.304411 2. 1. Severe erosion occurred on R/B of river Dhansiri at Kalbari village for a length of 500m on 23/6/2023(Lat: 26.706159, Long: 92.290079 3. 1. Severe erosion occurred on L/B of river Butiamari at No.1 Kadabil and No.2 Kadabil village for a length of 600m on 23/6/2023. (Lat: 26.861808, long: 92.311488) 0 (Long - 0.000000, Lat - 0.000000)
Landslid	District/S ub- division*	Details
e	Karimgan j	RK Nagar - kalinagar part 2 feeder name 11kv Bhairab Nagar Feeder 1 no. LT Pole. due to landslide on date 22-06 2023 as reported Ramkrishnanagar Electrical Sub-division APDCL on date 23-06-203 0 (Long - 92.462114, Lat - 24.568653)
Urban	District/S ub- division*	Details
Flood	Darrang	Dalgaon - Kharupetia Town(Ward No-1) As per report received from LM, water logging at kharupetia town ward no.1 under dalgaon revenue circle as on 24-06-2023 100 (Long - 92.149805, Lat - 26.519547)
		*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)