



Customer: ANNE CHAMPAGNE
Property: 1908 W 25TH ST
HOUSTON, TX 77008
Home: 1908 W 25TH ST
HOUSTON, TX 77008

Home: (832) 289-1530
Cell: (832) 289-1530

Claim Rep.: Brandon Hunt
Company: TRAVELERS PERSONAL INSURANCE COMPANY
Business: P.O. Box 650293
dallas, TX 75265-0293

Business: (346) 406-7221
E-mail: bhunt2@travelers.com

Claim Number: I8C6659001H

Policy Number: 0DHD93615843239633 1

Type of Loss: WATER DAMAGE - NON-WEATHER RELATED

Date of Loss: 8/13/2024 12:00 AM

Date Completed: 2/27/2025 5:01 AM

Price List: TXHO8X_FEB25

Coverage	Deductible	Policy Limit
Dwelling	\$4,710.00	\$471,000.00
Other Structures	\$0.00	\$47,100.00
Contents	\$0.00	\$235,500.00

Dear ANNE CHAMPAGNE:

We have prepared this estimate regarding your loss or damage. A letter that explains your coverage and benefits is being sent to you separately. Because the information in an estimate serves as the basis for a determination of your benefits, you (and if applicable, your contractor) should review this estimate carefully. Let us know immediately (and prior to beginning any work) if you have any questions regarding the estimate.

Under most insurance policies, claim settlement begins with an initial payment for the actual cash value of the covered loss or damage. To determine actual cash value, we estimate the item's replacement cost, and then, if appropriate, take a deduction for depreciation. Depreciation represents a loss in value that occurs over time. In determining the amount to deduct for depreciation, if any, to apply to an item, we consider not just the age of the item immediately prior to the loss or damage but also its condition at that time. For each line item included in this estimate, the estimate shows not only the estimated replacement cost value, but also the amount of depreciation (if any) applied to the item, the item age and item condition upon which the depreciation (if any) was based and the item's actual cash value.

Thank you for allowing us to be of service, and thank you for choosing TRAVELERS PERSONAL INSURANCE COMPANY for your insurance needs.

You can check the status of your claim, view your policy and much more at www.mytravelers.com.

Answers to commonly asked questions can be found at <https://www.travelers.com/claims/manage-claim/property-claim-process>

You can also upload documents directly to your claim at www.travelers.com/claimuploadcenter.

For more information about how the claim process works and where to find services to help you recover, visit travelers.com/claim.

Guide to Understanding Your Property Estimate

Your Estimate Cover Sheet

The cover sheet of your estimate includes important information such as:

- (A) Your Travelers claim professional's contact information
 - (B) Your claim number
 - (C) The types of coverage under your policy, including the applicable deductibles and policy limits.
 - (D) Your estimate may include policy sublimits for specific items, such as money. Each sublimit has a unique ID tag. That ID tag will appear next to any line item subject to the sublimit.

Your Estimate Detail

This is where the details about your lost or damaged property can be found.

- **(E) Description** – Details describing the activity or items being estimated.
 - **(F) Quantity** – The number of units (for example, square feet) for an item.
 - **(G) Unit** – The cost of a single unit.
 - **(H) Replacement Cost Value (RCV)** – The estimated cost of repairing a damaged item or replacing an item with a similar one. RCV is calculated by multiplying Quantity x Unit Cost.
 - **(I) Age** – The age of the item.
 - **(J) Life** – The item's expected life assuming normal wear and tear and proper maintenance.
 - **(K) Condition** – The item's condition relative to the expected condition of an item of that age. (New, Above Average, Average, Below Average, Replaced)
 - **(L) Depreciation %** – The percentage of the loss of value that has occurred over time based on factors such as age, life expectancy, condition, and obsolescence.
 - **(M) Depreciation** – Loss of value that has occurred over time based on factors such as age, life expectancy, condition, and obsolescence. If depreciation is recoverable, the amount is shown in **()**. If depreciation is not recoverable, the amount is shown in **< >**.
 - **(N) Actual Cash Value (ACV)** – The estimated value of the item or damage at the time of the loss. Generally, ACV is calculated as Replacement Cost Value (RCV) minus Depreciation.
 - **(O) Labor Minimums** – The cost of labor associated with drive time, setup time and applicable administrative tasks required to perform a minor repair.

Your Estimate Summary

For each type of coverage involved in your estimate there is a summary section that shows the total estimated costs (RCV and ACV) and net claim amount for the coverage type. The example to the right depicts a Dwelling coverage summary.

- **(P) Line Item Total** – The sum of all the line items for that particular coverage.
 - **(Q) Total Replacement Cost Value** – The total RCV of all items for that coverage.
 - **(R) Total Actual Cash Value** – The total ACV of all items for that coverage.
 - **(S) Deductible** – The amount of the loss paid by you. A deductible is generally a specified dollar amount or a percentage of your policy limit.
 - **(T) Net Claim** – The amount payable to you after depreciation and deductible have been applied. This amount can never be greater than your coverage limit.
 - **(U) Total Recoverable Depreciation** – The total amount of depreciation you can potentially recover.

Common Units of Measure

EA - Each	CY - Cubic Yard
LF - Linear Foot	SQ - Square
SF - Square Foot	HR - Hour
SY - Square Yard	DA - Day
CF - Cubic Foot	RM - Room

YOUR ESTIMATE COVER SHEET

 Claim Professional: John Doe Business: One Tower Square Hartford, CT 06183	 Claim Number: ABC1234001H Date of Loss: 10/10/2011 3:00 PM	 Coverage Dwelling Other Structures Contents	 Deductible \$500.00 \$0.00 \$0.00	Business: (860) 555-9876 E-mail: jdoe@travelers.com	Type of Loss: Fire Price List: CTH47X_DC11
			"Money, Gift Cards, etc. [S 3:1]		
			\$200.00/\$200.00		

YOUR ESTIMATE DETAIL

YOUR ESTIMATE SUMMARY

Summary for Dwelling	
P	Line Item Total Comm Rep/Renov Tax 113.35
Q	Replacement Cost Value Less Depreciation \$1,896.36 (272.13)
R	Actual Cash Value Less Deductible \$1,626.23 (1,000.00)
T	Net Claim \$626.23
U	Total Depreciation Less Non-Recoverable Depreciation Total Recoverable Depreciation Net Claim if Depreciation is Recovered 272.13 <179.03> 93.10 \$719.33

We encourage you to contact us if you have additional questions regarding your claim or anything in this guide.

For information about how the claim process works and where to find services to help you recover, visit travelers.com/claim.



ANNE_CHAMPAGNE**Packout**


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
1. Provide box, packing paper & tape - small size									
60.00 EA	2.93	33.34	38.06	247.20	0/NA	Avg.	0%	(0.00)	247.20
2. Provide box, packing paper & tape - medium size									
55.00 EA	3.87	40.37	46.10	299.32	0/NA	Avg.	0%	(0.00)	299.32
3. Provide box, packing paper & tape - large size									
50.00 EA	5.23	49.59	56.62	367.71	0/NA	Avg.	0%	(0.00)	367.71
4. Provide box, packing paper & tape - extra large size									
50.00 EA	7.40	70.18	80.10	520.28	0/NA	Avg.	0%	(0.00)	520.28
5. Provide stretch film/wrap*									
2.00 RL	29.83	11.32	12.92	83.90	0/NA	Avg.	0%	(0.00)	83.90
6. Provide furniture lightweight blanket/pad									
25.00 EA	9.07	43.01	49.10	318.86	0/NA	Avg.	0%	(0.00)	318.86
7. Provide furniture heavyweight blanket/pad									
25.00 EA	18.26	86.58	98.84	641.92	0/NA	Avg.	0%	(0.00)	641.92
8. Moving van (16'-20') and equipment - per day*									
2.00 EA	175.77	34.80	70.30	456.64	0/NA	Avg.	0%	(0.00)	456.64
9. Off-site storage & insur. - climate controlled - per month*									
625.00 SF	1.62	100.24	202.50	1,315.24	0/NA	Avg.	0%	(0.00)	1,315.24
10. Inventory, Packing, Boxing, and Moving charge - per hour									
66.00 HR	52.59	343.62	694.18	4,508.74	0/NA	Avg.	0%	(0.00)	4,508.74
Crew of 4 x 8 hours for pack-out + Crew of 4 x 6 hours for pack-back									
11. Contents Evaluation and/or Supervisor/Admin - per hour									
22.00 HR	68.43	149.04	301.10	1,955.60	0/NA	Avg.	0%	(0.00)	1,955.60
6 hours for pack-out + 4 hours for pack-back									
Totals: Packout		962.09	1,649.82	10,715.41				0.00	10,715.41

Dwelling**Dwelling**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
MITIGATION									
12. Equipment setup, take down, and monitoring (hourly charge)									
8.00 HR	64.46	0.00	0.00	515.68	0/NA	Avg.	0%	(0.00)	515.68
13. Equipment setup, take down, and monitoring (hourly charge)									
3.00 HR	64.46	0.00	0.00	193.38	0/NA	Avg.	0%	(0.00)	193.38
14. Haul debris - per pickup truck load - including dump fees									
1.00 EA	180.17	0.00	0.00	180.17	0/NA	Avg.	NA	(0.00)	180.17
REBUILD									

CONTINUED - Dwelling

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
15. Dumpster load - Approx. 12 yards, 1-3 tons of debris									
1.00 EA	471.60	0.00	94.32	565.92	0/NA	Avg.	NA	(0.00)	565.92
16. General Laborer - per hour									
8.00 HR	49.11	0.00	78.58	471.46	0/NA	Avg.	0%	(0.00)	471.46
Post construction cleanup as needed									
17. Detach & Reset Outlet									
12.00 EA	27.05	0.00	64.92	389.52	0/25 yrs	Avg.	0%	(0.00)	389.52
18. Remove Outlet or switch cover									
30.00 EA	0.84	0.00	5.04	30.24	0/25 yrs	Avg.	NA	(0.00)	30.24
19. Install Outlet or switch cover									
30.00 EA	3.27	0.00	19.62	117.72	0/25 yrs	Avg.	0%	(0.00)	117.72
Total: Dwelling		0.00	262.48	2,464.09				0.00	2,464.09

First Floor

Pantry
Height: 8'


99.96 SF Walls	13.76 SF Ceiling
113.72 SF Walls & Ceiling	13.76 SF Floor
1.53 SY Flooring	12.43 LF Floor Perimeter
14.88 LF Ceil. Perimeter	

Door
2' 5 7/16" X 7' 9 5/16"
Opens into KITCHEN

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
20. R&R Quarter round - for wood flooring									
12.43 LF	4.19	3.09	11.04	66.21	5/25 yrs	Avg.	20%	(12.56)	53.65
21. Paint baseboard, oversized - one coat									
12.43 LF	1.28	0.15	3.22	19.28	5/15 yrs	Avg.	33.33%	(6.43)	12.85
22. Paint door/window trim & jamb - 2 coats (per side)									
1.00 EA	38.24	0.47	7.74	46.45	0/15 yrs	Avg.	0%	(0.00)	46.45
FLOORS:									
23. R&R Engineered wood floor - floating - specs from ind analysis									
13.76 SF	14.05	9.93	40.66	243.92	5/50 yrs	Avg.	10%	(21.82)	222.10

CONTINUED - Pantry


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Totals: Pantry		13.64	62.66	375.86				40.81	335.05



Window
Window
Window

Dining Room
Height: Peaked


120.82 SF Walls	37.93 SF Ceiling
158.75 SF Walls & Ceiling	40.30 SF Floor
4.48 SY Flooring	11.57 LF Floor Perimeter
11.75 LF Ceil. Perimeter	



Missing Wall - Goes to Floor
Missing Wall
Missing Wall

Subroom: Dining Room (1)
Height: Peaked

57.43 SF Walls	45.97 SF Ceiling
103.40 SF Walls & Ceiling	46.54 SF Floor
5.17 SY Flooring	5.08 LF Floor Perimeter
24.72 LF Ceil. Perimeter	




Missing Wall
Missing Wall
Missing Wall
Missing Wall

Subroom: Dining Room (2)
Height: Peaked

94.89 SF Walls	29.89 SF Ceiling
124.78 SF Walls & Ceiling	33.36 SF Floor
3.71 SY Flooring	9.41 LF Floor Perimeter
27.66 LF Ceil. Perimeter	

9' 1/16" X 11'
3' 7 1/16" X 11'
1' 9 1/4" X 11'
9' 1/16" X 11'


Opens into ROOM2
Opens into Exterior
Opens into Exterior
Opens into ROOM1


Subroom: Dining Room (3)
Height: Peaked

63.25 SF Walls	46.32 SF Ceiling
109.57 SF Walls & Ceiling	48.75 SF Floor
5.42 SY Flooring	4.38 LF Floor Perimeter
15.62 LF Ceil. Perimeter	

- Missing Wall** **9' 1/16" X 11"** **Opens into DINING_ROOM**
Missing Wall **9' 1/16" X 11"** **Opens into ROOM3**
Missing Wall - Goes to Floor **11' 1" X 10' 10"** **Opens into MAIN**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
24. R&R Quarter round - for wood flooring									
30.43 LF	4.19	7.56	27.02	162.08	5/25 yrs	Avg.	20%	(30.73)	131.35
25. Paint baseboard, oversized - one coat									
30.43 LF	1.28	0.38	7.88	47.21	5/15 yrs	Avg.	33.33%	(15.73)	31.48
FLOORS:									
26. R&R Engineered wood floor - floating - specs from ind analysis									
168.96 SF	14.05	121.97	499.18	2,995.04	5/50 yrs	Avg.	10%	(267.87)	2,727.17
Totals: Dining Room		129.91	534.08	3,204.33				314.33	2,890.00


Closet under stairs
Height: Sloped

49.39 SF Walls	25.33 SF Ceiling
74.72 SF Walls & Ceiling	18.70 SF Floor
2.08 SY Flooring	15.45 LF Floor Perimeter
21.66 LF Ceil. Perimeter	

- Door** **2' 4" X 5' 6"** **Opens into KITCHEN_OFF2**


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
27. R&R Quarter round - for wood flooring									
15.45 LF	4.19	3.84	13.72	82.29	5/25 yrs	Avg.	20%	(15.61)	66.68
28. Paint baseboard, oversized - one coat									
15.45 LF	1.28	0.19	4.00	23.97	5/15 yrs	Avg.	33.33%	(7.99)	15.98
29. Paint door/window trim & jamb - 2 coats (per side)									
1.00 EA	38.24	0.47	7.74	46.45	0/15 yrs	Avg.	0%	(0.00)	46.45

- FLOORS:**


CONTINUED - Closet under stairs

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
30. R&R Engineered wood floor - floating - specs from ind analysis									
18.70 SF	14.05	13.50	55.26	331.49	5/50 yrs	Avg.	10%	(29.65)	301.84

Totals: Closet under stairs	18.00	80.72	484.20				53.25	430.95
------------------------------------	--------------	--------------	---------------	--	--	--	--------------	---------------



Living Room
Height: 11'

359.62 SF Walls	75.24 SF Ceiling
434.86 SF Walls & Ceiling	75.24 SF Floor
8.36 SY Flooring	26.96 LF Floor Perimeter
61.12 LF Cel. Perimeter	

Door
14' 2" X 7'
Opens into Exterior
Missing Wall - Goes to Floor
11' 1" X 10' 10"
Opens into ROOM1
Window
3' X 1' 7 3/16"
Opens into Exterior
Window
3' X 1' 7 3/16"
Opens into Exterior
Window
3' X 1' 7 3/16"
Opens into Exterior

Subroom: Living Room (3)
Height: Tray

33.17 SF Walls & Ceiling	33.17 SF Ceiling
2.17 SY Flooring	19.51 SF Floor

Missing Wall
4' 5" X 11'
Opens into ROOM9
Missing Wall
4' 5" X 11'
Opens into ROOM7
Missing Wall
4' 5" X 11'
Opens into MAIN
Missing Wall
4' 5" X 11'
Opens into MAIN



Subroom: Living Room (7)

Height: Tray


33.17 SF Walls & Ceiling
2.17 SY Flooring

33.17 SF Ceiling
19.51 SF Floor

Missing Wall
Missing Wall
Missing Wall
Missing Wall

4' 5" X 11'
4' 5" X 11'
4' 5" X 11'
4' 5" X 11'

Opens into ROOM11
Opens into ROOM7
Opens into ROOM9
Opens into ROOM13



Subroom: Living Room (5)

Height: Tray


33.17 SF Walls & Ceiling
2.17 SY Flooring

33.17 SF Ceiling
19.51 SF Floor

Missing Wall
Missing Wall
Missing Wall
Missing Wall

4' 5" X 11'
4' 5" X 11'
4' 5" X 11'
4' 5" X 11'

Opens into ROOM13
Opens into ROOM9
Opens into MAIN
Opens into MAIN



Subroom: Living Room (4)

Height: Tray


33.17 SF Walls & Ceiling
2.17 SY Flooring

33.17 SF Ceiling
19.51 SF Floor

Missing Wall
Missing Wall
Missing Wall
Missing Wall

4' 5" X 11'
4' 5" X 11'
4' 5" X 11'
4' 5" X 11'

Opens into ROOM5
Opens into ROOM10
Opens into ROOM12
Opens into MAIN

**Subroom: Living Room (2)**

33.17 SF Walls & Ceiling
2.17 SY Flooring

Height: Tray

33.17 SF Ceiling
19.51 SF Floor

Missing Wall

4' 5" X 11'

Opens into ROOM8

Missing Wall

4' 5" X 11'

Opens into MAIN

Missing Wall


4' 5" X 11'

Opens into ROOM6

Missing Wall

4' 5" X 11'

Opens into ROOM10

**Subroom: Living Room (6)**

33.17 SF Walls & Ceiling
2.17 SY Flooring

Height: Tray

33.17 SF Ceiling
19.51 SF Floor

Missing Wall

4' 5" X 11'

Opens into ROOM12

Missing Wall

4' 5" X 11'

Opens into ROOM10

Missing Wall


4' 5" X 11'

Opens into ROOM6

Missing Wall

4' 5" X 11'

Opens into MAIN




Subroom: Living Room (10)

Height: Tray

36.01 SF Walls	5.42 SF Ceiling
33.32 SF Walls & Ceiling	19.61 SF Floor
2.18 SY Flooring	

Missing Wall	4' 5 1/4" X 11'	Opens into ROOM11
Missing Wall	5 3/8" X 11'	Opens into ROOM4
Missing Wall	3' 11 5/8" X 11'	Opens into MAIN
Missing Wall	4' 5 1/4" X 11'	Opens into MAIN
Missing Wall	4' 5" X 11'	Opens into ROOM7




Subroom: Living Room (11)

Height: 11'

36.01 SF Walls	5.42 SF Ceiling
45.33 SF Walls & Ceiling	1.94 SF Floor
0.22 SY Flooring	6.15 LF Floor Perimeter
6.15 LF Ceil. Perimeter	

Missing Wall	11 3/8" X 11'	Opens into ROOM5
Missing Wall	4' 5" X 11'	Opens into ROOM11
Missing Wall	5 3/8" X 11'	Opens into ROOM8
Missing Wall	8" X 11'	Opens into MAIN
Missing Wall	8" X 11'	Opens into MAIN



Subroom: Living Room (1)


Height: 11'

35.92 SF Walls	5.45 SF Ceiling
41.37 SF Walls & Ceiling	0.51 SF Floor
0.06 SY Flooring	7.72 LF Floor Perimeter
12.22 LF Ceil. Perimeter	

Missing Wall - Goes to Floor **4' 6" X 9' 7"** **Opens into MAIN**

CONTINUED - Living Room

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
31. Paint the ceiling - one coat 388.98 SF	0.79	4.81	62.42	374.52	5/15 yrs	Avg.	33.33%	(124.83)	249.69
<u>WALLS:</u>									
32. R&R Quarter round - for wood flooring 48.55 LF	4.19	12.06	43.12	258.61	5/25 yrs	Avg.	20%	(49.04)	209.57
33. R&R T- molding - for wood flooring 14.17 LF	8.51	8.23	25.76	154.58	5/25 yrs	Avg.	20%	(29.15)	125.43
34. Paint baseboard, oversized - one coat 48.55 LF	1.28	0.60	12.54	75.28	5/15 yrs	Avg.	33.33%	(25.09)	50.19
35. Paint door/window trim & jamb - 2 coats (per side) 1.00 EA	38.24	0.47	7.74	46.45	0/15 yrs	Avg.	0%	(0.00)	46.45
<u>FLOORS:</u>									
36. R&R Engineered wood floor - floating - specs from ind analysis 254.10 SF	14.05	183.43	750.70	4,504.24	5/50 yrs	Avg.	10%	(402.85)	4,101.39
Totals: Living Room	209.60	902.28	5,413.68					630.96	4,782.72



1/2 Bath

Height: 8'

139.69 SF Walls
164.34 SF Walls & Ceiling
1.91 SY Flooring
22.05 LF Ceil. Perimeter

Door


2' X 6' 9"

Opens into KITCHEN_OFFSET

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
<u>REBUILD:</u>									
<u>WALLS:</u>									
37. R&R Quarter round - for wood flooring 20.05 LF	4.19	4.98	17.80	106.79	5/25 yrs	Avg.	20%	(20.26)	86.53
38. Paint baseboard, oversized - one coat 20.05 LF	1.28	0.25	5.20	31.11	5/15 yrs	Avg.	33.33%	(10.37)	20.74
39. Paint door/window trim & jamb - 2 coats (per side) 1.00 EA	38.24	0.47	7.74	46.45	0/15 yrs	Avg.	0%	(0.00)	46.45
40. Toilet - Detach & reset 1.00 EA	306.33	0.79	61.42	368.54	0/NA	Avg.	0%	(0.00)	368.54

CONTINUED - 1/2 Bath

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
41. Interior door - Detach & reset - slab only									
1.00 EA	27.56	0.00	5.52	33.08	0/NA	Avg.	0%	(0.00)	33.08
42. Mask and prep for paint - plastic, paper, tape (per LF)									
20.05 LF	1.65	0.45	6.72	40.25	0/15 yrs	Avg.	0%	(0.00)	40.25
making due to wallpaper for painting of baseboard and door opening									
FLOORS:									
43. R&R Engineered wood floor - floating - specs from ind analysis									
17.16 SF	14.05	12.39	50.70	304.19	5/50 yrs	Avg.	10%	(27.21)	276.98
Totals: 1/2 Bath		19.33	155.10	930.41				57.84	872.57

**Kitchen Offset****Height: Sloped**

51.76 SF Walls
67.60 SF Walls & Ceiling
1.29 SY Flooring
11.59 LF Ceil. Perimeter


15.84 SF Ceiling
11.63 SF Floor
6.08 LF Floor Perimeter

Missing Wall**3' 2 15/16" X 6'****Opens into ROOM17****Door****2' X 6' 9"****Opens into DEF_1_2_BATH****Door****2' 4" X 5' 6"****Opens into CLOSET_UNDER**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
44. R&R Quarter round - for wood flooring									
6.08 LF	4.19	1.51	5.40	32.39	5/25 yrs	Avg.	20%	(6.14)	26.25
45. Paint baseboard, oversized - one coat									
6.08 LF	1.28	0.08	1.58	9.44	5/15 yrs	Avg.	33.33%	(3.14)	6.30
46. Paint door/window trim & jamb - 2 coats (per side)									
1.00 EA	38.24	0.47	7.74	46.45	5/15 yrs	Avg.	33.33%	(15.49)	30.96
47. Interior door - Detach & reset - slab only									
1.00 EA	27.56	0.00	5.52	33.08	0/NA	Avg.	0%	(0.00)	33.08
FLOORS:									
48. R&R Engineered wood floor - floating - specs from ind analysis									
11.63 SF	14.05	8.40	34.36	206.16	5/50 yrs	Avg.	10%	(18.45)	187.71

CONTINUED - Kitchen Offset

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Totals: Kitchen Offset		10.46	54.60	327.52				43.22	284.30



Kitchen
Height: 12'

425.33 SF Walls	214.34 SF Ceiling
639.66 SF Walls & Ceiling	176.38 SF Floor
19.60 SY Flooring	43.19 LF Floor Perimeter
64.76 LF Ceil. Perimeter	

Window
2' X 2'
Opens into Exterior
Door
3' X 8'
Opens into Exterior
Missing Wall - Goes to Floor
10' 5" X 11' 5 3/8"
Opens into ROOM2
Door
2' 5 7/16" X 7' 9 5/16"
Opens into PANTRY
Door
2' 6 7/16" X 7' 10 1/8"
Opens into GARAGE

Subroom: Kitchen (2)
Height: 12'

40.91 SF Walls	2.02 SF Ceiling
42.93 SF Walls & Ceiling	2.02 SF Floor
0.22 SY Flooring	1.25 LF Floor Perimeter
7.74 LF Ceil. Perimeter	

Missing Wall
3' 2 15/16" X 12"
Opens into ROOM16
Missing Wall
3' 2 15/16" X 12"
Opens into KITCHEN_OFF2

Subroom: Kitchen (3)
Height: 7'

7.18 SF Walls	1.29 SF Ceiling
8.47 SF Walls & Ceiling	1.29 SF Floor
0.14 SY Flooring	0.88 LF Floor Perimeter
4.04 LF Ceil. Perimeter	

Missing Wall - Goes to Floor
3' 2" X 6' 10"
Opens into KITCHEN
Missing Wall
3' 2 15/16" X 7'
Opens into ROOM17

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
MITIGATION:									

CONTINUED - Kitchen


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
49. Containment Barrier/Airlock/Decon. Chamber - after hours									
122.13 SF	1.47	1.71	0.00	181.24	0/NA	Avg.	0%	(0.00)	181.24
50. Peel & seal zipper - heavy duty									
1.00 EA	17.59	1.04	0.00	18.63	0/NA	Avg.	NA	(0.00)	18.63
51. Protect - Cover with plastic - after hours									
193.67 SF	0.45	2.08	0.00	89.23	0/NA	Avg.	0%	(0.00)	89.23
52. Remove Outlet									
1.00 EA	6.72	0.00	0.00	6.72	0/25 yrs	Avg.	NA	(0.00)	6.72
53. Remove Light fixture - wall sconce									
1.00 EA	11.12	0.00	0.00	11.12	0/20 yrs	Avg.	NA	(0.00)	11.12
54. Tear out baseboard									
17.57 LF	0.59	0.00	0.00	10.37	0/NA	Avg.	NA	(0.00)	10.37
55. Tear out wet drywall, cleanup, bag - after hours									
100.00 SF	1.62	1.49	0.00	163.49	0/NA	Avg.	NA	(0.00)	163.49
56. Tear out wet drywall, cleanup, bag, per LF - 2' aft hrs									
14.75 LF	6.14	0.43	0.00	91.00	0/NA	Avg.	NA	(0.00)	91.00
57. Apply anti-microbial agent to the surface area									
130.00 SF	0.31	3.91	0.00	44.21	0/NA	Avg.	0%	(0.00)	44.21
58. Tear out and bag wet insulation - after hours									
70.50 SF	1.22	0.41	0.00	86.42	0/NA	Avg.	NA	(0.00)	86.42
59. Tear out and bag wet insulation, per LF - to 2' tall									
14.75 LF	1.67	0.16	0.00	24.79	0/NA	Avg.	NA	(0.00)	24.79
60. Clean stud wall									
120.50 SF	0.98	9.96	0.00	128.05	0/NA	Avg.	0%	(0.00)	128.05
FLOORS:									
61. Tear out non-salv floating floor & bag for disposal									
23.00 SF	2.16	0.15	0.00	49.83	0/NA	Avg.	NA	<0.00>	49.83
62. Apply anti-microbial agent to the surface area									
23.00 SF	0.31	0.69	0.00	7.82	0/NA	Avg.	0%	(0.00)	7.82
EQUIPMENT:									
63. Air mover (per 24 hour period) - No monitoring									
24.00 EA	26.77	0.00	0.00	642.48	0/NA	Avg.	0%	<0.00>	642.48
64. Dehumidifier (per 24 hr period)- up to 69 ppd- No monitor.									
6.00 EA	60.24	0.00	0.00	361.44	0/NA	Avg.	0%	<0.00>	361.44
REBUILD:									
CEILINGS:									
65. 1/2" drywall - hung, taped, floated, ready for paint									
20.00 SF	3.37	1.04	13.68	82.12	0/150 yrs	Avg.	0%	(0.00)	82.12

CONTINUED - Kitchen


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
66. Seal/prime (1 coat) then paint (1 coat) the surface area 20.00 SF	1.14	0.35	4.64	27.79	0/15 yrs	Avg.	0%	(0.00)	27.79
67. Paint the ceiling - one coat 217.65 SF	0.79	2.69	34.92	209.55	5/15 yrs	Avg.	33.33%	(69.85)	139.70
<u>WALLS:</u>									
68. Batt insulation replacement per LF - 4" - up to 2' tall 14.75 LF	3.24	2.54	10.06	60.39	0/150 yrs	Avg.	0%	(0.00)	60.39
69. 1/2" - drywall per LF - up to 2' tall 14.75 LF	13.91	1.70	41.38	248.25	0/150 yrs	Avg.	0%	(0.00)	248.25
70. 1/2" drywall - hung, taped, floated, ready for paint 60.00 SF	3.37	3.12	41.06	246.38	0/150 yrs	Avg.	0%	(0.00)	246.38
71. Seal/prime (1 coat) then paint (1 coat) the surface area 90.00 SF	1.14	1.56	20.84	125.00	0/15 yrs	Avg.	0%	(0.00)	125.00
72. Paint the walls - one coat 473.42 SF	0.79	5.86	75.98	455.84	5/15 yrs	Avg.	33.33%	(151.94)	303.90
73. Baseboard - 8" paint grade - 2 piece 17.57 LF	8.60	5.45	31.32	187.87	0/150 yrs	Avg.	0%	(0.00)	187.87
74. Seal (1 coat) & paint (1 coat) baseboard, oversized 17.57 LF	1.95	0.29	6.92	41.47	0/15 yrs	Avg.	0%	(0.00)	41.47
75. Paint baseboard, oversized - one coat 45.31 LF	1.28	0.56	11.72	70.28	5/15 yrs	Avg.	33.33%	(23.42)	46.86
76. Remove Quarter round - for wood flooring 18.83 LF	0.23	0.00	0.86	5.19	0/25 yrs	Avg.	NA	(0.00)	5.19
77. Quarter round - for wood flooring 36.40 LF	3.96	9.04	30.62	183.80	0/25 yrs	Avg.	0%	(0.00)	183.80
78. Paint door/window trim & jamb - 2 coats (per side) 2.00 EA	38.24	0.95	15.50	92.93	0/15 yrs	Avg.	0%	(0.00)	92.93
79. Interior door - Detach & reset - slab only 1.00 EA	27.56	0.00	5.52	33.08	0/NA	Avg.	0%	(0.00)	33.08
<u>FLOORS:</u>									
80. Remove Engineered wood flooring - floating 156.64 SF	1.56	0.00	48.88	293.24	0/50 yrs	Avg.	NA	(0.00)	293.24
81. Engineered wood floor - floating - specs from ind analysis 179.64 SF	12.49	129.68	474.68	2,848.06	5/50 yrs	Avg.	10%	(284.80)	2,563.26
82. Refrigerator - Remove & reset 1.00 EA	52.68	0.00	10.54	63.22	0/NA	Avg.	0%	(0.00)	63.22
83. Built-in oven - Detach & reset 1.00 EA	302.21	0.00	60.44	362.65	0/NA	Avg.	0%	(0.00)	362.65

CONTINUED - Kitchen


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
84. Dishwasher - Detach & reset									
1.00 EA	292.80	0.00	58.56	351.36	0/NA	Avg.	0%	(0.00)	351.36
Totals: Kitchen		186.86	998.12	7,905.31				530.01	7,375.30


Stairs3
Height: Sloped

75.01 SF Walls	19.46 SF Ceiling
94.47 SF Walls & Ceiling	26.71 SF Floor
2.97 SY Flooring	9.42 LF Floor Perimeter
10.40 LF Ceil. Perimeter	



Subroom: Landing (3)
Height: 10' 2"

73.21 SF Walls	13.01 SF Ceiling
86.22 SF Walls & Ceiling	13.03 SF Floor
1.45 SY Flooring	7.22 LF Floor Perimeter
7.22 LF Ceil. Perimeter	


Missing Wall
Missing Wall
3' 5 9/16" X 10' 1 11/16"
Opens into STAIRS6
3' 5 1/16" X 10' 1 11/16"
Opens into STAIRS2

Subroom: Stairs3 (1)
Height: Sloped

65.16 SF Walls	15.59 SF Ceiling
80.75 SF Walls & Ceiling	21.42 SF Floor
2.38 SY Flooring	8.07 LF Floor Perimeter
9.00 LF Ceil. Perimeter	


Missing Wall
Missing Wall
3' 5 9/16" X 8' 8"
Opens into STAIRS5
3' 5 9/16" X 8' 8"
Opens into STAIRS3


Subroom: Stairs4 (4)
Height: Sloped

32.34 SF Walls	15.25 SF Ceiling
47.59 SF Walls & Ceiling	24.99 SF Floor
2.78 SY Flooring	4.14 LF Floor Perimeter
4.02 LF Ceil. Perimeter	

Missing Wall
3' 5 9/16" X 10' 2"
Opens into LANDING
Missing Wall
3' 5 9/16" X 10' 2"
Opens into STAIRS3

Subroom: Stairs2 (2)
Height: 12'

6.95 SF Walls & Ceiling	6.95 SF Ceiling
1.69 SY Flooring	15.22 SF Floor


Missing Wall
3' 7 1/16" X 12'
Opens into Exterior
Missing Wall
3' 5 1/16" X 12'
Opens into LANDING
Missing Wall
1' 11 1/4" X 12'
Opens into Exterior

Subroom: Stairs3 (5)
Height: Sloped

58.65 SF Walls	13.53 SF Ceiling
72.18 SF Walls & Ceiling	19.93 SF Floor
2.21 SY Flooring	7.32 LF Floor Perimeter
7.82 LF Ceil. Perimeter	

Missing Wall
3' 5 9/16" X 9' 1"
Opens into STAIRS6
Missing Wall
3' 5 9/16" X 9' 1"
Opens into STAIRS4

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
85. Floor protection - cardboard and tape									
121.30 SF	0.61	2.80	15.36	92.15	0/NA	Avg.	NA	(0.00)	92.15
86. Paint stair skirt/apron									
30.33 LF	7.09	0.93	43.18	259.15	5/15 yrs	Avg.	33.33%	(86.39)	172.76
Totals: Stairs3		3.73	58.54	351.30				86.39	264.91
Total: First Floor		591.53	2,846.10	18,992.61				1,756.81	17,235.80

2nd Floor




Hallway Up

Height: 8'

	500.95 SF Walls	134.50 SF Ceiling
	635.45 SF Walls & Ceiling	134.50 SF Floor
	14.94 SY Flooring	61.60 LF Floor Perimeter
	81.26 LF Ceil. Perimeter	
Door	4' 9 9/16" X 7' 9 11/16"	Opens into MASTER_BEDR8
Missing Wall	3' 5" X 8'	Opens into STAIRS
Missing Wall	3' 5" X 8'	Opens into STAIRS
Door	2' 8" X 6' 8"	Opens into HALLWAY_CLOS
Door	5' 3 3/8" X 7' 11 11/16"	Opens into HALLWAY_CLO1
Door	2' 8" X 6' 8"	Opens into GUEST_BEDROO
Door	4' 3" X 8' 2"	Opens into BEDROOM


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
87. R&R Quarter round - for wood flooring									
61.60 LF	4.19	15.30	54.68	328.09	5/25 yrs	Avg.	20%	(62.21)	265.88
88. R&R T- molding - for wood flooring									
5.25 LF	8.51	3.05	9.56	57.29	0/25 yrs	Avg.	0%	(0.00)	57.29
89. Paint baseboard, oversized - one coat									
61.60 LF	1.28	0.76	15.94	95.55	5/15 yrs	Avg.	33.33%	(31.85)	63.70
90. Paint door/window trim & jamb - 2 coats (per side)									
1.00 EA	38.24	0.47	7.74	46.45	5/15 yrs	Avg.	33.33%	(15.49)	30.96
91. Paint door/window trim & jamb - Large - 2 coats (per side)									
1.00 EA	45.00	0.56	9.12	54.68	5/15 yrs	Avg.	33.33%	(18.23)	36.45
92. R&R Stair nosing - for wood flooring									
3.42 LF	10.51	2.49	7.70	46.14	0/25 yrs	Avg.	0%	(0.00)	46.14
FLOORS:									
93. R&R Engineered wood floor - floating - specs from ind analysis									
134.50 SF	14.05	97.09	397.36	2,384.18	5/50 yrs	Avg.	10%	(213.24)	2,170.94
94. Interior door - Detach & reset - slab only									
2.00 EA	27.56	0.00	11.02	66.14	0/NA	Avg.	0%	(0.00)	66.14
Totals: Hallway Up		119.72	513.12	3,078.52				341.02	2,737.50


Hallway Closet 1
Height: 10'

124.76 SF Walls	12.54 SF Ceiling
137.29 SF Walls & Ceiling	12.54 SF Floor
1.39 SY Flooring	11.59 LF Floor Perimeter
14.25 LF Cel. Perimeter	

Door **2' 8" X 6' 8"** **Opens into HALLWAY_UP**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
95. R&R Quarter round - for wood flooring									
11.59 LF	4.19	2.88	10.30	61.75	5/25 yrs	Avg.	20%	(11.72)	50.03
96. Paint baseboard, oversized - one coat									
11.59 LF	1.28	0.14	2.98	17.96	5/15 yrs	Avg.	33.33%	(6.00)	11.96
97. Paint door/window trim & jamb - 2 coats (per side)									
1.00 EA	38.24	0.47	7.74	46.45	5/15 yrs	Avg.	33.33%	(15.49)	30.96
FLOORS:									
98. R&R Engineered wood floor - floating - specs from ind analysis									
12.54 SF	14.05	9.05	37.06	222.29	5/50 yrs	Avg.	10%	(19.88)	202.41
Totals: Hallway Closet 1		12.54	58.08	348.45				53.09	295.36


Toilet Area
Height: 10'


75.94 SF Walls	12.03 SF Ceiling
87.97 SF Walls & Ceiling	12.03 SF Floor
1.34 SY Flooring	7.42 LF Floor Perimeter
9.81 LF Cel. Perimeter	

Door **2' 4 11/16" X 8' 1/16"** **Opens into BATHROOM2**
Missing Wall **4' 11 1/8" X 10'** **Opens into TOILET_AREA_**
Window **2' X 1' 6"** **Opens into Exterior**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
MITIGATION:									
99. Content Manipulation charge - per hour									
0.25 HR	49.11	0.00	0.00	12.28	0/NA	Avg.	0%	(0.00)	12.28
Removing of contents to complete mitigation									
FLOORS:									
100. Water extraction from carpeted floor									
12.03 SF	0.55	0.00	0.00	6.62	0/NA	Avg.	0%	<0.00>	6.62

CONTINUED - Toilet Area

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
101. Tear out non-salvageable tile floor & bag for disposal									
6.01 SF	4.27	0.10	0.00	25.76	0/NA	Avg.	NA	(0.00)	25.76
REBUILD:									
WALLS:									
103. Paint baseboard, oversized - one coat									
7.42 LF	1.28	0.09	1.92	11.51	5/15 yrs	Avg.	33.33%	(3.84)	7.67
104. Paint door/window trim & jamb - 2 coats (per side)									
1.00 EA	38.24	0.47	7.74	46.45	5/15 yrs	Avg.	33.33%	(15.49)	30.96
105. Interior door - Detach & reset - slab only									
2.00 EA	27.56	0.00	11.02	66.14	0/NA	Avg.	0%	(0.00)	66.14
106. Toilet - Detach & reset									
1.00 EA	306.33	0.79	61.42	368.54	0/NA	Avg.	0%	(0.00)	368.54
107. Detach & Reset Baseboard - 8" paint grade - 2 piece									
7.42 LF	4.07	0.02	6.04	36.26	0/150 yrs	Avg.	0%	(0.00)	36.26
d&r for flooring replacement									
FLOORS:									
108. Remove Tile floor covering									
6.01 SF	3.33	0.00	4.00	24.01	0/100 yrs	Avg.	NA	(0.00)	24.01
109. Tile floor covering - per specs from ind. tile analysis									
12.03 SF	11.53	5.11	28.76	172.58	5/100 yrs	Avg.	5%	(8.64)	163.94
CONTENTS									
110. Content Manipulation charge - per hour									
0.25 HR	49.11	0.00	2.46	14.74	0/NA	Avg.	0%	(0.00)	14.74
Resetting contents after repairs are complete									
Totals: Toilet Area	6.94	123.36	788.98					27.97	761.01


Bathroom
Height: 10'

125.76 SF Walls	29.29 SF Ceiling
155.05 SF Walls & Ceiling	17.40 SF Floor
1.93 SY Flooring	14.58 LF Floor Perimeter
21.74 LF Cel. Perimeter	

Door	2' 4 11/16" X 8' 1/16"	Opens into TOILET_AREA
Door	2' 4 1/4" X 7' 11 1/4"	Opens into GUEST_BEDROO
Door	2' 5" X 8' 7/8"	Opens into BEDROOM
Window	3' X 1' 6"	Opens into Exterior

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
----------	------	-----	-----	-----	----------	-------	-------	---------	-----

MITIGATION:

111. Content Manipulation charge - per hour

1.00 HR	49.11	0.00	0.00	49.11	0/NA	Avg.	0%	(0.00)	49.11
---------	-------	------	------	-------	------	------	----	--------	-------

Removing of contents to complete mitigation

WALLS:

112. Tear out trim

24.00 LF	0.59	0.00	0.00	14.16	0/NA	Avg.	NA	(0.00)	14.16
----------	------	------	------	-------	------	------	----	--------	-------

Casing around windows and doors as needed

113. Tear out baseboard

6.00 LF	0.59	0.00	0.00	3.54	0/NA	Avg.	NA	(0.00)	3.54
---------	------	------	------	------	------	------	----	--------	------

114. Cabinet - lower (base) unit w/shoring - Detach

5.92 LF	36.48	1.31	0.00	217.27	0/NA	Avg.	0%	(0.00)	217.27
---------	-------	------	------	--------	------	------	----	--------	--------

115. Tear out wet drywall, cleanup, bag, per LF - up to 2' tall

5.92 LF	4.22	0.17	0.00	25.15	0/NA	Avg.	NA	(0.00)	25.15
---------	------	------	------	-------	------	------	----	--------	-------

116. Tear out and bag wet insulation, per LF - to 2' tall

5.92 LF	1.67	0.06	0.00	9.95	0/NA	Avg.	NA	(0.00)	9.95
---------	------	------	------	------	------	------	----	--------	------

117. Apply anti-microbial agent to the surface area

11.83 SF	0.31	0.36	0.00	4.03	0/NA	Avg.	0%	(0.00)	4.03
----------	------	------	------	------	------	------	----	--------	------

118. Remove Cabinet knob or pull

6.00 EA	1.55	0.00	0.00	9.30	0/20 yrs	Avg.	NA	(0.00)	9.30
---------	------	------	------	------	----------	------	----	--------	------

119. Remove P-trap assembly - ABS (plastic)

2.00 EA	10.01	0.00	4.00	24.02	0/25 yrs	Avg.	NA	(0.00)	24.02
---------	-------	------	------	-------	----------	------	----	--------	-------

120. Remove Plumbing fixture supply line

4.00 EA	6.67	0.00	5.34	32.02	0/20 yrs	Avg.	NA	(0.00)	32.02
---------	------	------	------	-------	----------	------	----	--------	-------

FLOORS:

121. Water extraction from hard surface floor

17.40 SF	0.26	0.00	0.00	4.52	0/NA	Avg.	0%	<0.00>	4.52
----------	------	------	------	------	------	------	----	--------	------

122. Tear out non-salvageable tile floor & bag for disposal

17.40 SF	4.27	0.30	0.00	74.60	0/NA	Avg.	NA	(0.00)	74.60
----------	------	------	------	-------	------	------	----	--------	-------

123. Apply anti-microbial agent to the floor

17.40 SF	0.31	0.52	0.00	5.91	0/NA	Avg.	0%	(0.00)	5.91
----------	------	------	------	------	------	------	----	--------	------


EQUIPMENT:

CONTINUED - Bathroom

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
124. Air mover (per 24 hour period) - No monitoring									
6.00 EA	26.77	0.00	0.00	160.62	0/NA	Avg.	0%	<0.00>	160.62
REBUILD:									
WALLS:									
126. Batt insulation replacement per LF - 4" - up to 2' tall									
5.92 LF	3.24	1.02	4.04	24.24	0/150 yrs	Avg.	0%	(0.00)	24.24
127. 1/2" - drywall per LF - up to 2' tall									
5.92 LF	13.91	0.68	16.62	99.65	0/150 yrs	Avg.	0%	(0.00)	99.65
128. Seal/prime (1 coat) then paint (1 coat) the surface area									
11.83 SF	1.14	0.20	2.74	16.43	0/15 yrs	Avg.	0%	(0.00)	16.43
129. Paint the walls - one coat									
125.76 SF	0.79	1.56	20.20	121.11	5/15 yrs	Avg.	33.33%	(40.38)	80.73
130. Baseboard - 8" paint grade - 2 piece									
6.00 LF	8.60	1.86	10.70	64.16	0/150 yrs	Avg.	0%	(0.00)	64.16
131. Seal (1 coat) & paint (1 coat) baseboard, oversized									
6.00 LF	1.95	0.10	2.36	14.16	0/15 yrs	Avg.	0%	(0.00)	14.16
132. Paint baseboard, oversized - one coat									
14.58 LF	1.28	0.18	3.78	22.62	5/15 yrs	Avg.	33.33%	(7.54)	15.08
133. Casing - 2 1/4"									
24.00 LF	2.72	2.85	13.64	81.77	0/150 yrs	Avg.	0%	(0.00)	81.77
134. Seal (1 coat) & paint (1 coat) casing									
24.00 LF	1.85	0.34	8.94	53.68	0/15 yrs	Avg.	0%	(0.00)	53.68
135. Paint door/window trim & jamb - 2 coats (per side)									
3.00 EA	38.24	1.42	23.22	139.36	5/15 yrs	Avg.	33.33%	(46.45)	92.91
136. Interior door - Detach & reset - slab only									
3.00 EA	27.56	0.00	16.54	99.22	0/NA	Avg.	0%	(0.00)	99.22
137. Towel ring - Detach & reset									
2.00 EA	20.60	0.00	8.24	49.44	0/NA	Avg.	0%	(0.00)	49.44
138. Mirror - plate glass - Detach & reset									
15.00 SF	7.14	0.00	21.42	128.52	0/NA	Avg.	0%	(0.00)	128.52
139. Mask and cover light fixture									
2.00 EA	17.37	0.13	6.96	41.83	0/15 yrs	Avg.	0%	(0.00)	41.83
140. Custom cabinets - vanity units - High grade									
5.92 LF	388.55	163.11	492.66	2,955.99	0/50 yrs	Avg.	0%	(0.00)	2,955.99
141. Install Cabinet knob or pull									
6.00 EA	6.31	0.00	7.58	45.44	0/20 yrs	Avg.	0%	(0.00)	45.44

CONTINUED - Bathroom

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
142. Countertop - solid surface/granite - Detach & reset									
11.83 SF	41.97	0.11	99.32	595.94	0/NA	Avg.	0%	(0.00)	595.94
143. Backsplash - solid surface - Unattached - Detach & reset									
3.33 LF	4.85	0.03	3.24	19.42	0/NA	Avg.	0%	(0.00)	19.42
144. Install P-trap assembly - ABS (plastic)									
2.00 EA	68.06	0.00	27.22	163.34	0/25 yrs	Avg.	0%	(0.00)	163.34
145. Install Plumbing fixture supply line									
4.00 EA	17.02	0.00	13.62	81.70	0/20 yrs	Avg.	0%	(0.00)	81.70
146. Detach & Reset Baseboard - 8" paint grade - 2 piece									
14.58 LF	4.07	0.04	11.86	71.24	0/150 yrs	Avg.	0%	(0.00)	71.24
d&r baseboard for flooring replacement									
FLOORS:									
147. Tile floor covering - per specs from ind. tile analysis									
17.40 SF	11.53	7.39	41.60	249.61	5/100 yrs	Avg.	5%	(12.48)	237.13
148. R&R T-molding - for wood flooring									
3.00 LF	8.51	1.74	5.46	32.73	5/25 yrs	Avg.	20%	(6.16)	26.57
CONTENTS									
149. Content Manipulation charge - per hour									
1.00 HR	49.11	0.00	9.82	58.93	0/NA	Avg.	0%	(0.00)	58.93
Resetting contents after repairs are complete									
Totals: Bathroom		185.48		881.12		6,226.17			113.01
									6,113.16


Bedroom Closet
Height: 10'

 138.77 SF Walls
 151.45 SF Walls & Ceiling
 1.41 SY Flooring
 15.72 LF Ceil. Perimeter


 12.68 SF Ceiling
 12.68 SF Floor
 13.42 LF Floor Perimeter

Door
2' 3 5/8" X 8' 1/16"
Opens into BEDROOM

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
150. R&R Quarter round - for wood flooring									
13.42 LF	4.19	3.33	11.90	71.46	5/25 yrs	Avg.	20%	(13.56)	57.90

CONTINUED - Bedroom Closet

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
151. Paint baseboard, oversized - one coat									
13.42 LF	1.28	0.17	3.48	20.83	5/15 yrs	Avg.	33.33%	(6.95)	13.88
FLOORS:									
152. Paint door/window trim & jamb - 2 coats (per side)									
1.00 EA	38.24	0.47	7.74	46.45	5/15 yrs	Avg.	33.33%	(15.49)	30.96
Totals: Bedroom Closet									
	13.12		60.60		363.52			56.12	307.40


Bedroom
Height: 10'

375.23 SF Walls
 505.21 SF Walls & Ceiling
 14.44 SY Flooring
 45.99 LF Ceil. Perimeter

Door	2' 5" X 8' 7/8"	Opens into BATHROOM2
Door	2' 3 5/8" X 8' 1/16"	Opens into BEDROOM_CLOS
Door	4' 3" X 8' 2"	Opens into HALLWAY_UP
Window	3' X 4'	Opens into Exterior


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
MITIGATION:									
WALLS:									
154. Protect - Cover with plastic - after hours									
64.99 SF	0.45	0.70	0.00	29.95	0/NA	Avg.	0%	(0.00)	29.95
155. Tear out baseboard									
16.00 LF	0.59	0.00	0.00	9.44	0/NA	Avg.	NA	(0.00)	9.44
156. Tear out trim									
16.00 LF	0.59	0.00	0.00	9.44	0/NA	Avg.	NA	(0.00)	9.44
157. Tear out wet drywall, cleanup, bag, per LF - up to 2' tall									
13.83 LF	4.22	0.40	0.00	58.76	0/NA	Avg.	NA	(0.00)	58.76
158. Tear out and bag wet insulation, per LF - to 2' tall									
10.58 LF	1.67	0.11	0.00	17.78	0/NA	Avg.	NA	(0.00)	17.78
159. Apply anti-microbial agent to the surface area									
27.66 SF	0.31	0.83	0.00	9.40	0/NA	Avg.	0%	(0.00)	9.40

CONTINUED - Bedroom

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
160. Clean stud wall 27.66 SF	0.98	2.29	0.00	29.40	0/NA	Avg.	0%	(0.00)	29.40
Casing around windows and doors as needed									
FLOORS:									
161. Water extraction from hard surface floor 52.92 SF	0.26	0.00	0.00	13.76	0/NA	Avg.	0%	<0.00>	13.76
162. Tear out non-salv solid/eng. wood flr & bag for disposal 52.92 SF	4.26	0.35	0.00	225.79	0/NA	Avg.	NA	(0.00)	225.79
163. Apply anti-microbial agent to the surface area 55.00 SF	0.31	1.66	0.00	18.71	0/NA	Avg.	0%	<0.00>	18.71
164. Containment Barrier/Airlock/Decon. Chamber 42.00 SF	1.02	0.59	0.00	43.43	0/NA	Avg.	0%	<0.00>	43.43
EQUIPMENT:									
165. Air mover (per 24 hour period) - No monitoring 12.00 EA	26.77	0.00	0.00	321.24	0/NA	Avg.	0%	<0.00>	321.24
REBUILD:									
WALLS:									
166. Batt insulation replacement per LF - 4" - up to 2' tall 10.58 LF	3.24	1.82	7.22	43.32	0/150 yrs	Avg.	0%	(0.00)	43.32
167. 1/2" - drywall per LF - up to 2' tall 13.83 LF	13.91	1.60	38.80	232.78	0/150 yrs	Avg.	0%	(0.00)	232.78
168. Seal/prime (1 coat) then paint (1 coat) the surface area 27.66 SF	1.14	0.48	6.40	38.41	0/15 yrs	Avg.	0%	(0.00)	38.41
169. Paint the walls - one coat 375.23 SF	0.79	4.64	60.20	361.27	5/15 yrs	Avg.	33.33%	(120.42)	240.85
170. Baseboard - 8" paint grade - 2 piece 16.00 LF	8.60	4.96	28.52	171.08	0/150 yrs	Avg.	0%	(0.00)	171.08
171. Remove Quarter round - for wood flooring 21.02 LF	0.23	0.00	0.96	5.79	0/25 yrs	Avg.	NA	(0.00)	5.79
172. Quarter round - for wood flooring 37.02 LF	3.96	9.19	31.16	186.95	5/25 yrs	Avg.	20%	(37.40)	149.55
173. Seal (1 coat) & paint (1 coat) baseboard, oversized 16.00 LF	1.95	0.26	6.30	37.76	0/15 yrs	Avg.	0%	(0.00)	37.76
174. Paint baseboard, oversized - one coat 37.02 LF	1.28	0.46	9.58	57.43	5/15 yrs	Avg.	33.33%	(19.15)	38.28
175. Paint door/window trim & jamb - 2 coats (per side) 2.00 EA	38.24	0.95	15.50	92.93	5/15 yrs	Avg.	33.33%	(30.97)	61.96
176. Paint door/window trim & jamb - Large - 2 coats (per side) 1.00 EA	45.00	0.56	9.12	54.68	5/15 yrs	Avg.	33.33%	(18.23)	36.45

CONTINUED - Bedroom

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
177. Interior door - Detach & reset 3.00 EA	101.27	0.26	60.82	364.89	0/NA	Avg.	0%	(0.00)	364.89
FLOORS:									
178. Remove Engineered wood flooring - floating 77.05 SF	1.56	0.00	24.04	144.24	0/50 yrs	Avg.	NA	(0.00)	144.24
179. Engineered wood floor - floating - specs from ind analysis 129.97 SF	12.49	93.82	343.42	2,060.57	5/50 yrs	Avg.	10%	(206.05)	1,854.52
Totals: Bedroom		125.93	642.04	4,639.20				432.22	4,206.98


**Guest Bedroom****Height: 10'**

452.57 SF Walls
595.40 SF Walls & Ceiling
15.87 SY Flooring
50.82 LF Ceil. Perimeter

142.83 SF Ceiling
142.83 SF Floor
43.40 LF Floor Perimeter

Door	2' 8" X 6' 8"	Opens into HALLWAY_UP
Door	2' 4 13/16" X 8' 1/16"	Opens into GUEST_CLOSET
Door	2' 4 1/4" X 7' 11 1/4"	Opens into BATHROOM2


QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
180. R&R Quarter round - for wood flooring 43.40 LF	4.19	10.78	38.54	231.16	5/25 yrs	Avg.	20%	(43.83)	187.33
181. Paint baseboard, oversized - one coat 43.40 LF	1.28	0.54	11.22	67.31	5/15 yrs	Avg.	33.33%	(22.44)	44.87
182. Paint door/window trim & jamb - 2 coats (per side) 3.00 EA	38.24	1.42	23.22	139.36	5/15 yrs	Avg.	33.33%	(46.45)	92.91
FLOORS:									
183. R&R Engineered wood floor - floating - specs from ind analysis 142.83 SF	14.05	103.11	421.98	2,531.85	5/50 yrs	Avg.	10%	(226.45)	2,305.40
184. Interior door - Detach & reset - slab only 3.00 EA	27.56	0.00	16.54	99.22	0/NA	Avg.	0%	(0.00)	99.22
Totals: Guest Bedroom		115.85	511.50	3,068.90				339.17	2,729.73


Guest Closet
Height: 10'


169.61 SF Walls	22.24 SF Ceiling
191.85 SF Walls & Ceiling	22.24 SF Floor
2.47 SY Flooring	16.48 LF Floor Perimeter
18.88 LF Cel. Perimeter	

Door
2' 4 13/16" X 8' 1/16"
Opens into GUEST_BEDROO

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
185. R&R Quarter round - for wood flooring									
16.48 LF	4.19	4.09	14.64	87.78	5/25 yrs	Avg.	20%	(16.65)	71.13
186. Paint baseboard, oversized - one coat	16.48 LF	1.28	0.20	4.26	5/15 yrs	Avg.	33.33%	(8.52)	17.03
187. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	38.24	0.47	7.74	46.45	5/15 yrs	Avg. 33.33%	(15.49)	30.96
FLOORS:									
188. R&R Engineered wood floor - floating - specs from ind analysis									
22.24 SF	14.05	16.05	65.72	394.24	5/50 yrs	Avg.	10%	(35.27)	358.97
Totals: Guest Closet	20.81	92.36	554.02					75.93	478.09


Master Bedroom
Height: Tray


653.28 SF Walls	345.89 SF Ceiling
999.17 SF Walls & Ceiling	286.16 SF Floor
31.80 SY Flooring	67.73 LF Floor Perimeter
67.73 LF Cel. Perimeter	

Window
3' X 4'
Opens into Exterior
Window
3' X 4'
Opens into Exterior

Subroom: Master Bedroom (1)
Height: 10'

298.34 SF Walls	76.90 SF Ceiling
375.24 SF Walls & Ceiling	76.90 SF Floor
8.54 SY Flooring	27.88 LF Floor Perimeter
36.85 LF Cel. Perimeter	

Door
4' 2 1/16" X 7' 10 1/8"
Opens into MASTER_BATHR
Door
4' 9 9/16" X 7' 9 11/16"
Opens into HALLWAY_UP

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
REBUILD:									
WALLS:									
189. R&R Quarter round - for wood flooring									
95.61 LF	4.19	23.74	84.86	509.21	5/25 yrs	Avg.	20%	(96.57)	412.64
190. Paint baseboard, oversized - one coat									
95.61 LF	1.28	1.18	24.72	148.28	5/15 yrs	Avg.	33.33%	(49.42)	98.86
191. Interior door - Detach & reset - slab only									
1.00 EA	27.56	0.00	5.52	33.08	0/NA	Avg.	0%	(0.00)	33.08
192. Paint door/window trim & jamb - 2 coats (per side)									
1.00 EA	38.24	0.47	7.74	46.45	5/15 yrs	Avg.	33.33%	(15.49)	30.96
FLOORS:									
193. R&R Engineered wood floor - floating - specs from ind analysis									
363.06 SF	14.05	262.08	1,072.62	6,435.69	5/50 yrs	Avg.	10%	(575.61)	5,860.08
Totals: Master Bedroom		287.47	1,195.46	7,172.71				737.09	6,435.62



Stairs

Height: 10'

134.05 SF Walls
185.99 SF Walls & Ceiling
10.31 SY Flooring
30.40 LF Ceil. Perimeter

Missing Wall

3' 5" X 10'

Opens into HALLWAY_UP

Missing Wall

3' 5" X 10'

Opens into HALLWAY_UP

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
194. Floor protection - cardboard and tape									
92.81 SF	0.61	2.14	11.74	70.49	0/NA	Avg.	NA	(0.00)	70.49
195. Paint stair skirt/apron									
32.75 LF	7.09	1.00	46.64	279.84	5/15 yrs	Avg.	33.33%	(93.27)	186.57
Totals: Stairs		3.14	58.38	350.33				93.27	257.06
Total: 2nd Floor		891.00	4,136.02	26,590.80				2,268.89	24,321.91
Total: Dwelling		1,482.53	7,244.60	48,047.50				4,025.70	44,021.80
Line Item Totals: ANNE_CHAMPAGNE		2,444.62	8,894.42	58,762.91				4,025.70	54,737.21

[%] - Indicates that depreciate by percent was used for this item

[M] - Indicates that the depreciation percentage was limited by the maximum allowable depreciation for this item

Additional Charges	Charge
Electrical Consumption	82.25
Additional Charges Total	\$82.25

Grand Total Areas:

9,883.77 SF Walls	4,003.09 SF Ceiling	13,886.86 SF Walls and Ceiling
3,681.83 SF Floor	409.09 SY Flooring	1,119.25 LF Floor Perimeter
0.00 SF Long Wall	0.00 SF Short Wall	1,382.15 LF Ceil. Perimeter
3,681.83 Floor Area	3,991.34 Total Area	9,352.63 Interior Wall Area
5,474.69 Exterior Wall Area	580.71 Exterior Perimeter of Walls	
0.00 Surface Area	0.00 Number of Squares	0.00 Total Perimeter Length
0.00 Total Ridge Length	0.00 Total Hip Length	

Coverage	Item Total	%	ACV Total	%
Dwelling	43,465.98	73.97%	39,440.28	71.95%
Dwelling - Pack Out/Pack Back	10,715.41	18.23%	10,715.41	19.55%
Dwelling - Water Mitigation	4,581.52	7.80%	4,663.77	8.51%
Other Structures	0.00	0.00%	0.00	0.00%
Contents	0.00	0.00%	0.00	0.00%
Total	58,762.91	100.00%	54,819.46	100.00%

Loss Recap Summary

Coverage	Replacement Cost - RCV	Recoverable Depreciation	Prior Payments	Deductible	Net Claim
Structural	\$58,845.16	\$4,025.70	\$10,000.00	\$4,710.00	40,109.46
Dwelling	\$43,465.98	\$4,025.70	\$10,000.00	\$4,710.00	24,730.28
Dwelling - Pack Out/Pack Back	\$10,715.41	\$0.00	\$0.00	\$0.00	10,715.41
Dwelling - Water Mitigation	\$4,663.77	\$0.00	\$0.00	\$0.00	4,663.77
TOTAL	\$58,845.16	\$4,025.70	\$10,000.00	\$4,710.00	40,109.46

**Summary for
Dwelling****Summary for All Items**

Line Item Total	34,770.99
Material Sales Tax	1,450.39
Overhead	3,622.30
Profit	3,622.30
Replacement Cost Value	\$43,465.98
Less Depreciation	(4,025.70)
Actual Cash Value	\$39,440.28
Less Deductible	(4,710.00)
Less Prior Payment(s)	(10,000.00)
Net Claim Remaining	\$24,730.28
Total Depreciation	4,025.70
Total Recoverable Depreciation	4,025.70
Net Claim Remaining if Depreciation is Recovered	\$28,755.98

Brandon Hunt

**Summary for
Dwelling - Pack Out/Pack Back**

This is not an additional amount of insurance and does not increase the limit of coverage for the policy.

Summary for All Items

Line Item Total	8,103.50
Cleaning Mtl Tax	145.45
Overhead	824.91
Profit	824.91
Cleaning Sales Tax	816.64
Replacement Cost Value	\$10,715.41
Actual Cash Value	\$10,715.41
Net Claim	\$10,715.41

Brandon Hunt

**Summary for
Dwelling - Water Mitigation**

This is not an additional amount of insurance and does not increase the limit of coverage for the policy.

Summary for All Items

Line Item Total	4,549.38
Electrical Consumption	82.25
Material Sales Tax	5.17
Cleaning Mtl Tax	7.78
Overhead	0.00
Profit	0.00
Cleaning Sales Tax	19.19
Replacement Cost Value	\$4,663.77
Actual Cash Value	\$4,663.77
Net Claim	\$4,663.77

Brandon Hunt

Recap of Taxes, Overhead and Profit

Overhead (10%)	Profit (10%)	Material Sales Tax (8.25%)	Cleaning Mtl Tax (8.25%)	Cleaning Sales Tax (8.25%)	Manuf. Home Tax (5%)	Storage Rental Tax (8.25%)	Total Tax (8.25%)
Line Items							
4,447.21	4,447.21	1,455.56	153.23	835.83	0.00	0.00	0.00
Additional Charges							
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Total							
4,447.21	4,447.21	1,455.56	153.23	835.83	0.00	0.00	0.00

Recap by Room

Estimate: ANNE_CHAMPAGNE

Packout		8,103.50	17.09%
Coverage: Dwelling - Pack Out/Pack Back	100.00% =	8,103.50	
Area: Dwelling		2,201.61	4.64%
Coverage: Dwelling	59.61% =	1,312.38	
Coverage: Dwelling - Water Mitigation	40.39% =	889.23	
Area: First Floor			
Pantry		299.56	0.63%
Coverage: Dwelling	100.00% =	299.56	
Dining Room		2,540.34	5.36%
Coverage: Dwelling	100.00% =	2,540.34	
Closet under stairs		385.48	0.81%
Coverage: Dwelling	100.00% =	385.48	
Living Room		4,301.80	9.07%
Coverage: Dwelling	100.00% =	4,301.80	
1/2 Bath		755.98	1.59%
Coverage: Dwelling	100.00% =	755.98	
Kitchen Offset		262.46	0.55%
Coverage: Dwelling	100.00% =	262.46	
Kitchen		6,720.33	14.17%
Coverage: Dwelling	71.80% =	4,825.52	
Coverage: Dwelling - Water Mitigation	28.20% =	1,894.81	
Stairs3		289.03	0.61%
Coverage: Dwelling	100.00% =	289.03	
Area Subtotal: First Floor		15,554.98	32.80%
Coverage: Dwelling	87.82% =	13,660.17	
Coverage: Dwelling - Water Mitigation	12.18% =	1,894.81	
Area: 2nd Floor			
Hallway Up		2,445.68	5.16%
Coverage: Dwelling	100.00% =	2,445.68	
Hallway Closet 1		277.83	0.59%
Coverage: Dwelling	100.00% =	277.83	
Toilet Area		658.68	1.39%
Coverage: Dwelling	92.67% =	610.39	
Coverage: Dwelling - Water Mitigation	7.33% =	48.29	
Bathroom		5,159.57	10.88%
Coverage: Dwelling	81.84% =	4,222.69	
Coverage: Dwelling - Water Mitigation	18.16% =	936.88	
Bedroom Closet		289.80	0.61%


Coverage: Dwelling	100.00% =	289.80	
Bedroom		3,871.23	8.16%
Coverage: Dwelling	79.85% =	3,091.06	
Coverage: Dwelling - Water Mitigation	20.15% =	780.17	
Guest Bedroom		2,441.55	5.15%
Coverage: Dwelling	100.00% =	2,441.55	
Guest Closet		440.85	0.93%
Coverage: Dwelling	100.00% =	440.85	
Master Bedroom		5,689.78	12.00%
Coverage: Dwelling	100.00% =	5,689.78	
Stairs		288.81	0.61%
Coverage: Dwelling	100.00% =	288.81	
Area Subtotal: 2nd Floor		21,563.78	45.47%
Coverage: Dwelling	91.81% =	19,798.44	
Coverage: Dwelling - Water Mitigation	8.19% =	1,765.34	
Area Subtotal: Dwelling		39,320.37	82.91%
Coverage: Dwelling	88.43% =	34,770.99	
Coverage: Dwelling - Water Mitigation	11.57% =	4,549.38	
Subtotal of Areas		47,423.87	100.00%
Coverage: Dwelling	73.32% =	34,770.99	
Coverage: Dwelling - Pack Out/Pack Back	17.09% =	8,103.50	
Coverage: Dwelling - Water Mitigation	9.59% =	4,549.38	
Total		47,423.87	100.00%

Recap by Category with Depreciation

O&P Items		RCV	Deprec.	ACV
APPLIANCES		647.69		647.69
Coverage: Dwelling	@ 100.00% =	647.69		
CABINETRY		2,850.74		2,850.74
Coverage: Dwelling	@ 100.00% =	2,850.74		
CONTENT MANIPULATION		61.39		61.39
Coverage: Dwelling	@ 100.00% =	61.39		
CONT: PACKING,HANDLNG,STORAGE		8,103.50		8,103.50
Coverage: Dwelling - Pack Out/Pack Back	@ 100.00% =	8,103.50		
GENERAL DEMOLITION		2,996.11		2,996.11
Coverage: Dwelling	@ 100.00% =	2,996.11		
DOORS		689.65		689.65
Coverage: Dwelling	@ 100.00% =	689.65		
DRYWALL		749.50		749.50
Coverage: Dwelling	@ 100.00% =	749.50		
ELECTRICAL		422.70		422.70
Coverage: Dwelling	@ 100.00% =	422.70		
FLOOR COVERING - CERAMIC TILE		339.33	16.97	322.36
Coverage: Dwelling	@ 100.00% =	339.33		
FLOOR COVERING - WOOD		20,496.72	2,204.56	18,292.16
Coverage: Dwelling	@ 100.00% =	20,496.72		
FINISH CARPENTRY / TRIMWORK		495.12		495.12
Coverage: Dwelling	@ 100.00% =	495.12		
FINISH HARDWARE		41.20		41.20
Coverage: Dwelling	@ 100.00% =	41.20		
INSULATION		101.25		101.25
Coverage: Dwelling	@ 100.00% =	101.25		
LABOR ONLY		392.88		392.88
Coverage: Dwelling	@ 100.00% =	392.88		
MIRRORS & SHOWER DOORS		107.10		107.10
Coverage: Dwelling	@ 100.00% =	107.10		
PLUMBING		816.86		816.86
Coverage: Dwelling	@ 100.00% =	816.86		
PAINTING		3,562.75	991.18	2,571.57
Coverage: Dwelling	@ 100.00% =	3,562.75		
O&P Items Subtotal		42,874.49	3,212.71	39,661.78


Non-O&P Items		RCV	Deprec.	ACV
CLEANING		145.20		145.20
Coverage: Dwelling - Water Mitigation	@ 100.00% =	145.20		
CONTENT MANIPULATION		61.39		61.39
Coverage: Dwelling - Water Mitigation	@ 100.00% =	61.39		

Non-O&P Items			RCV	Deprec.	ACV
GENERAL DEMOLITION			1,121.04		1,121.04
Coverage: Dwelling - Water Mitigation	@	100.00% =	1,121.04		
WATER EXTRACTION & REMEDIATION			3,221.75		3,221.75
Coverage: Dwelling - Water Mitigation	@	100.00% =	3,221.75		
Non-O&P Items Subtotal			4,549.38	0.00	4,549.38
O&P Items Subtotal			42,874.49	3,212.71	39,661.78
Permits and Fees			82.25		82.25
Coverage: Dwelling - Water Mitigation	@	100.00% =	82.25		
Material Sales Tax			1,455.56	141.99	1,313.57
Coverage: Dwelling	@	99.64% =	1,450.39		
Coverage: Dwelling - Water Mitigation	@	0.36% =	5.17		
Cleaning Mtl Tax			153.23		153.23
Coverage: Dwelling - Pack Out/Pack Back	@	94.92% =	145.45		
Coverage: Dwelling - Water Mitigation	@	5.08% =	7.78		
Overhead			4,447.21	335.50	4,111.71
Coverage: Dwelling	@	81.45% =	3,622.30		
Coverage: Dwelling - Pack Out/Pack Back	@	18.55% =	824.91		
Profit			4,447.21	335.50	4,111.71
Coverage: Dwelling	@	81.45% =	3,622.30		
Coverage: Dwelling - Pack Out/Pack Back	@	18.55% =	824.91		
Cleaning Sales Tax			835.83		835.83
Coverage: Dwelling - Pack Out/Pack Back	@	97.70% =	816.64		
Coverage: Dwelling - Water Mitigation	@	2.30% =	19.19		
Total			58,845.16	4,025.70	54,819.46




N
↑

First Floor



N
↑

2nd Floor



N
↑

3rd Floor