Shift Indicator Panel

Adjustment —

- Check that the index mark of the indicator aligns with the N mark of the shift indicator panel with the transmission in NEUTRAL.
- 2. If not aligned, remove the panel mounting screws and adjust by moving the panel.

NOTE: Whenever the escutcheon is removed for indicator bulb replacement etc., reinstall the panel as described above.

