# Disable communication timeout on the GoPiGo

**#** dexterindustries.com/GoPiGo/learning-2/python-programming-for-the-raspberry-pigopigo/disable\_com\_timeout/

Enable the communication timeout on the GoPiGo. The GoPiGo automatically stops if it does not get a command from the GoPiGo in the time period specified. This could be helpful in automatically stopping a run away robot.

## **Syntax**

```
disable_com_timeout(time)
```

### Parameter:

None

#### Return:

1 on success

-1 on failure

## **Example**

```
from gopigo import *
enable_com_timeout(1000) #Stops motors after 1s
fwd()
disable_com_timeout()
fwd() #This will not stop
```