
Hard missions (99): low battery, cold, GPS lost or spoofed, wind, return home always asked
battery dead in the air
feelings of the core
raw telemetry instead
no slow layer
without "I am lost"
without "low energy"
0.29
0.16
0.29
0.30
0.29
0.0
0.2
0.4
0.6
0.8
1.0
share of missions [95 % CI]
came back and landed at home
0.52
0.63
0.53
0.53
0.53
0.0
0.2
0.4
0.6
0.8
1.0
share of missions [95 % CI]