

COCOA PRESS

Fastener Guide

M2

M2x10 SHCS

0 M2x10 Self Tapping

Hex Nuts

M6 Hex Nut

M5 Hex Nut

T-Nuts

M3

M5

Heatsets

M2

M3

Spacers

M5 / 1mm Spacer

20mm Calibration Cube

M3



M3x16 SHCS

M3x20 SHCS M3x30 SHCS

M3x40 SHCS

M5




M5x30 BHCS

M5x40 SHCS

Thumbscrews

Extruder Belt Tensioning Bed



V2.2 (8/10/2023