

Customer Return Assessment

Customer Quality · 2025-10 · Issue 1

1. Return details

Assessment of a customer return received against the reference below. The assembly was built at Plant X (Bamberg).

Field	Entry
Return	CR-RET-2025-233
Received	2025-10-07
Build site	Plant X (Bamberg)
Reported condition	Seepage at seal interface
Units returned	4

The customer reported seepage observed at the seal interface during routine inspection. The units were returned complete and unmodified.

2. Analysis

The seal was removed from each unit and assessed against the material specification.

Unit	Hardness	Dimensional	Assessment
1	Below lower limit	Conforming	Seal hardness below specification
2	Below lower limit	Conforming	Seal hardness below specification
3	Within band	Conforming	No material nonconformity
4	Below lower limit	Conforming	Seal hardness below specification

Seal hardness below specification was recorded against three of the four units assessed. The fourth unit returned a conforming result and no material nonconformity was recorded against it.

Replacement units were despatched to the customer against the original order reference. The assessed seals were retained.