

Supplier Corrective Action Request

Supplier Quality · 2025-05 · Issue 1

1. Request

Corrective action requested of the supplying source following a nonconforming delivery received at Plant X (Bamberg).

Field	Entry
Request	CAR-2025-007
Raised	2025-05-14
Receiving site	Plant X (Bamberg)
Delivery reference	DN-2025-1188
Nonconforming characteristic	Seal hardness below specification

The delivery was sampled at incoming inspection and rejected. A corrective action response is required within the interval stated in the supply agreement.

2. Supplier response

The supplying source responded within the stated interval. The response is summarised below and is held in full with this request.

Element	Response
Containment	Affected lot quarantined at source
Immediate action	Process parameters reset to nominal
Verification at source	Sample of 60 assessed, conforming
Response date	2025-05-28

The source attributed the condition to a process parameter drift at the moulding stage and stated that the parameter had been reset and the affected lot contained.

3. Verification

Verification was performed on the next two deliveries received at the site following the response.

Delivery	Sampled	Result
DN-2025-1256	30	Conforming
DN-2025-1301	30	Conforming

The request is closed on the basis of the verification above. Closure applies to this request only.