Complete schematic - sheet 2

Every component terminal is shown. Equal net labels are connected; use connection IDs in the CSV for physical routing.

E1 DESIGN HOLD | Physical connections unapproved | Generic ports require actual-part mapping | 02 Nov 2026

F1 | MCU buck input fuse / holder

ADDITIONAL / MISSING OR SELECT

DC A / interrupt rating TBD

IN	PACK_PROTECTED
OUT	MCU_BUCK_IN

BUCK2 | LM2596 #2

INVENTORY / VERIFY

5.0 V target

IN+	LOGIC_BUCK_IN
IN-	GND
OUT+	V5_LOGIC_RAW
OUT-	GND

FA | auxiliary driver fuse / holder

ADDITIONAL / MISSING OR SELECT

DC A / interrupt rating TBD

IN	MOTOR_SWITCHED
OUT	AUX_SUPPLY

BUCK1 | LM2596 #1

INVENTORY / VERIFY

5.0 V target

IN+	MCU_BUCK_IN
IN-	GND
OUT+	V5_MCU_RAW
OUT-	GND

FL | left driver fuse / holder

ADDITIONAL / MISSING OR SELECT

DC A / interrupt rating TBD

IN	MOTOR_SWITCHED
OUT	LEFT_SUPPLY

F2 | logic buck input fuse / holder

ADDITIONAL / MISSING OR SELECT

DC A / interrupt rating TBD

IN	PACK_PROTECTED
OUT	LOGIC_BUCK_IN

FK | contactor coil fuse / holder

ADDITIONAL / MISSING OR SELECT

DC A / interrupt rating TBD

IN	PACK_PROTECTED
OUT	COIL_FUSED

FR | right driver fuse / holder

ADDITIONAL / MISSING OR SELECT

DC A / interrupt rating TBD

IN	MOTOR_SWITCHED
OUT	RIGHT_SUPPLY

Red +supply | Black GND | Blue control | Green sensor | Orange motor | Thick = high-current | Dashed = missing/blocked

Net labels join across sheets. Crossings alone do not join. No component footprint / connector orientation is implied.