Motor-driver connections: seven motors

Each orange bundle represents two separate motor conductors. Exact per-terminal nets/fuses are shown in the complete schematic and CSV.

E2 DESIGN HOLD | Physical connections unapproved | Generic ports require actual-part mapping | 08 Nov 2026



M1/M2 and M3/M4 are parallel wheel pairs. M5/M6 are parallel on channel A; M7 is channel B. No motor lead to GND/chassis. Conveyor voltage and all motor running/start/stall currents remain unverified.

Red +supply | Black GND | Blue control | Green sensor | Orange motor | Thick = high-current | Dashed = missing/blocked

Net labels join across sheets. Crossings alone do not join. No component footprint / connector orientation is implied.