Calibration System

CALIBRA

Centro Universitario da FEI

Image

Load Image

Refresh

Options

Histogram

Convertion

RGB Matrix

Files

Color Config (.clr)

Save to File

Load from File

Dimension (.dim)

Save to File

Load from File



Colors	H max	H min	S max	S min	I max	I min
Color 1	191	104	100	30	85	30
Color 2	33	328	100	30	100	30
Color 3	83	16	100	45	100	45

New Color

Delete Color

Field Dimensions

Report

Color Specification

Color Range for Saturation (S)

100

30

Color Range for Intensity (I)

85

30

Color Range for Hue (H)

191

104