VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3318 DETAILS

PO# ITEM	TOTAL	DESCRIPTION	VPART NO.	CHID OTX	LOCATION	FOB	EXT COST
	HEM	DESCRIPTION	MAKE	SHIP QTY			
3318	3318 1103XB	55-59 VENT WINDOW ASSYLH		_ 1	B103	\$123.97	\$123.97
3318 1103AB	TINTED 5%	CHEVY PU		D103	\$123.77	Ψ123.71	
3318	1103XBF	55-59 VENT WINDOW FRAME PR	CHEVY PU	1		\$0.00	\$0.00
3318	3318 1103XG	51-54 DOOR WINDOW GLASS		1	B103	\$37.58	\$37.58
3310		RHW / LOWER FRAME CLEAR	CHEVY PU	•	B103	φ31.36	φυ1.υσ
3318	3318 1103XH	51-54 DOOR WINDOW GLASS		_ 1	B101	\$37.46	\$37.46
3310	11032111	LHW / LOWER FRAME CLEAR	CHEVY PU		D101	\$37.40	φ37. 4 0
3318	3318 1103XL	64-66 VENT WINDOW RH		1	B121	\$178.50	\$178.50
3310 1103AL	CHROME	CHEVY PU		D121	Ψ170.50	Ψ170.50	
3318	1103Y	DOOR LATCH RH 52-54	CHEVY PU	1	B32	\$14.74	\$14.74
3318	1103Z	DOOR LATCH LH 52-54	CHEVY PU	1	B32	\$14.34	\$14.34
3318	1104A	ROCKER PANEL RH 60-66	CHEVY PU	2	C124	\$38.72	\$38.72
3318	1104B	ROCKER PANEL LH 60-66	CHEVY PU	3	C124	\$56.28	\$56.28
3318	1104C	ROCKER PANEL RH 67-72	CHEVY PU	4	E102	\$36.64	\$36.64
3318	1104D	ROCKER PANEL LH 67-72	CHEVY PU	8	E102	\$73.28	\$73.28
2210	2210 1104D4	73-87 ROCKER PANEL RH OE			E101	#25.26	#27.26
3318 1104DA	STYLE	CHEVY PU	2	E101	\$25.26	\$25.26	
2210	3318 1104DB	73-87 ROCKER PANEL LH OE		1	E101	¢11.50	¢11.50
3318 11	1104DB	STYLE	CHEVY PU		EIVI	\$11.52	\$11.52
3318 1	1104H	INNER DOOR STEP WITH		1	C92	\$39.96	\$39.96
	110411	ROCKER LH55-59	CHEVY PU	1	C92	\$39.90	\$39.90
3318	1104I	55-59 BEDSIDE STEP RH LONG	CHEVY PU	1	C124	\$55.39	\$55.39

PAGE:9