VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

## **CONTAINER 70816 DETAILS**

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3293	1103E	DOOR RELAY RH 47-54	CHEVY PU	2	B94	\$22.68	\$23.19
3287	1103F	DOOR RELAY LH 47-54	CHEVY PU	2	B94	\$22.68	\$23.19
3285	1103IB	60-63 DOOR RELAY LH	CHEVY PU	2	В93	\$21.00	\$21.51
3287	1103KD	67-71 DOOR SHELL LH JIMMY/BLAZER	CHEVY PU	1	D61	\$205.00	\$245.28
3287	1103KE	72 DOOR SHELL LH BLAZER/JIMMY	CHEVY PU	1	D61	\$225.96	\$243.34
3287	1103KK	73-87 DOOR OUTER LOWER PANEL RH	TP CHEVY PU	2	F171	\$13.62	\$15.07
3287	1103KL	73-87 DOOR OUTER LOWER PANEL LH	TP CHEVY PU	1	F171	\$6.79	\$7.52
3287	1103KN	73-87 DOOR INNER LOWER PANEL LH	TP CHEVY PU	1	G64	\$18.50	\$19.86
3287	1103TB	72 DOOR LATCH/RODS REMOTE	CHEVY PU	2	B32	\$75.40	\$74.21
3287	1103XC	51-54 VENT WINDOW RH	CHEVY PU	1	B112	\$39.00	\$39.80
3287	1103XD	51-54 VENT WINDOW LH	CHEVY PU	1	B103	\$39.20	\$40.00
3287	1103XK	47-50 DOOR WINDOW GLASS LH	CHEVY PU	1	B101	\$66.13	\$68.95
3287	1103XU	64-66 DOOR WINDOW GLASS ASSY LH	CHEVY PU	1	C94	\$43.45	\$45.15
3287	1103Z	DOOR LATCH LH 52-54	CHEVY PU	2	B32	\$28.68	\$29.67
3287	1104A	ROCKER PANEL RH 60-66	CHEVY PU	2	C124	\$38.70	\$42.21

PAGE:5