VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-12-13	CEVA	ORGIN	2017-12-15

CONTAINER 71215 DETAILS

PO#	TOTAL	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT COST
	ITEM	DESCRIPTION	MAKE				
2226	3336 1067F	TAIL LIGHT PANEL 69 STD* USE	8716470		C81	\$202.68	\$220.05
3330		1067FA FOR RS MODEL *	CAMARO	3			
3336	1067FA	TAIL LIGHT PANEL 69 RS	CAMARO	3	F34	\$315.99	\$330.90
3336	3336 1067G	ROCKER PANEL RH 67-69 H / T	7741310		E111	¢170 55	¢100.25
3330	100/G		CAMARO	3	EIII	\$178.55	\$188.25
3336	1067Н	ROCKER PANEL LH 67-69 H / T	7741311		E111	\$178.80	\$188.50
3330	100/11		CAMARO	5	EIII	\$170.00	\$100.50
3336	1068F	HOOD LATCH ASSY 67-68 RS	CAMARO	2	A94	\$50.54	\$52.44
3336	1068J	HOOD LATCH ASSY 69	CAMARO	2	A92	\$48.48	\$49.30
3336	1068N	HOOD LOCK SUPPORT 69	CAMARO	3	A83	\$26.91	\$27.21
2226	1000	HOOD 67-69 SS	3938617	2	D71	\$240.00	\$262.26
3330	3336 1069		CAMARO	2	E71	\$249.90	\$263.26
2242	3342 1069A	HOOD 70-81 W / COWL		1	D11	\$172.83	\$190.30
3342		INDUCTION	CAMARO				
3346	3346 1069B	HOOD 67-69 FIREBIRD 400 **	7738876	2	E31	\$352.36	\$382.82
3340		SEE NOTE FOR 67 **	FIREBIRD				
3336	3336 1069CWT	67-69 COWL TOP VENT GRILLE PANEL* WTP *		3	A117	\$187.20	\$194.22
3330			CAMARO				
		FILLER PANEL (BEHIND REAR					
3336 1075	WINDOW)67-69 CAMARO &	CAMARO	4	F137	\$99.12	\$99.52	
		FIREBIRD COUPE	CAMAKO				
3336	1076B	DOOR SHELL LH 67ALSO FOR F /	CANADO	4	F02	\$578.08	\$611.80
		B B B B B B B B B B B B B B B B B B B	CAMARO	1			
3336	1076C	DOOR SHELL RH 68ALSO FOR F / B	CAMARO	1	F12	\$144.85	\$153.11
			CAMARO				
3336	1076D	DOOR SHELL LH 68ALSO FOR F / B	CAMARO	2	F12 / F11	\$289.38	\$305.90
		В	DACE:6				

PAGE:6