VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-12-13	CEVA	ORGIN	2017-12-15

CONTAINER 71215 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
			WAKE				COSI
3344	1114A	CAB CORNER RH 55-59	CHEVY PU	5	C122	\$61.55	\$62.05
3344	1114B	CAB CORNER LH 55-59	CHEVY PU	3	C122	\$36.69	\$41.70
3346	1114C	CAB CORNER RH 60-66	CHEVY PU	5	C122	\$27.55	\$29.45
3341	1114FA	47-55 CAB CORNER INNER RH	CHEVY PU	2	D94	\$30.60	\$30.86
3341	1114FB	47-55 CAB CORNER INNER LH	CHEVY PU	1	D94	\$15.19	\$15.32
3344	1115E	HEAD LAMP BEZEL 58-59 PAIR	CHEVY PU	1	C43	\$27.90	\$28.19
3342	1115HA	HEAD LAMP BEZEL 69-72 PAIR GMC	CHEVY PU	1	B34	\$75.60	\$76.02
		REAR BUMPER CHROME 67-72		3			
3346	1116B	FLEETSIDE	CHEVY PU		F124	\$241.20	\$247.98
3341	1119A	47-53 FRONT BED PANEL	CHEVY PU	3	M91	\$169.92	\$176.07
22.46	2214	54-59 FRONT BED PANEL STEPSIDE		3	3.504	Ø1.51.20	Ø1.50.0.4
3346	1119B		CHEVY PU		M91	\$151.20	\$158.94
22.42	2242 1110E	67-72 FRONT BED PANEL		2	3.401	¢12654	¢1.42.64
3342 1119E	FLEETSIDESTEEL FLOOR	CHEVY PU	_ 2	M91	\$136.54	\$143.64	
2244 44222	60-67 VENT WINDOW HANDLE				#10.3 0	#10. 7 0	
3344	3344 1130G	PR	CHEVY PU	2	A124	\$18.38	\$18.58
3341 1131	WINDOW REGULATOR CRANK		20		0101	0.4.0=	
	1131	HANDLE 47-66	CHEVY PU	30	A125	\$124.20	\$127.20
3342	1136	58-59 HOOD LATCH GMC ONLY	CHEVA DI	1	A35	\$24.02	\$24.13
		ES ES TIOUE ENTERING ONE I	CHEVY PU			Ψ202	Ψ210
3341	1136	58-59 HOOD LATCH GMC ONLY	CHEVY PU	1	A35	\$24.02	\$24.13

PAGE:10