VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3318 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3318	4554	55-57 FLOOR PAN LH SEDAN	CHEVROLET	1		\$0.00	\$0.00
3318	4560	55-57 TRUNK FLOOR COMPLETESEDAN,HT W / SPARE TIRE CUT	CHEVROLET	1	K41	\$288.73	\$288.73
3318	4564	55-57 TRUNK TAIL PANELCONVT / HT	CHEVROLET	1	D103	\$27.71	\$27.71
3318	4570B	55-57 WINDOW REGULATOR LH SEDAN	CHEVROLET	1	A81	\$50.01	\$50.01
3318	4570C	55-57 WINDOW REGULATOR RH CONVT / HT	CHEVROLET	1	A81	\$50.01	\$50.01
3318	4570D	55-57 WINDOW REGULATOR LH CONVT / HT	CHEVROLET	1		\$50.01	\$50.01
3318	4570E	55-57 QUARTER WINDOW REGULATOR RHSEDAN	CHEVROLET	1	A81	\$44.58	\$44.58
3318	4570F	55-57 QUARTER WINDOW REGULATOR LHSEDAN	CHEVROLET	1	A81	\$44.58	\$44.58
3318	4570G	55-57 QUARTER WINDOW REGULATOR RHCONVT	CHEVROLET	1	A81	\$44.60	\$44.60
3318	4570Н	55-57 QUARTER WINDOW REGULATOR LHCONVT	CHEVROLET	1	A81	\$44.60	\$44.60
3318	4570J	55-57 QUARTER WINDOW REGULATOR RHH / T	CHEVROLET	1	A81	\$44.58	\$44.58
3318	461	59 TRUNK ORIGINAL	CHEVROLET	1	3-1	\$0.00	\$0.00
3318	4866918	DOME LIGHT BASE.67 / 9 CAMARO.68 / 9NOVA,CHEVYII,64 / 7 CHEVELLE(NOT COVN	CAMARO	3	C43	\$10.38	\$10.38
3318 5	7CHEVYCU	P\$7 CHEVY DASH CUPSSET OF 2	KNOBS	2		\$0.00	\$0.00
3318	57KNOBKI	57 CHEVY KNOB SET CHROME	KNOBS	1		\$0.00	\$0.00

PAGE:97