## **GOLDEN LEAF AUTOMOTIVE**

## **INVOICE 63815**

## GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG MB R3E 2Z9 TELEPHONE: 204/775-2222 **INVOICE DATE 2017-11-14** 

PAGE: 4

SHIP TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG, MB R3E 2Z9 CANADA

## \*\*\* INVOICE \*\*\*

CHISTOLIER SHIP WAY FOR TERMS PONINTED SALES OUR ORDER									
CUSTOMER		SHIP VIA		F.O.B	TERMS	PO NUMBER	SALES	DATE	OUR ORDER #
W0004		BEST		ORIGIN	NET 10TH	WK OF OCT 30TH	M	2017-10-30	51739
ORDER	CIT	TD	B.O.	ITEM	ITEM DESCRIPTION		PRICE	EXT.PRICE	
	SH	IP .	в.о.	MAKE	ITEM DESCRIPTION				DIS%
1	1		0	1100G	BATTERY TRY ASSEMBLY 67-72 W / AC			\$ 50.00	\$ 50.00
	1			CHEVY PU				0 %	
1	1		0	GL-1100A	47-54 INNER FRONT COWL SIDE PANELLH			\$ 54.00	\$ 54.00
1	1		U	CHEVY PU	CHEVY / GMC*47-50 NEED LOUVER CUT*			0 %	\$ 34.00
1	0		1	1106DWT	47-54 COWL OUTER LOWER PANEL RH*		\$ 53.00	\$ 0.00	
1	U		1	CHEVY PU	NON WTP *			0 %	\$ 0.00
1	0		1	1106AC	47-54 CAB FLOOR PAN LH		\$ 63.00	\$ 0.00	
	<u> </u>		1	CHEVY PU	47-34 CAB FLOOR FAIN LH			0 %	\$ 0.00
1	1		0	1107CB	55-59 CAB FLOOR LH		\$ 63.00	\$ 63.00	
			U	CHEVY PU	55-59 CAB FLOOR EII				0 %
1	1		0	1104H	INNER DOOR STEP WITH ROCKER LH 55-59		\$ 89.00	\$ 89.00	
		•	U	CHEVY PU			0 %		
1	1		0	1104G	INNER DOOR STEP WITH ROCKER RH 55- 59		\$ 89.00	\$ 89.00	
•			Ů	CHEVY PU			0 %		
1	1		0	1153M	67-72 EXTERIOR MIRROR ARM LHSTAINLESS		\$ 26.00	\$ 26.00	
				CHEVY PU			0 %	Ψ 20.00	
1	0		1	1153P	67-72 EXTERIOR MIRROR ARM RHSTAINLESS		\$ 26.00	\$ 0.00	
•				CHEVY PU			0 %	Ψ 0.00	
1	1		0	1153L	67-72 EXTERIOR MIRROR ARM BLACK LH		\$ 17.00	\$ 17.00	
				CHEVY PU			0 %	<b>\$17.00</b>	
1	1	. 0	0	1153N	67-72 EXTERIOR MIRROR ARM BLACK RH		\$ 17.00	\$ 17.00	
				CHEVY PU			0 %		
2	2	0		LP21	54-55 TAIL LAMP ASSY BLK / STAINLESSBEZEL		\$ 33.00	\$ 66.00	
				CHEVY PU			0 %		
									CONTINUE