FILL UP DETAILS

DATE	SONO	CUST#	ITEM#	DESCRIPTION	SALES	LOC	QTYORD	FILLED	AMOU
DATE: 2017-09-	-05								
2017-09-05	51181	B0028	1106BJ	67-72 CAB FLOOR REAR PATCH RH	VY	G74	1	1	\$ 61.00
2017-09-05	51181	B0028	1102BS	67-72 FRONT LOWER DOOR PILLAR RH	VY	C74	1	1	\$ 17.00
2017-09-05	51181	B0028	1101Z	DOOR SKIN, PARTIAL LOWER LH 67-729"	VY	D102	1	1	\$ 27.00
2017-09-05	51181	B0028	1101Y	DOOR SKIN, PARTIAL LOWER RH 67-729"	VY	D102	1	1	\$ 27.00
2017-09-05	51181	B0028	1101ZA	67-72 DOOR INNER BOTTOM PANEL LH	VY	D104	1	1	\$ 38.00
2017-09-05	51181	B0028	1101YA	67-72 DOOR INNER BOTTOM PANEL RH	VY	D104	1	1	\$ 38.00
2017-09-05	51181	B0028	1099	FENDER LH 69-72	VY	N53	1	1	\$ 234.00
2017-09-05	51181	B0028	1098	FENDER RH 69-72	VY	N52	1	1	\$ 234.00
2017-09-05	51181	B0028	1106BD	67-72 OUTER CAB FLOOR / INNER ROCKERPATCH LH	VY	G63	1	1	\$ 94.00
2017-09-05	51181	B0028	1106BC	67-72 OUTER CAB FLOOR / INNER ROCKERPATCH RH	VY	G63	1	0	\$ 0.00
2017-09-05	51181	B0028	1106AN	60-72 CAB FLOOR REAR SUPPORT LH**PATCH PANEL** OVERLAYS SUPPORT **	VY	C33	1	1	\$ 16.00
2017-09-05	51181	B0028	1106AM	60-72 CAB FLOOR REAR SUPPORT RH**PATCH PANEL** OVERLAYS SUPPORT**	VY	C33	1	1	\$ 16.00
2017-09-05	51181	B0028	1106AL	67-72 FRONT CAB FLOOR SUPPORT MOUNTRH=LH	VY	B75	2	2	\$ 32.00
2017-09-05	51181	B0028	1106BK	67-72 CAB FLOOR REAR PATCH LH	VY	G74	1	1	\$ 61.00
2017-09-05	51181	B0028	1102BT	67-72 FRONT LOWER DOOR PILLAR LH	VY	C74	1	1	\$ 17.00
					SUBTOTAL: 16		L: 16	15	\$912.00
						ТОТА	L: 16	15	\$912.00