VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3318 DETAILS

PO# IT	ITEM	DESCRIPTION	VPART NO.	———SHIP OTV	LOCATION	FOB	EXT COST
	TIENI	DESCRIPTION	MAKE				
	3318 112A	67 TRUNK LOCK ORIGINAL 64-			3-4	\$36.00	\$36.00
3318		66 CHEVL63-65&68 GTO,64-66	CAMARO	4			
		MONTE,60-68 CHET	CAMARO				
3318	3318 112B	68 TRUNK LOCK68 MONTE		1	1-2	\$8.76	\$8.76
		CARLO / NOVA	CHEVELLE				
		68-69 TRUNK LOCK LATER67		1	4-1	\$6.24	\$6.24
3318	3318 113	CHEVELLE / MONTE,62 & 66-67	CAMARO				
		GTO	CAMARO				
3318	1130	DOOR HANDLE INSIDE 47-66	CHEVY PU	23	A125	\$95.22	\$95.22
		55-59 VENT WINDOW HANDLE		_			
3318 1130F	PR	CHEVY PU	2	A124	\$18.18	\$18.18	
	3318 1130G	60-67 VENT WINDOW HANDLE		1	A124	\$9.28	\$9.28
3318		PR	CHEVY PU				
2210	110077	68-72 VENT WINDOW HANDLE			A124	\$9.28	\$9.28
3318	3318 1130H	PR	CHEVY PU	1			
2210	1121	WINDOW REGULATOR CRANK			A125	\$12.42	\$12.42
3318	3318 1131	HANDLE 47-66	CHEVY PU	3			
2210	1122	EXTERIOR DOOR HANDLE 47-		4	A32	\$105.44	\$105.44
3318	1132	51PR	CHEVY PU				
2210	1122	EXTERIOR DOOR HANDLE 52-59		4	A125	\$89.20	\$89.20
3318	1133	PR	CHEVY PU				
2210	1124	60-66 EXTERIOR DOOR HANDLE		2	C63	\$58.80	\$58.80
3318	3318 1134	PR	CHEVY PU				
3318	1134A	67-72 EXT. DOOR HANDLEPR		2	A124	\$44.62	\$44.62
	3310 113 7 A	or 12 Extr. Book Inn (BEE) K	CHEVY PU		11121	Ψ11.02	Ψ11.02
3318	1134B	73-80 EXT. DOOR HANDLEPR	CHEVY PU	2	A124	\$46.82	\$46.82
2210	1124C	67-72 DOOR HANDLE TRIM			A124	\$2.16	\$2.16
3318	1134C	WASHER BLACK	CHEVY PU	2			
		68 TRUNK LOCK ORIGINAL67			4-4	\$18.40	\$18.40
3318	113A	CHEVELLE / MONTE,62 & 66-67		2			
		GTO	CAMARO				

PAGE:20